

Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

Contractor	Vendor ID	Address	City	State	ZIP	Telephone	FAX
Gerstner Electric, Inc.	0010340	2400 Cassens Drive	Fenton	MO	63026	(63-6)6-80-5	(63-6)6-80-5

Job Number	Federal/State Project Number	Description of work	Route Number	County	Location of work
J6Q3171E	FAS S501(49)	ITS improvements	Various	VARIOUS	in various locations in the St. Louis District

Critical Date	Actual Date	Key Date	Subject	Date Contractor Assumed Maintenance	Disturbed Area on Project	Authorized Area on Project	
Substantial Work Complete Date	0				0	0	Acres
Price Adjustments Base Date	0						
Physical Work Complete Date	0						
Contract Items Complete Date	0						
Final Acceptance Date	0						
Letting Date	20181019						
Execution Date	20181101						
Award Date	20181101						
Notice to Proceed Date	20190101						
Open to Traffic Date	20190102						
Work Begin Date	20190102						
Adjusted Completion Date	20191231						
Original Completion Date	20191231						

Totals by Job Number				
J6Q3171E		To Date	Previous	This estimate
	Participating	\$632,670.71	\$598,617.41	\$34,053.30
	Non-	\$0.00	\$0.00	\$0.00
	Participating	Ψ0.00	ψ0.00	ψ0.00
	Total	\$632,670.71	\$598,617.41	\$34,053.30
	Earnings	ΨΟΟΣ,ΟΤΟ.ΤΤ	φουσ,σττ.ττ	φο 1,000.00
	Stockpiled	\$0.00	\$0.00	\$0.00
	Materials	40.00	Ψ3.33	Ψ
	Gross	\$632,670.71	\$598,617.41	\$34,053.30
	Earnings	φοσΣ,στο	φουσ,στι.τι	φο 1,000.00
	Other	\$0.00	\$0.00	\$0.00
	Adjustments			
	Retainage	\$0.00	\$0.00	\$0.00



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

		, .,		,					
Incentive									\$0.00
	\$0.00)	\$0	0.00					\$0.00
Liquidated Damages	\$0.00)	\$0	0.00					\$0.00
Overrun Adjustments	(\$15,832.80)	(\$5,380.	.00)					(\$10,452.80)
Total:	\$616,837.9 ⁻								\$23,600.50
	Disincentive Liquidated Damages Overrun Adjustments	Disincentive \$0.00 Liquidated \$0.00 Damages Overrun Adjustments \$15,832.80	ncentive \$0.00 Disincentive \$0.00 Liquidated \$0.00 Damages Overrun (\$15,832.80)	ncentive \$0.00 \$0 Disincentive \$0.00 \$0 Liquidated \$0.00 \$0 Damages \$0.00 \$0 Verrun \$0.00 \$0 Adjustments \$15,832.80 \$0 Fotal: \$616,837.91 \$593,237	ncentive \$0.00 \$0.00 Disincentive \$0.00 \$0.00 Liquidated \$0.00 \$0.00 Damages \$0.00 \$0.00 Description \$	ncentive \$0.00 \$0.	ncentive \$0.00 \$0.	ncentive \$0.00 \$0.	ncentive \$0.00 \$0.00 Disincentive \$0.00 \$0.00 Liquidated \$0.00 \$0.00 Damages \$0.00 \$0.00 Overrun \$0.00 Disincentive \$0.00 \$0.0

Total Contract				
181019-F04		To Date	Previous	This Estimate
	Line Item Pay	\$632,670.71	\$598,617.41	\$34,053.30
	All Adjustments	(\$15,832.80)	(\$5,380.00)	(\$10,452.80)
	Total	\$616,837.91	\$593,237.41	\$23,600.50

If the "This Estimate" total is greater then \$100.00, this is a Pay estimate. If the "This Estimate" total is equal to \$0.00, this is a No Pay estimate. If the "This Estimate" total is between \$100.00 and \$0.00, this is a Minimum estimate and no payment will be made. This estimate will be rejected. If the "This Estimate" total is less than \$0.00, this is a Negative estimate and no payment will be made. This estimate will be rejected. You will be notified should this estimate be rejected for reasons other than those listed above.

Approval Date		User ID
20190716	Generated and Approved (and should be considered Draft) at the Project Office Level by	steink
20190716	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	silvej1
20190717	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Contract Amount	Net Change Order Amount to Date	Current Contract Amount	% of current contract amount complete
\$994,321.69	\$86037.01	\$1,080,358.70	58.6%

Contract Adjustments:

Line Iter	n Adjustı	ments:			
Project Number	Line Number		Adjustment Type	Line Item Adjustment Amount	Remarks
J6Q3171E	0040	SYSTEM	Overrun	(\$562.80)	Overrun adjustment created for the following discrepancy: Est Nbr: 0013 Type: El Seq No: 1 Desc: Minor Item J6Q3171E /0040 exceeds Overrun Limits. This adjustment applies to DWR Date 07/10/2019.
	0100	SYSTEM	Overrun	(\$4300.00)	Overrun adjustment created for the following discrepancy: Est Nbr: 0013 Type: El Seq No: 2 Desc: Minor Item J6Q3171E /0100



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

Line Iter	n Adjustı	ments:				
Project Number	Line Number	Entered by User	Adjustment Type	Line Item Adjustment Amount	Remarks	
J6Q3171E					exceeds Overrun Limits. This adjustment applies to DWR Date 07/02/2019.	
	0100	SYSTEM	Overrun	(\$1720.00)	Overrun adjustment created for the following discrepancy: Est Nbr: 0013 Type: El Seq No: 2 Desc: Minor Item J6Q3171E exceeds Overrun Limits. This adjustment applies to DWR Date 07/03/2019.	/0100
	0100	SYSTEM	Overrun	(\$860.00)	Overrun adjustment created for the following discrepancy: Est Nbr: 0013 Type: El Seq No: 2 Desc: Minor Item J6Q3171E exceeds Overrun Limits. This adjustment applies to DWR Date 07/08/2019.	/0100
	0100	SYSTEM	Overrun	(\$860.00)	Overrun adjustment created for the following discrepancy: Est Nbr: 0013 Type: El Seq No: 2 Desc: Minor Item J6Q3171E exceeds Overrun Limits. This adjustment applies to DWR Date 07/09/2019.	/0100
	0100	SYSTEM	Overrun	(\$860.00)	Overrun adjustment created for the following discrepancy: Est Nbr: 0013 Type: El Seq No: 2 Desc: Minor Item J6Q3171E exceeds Overrun Limits. This adjustment applies to DWR Date 07/12/2019.	/0100
	0100	SYSTEM	Overrun	(\$1290.00)	Overrun adjustment created for the following discrepancy: Est Nbr: 0013 Type: El Seq No: 2 Desc: Minor Item J6Q3171E exceeds Overrun Limits. This adjustment applies to DWR Date 07/15/2019.	/0100
J	6Q3171E			(\$10452.80)		
	Summary (\$10452.86		(\$10452.80)			

Discrepancies:		
Discrepancy Message	Resolved By User ID	Remarks
Minor Item J6Q3171E /0040 exceeds Overrun Limits.	SYSTEM	This discrepancy has been automatically addressed by line item adjustment: Est Nbr: 0013 Prj Nbr: J6Q3171E Line Item Nbr: 0040 Adjust Type: OVRN Adjust Seq Nbr: 1
Minor Item J6Q3171E /0100 exceeds Overrun Limits.	SYSTEM	This discrepancy has been automatically addressed by multiple line item adjustments: Est Nbr: 0013 Prj Nbr: J6Q3171E Line Item Nbr: 0100 Adjust Type: OVRN Adjust Seq Nbrs: 1 - 6
Minor Item J6Q3171E /1060 exceeds Overrun Limits.	SYSTEM	This discrepancy has been automatically addressed by material discrepancy payment adjustments or prior overrun discrepancy payment adjustments

All Items, T	his Estimate	:						
Project Number	Line Item Number	Item Code	Description	Unit Price	Previous Total Paid Quantity	Quantity this Period	Quantity to Date	Amount this Estimate
J6Q3171E	0040	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	\$8.40	155.00	162.00	317.00	\$1360.80
	0100	9109902	MISC. ADVANCED DIAGNOSTICS	\$430.00	111.00	23.00	134.00	\$9890.00
	0120	9109902	MISC. FandI FIBER OPTIC FUSION SPLICE, MULTI MODE	\$30.00	0.00	12.00	12.00	\$360.00
	0130	9109902	MISC. FandI FIBER OPTIC FUSION SPLICE, SINGLE MODE	\$10.00	316.00	82.00	398.00	\$820.00
	0230	9109902	MISC. FIBER OPTIC TERMINATION	\$25.00	44.00	25.00	69.00	\$625.00



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

All Items, T	his Estimate	:								
Project Number	Line Item Number	Item Code	Description	Unit Price	Previous Total Paid Quantity	Quantity this Period	Quantity to Date	Amount this Estimate		
J6Q3171E	0300	9109902	MISC. INSTALL SALVAGED FIELD CABINET (DUAL)	\$950.00	0.00	1.00	1.00	\$950.00		
	0400	9109902	MISC. INSTALL UPS SYSTEM ASSEMBLY	\$500.00	1.00	1.00	2.00	\$500.00		
	0420	9109902	MISC. MODOT BURIED CABLE DRIVABLE DELINEATOR P OST	\$100.00	3.00	2.00	5.00	\$200.00		
	0660	9109902	MISC. TROUBLESHOOTING	\$200.00	37.00	6.00	43.00	\$1200.00		
	0750	9109903	MISC. Fandl CABLE IN CONDUIT, #6 WIRE, VARIABL E CONDUCTORS	\$1.85	0.00	330.00	330.00	\$610.50		
	0780	9109903	MISC. Fandl CABLE IN CONDUIT: CAT5E OUTDOOR RA TED CABLE	\$2.50	1005.00	40.00	1,045.00	\$100.00		
	0790	9109903	MISC. FandI FIBER OPTIC CABLE, 24-STRAND SINGL E MODE	\$3.00	9788.00	714.00	10,502.00	\$2142.00		
	0830	9109902	MISC. PM CCTV CAMERA, ASSEMBLY, POLE, and FIEL D CABINET	\$420.00	305.00	11.00	316.00	\$4620.00		
	0890	9109902	MISC. PM NON-INTRUSIVE VEHICLE DETECTOR STATIO NS (MICROWAVE)	\$305.00	265.00	35.00	300.00	\$10675.00		
	1060	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED DMS PIX EL BOARD	\$650.00	2.00	0.00	2.00	\$0.00		
J6Q3171E										
Summary										

Estimate Item Detail, All Items to Date: Category **Project** Line Item Description Current Current Unit **Amount Paid** Number Number Code Bid + CO Installed to **Price** to Date Date \$20000.00 \$20,000.00 J6Q3171E 0001 0010 6169901 MISC. TEMPORARY TRAFFIC CONTROL 1.00 1.00 J6Q3171E MOBILIZATION 1.00 1.00 \$77950.69 \$77,950.69 0001 0020 6181000 9103700 | CCTV CAMERA ASSEMBLY, INSTALLED J6Q3171E 0050 0030 50.00 14.00 \$750.00 \$10,500.00 250.00 317.00 \$2,662.80 J6Q3171E 0050 0040 9105200 CONDUIT, 2 IN., RIGID, IN TRENCH \$8.40 100.00 0.00 \$9.00 \$0.00 J6Q3171E CONDUIT, 3 IN., RIGID, IN TRENCH 0050 0050 9105201 9105202 CONDUIT, 4 IN., RIGID, IN TRENCH \$10.00 J6Q3171E 0050 0060 100.00 0.00 \$0.00 CONDUIT, 3 IN., RIGID, PUSHED 0.00 \$19.00 \$0.00 J6Q3171E 0050 0070 9107201 50.00 J6Q3171E 0050 0800 9107202 CONDUIT, 4 IN., RIGID, PUSHED 50.00 0.00 \$20.00 \$0.00 J6Q3171E FIBER OPTIC CABLE, 24-STRAND, 18 SINGLE MODE, 6 MULTIMODE 500.00 0.00 \$3.00 \$0.00 0050 0090 9108352



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

Estimate I	tem Detail	, All Item	s to Date	:			'	
Project Number	Category #	Line Number	Item Code	Description	Current Bid + CO	Current Installed to Date	Unit Price	Amount Paid to Date
J6Q3171E	0050	0100	9109902	MISC. ADVANCED DIAGNOSTICS	100.00	134.00	\$430.00	\$57,620.00
J6Q3171E	0050	0110	9109902	MISC. Fandl CAMERA POLE (60FT) AND LOWERING S YSTEM	1.00	0.00	\$5500.00	\$0.00
J6Q3171E	0050	0120	9109902	MISC. FandI FIBER OPTIC FUSION SPLICE, MULTI M ODE	50.00	12.00	\$30.00	\$360.00
J6Q3171E	0050	0130	9109902	MISC. FandI FIBER OPTIC FUSION SPLICE, SINGLE MODE	1,250.00	398.00	\$10.00	\$3,980.00
J6Q3171E	0050	0140	9109902	MISC. FandI ITS PULLBOX CLASS 1	2.00	0.00	\$1070.00	\$0.00
J6Q3171E	0050	0150	9109902	MISC. FandI ITS PULLBOX CLASS 2	2.00	0.00	\$1800.00	\$0.00
J6Q3171E	0050	0160	9109902	MISC. FandI ITS PULLBOX CLASS 5	2.00	0.00	\$2400.00	\$0.00
J6Q3171E	0050	0170	9109902	MISC. FandI NON-INTRUSIVE VEHICLE DETECTOR POL E	5.00	0.00	\$1000.00	\$0.00
J6Q3171E	0050	0180	9109902	MISC. FandI TYPE 1 ITS CABINET	1.00	0.00	\$4500.00	\$0.00
J6Q3171E	0050	0190	9109902	MISC. FandI TYPE 2 ITS CABINET	1.00	0.00	\$1500.00	\$0.00
J6Q3171E	0050	0200	9109902	MISC. FandI TYPE 5 ITS CABINET	1.00	0.00	\$250.00	\$0.00
J6Q3171E	0050	0210	9109902	MISC. FandI TYPE 7 ITS CABINET	1.00	0.00	\$1000.00	\$0.00
J6Q3171E	0050	0220	9109902	MISC. FIBER OPTIC SPLICE ENCLOSURE	6.00	2.00	\$780.00	\$1,560.00
J6Q3171E	0050	0230	9109902	MISC. FIBER OPTIC TERMINATION	150.00	69.00	\$25.00	\$1,725.00
J6Q3171E	0050	0240	9109902	MISC. INSTALL IN-PAVEMENT WIRELESS SENSORS	50.00	0.00	\$60.00	\$0.00
J6Q3171E	0050	0250	9109902	MISC. INSTALL IP-ADDRESSABLE POWER STRIP	100.00	0.00	\$75.00	\$0.00
J6Q3171E	0050	0260	9109902	MISC. INSTALL NON-INTRUSIVE ACCESS POINT and A SSEMBLY	5.00	0.00	\$335.00	\$0.00
J6Q3171E	0050	0270	9109902	MISC. INSTALL NON-INTRUSIVE VEHICLE DETECTOR A SSEMBLY	10.00	5.00	\$630.00	\$3,150.00
J6Q3171E	0050	0280	9109902	MISC. INSTALL NON-INTRUSIVE WIRELESS REPEATER	5.00	0.00	\$220.00	\$0.00
J6Q3171E	0050	0290	9109902	MISC. INSTALL SALVAGED CAMERA POLE	6.00	2.00	\$1275.00	\$2,550.00
J6Q3171E	0050	0300	9109902	MISC. INSTALL SALVAGED FIELD CABINET (DUAL)	1.00	1.00	\$950.00	\$950.00
J6Q3171E	0050	0310	9109902	MISC. INSTALL SALVAGED FIELD CABINET (SINGLE)	10.00	2.00	\$760.00	\$1,520.00
J6Q3171E	0050	0320	9109902	MISC. INSTALL SALVAGED NON-INTRUSIVE VEHICLE D ETECTOR POLE	10.00	0.00	\$1000.00	\$0.00
J6Q3171E	0050	0330	9109902	MISC. INSTALL SOLAR POWER SYSTEM	1.00	0.00	\$1000.00	\$0.00
J6Q3171E	0050	0340	9109902	MISC. INSTALL SPREAD SPECTRUM WIRELESS COMMUNI CATION EQUIPMENT	2.00	0.00	\$125.00	\$0.00
J6Q3171E	0050	0350	9109902	MISC. INSTALL UPS AUTOMATIC GENERATOR SWITCH	10.00	0.00	\$100.00	\$0.00
J6Q3171E	0050	0360	9109902	MISC. INSTALL UPS AUTOMATIC TRANSFER SWITCH	10.00	0.00	\$100.00	\$0.00



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

Estimate I	Item Detai	I, All Item	s to Date	:				
Project Number	Category #	Line Number	Item Code	Description	Current Bid + CO	Current Installed to Date	Unit Price	Amount Paid to Date
J6Q3171E	0050	0370	9109902	MISC. INSTALL UPS BATTERY	10.00	4.00	\$100.00	\$400.00
J6Q3171E	0050	0380	9109902	MISC. INSTALL UPS BATTERY MONITOR	10.00	0.00	\$100.00	\$0.00
J6Q3171E	0050	0390	9109902	MISC. INSTALL UPS POWER INVERTER	10.00	0.00	\$200.00	\$0.00
J6Q3171E	0050	0400	9109902	MISC. INSTALL UPS SYSTEM ASSEMBLY	10.00	2.00	\$500.00	\$1,000.00
J6Q3171E	0050	0410	9109902	MISC. INSTALL WIRELESS ETHERNET BRIDGE COMMUNI CATION EQUIPMENT	8.00	6.00	\$1120.00	\$6,720.00
J6Q3171E	0050	0420	9109902	MISC. MODOT BURIED CABLE DRIVABLE DELINEATOR P OST	20.00	5.00	\$100.00	\$500.00
J6Q3171E	0050	0430	9109902	MISC. PEDESTAL BASE FOR SENSYS REPEATER POLE	1.00	0.00	\$500.00	\$0.00
J6Q3171E	0050	0440	9109902	MISC. RACK MOUNTED INTERCONNECT CENTER	5.00	0.00	\$325.00	\$0.00
J6Q3171E	0050	0450	9109902	MISC. REMOVE CAMERA POLE	1.00	0.00	\$775.00	\$0.00
J6Q3171E	0050	0460	9109902	MISC. REMOVE CCTV CAMERA and ASSEMBLY	20.00	13.00	\$430.00	\$5,590.00
J6Q3171E	0050	0470	9109902	MISC. REMOVE COMMUNICATION FIELD CABINET (DOUB LE CABINET)	1.00	0.00	\$655.00	\$0.00
J6Q3171E	0050	0480	9109902	MISC. REMOVE COMMUNICATION NODE FIELD CABINET (SINGLE CABINET)	7.00	3.00	\$355.00	\$1,065.00
J6Q3171E	0050	0490	9109902	MISC. REMOVE IN-PAVEMENT WIRELESS SENSORS	50.00	0.00	\$10.00	\$0.00
J6Q3171E	0050	0500	9109902	MISC. REMOVE NON-INTRUSIVE ACCESS POINT and AS SEMBLY	5.00	0.00	\$120.00	\$0.00
J6Q3171E	0050	0510	9109902	MISC. REMOVE NON-INTRUSIVE VEHICLE DETECTOR AS SEMBLY	20.00	5.00	\$225.00	\$1,125.00
J6Q3171E	0050	0520	9109902	MISC. REMOVE NON-INTRUSIVE VEHICLE DETECTOR PO LE	10.00	3.00	\$455.00	\$1,365.00
J6Q3171E	0050	0530	9109902	MISC. REMOVE NON-INTRUSIVE WIRELESS REPEATER	5.00	0.00	\$120.00	\$0.00
J6Q3171E	0050	0540	9109902	MISC. REMOVE SOLAR POWER SYSTEM	1.00	0.00	\$850.00	\$0.00
J6Q3171E	0050	0550	9109902	MISC. REMOVE UPS AUTOMATIC GENERATOR SWITCH	10.00	0.00	\$208.00	\$0.00
J6Q3171E	0050	0560	9109902	MISC. REMOVE UPS AUTOMATIC TRANSFER SWITCH	10.00	1.00	\$115.00	\$115.00
J6Q3171E	0050	0570	9109902	MISC. REMOVE UPS BATTERY	10.00	1.00	\$115.00	\$115.00
J6Q3171E	0050	0580	9109902	MISC. REMOVE UPS BATTERY MONITOR	1.00	0.00	\$115.00	\$0.00
J6Q3171E	0050	0590	9109902	MISC. REMOVE UPS POWER INVERTER	1.00	0.00	\$115.00	\$0.00
J6Q3171E	0050	0600	9109902	MISC. REMOVE UPS SYSTEM ASSEMBLY	10.00	1.00	\$125.00	\$125.00
J6Q3171E	0050	0610	9109902	MISC. REMOVE WIRELESS COMMUNICATION EQUIPMENT	8.00	6.00	\$335.00	\$2,010.00
J6Q3171E	0050	0620	9109902	MISC. SENSYS REPEATER POLE BASE ALUMINUM SQUAR E	1.00	0.00	\$1.00	\$0.00



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

Estimate	Item Detail	l, All Item	s to Date	:				
Project Number	Category #	Line Number	Item Code	Description	Current Bid + CO	Current Installed to Date	Unit Price	Amount Paid to Date
J6Q3171E	0050	0630	9109902	MISC. SIGNAL CABINET NETWORK COMMUNICATION and DEVICE VERIFICATION	27.00	0.00	\$250.00	\$0.00
J6Q3171E	0050	0640	9109902	MISC. TB1-17 ALUMINUM BASE FOR RTMS POLE	1.00	1.00	\$725.00	\$725.00
J6Q3171E	0050	0650	9109902	MISC. TB3-17 ALUMINUM BASE FOR RTMS POLE	1.00	0.00	\$900.00	\$0.00
J6Q3171E	0050	0660	9109902	MISC. TROUBLESHOOTING	50.00	43.00	\$200.00	\$8,600.00
J6Q3171E	0050	0670	9109903	MISC. CONDUIT, 2 IN., RIGID, PUSHED	250.00	0.00	\$8.00	\$0.00
J6Q3171E	0050	0680	9109903	MISC. CONDUIT, HIGH-DENSITY POLYETHYLENE, 2 IN ., IN TRENCH	50.00	0.00	\$10.00	\$0.00
J6Q3171E	0050	0690	9109903	MISC. CONDUIT, HIGH-DENSITY POLYETHYLENE, 2 IN ., PUSHED	300.00	0.00	\$16.00	\$0.00
J6Q3171E	0050	0700	9109903	MISC. FandI CABLE IN CONDUIT, #1/0 WIRE, VARIA BLE CONDUCTORS	500.00	0.00	\$3.50	\$0.00
J6Q3171E	0050	0710	9109903	MISC. Fandl CABLE IN CONDUIT, #14 WIRE, VARIAB LE CONDUCTORS	250.00	0.00	\$2.00	\$0.00
J6Q3171E	0050	0720	9109903	MISC. FandI CABLE IN CONDUIT, #2 WIRE, VARIABL E CONDUCTORS	100.00	0.00	\$3.25	\$0.00
J6Q3171E	0050	0730	9109903	MISC. FandI CABLE IN CONDUIT, #2/0 WIRE, VARIA BLE CONDUCTORS	100.00	0.00	\$5.40	\$0.00
J6Q3171E	0050	0740	9109903	MISC. FandI CABLE IN CONDUIT, #4 WIRE, VARIABL E CONDUCTORS	100.00	0.00	\$2.40	\$0.00
J6Q3171E	0050	0750	9109903	MISC. FandI CABLE IN CONDUIT, #6 WIRE, VARIABL E CONDUCTORS	500.00	330.00	\$1.85	\$610.50
J6Q3171E	0050	0760	9109903	MISC. FandI CABLE IN CONDUIT, #8 WIRE, VARIABL E CONDUCTORS	1,000.00	0.00	\$1.50	\$0.00
J6Q3171E	0050	0770	9109903	MISC. Fandl CABLE IN CONDUIT, VIDEO COAXIAL CA BLE	250.00	0.00	\$1.00	\$0.00
J6Q3171E	0050	0780	9109903	MISC. FandI CABLE IN CONDUIT: CAT5E OUTDOOR RA TED CABLE	1,075.00	1045.00	\$2.50	\$2,612.50
J6Q3171E	0050	0790	9109903	MISC. FandI FIBER OPTIC CABLE, 24-STRAND SINGL E MODE	10,718.00	10502.00	\$3.00	\$31,506.00
J6Q3171E	0050	0800	9109903	MISC. FandI FIBER OPTICE CABLE, 72-STRAND SING LE MODE	1,000.00	0.00	\$4.00	\$0.00
J6Q3171E	0050	0810	9109903	MISC. FandI TRACE WIRE	5,000.00	2390.00	\$1.75	\$4,182.50
J6Q3171E	0051	0820	9109902	MISC. PM AIR CONDITIONING UNITS FOR NODE CABIN ETS	64.00	28.00	\$250.00	\$7,000.00
J6Q3171E	0051	0830	9109902	MISC. PM CCTV CAMERA, ASSEMBLY, POLE, and FIEL D CABINET	636.00	316.00	\$420.00	\$132,720.00
J6Q3171E	0051	0840	9109902	MISC. PM COMMUNICATION LINK AND ASSEMBLY	323.00	22.00	\$160.00	\$3,520.00
J6Q3171E	0051	0850	9109902	MISC. PM COMMUNICATION NODE FIELD CABINET	35.00	0.00	\$520.00	\$0.00
J6Q3171E	0051	0860	9109902	MISC. PM DMP, ASSEMBLY, POLES, FOUNDATION, AND CABINET	2.00	0.00	\$330.00	\$0.00
J6Q3171E	0051	0870	9109902	MISC. PM DMS, ASSEMBLY, POLE, FOUNDATION and F IELD CABINET	169.00	159.00	\$440.00	\$69,960.00
J6Q3171E	0051	0880	9109902	MISC. PM NON-INTRUSIVE VEHICLE DETECTOR STATIO NS (BLUETOOTH)	36.00	0.00	\$200.00	\$0.00



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

Estimate	Item Detail	, All Item	s to Date	:				
Project Number	Category #	Line Number	Item Code	Description	Current Bid + CO	Current Installed to Date	Unit Price	Amount Paid to Date
J6Q3171E	0051	0890	9109902	MISC. PM NON-INTRUSIVE VEHICLE DETECTOR STATIO NS (MICROWAVE)	337.00	300.00	\$305.00	\$91,500.00
J6Q3171E	0051	0900	9109902	MISC. PM SOLAR POWER SYSTEM	20.00	10.00	\$210.00	\$2,100.00
J6Q3171E	0051	0910	9109902	MISC. PM UNINTERRUPTIBLE POWER SUPPLY (UPS) FO R NODE CABINETS	32.00	0.00	\$200.00	\$0.00
J6Q3171E	0051	0920	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED CCTV	1.00	1.00	\$520.00	\$520.00
J6Q3171E	0051	0930	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED CCTV CA BLES AND WIRES	1.00	0.00	\$610.00	\$0.00
J6Q3171E	0051	0940	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED CCTV CA MERA, ASSEMBLY, POLE, and FIELD CABINET	1.00	0.00	\$520.00	\$0.00
J6Q3171E	0051	0950	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED CCTV CO NNECTORS	1.00	0.00	\$520.00	\$0.00
J6Q3171E	0051	0960	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED CCTV DE VICE SERVER	1.00	0.00	\$520.00	\$0.00
J6Q3171E	0051	0970	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED CCTV EN CODER	1.00	0.00	\$520.00	\$0.00
J6Q3171E	0051	0980	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED CCTV PO LE ACCESS PANEL	1.00	0.00	\$600.00	\$0.00
J6Q3171E	0051	0990	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED CCTV PO WER SUPPLY	1.00	0.00	\$540.00	\$0.00
J6Q3171E	0051	1000	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED CCTV SU RGE PROTECTOR	1.00	0.00	\$610.00	\$0.00
J6Q3171E	0051	1010	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED DMP, AS SEMBLY, POLE, FOUNDATION, and FIELD CABI	1.00	0.00	\$650.00	\$0.00
J6Q3171E	0051	1020	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED DMS CON TROLLER	1.00	0.00	\$650.00	\$0.00
J6Q3171E	0051	1030	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED DMS DRI VER BOARD	1.00	0.00	\$650.00	\$0.00
J6Q3171E	0051	1040	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED DMS FAN	1.00	0.00	\$650.00	\$0.00
J6Q3171E	0051	1050	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED DMS LCA	1.00	0.00	\$650.00	\$0.00
J6Q3171E	0051	1060	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED DMS PIX EL BOARD	1.00	2.00	\$650.00	\$1,300.00
J6Q3171E	0051	1070	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED DMS POW ER SUPPLY	1.00	0.00	\$650.00	\$0.00
J6Q3171E	0051	1080	9109902	MISC. PM WITH REPAIRS - MODOT APPROVED IP ADDR ESSABLE POWER STRIP	1.00	0.00	\$650.00	\$0.00
J6Q3171E	0051	1090	9109902	MISC. PW WITH REPAIRS - MODOT SOLAR POWER SYST EM	1.00	0.00	\$650.00	\$0.00
J6Q3171E	0051	1100	9109902	MISC. REMOVE AND REPLACE NODE CABINET AIR COND ITIONER SYSTEM	4.00	4.00	\$15450.00	\$61,800.00
J6Q3171E	0050	5001	9109902	MISC. ITS	1.00	1.00	\$1782.80	\$1,782.80



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

Estimate I	tem Detail	l, All Item	s to Date	:				
Project Number	Category #	Line Number	Item Code	Description	Current Bid + CO	Current Installed to Date	Unit Price	Amount Paid to Date
J6Q3171E	0050	5002	9109902	MISC. ITS	1.00	1.00	\$193.97	\$193.97
J6Q3171E	0050	5003	9109902	MISC. ITS	1.00	1.00	\$478.10	\$478.10
J6Q3171E	0050	5004	9109902	MISC. ITS	1.00	1.00	\$6900.84	\$6,900.84
J6Q3171E	0050	5005	9109902	MISC. ITS	121.00	0.00	\$248.80	\$0.00
J6Q3171E	0050	5006	7079901	MISC. CONDUIT SYSTEM ON STRUCTURE	0.00	0.00	\$42.84	\$0.00
J6Q3171E	0050	5007	9109901	MISC. ITS	0.00	0.00	\$10602.60	\$0.00
J6Q3171E	0050	5008	9109901	MISC. ITS	0.00	0.00	\$2056.60	\$0.00
J6Q3171E	0050	5009	9109901	MISC. ITS	0.00	0.00	\$4706.98	\$0.00

The info	rmati	ion belo	w this line is	supplem	ental t	o the Estim	ate and	is pro	vided	for c	onfir	mation	of detai	l, loca	ation	and o	quantit	y of wor	k.	
Project Number	Line	Item	Item Description	Date	User ID	Description/ Information	Quantity	Units	From	+		Offset	Distance	То	+		Offset	Distance	From LM	To LM
J6Q3171E	0040	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	20190702	steink	MOMS WO 3369	2	LF	1	+	0		0		+	0		0	0	0
			Remarks																	
			Inspector Note -Repaired damag -Used 2' of 2" spli				ral Bridge -	Ref MON	1S WO 3:	369										
			CONDUIT, 2 IN., RIGID, IN TRENCH	20190710	steink	MOMS WO 3354	160	LF	1	+	0		0		+	0		0	0	0
			Remarks																	
			Inspector Note - MOMS WO 335	4 Installed 2'	' Conduit	N. Side 141 fron	n I-55 SB Ra	amp Sign	al Cabine	et to CC	CTV cro	ssing, bo	x to box.							
	0100	9109902	MISC. ITS	20190702	steink	MOMS WO 3354	6	EA	1	+	0		0		+	0		0	0	0
			MISC. ITS		steink	MOMS WO 3369	3	EA	1	+	0		0		+	0		0	0	0
			MISC. ITS		steink	MOMS WO 3391	1	EA	1	+	0		0		+	0		0	0	0
			Remarks																	



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. C
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

oject mber	Line	Item	Item Description	Date	User ID	Description/ Information	Quantity	Units	From	+		Offset	Distance	То	+		Offset	Distance	From LM	To LN
3171E	0100	9109902	Inspector Note -Investigated fibe	r damage be	tween Rte	e K and Rte 94 a	ilong I-64 - F	Ref MOM	S WO 33	91										
			MISC. ITS	20190703	steink	MOMS WO 3405	2	EA	1	+	0		0		+	0		0	0	0
			MISC. ITS		steink	MOMS WO 3391	2	EA	1	+	0		0		+	0		0	0	0
			Remarks																	
			Inspector Note -Trobleshoot and	repair fiber i	ssues on	I-64 between Rt	e K and Rte	94. Res	oliced fibe	er at IS	064E01	0.8D - Re	f MOMS WC	3391						
			MISC. ITS	20190708	steink	MOMS WO 3310	2	EA	1	+	0		0		+	0		0	0	0
			Remarks																	
			Inspector Note - MOMS WO # 3	310. STATUS	S - Restor	ed NODE 26 an	d all commu	nication	compone	nts to p	re-flood	d condition	ns.							
			MISC. ITS	20190709	steink	MOMS WO	2	EA	1	+	0		0		+	0		0	0	0
						3412														
			Remarks Inspector Note			3412														
			Remarks Inspector Note - SEE COST CO After performing the second radio cleaning of the cc - MOMS WO# 33	repairs and c repeater site orroded termi	hecking n e/o I-55 v nals did r	VO #3412 etwork status, it vas not powered eeal traces of vo	l. The appar Itage. It has	ent caus not beer	e is that tl n determir	he sola ned if t	r powe	supply w	ent uderwate	er durin	g flood	ing. No	voltage w	as present,	but some	that
			Inspector Note - SEE COST CO After performing the second radio cleaning of the co	repairs and c repeater site orroded termi	hecking n e/o I-55 v nals did r CE BROK	VO #3412 etwork status, it vas not powered eeal traces of vo	l. The appar Itage. It has	ent caus not beer	e is that tl n determir	he sola ned if t	r powe	supply w	ent uderwate	er durin	g flood	ing. No	voltage w	as present,	but some	that
			Inspector Note - SEE COST CO After performing the second radio cleaning of the co - MOMS WO# 33	repairs and c repeater site orroded termi 12 - REPLAC	hecking n e/o I-55 v nals did r CE BROK	VO #3412 etwork status, it was not powered eeal traces of vo EN PIGTAIL RT	I. The appar Itage. It has E. M @ I-55	ent caus not beer NB SIG	e is that the determine NAL CAB	he sola ned if th INET	r powe	supply w	ent uderwat fered any lor	er durin	g flood damag	ing. No le. Furth	voltage w	ras present, ation is need	but some led.	
			Inspector Note - SEE COST CO After performing the second radio cleaning of the cc - MOMS WO# 33	repairs and c repeater site proded termi 12 - REPLAC 20190712	thecking n e/o I-55 v nals did ro CE BROK	//O #3412 etwork status, it vas not powered eeal traces of vo EN PIGTAIL RT MOMS WO 3354	I. The appar itage. It has E. M @ I-55	ent caus not beer NB SIG	e is that the determine NAL CAB	he sola ned if th INET	r powe	supply w	ent uderwat fered any lor	er durin	g flood damag	ing. No le. Furth	voltage w	ras present, ation is need	but some led.	
			Inspector Note - SEE COST CO After performing the second radio cleaning of the cc - MOMS WO# 33 MISC. ITS	repairs and c repeater site proded termi 12 - REPLAC 20190712	hecking n e/o I-55 v nals did r CE BROK steink	//O #3412 etwork status, it vas not powered eeal traces of vo EN PIGTAIL RT MOMS WO 3354	I. The appar itage. It has E. M @ I-55	ent caus not beer NB SIG	e is that the determine NAL CAB	he sola ned if th INET	r powe	supply w	ent uderwat fered any lor	er durin	g flood damag	ing. No le. Furth	voltage w	ras present, ation is need	but some led.	
			Inspector Note - SEE COST CO After performing the second radio cleaning of the co - MOMS WO# 33 MISC. ITS Remarks Inspector Note - Completed splice	repairs and c repeater site proded termi 12 - REPLAC 20190712	hecking n e/o I-55 v nals did r CE BROK steink	WO #3412 etwork status, it was not powered eeal traces of vo EN PIGTAIL RT MOMS WO 3354	I. The appar Itage. It has E. M @ I-55	rent caus not beer 5 NB SIG	e is that the determination of the control of the c	he sola ned if the INET	r powerne Sun	supply w	ent uderwate fered any lor	er durin	g flood damag	ing. No ie. Furth	voltage w	as present, tion is need	but some led.	0
			Inspector Note - SEE COST CO After performing the second radio cleaning of the co - MOMS WO# 33 MISC. ITS Remarks Inspector Note - Completed splice MISC. ITS	repairs and c repeater site proded termi 12 - REPLAC 20190712 sing at 141/I-5	hecking n e/o I-55 v nals did r CE BROK steink	MO#3412 etwork status, it was not powered eeal traces of vo EN PIGTAIL RT MOMS WO 3354 sure all devices a MOMS WO 3189	I. The appar itage. It has E. M @ I-55	ent caus not beer is NB SIG	e is that the determinate of the control of the con	he sola ned if the INET	r powerne Sun	supply w	ent uderwate fered any lor	er durin	g flood damag	ing. No ie. Furth	voltage w	as present, tion is need	but some led.	0



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

ct I er	Line	Item	Item Description	Date	User ID	Description/ Information	Quantity	Units	From	+		Offset	Distance	То	+		Offset	Distance	From LM	To LI
'1E (0120	9109902	Remarks	:																
			-Repair damage	d fiber inside	231/Chris	stopher signal ca	abinet per M	OMS WO	3189											
C	0130	9109902	MISC. ITS	20190703	steink	MOMS WO 3391	26	EA	1	+	0		0		+	0		0	0	0
			Remarks																	
			Inspector Note -Trobleshoot and 24SM Fiber - (26)			I-64 between Rt	e K and Rte	94. Res	pliced fibe	er at IS	064E01	0.8D - Re	ef MOMS WO	3391						
			MISC. ITS	20190709	steink	MOMS WO 3412	1	EA	1	+	0		0		+	0		0	0	0
			Remarks																	
			After performing a determined that the voltage was presidamage. Further	he second ra ent, but some	idio repea e cleaning	ter site e/o I-55	was not pov	vered. Th	e appare	nt caus	se is tha	t the sola	r power supp	ly went	uderw	ater dur	ring floodi	ng. No		
			determined that to	he second ra ent, but some	ndio repea e cleaning needed.	ter site e/o I-55	was not pov	vered. Th	e appare	nt caus	se is tha	t the sola	r power supp	ly went	uderw	ater dur	ring floodi	ng. No	0	0
			determined that the voltage was presidamage. Further	he second ra ent, but some evaluation is	ndio repea e cleaning needed.	ter site e/o I-55 g of the corroded	was not pow I terminals d	vered. Th	e appare races of v	nt caus	se is tha	t the sola	r power supp determined	ly went	t uderw un Sav	ater dur er suffer	ring floodi	ng. No ng term	0	0
			determined that the voltage was present damage. Further	he second ra ent, but some evaluation is 20190711	adio repea e cleaning needed.	ter site e/o I-55 g of the corroded	was not pow I terminals d	vered. Th	e appare races of v	nt caus	se is tha	t the sola	r power supp determined	ly went	t uderw un Sav	ater dur er suffer	ring floodi	ng. No ng term	0	0
			determined that the voltage was present damage. Further MISC. ITS Remarks Inspector Note - MOMS WO 335	he second ra ent, but some evaluation is 20190711	dio repea e cleaning reded.	ter site e/o I-55 g of the corroded	was not pow I terminals d	vered. Th	e appare races of v	nt caus	se is tha	t the sola	r power supp determined	ly went	t uderw un Sav	ater dur er suffer	ring floodi	ng. No ng term	0	0
			determined that the voltage was present damage. Further MISC. ITS Remarks Inspector Note - MOMS WO 335 replaced from guarantee.	he second ra ent, but some evaluation is 20190711 4 ard rail dama	dio repea e cleaning reded.	MOMS WO MOMS WO	was not pow	vered. Thid reeal t	e appareraces of v	nt caus voltage	se is tha	t the sola	r power supp determined	ly went	t uderw un Sav	ater dur er suffer	ring floodi	ng. No ng term		
			determined that the voltage was present damage. Further MISC. ITS Remarks Inspector Note - MOMS WO 335 replaced from guident and the voltage was present and the voltage was present and the voltage with the voltage was present and the voltage was present	he second raent, but some evaluation is 20190711	dio repea e cleaninc r needed. steink	MOMS WO 3354	was not pow I terminals d	vered. Thid reeal t	e appareraces of v	nt caus voltage	se is tha	t the sola	r power supp determined	ly went	t uderw un Sav	ater dur er suffer	ring floodi	ng. No ng term		
			determined that the voltage was present damage. Further MISC. ITS Remarks Inspector Note - MOMS WO 335 replaced from guar MISC. ITS Remarks Inspector Note	he second raent, but some evaluation is 20190711 4 ard rail dama	dio repea e cleaning r needed. steink steink	MOMS WO 3354	was not pow I terminals d	vered. Thid reeal t	e appareraces of v	nt caus voltage	se is tha	t the sola	r power supp determined	ly went	t uderw un Sav	ater dur er suffer	ring floodi	ng. No ng term		
			determined that the voltage was present amage. Further MISC. ITS Remarks Inspector Note - MOMS WO 335 replaced from guide MISC. ITS Remarks Inspector Note - Completed splice	he second raent, but some evaluation is 20190711 4 and rail dama 20190712	dio repea e cleaning r needed. steink steink	MOMS WO 3354 MOMS WO 3354 MOMS WO 3054	was not pow I terminals d 15 20 are online.	ered. Thid reeal t	a apparer races of v	nt caus voltage	o o	t the sola	o power supplemental of the control	ly went	t uderw un Save	oter durer suffer	ring floodi	ong. No ng term	0	0
			determined that the voltage was present amage. Further MISC. ITS Remarks Inspector Note - MOMS WO 335 replaced from guar MISC. ITS Remarks Inspector Note - Completed splice MISC. ITS	he second raent, but some evaluation is 20190711 4 and rail dama 20190712 sing at 141/l-120190715	steink steink steink	MOMS WO 3354 MOMS WO 3354 MOMS WO 3354 MOMS WO 3354	was not pow I terminals d 15 20 are online.	EA EA	a appareiraces of v	nt caus voltage	o o	t the sola	o power supplemental of the control	ly went	t uderw un Save	oter durer suffer	ring floodi	ong. No ng term	0	0



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. C
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

umber	Line	Item	Item Description	Date	User ID	Description/ Information	Quantity	Units	From	+		Offset	Distance	То	+		Offset	Distance	From LM	To LN
Q3171E	0230	9109902	Remarks																	
			Inspector Note -Trobleshoot and 24SM Fiber - (4)			I-64 between Rte	e K and Rte	94. Res	oliced fibe	er at IS	6064E0	10.8D - Re	ef MOMS WC	3391						
			MISC. ITS	20190709	steink	MOMS WO 3412	1	EA	1	+	0		0		+	0		0	0	0
			Remarks																	
			the second radio cleaning of the co	repeater site orroded termi	e/o I-55 \ nals did r	was not powered eeal traces of vo	i. The appai Itage. It has	rent caus not beer	e is that t n determi	ne sola	ar powe the Sun	r supply w Saver suf	ent uderwate fered any lor	er durin ng term	g floodi damag	ing. No e. Furti	voltage w her evalua	as present, tion is need	but some led.	
			MISC. ITS	20190711	steink	MOMS WO 3354	12	EA	1	+	0		0		+	0		0	0	0
			Remarks				I											I		
			Inspector Note - MOMS WO 335 replaced from gua			MOMS WO	4	EA	1	+	0		0		+	0		0	0	0
			IVIIOC. ITO	20190712	SIGILIK	MOMS WO	4	EA							т —				1 0	- 0
						3354				·								0		
			Remarks			3354												0		
			Remarks Inspector Note - Completed splice	sing at 141/I-	55 made s	I	are online.											0		
			Inspector Note	sing at 141/I-		I	are online.	EA	1	+	0		0		+	0		0	0	0
			Inspector Note - Completed splice			sure all devices a		EA	1						+				0	0
			Inspector Note - Completed splic MISC. ITS	20190715	steink	sure all devices a MOMS WO 3189	4								+				0	0
	0300	9109902	Inspector Note - Completed splic MISC. ITS	20190715	steink	sure all devices a MOMS WO 3189	4								+				0	0
	0300	9109902	Inspector Note - Completed splic MISC. ITS Remarks -Repair damaged	20190715 d fiber inside	steink 231/Chris	MOMS WO 3189 stopher signal ca	4 abinet per M	OMS WO	3189	+	0		0			0		0		
	0300	9109902	Inspector Note - Completed splic MISC. ITS Remarks -Repair damager MISC. ITS	20190715 d fiber inside 20190708	steink 231/Chris steink	MOMS WO 3189 stopher signal ca MOMS WO 3310 ed NODE 26 and	4 binet per M	OMS WO	3189	+	0	d condition	0			0		0		



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

Project Number	Line	Item	Item Description	Date	User ID	Description/ Information	Quantity	Units	From	+		Offset	Distance	То	+		Offset	Distance	From LM	To LM
Q3171E	0400	9109902				3310														
			Remarks																	
			Inspector Note - MOMS WO #33	10 - Reinstal	led UPS f	for NODE 26														
	0420	9109902	MISC. ITS	20190710	steink	MOMS WO 3354	2	EA	1	+	0		0		+	0		0	0	0
			Remarks																	
			Inspector Note - MOMS WO 335	4 - Installed	per Kevin															
	0660	9109902	MISC. ITS	20190701	steink	MOMS WO 3369	1	EA	1	+	0		0		+	0		0	0	0
	0660		Remarks																	
			Inspector Note Investigate fiber of	conduit dama	ige - Ref I	MOMS WO 3369	9													
			MISC. ITS	20190702	steink	MOMS WO 3391	1	EA	1	+	0		0		+	0		0	0	0
			Remarks																	
			Inspector Note -Investigated fibe	r damage be	tween Rte	e K and Rte 94 a	along I-64 - I	Ref MOM	IS WO 33	91										
			MISC. ITS	20190709	steink	MOMS WO 3412	1	EA	1	+	0		0		+	0		0	0	0
			MISC. ITS		steink	MOMS WO 3416	1	EA	1	+	0		0		+	0		0	0	0
			Remarks																	
			Inspector Note - MOMS WO# 34 AND MADE NEC			PRAINING. STA	TUS - RESC	DLVED. A	AC COMF	ANY R	ESPO	NDED, DE	TERMINED	COND	ENSAT	ION DF	RAIN WAS	S BLACKED	,	
			MISC. ITS	20190710	steink	MOMS WO 3421	1	EA	1	+	0		0		+	0		0	0	0
			Remarks																	
			Inspector Note - MOMS 3421 - N repalced and unit				onded and	determin	ed that th	e evap	orator o	coil was fro	ozen and fou	ınd a le	aking s	chrader	valve. Va	llve was		
			MISC. ITS	20190715	steink	MOMS WO	1	EA	1	+	0		0		+	0		0	0	0



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

oject Imber	Line	Item	Item Description	Date	User ID	Description/ Information	Quantity	Units	From	+		Offset	Distance	То	+		Offset	Distance	From LM	To LN
3171E	0660	9109902	Remarks																	
317 IL	0000	3103302	-Repair damage	d fiher inside	231/Chris	stonher signal ca	ahinet ner M	OMS WC	3189											
				a libel liliside	201/011113	stoprici signai ce														
	0750	9109903	MISC. ITS	20190708	steink	MOMS WO 3310	330	LF	1	+	0		0		+	0		0	0	0
			Remarks	Remarks 110' #6 Black THHN																
			- 110' #6 White T - 110' #6 Bare Gr Related to MOMS	- 110' #6 White THHN - 110' #6 Bare Ground Related to MOMS WO #3310 - this was required because the foundation height was raised to prevent future flooding issues. The increased foundation height caused the existing wire to be shor t.																
	0780	9109903	MISC. ITS	20190708	steink	MOMS WO 3310	40	LF	1	+	0		0		+	0		0	0	0
			Remarks																	
			Inspector Note - MOMS WO #3310 - new cable required for UPS Communication connection.																	
	0790	9109903	MISC. ITS	20190711	steink	MOMS WO 3354	714	LF	1	+	0		0		+	0		0	0	0
			Remarks																	
				Inspector Note - MOMS WO 3354 replaced from guard rail damage																
			- MOMS WO 335		ige															
	0830	9109902	- MOMS WO 335			PM CAMERAS	9	EA	1	+	0		0		+	0		0	0	0
	0830	9109902	- MOMS WO 335 replaced from gu	ard rail dama			9	EA	1	+	0		0		+	0		0	0	0
	0830	9109902	- MOMS WO 335 replaced from guar MISC. ITS	20190712			9	EA	1	+	0		0		+	0		0	0	0
	0830	9109902	- MOMS WO 335 replaced from guident from gui	20190712	steink			EA	1	+	0		0		+	0		0	0	0



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Code
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

Project	Line	Item	Item Description	Date	User	o the Estim		_		+		1	Distance		+		-	Distance	From	To LM
Number	Lille	iteiii	item Description	Date	ID	Information	Quantity	Units	FIUIII			Onset	Distance	10			Onset	Distance	LM	TO LIVI
J6Q3171E	0830	9109902	Inspector Note MO030E023.3 Sig MO030E046.5 Sig	g pole ext (1 g pole ext (1) v1.16 M) v1.16 M	O 30 at Local Hi O 30 at Heege	llsboro (Jeff	Co)												
	0890	9109902	MISC. ITS	20190701	steink	PM RTMS	6	EA	1	+	0		0		+	0		0	0	0
			Remarks																	
			Inspector Note IS270E033.7 EIS IS270E034.5 EIS IS270W034.5 EIS IS270W033.7 EIS IS270W031.6 ISS IS270W030.3 EIS	- G4 I-270 w 6 - X3 I-270 v 6 - X3 I-270 a 6 - G4 - WB 8	v/o Riverv v/o Riverv at Lilac & EB I-270	view 0 at MO 367	AC)													
			MISC. ITS	20190702	steink	PM RTMS	6	EA	1	+	0		0		+	0		0	0	0
			Remarks Inspector Note																	
			IS270W028.6 EIS IS270W026.9 EIS IS270W025.1 EIS IS270W023.5 EIS IS270E025.1 EIS IS270S020.0 EIS	S - X3 I-270 a S - X3 I-270 a S - X3 I-270 a - X3 I-270 a	at N Hanle at US 67 at McDonr t US 67 (r	ey-Graham nell (radio conne mounted on WB	pole)		()											
			MISC. ITS	20190708	steink	PM RTMS	6	EA	1	+	0		0		+	0		0	0	0
			Inspector Note - IS270S018.1D - IS270S016.6D - IS270S015.4D - IS270S014.8D - IS270S013.6D - IS270S012.4D																	
			MISC. ITS	20190709	steink	PM RTMS	6	EA	1	+	0		0		+	0		0	0	0
			Remarks	_																



Contract ID	Estimate Number	Pay Period Start	Pay Period End	Date Generated	Estimate Type	District	Org. Co
181019-F04	0013	July 1, 2019	July 15, 2019	July 16, 2019	PROG	SL	FCJ

The info	rmati	ion belo	w this line is	supplem	ental t	o the Estim	ate and	is pro	vided	for c	onfir	mation	of detai	l, loca	ation	and o	quantit	y of wor	k.	
Project Number	Line	Item	Item Description	Date	User ID	Description/ Information	Quantity	Units	From	+		Offset	Distance	То	+		Offset	Distance	From LM	To LM
J6Q3171E	0890	9109902	- IS270S008.5D - IS270S007.6D - IS270N007.6D - IS270S007.0D																	
			MISC. ITS	20190710	steink	PM RTMS	6	EA	1	+	0		0		+	0		0	0	0
			Remarks																	
			- IS064W006.1D - IS070E218.3D - IS070E239.0D - IS270N004.7D - IS270N005.7D - IS270S005.7D																	
			MISC. ITS	20190711	steink	PM RTMS	5	EA	1	+	0		0		+	0		0	0	0
			Inspector Note - IS055N206.7D - IS055S209.0D - IS070E248.4D - IS070E250.0D - IL070E249.6D																	

Remarks in the following table are for documentation purposes:

Date User ID Remarks Text Field