

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 1, 2020

Progress Estim	Progress Estimate Number 4		190419-G03 Lehman Construction,			Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,267,148.89 \$25,018.45 \$1,292,167.34				
Approval Date							By User				
July 1, 2020		Generated and Approved (and should be considered Draft) at the Project Office Level by									
July 1, 2020		F	Reviewed and Approved	(and should be consider	ed Draft) at the	Resident Engineer Level by	capedj2				
July 2, 2020			Revi	ewed and Approved at th	e Central Office	Controllers Office Level by	greggd1				
Original Comp	Completion Date Current Completion Date Actual Completion Date % of Current Contract Amount										
October 1	October 1, 2020 October 1, 2020 36.66%										

No Milestones Exist for Contract

Contract Total Pay	y For Estimate No. 4				
		This Estimate	Previous	To Date	
190419-G03					
	Total Posted Items Pay	\$231,755.00	\$241,953.75	\$473,708.75	
	Gross Item Adjustments	(\$157,268.20)	(\$60,325.00)	(\$217,593.20)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$ <mark>181,628.75</mark>	\$256,115.55	
Contract Total Pay	yable This Estimate:	\$74,486.80			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J8S3110	0230	6181000	MOBILIZATION	LS	\$60,100.000	0.1	\$6,010.00		
	0390	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	SQYD	\$127.000	1,238	\$157,226.00		
	0410	7040101	SUBSTRUCTURE REPAIR (FORMED)	SQFT	\$102.000	59	\$6,018.00		
	0430	7040106	FULL DEPTH REPAIR	SQFT	\$159.000	21	\$3,339.00		
	0450	7040115	HYDRO SURFACE PROFILING	SQYD	\$38.000	1,240	\$47,120.00		
	0460	7040117	MONOLITHIC DECK REPAIR	CUYD	\$700.000	7.1	\$4,970.00		
	0630	7040101	SUBSTRUCTURE REPAIR (FORMED)	SQFT	\$104.000	68	\$7,072.00		
Project J8S311	\$231,755.00								
Overall - Total									

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		stments Exist on Contract						
Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J8S3110	0380	MISC.	MaterialCredit			24	\$659.00	\$15,816.00
	0380	MISC.	Material			-24	\$659.00	(\$15,816.00)
	0390	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			-1,238	\$127.00	(\$157,226.00)
	0410	SUBSTRUCTURE REPAIR (FORMED)	Overrun			-19	\$102.00	(\$1,938.00)
	0410	SUBSTRUCTURE REPAIR (FORMED)	Overrun			-7.6	\$102.00	(\$775.20)
	0430	FULL DEPTH REPAIR	Material			-21	\$159.00	(\$3,339.00)
	0460	MONOLITHIC DECK REPAIR	Material			-7.1	\$700.00	(\$4,970.00)
	0470	REINFORCING STEEL (EPOXY COATED)	MaterialCredit			3,660	\$3.00	\$10,980.00
	0470	REINFORCING STEEL (EPOXY COATED)	Material			-3,660	\$3.00	(\$10,980.00)
	0470	REINFORCING STEEL	Material		This adjustment offsets the original system-	3,660	\$3.00	\$10,980.00

Revision 4/1/2020 Page 1 of 9

(\$157,268.20)



Total

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 1, 2020

Progress Estimate Number 4 Contract ID 190419-G03 Pay Period Start June 16, 2020 Original Contract Ar Pay Period End June 30, 2020 Net Change Order A Current Contract An									1,267,148.89 25,018.45 1,292,167.34
Project Number	Line No.	Item Descr	iption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J8S3110		(EPOX	Y COATED)			generated Overrun Payment Estimate Item Adjustment (0009) due to user davisjf overridding Payment Estimate Exception 12 on the current Payment Estimate.			
	0540	STRIP SEAL E	EXPANSION NT SYSTEM	MaterialCredit			71	\$464.00	\$32,944.00
	0540	STRIP SEAL E	EXPANSION NT SYSTEM	Material			-71	\$464.00	(\$32,944.00)

Revision 4/1/2020 Page 2 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

Project Number Proj. Number Project Description Route County	Location of Work							
S3110 I Bridge 44-1(101) rehabilitation								
Totals by Job Numbers								
Posted Item Pay \$231,755.00 \$ Gross Item Adjustments (\$157,268.20) (\$	Previous \$241,953.75 (\$60,325.00) \$181,628.75	To Date \$473,708.75 (\$217,593.20) \$256,115.55						
Incentive \$0.00 \$ Disincentive \$0.00 \$	\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00						

Revision 4/1/2020 Page 3 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepancies	Explanation	Entered	Status
Exceptions / Biotropolitics	Explanation	Ву	Oldido
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 2169903, Project Item Line Number 0380, Material Set 2169903, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on Contractor to submit Material Certifications/Testing Results	davisjf	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 2169903, Project Item Line Number 0380, Material Set 2169903, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on Contractor to submit Material Certifications/Testing Results	davisjf	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 2169903, Project Item Line Number 0380, Material Set 2169903, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on Contractor to submit Material Certifications/Testing Results	davisjf	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 5052000, Project Item Line Number 0390, Material Set 505200096, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	Waiting on Contractor to submit Material Certifications/Testing Results	davisjf	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 5052000, Project Item Line Number 0390, Material Set 505200096, Material 1054CXLE - Latex Emulsion Admixture @, Acceptance Action Generic 1054CXLE is insufficient.	Waiting on Contractor to submit Material Certifications/Testing Results	davisjf	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 5052000, Project Item Line Number 0390, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Waiting on Contractor to submit Material Certifications/Testing Results	davisjf	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 7040106, Project Item Line Number 0430, Material Set 704010696, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Waiting on Contractor to submit Material Certifications/Testing Results	davisjf	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 7040106, Project Item Line Number 0430, Material Set 704010696, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	Waiting on Contractor to submit Material Certifications/Testing Results	davisjf	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 7040117, Project Item Line Number 0460, Material Set 7040117, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	Waiting on Contractor to submit Material Certifications/Testing Results	davisjf	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 7040117, Project Item Line Number 0460, Material Set 7040117, Material 1054CXLE - Latex Emulsion Admixture @, Acceptance Action Generic 1054CXLE is insufficient.	Waiting on Contractor to submit Material Certifications/Testing Results	davisjf	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 7040117, Project Item Line Number 0460, Material Set 7040117, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Waiting on Contractor to submit Material Certifications/Testing Results	davisjf	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 7101000, Project Item Line Number 0470, Material Set 710100096, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Overridden - Waiting for PAL approval.	davisjf	Overridden
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 7101000, Project Item Line Number 0470, Material Set 710100096, Material 1036RSDFEC42M19 - Rein Steel EC No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Overridden - Waiting for PAL approval.	davisjf	Overridden
Estimate Exception Type: Insufficient Materials: Project J8S3110, Item 7172001, Project Item Line Number 0540, Material Set 717200196, Material 1073JMSS - Strip Seal @, Acceptance Action Generic 1073JMSS is insufficient.	Waiting on Contractor to submit Material Certifications/Testing Results	davisjf	Acknowledged
Estimate Exception Type: Item Overrun: Contract 190419-G03, Contract Project J8S3110, Project Item Line Number 0400, Contract Line Item Number 0400, Item 7034214, Minor Item.	Will adjust quantity with change order.	davisjf	Acknowledged
Estimate Exception Type: Item Overrun: Contract 190419-G03, Contract Project J8S3110, Project Item Line Number 0410, Contract Line Item Number 0410, Item 7040101, Minor Item.	Will adjust quantity with change order.	davisjf	Acknowledged

Revision 4/1/2020 Page 4 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
90419-G03	J8S3110	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.90	\$4,400.00	\$3,960.0
		0001	0020	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	364.60	0.00	364.60	SQYD	0.00	\$9.00	\$0.0
		0001	0030	4030003	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	124.40	0.00	124.40	TONS	0.00	\$125.00	\$0.0
		0001	0040	4071005	TACK COAT	228.00	0.00	228.00	GAL	0.00	\$2.30	\$0.0
		0001	0050	5041000	CONCRETE APPROACH PAVEMENT	23.10	0.00	23.10	SQYD	0.00	\$143.00	\$0.0
		0001	0060	6083006	6 IN. CONCRETE MEDIAN STRIP	341.50	0.00	341.50	SQYD	0.00	\$56.00	\$0.0
		0001	0070	6122008	IMPACT ATTENUATOR 40 MPH (SAND BARRELS)	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.0
		0001	0080	6122020	REPLACEMENT SAND BARREL	2.00	0.00	2.00	EA	0.00	\$300.00	\$0.0
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	1.00	\$2,500.00	\$2,500.0
		0001	0100	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	341.50	0.00	341.50	SQYD	0.00	\$88.00	\$0.0
		0001	0110	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	364.60	0.00	364.60	SQYD	0.00	\$6.00	\$0.0
		0001	0120	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,227.00	0.00	1,227.00	LF	0.00	\$3.75	\$0.0
		0001	0130	6161005	CONSTRUCTION SIGNS	609.00	0.00	609.00	SQFT	500.00	\$7.00	\$3,500.0
		0001	0140	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	2.00	\$50.00	\$100.0
		0001	0150	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	2.00	\$20.00	\$40.0
		0001	0160	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	200.00	\$13.00	\$2,600.0
		0001	0170	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	38.00	0.00	38.00	EA	27.00	\$200.00	\$5,400.0
		0001	0180	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.0
		0001	0190	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	2.00	4.00	EA	4.00	\$3,500.00	\$14,000.0
		0001	0200	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	8.00	-8.00	0.00	EA	0.00	\$2,600.00	\$0.0
		0001	0210	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	150.00	350.00	500.00	LF	50.00	\$45.00	\$2,250.0
		0001	0220	6175010A	RETAINED RELOCATING TEMPORARY TRAFFIC BARRIER	50.00	0.00	50.00	LF	0.00	\$35.00	\$0.0
		0001	0230	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.30	\$60,100.00	\$18,030.0
		0001	0240	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	2,660.00	0.00	2,660.00	LF	0.00	\$1.85	\$0.
		0001	0250	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	5,801.00	0.00	5,801.00	LF	0.00	\$1.85	\$0.
		0001	0260	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	3,368.00	0.00	3,368.00	LF	0.00	\$0.35	\$0.
		0001	0270	6205903A	PAINT, TYPE L BEADS 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	3,966.00	0.00	3,966.00	LF	0.00	\$0.35	\$0.0
					MARKING PAINT, TYPE L BEADS							
		0001	0280	6207001	PAVEMENT MARKING REMOVAL	2,185.00	0.00	2,185.00	LF	385.00	\$1.00	\$385.0
		0001	0290	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,528.30	0.00	1,528.30	SQYD	678.00	\$7.95	\$5,390.
		0001	0300	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$7,500.00	\$0.0
		0001	0310	8061007A	CURB INLET CHECK	9.00	0.00	9.00	EA	5.00	\$275.00	\$1,375.
		0001	0320	8061016	SEDIMENT REMOVAL	0.90	0.00	0.90	CUYD	0.00	\$223.00	\$0.0
		0070	0330	2161000	SCARIFICATION OF BRIDGE DECK	1,240.00	0.00	1,240.00	SQYD	1,240.00	\$8.50	\$10,540.0
		0070	0340	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	142.00	0.00	142.00	SQFT	142.00	\$57.00	\$8,094.0
		0070	0350	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	71.00	0.00	71.00	LF	71.00	\$212.00	\$15,052.0
		0070	0360	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	39.00	0.00	39.00	LF	39.00	\$76.00	\$2,964.
		0070	0370	2169902	MISC.REMOVAL OF EXISTING BEARINGS	5.00	0.00	5.00	EA	5.00	\$800.00	\$4,000.0
		0070	0380	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	24.00	0.00	24.00	LF	24.00	\$659.00	\$15,816.0
		0070	0390	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,238.00	0.00	1,238.00	SQYD	1,238.00	\$127.00	\$157,226.0
		0070	0400	7034214	CLASS B-2 CONCRETE	26.00	0.00	26.00	CUYD	26.50	\$1,170.00	\$31,005.0
		0070	0410	7040101	SUBSTRUCTURE REPAIR (FORMED)	155.00	0.00	155.00	SQFT	181.60	\$102.00	\$18,523.
		0070	0420	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	75.00	0.00	75.00	SQFT	0.00	\$114.00	\$0.0
		0070	0430	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	21.00	\$159.00	\$3,339.0
		0070	0440	7040113	CLEAN AND EPOXY SEAL	862.00	0.00	862.00	SQFT	0.00	\$9.00	\$0.0

Revision 4/1/2020 Page 5 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract LCONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
)419-G03	J8S3110	0070	0450	7040115	HYDRO SURFACE PROFILING	1,240.00	0.00	1,240.00	SQYD	1,240.00	\$38.00	\$47,120.0
		0070	0460	7040117	MONOLITHIC DECK REPAIR	8.00	0.00	8.00	CUYD	7.10	\$700.00	\$4,970.0
		0070	0470	7101000	REINFORCING STEEL (EPOXY COATED)	3,660.00	0.00	3,660.00	LB	3,660.00	\$3.00	\$10,980.0
		0070	0480	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$8,500.00	\$0.0
		0070	0490	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	2,200.00	0.00	2,200.00	SQFT	0.00	\$46.75	\$0.0
		0070	0500	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	2,200.00	0.00	2,200.00	SQFT	0.00	\$2.75	\$0.0
		0070	0510	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	2,200.00	0.00	2,200.00	SQFT	0.00	\$1.75	\$0.0
		0070	0520	7125370A	FINISH FIELD COAT (SYSTEM G)	2,200.00	0.00	2,200.00	SQFT	0.00	\$1.75	\$0.0
		0070	0530	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	5.00	0.00	5.00	EA	5.00	\$3,035.00	\$15,175.0
		0070	0540	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	71.00	0.00	71.00	LF	71.00	\$464.00	\$32,944.0
		0070	0550	7172054	OPEN CELL FOAM JOINT SEAL	77.00	0.00	77.00	LF	0.00	\$71.00	\$0.0
		0071	0560	2161000	SCARIFICATION OF BRIDGE DECK	1,447.00	0.00	1,447.00	SQYD	0.00	\$8.50	\$0.0
		0071	0570	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	142.00	0.00	142.00	SQFT	0.00	\$54.00	\$0.0
		0071	0580	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	71.00	0.00	71.00	LF	0.00	\$212.00	\$0.0
		0071	0590	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	350.00	0.00	350.00	LF	0.00	\$76.00	\$0.
		0071	0600	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	13.00	0.00	13.00	LF	0.00	\$686.00	\$0.
		0071	0610	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,445.00	0.00	1,445.00	SQYD	0.00	\$119.00	\$0.
		0071	0620	7034214	CLASS B-2 CONCRETE	27.50	0.00	27.50	CUYD	0.00	\$1,110.00	\$0.
		0071	0630	7040101	SUBSTRUCTURE REPAIR (FORMED)	185.00	0.00	185.00	SQFT	160.00	\$104.00	\$16,640
		0071	0640	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	45.00	0.00	45.00	SQFT	0.00	\$116.00	\$0.
		0071	0650	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$159.00	\$0.
		0071	0660	7040113	CLEAN AND EPOXY SEAL	862.00	0.00	862.00	SQFT	0.00	\$9.00	\$0
		0071	0670	7040115	HYDRO SURFACE PROFILING	1,447.00	0.00	1,447.00	SQYD	0.00	\$41.00	\$0
		0071	0680	7040117	MONOLITHIC DECK REPAIR	8.00	0.00	8.00	CUYD	0.00	\$700.00	\$0
		0071	0690	7101000	REINFORCING STEEL (EPOXY COATED)	3,980.00	0.00	3,980.00	LB	0.00	\$3.00	\$0
		0071	0700	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$6,000.00	\$0.
		0071	0710	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	900.00	0.00	900.00	SQFT	0.00	\$46.75	\$0
		0071	0720	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	900.00	0.00	900.00	SQFT	0.00	\$2.75	\$0
		0071	0730	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	900.00	0.00	900.00	SQFT	0.00	\$1.75	\$0
		0071	0740	7125370A	FINISH FIELD COAT (SYSTEM G)	900.00	0.00	900.00	SQFT	0.00	\$1.75	\$0
		0071	0750	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	71.00	0.00	71.00	LF	0.00	\$464.00	\$0
		0071	0760	7172054	OPEN CELL FOAM JOINT SEAL	399.00	0.00	399.00	LF	0.00	\$61.00	\$0
		0001	5001	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	0.00	8.00	8.00	EA	8.00	\$1,350.00	\$10,800
		0001	5002	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0.00	2,660.00	2,660.00	LF	1,366.00	\$1.45	\$1,980
		0001	5003	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0.00	5,801.00	5,801.00	LF	3,455.00	\$1.45	\$5,009
	Project J	8S3110 - To	otal Value	Posted to D	ate as of Report Generated Date							\$473,708
19-G03 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$473,708

Revision 4/1/2020 Page 6 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J8S3110

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0230	6181000	MOBILIZATION	6/30/20	7/1/20	0.10	LS	Bridge A02805					
0390	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	6/25/20	7/1/20	1,238.00	SQYD	Bridge A02805					
0410	7040101	SUBSTRUCTURE REPAIR (FORMED)	6/16/20	6/23/20	19.00	SQFT	Bent5 North pier					
			6/17/20	6/23/20	40.00	SQFT	Bent5 North Pier					
0430	7040106	FULL DEPTH REPAIR	6/25/20	7/1/20	21.00	SQFT	Bridge A02805 at Joint 6 under outside parapet.					
0450	7040115	HYDRO SURFACE PROFILING	6/18/20	6/23/20	1,240.00	SQYD	West Bound Bridge					
0460	7040117	MONOLITHIC DECK REPAIR	6/25/20	7/1/20	7.10	CUYD	Bridge A02805					
0630	7040101	SUBSTRUCTURE REPAIR (FORMED)	6/16/20	6/23/20	68.00	SQFT	Bent5 north side of cap					

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 7 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	2-2-1-	Туре	Adjustment Type	Number	Date	Ву		
0190	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED,	Overrun	Overrun	1	May 18, 2020	SYSTEM	(\$7,000.00)	
	CONTRACTOR RETAINED			2	Jun 2, 2020	SYSTEM	\$7,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3500.00000 - 3500.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0190 -	Total						\$0.00	
0380	MISC. REMOVE AND REPLACE BARRIER CURB	Material		3	Jun 15, 2020	SYSTEM	(\$15,816.00)	
				4	Jul 1, 2020	SYSTEM	(\$15,816.00)	
			- Total				(\$31,632.00)	
	Material - Total						(\$31,632.00)	
	MISC. REMOVE AND REPLACE BARRIER CURB	MaterialCredit		4	Jul 1, 2020	SYSTEM	\$15,816.00	
			- Total				\$15,816.00	
	MaterialCredit - Total						\$15,816.00	
0380 -							(\$15,816.00)	
0390	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		4	Jul 1, 2020	SYSTEM	(\$157,226.00)	
			- Total				(\$157,226.00)	
	Material - Total						(\$157,226.00)	
0390 -							(\$157,226.00)	
0400	CLASS B-2 CONCRETE	Material		2	Jun 2, 2020	SYSTEM	(\$6,435.00)	
			- Total				(\$6,435.00)	
	Material - Total						(\$6,435.00)	
	CLASS B-2 CONCRETE	MaterialCredit	Total	3	Jun 15, 2020	SYSTEM	\$6,435.00	
	Make dia 10 media - Texasi		- Total				\$6,435.00	
	MaterialCredit - Total		0		1 45	OVOTEN	\$6,435.00	
	CLASS B-2 CONCRETE	Overrun	Overrun - To		Jun 15, 2020	SYSTEM	(\$585.00)	
	Overrun - Total		Overruit - 1	Otai			(\$585.00) (\$585.00)	
0400 -								
0410	SUBSTRUCTURE REPAIR (FORMED)	Overrun	Overrun	4	Jul 1, 2020	SYSTEM	(\$585.00) (\$2,713.20)	
			Overrun - To	otal			(\$2,713.20)	
	Overrun - Total						(\$2,713.20)	
0410 -	Total						(\$2,713.20)	
0430	FULL DEPTH REPAIR	Material		4	Jul 1, 2020	SYSTEM	(\$3,339.00)	
			- Total				(\$3,339.00)	
	Material - Total						(\$3,339.00)	
0430 -	Total						(\$3,339.00)	
0460	MONOLITHIC DECK REPAIR	Material		4	Jul 1, 2020	SYSTEM	(\$4,970.00)	
			- Total				(\$4,970.00)	
	Material - Total						(\$4,970.00)	
0460 -	Total						(\$4,970.00)	
0470	REINFORCING STEEL (EPOXY COATED)	Material		2	Jun 2, 2020	SYSTEM	(\$2,640.00)	
				3	Jun 15, 2020	SYSTEM	(\$10,980.00)	
				4	Jul 1, 2020	SYSTEM	(\$10,980.00)	

Revision 4/1/2020 Page 8 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment	Other	Est. Number	Created Date	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0470	REINFORCING STEEL (EPOXY COATED)	Material		4	Jul 1, 2020	SYSTEM	\$10,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user davisjf overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				(\$13,620.00)	
	Material - Total						(\$13,620.00)	
	REINFORCING STEEL (EPOXY COATED)	MaterialCredit		3	Jun 15, 2020	SYSTEM	\$2,640.00	
				4	Jul 1, 2020	SYSTEM	\$10,980.00	
			- Total				\$13,620.00	
	MaterialCredit - Total						\$13,620.00	
0470 -	Total						\$0.00	
0540	STRIP SEAL EXPANSION JOINT SYSTEM	Material		2	Jun 2, 2020	SYSTEM	(\$16,472.00)	
				3	Jun 15, 2020	SYSTEM	(\$32,944.00)	
				4	Jul 1, 2020	SYSTEM	(\$32,944.00)	
			- Total				(\$82,360.00)	
	Material - Total						(\$82,360.00)	
	STRIP SEAL EXPANSION JOINT SYSTEM	MaterialCredit		3	Jun 15, 2020	SYSTEM	\$16,472.00	
				4	Jul 1, 2020	SYSTEM	\$32,944.00	
			- Total				\$49,416.00	
	MaterialCredit - Total						\$49,416.00	
0540 -	Total						(\$32,944.00)	
Overa	II - Total						(\$217,593.20)	

Revision 4/1/2020 Page 9 of 9