

Pay Estimate Created Date: August 17, 2020

Progress Estimate Number 23		Contract ID 190517-F06 Prime Contractor N.B. West Contraction		just 2, 2020 Original Contract Amoun just 15, 2020 Net Change Order Amoun Current Contract Amoun	nt \$49,140.03			
Approval Date					By User			
August 18, 2020		Generated and Approved (and should be considered Draft) at the Project Office Level by						
August 18, 2020		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by						
August 18, 2020		Reviewed and Approved at the Central Office Controllers Office Level by						
Original Completion Date		Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete				
November 1, 2020 November 1, 2020				95.13%				

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 23									
		This Estimate	Previous	To Date					
190517-F06									
	Total Posted Items Pay	\$553,825.80	\$4,090,365.08	\$4,644,190.88					
	Gross Item Adjustments	(\$64,412.51)	(\$140,302.53)	(\$204,715.04)					
	Incentive	\$0.00	\$0.00	\$0.00					
	Disincentive	\$0.00	\$0.00	\$0.00					
	Liquidated Damage	\$0.00	\$0.00	\$0.00					
	Other Contract Adjustments	\$69,957.30	\$0.00	\$69,957.30					
			\$3,950,062.55	\$4,509,433.14					
Contract Total Pa	ayable This Estimate:	\$559,370.59							

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J6S3196	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$448,000.000	0.5	\$224,000.00	
	0150	6081000	CONCRETE MEDIAN	SQYD	\$52.000	3,996	\$207,792.00	
	0160	6081012	TRUNCATED DOMES	SQFT	\$30.000	101	\$3,030.00	
	0390	6169901	MISC.TEMPORARY TRAFFIC CONTROL	LS	\$56,000.000	0.2	\$11,200.00	
	0460	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$25.000	631	\$15,775.00	
	0470	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	LF	\$25.000	117	\$2,925.00	
	0480	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$350.000	31	\$10,850.00	
	0490	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	EA	\$350.000	16	\$5,600.00	
	0510	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.200	36,677	\$7,335.40	
	0520	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.500	47,289	\$23,644.50	
	0530	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.500	4,775	\$2,387.50	
	0540	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION(LEFT)	EA	\$2,000.000	5	\$10,000.00	
	0550	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, UTURN ARROW (LEFT)	EA	\$1,500.000	2	\$3,000.00	
	0560	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, UTURN ONLY WORD	EA	\$1,500.000	1	\$1,500.00	
	0600	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$61,966.000	0.4	\$24,786.40	
Project J6S3196 - Total								
Overall - To	otal						\$553,825.80	

Contract Adjustments This Estimate

Adj Type	Entered By	Comments	Time Units	Rate	Amount
SPADOther Contract Adjustment		JOB NUMBER: J6S3196 LINE NUMBER: 0090 2 INCHES, ASPH. CONC. PAVEMENT SP125B			\$38,054.16
		Pay factor SP125B (76-22)			

Revision 4/1/2020 Page 1 of 31



Pay Estimate Created Date: August 17, 2020

Progress Estimate Number	Contract ID	190517-F06	Pay Period Start	August 2, 2020	Original Contract Amount	\$4,832,794.40
23	Prime Contractor	N.B. West Contracting Company	Pay Period End	August 15, 2020		
20					Current Contract Amount	\$4,881,934.43

Adj Type	Entered By	Comments	Time Units	Rate	Amount
		Lot 1 = 101.8% or \$6,984.00 bonus Pay factor SP125B (76-22) Lot 2 = 104.6% or \$31,070.16 bonus			
SPADOther Contract Adjustment	clowez1	JOB NUMBER: J6S3196 LINE NUMBER: 0090 2 INCHES, ASPH. CONC. PAVEMENT SP125B SP125B (76-22) LOTS 1 & 2 TSR Bonus Lot 1 = 103% or \$29,100.00 TSR Bonus Lot 2 = 103% or \$2,803.14			\$31,903.14

Overall - Total

\$69,957.30

ne nem	Aujusti	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
6S3196	0080	TYPE A2 SHOULDER	Material			-1,873	\$45.00	(\$84,285.00
	0080	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	1,873	\$45.00	\$84,285.00
	0090	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Material			-10,949	\$97.00	(\$1,062,053.00
	0090	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	10,949	\$97.00	\$1,062,053.00
	0090	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Other Item Adjustment	Smoothness Adjustment Asphalt Bonus	IRI Smoothness bonus Rt. H Southbound and Northbound.			\$6,314.89
	0150	CONCRETE MEDIAN	Overrun			-196	\$52.00	(\$10,192.00
	0150	CONCRETE MEDIAN	Material			-6,661	\$52.00	(\$346,372.00
	0150	CONCRETE MEDIAN	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 52 on the current Payment Estimate.	196	\$52.00	\$10,192.00
	0150	CONCRETE MEDIAN	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	6,661	\$52.00	\$346,372.00
	0160	TRUNCATED DOMES	Overrun			-57	\$30.00	(\$1,710.00
	0170	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-478	\$15.00	(\$7,170.00
	0170	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Material			-17,053	\$15.00	(\$255,795.00
	0170	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 54 on the current Payment Estimate.	478	\$15.00	\$7,170.00

Page 2 of 31 Revision 4/1/2020



Pay Estimate Created Date: August 17, 2020

Progress Estimate Number
23

Contract ID 190517-F06 Pay Period Start August 2, 2020 Original Contract Amount \$4,832,794.40 Prime Contractor N.B. West Contracting Company Pay Period End August 15, 2020 Original Contract Amount \$49,140.03 Current Contract Amount \$4,881,934.43

Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.
\$255,795.00	\$15.00	17,053	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user clowez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		Material	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	0170
(\$62,468.00	\$46.00	-1,358			Material	CONCRETE GUTTER TYPE A	0180
\$62,468.00	\$46.00	1,358	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user clowez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		Material	CONCRETE GUTTER TYPE A	0180
(\$13,692.00	\$42.00	-326			Material	CONCRETE GUTTER TYPE B	0190
\$13,692.00	\$42.00	326	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user clowez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.		Material	CONCRETE GUTTER TYPE B	0190
(\$4,890.00	\$30.00	-163			Material	CURB AND GUTTER TYPE B	0200
\$4,890.00	\$30.00	163	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		Material	CURB AND GUTTER TYPE B	0200
(\$1,650.00	\$25.00	-66			Material	INTEGRAL CURB TYPE N	0210
\$1,650.00	\$25.00	66	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user clowez1 overridding Payment Estimate Exception 23 on the current Payment Estimate.		Material	INTEGRAL CURB TYPE N	0210
(\$1,200.00	\$40.00	-30	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		Overrun	FURNISHING TYPE 2 ROCK DITCH LINER	0220
\$2,600.00	\$40.00	65			MaterialCredit	FURNISHING TYPE 2 ROCK DITCH LINER	0220
(\$2,600.00	\$40.00	-65			Material	FURNISHING TYPE 2 ROCK DITCH LINER	0220
\$1,200.00	\$40.00	30	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 55 on the current Payment Estimate.		Overrun	FURNISHING TYPE 2 ROCK DITCH LINER	0220
(\$15,132.00	\$26.00	-582			Material	MISC.	0240
\$15,132.00	\$26.00	582	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 30 on the current Payment Estimate.		Material	MISC.	0240
(\$780.00	\$30.00	-26			Material	MISC.	0250
\$780.00	\$30.00	26	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0016) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		Material	MISC.	0250
(\$900.00	\$30.00	-30			Material	MISC.	0260
\$900.00	\$30.00	30	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0017) due to user clowez1 overridding Payment Estimate Exception 26 on the current Payment Estimate.		Material	MISC.	0260

Revision 4/1/2020 Page 3 of 31



Pay Estimate Created Date: August 17, 2020

Progress Estimate Number
23

Contract ID 190517-F06 Pay Period Start August 2, 2020 Original Contract Amount \$4,832,794.40 Pay Period End August 15, 2020 Original Contract Amount \$49,140.03 Current Contract Amount \$49,140.03 Current Contract Amount \$4,881,934.43

					C	\$4,881,934.43		
ct er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
96	0310	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-794	\$110.00	(\$87,340.00
	0310	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0018) due to user clowez1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	794	\$110.00	\$87,340.00
	0320	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-143	\$0.01	(\$1.43
	0320	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0019) due to user clowez1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	143	\$0.01	\$1.43
	0330	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material			-1,174	\$0.01	(\$11.74
	0330	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0020) due to user clowez1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	1,174	\$0.01	\$11.74
	0390	MISC.	MaterialCredit			0.25	\$56,000.00	\$14,000.00
	0460	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-631	\$25.00	(\$15,775.00
	0470	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material			-117	\$25.00	(\$2,925.00
	0480	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-31	\$350.00	(\$10,850.00
	0490	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material			-16	\$350.00	(\$5,600.00
	0510	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-36,677	\$0.20	(\$7,335.40
	0520	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-47,289	\$0.50	(\$23,644.50
	0530	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-4,775	\$0.50	(\$2,387.50
	0540	MISC.	Material			-5	\$2,000.00	(\$10,000.00
	0550	MISC.	Material			-2	\$1,500.00	(\$3,000.00
	0560	MISC.	Material			-1	\$1,500.00	(\$1,500.00

Revision 4/1/2020 Page 4 of 31



						Contract Project Information	1
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6S3196	FAS S501(24)	Resurface	Н	ST LOUIS CITY	from Hall Street to North of	I-270 Interchange	
Γotals by J	Job Numbe	rs					
J6S3196					This Estimate	Previous	To Date
		d Item Pay Item Adjustm	ents		\$553,825.80 (\$64,412.51)	\$4,090,365.08 (\$140,302.53)	\$4,644,190.88 (\$204,715.04)
			Gross	Item Pay	\$489,413.29	\$3,950,062.55	\$4,439,475.84
	Incent	tive			\$0.00	\$0.00	\$0.00
		entive			\$0.00	\$0.00	\$0.00
		lated Damages			\$0.00	\$0.00	\$0.00
	Other	Contract Adju	stments		\$69,957.30	\$0.00	\$69,957.30

Revision 4/1/2020 Page 5 of 31



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period		1	
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0250, Material Set 0501CCBA, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QC/QA Test	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0250, Material Set 0501CCB.A, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QC/QA Test	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0250, Material Set 0501CCBA, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Awaiting successful PAL submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0250, Material Set 0501CCBA, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Awaiting successful PAL submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 4010150, Project Item Line Number 0080, Material Set 401015096, Material 1007RCBT1T5 - Agg Base T1/T5 Reclaimed Concrete, Acceptance Action Generic 1007RCBT1T5 is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 4010150, Project Item Line Number 0080, Material Set 401015096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 4010150, Project Item Line Number 0080, Material Set 401015096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 4030116, Project Item Line Number 0090, Material Set 403011696, Material 0403SP125B - Superpave 12.5 mm, Des B, Acceptance Action Generic AspHigh is insufficient.	Awaiting QA/QC Testing submissions	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6081000, Project Item Line Number 0150, Material Set 608100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC test submission.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6081000, Project Item Line Number 0150, Material Set 608100096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC test submission.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091011, Project Item Line Number 0170, Material Set 609101196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091011, Project Item Line Number 0170, Material Set 609101196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091041, Project Item Line Number 0180, Material Set 609104196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QC/QA Test	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091041, Project Item Line Number 0180, Material Set 609104196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091041, Project Item Line Number 0180, Material Set 609104196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Awaiting successful PAL submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091041, Project Item Line Number 0180, Material Set 609104196, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Awaiting successful PAL submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091042, Project Item Line Number 0190, Material Set 609104296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QC/QA test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091042, Project Item Line Number 0190, Material Set 609104296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091042, Project Item Line Number 0190, Material Set 609104296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Awaiting successful PAL submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091042, Project Item Line Number 0190, Material Set 609104296, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Awaiting successful PAL submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091052, Project Item Line Number 0200, Material Set 609105296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091052, Project Item Line Number 0200, Material Set 609105296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6092014, Project Item Line Number 0210, Material Set 609201496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QC/QA Test.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6092014, Project Item Line Number 0210, Material Set 609201496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO,	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden

Revision 4/1/2020 Page 6 of 31



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 100510CPCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6096020, Project Item Line Number 0220, Material Set 609602096, Material 0609PDDL - Paved Drainage Material for Ditch Liner, Acceptance Action Generic PipeDrainageMisc is insufficient.	Awaiting PAL form and visual inspection tests	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0260, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QC/QA test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0260, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QC/QA test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0260, Material Set 6099903, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Awaiting successful PAL submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0260, Material Set 6099903, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Awaiting successful PAL submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0240, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC test.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0240, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC test.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6131010, Project Item Line Number 0310, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6131010, Project Item Line Number 0310, Material Set 613101096, Material 100510OPTLD1 - PCCP 1" Max LS/DO, Acceptance Action Generic 100510OPTLD1 is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6131012, Project Item Line Number 0320, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Awaiting successful QC test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6131013, Project Item Line Number 0330, Material Set 613101396, Material 1007RCBT1T5 - Agg Base T1/T5 Reclaimed Concrete, Acceptance Action Generic 1007RCBT1T5 is insufficient.	Awaiting successful QC test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6200015, Project Item Line Number 0460, Material Set 6200015, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Awaiting certification submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6200018, Project Item Line Number 0470, Material Set 620001896, Material 1048PMPFYL - Performed Thermoplastic Marking Tape YL, Acceptance Action Generic 1048PMPFYL is insufficient.	Awaiting certification submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6200021, Project Item Line Number 0480, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indicat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Awaiting certification submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6200036, Project Item Line Number 0490, Material Set 620003696, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Awaiting certification submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6205901A, Project Item Line Number 0510, Material Set 6205901A96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Awaiting pavement marking performance test submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6205901A, Project Item Line Number 0510, Material Set 6205901A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Awaiting certification submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6205901A, Project Item Line Number 0510, Material Set 6205901A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Awaiting certification submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6205902A, Project Item Line Number 0520, Material Set 6205902A96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Awaiting pavement marking performance test submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6205902A, Project Item Line Number 0520, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Awaiting certification submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6205902A, Project Item Line Number 0520, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Awaiting certification submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6205903A, Project Item Line Number 0530, Material Set 6205903A96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Awaiting pavement marking performance test submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6205903A, Project Item Line Number 0530, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Awaiting certification submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6205903A, Project Item Line	Awaiting certification submission.	clowez1	Acknowledged

Revision 4/1/2020 Page 7 of 31



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Number 0530, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6209902, Project Item Line Number 0540, Material Set 6209902, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Awaiting certification submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6209902, Project Item Line Number 0560, Material Set 6209902, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Awaiting certification submission.	clowez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6209902, Project Item Line Number 0550, Material Set 6209902, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Awaiting certification submission.	clowez1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 190517-F06, Contract Project J6S3196, Project Item Line Number 0150, Contract Line Item Number 0150, Item 6081000, Minor Item.	System Generated Override	clowez1	Overridden
Estimate Exception Type: Item Overrun: Contract 190517-F06, Contract Project J6S3196, Project Item Line Number 0160, Contract Line Item Number 0160, Item 6081012, Minor Item.	Awaiting change order.	clowez1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 190517-F06, Contract Project J6S3196, Project Item Line Number 0170, Contract Line Item Number 0170, Item 6091011, Minor Item.	System Generated Override	clowez1	Overridden
Estimate Exception Type: Item Overrun: Contract 190517-F06, Contract Project J6S3196, Project Item Line Number 0220, Contract Line Item Number 0220, Item 6096020, Minor Item.	System Generated Override	clowez1	Overridden
Estimate Exception Type: Item Overrun: Contract 190517-F06, Contract Project J6S3196, Project Item Line Number 0230, Contract Line Item Number 0230, Item 6096042, Minor Item.	Awaiting change order.	clowez1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 190517-F06, Contract Project J6S3196, Project Item Line Number 0570, Contract Line Item Number 0570, Item 6221001, Minor Item.	Awaiting change order	clowez1	Acknowledged

Revision 4/1/2020 Page 8 of 31



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190517-F06	J6S3196	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$448,000.00	\$448,000.00
		0001	0020	2063000	CLASS 3 EXCAVATION	10,653.00	0.00	10,653.00	CUYD	10,653.00	\$0.01	\$106.53
		0001	0030	2063300	CLASS 4 EXCAVATION	588.00	0.00	588.00	CUYD	531.00	\$40.00	\$21,240.00
		0001	0040	2063500	CULVERT CLEANOUT	82.00	0.00	82.00	EA	47.00	\$300.00	\$14,100.00
		0001	0050	2072000	LINEAR GRADING CLASS 2	136.00	0.00	136.00	STA	121.00	\$600.00	\$72,600.00
		0001	0060	2142000	FURNISHING ROCK FILL	42.00	0.00	42.00	CUYD	0.00	\$40.00	\$0.00
		0001	0070	2143000	PLACING ROCK FILL	42.00	0.00	42.00	CUYD	0.00	\$40.00	\$0.00
		0001	0800	4010150	TYPE A2 SHOULDER	2,264.00	0.00	2,264.00	SQYD	2,264.00	\$45.00	\$101,880.00
		0001	0090	4030116	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	11,654.80	0.00	11,654.80	TONS	10,949.00	\$97.00	\$1,062,053.00
		0001	0100	4039905	MISC.OPTIONAL PAVEMENT	938.00	0.00	938.00	SQYD	902.00	\$62.00	\$55,924.00
		0001	0110	4079912	MISC.POLYMER MODIFIED EMULSION MEMBRANE	21,381.00	0.00	21,381.00	GAL	18,939.00	\$2.50	\$47,347.50
		0001	0120	6044011	PIPE COLLAR, TYPE A	2.00	0.00	2.00	EA	0.00	\$2,000.00	\$0.00
		0001	0130	6049902	MISC.ADJUSTING MANHOLES, VALVES AND PULL BOXES	17.00	0.00	17.00	EA	0.00	\$350.00	\$0.00
		0001	0140	6049902	MISC.INLET TOP REPLACEMENT	20.00	0.00	20.00	EA	0.00	\$800.00	\$0.00
		0001	0150	6081000	CONCRETE MEDIAN	6,465.00	0.00	6,465.00	SQYD	6,661.00	\$52.00	\$346,372.00
		0001	0160	6081012	TRUNCATED DOMES	64.00	0.00	64.00	SQFT	121.00	\$30.00	\$3,630.00
		0001	0170	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	16,575.00	0.00	16,575.00	LF	17,053.00	\$15.00	\$255,795.00
		0001	0180	6091041	CONCRETE GUTTER TYPE A	1,358.00	0.00	1,358.00	LF	1,358.00	\$46.00	\$62,468.00
		0001	0190	6091042	CONCRETE GUTTER TYPE B	326.00	0.00	326.00	LF	326.00	\$42.00	\$13,692.00
		0001	0200	6091052	CURB AND GUTTER TYPE B	178.00	0.00	178.00	LF	163.00	\$30.00	\$4,890.00
		0001	0210	6092014	INTEGRAL CURB TYPE N	76.00	0.00	76.00	LF	66.00	\$25.00	\$1,650.00
		0001	0220	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	35.00	0.00	35.00	CUYD	65.00	\$40.00	\$2,600.00
		0001	0230	6096042	PLACING TYPE 2 ROCK DITCH LINER	35.00	0.00	35.00	CUYD	65.00	\$80.00	\$5,200.00
		0001	0240	6099903	MISC.MODIFIED 4 IN. CURB AND GUTTER, TYPE A	660.00	0.00	660.00	LF	582.00	\$26.00	\$15,132.00
		0001	0250	6099903	MISC.TRANSITION TYPE A TO TYPE B GUTTER	26.00	0.00	26.00	LF	26.00	\$30.00	\$780.00
		0001	0260	6099903	MISC.TRANSITION TYPE B TO TYPE A GUTTER	30.00	0.00	30.00	LF	30.00	\$30.00	\$900.00
		0001	0270	6116010A	SLOPE PROTECTION	52.00	0.00	52.00	SQYD	0.00	\$120.00	\$0.00
		0001	0280	6122009	IMPACT ATTENUATOR 45 MPH (SAND BARRELS)	1.00	0.00	1.00	EA	0.00	\$1,500.00	\$0.00
		0001	0290	6122020	REPLACEMENT SAND BARREL	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0001	0300	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.00
		0001	0310	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	1,434.00	0.00	1,434.00	SQYD	794.00	\$110.00	\$87,340.00
		0001	0320	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	143.00	0.00	143.00	SQYD	143.00	\$0.01	\$1.43
		0001	0330	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	1,174.00	0.00	1,174.00	SQYD	1,174.00	\$0.01	\$11.74
		0001	0340	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	2,378.00	0.00	2,378.00	LF	1,950.00	\$6.00	\$11,700.00
		0001	0350	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,680.00	0.00	1,680.00	EA	1,674.00	\$6.00	\$10,044.00
		0001	0360	6149902	MISC.MSD MANHOLE PRECAST 48 IN.	14.00	0.00	14.00	EA	14.00	\$3,000.00	\$42,000.00
		0001	0370	6149902	MISC.MSD MANHOLE PRECAST 60 IN.	1.00	0.00	1.00	EA	1.00	\$4,500.00	\$4,500.00
		0001	0380	6149902	MISC.MSD STANDARD MANHOLE FRAME AND COVER	15.00	0.00	15.00	EA	15.00	\$400.00	\$6,000.00
		0001	0390	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.95	\$56,000.00	\$53,200.00
		0001	0400	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN CONTRACTOR FURNISHED/RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0001	0410	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,000.00	0.00	1,000.00	LF	0.00	\$5.00	\$0.00
		0001	0420	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	9,000.00	0.00	9,000.00	LF	0.00	\$1.00	\$0.00
		0001	0430	6179903	MISC.GRAVITY RETAINING WALL	456.00	0.00	456.00	LF	365.00	\$250.00	\$91,250.00
		0001	0440	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$311,345.00	\$311,345.00
		0001	0450	6189902		2.00	0.00	2.00	EA	0.00	\$600.00	\$0.00

Page 9 of 31 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	Line	Item	Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTE	
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)	
90517-F06	J6S3196	0001	0460	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	631.00	0.00	631.00	LF	631.00	\$25.00	\$15,775.00	
		0001	0470	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	117.00	0.00	117.00	LF	117.00	\$25.00	\$2,925.00	
		0001	0480	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	31.00	0.00	31.00	EA	31.00	\$350.00	\$10,850.00	
		0001	0490	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	16.00	0.00	16.00	EA	16.00	\$350.00	\$5,600.00	
		0001	0500	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	24.00	0.00	24.00	EA	0.00	\$55.00	\$0.00	
		0001	0510	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	36,677.00	0.00	36,677.00	LF	36,677.00	\$0.20	\$7,335.40	
		0001	0520	6205902A	$6\mbox{IN}.$ WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	47,289.00	0.00	47,289.00	LF	47,289.00	\$0.50	\$23,644.5	
		0001	0530	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,775.00	0.00	4,775.00	LF	4,775.00	\$0.50	\$2,387.5	
		0001	0540	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION(LEFT)	6.00	0.00	6.00	EA	5.00	\$2,000.00	\$10,000.0	
		0001	0550	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, UTURN ARROW (LEFT)	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.0	
		0001	0560	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, UTURN ONLY WORD	2.00	0.00	2.00	EA	1.00	\$1,500.00	\$1,500.0	
		0001	0570	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	20,926.00	0.00	20,926.00	SQYD	50,535.00	\$2.55	\$128,864.2	
		0001	0580	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	21,450.00	0.00	21,450.00	SQYD	21,450.00	\$4.00	\$85,800.0	
		0001	0590	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	285.00	0.00	285.00	STA	0.00	\$40.00	\$0.0	
		0001	0600	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$61,966.00	\$61,966.0	
		0001	0670	7269903	MISC.12 IN. CLASS 3 RCP	1,707.00	-1,707.00	0.00	LF	0.00	\$50.00	\$0.0	
		0001	0680	7269903	MISC.15 IN. CLASS 3 RCP	1,915.00	-1,101.00	814.00	LF	814.00	\$53.00	\$43,142.0	
		0001		7269903 MISC.18 IN. CLASS 3 RCP				-1,807.00	2,121.00	LF	2,121.00	\$58.00	\$123,018.0
		0001	0700	7269903 7269903	MISC.21 IN. CLASS 3 RCP MISC.24 IN. CLASS 3 RCP	1,971.00 556.00	-1,011.00	960.00	LF LF	960.00	\$61.00 \$66.00	\$58,560.0 \$29,568.0	
		0001	0710	7269903	MISC.30 IN. CLASS 3 RCP	94.00	-45.00	49.00	LF	49.00	\$76.00	\$3,724.0	
		0001	0722	7269903	MISC.12 IN. CLASS 4 RCP	328.00	509.00	837.00	LF	837.00	\$50.00	\$41,850.0	
		0001	0724	7269903	MISC.15 IN. CLASS 4 RCP	365.00	-365.00	0.00	LF	0.00	\$54.00	\$0.0	
		0001	0726	7269903	MISC.18 IN. CLASS 4 RCP	538.00	-538.00	0.00	LF	0.00	\$59.00	\$0.	
		0001	0728	7269903	MISC.21 IN. CLASS 4 RCP	123.00	-123.00	0.00	LF	0.00	\$63.00	\$0.	
		0001	0730	7319902	MISC.MSD 2 GRATE INLET W/ SIDE INTAKE 48 IN. X 48 IN.	51.00	0.00	51.00	EA	51.00	\$3,400.00	\$173,400.	
		0001	0740	7319902	MISC.MSD AREA INLET 58 IN. X 58 IN.	4.00	0.00	4.00	EA	4.00	\$2,500.00	\$10,000.	
		0001	0750	7319902	MISC.MSD DOUBLE STREET INLET 108 IN. X 52 IN.	20.00	0.00	20.00	EA	20.00	\$4,000.00	\$80,000.0	
		0001	0760	7319902	MISC.MSD SINGLE STREET INLET 54 IN. X 48 IN.	22.00	0.00	22.00	EA	22.00	\$3,000.00	\$66,000.0	
		0001	0770	7319902	MISC.REPLACE INLET TOP TO NEW GRADE	56.00	0.00	56.00	EA	56.00	\$800.00	\$44,800.0	
		0001	0780	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$800.00	\$800.0	
		0001	0790	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	4.00	0.00	4.00	EA	4.00	\$850.00	\$3,400.	
		0001	0800	8051000A	SEEDING - COOL SEASON MIXTURES	5.80	0.00	5.80	ACRE	3.75	\$3,200.00	\$12,000.	
		0001	0810	8061005	ROCK DITCH CHECK	6.00	0.00	6.00	LF	0.00	\$30.00	\$0.	
		0001	0820	8061007A	CURB INLET CHECK	114.00	0.00	114.00	EA	43.00	\$50.00	\$2,150.	
		0001	0830	8061016	SEDIMENT REMOVAL	311.00	0.00	311.00	CUYD	0.00	\$0.01	\$0.	
		0001	0840	8061019	SILT FENCE	19,279.00	0.00	19,279.00	LF	0.00	\$0.01	\$0.	
		0010	0850	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	2.00	0.00	2.00	EA	0.00	\$3,600.00	\$0.	
		0010	0860	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$3,200.00	\$0.	
		0020	0870	9019902	MISC.RELOCATION OF CITY LIGHTING POLE	4.00	0.00	4.00	EA	4.00	\$2,500.00	\$10,000.	
		0020	0880	9019902	MISC.RELOCATION OF FLASHING BEACON	1.00	0.00	1.00	EA	1.00	\$2,500.00	\$2,500.0	
		0030	0890	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	634.00	0.00	634.00	LF	634.00	\$15.00	\$9,510.0	
		0030	0900	9028311	CABLE, 16 AWG 7 CONDUCTOR	750.00	0.00	750.00	LF	750.00	\$3.00	\$2,250.0	

Revision 4/1/2020 Page 10 of 31



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190517-F06	J6S3196	0030	0910	9028810	PULL BOX, PREFORMED CLASS 1	3.00	0.00	3.00	EA	3.00	\$1,500.00	\$4,500.00
		0040	0920	9031242	36 IN. SURFACE-MOUNT DELINEATOR POST	288.00	0.00	288.00	EA	0.00	\$90.00	\$0.00
		0040	0930	9031270A	2 IN. PSST POST - 12 GA.	265.00	0.00	265.00	LF	0.00	\$16.00	\$0.00
		0040	0940	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	81.00	0.00	81.00	LF	0.00	\$36.00	\$0.00
		0040	0950	9031280	2.5 IN. PSST POST - 12 GA.	97.00	0.00	97.00	LF	0.00	\$17.00	\$0.00
		0040	0960	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	18.00	0.00	18.00	LF	0.00	\$48.00	\$0.00
		0040	0970	9035004A	SH-FLAT SHEET	152.00	0.00	152.00	SQFT	0.00	\$26.00	\$0.00
		0040	0980	9035069A	SHF-FLAT SHEET FLUORESCENT	32.00	0.00	32.00	SQFT	0.00	\$30.00	\$0.00
		0001	5001	7269903	MISC.12 IN. CLASS 5 RCP	0.00	1,198.00	1,198.00	LF	1,198.00	\$51.31	\$61,469.38
		0001	5002	7269903	MISC.15 IN. CLASS 5 RCP	0.00	1,466.00	1,466.00	LF	1,466.00	\$58.65	\$85,980.90
		0001	5003	7269903	MISC.18 IN. CLASS 5 RCP	0.00	2,477.00	2,477.00	LF	2,477.00	\$60.03	\$148,694.31
		0001	5004	7269903	MISC.21 IN. CLASS 5 RCP	0.00	1,002.00	1,002.00	LF	1,002.00	\$79.40	\$79,558.80
		0001	5005	7269903	MISC.24 IN. CLASS 5 RCP	0.00	108.00	108.00	LF	108.00	\$79.11	\$8,543.88
		0001	5006	7269903	MISC.30 IN. CLASS 5 RCP	0.00	45.00	45.00	LF	45.00	\$91.93	\$4,136.85
		0030	5007	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	0.00	2.00	2.00	EA	2.00	\$2,275.00	\$4,550.00
		0030	5008	9028354	FIBER OPTIC CABLE, 24 - FIBER, 18 SINGLE MODE, 6 MULTIMODE	0.00	371.00	371.00	LF	371.00	\$3.75	\$1,391.25
		0001	5009	6031015	RELOCATING SERVICE CONNECTIONS(CLASS 3)	0.00	1.00	1.00	EA	1.00	\$9,293.66	\$9,293.66
	Project Je	6S3196 - To	otal Value	Posted to D	ate as of Report Generated Date							\$4,644,190.88
190517-F06 Ove	rall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$4,644,190.88

Revision 4/1/2020 Page 11 of 31



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3196

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	8/7/20	8/13/20	0.50	LS	Remainder qty	0		0		
0150	6081000	CONCRETE MEDIAN	8/4/20	8/13/20	2,621.00	SQYD	Concrete median update, 5' width median through the North end of the job.	158+08		2+85		
			8/5/20	8/13/20	849.00	SQYD		136+33.63		88+78.95		
			8/7/20	8/13/20	459.00	SQYD	STA 72+86 - 79+19 and 88+20 - 91+19. 4' W	72+86		91+19		
			8/10/20	8/13/20	67.00	SQYD	Final payment for concrete median. Section that connects 4' width to 5' width.					
0160	6081012	TRUNCATED DOMES	8/11/20	8/13/20	101.00	SQFT	Both sets of domes at North crossing, East set of domes at the South crossing.					
0390	6169901	MISC.	8/4/20	8/13/20	0.20	LS	75% of contract was reached.					
0460	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	8/13/20	8/14/20	631.00	LF	See B-Sheets	0		0		
0470	6200018	PREF THERMO PVMT MARK, 24 IN YELLOW	8/13/20	8/14/20	117.00	LF	See B Sheets	0		0		
0480	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	8/13/20	8/14/20	31.00	EA	See B sheets. Eliminated 2 N I270, added 2 Scranton Ave	0		0		
0490	6200036	PREF THERMO PVMT MARK, 30" WHT MIDBL	8/13/20	8/14/20	16.00	EA	See B Sheets	0		0		
0510	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAINT	8/13/20	8/14/20	36,677.00	LF	See B Sheets	0		0		
0520	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	8/13/20	8/14/20	47,289.00	LF	See B Sheets	0		0		
0530	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	8/13/20	8/14/20	4,775.00	LF	See B Sheets	0		0		
0540	6209902	MISC. PAVEMENT MARKINGS	8/13/20	8/14/20	5.00	EA	See B sheets Eliminated one north of 270	0		0		
0550	6209902	MISC. PAVEMENT MARKINGS	8/13/20	8/14/20	2.00	EA	Adrian u-turn	0		0		
0560	6209902	MISC. PAVEMENT MARKINGS	8/13/20	8/14/20	1.00	EA	installed 1 adrian	0		0		
0600	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	8/7/20	8/13/20	0.40	LS	Remainder qty.	0		0		

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 12 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0080	TYPE A2 SHOULDER	Material	Туре	9	Jan 16, 2020	SYSTEM	(\$32,985.00)	
				10	Feb 3, 2020	SYSTEM	(\$32,985.00)	
				11	Feb 18, 2020	SYSTEM	(\$32,985.00)	
				12	Mar 2, 2020	SYSTEM	(\$32,985.00)	
				12	Mar 2, 2020	SYSTEM	\$32,985.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				13	Mar 16, 2020	SYSTEM	(\$32,985.00)	
				13	Mar 16, 2020	SYSTEM	\$32,985.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				14	Apr 2, 2020	SYSTEM	(\$32,985.00)	
				14	Apr 2, 2020	SYSTEM	\$32,985.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				15	Apr 15, 2020	SYSTEM	(\$57,510.00)	
				15	Apr 15, 2020	SYSTEM	\$57,510.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				16	May 4, 2020	SYSTEM	(\$61,020.00)	
				16	May 4, 2020	SYSTEM	\$61,020.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				17	May 15, 2020	SYSTEM	(\$66,960.00)	
				17	May 15, 2020	SYSTEM	\$66,960.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user cunnid3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				18	Jun 2, 2020	SYSTEM	(\$66,960.00)	
				18	Jun 2, 2020	SYSTEM	\$66,960.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user cunnid3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				19	Jun 15, 2020	SYSTEM	(\$74,430.00)	
				19	Jun 15, 2020	SYSTEM	\$74,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				20	Jul 1, 2020	SYSTEM	(\$84,285.00)	
				20	Jul 1, 2020	SYSTEM	\$84,285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				21	Jul 16, 2020	SYSTEM	(\$84,285.00)	
				21	Jul 16, 2020	SYSTEM	\$84,285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user clowez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$84,285.00)	
				22	Aug 3, 2020	SYSTEM	\$84,285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 6 on the current Payment

Revision 4/1/2020 Page 13 of 31



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Type	Adjustment Type	Number	Date	Ву		
0800	TYPE A2 SHOULDER	Material						Estimate.
				23	Aug 17, 2020	SYSTEM	(\$84,285.00)	
				23	Aug 17, 2020	SYSTEM	\$84,285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				(\$98,955.00)	
	Material - Total						(\$98,955.00)	
	TYPE A2 SHOULDER	MaterialCredit		10	Feb 3, 2020	SYSTEM	\$32,985.00	
				11	Feb 18, 2020	SYSTEM	\$32,985.00	
				12	Mar 2, 2020	SYSTEM	\$32,985.00	
			- Total				\$98,955.00	
	MaterialCredit - Total						\$98,955.00	
0080 -	Total						\$0.00	
0090	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Material		21	Jul 16, 2020	SYSTEM	(\$1,062,053.00)	
				21	Jul 16, 2020	SYSTEM	\$1,062,053.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$1,062,053.00)	
				22	Aug 3, 2020	SYSTEM	\$1,062,053.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user clowez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$1,062,053.00)	
				23	Aug 17, 2020	SYSTEM	\$1,062,053.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Other Item Adjustment	ACAD	21	Jul 16, 2020	clowez1	(\$43,768.63)	Asphalt Cement Price Adjustment
			ACAD - Tota	al			(\$43,768.63)	
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)		SMAB	23	Aug 17, 2020	clowez1	\$6,314.89	IRI Smoothness bonus Rt. H Southbound and Northbound.
			SMAB - Tota	al			\$6,314.89	
	Other Item Adjustment - Total						(\$37,453.74)	
0090 -	Total						(\$37,453.74)	
0110	MISC. POLYMER MODIFIED EMULSION MEMBRANE	Material		21	Jul 16, 2020	SYSTEM	(\$47,347.50)	
				21	Jul 16, 2020	SYSTEM	\$47,347.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user clowez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$47,347.50)	
				22	Aug 3, 2020	SYSTEM	\$47,347.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	MISC. POLYMER MODIFIED EMULSION MEMBRANE	Other Item Adjustment	UBAW	21	Jul 16, 2020	clowez1	(\$830.95)	UBAWS Adjustment (Membrane)
			UBAW - Tot	al			(\$830.95)	
	Other Item Adjustment - Total						(\$830.95)	

Revision 4/1/2020 Page 14 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0110 -	- Total						(\$830.95)	
0150	CONCRETE MEDIAN	Material		22	Aug 3, 2020	SYSTEM	(\$138,580.00)	
				22	Aug 3, 2020	SYSTEM	\$138,580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user clowez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$346,372.00)	
				23	Aug 17, 2020	SYSTEM	\$346,372.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CONCRETE MEDIAN	Overrun	Overrun	23	Aug 17, 2020	SYSTEM	(\$10,192.00)	
				23	Aug 17, 2020	SYSTEM	\$10,192.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 52 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0150 -	- Total						\$0.00	
0160	TRUNCATED DOMES	Material		20	Jul 1, 2020	SYSTEM	(\$600.00)	
				20	Jul 1, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				21	Jul 16, 2020	SYSTEM	(\$600.00)	
				21	Jul 16, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TRUNCATED DOMES	Overrun	Overrun	23	Aug 17, 2020	SYSTEM	(\$1,710.00)	
			Overrun - T	otal			(\$1,710.00)	
	Overrun - Total						(\$1,710.00)	
	- Total						(\$1,710.00)	
0170	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Material		7	Dec 17, 2019	SYSTEM	(\$45,000.00)	
				8	Jan 2, 2020	SYSTEM	(\$50,970.00)	
				9	Jan 16, 2020	SYSTEM	(\$74,070.00)	
				10	Feb 3, 2020	SYSTEM	(\$74,070.00)	
				11	Feb 18, 2020	SYSTEM	(\$74,070.00)	
				12	Mar 2, 2020	SYSTEM	(\$86,040.00)	
				12	Mar 2, 2020	SYSTEM	\$86,040.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				13	Mar 16, 2020	SYSTEM	(\$117,585.00)	
				13	Mar 16, 2020	SYSTEM	\$117,585.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user clowez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				14	Apr 2, 2020	SYSTEM	(\$143,040.00)	

Revision 4/1/2020 Page 15 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0170	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Material		14	Apr 2, 2020	SYSTEM	\$143,040.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user clowez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				15	Apr 15, 2020	SYSTEM	(\$156,585.00)	
				15	Apr 15, 2020	SYSTEM	\$156,585.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				16	May 4, 2020	SYSTEM	(\$174,855.00)	
				16	May 4, 2020	SYSTEM	\$174,855.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				17	May 15, 2020	SYSTEM	(\$181,290.00)	
				17	May 15, 2020	SYSTEM	\$181,290.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user cunnid3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				18	Jun 2, 2020	SYSTEM	(\$182,310.00)	
				18	Jun 2, 2020	SYSTEM	\$182,310.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user cunnid3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				19	Jun 15, 2020	SYSTEM	(\$211,140.00)	
				19	Jun 15, 2020	SYSTEM	\$211,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				20	Jul 1, 2020	SYSTEM	(\$245,535.00)	
				20	Jul 1, 2020	SYSTEM	\$245,535.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				21	Jul 16, 2020	SYSTEM	(\$245,535.00)	
				21	Jul 16, 2020	SYSTEM	\$245,535.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user clowez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$255,795.00)	
				22	Aug 3, 2020	SYSTEM	\$255,795.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$255,795.00)	
				23	Aug 17, 2020	SYSTEM	\$255,795.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user clowez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				(\$318,180.00)	
	Material - Total	MaterialCredit		8	lan 2	SYSTEM	(\$318,180.00)	
	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	waterialCredit		9	Jan 2, 2020		\$45,000.00	
				10	Jan 16, 2020 Feb 3,	SYSTEM	\$50,970.00 \$74,070.00	
				11	2020 Feb 18,	SYSTEM	\$74,070.00	
				12	2020 Mar 2,	SYSTEM	\$74,070.00	
				14	2020	SISIEW	φι4,υιυ.υυ	

Revision 4/1/2020 Page 16 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0170		MaterialCredit	- Total				\$318,180.00	
	MaterialCredit - Total						\$318,180.00	
	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Other Item Adjustment	PPPS	8	Jan 2, 2020	clowez1	\$50,970.00	Return of 15+00 - 38+98
				10	Feb 3, 2020	clowez1	\$23,100.00	Awaiting successful cre2o submission.
				12	Mar 2, 2020	clowez1	(\$74,070.00)	Taking back PPPS due to new adjustment method in AWP.
			PPPS - Tota	ıl			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Overrun	Overrun	22	Aug 3, 2020	SYSTEM	(\$7,170.00)	
				22	Aug 3, 2020	SYSTEM	\$7,170.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 43 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$7,170.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				23	Aug 17, 2020	SYSTEM	\$7,170.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 54 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0170 -	· Total						\$0.00	
0180	CONCRETE GUTTER TYPE A	Material		21	Jul 16, 2020	SYSTEM	(\$62,468.00)	
				21	Jul 16, 2020	SYSTEM	\$62,468.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$62,468.00)	
				22	Aug 3, 2020	SYSTEM	\$62,468.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$62,468.00)	
				23	Aug 17, 2020	SYSTEM	\$62,468.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user clowez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0180 -	Total						\$0.00	
0190	CONCRETE GUTTER TYPE B	Material		21	Jul 16, 2020	SYSTEM	(\$13,692.00)	
				21	Jul 16, 2020	SYSTEM	\$13,692.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$13,692.00)	
				22	Aug 3, 2020	SYSTEM	\$13,692.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$13,692.00)	
				23	Aug 17, 2020	SYSTEM	\$13,692.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user clowez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0190	· Total						\$0.00	
0130 -	Total						Ψ0.00	

Revision 4/1/2020 Page 17 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0200	CURB AND GUTTER TYPE B	Material		18	Jun 2, 2020	SYSTEM	(\$4,890.00)	
				18	Jun 2, 2020	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user cunnid3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				19	Jun 15, 2020	SYSTEM	(\$4,890.00)	
				19	Jun 15, 2020	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user clowez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				20	Jul 1, 2020	SYSTEM	(\$4,890.00)	
				20	Jul 1, 2020	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user clowez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				21	Jul 16, 2020	SYSTEM	(\$4,890.00)	
				21	Jul 16, 2020	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user clowez1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$4,890.00)	
				22	Aug 3, 2020	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$4,890.00)	
				23	Aug 17, 2020	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0200	- Total INTEGRAL CURB TYPE N	Material		15	Apr 15,	SYSTEM	\$0.00 (\$1,650.00)	
					0000			
				16	2020 May 4.	SYSTEM		
				16	May 4, 2020	SYSTEM	(\$1,650.00)	
				17	May 4, 2020 May 15, 2020	SYSTEM	(\$1,650.00) (\$1,650.00)	
				17	May 4, 2020 May 15, 2020 Jun 2, 2020	SYSTEM SYSTEM	(\$1,650.00) (\$1,650.00) (\$1,650.00)	
				17 18 19	May 4, 2020 May 15, 2020 Jun 2, 2020 Jun 15, 2020	SYSTEM SYSTEM	(\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00)	
				17	May 4, 2020 May 15, 2020 Jun 2, 2020 Jun 15,	SYSTEM SYSTEM	(\$1,650.00) (\$1,650.00) (\$1,650.00)	
				17 18 19	May 4, 2020 May 15, 2020 Jun 2, 2020 Jun 15, 2020 Jul 1,	SYSTEM SYSTEM	(\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00)	
				17 18 19 20	May 4, 2020 May 15, 2020 Jun 2, 2020 Jun 15, 2020 Jul 1, 2020 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				17 18 19 20 21	May 4, 2020 May 15, 2020 Jun 2, 2020 Jun 15, 2020 Jul 1, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00)	Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 27 on the current Payment
				17 18 19 20 21 21	May 4, 2020 May 15, 2020 Jun 2, 2020 Jun 15, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00)	Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 27 on the current Payment
				17 18 19 20 21 21 22	May 4, 2020 May 15, 2020 Jun 2, 2020 Jul 15, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00) (\$1,650.00) \$1,650.00	Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user clowez1 overridding Payment Estimate Exception 26 on the current Payment

Revision 4/1/2020 Page 18 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
0210		Material	- Total				(\$9,900.00)										
	Material - Total						(\$9,900.00)										
	INTEGRAL CURB TYPE N	MaterialCredit		16	May 4, 2020	SYSTEM	\$1,650.00										
				17	May 15, 2020	SYSTEM	\$1,650.00										
				18	Jun 2, 2020	SYSTEM	\$1,650.00										
				19	Jun 15, 2020	SYSTEM	\$1,650.00										
				20	Jul 1, 2020	SYSTEM	\$1,650.00										
				21	Jul 16, 2020	SYSTEM	\$1,650.00										
			- Total				\$9,900.00										
	MaterialCredit - Total						\$9,900.00										
0210	Total						\$0.00										
0220	FURNISHING TYPE 2 ROCK DITCH LINER	Material		17	May 15, 2020	SYSTEM	(\$2,600.00)										
				17	May 15, 2020	SYSTEM	\$2,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user cunnid3 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
				18	Jun 2, 2020	SYSTEM	(\$2,600.00)										
				18	Jun 2, 2020	SYSTEM	\$2,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user cunnid3 overridding Payment Estimate Exception 16 on the current Payment Estimate.									
													19	Jun 15, 2020	SYSTEM	(\$2,600.00)	
				20	Jul 1, 2020	SYSTEM	(\$2,600.00)										
				21	Jul 16, 2020	SYSTEM	(\$2,600.00)										
				22	Aug 3, 2020	SYSTEM	(\$2,600.00)										
				23	Aug 17, 2020	SYSTEM	(\$2,600.00)										
			- Total				(\$13,000.00)										
	Material - Total						(\$13,000.00)										
	FURNISHING TYPE 2 ROCK DITCH LINER	MaterialCredit		20	Jul 1, 2020	SYSTEM	\$2,600.00										
				21	Jul 16, 2020	SYSTEM	\$2,600.00										
				22	Aug 3, 2020	SYSTEM	\$2,600.00										
				23	Aug 17, 2020	SYSTEM	\$2,600.00										
			- Total				\$10,400.00										
	MaterialCredit - Total						\$10,400.00										
	FURNISHING TYPE 2 ROCK DITCH LINER		OADJ	17	May 18, 2020	brookw1	(\$1,200.00)	material discrepancy over-ridden, adjusting for overrun override.									
			OADJ - Tota	al			(\$1,200.00)										
	Other Item Adjustment - Total						(\$1,200.00)										
	FURNISHING TYPE 2 ROCK DITCH LINER	Overrun	Overrun	17	May 15, 2020	SYSTEM	(\$1,200.00)										
				17	May 15, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 16 on the current Payment Estimate.									
				18	Jun 2, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
				18	Jun 2,	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun									

Revision 4/1/2020 Page 19 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
0220	FURNISHING TYPE 2 ROCK DITCH LINER	Overrun	Overrun		2020			Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 27 on the current Payment Estimate.									
				19	Jun 15, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
				19	Jun 15, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 28 on the current Payment Estimate.									
				20	Jul 1, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
						20	Jul 1, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 21 on the current Payment Estimate.							
				21	Jul 16, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
					21	Jul 16, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 44 on the current Payment Estimate.								
							22	Aug 3, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
						22	Aug 3, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 44 on the current Payment Estimate.							
				23	Aug 17, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
				23	Aug 17, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 55 on the current Payment Estimate.									
			Overrun - T	otal			\$0.00										
	Overrun - Total						\$0.00										
0220 -		0	0	47	May 45	OVOTEM	(\$3,800.00)										
0230	PLACING TYPE 2 ROCK DITCH LINER	Overrun	Overrun		May 15, 2020	SYSTEM	(\$2,400.00)										
			Overrun - T	otal			(\$2,400.00)										
	Overrun - Total						(\$2,400.00)										
0230 -	MISC. MODIFIED 4 IN. CURB AND	Material		18	Jun 2,	SYSTEM	(\$2,400.00)										
0240	GUTTER, TYPE A	ivialerial		10	2020	STSTEIN	(\$15,132.00)										
				18	Jun 2, 2020	SYSTEM	\$15,132.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user cunnid3 overridding Payment Estimate Exception 18 on the current Payment Estimate.									
				19	Jun 15, 2020	SYSTEM	(\$15,132.00)										
				19	Jun 15, 2020	SYSTEM	\$15,132.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.									
												2	20	Jul 1, 2020	SYSTEM	(\$15,132.00)	
						20	Jul 1, 2020	SYSTEM	\$15,132.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user clowez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
						21	Jul 16, 2020	SYSTEM	(\$15,132.00)								
				21	Jul 16, 2020	SYSTEM	\$15,132.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user clowez1 overridding Payment Estimate Exception 36 on the current Payment Estimate.									
				22	Aug 3, 2020	SYSTEM	(\$15,132.00)										
					22	Aug 3, 2020	SYSTEM	\$15,132.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user clowez1 overridding Payment Estimate Exception 35 on the current Payment Estimate.								
				23	Aug 17, 2020	SYSTEM	(\$15,132.00)										

Revision 4/1/2020 Page 20 of 31



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0240	MISC. MODIFIED 4 IN. CURB AND	Material	Туре	23	Aug 17,	SYSTEM	\$15,132.00	This adjustment offsets the original system-generated Overrun
	GUTTER, TYPE A				2020			Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0240 -	· Total						\$0.00	
0250	MISC. TRANSITION TYPE A TO TYPE B GUTTER	Material		21	Jul 16, 2020	SYSTEM	(\$780.00)	
				21	Jul 16, 2020	SYSTEM	\$780.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$780.00)	
				22	Aug 3, 2020	SYSTEM	\$780.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$780.00)	
				23	Aug 17, 2020	SYSTEM	\$780.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0250 -	· Total						\$0.00	
0260	MISC. TRANSITION TYPE B TO TYPE A GUTTER	Material		21	Jul 16, 2020	SYSTEM	(\$900.00)	
				21	Jul 16, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user clowez1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$900.00)	
				22	Aug 3, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user clowez1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$900.00)	
				23	Aug 17, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user clowez1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0260 -	· Total						\$0.00	
0310	CONCRETE MATERIAL FOR FULL	Material		4	Nov 4, 2019	SYSTEM	(\$9,570.00)	
	DEPTH PAVEMENT REPAIR			5	Nov 18, 2019	SYSTEM	(\$1,760.00)	
				6	Dec 2, 2019	SYSTEM	(\$1,760.00)	
				7	Dec 17, 2019	SYSTEM	(\$1,760.00)	
				8	Jan 2, 2020	SYSTEM	(\$1,760.00)	
				9	Jan 16, 2020	SYSTEM	(\$9,790.00)	
				10	Feb 3, 2020	SYSTEM	(\$9,790.00)	
				11	Feb 18, 2020	SYSTEM	(\$9,790.00)	
				12	Mar 2,	SYSTEM	(\$9,790.00)	

Revision 4/1/2020 Page 21 of 31



Line	Description	Type Adjus		st. Create		Amount	Remarks											
0310	FURNISHING AND PLACING	Material		2020														
	CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR		12	Mar 2, 2020	SYSTEM	\$9,790.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.											
			13	Mar 16 2020	S, SYSTEM	(\$26,070.00)												
			13	Mar 16 2020	S, SYSTEM	\$26,070.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user clowez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
			14	Apr 2, 2020	SYSTEM	(\$31,460.00)												
			14	Apr 2, 2020	SYSTEM	\$31,460.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user clowez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
			15	Apr 15	, SYSTEM	(\$37,730.00)												
			15	Apr 15 2020	, SYSTEM	\$37,730.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user clowez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.											
				16	May 4 2020	SYSTEM	(\$41,030.00)											
			16	May 4 2020	SYSTEM	\$41,030.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.											
			17	May 1 2020	5, SYSTEM	(\$41,030.00)												
					17	May 1 2020	5, SYSTEM	\$41,030.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user cunnid3 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					18	Jun 2, 2020	SYSTEM	(\$41,030.00)										
			18	Jun 2, 2020	SYSTEM	\$41,030.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user cunnid3 overridding Payment Estimate Exception 22 on the current Payment Estimate.											
			19	Jun 15 2020	, SYSTEM	(\$64,460.00)												
			19	Jun 15 2020	, SYSTEM	\$64,460.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user clowez1 overridding Payment Estimate Exception 22 on the current Payment Estimate.											
			20	Jul 1, 2020	SYSTEM	(\$81,730.00)												
					20	Jul 1, 2020	SYSTEM	\$81,730.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.									
			21	Jul 16 2020	SYSTEM	1 (\$81,730.00)												
														21	Jul 16 2020	SYSTEM	\$81,730.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user clowez1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
																	22	Aug 3, 2020
								22	Aug 3, 2020	SYSTEM	\$87,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user clowez1 overridding Payment Estimate Exception 38 on the current Payment Estimate.						
			23	Aug 1 ⁻ 2020	7, SYSTEM	(\$87,340.00)												
			23	Aug 1 2020	, SYSTEM	\$87,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user clowez1 overridding Payment Estimate Exception 32 on the current Payment Estimate.											

Revision 4/1/2020 Page 22 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0310		Material	- Total				(\$45,980.00)	
	Material - Total						(\$45,980.00)	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	MaterialCredit		5	Nov 18, 2019	SYSTEM	\$9,570.00	
	DEPTH PAVEMENT REPAIR			6	Dec 2, 2019	SYSTEM	\$1,760.00	
				7	Dec 17, 2019	SYSTEM	\$1,760.00	
				8	Jan 2, 2020	SYSTEM	\$1,760.00	
				9	Jan 16, 2020	SYSTEM	\$1,760.00	
				10	Feb 3, 2020	SYSTEM	\$9,790.00	
				11	Feb 18, 2020	SYSTEM	\$9,790.00	
				12	Mar 2, 2020	SYSTEM	\$9,790.00	
			- Total				\$45,980.00	
	MaterialCredit - Total						\$45,980.00	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Other Item Adjustment	PPPS		Jan 2, 2020	clowez1	\$1,760.00	19 and 20 series crossover.
				9	Jan 16, 2020	clowez1	\$8,030.00	15 series crossover.
			DDD0 T /	12	Mar 2, 2020	clowez1	(\$9,790.00)	Taking back PPPS due to new adjustment method in AWP.
			PPPS - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0310 -					1 10	OVOTEN	\$0.00	
0320	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		9	Jan 16, 2020 Feb 3,	SYSTEM	(\$0.73)	
				11	2020 Feb 18,	SYSTEM	(\$0.89)	
				12	2020 Mar 2,	SYSTEM	(\$0.89)	
				13	2020 Mar 16,	SYSTEM	` ′	
				14	2020	SYSTEM	(\$1.43)	
				14	Apr 2, 2020	SYSTEM	(\$1.43) \$1.43	This adjustment offsets the original system-generated Overrun
				14	2020	STSTEIN	φ1.43	Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				15	Apr 15, 2020	SYSTEM	(\$1.43)	
				15	Apr 15, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				16	May 4, 2020	SYSTEM	(\$1.43)	
				16	May 4, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user clowez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				17	May 15, 2020	SYSTEM	(\$1.43)	
				18	Jun 2, 2020	SYSTEM	(\$1.43)	
				18	Jun 2, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user cunnid3 overridding Payment Estimate Exception 24 on the current Payment Estimate.

Revision 4/1/2020 Page 23 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0320	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		19	Jun 15, 2020	SYSTEM	(\$1.43)	
				19	Jun 15, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user clowez1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				20	Jul 1, 2020	SYSTEM	(\$1.43)	
				20	Jul 1, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				21	Jul 16, 2020	SYSTEM	(\$1.43)	
				21	Jul 16, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user clowez1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$1.43)	
				22	Aug 3, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user clowez1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$1.43)	
				23	Aug 17, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user clowez1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
			- Total				(\$6.26)	
	Material - Total						(\$6.26)	
	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	MaterialCredit		10	Feb 3, 2020	SYSTEM	\$0.73	
				11	Feb 18, 2020	SYSTEM	\$0.89	
				12	Mar 2, 2020	SYSTEM	\$0.89	
				13	Mar 16, 2020	SYSTEM	\$0.89	
				14	Apr 2, 2020	SYSTEM	\$1.43	
				18	Jun 2, 2020	SYSTEM	\$1.43	
			- Total				\$6.26	
	MaterialCredit - Total						\$6.26	
0320 -	Total						\$0.00	
0330	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT	Material		9	Jan 16, 2020	SYSTEM	(\$0.73)	
	REPAIR)			10	Feb 3, 2020	SYSTEM	(\$0.89)	
				11	Feb 18, 2020	SYSTEM	(\$0.89)	
				13	Mar 16, 2020	SYSTEM	(\$2.37)	
				14	Apr 2, 2020	SYSTEM	(\$2.86)	
				14	Apr 2, 2020	SYSTEM	\$2.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				15	Apr 15, 2020	SYSTEM	(\$6.49)	
					15	Apr 15, 2020	SYSTEM	\$6.49

Revision 4/1/2020 Page 24 of 31



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0330	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT	Material	Туре	16	May 4, 2020	SYSTEM	(\$6.49)	
	REPAIR)			16	May 4, 2020	SYSTEM	\$6.49	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				17	May 15, 2020	SYSTEM	(\$6.49)	
				18	Jun 2, 2020	SYSTEM	(\$11.74)	
				18	Jun 2, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user cunnid3 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				19	Jun 15, 2020	SYSTEM	(\$11.74)	
				19	Jun 15, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				20	Jul 1, 2020	SYSTEM	(\$11.74)	
				20	Jul 1, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				21	Jul 16, 2020	SYSTEM	(\$11.74)	
				21	Jul 16, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user clowez1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$11.74)	
				22	Aug 3, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user clowez1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$11.74)	
				23	Aug 17, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user clowez1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
			- Total				(\$11.37)	
	Material - Total						(\$11.37)	
	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	MaterialCredit		10	Feb 3, 2020	SYSTEM	\$0.73	
	,			11	Feb 18, 2020	SYSTEM	\$0.89	
				12	Mar 2, 2020	SYSTEM	\$0.89	
				14	Apr 2, 2020	SYSTEM	\$2.37	
				18	Jun 2, 2020	SYSTEM	\$6.49	
			- Total				\$11.37	
	MaterialCredit - Total						\$11.37	
	- Total						\$0.00	
0350	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		4	Nov 4, 2019	SYSTEM	(\$264.00)	
			- Total				(\$264.00)	
	Material - Total						(\$264.00)	
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL	MaterialCredit		5	Nov 18, 2019	SYSTEM	\$264.00	

Revision 4/1/2020 Page 25 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0350	DEPTH PAVEMENT REPAIR	MaterialCredit	, ,,					
			- Total				\$264.00	
	MaterialCredit - Total						\$264.00	
0350 -	- Total						\$0.00	
0380	MISC. MSD STANDARD MANHOLE FRAME AND COVER	Material		4	Nov 4, 2019	SYSTEM	(\$800.00)	
				5	Nov 18, 2019	SYSTEM	(\$800.00)	
				6	Dec 2, 2019	SYSTEM	(\$800.00)	
				7	Dec 17, 2019	SYSTEM	(\$800.00)	
				8	Jan 2, 2020	SYSTEM	(\$800.00)	
			- Total				(\$4,000.00)	
	Material - Total						(\$4,000.00)	
	MISC. MSD STANDARD MANHOLE FRAME AND COVER	MaterialCredit		5	Nov 18, 2019	SYSTEM	\$800.00	
				6	Dec 2, 2019	SYSTEM	\$800.00	
				7	Dec 17, 2019	SYSTEM	\$800.00	
				8	Jan 2, 2020	SYSTEM	\$800.00	
				9	Jan 16, 2020	SYSTEM	\$800.00	
			- Total				\$4,000.00	
	MaterialCredit - Total						\$4,000.00	
	MISC. MSD STANDARD MANHOLE FRAME AND COVER	Other Item Adjustment	PPPS	6	Dec 2, 2019	clowez1	\$800.00	Return of 2 structures.
				9	Jan 16, 2020	clowez1	(\$800.00)	Taking back the 2 structures that were returned.
			PPPS - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0380 -	- Total						\$0.00	
0390	MISC. TEMPORARY TRAFFIC CONTROL	Material		21	Jul 16, 2020	SYSTEM	(\$14,000.00)	
				22	Aug 3, 2020	SYSTEM	(\$14,000.00)	
			- Total				(\$28,000.00)	
	Material - Total						(\$28,000.00)	
	MISC. TEMPORARY TRAFFIC CONTROL	MaterialCredit		22	Aug 3, 2020	SYSTEM	\$14,000.00	
				23	Aug 17, 2020	SYSTEM	\$14,000.00	
			- Total				\$28,000.00	
	MaterialCredit - Total						\$28,000.00	
	- Total						\$0.00	
0460	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	Material		23	Aug 17, 2020	SYSTEM	(\$15,775.00)	
	WHITE						(\$15,775.00)	
	WHITE		- Total					
	WHITE Material - Total		- Total				(\$15,775.00)	
0460 -			- Total					
0460 - 0470	Material - Total - Total PREFORMED THERMOPLASTIC	Material	- Total	23	Aug 17, 2020	SYSTEM	(\$15,775.00)	
	Material - Total Total	Material	- Total	23	Aug 17, 2020	SYSTEM	(\$15,775.00) (\$15,775.00)	
	Material - Total Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	Material	- Total	23	Aug 17, 2020	SYSTEM	(\$15,775.00) (\$15,775.00)	
	Material - Total Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	Material		23	Aug 17, 2020	SYSTEM	(\$15,775.00) (\$15,775.00) (\$2,925.00)	

Revision 4/1/2020 Page 26 of 31



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0480	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		23	Aug 17, 2020	SYSTEM	(\$10,850.00)	
			- Total				(\$10,850.00)	
	Material - Total						(\$10,850.00)	
0480 -							(\$10,850.00)	
0490	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material		23	Aug 17, 2020	SYSTEM	(\$5,600.00)	
			- Total				(\$5,600.00)	
	Material - Total						(\$5,600.00)	
0490 -	Total						(\$5,600.00)	
0510	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		23	Aug 17, 2020	SYSTEM	(\$7,335.40)	
			- Total				(\$7,335.40)	
	Material - Total						(\$7,335.40)	
0510 -	Total						(\$7,335.40)	
0520	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		23	Aug 17, 2020	SYSTEM	(\$23,644.50)	
			- Total				(\$23,644.50)	
	Material - Total						(\$23,644.50)	
0520 -	Total						(\$23,644.50)	
0530	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		23	Aug 17, 2020	SYSTEM	(\$2,387.50)	
			- Total				(\$2,387.50)	
	Material - Total						(\$2,387.50)	
0530 -	Total						(\$2,387.50)	
0540	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION(LEFT)	Material		23	Aug 17, 2020	SYSTEM	(\$10,000.00)	
			- Total				(\$10,000.00)	
	Material - Total						(\$10,000.00)	
0540 -	Total						(\$10,000.00)	
0550	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, U-TURN ARROW (LEFT)	Material		23	Aug 17, 2020	SYSTEM	(\$3,000.00)	
			- Total				(\$3,000.00)	
	Material - Total						(\$3,000.00)	
0550 -	Total						(\$3,000.00)	
0560	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, U-TURN ONLY WORD	Material		23	Aug 17, 2020	SYSTEM	(\$1,500.00)	
			- Total				(\$1,500.00)	
	Material - Total						(\$1,500.00)	
0560 -							(\$1,500.00)	
0570	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	Overrun	Overrun	21	Jul 16, 2020	SYSTEM	(\$75,502.95)	
			Overrun - T	otal			(\$75,502.95)	
	Overrun - Total						(\$75,502.95)	
0570 -	Total						(\$75,502.95)	
0670	MISC. 12 IN. CLASS 3 RCP	Material		6	Dec 2, 2019	SYSTEM	(\$7,250.00)	
				7	Dec 17, 2019	SYSTEM	(\$11,450.00)	

Revision 4/1/2020 Page 27 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0670	MISC. 12 IN. CLASS 3 RCP	Material		8	Jan 2, 2020	SYSTEM	(\$11,450.00)	
			- Total				(\$30,150.00)	
	Material - Total						(\$30,150.00)	
	MISC. 12 IN. CLASS 3 RCP	MaterialCredit		7	Dec 17, 2019	SYSTEM	\$7,250.00	
				8	Jan 2, 2020	SYSTEM	\$11,450.00	
				9	Jan 16, 2020	SYSTEM	\$11,450.00	
			- Total				\$30,150.00	
	MaterialCredit - Total						\$30,150.00	
0670 -	- Total						\$0.00	
0680	MISC. 15 IN. CLASS 3 RCP	Material		6	Dec 2, 2019	SYSTEM	(\$1,749.00)	
				7	Dec 17, 2019	SYSTEM	(\$16,006.00)	
				8	Jan 2, 2020	SYSTEM	(\$16,006.00)	
			- Total				(\$33,761.00)	
	Material - Total MISC. 15 IN. CLASS 3 RCP	MaterialCredit		7	Dec 17, 2019	SYSTEM	(\$33,761.00) \$1,749.00	
				8	Jan 2, 2020	SYSTEM	\$16,006.00	
				9	Jan 16, 2020	SYSTEM	\$16,006.00	
			- Total		2020		\$33,761.00	
	MaterialCredit - Total						\$33,761.00	
	MISC. 15 IN. CLASS 3 RCP	Other Item Adjustment	PPPS	6	Dec 2, 2019	clowez1	\$1,749.00	Return of 33 LF.
				8	Jan 2, 2020	clowez1	\$14,257.00	269 linear ft. for description.
				9	Jan 16, 2020	clowez1	(\$16,006.00)	Taking back 302 ft. from estimate 6 and 8.
			PPPS - Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0680 -	- Total						\$0.00	
0722	MISC. 12 IN. CLASS 4 RCP	Other Item Adjustment	PPPS	9	Jan 16, 2020	clowez1	\$11,450.00	NB West used class 4 12" pipe instead of class 3.
				12	Mar 2, 2020	clowez1		Taking back PPPS due to new adjustment method in AWP.
			PPPS - Tota	1			\$0.00	
	Other Item Adjustment - Total	0	6		,	0)/075	\$0.00	
	MISC. 12 IN. CLASS 4 RCP	Overrun	Overrun		Jan 16, 2020	SYSTEM	(\$11,450.00)	
				13	Mar 16, 2020	SYSTEM	(\$7,450.00)	
				14	Apr 2, 2020 Apr 15,	SYSTEM	(\$13,850.00)	
					2020			
				16	May 4, 2020	SYSTEM	\$35,900.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',50.00000 - 50.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0722 -	- Total						\$0.00	
0740	MISC. MSD AREA INLET 58 IN. X 58 IN.	Material		19	Jun 15, 2020	SYSTEM	(\$2,500.00)	

Revision 4/1/2020 Page 28 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0740		Material	- Total				(\$2,500.00)	
	Material - Total						(\$2,500.00)	
	MISC. MSD AREA INLET 58 IN. X 58 IN.	MaterialCredit		20	Jul 1, 2020	SYSTEM	\$2,500.00	
			- Total				\$2,500.00	
	MaterialCredit - Total						\$2,500.00	
0740 -	Total						\$0.00	
0750	MISC. MSD DOUBLE STREET INLET 108 IN. X 52 IN.	Material		17	May 15, 2020	SYSTEM	(\$16,000.00)	
			- Total				(\$16,000.00)	
	Material - Total						(\$16,000.00)	
	MISC. MSD DOUBLE STREET INLET 108 IN. X 52 IN.	MaterialCredit		18	Jun 2, 2020	SYSTEM	\$16,000.00	
			- Total				\$16,000.00	
	MaterialCredit - Total						\$16,000.00	
0750 -	Total						\$0.00	
0770	MISC. REPLACE INLET TOP TO NEW GRADE	Material		4	Nov 4, 2019	SYSTEM	(\$4,800.00)	
				5	Nov 18, 2019	SYSTEM	(\$4,800.00)	
				6	Dec 2, 2019	SYSTEM	(\$6,400.00)	
				7	Dec 17, 2019	SYSTEM	(\$6,400.00)	
				8	Jan 2, 2020	SYSTEM	(\$6,400.00)	
				9	Jan 16, 2020	SYSTEM	(\$9,600.00)	
				10	Feb 3, 2020	SYSTEM	(\$12,800.00)	
				11	Feb 18, 2020	SYSTEM	(\$18,400.00)	
				12	Mar 2, 2020	SYSTEM	(\$20,000.00)	
				12	Mar 2, 2020	SYSTEM	\$20,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				(\$69,600.00)	
	Material - Total						(\$69,600.00)	
	MISC. REPLACE INLET TOP TO NEW GRADE	MaterialCredit		5	Nov 18, 2019	SYSTEM	\$4,800.00	
				6	Dec 2, 2019	SYSTEM	\$4,800.00	
				7	Dec 17, 2019	SYSTEM	\$6,400.00	
				8	Jan 2, 2020	SYSTEM	\$6,400.00	
				9	Jan 16, 2020	SYSTEM	\$6,400.00	
				10	Feb 3, 2020	SYSTEM	\$9,600.00	
				11	Feb 18, 2020	SYSTEM	\$12,800.00	
				12	Mar 2, 2020	SYSTEM	\$18,400.00	
			- Total				\$69,600.00	
	MaterialCredit - Total	a.i.					\$69,600.00	
	MISC. REPLACE INLET TOP TO NEW GRADE		PPPS		Dec 2, 2019	clowez1	\$6,400.00	Return of 8 inlet tops.
				9	Jan 16, 2020	clowez1	\$3,200.00	13 series inlets.

Revision 4/1/2020 Page 29 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0770	MISC. REPLACE INLET TOP TO NEW GRADE	Other Item Adjustment	PPPS	12	Mar 2, 2020	clowez1	(\$9,600.00)	Taking back PPPS due to new adjustment method in AWP.
			PPPS - Tota	ıl			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0770 -	· Total						\$0.00	
0780	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		15	Apr 15, 2020	SYSTEM	(\$800.00)	
				15	Apr 15, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0780 -	Total						\$0.00	
0790	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		12	Mar 2, 2020	SYSTEM	(\$1,700.00)	
				12	Mar 2, 2020	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0790 -	· Total						\$0.00	
0890	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material		13	Mar 16, 2020	SYSTEM	(\$9,510.00)	
			- Total				(\$9,510.00)	
	Material - Total						(\$9,510.00)	
	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	MaterialCredit		14	Apr 2, 2020	SYSTEM	\$9,510.00	
			- Total				\$9,510.00	
	MaterialCredit - Total						\$9,510.00	
0890 -	Total						\$0.00	
0900	CABLE, 16 AWG 7 CONDUCTOR	Material		13	Mar 16, 2020	SYSTEM	(\$2,250.00)	
			- Total				(\$2,250.00)	
	Material - Total						(\$2,250.00)	
	CABLE, 16 AWG 7 CONDUCTOR	MaterialCredit		14	Apr 2, 2020	SYSTEM	\$2,250.00	
			- Total				\$2,250.00	
	MaterialCredit - Total						\$2,250.00	
0900 -	Total						\$0.00	
0910	PULL BOX, PREFORMED CLASS 1	Material		13	Mar 16, 2020	SYSTEM	(\$4,500.00)	
			- Total				(\$4,500.00)	
	Material - Total						(\$4,500.00)	
	PULL BOX, PREFORMED CLASS 1	MaterialCredit		14	Apr 2, 2020	SYSTEM	\$4,500.00	
			- Total				\$4,500.00	
	MaterialCredit - Total						\$4,500.00	
0910 -							\$0.00	
5001	MISC. 12 IN. CLASS 5 RCP	Material		13	Mar 16, 2020	SYSTEM	(\$13,084.05)	
				13	Mar 16, 2020	SYSTEM	\$13,084.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5001 -	Total						\$0.00	

Revision 4/1/2020 Page 30 of 31



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5002	MISC. 15 IN. CLASS 5 RCP	Material		13	Mar 16, 2020	SYSTEM	(\$8,738.85)	
				13	Mar 16, 2020	SYSTEM	\$8,738.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5002 -	02 - Total						\$0.00	
5003	MISC. 18 IN. CLASS 5 RCP	Material		13	Mar 16, 2020	SYSTEM	(\$9,004.50)	
				13	Mar 16, 2020	SYSTEM	\$9,004.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5003 -	Total						\$0.00	
5005	MISC. 24 IN. CLASS 5 RCP	Material		18	Jun 2, 2020	SYSTEM	(\$5,854.14)	
				18	Jun 2, 2020	SYSTEM	\$5,854.14	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user cunnid3 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				19	Jun 15, 2020	SYSTEM	(\$5,854.14)	
				19	Jun 15, 2020	SYSTEM	\$5,854.14	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5005 -	Total						\$0.00	
5008	FIBER OPTIC CABLE, 24 - FIBER, 18 SINGLE MODE, 6 MULTIMODE	Material		16	May 4, 2020	SYSTEM	(\$1,391.25)	
			- Total				(\$1,391.25)	
	Material - Total						(\$1,391.25)	
	FIBER OPTIC CABLE, 24 - FIBER, 18 SINGLE MODE, 6 MULTIMODE	MaterialCredit		17	May 15, 2020	SYSTEM	\$1,391.25	
			- Total				\$1,391.25	
	MaterialCredit - Total						\$1,391.25	
5008 -	Total						\$0.00	
Overa	II - Total						(\$204,715.04)	

Revision 4/1/2020 Page 31 of 31