

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 1, 2021

Progress Estir 25		Contract ID Prime Contractor	190816-B02 Phillips Hardy, Inc.	Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,754,744.10 \$154,414.60 \$1,909,158.70
Approval Date							By User
April 1, 2021		Ger	nerated and Approve	ed (and should be co	onsidered Draft)	at the Project Office Level by	dwighj1
April 3, 2021		Reviewe	ed and Approved (ar	nd should be consid	ered Draft) at the	e Resident Engineer Level by	lincom
April 5, 2021	Reviewed and Approved at the Central Office Controllers Office Level by						ramses1
Original Comp	Original Completion Date		etion Date	Actual Completion	Date	% of Current Contract Amou	nt Complete
September	1, 2020	September 1	1, 2020			100.00%	

	Contract Informational Dates										
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract								
Acceptance Date											
Awarded Date	September 5, 2019	September 5, 2019									
Letting Date	August 16, 2019	August 16, 2019									
Notice to Proceed Date	March 16, 2020	March 16, 2020									
Open to Traffic Date											
Work Began Date											

Contract Total Pay For Estimate No. 25											
	This Estimate	Previous	To Date								
190816-B02											
Total Posted Items Pay	\$0.00	\$1,909,158.70	\$1,909,158.70								
Gross Item Adjustments	\$0.00	\$15,268.62	\$15,268.62								
Incentive	\$0.00	\$0.00	\$0.00								
Disincentive	\$0.00	\$0.00	\$0.00								
Liquidated Damage	\$0.00	\$0.00	\$0.00								
Other Contract Adjustments	\$0.00	(\$45,000.00)	(\$45,000.00)								
		\$1,879,427.32	\$1,879,427.32								
Contract Total Payable This Estimate:	\$0.00										

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item Adjustments This Estimate

No Data Available

Revision 4/1/2020 Page 1 of 20




Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information				
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work				
J2P3182	FAF 61-4(177)	2 Bridge rehabilitations	61	MARION	over Rte. 24 outer road 1.5 miles north of Rte. 6 near Taylor				
J2P3342	FAF-61-4(180)	Bridge rehabilitation	24	MARION	ION on ramp over Rte. 24 1.6 miles north of Rte. 6 at Taylor interchange				

otals by Job Numbers			
I2P3182	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$1,157,243.00	\$1,157,243.00
Gross Item Adjustments	\$0.00	\$15,615.86	\$15,615.86
Gross Item Pay	\$0.00	\$1,172,858.86	\$1,172,858.86
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	(\$27,279.00)	(\$27,279.00)
2P3342	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$751,915.70	\$751,915.70
Gross Item Adjustments	\$0.00	(\$347.24)	(\$347.24)
Gross Item Pay	\$0.00	\$751,568.46	\$751,568.46
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	(\$17,721.00)	(\$17,721.00)

Revision 4/1/2020 Page 2 of 20





Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 3 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					eport Generated date and can differ from the posted amo							
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190816-B02	J2P3182	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$18,100.00	\$18,100.00
		0001	0020	2153000	SHAPING SLOPES, CLASS III	7.00	-7.00	0.00	100F	0.00	\$1,100.00	\$0.00
		0001	0030	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	134.30	40.00	174.30	TONS	174.30	\$240.00	\$41,832.00
		0001	0040	4071005	TACK COAT	144.00	-16.00	128.00	GAL	128.00	\$6.00	\$768.00
		0001	0050	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$3,400.00	\$6,800.00
		0001	0060	6122020	REPLACEMENT SAND BARREL	4.00	-4.00	0.00	EA	0.00	\$200.00	\$0.00
		0001	0070	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.00
		0001	0080	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1.00	\$2.00
		0001	0090	6161005	CONSTRUCTION SIGNS	1,523.00	-314.00	1,209.00	SQFT	1,209.00	\$8.00	\$9,672.00
		0001	0100	6161008	ADVANCED WARNING RAIL SYSTEM	20.00	-4.00	16.00	EA	16.00	\$35.00	\$560.00
		0001	0110	6161009	FLAG ASSEMBLY	10.00	-4.00	6.00	EA	6.00	\$20.00	\$120.00
		0001	0120	6161025	CHANNELIZER (TRIM LINE)	150.00	-42.00	108.00	EA	108.00	\$20.00	\$2,160.00
		0001	0130	6161030	TYPE III MOVEABLE BARRICADE	15.00	-4.00	11.00	EA	11.00	\$100.00	\$1,100.00
		0001	0140	6161033	DIRECTIONAL INDICATOR BARRICADE	54.00	-12.00	42.00	EA	42.00	\$55.00	\$2,310.00
		0001	0150	6161040	FLASHING ARROW PANEL	3.00	0.00	3.00	EA	3.00	\$850.00	\$2,550.00
		0001	0160	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	3.00	0.00	3.00	EA	3.00	\$2,800.00	\$8,400.00
		0001	0170	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	6.00	0.00	6.00	EA	6.00	\$1,000.00	\$6,000.00
		0001	0180	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	976.00	48.00	1,024.00	LF	1,024.00	\$26.00	\$26,624.00
		0001	0190	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	976.00	48.00	1,024.00	LF	1,024.00	\$11.00	\$11,264.00
		0001	0200	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$134,000.00	\$134,000.00
		0001	0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,024.00	-41.00	983.00	LF	983.00	\$1.00	\$983.00
		0001	0220	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	823.00	0.00	823.00	LF	823.00	\$1.00	\$823.00
		0001	0230	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	845.00	79.00	924.00	LF	924.00	\$2.25	\$2,079.00
		0001	0240	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	165.00	-37.00	128.00	LF	128.00	\$8.00	\$1,024.00
		0001	0250	6207001	PAVEMENT MARKING REMOVAL	245.00	-81.00	164.00	LF	164.00	\$5.00	\$820.00
		0001	0260	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,434.00	0.00	1,434.00	SQYD	1,434.00	\$14.00	\$20,076.00
		0001	0270	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	3.00	0.00	3.00	STA	3.00	\$1,000.00	\$3,000.00
		0001	0280	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$3,000.00	\$3,000.00
		0010	0290	6061060	MGS GUARDRAIL	463.00	-463.00	0.00	LF	0.00	\$42.50	\$0.00
		0010	0300	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	-4.00	0.00	EA	0.00	\$3,940.00	\$0.00
		0010	0310	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	-2.00	0.00	EA	0.00	\$3,850.00	\$0.00
		0070	0320	2161501	REMOVAL OF ASPHALT WEARING SURFACE	11,356.00	0.00	11,356.00	SQFT	11,356.00	\$2.50	\$28,390.00
		0070	0330	2169904	MISC.RUBBLIZE EXISTING DECK REPAIR	500.00	2,091.00	2,591.00	SQFT	2,591.00	\$41.00	\$106,231.00
		0070	0340	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,262.00	0.00	1,262.00	SQYD	1,262.00	\$94.00	\$118,628.00
		0070	0350	7034600	CURB BLOCKOUT	514.00	0.00	514.00	LF	514.00	\$100.00	\$51,400.00
		0070	0360	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	25.00	-25.00	0.00	SQFT	0.00	\$145.00	\$0.00
		0070	0370	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	150.00	-63.00	87.00	SQFT	87.00	\$55.00	\$4,785.00
		0070	0380	7040106	FULL DEPTH REPAIR	25.00	-25.00	0.00	SQFT	0.00	\$130.00	\$0.00
		0070	0390	7040107	SLAB EDGE REPAIR (BRIDGES)	100.00	-71.00	29.00	LF	29.00	\$150.00	\$4,350.00
		0070	0400	7040109	TOTAL SURFACE HYDRO DEMOLITION	1,262.00	0.00	1,262.00	SQYD	1,262.00	\$48.50	\$61,207.00
		0070	0410	7040113	CLEANING AND EPOXY COATING	358.00	0.00	358.00	SQFT	358.00	\$10.00	\$3,580.00
		0070	0420	7040117	MONOLITHIC DECK REPAIR	11.00	31.00	42.00	CUYD	42.00	\$700.00	\$29,400.00
		0070	0430	7129902	MISC.CORED SLAB DRAINS	22.00	0.00	22.00	EA	22.00	\$605.00	\$13,310.00
		0071	0440	2161501	REMOVAL OF ASPHALT WEARING SURFACE	11,356.00	0.00	11,356.00	SQFT	11,356.00	\$2.50	\$28,390.00

Revision 4/1/2020 Page 4 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

1991 1992	Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
COUNTY GROUND COUNTY C	190816-B02	J2P3182	0071	0450	2169904	MISC.RUBBLIZE EXISTING DECK REPAIR	500.00	1,960.00	2,460.00	SQFT		\$41.00	\$100,860.00
1001 0-00 740/012 SUBSTRUCTURE REPAIR (UNFORMED) 2500 2500 0.00 541-00 0.00 140-00 300-00 310-000 0.00			0071	0460	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,262.00	0.00	1,262.00	SQYD	1,262.00	\$94.00	\$118,628.00
COT1 0890 70-0100 SUPERSTRUCTURE REPART (INFORMED) 150.00 -0.00 144.00 00TT 144.00 355.00 S 100.00 100T 144.00 355.00 S 100T 350.00 S 10			0071	0470	7034600	CURB BLOCKOUT	514.00	0.00	514.00	LF	514.00	\$100.00	\$51,400.00
			0071	0480	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	25.00	-25.00	0.00	SQFT	0.00	\$145.00	\$0.00
			0071	0490	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	150.00	-6.00	144.00	SQFT	144.00	\$55.00	\$7,920.00
DOT 0507 05010 TOTAL SURPACE HYDRO DEMOLITICM 1,992.01 0.00 1,962.00 0,907 1,962.00 546.00			0071	0500	7040106	FULL DEPTH REPAIR	25.00	-25.00	0.00	SQFT	0.00	\$130.00	\$0.00
COTT 0502 7340113 CLEANING AND EPICAY COATING 3860 0.00 356.00 0.00 356.00 0.00			0071	0510	7040107	SLAB EDGE REPAIR (BRIDGES)	100.00	-36.00	64.00	LF	64.00	\$150.00	\$9,600.00
1077 656			0071	0520	7040109	TOTAL SURFACE HYDRO DEMOLITION	1,262.00	0.00	1,262.00	SQYD	1,262.00	\$48.50	\$61,207.00
MOST 0550 7129902 MISC CORED SLAG DIVANES 22.00 0.00 22.00 EA 22.00 8005.000 ST			0071	0530	7040113	CLEANING AND EPOXY COATING	358.00	0.00	358.00	SQFT	358.00	\$10.00	\$3,580.00
			0071	0540	7040117	MONOLITHIC DECK REPAIR	11.00	27.00	38.00	CUYD	38.00	\$700.00	\$26,600.00
TRANSPIRON SECTION			0071	0550	7129902	MISC.CORED SLAB DRAINS	22.00	0.00	22.00	EA	22.00	\$605.00	\$13,310.00
Project JUZP-182 - Total Value Posted to Date and Report Generated Date 1.00 0			0001	5001	6069902	MISC.REINSTALLATION OF EXISTING BRIDGE APPROACH	0.00	4.00	4.00	EA	4.00	\$2,100.00	\$8,400.00
1,00 1,00		Dunia at II	2D2402 T	tol Value	Decked to D								64 457 242 00
0001 0600 3046910 MISC.TYPE 1 AGGREGATE 13.00 13.0							1.00	0.00	1.00	LS	1.00	\$11,000.00	\$1,157,243.00 \$11,000.00
MISC.TYPE 1 AGGREGATE				0570	2153000	SHAPING SLOPES, CLASS III	25.00		25.00	100F		\$1,015.00	\$25,375.00
Mathematical Control Mathematical Control Mathematical Control Mathematical Control Mathematical Ma				0580	3049910	MISC.TYPE 1 AGGREGATE	13.50	-13.50	0.00	TONS	0.00	\$48.50	\$0.00
0001 0600 071005 TACK COAT 30 00 17 00 47 00 GAL 47 00 \$6 00													\$18,550.00
Decoration Dec					4071005								\$282.00
0001 0020 6205002A 6. IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING 528.00 0.00 528.00 LF 528.00 \$1.00													\$84,000.00
PAINT, TYPE LEBADS CASSONA & STORMAN OF INTERPRETATION PAVEMENT S28.00													\$528.00
MARKING PAINT, TYPE L BEADS 417.00 417.00 50.00 417.00 50.00 417.00 50.00 52.00 51.00 52.00 51.00 52.00 51.00 52.00 51.00 52.00 51.00 52.00 51.00 52.00 51.00 52.00 51.00 52.00 52.00 51.00 52						PAINT, TYPE L BEADS							
D001			0001	0630	6205903A		528.00	0.00	528.00	LF	528.00	\$1.00	\$528.00
0010 0660 6061060 MGS GUARDRAIL 2.063.00 0.00 2.063.00 LF 2.063.00 \$25.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70 \$55.00 \$55.70			0001	0640	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	417.00	0.00	417.00	SQYD	417.00	\$25.00	\$10,425.00
0110 0670 6061069 MGS BRIDGE APPROACH TRANSITION SECTION 4.00 0.00 4.00 EA 4.00 \$2,795.00 \$\$1 0010 0680 6061080 MGS END ANCHOR 2.00 0.00 2.00 EA 2.00 \$1,100.00 \$\$ 0010 0680 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 2.00 0.00 2.00 EA 2.00 \$2,750.00 \$\$ 0079 0700 2161000 SCARIFICATION OF BRIDGE DECK 995.00 0.00 995.00 SQVD 995.00 \$215.00 \$\$2 0079 0710 2163000 PARTIAL REMOVAL OF EXISTING BRIDGE DECK 145.00 0.00 145.00 SQFT 145.00 \$76.50 \$\$1 0079 0720 2163502 PARTIAL REMOVAL OF EXISTING BRIDGE DECK 145.00 0.00 1.00 LS 1.00 \$94.00.00 \$\$ 0079 0730 2164500 REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT 76.00 0.00 76.00 LF 76.00 \$\$170.00 \$\$1 0079 0740 2169904 MISC REMOVE AND REPLACE BARRIER CURB 28.00 0.00 28.00 SQFT 28.00 \$1.050.00 \$\$2 0079 0760 5052000 LATEX MODIFIED CONCRETE WEARING SURFACE 995.00 0.00 995.00 SQVD 995.00 \$75.00 \$\$7 0079 0760 5052000 LATEX MODIFIED CONCRETE 19.90 0.00 19.90 CUYD 19.90 \$3.000.00 \$\$5 0079 0780 7034214 CLASS B-2 CONCRETE 19.90 0.00 19.90 CUYD 19.90 \$3.000.00 \$\$5 0079 0780 7034600 CURB BLOCKOUT 758.00 0.00 758.00 LF 758.00 \$85.00 \$\$6 0079 0800 7040101 SUBSTRUCTURE REPAIR (FORMED) 10.00 -1.00 9.00 SQFT 9.00 \$205.00 \$\$1 0079 0802 7040103 SUPERSTRUCTURE REPAIR (UNFORMED) 35.00 -25.00 0.00 SQFT 0.00 \$\$15.00 \$\$1 0079 0803 7040105 SUBSTRUCTURE REPAIR (UNFORMED) 35.00 -25.00 0.00 SQFT 0.00 \$\$15.00 \$\$1 0079 0800 7040101 SUBSTRUCTURE REPAIR (UNFORMED) 35.00 -25.00 0.00 SQFT 0.00 \$\$15.00 \$\$10.00 \$			0001	0650	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$3,000.00	\$3,000.00
(REGULARING CURB) 0010 0680 6061801 MGS END ANCHOR 0010 0690 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 2.00 0.00 2.00 EA 2.00 \$1,100.00 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$			0010	0660	6061060	MGS GUARDRAIL	2,063.00	0.00	2,063.00	LF	2,063.00	\$25.70	\$53,019.10
0010			0010	0670	6061069		4.00	0.00	4.00	EA	4.00	\$2,795.00	\$11,180.00
0079 0700 2161000 SCARIFICATION OF BRIDGE DECK 995.00 0.00 995.00 SQYD 995.00 \$21.50 \$22.50 \$20.0079 0710 2163000 PARTIAL REMOVAL OF EXISTING BRIDGE DECK 145.00 0.00 145.00 SQFT 145.00 \$76.50 \$1 \$1.00			0010	0680	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	2.00	\$1,100.00	\$2,200.00
0779 0710 2163000 PARTIAL REMOVAL OF EXISTING BRIDGE DECK 145.00 0.00 145.00 SQFT 145.00 \$76.50 \$1 10079 0720 2163502 PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE 1.00 0.00 1.00 LS 1.00 \$9,400.00 \$1 1.00 \$9,400.00 \$1 1.00			0010	0690	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	2.00	\$2,750.00	\$5,500.00
0079 0720 2163502 PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE 1.00 0.00 1.00 LS 1.00 \$9,400.00 \$ \$ \$ \$ \$ \$ \$ \$ \$			0079	0700	2161000	SCARIFICATION OF BRIDGE DECK	995.00	0.00	995.00	SQYD	995.00	\$21.50	\$21,392.50
0079 0730 2164500 REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT 76.00 0.00 76.00 LF 76.00 \$170.00 \$1 0079 0740 2169904 MISC.REMOVE AND REPLACE BARRIER CURB 28.00 0.00 28.00 \$QFT 28.00 \$1,050.00 \$2 0079 0750 2169904 MISC.RUBBLIZE EXISTING DECK REPAIR 100.00 53.00 153.00 \$QFT 153.00 \$41.00 \$ 0079 0760 5052000 LATEX MODIFIED CONCRETE WEARING SURFACE 995.00 0.00 995.00 \$QYD 995.00 \$75.00 \$7 0079 0770 7031004 DIAMOND GRINDING 995.00 -248.00 747.00 \$QYD 747.00 \$11.00 \$ 0079 0780 7034214 CLASS B-2 CONCRETE 19.90 0.00 19.90 CUYD 19.90 \$3,000.00 \$5 0079 0790 7034600 CURB BLOCKOUT 758.00 0.00 758.00 LF 758.00 \$6			0079	0710	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	145.00	0.00	145.00	SQFT	145.00	\$76.50	\$11,092.50
CONCRETE 0079 0740 2169904 MISC.REMOVE AND REPLACE BARRIER CURB 28.00 0.00 28.00 SQFT 28.00 \$1,050.00 \$2 0079 0750 2169904 MISC.RUBBLIZE EXISTING DECK REPAIR 100.00 53.00 153.00 SQFT 153.00 \$41.00 \$ 0079 0760 5052000 LATEX MODIFIED CONCRETE WEARING SURFACE 995.00 0.00 995.00 SQYD 995.00 \$75.00 \$7 0079 0770 7031004 DIAMOND GRINDING 995.00 -248.00 747.00 SQYD 747.00 \$11.00 \$ 0079 0780 7034214 CLASS B-2 CONCRETE 19.90 0.00 19.90 CUYD 19.90 \$3,000.00 \$55 0079 0790 7034600 CURB BLOCKOUT 758.00 0.00 758.00 LF 758.00 \$85.00 \$6 0079 0800 7040101 SUBSTRUCTURE REPAIR (FORMED) 10.00 -1.00 9.00 SQFT 9.00 \$205.00 \$ 0079 0810 7040102 SUBSTRUCTURE REPAIR (UNFORMED) 35.00 -35.00 0.00 SQFT 0.00 \$105.00 \$ 0079 0820 7040103 SUPERSTRUCTURE REPAIR (UNFORMED) 200.00 -139.00 61.00 SQFT 61.00 \$65.00 \$ 0079 0830 7040106 FULL DEPTH REPAIR (UNFORMED) 200.00 -139.00 61.00 SQFT 0.00 \$120.00 \$ 0079 0840 7040107 SLAB EDGE REPAIR (BRIDGES) 100.00 -4.00 96.00 LF 96.00 \$150.00 \$44.00			0079	0720	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	1.00	\$9,400.00	\$9,400.00
0079 0750 2169904 MISC.RUBBLIZE EXISTING DECK REPAIR 100.00 53.00 153.00 SQFT 153.00 \$41.00 \$ 0079 0760 5052000 LATEX MODIFIED CONCRETE WEARING SURFACE 995.00 0.00 995.00 SQYD 995.00 \$75.00 \$7 0079 0770 7031004 DIAMOND GRINDING 995.00 -248.00 747.00 SQYD 747.00 \$11.00 \$ 0079 0780 7034214 CLASS B-2 CONCRETE 19.90 0.00 19.90 CUYD 19.90 \$3,000.00 \$5 0079 0790 7034600 CURB BLOCKOUT 758.00 0.00 758.00 LF 758.00 \$85.00 \$8 0079 0800 7040101 SUBSTRUCTURE REPAIR (FORMED) 10.00 -1.00 9.00 SQFT 9.00 \$205.00 \$ 0079 0810 7040102 SUBSTRUCTURE REPAIR (UNFORMED) 35.00 -35.00 0.00 SQFT 0.00 \$150.00 \$			0079	0730	2164500		76.00	0.00	76.00	LF	76.00	\$170.00	\$12,920.00
0079 0760 5052000 LATEX MODIFIED CONCRETE WEARING SURFACE 995.00 0.00 995.00 SQYD 995.00 \$75.00 \$7 0079 0770 7031004 DIAMOND GRINDING 995.00 -248.00 747.00 SQYD 747.00 \$11.00 \$ 0079 0780 7034214 CLASS B-2 CONCRETE 19.90 0.00 19.90 CUYD 19.90 \$3,000.00 \$5 0079 0790 7034600 CURB BLOCKOUT 758.00 0.00 758.00 LF 758.00 \$6 0079 0800 7040101 SUBSTRUCTURE REPAIR (FORMED) 10.00 -1.00 9.00 SQFT 9.00 \$205.00 \$ 0079 0810 7040102 SUBSTRUCTURE REPAIR (UNFORMED) 35.00 -35.00 0.00 SQFT 0.00 \$105.00 0079 0820 7040103 SUPERSTRUCTURE REPAIR (UNFORMED) 200.00 -139.00 61.00 SQFT 61.00 \$65.00 \$ 0079 0830			0079	0740	2169904	MISC.REMOVE AND REPLACE BARRIER CURB	28.00	0.00	28.00	SQFT	28.00	\$1,050.00	\$29,400.00
0079 0770 7031004 DIAMOND GRINDING 995.00 -248.00 747.00 SQYD 747.00 \$11.00 \$ 0079 0780 7034214 CLASS B-2 CONCRETE 19.90 0.00 19.90 CUYD 19.90 \$3,000.00 \$5 0079 0790 7034600 CURB BLOCKOUT 758.00 0.00 758.00 LF 758.00 \$85.00 \$6 0079 0800 7040101 SUBSTRUCTURE REPAIR (FORMED) 10.00 -1.00 9.00 SQFT 9.00 \$205.00 \$ 0079 0810 7040102 SUBSTRUCTURE REPAIR (UNFORMED) 35.00 -35.00 0.00 SQFT 0.00 \$105.00 0079 0820 7040103 SUPERSTRUCTURE REPAIR (UNFORMED) 200.00 -139.00 61.00 SQFT 61.00 \$65.00 \$ 0079 0830 7040106 FULL DEPTH REPAIR 25.00 -25.00 0.00 SQFT 0.00 \$120.00 0079 0840 7040107 <td></td> <td></td> <td>0079</td> <td>0750</td> <td>2169904</td> <td>MISC.RUBBLIZE EXISTING DECK REPAIR</td> <td>100.00</td> <td>53.00</td> <td>153.00</td> <td>SQFT</td> <td>153.00</td> <td>\$41.00</td> <td>\$6,273.00</td>			0079	0750	2169904	MISC.RUBBLIZE EXISTING DECK REPAIR	100.00	53.00	153.00	SQFT	153.00	\$41.00	\$6,273.00
0079 0780 7034214 CLASS B-2 CONCRETE 19.90 0.00 19.90 CUYD 19.90 \$3,000.00 \$5 0079 0790 7034600 CURB BLOCKOUT 758.00 0.00 758.00 LF 758.00 \$85.00 \$6 0079 0800 7040101 SUBSTRUCTURE REPAIR (FORMED) 10.00 -1.00 9.00 SQFT 9.00 \$205.00 \$ 0079 0810 7040102 SUBSTRUCTURE REPAIR (UNFORMED) 35.00 -35.00 0.00 SQFT 0.00 \$105.00 0079 0820 7040103 SUPERSTRUCTURE REPAIR (UNFORMED) 200.00 -139.00 61.00 SQFT 61.00 \$65.00 \$ 0079 0830 7040106 FULL DEPTH REPAIR 25.00 -25.00 0.00 SQFT 0.00 \$120.00 0079 0840 7040107 SLAB EDGE REPAIR (BRIDGES) 100.00 -4.00 96.00 LF 96.00 \$43.00 \$4 0079 0850 704010			0079	0760	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	995.00	0.00	995.00	SQYD	995.00	\$75.00	\$74,625.00
0079 0790 7034600 CURB BLOCKOUT 758.00 0.00 758.00 LF 758.00 \$85.00 \$6 0079 0800 7040101 SUBSTRUCTURE REPAIR (FORMED) 10.00 -1.00 9.00 SQFT 9.00 \$205.00 \$ 0079 0810 7040102 SUBSTRUCTURE REPAIR (UNFORMED) 35.00 -35.00 0.00 SQFT 0.00 \$105.00 0079 0820 7040103 SUPERSTRUCTURE REPAIR (UNFORMED) 200.00 -139.00 61.00 SQFT 61.00 \$65.00 \$ 0079 0830 7040106 FULL DEPTH REPAIR 25.00 -25.00 0.00 SQFT 0.00 \$120.00 0079 0840 7040107 SLAB EDGE REPAIR (BRIDGES) 100.00 -4.00 96.00 LF 96.00 \$150.00 \$4 0079 0850 7040109 TOTAL SURFACE HYDRO DEMOLITION 995.00 0.00 995.00 \$QYD 995.00 \$43.00 \$4			0079	0770	7031004	DIAMOND GRINDING	995.00	-248.00	747.00	SQYD	747.00	\$11.00	\$8,217.00
0079 0800 7040101 SUBSTRUCTURE REPAIR (FORMED) 10.00 -1.00 9.00 SQFT 9.00 \$205.00 \$ 0079 0810 7040102 SUBSTRUCTURE REPAIR (UNFORMED) 35.00 -35.00 0.00 SQFT 0.00 \$105.00 0079 0820 7040103 SUPERSTRUCTURE REPAIR (UNFORMED) 200.00 -139.00 61.00 SQFT 61.00 \$65.00 \$ 0079 0830 7040106 FULL DEPTH REPAIR 25.00 -25.00 0.00 SQFT 0.00 \$120.00 0079 0840 7040107 SLAB EDGE REPAIR (BRIDGES) 100.00 -4.00 96.00 LF 96.00 \$150.00 \$1 0079 0850 7040109 TOTAL SURFACE HYDRO DEMOLITION 995.00 0.00 995.00 \$QYD 995.00 \$43.00 \$4			0079	0780	7034214	CLASS B-2 CONCRETE	19.90	0.00	19.90	CUYD	19.90	\$3,000.00	\$59,700.00
0079 0810 7040102 SUBSTRUCTURE REPAIR (UNFORMED) 35.00 -35.00 0.00 SQFT 0.00 \$105.00 0079 0820 7040103 SUPERSTRUCTURE REPAIR (UNFORMED) 200.00 -139.00 61.00 SQFT 61.00 \$65.00 \$ 0079 0830 7040106 FULL DEPTH REPAIR 25.00 -25.00 0.00 SQFT 0.00 \$120.00 0079 0840 7040107 SLAB EDGE REPAIR (BRIDGES) 100.00 -4.00 96.00 LF 96.00 \$150.00 \$1 0079 0850 7040109 TOTAL SURFACE HYDRO DEMOLITION 995.00 0.00 995.00 \$QYD 995.00 \$43.00 \$4			0079	0790	7034600	CURB BLOCKOUT	758.00	0.00	758.00	LF	758.00	\$85.00	\$64,430.00
0079 0820 7040103 SUPERSTRUCTURE REPAIR (UNFORMED) 200.00 -139.00 61.00 SQFT 61.00 \$65.00 \$ 0079 0830 7040106 FULL DEPTH REPAIR 25.00 -25.00 0.00 SQFT 0.00 \$120.00 0079 0840 7040107 SLAB EDGE REPAIR (BRIDGES) 100.00 -4.00 96.00 LF 96.00 \$150.00 \$1 0079 0850 7040109 TOTAL SURFACE HYDRO DEMOLITION 995.00 0.00 995.00 SQYD 995.00 \$43.00 \$4			0079	0800	7040101	SUBSTRUCTURE REPAIR (FORMED)	10.00	-1.00	9.00	SQFT	9.00	\$205.00	\$1,845.00
0079 0830 7040106 FULL DEPTH REPAIR 25.00 -25.00 0.00 SQFT 0.00 \$120.00 0079 0840 7040107 SLAB EDGE REPAIR (BRIDGES) 100.00 -4.00 96.00 LF 96.00 \$150.00 \$1 0079 0850 7040109 TOTAL SURFACE HYDRO DEMOLITION 995.00 0.00 995.00 SQYD 995.00 \$43.00 \$4			0079	0810	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	35.00	-35.00	0.00	SQFT	0.00	\$105.00	\$0.00
0079 0840 7040107 SLAB EDGE REPAIR (BRIDGES) 100.00 -4.00 96.00 LF 96.00 \$150.00 \$1 0079 0850 7040109 TOTAL SURFACE HYDRO DEMOLITION 995.00 0.00 995.00 SQYD 995.00 \$43.00 \$4			0079	0820	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	200.00	-139.00	61.00	SQFT	61.00	\$65.00	\$3,965.00
0079 0850 7040109 TOTAL SURFACE HYDRO DEMOLITION 995.00 0.00 995.00 SQYD 995.00 \$43.00 \$4			0079	0830	7040106	FULL DEPTH REPAIR	25.00	-25.00	0.00	SQFT	0.00	\$120.00	\$0.00
			0079	0840	7040107	SLAB EDGE REPAIR (BRIDGES)	100.00	-4.00	96.00	LF	96.00	\$150.00	\$14,400.00
0079 0860 7040113 CLEANING AND EPOXY COATING 355.00 0.00 355.00 SQFT 355.00 \$10.00 \$			0079	0850	7040109	TOTAL SURFACE HYDRO DEMOLITION	995.00	0.00	995.00	SQYD	995.00	\$43.00	\$42,785.00
			0079	0860	7040113	CLEANING AND EPOXY COATING	355.00	0.00	355.00	SQFT	355.00	\$10.00	\$3,550.00
0079 0870 7040117 MONOLITHIC DECK REPAIR 9.00 19.00 28.00 CUYD 28.00 \$700.00 \$1			0079	0870	7040117	MONOLITHIC DECK REPAIR	9.00	19.00	28.00	CUYD	28.00	\$700.00	\$19,600.00

Page 5 of 20 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190816-B02	J2P3342	0079	0880	7101000	REINFORCING STEEL (EPOXY COATED)	2,670.00	0.00	2,670.00	LB	2,670.00	\$3.25	\$8,677.50
		0079	0890	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.00
		0079	0900	7123130	REHABILITATE BEARING	4.00	0.00	4.00	EA	4.00	\$6,100.00	\$24,400.00
		0079	0910	7129902	MISC.CORED SLAB DRAIN	10.00	0.00	10.00	EA	10.00	\$710.00	\$7,100.00
		0079	0920	7129902	MISC.PIN AND PIN PLATE REPLACEMENT	2.00	0.00	2.00	EA	2.00	\$24,500.00	\$49,000.00
		0079	0930	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	76.00	0.00	76.00	LF	76.00	\$425.00	\$32,300.00
		0079	0940	7172054	OPEN CELL FOAM JOINT SEAL	32.00	0.00	32.00	LF	32.00	\$68.00	\$2,176.00
		0079	5101	7129901	MISC.Misc. Pin and Pin Plate ReplacementMisc. Pin and Plate Replacement, Thicker Plate Substitution Labor and Material	0.00	1.00	1.00	LS	1.00	\$14,080.10	\$14,080.10
	Project J	2P3342 - To	otal Value	Posted to E	ate as of Report Generated Date							\$751,915.70
190816-B02 Ove	rall - Total	Value Pos	ted to Da	te as of Rep	ort Generated Date							\$1,909,158.70

Page 6 of 20 Revision 4/1/2020



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable). DWR Total SF Project Line Sign Information Station Location Number Special Sign SF Total Quantity Mile Number Each Date of Items Each SF Posted For Special to Sign **DWR Date** Sign Post J2P3182 0090 March 30, SPECIAL 36x60 15.00 DETOUR ASSEMBLY 0.063 16' Rt of CL of Route 6 1.00 15 15 2020 (51C) WO20-1 48x48 16.00 20' Lt of CL of WB Route 3.780 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD WO20-1 48x48 16.00 24' Rt of CL of WB Route 16 16 3.780 1.00 ROAD/BRIDGE/RAMP WORK AHEAD EO5-2a 48x36 12.00 EXIT CLOSED 3.882 24' Rt of CL of WB Route 1.00 12 12 24 SPECIAL 7 96x48 32.00 POINT OF 24' Rt of CL of NBL Route 32 352.076 1.00 32 **PRESENCE** CONST-7-72 72x36 18.00 RATE OUR 352.193 24' Rt of CL of NBL Route 1.00 18 18 WORK ZONE CONST-8 48X36 See Special Sign Details 24' Lt of CL of NBL Route 12.00 352.286 1.00 12 12.00 WORK ZONE NO PHONE ZONE See Special Sign Details 20' Rt of CL of NBL Route 1.00 CONST-8 48X36 12.00 12 352.286 61 WORK ZONE NO PHONE ZONE WO20-1 48x48 16.00 16 20' Lt of CL of NB Route 1.00 16 ROAD/BRIDGE/RAMP WORK AHEAD WO20-1 48x48 16.00 24' Rt of CL of NB Route 16 16 352.395 1.00 ROAD/BRIDGE/RAMP WORK AHEAD R4-1 36x48 12.00 DO NOT PASS 20' Lt of CL of NBL Route 352,604 1.00 12 12 R4-1 36x48 12.00 DO NOT PASS 352.604 24' Rt of CL of NBL Route 1.00 12 12 G020-5aP 36x24 6.00 WORK ZONE 352.604 20' Lt of CL of NBL Route 1.00 6 6 (PLAQUE) 61 G020-5aP 36x24 6.00 WORK ZONE 352.604 24' Rt of CL of NBL Route 1.00 (PLAQUE) WO3-5 48x48 16.00 SPEED LIMIT 352.803 20' Lt of CL of NBL Route 1.00 16 16 XX AHEAD (SYMBOL) 48x48 16.00 SPEED LIMIT 352.803 24' Rt of CL of NBL Route 1.00 16 16 XX AHEAD (SYMBOL) R2-1 36x48 12.00 SPEED LIMIT 353.019 20' Lt of CL of NBL Route 1.00 12 12 XX R2-1 36x48 12.00 SPEED LIMIT 24' Rt of CL of NBL Route 12 12 353.019 1.00 XX 61 G020-5aP 36x24 6.00 WORK ZONE 20' Lt of CL of NBL Route 1.00 6 6 353.019 (PLAQUE) G020-5aP 36x24 6.00 WORK ZONE 6 6 353.019 24' Rt of CL of NBL Route 1.00 (PLAQUE) R4-2 36x48 12.00 PASS WITH 353.972 20' Lt of CL of NBL Route 1.00 12 12 CARE R4-2 36x48 12.00 PASS WITH 353.972 24' Rt of CL of NBL Route 1.00 12 12 CARE R2-1 36x48 12.00 SPEED LIMIT 20' Lt of CL of NBL Route 12 12 354.185 1.00 XX 61 R2-1 36x48 12.00 SPEED LIMIT 24' Rt of CL of NBL Route 1.00 12 12 354.185 SPECIAL 7 96x48 32.00 POINT OF 37.459 24' Rt of CL of SBL Route 1.00 32 32 CONST-7-72 72x36 18.00 RATE OUR 37.565 24' Rt of CL of SBL Route 1.00 18 18 WORK ZONE See Special Sign Details 37.701 20' Lt of CL of SBL Route 1.00 CONST-8 48X36 12.00 12 12 00 WORK ZONE 61 NO PHONE ZONE See Special Sign Details 37.701 24' Rt of CL of SBL Route 1.00 CONST-8 48x36 12.00 12 12.00 WORK ZONE NO PHONE ZONE WO20-1 48x48 16.00 37 783 20' Lt of CL of SB Route 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD

Revision 4/1/2020 Page 7 of 20

37.783

24' Rt of CL of SB Route

1.00

16

16

WO20-1 48x48 16.00



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

roject	Line	DWR	Total	etails for Construction Signs (if a	Station	Log	Location	Number	SF	Special Sign	SF	Tota
roject	Number	Date	Quantity Posted For DWR Date	Sign mormation	Station	Mile	Location	of Items	Each Sign	Special Sign	Each Special Sign	SF to Pos
P3182	0090	March 30, 2020	832	ROAD/BRIDGE/RAMP WORK AHEAD			61					
		2020		R4-1 36x48 12.00 DO NOT PASS		37.980	20' Lt of CL of SB Route 61	1.00	12			1
				R4-1 36x48 12.00 DO NOT PASS		37.980	24' Rt of CL of SB Route 61	1.00	12			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		37.980	20' Lt of CL of SB Route 61	1.00	6			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		37.980	24' Rt of CL of SB Route 61	1.00	6			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		38.185	20' Lt of CL of SB Route 61	1.00	16			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		38.185	24' Rt of CL of SB Route 61	1.00	16			
				WO3-5 48x48 16.00 SPEED LIMIT XX AHEAD (SYMBOL)		38.384	20' Lt of CL of SB Route 61	1.00	16			
				WO3-5 48x48 16.00 SPEED LIMIT XX AHEAD (SYMBOL)		38.384	24' Rt of CL of SB Route 61	1.00	16			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		38.585	24' Rt of CL of SB Route 61	1.00	16			
				WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)		38.585	20' Lt of CL of SB Route 61	1.00	16			
				R2-1 36x48 12.00 SPEED LIMIT XX		38.695	20' Lt of CL of SB Route 61	1.00	12			
				R2-1 36x48 12.00 SPEED LIMIT XX		38.695	24' Rt of CL of SB Route 61	1.00	12			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		38.695	20' Lt of CL of SB Route 61	1.00	6			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		38.695	24' Rt of CL of SB Route 61	1.00	6			
				EO5-2 48x36 12.00 EXIT OPEN		39.173	24' Rt of CL of SBL Route 61	1.00	12			
				R4-2 36x48 12.00 PASS WITH CARE		39.513	20' Lt of CL of SBL Route 61	1.00	12			
				R4-2 36x48 12.00 PASS WITH CARE		39.513	24' Rt of CL of SBL Route 61	1.00	12			
				R2-1 36x48 12.00 SPEED LIMIT XX		39.718	20' Lt of CL of SBL Route 61	1.00	12			
				R2-1 36x48 12.00 SPEED LIMIT XX		39.718	24' Rt of CL of SBL Route 61	1.00	12			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		4.284	20' Lt of CL of WB Route 24	1.00	16			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		4.284	24' Rt of CL of WB Route 24	1.00	16			
				EO5-2a 48x36 12.00 EXIT CLOSED		4.494	24' Rt of CL of WB Route 24	1	12			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		4.617	20' Lt of CL of WB Route 24	1.00	16			
				WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		4.617	24' Rt of CL of WB Route 24	1.00	16			
				R2-1 36x48 12.00 SPEED LIMIT XX		4.763	20' Lt of CL of WB Route 24	1.00	12			
				R2-1 36x48 12.00 SPEED LIMIT XX		4.763	24' Rt of CL of WB Route 24	1.00	12			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		4.763	20' Lt of CL of WB Route 24	1.00	6			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		4.763	24' Rt of CL of WB Route 24	1.00	6			
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		40.506	16' Rt of CL of WB Route 24/61 (51B)	1.00	15			

Revision 4/1/2020 Page 8 of 20



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable)

The info	rmation	below this	s line are de	etails for Construction Signs (if a	pplicat	ole).								
Project	Number DWR Total Quantity Posted For DWR Date		Posted For	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post		
J2P3182	0090	March 30, 2020	832	SPECIAL 36x60 15.00 DETOUR ASSEMBLY		40.777	13' Rt of CL of Ramp 2 @ Rte 6 (51C)	1.00	15			15		
				EO5-2a 48x36 12.00 EXIT CLOSED		5.043	6' Rt of CL of WB Route 24	1.00	12			12		
				EO5-2a 48x36 12.00 EXIT CLOSED		5.051	20' Rt of CL of WB Route 24	1.00	12			12		
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.195	16' Rt of CL of WB Route 24 (51A)	1	15			15		
		June 22, 2020	120	SPECIAL 36x60 15.00 DETOUR ASSEMBLY		39.428	24' Right of centerline of SB Route 61 (SB 61 to EB 24 detour)	1.00	15			15		
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		40.506	16' Right of centerline of SB Route 61 (SB 61 to EB 24 detour)	1.00	15			15		
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		40.777	13' Right of centerline of Ramp 2 @ Route 6 (SB 61 to EB 24 detour)	1.00	15			15		
				EO5-2a 48x36 12.00 EXIT CLOSED		37.822	34' Rt of centerline SB Route 61 (placard on existing shoulder sign)	1.00	12			12		
				EO5-2a 48x36 12.00 EXIT CLOSED		38.872	34' Right of centerline of SB Route 61 (placard on existing shoulder sign)	1.00	12			12		
				EO5-2a 48x36 12.00 EXIT CLOSED		39.207	32' Right of centelrine of SB Route 61 (placard on existing shoulder sign)	1.00	12			12		
				EO5-2a 48x36 12.00 EXIT CLOSED		39.382	18' Right of centelrine of SB Route 61 (placard on overhead sign)	1.00	12			12		
				EO5-2a 48x36 12.00 EXIT CLOSED		39.171	30' Right of centerline of SB Route 61 (post mounted sign)	1.00	12			12		
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.063	16' Right of centerline of EB Route 6 (SB 61 to EB 24)	1.00	15			15		
		June 26, 2020	64	WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		38.185	20' Left of centerline of SB Route 61	1.00	16			16		
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		38.185	24' Right of centerline of SB Route 61	1.00	16			16		
				WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		38.585	24' Right of centerline of SB Route 61	1.00	16			16		
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		38.585	20' Left of centerline of SB Route 61	1.00	16			16		
		November 4, 2020	193	See Special Sign Details		37.459	24' Rt of centerline of Southbound Route 61	1.00		Point of Presence (placard)	3.33	3.33		
				EO5-1 36x48 12.00 GORE EXIT		39.408	8' Rt of centerline of Southbound Route 61	1.00	12			12		
				R11-2 48x30 10.00 ROAD CLOSED		39.425	18' Rt of centerline of Southbound Route 61	1.00	10			10		
				EO5-1 36x48 12.00 GORE EXIT		5.124	12' Rt of centerline of Northbound Route 61	1.00	12			12		
						R11-2 48x30 10.00 ROAD CLOSED		5.152	on centerline of Eastbound Route 24 Ramp	1.00	10			10
								MO4-8a 24x18 3.00 END DETOUR		352.499	24' Rt of centerline of Northbound Route 61	1.00	3	
				See Special Sign Details		352.076	24' Rt of centerline of Northbound Route 61	1.00		Point of Presence (placard)	3.33	3.33		
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		3.698	24' Rt of centerline of Westbound Route 24	1.00	12			12		
			(CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		3.698	20' Lt of centerline of Westbound Route 24	1.00	12			12		
				CONST-7-72 72x36 18.00 RATE OUR WORK ZONE		3.562	24' Rt of centerline of Westbound Route 24	1.00	18			18		

Revision 4/1/2020 Page 9 of 20



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Tota SF to Pos
P3182	0090	November 4, 2020	193	SPECIAL 7 96x48 32.00 POINT OF PRESENCE		3.456	24' Rt of centerline of Westbound Route 24	1.00	32			32
				See Special Sign Details		3.456	24' Rt of centerline of Westbound Route 24	1.00		Point of Presence (placard)	3.33	3.33
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.871	16' Lt of centerline of County Road 308 (Eastbound Shoulder)	1.00	16			16
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.587	16' Rt of centerline of County Road 308 (Westbound Shoulder)	1.00	16			16
				R11-2 48x30 10.00 ROAD CLOSED		0.412	on centerline of Eastbound Route 24 Ramp	1.00	10			10
				See Special Sign Details				1.00		Wet Paint (Arrow Pivots)	2.19	2.19
				See Special Sign Details	0	0	on TMA truck for mobile work zone	1.00		Wet Paint (Arrow Pivots)	2.19	2.19
				See Special Sign Details		0	rounding to the nearest Square Foot for final quantity	1.00		rounding to the nearest square feet	-0.37	-0.3
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	0	0	on TMA truck for mobile work zone	1.00	16			10
	0090 - To	tal										120

Revision 4/1/2020 Page 10 of 20



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
82	0030	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	4	May 18, 2020	dwighj1	(\$50.32)	This AC Index Adjustment is for asphalt mix that was placed on April 30, 2020. The material was not paid for until Estimate 0004, which is the May 15, 2020 pay estimate, but it was placed during the previous estimate period. There were a total of 30.27 tons of SP125C mix placed (Mix ID: SP125 20-41), with a virgin AC of 3.8%.
					6	Jun 16, 2020	dwighj1	(\$359.10)	This Line Item Adjustment is for the AC Price Adjustment for asphalt that was placed on June 15, 2020. There were a total of 90 tons placed on that day, with a virgin asphalt content of 3.8%, with a mix ID of SP125 20-41.
					17	Dec 2, 2020	dwighj1	(\$228.41)	This Asphalt Cement Price Adjustment is being paid out for asphalt that was actually placed on August 28, 2020. The material was not paid until this estimate because the 54.03 tons that were paid on this estimate are an overrun and had to be approved by change order before payment. This adjustment is for Line No. 0030, and it is for 54.03 tons of asphalt, mix ID SP125 20-41, which has a 3.8% Virgin Asphalt Content. The total amount calculated by the AC Index spreadsheet was a deduction of -\$228.41 from the estimate.
				ACAD - Tota	al			(\$637.83)	
				FUEL	17	Dec 2, 2020	dwighj1	(\$130.95)	The system calculated and assessed fuel price index adjustment was applied to the amount of asphalt that was paid for on this estimate. A total of 54.03 tons were paid for on Line No. 0030 (Asphaltic Concrete Mixture PG 70-22, SP125C Mix), and the system used the fuel price index factor from November 2020, which is the period of time when the material amount was paid out. However, the asphalt was actually placed on August 28, 2020, and it was not paid for then due to a change order that was required authorizing the extra quantity. That change order was approved this pay period, and the 54.03 tons were paid out as a result. The fuel index changed slightly from the November 2020 calculation to the August 2020 calculation, so the underrun amount that the system assessed on this estimate is being added back to the estimate with another line adjustment. This adjustment is to deduct the correct amount for the fuel price index adjustment that was assessed using the August 2020 factor. The amount that should have been deducted from the estimate is -\$130.95, as the Fuel Price Index calculation sheet showed.
				FUEL - Tota				(\$130.95)	
				OTHR	17	Dec 2, 2020	dwighj1	\$132.74	The system calculated and assessed fuel price index adjustment was applied to the amount of asphalt that was paid for on this estimate. A total of 54.03 tons were paid for on Line No. 0030 (Asphaltic Concrete Mixture PG 70-22, SP125C Mix), and the system used the fuel price index factor from November 2020, which is the period of time when the material amount was paid out. However, the asphalt was actually placed on August 28, 2020, and it was not paid for then due to a change order that was required authorizing the extra quantity. That change order was approved this pay period, and the 54.03 tons were paid out as a result. The fuel index changed slightly from the November 2020 calculation to the August 2020 calculation, so the underrun amount that the system assessed on this estimate is being added back to the estimate with this Other line adjustment. The amount the system assessed was \$132.74, so that amount is being added back to the estimate. The correct assessment will be calculated and deducted back from the estimate on another line item adjustment.
				OTHR - Tota	al			\$132.74	
			Other Item Ad	ustment - To	tal			(\$636.04)	
			Price FUEL		4	May 18, 2020	SYSTEM	(\$108.54)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Jun 16, 2020	SYSTEM	(\$292.82)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					17	Dec 2, 2020	SYSTEM	(\$132.74)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Deion Elife	- Total				(\$534.10)	
	0000	T-4-1	Price FUEL - T	otal				(\$534.10)	
	0030 -							(\$1,170.14)	
	0050	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	Material		1	Apr 3, 2020	SYSTEM	\$6,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		DANNEL ARRAY)			1	Apr 3, 2020	SYSTEM	(\$6,800.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	0050 -	Total						\$0.00	
	0800	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	Material		1	Apr 3, 2020	SYSTEM	\$1.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		ATTEN (TMA)			1	Apr 3, 2020	SYSTEM	(\$1.00)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3182	0800	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	Material - Tota					\$0.00	
	0080 -	Total						\$0.00	
	0090	CONSTRUCTION SIGNS	Material		1	Apr 3, 2020	SYSTEM	\$6,656.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Apr 3, 2020	SYSTEM	(\$6,656.00)	
				- Total				\$0.00	
			Material - Tota	<u> </u>				\$0.00	
	0090 -	Total						\$0.00	
	0100	ADVANCED WARNING RAIL SYSTEM	Material		1	Apr 3, 2020	SYSTEM	\$560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Apr 3, 2020	SYSTEM	(\$560.00)	
				- Total				\$0.00	
			Material - Tota	1			\$0.00		
	0100 -	Total						\$0.00	
	0110	FLAG ASSEMBLY	Material		1	Apr 3, 2020	SYSTEM	\$120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					1	Apr 3, 2020	SYSTEM	(\$120.00)	
				- Total				\$0.00	
			Material - Tota	l				\$0.00	
	0110 -	Total						\$0.00	
	0120	CHANNELIZER (TRIM LINE)	Material		1	Apr 3, 2020	SYSTEM	\$1,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					1	Apr 3, 2020	SYSTEM	(\$1,860.00)	
				- Total				\$0.00	
			Material - Tota	<u> </u>				\$0.00	
	0120 -	Total						\$0.00	
	0130	TYPE III MOVEABLE BARRICADE	Material		1	Apr 3, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dwighj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				1		Apr 3, 2020	SYSTEM	(\$300.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0130 - 0140	Total DIRECTIONAL INDICATOR	Material		1	Apr 3, 2020	SYSTEM	\$0.00 \$2,310.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dwighj1 overridding Payment
		BARRICADE			1	Apr 3,	SYSTEM	(\$2,310.00)	Estimate Exception 8 on the current Payment Estimate.
				- Total		2020		\$0.00	
			Material - Tota						
	0140 -	Total	material - Tota					\$0.00	
	0140 -	FLASHING ARROW PANEL	Material		1	Apr 3, 2020	SYSTEM	\$0.00 \$2,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dwighj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					1	Apr 3, 2020	SYSTEM	(\$2,550.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0150 -	Total						\$0.00	
	0160	CMS W/O COMMUNICATION	Material		1	Apr 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dwighj1 overridding Payment



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
182	0160	INTERFACE, CONT	Material	,,,					Estimate Exception 10 on the current Payment Estimate.
		F/			1	Apr 3, 2020	SYSTEM	(\$8,400.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	0160 -							\$0.00	
	0170	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		1	Apr 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dwighj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					1	Apr 3, 2020	SYSTEM	(\$4,000.00)	
				- Total				\$0.00	
	0470	T-4-1	Material - Tota	<u> </u>				\$0.00	
ı	0170 -		Material		1	Apr 2	SVSTEM	\$0.00	This adjustment effects the original system generated Overrup Devment
	0180	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		1	Apr 3, 2020	SYSTEM	\$25,376.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dwighj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					1	Apr 3, 2020	SYSTEM	(\$25,376.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	0180 -	Total						\$0.00	
	0210	6 IN. WHITE HIGH BUILD WATERBORNE	Material		15	Nov 1, 2020	SYSTEM	\$983.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		PAINT			15	Nov 1, 2020	SYSTEM	(\$983.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0210 -	Total						\$0.00	
	0220	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		15	Nov 1, 2020	SYSTEM	\$823.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					15	Nov 1, 2020	SYSTEM	(\$823.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
J	0220 -	Total						\$0.00	
	0230	12 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material		15	Nov 1, 2020	SYSTEM	\$2,079.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dwighj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
		FAINT			15	Nov 1, 2020	SYSTEM	(\$2,079.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
			Overrun	Overrun	15	Nov 1, 2020	SYSTEM	\$177.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 20 on the current Payment Estimate.
					15	Nov 1, 2020	SYSTEM	(\$177.75)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
								\$0.00	
	0230 -								
	0230 - 0240	Total 24 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		15	Nov 1, 2020	SYSTEM	\$1,024.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
		24 IN. WHITE WATERBORNE PAVEMENT	Material		15		SYSTEM	\$1,024.00 (\$1,024.00)	Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment
		24 IN. WHITE WATERBORNE PAVEMENT	Material	- Total		2020 Nov 1,			Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment
		24 IN. WHITE WATERBORNE PAVEMENT MARKING	Material Material - Tota			2020 Nov 1,		(\$1,024.00)	Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J2P3182	0340	LATEX MODIFIED CONCRETE WEARING	Material		7	Jul 1, 2020	SYSTEM	\$59,314.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
		SURFACE			7	Jul 1, 2020	SYSTEM	(\$59,314.00)																	
				- Total				\$0.00																	
			Material - Tota					\$0.00																	
	0340 -	Total						\$0.00																	
	0350	CURB BLOCKOUT	Material		2	Apr 15, 2020	SYSTEM	(\$25,700.00)																	
					3	May 4, 2020	SYSTEM	\$25,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
					3	May 4, 2020	SYSTEM	(\$25,700.00)																	
					4	May 18, 2020	SYSTEM	\$25,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
					4	May 18, 2020	SYSTEM	(\$25,700.00)																	
					5	Jun 2, 2020	SYSTEM	\$25,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
					5	Jun 2, 2020	SYSTEM	(\$25,700.00)																	
					6	Jun 16, 2020	SYSTEM	\$25,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
					6	Jun 16, 2020	SYSTEM	(\$25,700.00)																	
					7	Jul 1, 2020	SYSTEM	\$25,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
					7	Jul 1, 2020	SYSTEM	(\$25,700.00)																	
					8	Jul 15, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
					8	Jul 15, 2020	SYSTEM	(\$51,400.00)																	
					9	Aug 3, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
					9	Aug 3, 2020	SYSTEM	(\$51,400.00)																	
																						10	Aug 16, 2020	SYSTEM	\$51,400.00
																					10	Aug 16, 2020	SYSTEM	(\$51,400.00)	
																11	Sep 2, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dwighj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
																	11	Sep 2, 2020	SYSTEM	(\$51,400.00)					
					12	Sep 15, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
					12	Sep 15, 2020	SYSTEM	(\$51,400.00)																	
				- Total				(\$25,700.00)																	
			Material - Tota					(\$25,700.00)																	
			MaterialCredit		3	May 4, 2020	SYSTEM	\$25,700.00																	
				- Total				\$25,700.00																	
			MaterialCredit	- Total				\$25,700.00																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
I2P3182	0350 -	Total						\$0.00	
	0370	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		7	Jul 1, 2020	SYSTEM	\$4,179.45	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dwighj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Jul 1, 2020	SYSTEM	(\$4,179.45)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0370 -	Total						\$0.00	
	0390	SLAB EDGE REPAIR (BRIDGES)	Material		7	Jul 1, 2020	SYSTEM	\$3,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dwighj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Jul 1, 2020	SYSTEM	(\$3,750.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0390 -	Total						\$0.00	
	0410	CLEANING AND EPOXY COATING	Material		11	Sep 2, 2020	SYSTEM	\$3,580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Sep 2, 2020	SYSTEM	(\$3,580.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0410 -	Total						\$0.00	
	0420	MONOLITHIC DECK REPAIR	Material		7	Jul 1, 2020	SYSTEM	\$13,153.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Jul 1, 2020	SYSTEM	(\$13,153.00)	
				- Total				\$0.00	
			Material - Tota	l				\$0.00	
			Overrun	Overrun	10	Aug 16, 2020	SYSTEM SYSTEM	(\$2,877.00) \$2,877.00	Unit price based on averaged overrun adjustments for installed quantity on all
					10	2020	STSTEW	\$2,077.00	previous payment estimates. Price Adjustments of ',700.00000 - 700.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0420 -						0.40===	\$0.00	
	0450	MISC. REMOVALS	Overrun	Overrun	7	May 18, 2020 Jul 1,	SYSTEM	(\$39,595.75) \$39,595.75	Unit price based on averaged overrun adjustments for installed quantity on all
						2020	2.0101		previous payment estimates. Price Adjustments of ',41.00000 - 41.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
	0.450	Total	Overrun - Tota	"				\$0.00	
		Total	Motorial		_	lu- 0	ever-1	\$0.00	This adjustment affects the original system research of Community
	0460	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		5	Jun 2, 2020	SYSTEM	\$118,628.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		-			5	Jun 2, 2020	SYSTEM	(\$118,628.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0460 -	Total						\$0.00	
	0470	CURB BLOCKOUT	Material		2	Apr 15, 2020	SYSTEM	(\$25,700.00)	
					3	May 4, 2020	SYSTEM	\$25,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment
						2020			Estimate Exception 1 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
82 0	0470	CURB BLOCKOUT	Material			2020			
					4	May 18, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 18, 2020	SYSTEM	(\$51,400.00)	
					5	Jun 2, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jun 2, 2020	SYSTEM	(\$51,400.00)	,
					6	Jun 16, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2020	SYSTEM	(\$51,400.00)	
					7	Jul 1, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jul 1, 2020	SYSTEM	(\$51,400.00)	
					8	Jul 15, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jul 15, 2020	SYSTEM	(\$51,400.00)	
					9	Aug 3, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Aug 3, 2020	SYSTEM	(\$51,400.00)	
					10	Aug 16, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Aug 16, 2020	SYSTEM	(\$51,400.00)	
					11	Sep 2, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Sep 2, 2020	SYSTEM	(\$51,400.00)	
					12	Sep 15, 2020	SYSTEM	\$51,400.00	This adjustment offsets the original system-generated Overrun Payment
									Estimate Exception 3 on the current Payment Estimate.
					12	Sep 15, 2020	SYSTEM	(\$51,400.00)	
				- Total	12		SYSTEM	(\$51,400.00) (\$25,700.00)	
			Material - Tota		12		SYSTEM	, , ,	
			Material - Tota MaterialCredit		3		SYSTEM	(\$25,700.00)	
						2020 May 4,		(\$25,700.00) (\$25,700.00)	
				l - Total		2020 May 4,		(\$25,700.00) (\$25,700.00) \$25,700.00	
	0470 -		MaterialCredit	l - Total		2020 May 4,	SYSTEM	(\$25,700.00) (\$25,700.00) \$25,700.00 \$25,700.00	Estimate Exception 3 on the current Payment Estimate.
		Total SUPERSTRUCTURE REPAIR (UNFORMED)	MaterialCredit	l - Total		2020 May 4,		(\$25,700.00) (\$25,700.00) \$25,700.00 \$25,700.00 \$25,700.00	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment
		SUPERSTRUCTURE REPAIR	MaterialCredit MaterialCredit	l - Total	3	May 4, 2020	SYSTEM	(\$25,700.00) (\$25,700.00) \$25,700.00 \$25,700.00 \$25,700.00 \$0.00	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dwighj1 overridding Payment
		SUPERSTRUCTURE REPAIR	MaterialCredit MaterialCredit Material	- Total - Total - Total	7	2020 May 4, 2020 Jul 1, 2020	SYSTEM	(\$25,700.00) (\$25,700.00) \$25,700.00 \$25,700.00 \$25,700.00 \$0.00 \$7,920.00	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dwighj1 overridding Payment
0.	0490	SUPERSTRUCTURE REPAIR (UNFORMED)	MaterialCredit MaterialCredit	- Total - Total - Total	7	2020 May 4, 2020 Jul 1, 2020	SYSTEM	(\$25,700.00) (\$25,700.00) \$25,700.00 \$25,700.00 \$25,700.00 \$0.00 \$7,920.00) \$0.00 \$0.00	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dwighj1 overridding Payment
0	0490 0490 -	SUPERSTRUCTURE REPAIR (UNFORMED)	MaterialCredit MaterialCredit Material Material - Tota	- Total - Total - Total	7	May 4, 2020 Jul 1, 2020 Jul 1, 2020	SYSTEM SYSTEM	(\$25,700.00) (\$25,700.00) \$25,700.00 \$25,700.00 \$25,700.00 \$0.00 \$7,920.00) \$0.00 \$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
0	0490	SUPERSTRUCTURE REPAIR (UNFORMED)	MaterialCredit MaterialCredit Material Material - Tota	- Total - Total - Total	7	2020 May 4, 2020 Jul 1, 2020	SYSTEM	(\$25,700.00) (\$25,700.00) \$25,700.00 \$25,700.00 \$25,700.00 \$0.00 \$7,920.00) \$0.00 \$0.00	Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dwighj1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3182	0510	SLAB EDGE REPAIR (BRIDGES)	Material	- Total				\$0.00	
		, ,	Material - Total					\$0.00	
		Total						\$0.00	
	0530	CLEANING AND EPOXY COATING	Material		11	Sep 2, 2020	SYSTEM	\$3,580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user dwighj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Sep 2, 2020	SYSTEM	(\$3,580.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	0530 -							\$0.00	
	0540	MONOLITHIC DECK REPAIR	Material		5	Jun 2, 2020	SYSTEM	\$26,565.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Jun 2, 2020	SYSTEM	(\$26,565.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
			Other Item Adjustment	OTHR	6	Jun 16, 2020	dwighj1	\$16,786.00	This Line Item Adjustment is to put back the amount deducted by the system on this line number on estimate 0006. The system made an overrun adjustment automatically of -\$16,786.00, and nothing was paid out on this line number on this estimate. Change Order 0002 will correct the quantity to resolve this discrepancy, but the system is trying to deduct the overrun amount again on this estimate.
				OTHR - Tota	ıl			\$16,786.00	
			Other Item Ad	justment - To	tal			\$16,786.00	
			Overrun	Overrun	3	May 4, 2020	SYSTEM	\$2,079.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dwighj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	May 4, 2020	SYSTEM	(\$2,079.00)	
					4	May 18, 2020	SYSTEM	(\$2,079.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Jun 2, 2020	SYSTEM	\$16,786.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Jun 2, 2020	SYSTEM	(\$16,786.00)	
					6	Jun 16, 2020	SYSTEM	(\$16,786.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Jul 1, 2020	SYSTEM	\$18,865.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',700.00000 - 700.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0540 -	Total						\$16,786.00	
J2P3182 -	- Total							\$15,615.86	
J2P3342	0590	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	17	Dec 2, 2020	dwighj1	(\$224.06)	This Asphalt Cement Price Adjustment is being paid out for asphalt that was actually placed on September 3, 2020. The material was not paid until this estimate because the 53.00 tons that were paid on this estimate are an overrun and had to be approved by change order before payment. This adjustment is for Line No. 0590, and it is for 53.00 tons of asphalt, mix ID SP125 20-41, which has a 3.8% Virgin Asphalt Content. The total amount calculated by the AC Index spreadsheet was a deduction of \$224.06 from the estimate.
				ACAD - Tota	al			(\$224.06)	
				OTHR		Dec 16, 2020	dwighj1	\$6.64	This adjustment is to give back the system generated fuel adjustment assessed for the 4 tons of asphalt that was paid out on this pay estimate. The material was actually placed on September 4, 2020, and that fuel price index should used for the material. It was paid on this estimate because a change order was needed to get the line item to the correct final quantity.
					18	Dec 16, 2020	dwighj1	(\$9.30)	This line item adjustment is to deduct the correct amount from the contract for the fuel adjustment for the asphalt that was placed on September 3, 2020. There were an additional four tons that had to be paid for this pay period, due to a change order that added those four tons to the contract. The system assessed a fuel adjustment using the December index, which was added back with another contract adjustment on this estimate (Estimate #0018). This adjustment is deducting a total of -\$9.30 from the contract, which is the correct



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
23342	0590	ASPHALTIC	Other Item	OTHR					amount to deduct using the First Period of September 2020 Fuel Index.
		CONCRETE MIXTURE PG 70-22	Adjustment	OTHR - Tota	al			(\$2.66)	
		(SP125C MIX)	Other Item Ad	justment - To	tal			(\$226.72)	
			Overrun	Overrun	12	Sep 15, 2020	SYSTEM	(\$7,266.43)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					16	Nov 16, 2020	SYSTEM	\$7,266.43	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',347.67608 - 350.00000, 'is applied (if non-zero).
				Overrun - T	- Total			\$0.00	is applied (if first 2010).
			Overrun - Tota					\$0.00	
			Price FUEL		12	Sep 15, 2020	SYSTEM	(\$113.88)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					18	Dec 16, 2020	SYSTEM	(\$6.64)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$120.52)	
			Price FUEL - T	Fotal Fotal				(\$120.52)	
	0590 -				40	0 45	OVOTELA	(\$347.24)	
	0600	TACK COAT	Overrun	Overrun	12	Sep 15, 2020 Nov 16,	SYSTEM	(\$102.00) \$102.00	Unit price based on averaged overrun adjustments for installed quantity on all
					10	2020	OTOTEW	ψ102.00	previous payment estimates. Price Adjustments of ',6.00000 - 6.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0600 -							\$0.00	
	0620	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material		15	Nov 1, 2020	SYSTEM	\$528.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Nov 1, 2020	SYSTEM	(\$528.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0620 -	Total						\$0.00	
	0630	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	BUILD		15	Nov 1, 2020	SYSTEM	\$528.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dwighj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					15	Nov 1, 2020	SYSTEM	(\$528.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	0630 -	Total						\$0.00	
	0660	MGS GUARDRAIL	Construction Stockpile		10	Aug 16, 2020	SYSTEM	(\$22,012.21)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$22,012.21)	
			Construction Stockpile	Stockpile - To	3	May 4, 2020	SYSTEM	(\$22,012.21) \$22,012.21	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$22,012.21	
			Construction :	l Stockpile STI	/II - Total			\$22,012.21	
	0660 -	Total						\$0.00	
	0670	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		10	Aug 16, 2020	SYSTEM	(\$5,541.59)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(INCOMO CORD)			11	Sep 1, 2020	SYSTEM	(\$454.41)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$5,996.00)	
			Construction	otockpile - To		Mov 4	SYSTEM	(\$5,996.00)	Payment Estimate Item Adjustment generated Starting Transaction
			Construction Stockpile STMI		3	May 4, 2020	SISIEM	\$5,996.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$5,996.00	
			Construction	Stockpile STI	/II - Total			\$5,996.00	



Page March Michael Page	oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Stocyto Construction Stockpile Total Stock Sto	23342	0670 -	Total						\$0.00	
Construction Stockpile Total S SYSTEM System-percental Coverus Payment Estimate Exception 1 on the current Payment Estimate System-percental Coverus Payment Statement Syste		0680	MGS END ANCHOR			11		SYSTEM	(\$1,070.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Study Train Total Study										
Sincaple 2000					Stockpile - To					
				Stockpile		3		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
March September March September		0000	T-4-1	Construction	Stockpile STI	VII - I otal				
Construction Stockpile Total (\$3,000,000) Construction Stockpile Total (\$3,000,000) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Transaction Stockpile Transaction Stockpile Transaction Trans			TYPE A CRSHWTHY			10		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile - Total Suggest				Otockpile	- Total		2020		(\$3,020,00)	
Construction Stocklete STM Total S.0.00.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STM Total S.0.00.00				Construction S		otal				
Stockpile STM					oto on pilo		May 4.	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile STMI - Total Substitution S				Stockpile					**,*=****	3
				OTIVII	- Total				\$3,020.00	
Overrun				Construction S	Stockpile STMI - Total				\$3,020.00	
2020 16		0690 -	Total						\$0.00	
2020 September		0750	MISC. REMOVALS	Overrun	Overrun	8		SYSTEM	(\$2,180.38)	
						16		SYSTEM	\$2,180.38	previous payment estimates. Price Adjustments of ',41.00000 - 41.00000, 'is
CLASS B-2					Overrun - T	otal			\$0.00	
Total				Overrun - Tota	ıl				\$0.00	
CONCRETE 2020 Estimate Item Adjustment (006) due to user dwight] overridding Payment Estimate Exception 1 on the current Payment Estimate.		0750 -	Total						\$0.00	
1		0780		Material		10		SYSTEM	\$18,300.00	Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment
2020 Estimate tem Adjustment (0018) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 10						10		SYSTEM	(\$18,300.00)	
11						11		SYSTEM	\$59,700.00	Estimate Item Adjustment (0018) due to user dwighj1 overridding Payment
Naterial - Total S0.00						11		SYSTEM	(\$59,700.00)	,
O790 CURB BLOCKOUT Material 10					- Total				\$0.00	
10				Material - Tota	ı				\$0.00	
2020 Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		0780 -	Total						\$0.00	
11		0790	CURB BLOCKOUT	Material		10		SYSTEM	\$64,430.00	Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment
Estimate Item Adjustment (0016) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 11 Sep 2, 2020 12 Sep 15, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 12 Sep 15, 2020 SySTEM (\$64,430.00) -Total \$0.00 Material - Total \$0.00 Overrun Overrun Overrun 11 Sep 2, 2020 SySTEM (\$13,139.00) Unit price based on averaged overrun adjustments for installed quantity on all						10		SYSTEM	(\$64,430.00)	
2020 12 Sep 15, 2YSTEM \$64,430.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 12 Sep 15, 2YSTEM \$64,430.00 - Total \$0.00 Material - Total \$0.00 0790 - Total \$0.00 0870 MONOLITHIC DECK REPAIR Overrun Overrun 11 Sep 2, 2020 SYSTEM \$13,139.00 16 Nov 16, SYSTEM \$13,139.00 Unit price based on averaged overrun adjustments for installed quantity on all						11		SYSTEM	\$64,430.00	Estimate Item Adjustment (0016) due to user dwighj1 overridding Payment
2020 Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 12 Sep 15, 2020 SYSTEM (\$64,430.00)						11		SYSTEM	(\$64,430.00)	
12 Sep 15, 2020 SYSTEM (\$64,430.00)						12		SYSTEM	\$64,430.00	Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment
Material - Total						12		SYSTEM	(\$64,430.00)	, , , , , , , , , , , , , , , , , , , ,
Material - Total					- Total				\$0.00	
Nov 16, SYSTEM Sq.00 Unit price based on averaged overrun adjustments for installed quantity on all				Material - Tota						
0870 MONOLITHIC DECK REPAIR Overrun Overrun 11 Sep 2, SYSTEM (\$13,139.00) 16 Nov 16, SYSTEM \$13,139.00 Unit price based on averaged overrun adjustments for installed quantity on all		07 <u>90</u> -	Total							
16 Nov 16, SYSTEM \$13,139.00 Unit price based on averaged overrun adjustments for installed quantity on all			MONOLITHIC DECK	Overrun	Overrun	11		SYSTEM		
						16	Nov 16,	SYSTEM	\$13,139.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',700.00000 - 700.00000,



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3342	0870	MONOLITHIC DECK	Overrun	Overrun					'is applied (if non-zero).
		REPAIR		Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0870 -	· Total						\$0.00	
	0890	PROTECTIVE COATING - CONCRETE BENTS	Material		12	Sep 15, 2020	SYSTEM	(\$5,000.00)	
		AND			13	Sep 30, 2020	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Sep 30, 2020	SYSTEM	(\$5,000.00)	
				- Total				(\$5,000.00)	
			Material - Tota	ı				(\$5,000.00)	
			MaterialCredit		13	Sep 30, 2020	SYSTEM	\$5,000.00	
				- Total				\$5,000.00	
			MaterialCredit	- Total				\$5,000.00	
	0890 -	· Total						\$0.00	
	0900	REHABILITATE BEARING	Material		9	Aug 3, 2020	SYSTEM	\$12,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Aug 3, 2020	SYSTEM	(\$12,200.00)	
					10	Aug 16, 2020	SYSTEM	\$12,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dwighj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Aug 16, 2020	SYSTEM	(\$12,200.00)	
					11	Sep 2, 2020	SYSTEM	\$12,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user dwighj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					11	Sep 2, 2020	SYSTEM	(\$12,200.00)	
				- Total				\$0.00	
			Material - Tota	l				\$0.00	
	0900 -	· Total						\$0.00	
	0920	MISC.	Material		10	Aug 16, 2020	SYSTEM	\$24,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dwighj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Aug 16, 2020	SYSTEM	(\$24,500.00)	
					11	Sep 2, 2020	SYSTEM	\$49,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user dwighj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Sep 2, 2020	SYSTEM	(\$49,000.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0920 -	· Total						\$0.00	
J2P3342 -	Total							(\$347.24)	
Overall -	Total							\$15,268.62	