

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 15, 2021

| Progress Estir 28 | | Contract ID Prime Contractor | 190816-B02 Phillips Hardy, Inc. | Pay Period Start Pay Period End | | Original Contract Amount Net Change Order Amount Current Contract Amount | \$1,754,744.10 \$154,414.60 \$1,909,158.70 |
|----------------------|---|------------------------------|------------------------------------|------------------------------------|-------------------|--|--|
| Approval Date | | | | | | | By User |
| May 15, 2021 | | Gen | erated and Approve | d (and should be co | nsidered Draft) | at the Project Office Level by | dwighj1 |
| May 17, 2021 | | Reviewe | d and Approved (and | d should be conside | red Draft) at the | e Resident Engineer Level by | lincom |
| May 18, 2021 | | | Reviewe | d and Approved at t | the Central Offi | ce Controllers Office Level by | ramses1 |
| Original Comp | npletion Date Current Completion Date Actual Completion Date % of Current Contract Am | | | | | | |
| September | ber 1, 2020 September 1, 2020 100.00% | | | | | | |

| | Contract Informational Dat | es | Milestones |
|------------------------|----------------------------|--------------------------------|----------------------------------|
| Date Description | Original Completion Date | Current Completion Date | No Milestones Exist for Contract |
| Acceptance Date | | | |
| Awarded Date | September 5, 2019 | September 5, 2019 | |
| Letting Date | August 16, 2019 | August 16, 2019 | |
| Notice to Proceed Date | March 16, 2020 | March 16, 2020 | |
| Open to Traffic Date | | | |
| Work Began Date | | | |

| Contract Total Pay For Estimate No. 28 | | | | | | | | | | | | | |
|--|---------------|----------------|----------------|--|--|--|--|--|--|--|--|--|--|
| | This Estimate | Previous | To Date | | | | | | | | | | |
| 190816-B02 | | | | | | | | | | | | | |
| Total Posted Items Pay | \$0.00 | \$1,909,158.70 | \$1,909,158.70 | | | | | | | | | | |
| Gross Item Adjustments | \$0.00 | \$15,268.62 | \$15,268.62 | | | | | | | | | | |
| Incentive | \$0.00 | \$0.00 | \$0.00 | | | | | | | | | | |
| Disincentive | \$0.00 | \$0.00 | \$0.00 | | | | | | | | | | |
| Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | | | | | | | | | | |
| Other Contract Adjustments | \$0.00 | (\$45,000.00) | (\$45,000.00) | | | | | | | | | | |
| | | \$1,879,427.32 | \$1,879,427.32 | | | | | | | | | | |
| Contract Total Payable This Estimate: | \$0.00 | | | | | | | | | | | | |

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item Adjustments This Estimate

No Data Available

Revision 4/1/2020 Page 1 of 20




Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | Contract Project Information | | | | | | |
|-------------------|--------------------------|--------------------------|----|--------|--|--|--|--|--|--|--|
| Project Number | umber Number Description | | | | | | | | | | |
| J2P3182 | FAF 61-4(177) | 2 Bridge rehabilitations | 61 | MARION | over Rte. 24 outer road 1.5 miles north of Rte. 6 near Taylor | | | | | | |
| J2P3342 | FAF-61-4(180) | Bridge rehabilitation | 24 | MARION | on ramp over Rte. 24 1.6 miles north of Rte. 6 at Taylor interchange | | | | | | |

| I2P3182 | This Estimate | Previous | To Date |
|----------------------------|---------------|----------------|----------------|
| Posted Item Pay | \$0.00 | \$1,157,243.00 | \$1,157,243.00 |
| Gross Item Adjustments | \$0.00 | \$15,615.86 | \$15,615.86 |
| Gross Item Pay | \$0.00 | \$1,172,858.86 | \$1,172,858.86 |
| Incentive | \$0.00 | \$0.00 | \$0.00 |
| Disincentive | \$0.00 | \$0.00 | \$0.00 |
| Liquidated Damages | \$0.00 | \$0.00 | \$0.00 |
| Other Contract Adjustments | \$0.00 | (\$27,279.00) | (\$27,279.00) |
| | | , | , |
| 2P3342 | This Estimate | Previous | To Date |
| Posted Item Pay | \$0.00 | \$751,915.70 | \$751,915.70 |
| Gross Item Adjustments | \$0.00 | (\$347.24) | (\$347.24) |
| Gross Item Pay | \$0.00 | \$751,568.46 | \$751,568.46 |
| Incentive | \$0.00 | \$0.00 | \$0.00 |
| Disincentive | \$0.00 | \$0.00 | \$0.00 |
| Liquidated Damages | \$0.00 | \$0.00 | \$0.00 |
| Other Contract Adjustments | \$0.00 | (\$17,721.00) | (\$17,721.00) |

Revision 4/1/2020 Page 2 of 20





Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 3 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| | | | | | eport Generated date and can differ from the posted amo | | | | | | | |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| 190816-B02 | J2P3182 | 0001 | 0010 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$18,100.00 | \$18,100.00 |
| | | 0001 | 0020 | 2153000 | SHAPING SLOPES, CLASS III | 7.00 | -7.00 | 0.00 | 100F | 0.00 | \$1,100.00 | \$0.00 |
| | | 0001 | 0030 | 4030103 | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) | 134.30 | 40.00 | 174.30 | TONS | 174.30 | \$240.00 | \$41,832.00 |
| | | 0001 | 0040 | 4071005 | TACK COAT | 144.00 | -16.00 | 128.00 | GAL | 128.00 | \$6.00 | \$768.00 |
| | | 0001 | 0050 | 6122017 | IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,400.00 | \$6,800.00 |
| | | 0001 | 0060 | 6122020 | REPLACEMENT SAND BARREL | 4.00 | -4.00 | 0.00 | EA | 0.00 | \$200.00 | \$0.00 |
| | | 0001 | 0070 | 6122030 | IMPACT ATTENUATOR (RELOCATION) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,000.00 | \$2,000.00 |
| | | 0001 | 0080 | 6123000A | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1.00 | \$2.00 |
| | | 0001 | 0090 | 6161005 | CONSTRUCTION SIGNS | 1,523.00 | -314.00 | 1,209.00 | SQFT | 1,209.00 | \$8.00 | \$9,672.00 |
| | | 0001 | 0100 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 20.00 | -4.00 | 16.00 | EA | 16.00 | \$35.00 | \$560.00 |
| | | 0001 | 0110 | 6161009 | FLAG ASSEMBLY | 10.00 | -4.00 | 6.00 | EA | 6.00 | \$20.00 | \$120.00 |
| | | 0001 | 0120 | 6161025 | CHANNELIZER (TRIM LINE) | 150.00 | -42.00 | 108.00 | EA | 108.00 | \$20.00 | \$2,160.00 |
| | | 0001 | 0130 | 6161030 | TYPE III MOVEABLE BARRICADE | 15.00 | -4.00 | 11.00 | EA | 11.00 | \$100.00 | \$1,100.00 |
| | | 0001 | 0140 | 6161033 | DIRECTIONAL INDICATOR BARRICADE | 54.00 | -12.00 | 42.00 | EA | 42.00 | \$55.00 | \$2,310.00 |
| | | 0001 | 0150 | 6161040 | FLASHING ARROW PANEL | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$850.00 | \$2,550.00 |
| | | 0001 | 0160 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$2,800.00 | \$8,400.00 |
| | | 0001 | 0170 | 6162002 | TEMPORARY LONG-TERM RUMBLE STRIPS | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$1,000.00 | \$6,000.00 |
| | | 0001 | 0180 | 6173600D | TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED | 976.00 | 48.00 | 1,024.00 | LF | 1,024.00 | \$26.00 | \$26,624.00 |
| | | 0001 | 0190 | 6175010A | RELOCATING TEMPORARY TRAFFIC BARRIER | 976.00 | 48.00 | 1,024.00 | LF | 1,024.00 | \$11.00 | \$11,264.00 |
| | | 0001 | 0200 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$134,000.00 | \$134,000.00 |
| | | 0001 | 0210 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 1,024.00 | -41.00 | 983.00 | LF | 983.00 | \$1.00 | \$983.00 |
| | | 0001 | 0220 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 823.00 | 0.00 | 823.00 | LF | 823.00 | \$1.00 | \$823.00 |
| | | 0001 | 0230 | 6205906A | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 845.00 | 79.00 | 924.00 | LF | 924.00 | \$2.25 | \$2,079.00 |
| | | 0001 | 0240 | 6206124A | 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 165.00 | -37.00 | 128.00 | LF | 128.00 | \$8.00 | \$1,024.00 |
| | | 0001 | 0250 | 6207001 | PAVEMENT MARKING REMOVAL | 245.00 | -81.00 | 164.00 | LF | 164.00 | \$5.00 | \$820.00 |
| | | 0001 | 0260 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 1,434.00 | 0.00 | 1,434.00 | SQYD | 1,434.00 | \$14.00 | \$20,076.00 |
| | | 0001 | 0270 | 6261000A | BITUMINOUS SHOULDER RUMBLE STRIP | 3.00 | 0.00 | 3.00 | STA | 3.00 | \$1,000.00 | \$3,000.00 |
| | | 0001 | 0280 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$3,000.00 | \$3,000.00 |
| | | 0010 | 0290 | 6061060 | MGS GUARDRAIL | 463.00 | -463.00 | 0.00 | LF | 0.00 | \$42.50 | \$0.00 |
| | | 0010 | 0300 | 6061069 | MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) | 4.00 | -4.00 | 0.00 | EA | 0.00 | \$3,940.00 | \$0.00 |
| | | 0010 | 0310 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 2.00 | -2.00 | 0.00 | EA | 0.00 | \$3,850.00 | \$0.00 |
| | | 0070 | 0320 | 2161501 | REMOVAL OF ASPHALT WEARING SURFACE | 11,356.00 | 0.00 | 11,356.00 | SQFT | 11,356.00 | \$2.50 | \$28,390.00 |
| | | 0070 | 0330 | 2169904 | MISC.RUBBLIZE EXISTING DECK REPAIR | 500.00 | 2,091.00 | 2,591.00 | SQFT | 2,591.00 | \$41.00 | \$106,231.00 |
| | | 0070 | 0340 | 5052000 | LATEX MODIFIED CONCRETE WEARING SURFACE | 1,262.00 | 0.00 | 1,262.00 | SQYD | 1,262.00 | \$94.00 | \$118,628.00 |
| | | 0070 | 0350 | 7034600 | CURB BLOCKOUT | 514.00 | 0.00 | 514.00 | LF | 514.00 | \$100.00 | \$51,400.00 |
| | | 0070 | 0360 | 7040102 | SUBSTRUCTURE REPAIR (UNFORMED) | 25.00 | -25.00 | 0.00 | SQFT | 0.00 | \$145.00 | \$0.00 |
| | | 0070 | 0370 | 7040103 | SUPERSTRUCTURE REPAIR (UNFORMED) | 150.00 | -63.00 | 87.00 | SQFT | 87.00 | \$55.00 | \$4,785.00 |
| | | 0070 | 0380 | 7040106 | FULL DEPTH REPAIR | 25.00 | -25.00 | 0.00 | SQFT | 0.00 | \$130.00 | \$0.00 |
| | | 0070 | 0390 | 7040107 | SLAB EDGE REPAIR (BRIDGES) | 100.00 | -71.00 | 29.00 | LF | 29.00 | \$150.00 | \$4,350.00 |
| | | 0070 | 0400 | 7040109 | TOTAL SURFACE HYDRO DEMOLITION | 1,262.00 | 0.00 | 1,262.00 | SQYD | 1,262.00 | \$48.50 | \$61,207.00 |
| | | 0070 | 0410 | 7040113 | CLEANING AND EPOXY COATING | 358.00 | 0.00 | 358.00 | SQFT | 358.00 | \$10.00 | \$3,580.00 |
| | | 0070 | 0420 | 7040117 | MONOLITHIC DECK REPAIR | 11.00 | 31.00 | 42.00 | CUYD | 42.00 | \$700.00 | \$29,400.00 |
| | | 0070 | 0430 | 7129902 | MISC.CORED SLAB DRAINS | 22.00 | 0.00 | 22.00 | EA | 22.00 | \$605.00 | \$13,310.00 |
| | | 0071 | 0440 | 2161501 | REMOVAL OF ASPHALT WEARING SURFACE | 11,356.00 | 0.00 | 11,356.00 | SQFT | 11,356.00 | \$2.50 | \$28,390.00 |

Revision 4/1/2020 Page 4 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|--|-------------|----------------------------------|--------------|---|-----------------|------------------------|------------------------|---------|------------------------------------|-------------|--|
| 190816-B02 | J2P3182 | 0071 | 0450 | 2169904 | MISC.RUBBLIZE EXISTING DECK REPAIR | 500.00 | 1,960.00 | 2,460.00 | SQFT | 2,460.00 | \$41.00 | \$100,860.00 |
| | | 0071 | 0460 | 5052000 | LATEX MODIFIED CONCRETE WEARING SURFACE | 1,262.00 | 0.00 | 1,262.00 | SQYD | 1,262.00 | \$94.00 | \$118,628.00 |
| | | 0071 | 0470 | 7034600 | CURB BLOCKOUT | 514.00 | 0.00 | 514.00 | LF | 514.00 | \$100.00 | \$51,400.00 |
| | | 0071 | 0480 | 7040102 | SUBSTRUCTURE REPAIR (UNFORMED) | 25.00 | -25.00 | 0.00 | SQFT | 0.00 | \$145.00 | \$0.00 |
| | Project Category Line Rem Code C | | SUPERSTRUCTURE REPAIR (UNFORMED) | 150.00 | -6.00 | 144.00 | SQFT | 144.00 | \$55.00 | \$7,920.00 | | |
| | | 0071 | 0500 | 7040106 | FULL DEPTH REPAIR | 25.00 | -25.00 | 0.00 | SQFT | 0.00 | \$130.00 | \$0.00 |
| | | 0071 | 0510 | 7040107 | SLAB EDGE REPAIR (BRIDGES) | 100.00 | -36.00 | 64.00 | LF | 64.00 | \$150.00 | \$9,600.00 |
| | | 0071 | 0520 | 7040109 | TOTAL SURFACE HYDRO DEMOLITION | 1,262.00 | 0.00 | 1,262.00 | SQYD | 1,262.00 | \$48.50 | \$61,207.00 |
| | | 0071 | 0530 | 7040113 | CLEANING AND EPOXY COATING | 358.00 | 0.00 | 358.00 | SQFT | 358.00 | \$10.00 | \$3,580.00 |
| | | 0071 | 0540 | 7040117 | MONOLITHIC DECK REPAIR | 11.00 | 27.00 | 38.00 | CUYD | 38.00 | \$700.00 | \$26,600.00 |
| | | 0071 | 0550 | 7129902 | MISC.CORED SLAB DRAINS | 22.00 | 0.00 | 22.00 | EA | 22.00 | \$605.00 | \$13,310.00 |
| | | 0001 | 5001 | 6069902 | MISC.REINSTALLATION OF EXISTING BRIDGE APPROACH TRANSITION SECTION | 0.00 | 4.00 | 4.00 | EA | 4.00 | \$2,100.00 | \$8,400.00 |
| | Project J2 | 2P3182 - To | tal Value | Posted to D | | | | | | | | \$1,157,243.00 |
| | J2P3342 | 0001 | 0560 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$11,000.00 | \$11,000.00 |
| | | 0001 | 0570 | 2153000 | SHAPING SLOPES, CLASS III | 25.00 | 0.00 | 25.00 | 100F | 25.00 | \$1,015.00 | \$25,375.00 |
| | | 0001 | 0580 | 3049910 | MISC.TYPE 1 AGGREGATE | 13.50 | -13.50 | 0.00 | TONS | 0.00 | \$48.50 | \$0.00 |
| | | 0001 | 0590 | 4030103 | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) | 28.10 | 24.90 | 53.00 | TONS | 53.00 | \$350.00 | \$18,550.00 |
| | | 0001 | 0600 | 4071005 | TACK COAT | 30.00 | 17.00 | 47.00 | GAL | 47.00 | \$6.00 | \$282.00 |
| | | 0001 | 0610 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$84,000.00 | \$84,000.00 |
| | | 0001 | 0620 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 528.00 | 0.00 | 528.00 | LF | 528.00 | \$1.00 | \$528.00 |
| | | 0001 | 0630 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 528.00 | 0.00 | 528.00 | LF | 528.00 | \$1.00 | \$528.00 |
| | | 0001 | 0640 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 417.00 | 0.00 | 417.00 | SQYD | 417.00 | \$25.00 | \$10,425.00 |
| | | 0001 | 0650 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$3,000.00 | \$3,000.00 |
| | | 0010 | 0660 | 6061060 | MGS GUARDRAIL | 2,063.00 | 0.00 | 2,063.00 | LF | 2,063.00 | \$25.70 | \$53,019.10 |
| | | 0010 | 0670 | 6061069 | MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$2,795.00 | \$11,180.00 |
| | | 0010 | 0680 | 6061080 | MGS END ANCHOR | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,100.00 | \$2,200.00 |
| | | 0010 | 0690 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$2,750.00 | \$5,500.00 |
| | | 0079 | 0700 | 2161000 | SCARIFICATION OF BRIDGE DECK | 995.00 | 0.00 | 995.00 | SQYD | 995.00 | \$21.50 | \$21,392.50 |
| | | 0079 | 0710 | 2163000 | PARTIAL REMOVAL OF EXISTING BRIDGE DECK | 145.00 | 0.00 | 145.00 | SQFT | 145.00 | \$76.50 | \$11,092.50 |
| | | 0079 | 0720 | 2163502 | PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$9,400.00 | \$9,400.00 |
| | | 0079 | 0730 | 2164500 | REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE | 76.00 | 0.00 | 76.00 | LF | 76.00 | \$170.00 | \$12,920.00 |
| | | 0079 | 0740 | 2169904 | MISC.REMOVE AND REPLACE BARRIER CURB | 28.00 | 0.00 | 28.00 | SQFT | 28.00 | \$1,050.00 | \$29,400.00 |
| | | 0079 | 0750 | 2169904 | MISC.RUBBLIZE EXISTING DECK REPAIR | 100.00 | 53.00 | 153.00 | SQFT | 153.00 | \$41.00 | \$6,273.00 |
| | | 0079 | 0760 | 5052000 | LATEX MODIFIED CONCRETE WEARING SURFACE | 995.00 | 0.00 | 995.00 | SQYD | 995.00 | \$75.00 | \$74,625.00 |
| | | 0079 | 0770 | 7031004 | DIAMOND GRINDING | 995.00 | -248.00 | 747.00 | SQYD | 747.00 | \$11.00 | \$8,217.00 |
| | | 0079 | 0780 | 7034214 | CLASS B-2 CONCRETE | 19.90 | 0.00 | 19.90 | CUYD | 19.90 | \$3,000.00 | \$59,700.00 |
| | | 0079 | 0790 | 7034600 | CURB BLOCKOUT | 758.00 | 0.00 | 758.00 | LF | 758.00 | \$85.00 | \$64,430.00 |
| | | 0079 | 0800 | 7040101 | SUBSTRUCTURE REPAIR (FORMED) | 10.00 | -1.00 | 9.00 | SQFT | 9.00 | \$205.00 | \$1,845.00 |
| | | 0079 | 0810 | 7040102 | SUBSTRUCTURE REPAIR (UNFORMED) | 35.00 | -35.00 | 0.00 | SQFT | 0.00 | \$105.00 | \$0.00 |
| | | 0079 | 0820 | 7040103 | SUPERSTRUCTURE REPAIR (UNFORMED) | 200.00 | -139.00 | 61.00 | SQFT | 61.00 | \$65.00 | \$3,965.00 |
| | | 0079 | 0830 | 7040106 | FULL DEPTH REPAIR | 25.00 | -25.00 | 0.00 | SQFT | 0.00 | \$120.00 | \$0.00 |
| | | 0079 | 0840 | 7040107 | SLAB EDGE REPAIR (BRIDGES) | 100.00 | -4.00 | 96.00 | LF | 96.00 | \$150.00 | \$14,400.00 |
| | | 0079 | 0850 | 7040109 | TOTAL SURFACE HYDRO DEMOLITION | 995.00 | 0.00 | 995.00 | SQYD | 995.00 | \$43.00 | \$42,785.00 |
| | | 0079 | 0860 | 7040113 | CLEANING AND EPOXY COATING | 355.00 | 0.00 | 355.00 | SQFT | 355.00 | \$10.00 | \$3,550.00 |
| | | 0079 | 0870 | 7040117 | MONOLITHIC DECK REPAIR | 9.00 | 19.00 | 28.00 | CUYD | 28.00 | \$700.00 | \$19,600.00 |

Page 5 of 20 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|-------------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 190816-B02 | J2P3342 | 0079 | 0880 | 7101000 | REINFORCING STEEL (EPOXY COATED) | 2,670.00 | 0.00 | 2,670.00 | LB | 2,670.00 | \$3.25 | \$8,677.50 |
| | | 0079 | 0890 | 7110200 | PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY) | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$5,000.00 | \$5,000.00 |
| | | 0079 | 0900 | 7123130 | REHABILITATE BEARING | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$6,100.00 | \$24,400.00 |
| | | 0079 | 0910 | 7129902 | MISC.CORED SLAB DRAIN | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$710.00 | \$7,100.00 |
| | | 0079 | 0920 | 7129902 | MISC.PIN AND PIN PLATE REPLACEMENT | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$24,500.00 | \$49,000.00 |
| | | 0079 | 0930 | 7172001 | STRIP SEAL EXPANSION JOINT SYSTEM | 76.00 | 0.00 | 76.00 | LF | 76.00 | \$425.00 | \$32,300.00 |
| | | 0079 | 0940 | 7172054 | OPEN CELL FOAM JOINT SEAL | 32.00 | 0.00 | 32.00 | LF | 32.00 | \$68.00 | \$2,176.00 |
| | | 0079 | 5101 | 7129901 | MISC.Misc. Pin and Pin Plate ReplacementMisc. Pin and Plate Replacement, Thicker Plate Substitution Labor and Material | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$14,080.10 | \$14,080.10 |
| | Project J | 2P3342 - To | tal Value | Posted to D | Date as of Report Generated Date | | | | | | | \$751,915.70 |
| 190816-B02 Ove | rall - Total | Value Post | ed to Da | te as of Rep | ort Generated Date | | | | | | | \$1,909,158.70 |

Page 6 of 20 Revision 4/1/2020



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

| The info | rmation | below this | s line are de | etails for Construction Signs (if a | pplicat | ole). | | | | | | | | | | | | | | | | | | | | | | | |
|----------|----------------|-------------------|---|--|---------|-------------|---------------------------------|--------------------|---|---|-------------------------------|---------------------------------|------|----|--------------------------|--|--------|---------------------------------|------|--|---|-------|--------|---------------------------------|------|--|---|-------|----|
| Project | Line Number | DWR Date | Total Quantity Posted For DWR Date | Sign Information | Station | Log Mile | Location | Number of Items | SF Each Sign | Special Sign | SF Each Special Sign | Total SF to Post | | | | | | | | | | | | | | | | | |
| J2P3182 | 0090 | March 30, 2020 | 832 | SPECIAL 36x60 15.00 DETOUR ASSEMBLY | | 0.063 | 16' Rt of CL of Route 6 (51C) | 1.00 | 15 | | | 15 | | | | | | | | | | | | | | | | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 3.780 | 20' Lt of CL of WB Route 24 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 3.780 | 24' Rt of CL of WB Route 24 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | | |
| | | | | EO5-2a 48x36 12.00 EXIT CLOSED | | 3.882 | 24' Rt of CL of WB Route 24 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | | |
| | | | | SPECIAL 7 96x48 32.00 POINT OF PRESENCE | | 352.076 | 24' Rt of CL of NBL Route 61 | 1.00 | 32 | | | 32 | | | | | | | | | | | | | | | | | |
| | | | | CONST-7-72 72x36 18.00 RATE OUR WORK ZONE | | 352.193 | 24' Rt of CL of NBL Route 61 | 1.00 | 18 | | | 18 | | | | | | | | | | | | | | | | | |
| | | | | See Special Sign Details | | 352.286 | 24' Lt of CL of NBL Route 61 | 1.00 | | CONST-8 48X36 12.00 WORK ZONE NO PHONE ZONE | 12.00 | 12 | | | | | | | | | | | | | | | | | |
| | | | | See Special Sign Details | | 352.286 | 20' Rt of CL of NBL Route 61 | 1.00 | | CONST-8 48X36 WORK ZONE NO PHONE ZONE | 12.00 | 12 | | | | | | | | | | | | | | | | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 352.395 | 20' Lt of CL of NB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 352.395 | 24' Rt of CL of NB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | | |
| | | | | R4-1 36x48 12.00 DO NOT PASS | | 352.604 | 20' Lt of CL of NBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | | |
| | | | | R4-1 36x48 12.00 DO NOT PASS | | 352.604 | 24' Rt of CL of NBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | | |
| | | | | G020-5aP 36x24 6.00 WORK ZONE (PLAQUE) | | 352.604 | 20' Lt of CL of NBL Route 61 | 1.00 | 6 | | | 6 | | | | | | | | | | | | | | | | | |
| | | | | G020-5aP 36x24 6.00 WORK ZONE (PLAQUE) | | 352.604 | 24' Rt of CL of NBL Route 61 | 1.00 | 6 | | | 6 | | | | | | | | | | | | | | | | | |
| | | | | WO3-5 48x48 16.00 SPEED LIMIT XX AHEAD (SYMBOL) | | 352.803 | 20' Lt of CL of NBL Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | | |
| | | | | WO3-5 48x48 16.00 SPEED LIMIT XX AHEAD (SYMBOL) | | 352.803 | 24' Rt of CL of NBL Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | | |
| | | | | R2-1 36x48 12.00 SPEED LIMIT XX | | 353.019 | 20' Lt of CL of NBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | | |
| | | | | R2-1 36x48 12.00 SPEED LIMIT XX | | 353.019 | 24' Rt of CL of NBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | | |
| | | | | G020-5aP 36x24 6.00 WORK ZONE (PLAQUE) | | 353.019 | 20' Lt of CL of NBL Route 61 | 1.00 | 6 | | | 6 | | | | | | | | | | | | | | | | | |
| | | | | G020-5aP 36x24 6.00 WORK ZONE (PLAQUE) | | 353.019 | 24' Rt of CL of NBL Route 61 | 1.00 | 6 | | | 6 | | | | | | | | | | | | | | | | | |
| | | | | R4-2 36x48 12.00 PASS WITH CARE | | 353.972 | 20' Lt of CL of NBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | | |
| | | | | R4-2 36x48 12.00 PASS WITH CARE | | 353.972 | 24' Rt of CL of NBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | | |
| | | | | R2-1 36x48 12.00 SPEED LIMIT XX | | 354.185 | 20' Lt of CL of NBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | | |
| | | | | R2-1 36x48 12.00 SPEED LIMIT XX | | 354.185 | 24' Rt of CL of NBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | | |
| | | | | SPECIAL 7 96x48 32.00 POINT OF PRESENCE | | 37.459 | 24' Rt of CL of SBL Route 61 | 1.00 | 32 | | | 32 | | | | | | | | | | | | | | | | | |
| | | | | | | | | | CONST-7-72 72x36 18.00 RATE OUR WORK ZONE | | 37.565 | 24' Rt of CL of SBL Route 61 | 1.00 | 18 | | | 18 | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | See Special Sign Details | | 37.701 | 20' Lt of CL of SBL Route 61 | 1.00 | | CONST-8 48X36 12.00 WORK ZONE NO PHONE ZONE | 12.00 | 12 |
| | | | | | | | | | | | | | | | See Special Sign Details | | 37.701 | 24' Rt of CL of SBL Route 61 | 1.00 | | CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE | 12.00 | 12 | | | | | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 37.783 | 20' Lt of CL of SB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | | |
| | | | | WO20-1 48x48 16.00 | | 37.783 | 24' Rt of CL of SB Route | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | | |

Revision 4/1/2020 Page 7 of 20



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

| Project | Line | DWR | Total | Sign Information | Station | Log | Location | Number | SF | Special Sign | SF | Total | | | | | | | | | | | | | | | | |
|---------|--------|-----------|------------------------------------|--|---------|--------|---|--|--------------|--------------|--------------------------------|------------------|---------------------------------|--|--------|--|------|--|--|---------------------------------|--------------------------------|--------------------------------|--------------------------------|------|----|----|----|----|
| | Number | Date | Quantity Posted For DWR Date | | | Mile | | of Items | Each Sign | | Each Special Sign | SF to Post | | | | | | | | | | | | | | | | |
| J2P3182 | 0090 | March 30, | 832 | ROAD/BRIDGE/RAMP WORK AHEAD | | | 61 | | | | | | | | | | | | | | | | | | | | | |
| | | 2020 | | R4-1 36x48 12.00 DO NOT PASS | | 37.980 | 20' Lt of CL of SB Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | |
| | | | | R4-1 36x48 12.00 DO NOT PASS | | 37.980 | 24' Rt of CL of SB Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | |
| | | | | G020-5aP 36x24 6.00 WORK ZONE (PLAQUE) | | 37.980 | 20' Lt of CL of SB Route 61 | 1.00 | 6 | | | 6 | | | | | | | | | | | | | | | | |
| | | | | G020-5aP 36x24 6.00 WORK ZONE (PLAQUE) | | 37.980 | 24' Rt of CL of SB Route 61 | 1.00 | 6 | | | 6 | | | | | | | | | | | | | | | | |
| | | | | WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD | | 38.185 | 20' Lt of CL of SB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | |
| | | | | WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD | | 38.185 | 24' Rt of CL of SB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | |
| | | | | WO3-5 48x48 16.00 SPEED LIMIT XX AHEAD (SYMBOL) | | 38.384 | 20' Lt of CL of SB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | |
| | | | | WO3-5 48x48 16.00 SPEED LIMIT XX AHEAD (SYMBOL) | | 38.384 | 24' Rt of CL of SB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | |
| | | | | WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED | | 38.585 | 24' Rt of CL of SB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | |
| | | | | WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT) | | 38.585 | 20' Lt of CL of SB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | |
| | | | | R2-1 36x48 12.00 SPEED LIMIT XX | | 38.695 | 20' Lt of CL of SB Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | |
| | | | | R2-1 36x48 12.00 SPEED LIMIT XX | | 38.695 | 24' Rt of CL of SB Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | |
| | | | | G020-5aP 36x24 6.00 WORK ZONE (PLAQUE) | | 38.695 | 20' Lt of CL of SB Route 61 | 1.00 | 6 | | | 6 | | | | | | | | | | | | | | | | |
| | | | | G020-5aP 36x24 6.00 WORK ZONE (PLAQUE) | | 38.695 | 24' Rt of CL of SB Route 61 | 1.00 | 6 | | | 6 | | | | | | | | | | | | | | | | |
| | | | | EO5-2 48x36 12.00 EXIT OPEN | | 39.173 | 24' Rt of CL of SBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | |
| | | | | R4-2 36x48 12.00 PASS WITH CARE | | 39.513 | 20' Lt of CL of SBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | R4-2 36x48 12.00 PASS WITH CARE | | 39.513 | 24' Rt of CL of SBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | |
| | | | | R2-1 36x48 12.00 SPEED LIMIT XX | | 39.718 | 20' Lt of CL of SBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | |
| | | | | R2-1 36x48 12.00 SPEED LIMIT XX | | 39.718 | 24' Rt of CL of SBL Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | | | | | |
| | | | | WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD | | 4.284 | 20' Lt of CL of WB Route 24 | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD | | 4.284 | 24' Rt of CL of WB Route 24 | 1.00 | 16 | | | 16 | |
| | | | | EO5-2a 48x36 12.00 EXIT CLOSED | | 4.494 | 24' Rt of CL of WB Route 24 | 1 | 12 | | | 12 | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED | | 4.617 | 20' Lt of CL of WB Route 24 | 1.00 | 16 | | | 16 | | | | |
| | | | | | | | | | | | | | | | | | | WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT) | | 4.617 | 24' Rt of CL of WB Route 24 | 1.00 | 16 | | | 16 | | |
| | | | | | | | | | | | | | | | | | | | | R2-1 36x48 12.00 SPEED LIMIT XX | | 4.763 | 20' Lt of CL of WB Route 24 | 1.00 | 12 | | | 12 |
| | | | | | | | | | | | | | | | | | | R2-1 36x48 12.00 SPEED LIMIT XX | | 4.763 | 24' Rt of CL of WB Route 24 | 1.00 | 12 | | | 12 | | |
| | | | | | | | | G020-5aP 36x24 6.00 WORK ZONE (PLAQUE) | | 4.763 | 20' Lt of CL of WB Route 24 | 1.00 | 6 | | | 6 | | | | | | | | | | | | |
| | | | | G020-5aP 36x24 6.00 WORK ZONE (PLAQUE) | | 4.763 | 24' Rt of CL of WB Route 24 | 1.00 | 6 | | | 6 | | | | | | | | | | | | | | | | |
| | | | | SPECIAL 36x60 15.00 DETOUR ASSEMBLY | | 40.506 | 16' Rt of CL of WB Route 24/61 (51B) | 1.00 | 15 | | | 15 | | | | | | | | | | | | | | | | |

Revision 4/1/2020 Page 8 of 20



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

| | | | | etails for Construction Signs (if | | | | | | | | | | | | | | | | | | | | |
|---------|----------------|---------------------|---|--|---------|----------------------------------|--|--------------------|--|--|-------------------------------|-----------------------------|------|------|----|--------------------------|--|--------|--|------|--|-----------------------------|------|------|
| Project | Line Number | DWR Date | Total Quantity Posted For DWR Date | Sign Information | Station | Log Mile | Location | Number of Items | SF Each Sign | Special Sign | SF Each Special Sign | Total SF to Post | | | | | | | | | | | | |
| J2P3182 | 0090 | March 30, 2020 | 832 | SPECIAL 36x60 15.00 DETOUR ASSEMBLY | | 40.777 | 13' Rt of CL of Ramp 2 @ Rte 6 (51C) | 1.00 | 15 | | | 15 | | | | | | | | | | | | |
| | | | | EO5-2a 48x36 12.00 EXIT CLOSED | | 5.043 | 6' Rt of CL of WB Route 24 | 1.00 | 12 | | | 12 | | | | | | | | | | | | |
| | | | | EO5-2a 48x36 12.00 EXIT CLOSED | | 5.051 | 20' Rt of CL of WB Route 24 | 1.00 | 12 | | | 12 | | | | | | | | | | | | |
| | | | | SPECIAL 36x60 15.00 DETOUR ASSEMBLY | | 5.195 | 16' Rt of CL of WB Route 24 (51A) | 1 | 15 | | | 15 | | | | | | | | | | | | |
| | | June 22, 2020 | 120 | SPECIAL 36x60 15.00 DETOUR ASSEMBLY | | 39.428 | 24' Right of centerline of SB Route 61 (SB 61 to EB 24 detour) | 1.00 | 15 | | | 15 | | | | | | | | | | | | |
| | | | | SPECIAL 36x60 15.00 DETOUR ASSEMBLY | | 40.506 | 16' Right of centerline of SB Route 61 (SB 61 to EB 24 detour) | 1.00 | 15 | | | 15 | | | | | | | | | | | | |
| | | | | SPECIAL 36x60 15.00 DETOUR ASSEMBLY | | 40.777 | 13' Right of centerline of Ramp 2 @ Route 6 (SB 61 to EB 24 detour) | 1.00 | 15 | | | 15 | | | | | | | | | | | | |
| | | | | EO5-2a 48x36 12.00 EXIT CLOSED | | 37.822 | 34' Rt of centerline SB Route 61 (placard on existing shoulder sign) | 1.00 | 12 | | | 12 | | | | | | | | | | | | |
| | | | | EO5-2a 48x36 12.00 EXIT CLOSED | | 38.872 | 34' Right of centerline of SB Route 61 (placard on existing shoulder sign) | 1.00 | 12 | | | 12 | | | | | | | | | | | | |
| | | | | EO5-2a 48x36 12.00 EXIT CLOSED | | 39.207 | 32' Right of centelrine of SB Route 61 (placard on existing shoulder sign) | 1.00 | 12 | | | 12 | | | | | | | | | | | | |
| | | | | EO5-2a 48x36 12.00 EXIT CLOSED | | 39.382 | 18' Right of centelrine of SB Route 61 (placard on overhead sign) | 1.00 | 12 | | | 12 | | | | | | | | | | | | |
| | | | | EO5-2a 48x36 12.00 EXIT CLOSED | | 39.171 | 30' Right of centerline of SB Route 61 (post mounted sign) | 1.00 | 12 | | | 12 | | | | | | | | | | | | |
| | | | | SPECIAL 36x60 15.00 DETOUR ASSEMBLY | | 0.063 | 16' Right of centerline of EB Route 6 (SB 61 to EB 24) | 1.00 | 15 | | | 15 | | | | | | | | | | | | |
| | | June 26, 2020 | 64 | WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD | | 38.185 | 20' Left of centerline of SB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | |
| | | | | WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD | | 38.185 | 24' Right of centerline of SB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | |
| | | | | | | | WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT) | | 38.585 | 24' Right of centerline of SB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | |
| | | | | WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED | | 38.585 | 20' Left of centerline of SB Route 61 | 1.00 | 16 | | | 16 | | | | | | | | | | | | |
| | | November 4, 2020 | 193 | 193 | 193 | 193 | 193 | 193 | 193 | 193 | 193 | 193 | 193 | 193 | | See Special Sign Details | | 37.459 | 24' Rt of centerline of Southbound Route 61 | 1.00 | | Point of Presence (placard) | 3.33 | 3.33 |
| | | | | EO5-1 36x48 12.00 GORE EXIT | | 39.408 | 8' Rt of centerline of Southbound Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | |
| | | | | R11-2 48x30 10.00 ROAD CLOSED | | 39.425 | 18' Rt of centerline of Southbound Route 61 | 1.00 | 10 | | | 10 | | | | | | | | | | | | |
| | | | | EO5-1 36x48 12.00 GORE EXIT | | 5.124 | 12' Rt of centerline of Northbound Route 61 | 1.00 | 12 | | | 12 | | | | | | | | | | | | |
| | | | | | | R11-2 48x30 10.00 ROAD CLOSED | | 5.152 | on centerline of Eastbound Route 24 Ramp | 1.00 | 10 | | | 10 | | | | | | | | | | |
| | | | | | | | MO4-8a 24x18 3.00 END DETOUR | | 352.499 | 24' Rt of centerline of Northbound Route 61 | 1.00 | 3 | | | 3 | | | | | | | | | |
| | | | | | | See Special Sign Details | | 352.076 | 24' Rt of centerline of Northbound Route 61 | 1.00 | | Point of Presence (placard) | 3.33 | 3.33 | | | | | | | | | | |
| | | | | CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE | | 3.698 | 24' Rt of centerline of Westbound Route 24 | 1.00 | 12 | | | 12 | | | | | | | | | | | | |
| | | | | CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE | | 3.698 | 20' Lt of centerline of Westbound Route 24 | 1.00 | 12 | | | 12 | | | | | | | | | | | | |
| | | | | CONST-7-72 72x36 18.00 RATE OUR WORK ZONE | | 3.562 | 24' Rt of centerline of Westbound Route 24 | 1.00 | 18 | | | 18 | | | | | | | | | | | | |

Revision 4/1/2020 Page 9 of 20



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

| roject | Line Number | DWR Date | Total Quantity Posted For DWR Date | Sign Information | Station | Log Mile | Location | Number of Items | SF Each Sign | Special Sign | SF Each Special Sign | Tota SF to Pos | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--------|-------------------------------|-------------|---|--|---|---|---|--|--|--|-------------------------------|-------------------------|----|----|----|--|--|--|--|--|--|--------------------------|--|---|--|------|--|-------------------------------------|-------|------|--------------------------|---|---|-----------------------------------|------|--|-----------------------------|------|------|
| P3182 | 82 0090 November 1 4, 2020 | 193 | SPECIAL 7 96x48 32.00 POINT OF PRESENCE | | 3.456 | 24' Rt of centerline of Westbound Route 24 | 1.00 | 32 | | | 32 | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | See Special Sign Details | | 3.456 | 24' Rt of centerline of Westbound Route 24 | 1.00 | | Point of Presence (placard) | 3.33 | 3.33 | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | WO20-3 48x48 16.00 ROAD CLOSED AHEAD | | 0.871 | 16' Lt of centerline of County Road 308 (Eastbound Shoulder) | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | WO20-3 48x48 16.00 ROAD CLOSED AHEAD | | 0.587 | 16' Rt of centerline of County Road 308 (Westbound Shoulder) | 1.00 | 16 | | | 16 | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | R11-2 48x30 10.00 ROAD CLOSED | | 0.412 | on centerline of Eastbound Route 24 Ramp | 1.00 | 10 | | | 10 | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | See Special Sign Details | | | | 1.00 | | Wet Paint (Arrow Pivots) | 2.19 | 2.19 | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | See Special Sign Details | 0 | 0 | on TMA truck for mobile work zone | 1.00 | | Wet Paint (Arrow Pivots) | 2.19 | 2.19 |
| | | | | | | | | | | | | | | | | | | | | | | See Special Sign Details | | 0 | rounding to the nearest Square Foot for final quantity | 1.00 | | rounding to the nearest square feet | -0.37 | -0.3 | | | | | | | | | |
| | | | | WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED | 0 | 0 | on TMA truck for mobile work zone | 1.00 | 16 | | | 10 | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 0090 - To | tal | | | | | | | | | | 120 | | | | | | | | | | | | | | | | | | | | | | | | | | | |

Revision 4/1/2020 Page 10 of 20



| ct | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|----|--------|---|--------------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| 82 | 0030 | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) | Other Item Adjustment | ACAD | 4 | May 18, 2020 | dwighj1 | (\$50.32) | This AC Index Adjustment is for asphalt mix that was placed on April 30, 2020. The material was not paid for until Estimate 0004, which is the May 15, 2020 pay estimate, but it was placed during the previous estimate period. There were a total of 30.27 tons of SP125C mix placed (Mix ID: SP125 20-41), with a virgin AC of 3.8%. |
| | | | | | 6 | Jun 16, 2020 | dwighj1 | (\$359.10) | This Line Item Adjustment is for the AC Price Adjustment for asphalt that was placed on June 15, 2020. There were a total of 90 tons placed on that day, with a virgin asphalt content of 3.8%, with a mix ID of SP125 20-41. |
| | | | | | 17 | Dec 2, 2020 | dwighj1 | (\$228.41) | This Asphalt Cement Price Adjustment is being paid out for asphalt that was actually placed on August 28, 2020. The material was not paid until this estimate because the 54.03 tons that were paid on this estimate are an overrun and had to be approved by change order before payment. This adjustment is for Line No. 0030, and it is for 54.03 tons of asphalt, mix ID SP125 20-41, which has a 3.8% Virgin Asphalt Content. The total amount calculated by the AC Index spreadsheet was a deduction of -\$228.41 from the estimate. |
| | | | | ACAD - Tota | al | | | (\$637.83) | |
| | | | | FUEL | | Dec 2, 2020 | dwighj1 | (\$130.95) | The system calculated and assessed fuel price index adjustment was applied to the amount of asphalt that was paid for on this estimate. A total of 54.03 tons were paid for on Line No. 0030 (Asphaltic Concrete Mixture PG 70-22, SP125C Mix), and the system used the fuel price index factor from November 2020, which is the period of time when the material amount was paid out. However, the asphalt was actually placed on August 28, 2020, and it was not paid for then due to a change order that was required authorizing the extra quantity. That change order was approved this pay period, and the 54.03 tons were paid out as a result. The fuel index changed slightly from the November 2020 calculation to the August 2020 calculation, so the underrun amount that the system assessed on this estimate is being added back to the estimate with another line adjustment. This adjustment is to deduct the correct amount for the fuel price index adjustment that was assessed using the August 2020 factor. The amount that should have been deducted from the estimate is -\$130.95, as the Fuel Price Index calculation sheet showed. |
| | | | | FUEL - Tota | | | | (\$130.95) | |
| | | | | OTHR | 17 | Dec 2, 2020 | dwighj1 | \$132.74 | The system calculated and assessed fuel price index adjustment was applied to the amount of asphalt that was paid for on this estimate. A total of 54.03 tons were paid for on Line No. 0030 (Asphaltic Concrete Mixture PG 70-22, SP125C Mix), and the system used the fuel price index factor from November 2020, which is the period of time when the material amount was paid out. However, the asphalt was actually placed on August 28, 2020, and it was not paid for then due to a change order that was required authorizing the extra quantity. That change order was approved this pay period, and the 54.03 tons were paid out as a result. The fuel index changed slightly from the November 2020 calculation to the August 2020 calculation, so the underrun amount that the system assessed on this estimate is being added back to the estimate with this Other line adjustment. The amount the system assessed was -\$132.74, so that amount is being added back to the estimate. The correct assessment will be calculated and deducted back from the estimate on another line item adjustment. |
| | | | | OTHR - Tota | al | | | \$132.74 | |
| | | | Other Item Ad | ustment - To | tal | | | (\$636.04) | |
| | | | Price FUEL | | 4 | May 18, 2020 | SYSTEM | (\$108.54) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 6 | Jun 16, 2020 | SYSTEM | (\$292.82) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 17 | Dec 2, 2020 | SYSTEM | (\$132.74) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | Deion Elife | - Total | | | | (\$534.10) | |
| | 0000 | T-4-1 | Price FUEL - T | otal | | | | (\$534.10) | |
| | 0030 - | | | | | | | (\$1,170.14) | |
| | 0050 | IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY) | Material | | 1 | Apr 3, 2020 | SYSTEM | \$6,800.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | DAINLL ARRAT) | | | 1 | Apr 3, 2020 | SYSTEM | (\$6,800.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | 1 | | | | \$0.00 | |
| | 0050 - | Total | | | | | | \$0.00 | |
| | 0800 | TRUCK OR TRAILER MOUNTED ATTEN (TMA) | Material | | 1 | Apr 3, 2020 | SYSTEM | \$1.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | ATTEN (TMA) | ATTEN (TMA) | | 1 | Apr 3, 2020 | SYSTEM | (\$1.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|----------------------|---|
| 2P3182 | 0800 | TRUCK OR TRAILER MOUNTED ATTEN (TMA) | Material - Tota | | | | | \$0.00 | |
| | 0080 - | - Total | | | | | | \$0.00 | |
| | 0090 | CONSTRUCTION SIGNS | Material | | 1 | Apr 3, 2020 | SYSTEM | \$6,656.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 1 | Apr 3, 2020 | SYSTEM | (\$6,656.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 0090 - | - Total | | | | | | \$0.00 | |
| | 0100 | ADVANCED WARNING RAIL SYSTEM | Material | | 1 | Apr 3, 2020 | SYSTEM | \$560.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 1 | Apr 3, 2020 | SYSTEM | (\$560.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 0100 - | - Total | | | | | | \$0.00 | |
| | 0110 | FLAG ASSEMBLY | Material | | 1 | Apr 3, 2020 | SYSTEM | \$120.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 1 | Apr 3, 2020 | SYSTEM | (\$120.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | l . | | | | \$0.00 | |
| | 0110 - | - Total | | | | | | \$0.00 | |
| | 0120 | CHANNELIZER (TRIM LINE) | Material | | 1 | Apr 3, 2020 | SYSTEM | \$1,860.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 1 | Apr 3, 2020 | SYSTEM | (\$1,860.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | _ | Material - Tota | 1 | | | | \$0.00 | |
| | | - Total | | | | | 2) (2 === 1 | \$0.00 | |
| | 0130 | TYPE III MOVEABLE BARRICADE | Material | | 1 | Apr 3, 2020 | SYSTEM | \$300.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dwighj1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 1 | Apr 3, 2020 | SYSTEM | (\$300.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 0130 | - Total DIRECTIONAL INDICATOR | Material | | 1 | Apr 3, 2020 | SYSTEM | \$0.00 \$2,310.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dwighj1 overridding Payment |
| | | BARRICADE | | | 1 | Apr 3, | SYSTEM | (\$2,310.00) | Estimate Exception 8 on the current Payment Estimate. |
| | | | | - Total | | 2020 | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 0140 | · Total | 1010 | | | | | \$0.00 | |
| | 0150 | FLASHING ARROW PANEL | Material | | 1 | Apr 3, 2020 | SYSTEM | \$2,550.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dwighj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 1 | Apr 3, 2020 | SYSTEM | (\$2,550.00) | , |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | l e | | | | \$0.00 | |
| | 0150 | - Total | | | | | | \$0.00 | |
| | 0160 | CMS W/O COMMUNICATION | Material | | 1 | Apr 3, 2020 | SYSTEM | \$8,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dwighj1 overridding Payment |



| ect | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----|--------------------|---|---------------------------|-----------------------------|----------------|-----------------|---------------|----------------------------|--|
| 182 | 0160 | INTERFACE, CONT | Material | ,,, | | | | | Estimate Exception 10 on the current Payment Estimate. |
| | | F/ | | | 1 | Apr 3, 2020 | SYSTEM | (\$8,400.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | 1 | | | | \$0.00 | |
| | 0160 - | | | | | | | \$0.00 | |
| | 0170 | TEMPORARY LONG-TERM RUMBLE STRIPS | Material | | 1 | Apr 3, 2020 | SYSTEM | \$4,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dwighj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 1 | Apr 3, 2020 | SYSTEM | (\$4,000.00) | |
| | | | | - Total | | | | \$0.00 | |
| | 0470 | T-4-1 | Material - Tota | <u> </u> | | | | \$0.00 | |
| ı | 0170 - | | Material | | 1 | Apr 2 | SVSTEM | \$0.00 | This adjustment effects the original system generated Overrup Devment |
| | 0180 | TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE | Material | | 1 | Apr 3, 2020 | SYSTEM | \$25,376.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dwighj1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 1 | Apr 3, 2020 | SYSTEM | (\$25,376.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Total | | | | | \$0.00 | |
| | 0180 - | Total | | | | | | \$0.00 | |
| | 0210 | 6 IN. WHITE HIGH BUILD WATERBORNE | Material | | 15 | Nov 1, 2020 | SYSTEM | \$983.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | PAINT | | | 15 | Nov 1, 2020 | SYSTEM | (\$983.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 0210 - | Total | | | | | | \$0.00 | |
| | 0220 | 6 IN. YELLOW HIGH BUILD WATERBORNE PAINT | Material | | 15 | Nov 1, 2020 | SYSTEM | \$823.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | FAINT | | | 15 | Nov 1, 2020 | SYSTEM | (\$823.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | 1 | | | | \$0.00 | |
| J | 0220 - | Total | | | | | | \$0.00 | |
| | 0230 | 12 IN. WHITE HIGH BUILD WATERBORNE PAINT | Material | | 15 | Nov 1, 2020 | SYSTEM | \$2,079.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dwighj1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | FAINT | | | 15 | Nov 1, 2020 | SYSTEM | (\$2,079.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | | | Overrun | Overrun | 15 | Nov 1, 2020 | SYSTEM | \$177.75 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 15 | Nov 1, 2020 | SYSTEM | (\$177.75) | |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | ıl | | | | \$0.00 | |
| | | | | | | | | \$0.00 | |
| | 0230 - | | | | | | | | |
| | 0230 - 0240 | Total 24 IN. WHITE WATERBORNE PAVEMENT MARKING | Material | | 15 | Nov 1, 2020 | SYSTEM | \$1,024.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | 24 IN. WHITE WATERBORNE PAVEMENT | Material | | 15 | | SYSTEM | \$1,024.00 (\$1,024.00) | Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment |
| | | 24 IN. WHITE WATERBORNE PAVEMENT | Material | - Total | | 2020 Nov 1, | | | Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment |
| | | 24 IN. WHITE WATERBORNE PAVEMENT MARKING | Material Material - Tota | | | 2020 Nov 1, | | (\$1,024.00) | Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J2P3182 | 0340 | LATEX MODIFIED CONCRETE WEARING | Material | | 7 | Jul 1, 2020 | SYSTEM | \$59,314.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | SURFACE | | | 7 | Jul 1, 2020 | SYSTEM | (\$59,314.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 0340 - | Total | | | | | | \$0.00 | |
| | 0350 | CURB BLOCKOUT | Material | | 2 | Apr 15, 2020 | SYSTEM | (\$25,700.00) | |
| | | | | | 3 | May 4, 2020 | SYSTEM | \$25,700.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 3 | May 4, 2020 | SYSTEM | (\$25,700.00) | |
| | | | | | 4 | May 18, 2020 | SYSTEM | \$25,700.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 4 | May 18, 2020 | SYSTEM | (\$25,700.00) | |
| | | | | | 5 | Jun 2, 2020 | SYSTEM | \$25,700.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 5 | Jun 2, 2020 | SYSTEM | (\$25,700.00) | |
| | | | | | 6 | Jun 16, 2020 | SYSTEM | \$25,700.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 6 | Jun 16, 2020 | SYSTEM | (\$25,700.00) | |
| | | | | | 7 | Jul 1, 2020 | SYSTEM | \$25,700.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 7 | Jul 1, 2020 | SYSTEM | (\$25,700.00) | |
| | | | | | 8 | Jul 15, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 8 | Jul 15, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | | 9 | Aug 3, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 9 | Aug 3, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | | 10 | Aug 16, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 10 | Aug 16, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | | 11 | Sep 2, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dwighj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 11 | Sep 2, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | | 12 | Sep 15, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 12 | Sep 15, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | - Total | | | | (\$25,700.00) | |
| | | | Material - Tota | | | | | (\$25,700.00) | |
| | | | MaterialCredit | | 3 | May 4, 2020 | SYSTEM | \$25,700.00 | |
| | | | | - Total | | | | \$25,700.00 | |
| | | | MaterialCredit | - Total | | | | \$25,700.00 | |



| roject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|
| P3182 | 0350 - | Total | | | | | | \$0.00 | |
| | 0370 | SUPERSTRUCTURE REPAIR (UNFORMED) | Material | | 7 | Jul 1, 2020 | SYSTEM | \$4,179.45 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dwighj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 7 | Jul 1, 2020 | SYSTEM | (\$4,179.45) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 0370 - | Total | | | | | | \$0.00 | |
| | 0390 | SLAB EDGE REPAIR (BRIDGES) | Material | | 7 | Jul 1, 2020 | SYSTEM | \$3,750.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dwighj1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 7 | Jul 1, 2020 | SYSTEM | (\$3,750.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 0390 - | Total | | | | | | \$0.00 | |
| | 0410 | CLEANING AND EPOXY COATING | Material | | 11 | Sep 2, 2020 | SYSTEM | \$3,580.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dwigh]1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 11 | Sep 2, 2020 | SYSTEM | (\$3,580.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 0410 - | Total | | | | | | \$0.00 | |
| | 0420 | 20 MONOLITHIC DECK REPAIR | Material | | 7 | Jul 1, 2020 | SYSTEM | \$13,153.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 7 | Jul 1, 2020 | SYSTEM | (\$13,153.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | | | Overrun | Overrun | | Aug 16, 2020 | SYSTEM | (\$2,877.00) | |
| | | | | | 16 | Nov 16, 2020 | SYSTEM | \$2,877.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',700.00000 - 700.00000, 'is applied (if non-zero). |
| | | | | Overrun - Total | | | | \$0.00 | |
| | | | Overrun - Tota | d | | | | \$0.00 | |
| | 0420 - | Total | | | | | | \$0.00 | |
| | 0450 | MISC. REMOVALS | Overrun | Overrun | 7 | May 18, 2020 | SYSTEM | (\$39,595.75) | Unit price based on averaged overrun adjustments for installed quantity on all |
| | | | | | , | Jul 1, 2020 | SYSTEM | \$39,595.75 | previous payment estimates. Price Adjustments of ',41.00000 - 41.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | ıl | | | | \$0.00 | |
| | 0450 - | | | | | | | \$0.00 | |
| | 0460 | LATEX MODIFIED CONCRETE WEARING SURFACE | Material | | 5 | Jun 2, 2020 | SYSTEM | \$118,628.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | SON AGE | | | 5 | Jun 2, 2020 | SYSTEM | (\$118,628.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ı | | | | \$0.00 | |
| | 0460 - | Total | | | | | | \$0.00 | |
| | 0470 | CURB BLOCKOUT | Material | | 2 | Apr 15, 2020 | SYSTEM | (\$25,700.00) | |
| | | | | | 3 | May 4, 2020 | SYSTEM | \$25,700.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | | | | | |



| ct L | ine | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-------|-----|-------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|------------------|---|
| 82 04 | 470 | CURB BLOCKOUT | Material | . 7 - | | 2020 | | | |
| | | | | | 4 | May 18, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 4 | May 18, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | | 5 | Jun 2, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 5 | Jun 2, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | | 6 | Jun 16, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 6 | Jun 16, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | | 7 | Jul 1, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 7 | Jul 1, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | | 8 | Jul 15, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 8 | Jul 15, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | | 9 | Aug 3, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 9 | Aug 3, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | | 10 | Aug 16, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 10 | Aug 16, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | | 11 | Sep 2, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 11 | Sep 2, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | | 12 | Sep 15, 2020 | SYSTEM | \$51,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 12 | Sep 15, 2020 | SYSTEM | (\$51,400.00) | |
| | | | | - Total | | | | (\$25,700.00) | |
| | | | Material - Tota | | | | | (\$25,700.00) | |
| | | | MaterialCredit | | 3 | May 4, 2020 | SYSTEM | \$25,700.00 | |
| | | | | - Total | | | | \$25,700.00 | |
| | 470 | Total | MaterialCredit | - Total | | | | \$25,700.00 | |
| | | Total SUPERSTRUCTURE | Material | | 7 | lul 1 | SVSTEM | \$0.00 | This adjustment offsets the original system generated Oversun Reymont |
| U4 | 490 | REPAIR (UNFORMED) | iviaterial | | | Jul 1, 2020 | SYSTEM | \$7,920.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 7 | Jul 1, 2020 | SYSTEM | (\$7,920.00) | |
| | | | | - Total | | | | \$0.00 | |
| 0 | 190 | Total | Material - Tota | | | | | \$0.00 \$0.00 | |
| | 510 | SLAB EDGE REPAIR (BRIDGES) | Material | | 7 | Jul 1, 2020 | SYSTEM | \$9,600.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dwighj1 overridding Payment |
| | | | | | 7 | Jul 1, | SYSTEM | (\$9,600.00) | Estimate Exception 7 on the current Payment Estimate. |
| | | | | | | 2020 | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|---------|---|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J2P3182 | 0510 | SLAB EDGE REPAIR (BRIDGES) | Material | - Total | | | | \$0.00 | |
| | | , , | Material - Tota | | | | | \$0.00 | |
| | 0510 - | | | | | | | \$0.00 | |
| | 0530 | CLEANING AND EPOXY COATING | Material | | 11 | Sep 2, 2020 | SYSTEM | \$3,580.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user dwighj1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 11 | Sep 2, 2020 | SYSTEM | (\$3,580.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 0530 - | Total | | | | | | \$0.00 | |
| | 0540 | MONOLITHIC DECK REPAIR | Material | | 5 | Jun 2, 2020 | SYSTEM | \$26,565.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 5 | Jun 2, 2020 | SYSTEM | (\$26,565.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | | | Other Item Adjustment | OTHR | 6 | Jun 16, 2020 | dwighj1 | \$16,786.00 | This Line Item Adjustment is to put back the amount deducted by the system on this line number on estimate 0006. The system made an overrun adjustment automatically of -\$16,786.00, and nothing was paid out on this line number on this estimate. Change Order 0002 will correct the quantity to resolve this discrepancy, but the system is trying to deduct the overrun amount again on this estimate. |
| | | | | OTHR - Tota | al | | | \$16,786.00 | |
| | | | Other Item Adj | ustment - To | tal | | | \$16,786.00 | |
| | | | Overrun | Overrun | 3 | May 4, 2020 | SYSTEM | \$2,079.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dwighj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 3 | May 4, 2020 | SYSTEM | (\$2,079.00) | |
| | | | | | 4 | May 18, 2020 | SYSTEM | (\$2,079.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 5 | Jun 2, 2020 | SYSTEM | \$16,786.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 5 | Jun 2, 2020 | SYSTEM | (\$16,786.00) | |
| | | | | | 6 | Jun 16, 2020 | SYSTEM | (\$16,786.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 7 | Jul 1, 2020 | SYSTEM | \$18,865.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',700.00000 - 700.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | | | | | \$0.00 | |
| | 0540 - | Total | | | | | | \$16,786.00 | |
| J2P3182 | - Total | | | | | | | \$15,615.86 | |
| J2P3342 | 0590 | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) | Other Item Adjustment | | 17 | Dec 2, 2020 | dwighj1 | (\$224.06) | This Asphalt Cement Price Adjustment is being paid out for asphalt that was actually placed on September 3, 2020. The material was not paid until this estimate because the 53.00 tons that were paid on this estimate are an overrun and had to be approved by change order before payment. This adjustment is for Line No. 0590, and it is for 53.00 tons of asphalt, mix ID SP125 20-41, which has a 3.8% Virgin Asphalt Content. The total amount calculated by the AC Index spreadsheet was a deduction of -\$224.06 from the estimate. |
| | | | | ACAD - Tota | al | | | (\$224.06) | |
| | | | | OTHR | 18 | Dec 16, 2020 | dwighj1 | \$6.64 | This adjustment is to give back the system generated fuel adjustment assessed for the 4 tons of asphalt that was paid out on this pay estimate. The material was actually placed on September 4, 2020, and that fuel price index should used for the material. It was paid on this estimate because a change order was needed to get the line item to the correct final quantity. |
| | | | | | 18 | Dec 16, 2020 | dwighj1 | (\$9.30) | This line item adjustment is to deduct the correct amount from the contract for the fuel adjustment for the asphalt that was placed on September 3, 2020. There were an additional four tons that had to be paid for this pay period, due to a change order that added those four tons to the contract. The system assessed a fuel adjustment using the December index, which was added back with another contract adjustment on this estimate (Estimate #0018). This adjustment is deducting a total of -\$9.30 from the contract, which is the correct |



| roject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--------|---|-----------------------------------|-----------------------------|----------------|----------------------------|---------------|------------------------------|---|
| 23342 | 0590 | ASPHALTIC | Other Item | OTHR | | | | | amount to deduct using the First Period of September 2020 Fuel Index. |
| | | CONCRETE MIXTURE PG 70-22 | Adjustment | OTHR - Tota | al | | | (\$2.66) | |
| | | (SP125C MIX) | Other Item Ad | justment - To | tal | | | (\$226.72) | |
| | | | Overrun | Overrun | 12 | Sep 15, 2020 | SYSTEM | (\$7,266.43) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 16 | Nov 16, 2020 | SYSTEM | \$7,266.43 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',347.67608 - 350.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | is applied (if first 2010). |
| | | | Overrun - Tota | | | | | \$0.00 | |
| | | | Price FUEL | | 12 | Sep 15, 2020 | SYSTEM | (\$113.88) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 18 | Dec 16, 2020 | SYSTEM | (\$6.64) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | - Total | | | | (\$120.52) | |
| | | | Price FUEL - T | otal | | | | (\$120.52) | |
| | 0590 - | | | | 40 | 0 45 | OVOTELA | (\$347.24) | |
| | 0600 | TACK COAT | Overrun | Overrun | 12 | Sep 15, 2020 Nov 16, | SYSTEM | (\$102.00) \$102.00 | Unit price based on averaged overrun adjustments for installed quantity on all |
| | | | | | 10 | 2020 | OTOTEW | ψ102.00 | previous payment estimates. Price Adjustments of ',6.00000 - 6.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - Tota | ıl | | | | \$0.00 | |
| | 0600 - | | | | | | | \$0.00 | |
| | 0620 | 6 IN. WHITE HIGH BUILD WATERBORNE | UILD | | 15 | Nov 1, 2020 | SYSTEM | \$528.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | FAINT | | | 15 | Nov 1, 2020 | SYSTEM | (\$528.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 0620 - | Total | | | | | | \$0.00 | |
| | 0630 | 6 IN. YELLOW HIGH BUILD WATERBORNE | BUILD ERBORNE | | 15 | Nov 1, 2020 | SYSTEM | \$528.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dwighj1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | PAINT | | | 15 | Nov 1, 2020 | SYSTEM | (\$528.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | 1 | | | | \$0.00 | |
| | 0630 - | Total | | | | | | \$0.00 | |
| | 0660 | MGS GUARDRAIL | Construction Stockpile | | 10 | Aug 16, 2020 | SYSTEM | (\$22,012.21) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | (\$22,012.21) | |
| | | | Construction Stockpile | Stockpile - To | 3 | May 4, 2020 | SYSTEM | (\$22,012.21) \$22,012.21 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | STMI | - Total | | | | \$22,012.21 | |
| | | | Construction : | l Stockpile STI | /II - Total | | | \$22,012.21 | |
| | 0660 - | Total | | | | | | \$0.00 | |
| | 0670 | MGS BRIDGE APP. TRANS SEC (REG/NO CURB) | Construction Stockpile | | 10 | Aug 16, 2020 | SYSTEM | (\$5,541.59) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | (INCOMO CORD) | | | 11 | Sep 1, 2020 | SYSTEM | (\$454.41) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | (\$5,996.00) | |
| | | | Construction | otockpile - To | | Mov 4 | SYSTEM | (\$5,996.00) | Payment Estimate Item Adjustment generated Starting Transaction |
| | | | Construction Stockpile STMI | | 3 | May 4, 2020 | SISIEM | \$5,996.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | \$5,996.00 | |
| | | | Construction | Stockpile STI | /II - Total | | | \$5,996.00 | |



| Page March Michael Page | oject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--|-------|----------------|-----------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| Stocyto Construction Stockpile Total Stock Sto | 23342 | 0670 - | Total | | | | | | \$0.00 | |
| Construction Stockpile Total S SYSTEM System-percental Coverus Payment Estimate Exception 1 on the current Payment Estimate System-percental Coverus Payment Statement Syste | | 0680 | MGS END ANCHOR | | | 11 | | SYSTEM | (\$1,070.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| Construction Study Train Total Study | | | | | | | | | | |
| Sincaple 2000 | | | | | Stockpile - To | | | | | |
| | | | | Stockpile | | 3 | | SYSTEM | | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | | | | | | | |
| March September March September | | 0000 | T-4-1 | Construction | Stockpile STI | VII - I otal | | | | |
| Construction Stockpile Total (\$3,000,000) Construction Stockpile Total (\$3,000,000) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Transaction Stockpile Transaction Stockpile Transaction Trans | | | TYPE A CRSHWTHY | | | 10 | | SYSTEM | | Payment Estimate Item Adjustment generated Stockpile Transaction |
| Construction Stockpile - Total Suggest | | | | Otockpile | - Total | | 2020 | | (\$3,020,00) | |
| Construction Stocklete STM Total S.0.00.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STM Total S.0.00.00 | | | | Construction S | | otal | | | | |
| Stockpile STM | | | | | oto on pilo | | May 4. | SYSTEM | | Payment Estimate Item Adjustment generated Stockpile Transaction |
| Construction Stockpile STMI - Total Substitution S | | | | Stockpile | | | | | **,*=**** | 3 |
| | | | | OTIVII | - Total | | | | \$3,020.00 | |
| Overrun | | | | Construction S | Stockpile STI | MI - Total | | | \$3,020.00 | |
| 2020 16 | | 0690 - | Total | | | | | | \$0.00 | |
| 2020 September | | 0750 | MISC. REMOVALS | Overrun | Overrun | 8 | | SYSTEM | (\$2,180.38) | |
| | | | | | | 16 | | SYSTEM | \$2,180.38 | previous payment estimates. Price Adjustments of ',41.00000 - 41.00000, 'is |
| CLASS B-2 | | | | | Overrun - T | otal | | | \$0.00 | |
| Total | | | | Overrun - Tota | ıl | | | | \$0.00 | |
| CONCRETE 2020 Estimate Item Adjustment (006) due to user dwight] overridding Payment Estimate Exception 1 on the current Payment Estimate. | | 0750 - | Total | | | | | | \$0.00 | |
| 1 | | 0780 | | Material | | 10 | | SYSTEM | \$18,300.00 | Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment |
| 2020 Estimate tem Adjustment (0018) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 10 | | | | | | 10 | | SYSTEM | (\$18,300.00) | |
| 11 | | | | | | 11 | | SYSTEM | \$59,700.00 | Estimate Item Adjustment (0018) due to user dwighj1 overridding Payment |
| Naterial - Total S0.00 | | | | | | 11 | | SYSTEM | (\$59,700.00) | , |
| O790 CURB BLOCKOUT Material 10 | | | | | - Total | | | | \$0.00 | |
| 10 | | | | Material - Tota | ı | | | | \$0.00 | |
| 2020 Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | 0780 - | Total | | | | | | \$0.00 | |
| 11 | | 0790 | CURB BLOCKOUT | Material | | 10 | | SYSTEM | \$64,430.00 | Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment |
| Estimate Item Adjustment (0016) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 11 Sep 2, 2020 12 Sep 15, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 12 Sep 15, 2020 SySTEM (\$64,430.00) -Total \$0.00 Material - Total \$0.00 Overrun Overrun Overrun 11 Sep 2, 2020 SySTEM (\$13,139.00) Unit price based on averaged overrun adjustments for installed quantity on all | | | | | | 10 | | SYSTEM | (\$64,430.00) | |
| 2020 12 Sep 15, 2YSTEM \$64,430.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 12 Sep 15, 2YSTEM \$64,430.00 - Total \$0.00 Material - Total \$0.00 0790 - Total \$0.00 0870 MONOLITHIC DECK REPAIR Overrun Overrun 11 Sep 2, 2020 SYSTEM \$13,139.00 16 Nov 16, SYSTEM \$13,139.00 Unit price based on averaged overrun adjustments for installed quantity on all | | | | | | 11 | | SYSTEM | \$64,430.00 | Estimate Item Adjustment (0016) due to user dwighj1 overridding Payment |
| 2020 Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 12 Sep 15, 2020 SYSTEM (\$64,430.00) | | | | | | 11 | | SYSTEM | (\$64,430.00) | |
| 12 Sep 15, 2020 SYSTEM (\$64,430.00) | | | | | | 12 | | SYSTEM | \$64,430.00 | Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment |
| Material - Total | | | | | | 12 | | SYSTEM | (\$64,430.00) | , |
| Material - Total | | | | | - Total | | | | \$0.00 | |
| Solution | | | | Material - Tota | | | | | | |
| 0870 MONOLITHIC DECK REPAIR Overrun Overrun 11 Sep 2, SYSTEM (\$13,139.00) 16 Nov 16, SYSTEM \$13,139.00 Unit price based on averaged overrun adjustments for installed quantity on all | | 07 <u>90</u> - | Total | | | | | | | |
| 16 Nov 16, SYSTEM \$13,139.00 Unit price based on averaged overrun adjustments for installed quantity on all | | | MONOLITHIC DECK | Overrun | Overrun | 11 | | SYSTEM | | |
| | | | | | | 16 | Nov 16, | SYSTEM | \$13,139.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',700.00000 - 700.00000, |

May 18, 2021



Line Item Adjustments by Estimate

| 2020 Estimate Item Adjustment (0002) due to user dwight overridding Payr Estimate Exception 2 on the current Payment Estimate. (\$5,000.00) | Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---|-----------|--------|-------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| Operation Total Sep 30 SYSTEM Sep 30 | J2P3342 | 0870 | | Overrun | Overrun | | | | | 'is applied (if non-zero). |
| 12 Sep 15 SYSTEM (\$5,000.00) This adjustment offsets the original system-generated Overrun Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate (Overrun Payment Estimate Exception 6 on the current Payment Estimate (Payment Estimate Exception 6 on the current Payment Estimate) 13 Sep 2, SYSTEM S | | | REPAIR | | Overrun - T | otal | | | \$0.00 | |
| 1 | | | | Overrun - Tota | | | | | \$0.00 | |
| COATNCE SENTS | | 0870 - | Total | | | | | | \$0.00 | |
| AND 13 Sep 30 SYSTEM \$5,000.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwight) overridding Payr Estimate Exception 2 on the current Payment Estimate \$6,000.00 | | 0890 | COATING - | Material | | 12 | | SYSTEM | (\$5,000.00) | |
| Total (\$5,000.00) | | | | | | 13 | | SYSTEM | \$5,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| Material - Total 13 Sep 30, SYSTEM \$5,000.00 | | | | | | 13 | | SYSTEM | (\$5,000.00) | |
| Material Credit 13 Sep 30 SYSTEM \$5,000.00 | | | | | - Total | | | | (\$5,000.00) | |
| 1-Total | | | | Material - Tota | | | | | (\$5,000.00) | |
| MaterialCredit - Total S5,000.00 | | | | MaterialCredit | | 13 | | SYSTEM | \$5,000.00 | |
| September Sept | | | | | - Total | | | | \$5,000.00 | |
| 10 | | | | MaterialCredit | - Total | | | | \$5,000.00 | |
| BEARING | | 0890 - | Total | | | | | | \$0.00 | |
| 10 | | 0900 | | Material | | 9 | | SYSTEM | \$12,200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| 2020 SYSTEM S12,200.00 Estimate Exception 5 on the current Payment Estimate. | | | | | | 9 | | SYSTEM | (\$12,200.00) | |
| 2020 11 Sep 2, 2020 20 | | | | | | 10 | | SYSTEM | \$12,200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dwighj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| 2020 Estimate Item Adjustment (0019) due to user dwighj1 overridding Payr Estimate Exception 8 on the current Payment Estimate. | | | | | | 10 | | SYSTEM | (\$12,200.00) | |
| Total \$0.00 | | | | | | 11 | | SYSTEM | \$12,200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user dwighj1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| Material - Total \$0.00 | | | | | | 11 | | SYSTEM | (\$12,200.00) | |
| Solid Control of State Solid Control of St | | | | | - Total | | | | \$0.00 | |
| MISC. Material 10 | | | | Material - Tota | | | | | \$0.00 | |
| Estimate Item Adjustment (0008) due to user dwighj1 overridding Payr Estimate Exception 6 on the current Payment Estimate. 10 Aug 16, 2020 11 Sep 2, 2020 11 Sep 2, 2020 11 Sep 2, 2020 11 Sep 2, SYSTEM \$49,000.00 11 Sep 2, SYSTEM \$0.00 11 Sep 2, SYSTEM \$0.00 12 Sep 2, SYSTEM \$0.00 13 Sep 2, SYSTEM \$0.00 14 Sep 2, SYSTEM \$0.00 | | 0900 - | Total | | | | | | \$0.00 | |
| 2020 This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0020) due to user dwighj1 overridding Payr Estimate Exception 9 on the current Payment Estimate. 11 | | 0920 | MISC. | Material | | 10 | | SYSTEM | \$24,500.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dwighj1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| 2020 Estimate Item Adjustment (0020) due to user dwighj1 overridding Payr Estimate Exception 9 on the current Payment Estimate. 11 | | | | | | 10 | | SYSTEM | (\$24,500.00) | |
| 2020 Waterial - Total \$0.00 | | | | | | 11 | | SYSTEM | \$49,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user dwighj1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| Material - Total \$0.00 0920 - Total \$0.00 | | | | | | 11 | | SYSTEM | (\$49,000.00) | |
| 0920 - Total \$0.00 | | | | | - Total | | | | \$0.00 | |
| | | | | Material - Tota | | | | | \$0.00 | |
| J2P3342 - Total (\$347.24) | | 0920 - | Total | | | | | | \$0.00 | |
| | J2P3342 - | Total | | | | | | | (\$347.24) | |
| Overall - Total \$15,268.62 | Overall - | Total | | | | | | | \$15,268.62 | |