

#### Pay Estimate Created Date: January 19, 2021

Progress	Estimate Number	Contract ID	190816-C02	Pay Period Start	January 2, 2021	Original Contract Amount	\$732,814.10
10		Prime Contractor	Radmacher Brothers Co.,Inc.	Excavating Pay Period Er	nd January 15, 2021	Net Change Order Amount Current Contract Amo	\$11,403.00 wint\$744,217.10
Approval Date							By User
January 19, 2021			Generated and A	Approved (and should be conside	ered Draft) at the P	roject Office Level by	schnod1
January 19, 2021			Reviewed and Appro	oved (and should be considered [	Draft) at the Reside	ent Engineer Level by	warrem1
January 20, 2021			F	Reviewed and Approved at the C	entral Office Contr	ollers Office Level by	greggd1
Original Comp	letion Date	Currei	nt Completion Date	Actual Completion Date	% of Cu	Irrent Contract Amount	Complete
December	1, 2020	De	cember 1, 2020	October 30, 2020		95.78%	

No Milestones Exist for Contract

Contract Total Pa	y For Estimate No. 10			
		This Estimate	Previous	To Date
190816-C02				
	Total Posted Items Pay	\$11,141.75	\$701,681.00	\$712,822.75
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liguidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		-	\$701,681.00	\$712,822.75
Contract Total Pa	yable This Estimate:	\$11,141.75		

### Contract Total Payable This Estimate: Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4I3219	0320	6061010	GUARDRAIL TYPE A	LF	\$20.900	-12.5	(\$261.25)
	5001	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	EA	\$3,780.000	1	\$3,780.00
	5002	6161033	DIRECTIONAL INDICATOR BARRICADE	EA	\$63.000	28	\$1,764.00
	5003	6161055	SEQUENTIAL FLASHING WARNING LIGHT	EA	\$89.250	28	\$2,499.00
	5004	8051000A	SEEDING - COOL SEASON MIXTURES	ACRE	\$5,600.000	0.6	\$3,360.00
Project J4I321	9 - Total						\$11,141.75
<b>Overall - Total</b>							\$11,141.75

#### Contract Adjustments This Estimate

#### No Contract Adjustments Exist on Contract

Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3219	0420	SLAB ON STEEL	Material			-809	\$287.30	(\$232,425.70)
	0420	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	809	\$287.30	\$232,425.70
	0430	SAFETY BARRIER CURB	Material			-502	\$52.50	(\$26,355.00)
	0430	SAFETY BARRIER CURB	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	502	\$52.50	\$26,355.00
	0440	SUBSTRUCTURE REPAIR (UNFORMED)	Material			-31.4	\$90.85	(\$2,852.69)
	0440	SUBSTRUCTURE REPAIR (UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 6 on	31.4	\$90.85	\$2,852.69



#### Pay Estimate Created Date: January 19, 2021

	Progre	ess Estimate Number	Contract ID Prime Contractor	190816-C0 Radmache Co.,Inc.	)2 r Brothers Ex	cavating	Pay Period Start Pay Period End	January 2, 2021 January 15, 2021	Original Con Amount Net Change Amount Current Cor	Order	\$732,814.10 \$11,403.00 nt\$744,217.10
Project Number	Line No.	Item De	escription	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3219							the current Pay	/ment Estimate.			
	0540	VERTICAL	DRAIN AT END BENTS	Material					-2	\$2,193.55	(\$4,387.10
	0540	VERTICAL	DRAIN AT END BENTS	Material		generat Adju	ustment offsets the ed Material Paymer stment (0002) due g Payment Estimate the current Pay	nt Estimate Item to user schnod1	2	\$2,193.55	\$4,387.10
	5001		TTENUATOR 60 (SAND BARREL ARRAY)	Material					-1	\$3,780.00	(\$3,780.00
	5001		ITENUATOR 60 (SAND BARREL ARRAY)	Material		generat Adju	ustment offsets the ed Material Paymer stment (0007) due payment Estimate the current Pay	nt Estimate Item to user schnod1	1	\$3,780.00	\$3,780.00
	5002	DIRECTION	IAL INDICATOR BARRICADE	Material					-28	\$63.00	(\$1,764.00
	5002	DIRECTION	IAL INDICATOR BARRICADE	Material		generat Adju	ustment offsets the ed Material Paymer stment (0008) due p Payment Estimate the current Pay	nt Estimate Item to user schnod1	28	\$63.00	\$1,764.00
	5003		TIAL FLASHING ARNING LIGHT	Material					-28	\$89.25	(\$2,499.00
	5003		TIAL FLASHING ARNING LIGHT	Material		generat Adju	ustment offsets the ed Material Paymer stment (0005) due payment Estimate the current Pay	nt Estimate Item to user schnod1	28	\$89.25	\$2,499.00
	5004	SEEDING -	COOL SEASON MIXTURES	Material					-0.6	\$5,600.00	(\$3,360.00
	5004	SEEDING -	COOL SEASON MIXTURES	Material		generat Adju	ustment offsets the ed Material Paymer stment (0006) due f p Payment Estimate the current Pay	nt Estimate Item to user schnod1	0.6	\$5,600.00	\$3,360.00
Total											\$0.00



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4I3219	FAS S302(001)	Bridge deck replacement	I-35	CLAY	on 128th Street		
Totals by	Job Numbe	rs					
J4I3219		d Item Pay Item Adjustme		Item Pay	This Estimate \$11,141.75 \$0.00 <b>\$11,141.75</b>	Previous \$701,681.00 \$0.00 <b>\$701,681.00</b>	To Date \$712,822.75 \$0.00 <b>\$712,822.75</b>
					\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 6122014, Project Item Line Number 5001, Material Set 612201496, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 6161033, Project Item Line Number 5002, Material Set 616103396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 6161055, Project Item Line Number 5003, Material Set 616105596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034212, Project Item Line Number 0420, Material Set 703421296, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034215, Project Item Line Number 0430, Material Set 703421596, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7040102, Project Item Line Number 0440, Material Set 704010296, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7151001, Project Item Line Number 0540, Material Set 7151001, Material 0715DRVT - Vertical Drain at End Bents, Acceptance Action Generic 0715DRVT is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 8051000A, Project Item Line Number 5004, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 8051000A, Project Item Line Number 5004, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 8051000A, Project Item Line Number 5004, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3219, Item 8051000A, Project Item Line Number 5004, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	No Remark was entered by Engineer	schnod1	Overridden

#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report General

Note: Posted Q	uantities	and Valu	ies are l	based on F	Report Generated date and can differ from the posted am	iount at th	ne time th	ne Estimate	was Ger	nerated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190816-C02	J4I3219	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$3,580.95	\$3,580.95
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$829.00	\$829.00
		0001	0030	2069903	MISC.Ditch Cleanout	228.00	0.00	228.00	LF	228.00	\$11.00	\$2,508.00
		0001	0040	2153000	SHAPING SLOPES, CLASS III	5.00	0.00	5.00	100F	5.00	\$1,098.25	\$5,491.25
		0001	0050	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	48.00	0.00	48.00	SQYD	48.00	\$20.90	\$1,003.20
		0001	0060	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	28.80	0.00	28.80	TONS	28.80	\$288.75	\$8,316.00
		0001	0070	4071005	TACK COAT	3.00	0.00	3.00	GAL	3.00	\$10.50	\$31.50
		0001	0080	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	9.00	0.00	9.00	CUYD	9.00	\$45.55	\$409.95
		0001	0090	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	15.00	0.00	15.00	CUYD	15.00	\$45.55	\$683.25
		0001	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	9.00	0.00	9.00	CUYD	9.00	\$48.95	\$440.55
		0001	0110	6096042	PLACING TYPE 2 ROCK DITCH LINER	15.00	0.00	15.00	CUYD	15.00	\$48.95	\$734.25
		0001	0120	6113020	FURNISHING TYPE 2 ROCK BLANKET	215.00	0.00	215.00	CUYD	215.00	\$37.10	\$7,976.50
		0001	0130	6113040	PLACING TYPE 2 ROCK BLANKET	215.00	0.00	215.00	CUYD	215.00	\$40.80	\$8,772.00
		0001	0140	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$685.35	\$0.00
		0001	0150	6161005	CONSTRUCTION SIGNS	658.00	0.00	658.00	SQFT	593.00	\$6.30	\$3,735.90
		0001	0160	6161009	FLAG ASSEMBLY	12.00	0.00	12.00	EA	4.00	\$18.90	\$75.60
		0001	0170	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	50.00	\$13.65	\$682.50
		0001	0180	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	8.00	0.00	8.00	EA	8.00	\$157.50	\$1,260.00
		0001	0190	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$525.00	\$1,050.00
		0001	0200	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$2,887.50	\$11,550.00
		0001	0210	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	600.00	0.00	600.00	LF	125.00	\$12.95	\$1,618.75
		0001	0220	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	600.00	0.00	600.00	LF	0.00	\$8.35	\$0.00
		0001	0230	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$99,709.60	\$99,709.60
		0001	0240	6200001	COLD APPLIED TAPE PAVEMENT MARKING, 4 IN., WHITE	3,920.00	0.00	3,920.00	LF	0.00	\$1.00	\$0.00
		0001	0250	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,900.00	0.00	4,900.00	LF	0.00	\$0.55	\$0.00
		0001	0260	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,375.00	0.00	1,375.00	LF	890.00	\$0.55	\$489.50
		0001	0270	6207001	PAVEMENT MARKING REMOVAL	8,820.00	0.00	8,820.00	LF	0.00	\$0.45	\$0.00
		0001	0280	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	298.00	0.00	298.00	SQYD	298.00	\$15.25	\$4,544.50
		0001	0290	6240104A	SEPARATION GEOTEXTILE	500.00	0.00	500.00	SQYD	456.93	\$2.25	\$1,028.09
		0001	0300	8061005	ROCK DITCH CHECK	30.00	0.00	30.00	LF	0.00	\$21.00	\$0.00
		0001	0310	9035004A	SH-FLAT SHEET	24.00	0.00	24.00	SQFT	24.00	\$23.10	\$554.40
		0010	0320	6061010	GUARDRAIL TYPE A	12.50	0.00	12.50	LF	0.00	\$20.90	\$0.00
		0010	0330	6061060	MGS GUARDRAIL	112.50	0.00	112.50	LF	112.50	\$20.90	\$2,351.25
		0010	0340	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	3.00	0.00	3.00	EA	3.00	\$2,887.50	\$8,662.50
		0010	0350	6062200A	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (ROADWAY AND REHABILITATION WORK ONLY)	1.00	0.00	1.00	EA	1.00	\$1,995.00	\$1,995.00
		0010	0360	6062300A	TRANSITION SECTION, 6.5 FT. POSTS	1.00	0.00	1.00	EA	1.00	\$472.50	\$472.50
		0010	0370	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	3.00	\$2,940.00	\$8,820.00
		0010	0380	6063015	TYPE A CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	1.00	\$2,940.00	\$2,940.00
		0070	0390	2162500	REMOVAL OF EXISTING BRIDGE DECK		0.00	6,977.00	SQFT	6,977.00	\$9.65	\$67,328.05
		0070	0400	2169902	MISC.REMOVAL OF EXISTING BEARINGS		0.00	8.00	EA	8.00	\$384.70	\$3,077.60
		0070	0410	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)		0.00	112.00	SQYD	112.00	\$153.30	\$17,169.60
		0070	0420	7034212	SLAB ON STEEL	809.00	0.00	809.00	SQYD	809.00	\$287.30	\$232,425.70
		0070	0430	7034215	SAFETY BARRIER CURB	502.00	0.00	502.00	LF	502.00	\$52.50	\$26,355.00

# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

## Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report General

ed date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190816-C02	J4I3219	0070	0440	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	80.00	0.00	80.00	SQFT	31.40	\$90.85	\$2,852.69
		0070	0450	7040164	FIBER REINFORCED POLYMER WRAP	94.00	0.00	94.00	SF	94.00	\$151.95	\$14,283.30
		0070	0460	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$7,068.60	\$7,068.60
		0070	0470	7121250	STRENGTHENING EXISTING BEAMS	1.00	0.00	1.00	LS	1.00	\$54,075.60	\$54,075.60
		0070	0480	7123610	SLAB DRAIN	4.00	0.00	4.00	EA	4.00	\$347.00	\$1,388.00
		0070	0490	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	600.00	0.00	600.00	SQFT	600.00	\$44.75	\$26,850.00
		0070	0500	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	600.00	0.00	600.00	SQFT	600.00	\$2.50	\$1,500.00
		0070	0510	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	600.00	0.00	600.00	SQFT	600.00	\$1.50	\$900.00
		0070	0520	7125370A	FINISH FIELD COAT (SYSTEM G)	600.00	0.00	600.00	SQFT	600.00	\$1.50	\$900.00
		0070	0530	7126000	NON-DESTRUCTIVE TESTING	68.00	0.00	68.00	LF	68.00	\$31.50	\$2,142.00
		0070	0540	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$2,193.55	\$4,387.10
		0070	0550	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$2,225.10	\$17,800.80
		0070	0560	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	56.00	0.00	56.00	LF	56.00	\$510.70	\$28,599.20
		0001	5001	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	0.00	1.00	1.00	EA	1.00	\$3,780.00	\$3,780.00
		0001	5002	6161033	DIRECTIONAL INDICATOR BARRICADE	0.00	28.00	28.00	EA	28.00	\$63.00	\$1,764.00
		0001	5003	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	28.00	28.00	EA	28.00	\$89.25	\$2,499.00
		0001	5004	8051000A	SEEDING - COOL SEASON MIXTURES	0.00	0.60	0.60	ACRE	0.60	\$5,600.00	\$3,360.00
	Project	J4I3219 - To	otal Value	e Posted to D	ate as of Report Generated Date							\$712,822.73
190816-C02 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$712,822.73



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	C	Description	DWR Date	DWR Approval Date	Quantity Posted	Units			Loca	ation		From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance		Comments	
0320	6061010	GUARDRAIL TYPE A		1/12/21	I 1/19/21	-12.50	LF						0		0				
5001		IMPACT ATTENUATOR ARRAY)	60 MPH (SAND BARREL	1/12/21	1/19/21	1.00	EA	NB I-35	Inside sho	oulder			0		0				
5002	6161033	DIRECTIONAL INDICAT	OR BARRICADE	1/12/21	1/19/21	28.00	EA	Various	Locations				0		0				
5003	6161055	SEQUENTIAL FLASHIN	G WARNING LIGHT	1/12/21	1/19/21	28.00	EA	Various	Locations				0		0				
5004	8051000A	SEEDING - COOL SEAS	ON MIXTURES	1/12/21	1/19/21	0.60	ACRE	Various	Locations				0		0				
e infor	mation bel	ow this line are de	tails for Construction S	igns (if a	pplicable	<u>).</u>													
,	Line Number		Total Quantity Posted For D			Sign Inform			Station	Log Mile	Location	Number of Iter		Each Sign		Special	Sign	SF Each Special Sign	
413219	0150	September 21, 2020	593		R11-2 48 CLOSED	x30 10.00	ROAD			.066	128th Street	1.00	10						
					WO20-6a RIGHT/CEN			OSED		Various	135	4.00	16						e
					See Special	Sign Detail	ls			.326	128th Street	1.00			Bridge I	Rehabilitati	on Spring 2020	32.00	:
					R11-4 60 CLOSED TO	x30 12.50 THRU TR	AFFIC			.504	128th Street	1.00	12.	5					12
					See Special	Sign Detail	ls			.572	128th Street	1.00			Bridge I	Rehabilitati	on Spring 2020	32.00	:
					WO20-3 4 CLOSED AF		00 ROAD			1.13	128th Street	1.00	16						1
					R11-2 48 CLOSED	x30 10.00	ROAD			1.311	128th Street	1.00	10						
					R2-1 36: XX	x48 12.00	SPEED L	IMIT		Various	135	0.00	12						
					WO20-6a RIGHT/CEN			OSED		Various	135	0.00	16						
					G020-5aP (PLAQUE)	36x24 6.0	0 WORK	ZONE		Various	135	0.00	6						
					CONST-8 ZONE NO P	48x36 12 HONE ZOM	2.00 WOF	RK		Various	135	2.00	12						:
					WO4-1L 4 (SYMBOL F	18x48 16.0 ROM LEFT	00 MERG	E		Various	135	2.00	16						:
					WO4-1R (SYMBOL F			E		Various	135	2.00	16						3
					CONST-7-7 WORK ZON		8.00 RAT	EOUR		Various	135	2.00	18						:
					G020-5aP (PLAQUE)	36x24 6.0	0 WORK	ZONE		Various	135	4.00	6						:
					GO20-2 4 WORK	8x24 8.00	0 END RO	DAD		Various	135	4.00	8						:
					R2-1 36: XX	x48 12.00	SPEED L	IMIT		Various	135	4.00	12						
					WO20-1 4 ROAD/BRID			HEAD		Various	135	4.00	16						
					WO20-5 4 RIGHT/CEN AHEAD			OSED		Various	135	4.00	16						6
					R11-4 60 CLOSED TO					.152	128th Street	1.00	12.	5					12



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0050	TYPE 5 AGGREGATE FOR BASE (4 IN.	Material	Туре	6	Nov 16,	SYSTEM	(\$1,003.20)	
	THICK)			6	2020 Nov 16, 2020	SYSTEM	\$1,003.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Dec 2, 2020	SYSTEM	(\$1,003.20)	
				7	Dec 2, 2020	SYSTEM	\$1,003.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0050 ·	Total						\$0.00	
0060	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material		5	Nov 2, 2020	SYSTEM	(\$8,316.00)	
				5	Nov 2, 2020	SYSTEM	\$8,316.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0060 ·	Total						\$0.00	
0070	TACK COAT	Material		5	Nov 2, 2020	SYSTEM	(\$31.50)	
				5	Nov 2, 2020	SYSTEM	\$31.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0070 ·	Total						\$0.00	
0120	FURNISHING TYPE 2 ROCK BLANKET	Material		2	Sep 16, 2020	SYSTEM	(\$7,974.64)	
				2	Sep 16, 2020	SYSTEM	\$7,974.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Oct 2, 2020	SYSTEM	(\$7,974.64)	
				3	Oct 2, 2020	SYSTEM	\$7,974.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0120 ·	Total						\$0.00	
0190	FLASHING ARROW PANEL	Material		1	Sep 2, 2020	SYSTEM	(\$1,050.00)	
				1	Sep 2, 2020	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Paymen Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total						\$0.00	
0190 -		Material		1	Sep 2, 2020	SYSTEM	(\$11,550.00)	
	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE,				Sep 2,	SYSTEM	\$11,550.00	This adjustment offsets the original system-generated Overrun
0190 · 0200				1	2020			Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Paymen Estimate.
	COMMUNICATION INTERFACE, CONTRACTOR FURNISHED,		- Total	1			\$0.00	overridding Payment Estimate Exception 2 on the current Paymer



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0200 -	Total						\$0.00	
0210	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		8	Dec 16, 2020	SYSTEM	(\$1,618.75)	
				8	Dec 16, 2020	SYSTEM	\$1,618.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
)210 -	Total						\$0.00	
0260	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		6	Nov 16, 2020	SYSTEM	(\$489.50)	
	BEADS			6	Nov 16, 2020	SYSTEM	\$489.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 6 on the current Paymen Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
260 -	Total						\$0.00	
)290	SEPARATION GEOTEXTILE	Material		2	Sep 16, 2020	SYSTEM	(\$725.47)	
				2	Sep 16, 2020	SYSTEM	\$725.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	Oct 2, 2020	SYSTEM	(\$725.47)	
				3	Oct 2, 2020	SYSTEM	\$725.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Paymen Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
)290 -	Total						\$0.00	
0310	SH-FLAT SHEET	Material		6	Nov 16, 2020	SYSTEM	(\$554.40)	
				6	Nov 16, 2020	SYSTEM	\$554.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				7	Dec 2, 2020	SYSTEM	(\$554.40)	
				7	Dec 2, 2020	SYSTEM	\$554.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$554.40)	
				8	Dec 16, 2020	SYSTEM	\$554.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0310 -	Total						\$0.00	
)320	GUARDRAIL TYPE A	Material		6	Nov 16, 2020	SYSTEM	(\$261.25)	
				6	Nov 16, 2020	SYSTEM	\$261.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Dec 2, 2020	SYSTEM	(\$261.25)	
				7	Dec 2, 2020	SYSTEM	\$261.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 4 on the current Paymer Estimate.



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0320	GUARDRAIL TYPE A	Material	Туре	8	Dec 16, 2020	SYSTEM	(\$261.25)	
				8	Dec 16, 2020	SYSTEM	\$261.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$261.25)	
				9	Jan 4, 2021	SYSTEM	\$261.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0320 -							\$0.00	
0330	MGS GUARDRAIL	Material		6	Nov 16, 2020	SYSTEM	(\$2,351.25)	
				6	Nov 16, 2020	SYSTEM	\$2,351.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Dec 2, 2020	SYSTEM	(\$2,351.25)	
				7	Dec 2, 2020	SYSTEM	\$2,351.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0330 -	Total						\$0.00	
0410	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		5	Nov 2, 2020	SYSTEM	(\$17,169.60)	
				5	Nov 2, 2020	SYSTEM	\$17,169.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$17,169.60)	
				6	Nov 16, 2020	SYSTEM	\$17,169.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Dec 2, 2020	SYSTEM	(\$17,169.60)	
				7	Dec 2, 2020	SYSTEM	\$17,169.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0410 - 0420	Total SLAB ON STEEL	Material		4	Oct 16,	SYSTEM	\$0.00 (\$232,425.70)	
0420	SLAD ON STELL	Material			2020		,	This adjustment off als the existence expressed Querry
				4	Oct 16, 2020	SYSTEM	\$232,425.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Nov 2, 2020	SYSTEM	(\$232,425.70)	
				5	Nov 2, 2020	SYSTEM	\$232,425.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$232,425.70)	
				6	Nov 16, 2020	SYSTEM	\$232,425.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0420	SLAB ON STEEL	Material						Estimate.
				7	Dec 2, 2020	SYSTEM	(\$232,425.70)	
				7	Dec 2, 2020	SYSTEM	\$232,425.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$232,425.70)	
				8	Dec 16, 2020	SYSTEM	\$232,425.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$232,425.70)	
				9	Jan 4, 2021	SYSTEM	\$232,425.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Jan 19, 2021	SYSTEM	(\$232,425.70)	
				10	Jan 19, 2021	SYSTEM	\$232,425.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0420 -	Total						\$0.00	
0430	SAFETY BARRIER CURB	Material		4	Oct 16, 2020	SYSTEM	(\$26,355.00)	
				4	Oct 16, 2020	SYSTEM	\$26,355.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				5	Nov 2, 2020	SYSTEM	(\$26,355.00)	
				5	Nov 2, 2020	SYSTEM	\$26,355.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$26,355.00)	
				6	Nov 16, 2020	SYSTEM	\$26,355.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				7	Dec 2, 2020	SYSTEM	(\$26,355.00)	
				7	Dec 2, 2020	SYSTEM	\$26,355.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$26,355.00)	
				8	Dec 16, 2020	SYSTEM	\$26,355.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$26,355.00)	
				9	Jan 4, 2021	SYSTEM	\$26,355.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				10	Jan 19, 2021	SYSTEM	(\$26,355.00)	
				10	Jan 19, 2021	SYSTEM	\$26,355.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0430		Material	- Total				\$0.00	
	Material - Total						\$0.00	
)430 -	Total						\$0.00	
0440	SUBSTRUCTURE REPAIR (UNFORMED)	Material		7	Dec 2, 2020	SYSTEM	(\$2,852.69)	
				7	Dec 2, 2020	SYSTEM	\$2,852.69	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$2,852.69)	
				8	Dec 16, 2020	SYSTEM	\$2,852.69	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 6 on the current Paymen Estimate.
				9	Jan 4, 2021	SYSTEM	(\$2,852.69)	
				9	Jan 4, 2021	SYSTEM	\$2,852.69	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 5 on the current Paymen Estimate.
				10	Jan 19, 2021	SYSTEM	(\$2,852.69)	
				10	Jan 19, 2021	SYSTEM	\$2,852.69	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
440 -	Total						\$0.00	
0460	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)			6	Nov 16, 2020	SYSTEM	(\$7,068.60)	
				6	Nov 16, 2020	SYSTEM	\$7,068.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				7	Dec 2, 2020	SYSTEM	(\$7,068.60)	
				7	Dec 2, 2020	SYSTEM	\$7,068.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$7,068.60)	
				8	Dec 16, 2020	SYSTEM	\$7,068.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total						\$0.00	
0490	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material		5	Nov 2, 2020	SYSTEM	(\$26,850.00)	
				5	Nov 2, 2020	SYSTEM	\$26,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$26,850.00)	
				6	Nov 16, 2020	SYSTEM	\$26,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				7	Dec 2, 2020	SYSTEM	(\$26,850.00)	
				7	Dec 2, 2020	SYSTEM	\$26,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 15 on the current



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0490	SURFACE PREPARATION FOR	Material	51					Payment Estimate.
	RECOATING STRUCTURAL STEEL			8	Dec 16, 2020	SYSTEM	(\$26,850.00)	
				8	Dec 16, 2020	SYSTEM	\$26,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0490 -	- Total						\$0.00	
0500	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material		5	Nov 2, 2020	SYSTEM	(\$1,500.00)	
				5	Nov 2, 2020	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$1,500.00)	
				6	Nov 16, 2020	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				7	Dec 2, 2020	SYSTEM	(\$1,500.00)	
				7	Dec 2, 2020	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$1,500.00)	
				8	Dec 16, 2020	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total							
							\$0.00	
0500 -	Total						\$0.00 \$0.00	
<b>0500</b> - 0510		Material		5	Nov 2, 2020	SYSTEM	<b>\$0.00</b> (\$900.00)	
	Total INTERMEDIATE FIELD COAT (SYSTEM	Material		5		SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
	Total INTERMEDIATE FIELD COAT (SYSTEM	Material		5	2020 Nov 2, 2020 Nov 16, 2020	SYSTEM	\$0.00 (\$900.00) \$900.00 (\$900.00)	Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
	Total INTERMEDIATE FIELD COAT (SYSTEM	Material		5	2020 Nov 2, 2020 Nov 16,	SYSTEM	\$0.00 (\$900.00) \$900.00	Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 18 on the current
	Total INTERMEDIATE FIELD COAT (SYSTEM	Material		5	2020 Nov 2, 2020 Nov 16, 2020 Nov 16,	SYSTEM	\$0.00 (\$900.00) \$900.00 (\$900.00)	Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 17 on the current
	Total INTERMEDIATE FIELD COAT (SYSTEM	Material		5 6 6	2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 2,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$900.00) \$900.00 (\$900.00) \$900.00	Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 17 on the current
	Total INTERMEDIATE FIELD COAT (SYSTEM	Material		5 6 6 7	2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$900.00) \$900.00 (\$900.00) \$900.00 (\$900.00)	Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 18 on the current
	Total INTERMEDIATE FIELD COAT (SYSTEM	Material		5 6 6 7 7 7	2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$900.00) \$900.00 (\$900.00) \$900.00 (\$900.00) \$900.00	Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 18 on the current
	Total INTERMEDIATE FIELD COAT (SYSTEM	Material	- Total	5 6 6 7 7 7 8	2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Dec 16, Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$900.00) \$900.00 (\$900.00) \$900.00 (\$900.00) \$900.00	Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate.
	Total INTERMEDIATE FIELD COAT (SYSTEM	Material	- Total	5 6 6 7 7 7 8	2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Dec 16, Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$900.00) \$900.00 (\$900.00) \$900.00 (\$900.00) \$900.00 (\$900.00)	Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate.
0510	Total INTERMEDIATE FIELD COAT (SYSTEM G)	Material	- Total	5 6 6 7 7 7 8	2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Dec 16, Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$900.00) \$900.00 (\$900.00) \$900.00 (\$900.00) \$900.00 (\$900.00) \$900.00	Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate.
0510	Total INTERMEDIATE FIELD COAT (SYSTEM G) Material - Total Total	Material	- Total	5 6 6 7 7 7 8	2020 Nov 2, 2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Dec 16, Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$900.00) \$900.00 (\$900.00) (\$900.00) \$900.00 (\$900.00) \$900.00 \$900.00	Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
)520	FINISH FIELD COAT (SYSTEM G)	Material	75-		2020			Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
				6	Nov 16, 2020	SYSTEM	(\$900.00)										
				6	Nov 16, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.									
				7	Dec 2, 2020	SYSTEM	(\$900.00)										
				7	Dec 2, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
				8	Dec 16, 2020	SYSTEM	(\$900.00)										
				8	Dec 16, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
			- Total				\$0.00										
	Material - Total						\$0.00										
520 - 540	Total VERTICAL DRAIN AT END BENTS	Material		4	Oct 16,	SYSTEM	\$0.00										
940	VERTICAL DRAIN AT END BENTS	watenai		4	2020	STSTEM	(\$4,387.10)										
				4	Oct 16, 2020	SYSTEM	\$4,387.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.									
				5	Nov 2, 2020	SYSTEM	(\$4,387.10)										
				5	Nov 2, 2020	SYSTEM	\$4,387.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.									
				6	Nov 16, 2020	SYSTEM	(\$4,387.10)										
				6	Nov 16, 2020	SYSTEM	\$4,387.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
				7	Dec 2, 2020	SYSTEM	(\$4,387.10)										
				7	Dec 2, 2020	SYSTEM	\$4,387.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.									
				8	Dec 16, 2020	SYSTEM	(\$4,387.10)										
													8	Dec 16, 2020	SYSTEM	\$4,387.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$4,387.10)										
				9	Jan 4, 2021	SYSTEM	\$4,387.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 6 on the current Paymer Estimate.									
				10	Jan 19, 2021	SYSTEM	(\$4,387.10)										
				10	Jan 19, 2021	SYSTEM	\$4,387.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 7 on the current Paymer Estimate.									
			- Total				\$0.00										
	Material - Total						\$0.00										
	Total						\$0.00										



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5001	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	Material		10	Jan 19, 2021	SYSTEM	(\$3,780.00)	
				10	Jan 19, 2021	SYSTEM	\$3,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
5001 -	Total						\$0.00	
5002	DIRECTIONAL INDICATOR BARRICADE	Material		10	Jan 19, 2021	SYSTEM	(\$1,764.00)	
				10	Jan 19, 2021	SYSTEM	\$1,764.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
5002 -	- Total						\$0.00	
5003	SEQUENTIAL FLASHING WARNING LIGHT	Material		10	Jan 19, 2021	SYSTEM	(\$2,499.00)	
				10	Jan 19, 2021	SYSTEM	\$2,499.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
5003 -	- Total						\$0.00	
5004	SEEDING - COOL SEASON MIXTURES	Material		10	Jan 19, 2021	SYSTEM	(\$3,360.00)	
				10	Jan 19, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
5004 -	Total						\$0.00	
	ill - Total				\$0.00			