

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 12, 2020

Progress Estimate Number	Contract ID	190920-B02	Pay Period Start	July 31, 2020	Original Contract Amount	\$1,161,369.55
6	Prime Contractor	Pavement Solutions, LLC	Pay Period End	,	Net Change Order Amount Current Contract Amount	
					Current Contract Amount	ψ1,101,009.00

Approval Date		By User
August 17, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by	vierss
August 17, 2020	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	vierss
August 18, 2020	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Completion Date	<b>Current Completion Date</b>	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2020	November 1, 2020		47.41%

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 6			
	This Estimate	Previous	To Date
190920-B02			
Total Posted Items Pay	\$0.00	\$550,593.81	\$550,593.81
Gross Item Adjustments	\$0.00	\$0.00	\$0.00
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	(\$36,000.00)	(\$36,000.00)
Other Contract Adjustme	ents \$0.00	\$0.00	\$0.00
		\$514,593.81	\$514,593.81
Contract Total Payable This Estimate:	\$0.00		

### Items Paid This Estimate Period

No Data Available

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
2S3172	0030	COMPACTING EMBANKMENT	Material			-246	\$9.93	(\$2,442.78)
	0030	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user liebhd overridding Payment Estimate Exception 1 on the current Payment Estimate.	246	\$9.93	\$2,442.78
	0060	SUBGRADE COMPACTION (6-INCH DEPTH)	Material			-11	\$736.36	(\$8,099.96)
	0060	SUBGRADE COMPACTION (6-INCH DEPTH)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.	11	\$736.36	\$8,099.96
	0100	GRAVEL (A) OR CRUSHED STONE (B)	Material			-7.4	\$56.95	(\$421.43)
	0100	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.	7.4	\$56.95	\$421.43
	0160	PIPE COLLAR, TYPE A	Material			-1	\$1,308.49	(\$1,308.49)
	0160	PIPE COLLAR, TYPE A	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user liebhd overridding Payment Estimate Exception 4 on the current Payment Estimate.	1	\$1,308.49	\$1,308.49
	0210	CURB AND GUTTER TYPE B	Material			-452.6	\$24.79	(\$11,219.95)
	0210	CURB AND GUTTER TYPE B	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user liebhd	452.6	\$24.79	\$11,219.95

Revision 4/1/2020 Page 1 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 12, 2020

Progress Estimate Number 6 Contract ID 190920-B02 Pay Period Start July 31, 2020 Original Contract Amount \$1,161,369.55 Pay Period End August 12, 2020 Net Change Order Amount \$0.00 \$1,161,369.55

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2S3172					overridding Payment Estimate Exception 5 on the current Payment Estimate.			
	0220	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-2.3	\$103.53	(\$238.12)
	0220	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 8 on the current Payment Estimate.	2.3	\$103.53	\$238.12
	0230	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-2	\$70.91	(\$141.82)
	0230	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 10 on the current Payment Estimate.	2	\$70.91	\$141.82
	0240	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material			-2	\$79.53	(\$159.06)
	0240	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user liebhd overridding Payment Estimate Exception 11 on the current Payment Estimate.	2	\$79.53	\$159.06
Total								\$0.00

Revision 4/1/2020 Page 2 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information	ı
Project Number	Federal Proj. Number	Description	Route	County			Location of Work
J2S3172	FAS S201(12)	Pavement improvements and ADA improvements	С	MACON	in Bevier		
J2S3223	FAS- S201(041	ADA improvements	149	MACON	from Trailer Court Lane	to Delmar Place in New Ca	ambria
Totals by	Job Numb	ers					
J2S3172		ed Item Pay s Item Adjustmen	its Gross It	em Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$536,070.81 \$0.00 \$536,070.81	To Date \$536,070.81 \$0.00 \$536,070.81
	Liqui	itive centive dated Damages r Contract Adjust	ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 (\$25,596.00) \$0.00	\$0.00 \$0.00 (\$25,596.00) \$0.00
J2S3223		ed Item Pay s Item Adjustmen	its Gross It	em Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$14,523.00 \$0.00 <b>\$14,523.00</b>	To Date \$14,523.00 \$0.00 <b>\$14,523.00</b>
	Liqui	tive centive dated Damages r Contract Adjust	ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 (\$10,404.00) \$0.00	\$0.00 \$0.00 (\$10,404.00) \$0.00

Revision 4/1/2020 Page 3 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J2S3172, Item 2036000, Project Item Line Number 0030, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	LIEBHD	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3172, Item 2101006A, Project Item Line Number 0060, Material Set 2101006A96, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	LIEBHD	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3172, Item 3105002, Project Item Line Number 0100, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	LIEBHD	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3172, Item 6044011, Project Item Line Number 0160, Material Set 6044011, Material 0604CPCR - Collar for Pipe Connection, Acceptance Action Generic 0604CPCR is insufficient.	No Remark was entered by Engineer	LIEBHD	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3172, Item 6091052, Project Item Line Number 0210, Material Set 609105296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	LIEBHD	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3172, Item 6091052, Project Item Line Number 0210, Material Set 609105296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	LIEBHD	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3172, Item 6091052, Project Item Line Number 0210, Material Set 609105296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	LIEBHD	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3172, Item 6131010, Project Item Line Number 0220, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	LIEBHD	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3172, Item 6131010, Project Item Line Number 0220, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	LIEBHD	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3172, Item 6131012, Project Item Line Number 0230, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	LIEBHD	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3172, Item 6131013, Project Item Line Number 0240, Material Set 613101396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	LIEBHD	Overridden

Revision 4/1/2020 Page 4 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
90920-B02	J2S3172	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.90	\$90,000.00	\$81,000.00
		0001	0020	2031000	CLASS A EXCAVATION	2,456.00	0.00	2,456.00	CUYD	2,456.00	\$19.11	\$46,934.16
		0001	0030	2036000	COMPACTING EMBANKMENT	246.00	0.00	246.00	CUYD	246.00	\$9.93	\$2,442.78
		0001	0040	2063000	CLASS 3 EXCAVATION	1,035.00	0.00	1,035.00	CUYD	1,035.00	\$20.11	\$20,813.8
		0001	0050	2071000	LINEAR GRADING CLASS 1	3.20	0.00	3.20	STA	2.00	\$843.75	\$1,687.50
		0001	0060	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	11.00	0.00	11.00	100F	11.00	\$736.36	\$8,099.96
		0001	0070	2142000	FURNISHING ROCK FILL	23.00	0.00	23.00	CUYD	0.00	\$43.00	\$0.0
		0001	0800	2143000	PLACING ROCK FILL	23.00	0.00	23.00	CUYD	0.00	\$39.03	\$0.0
		0001	0090	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	283.00	0.00	283.00	SQYD	0.00	\$8.02	\$0.0
		0001	0100	3105002	GRAVEL (A) OR CRUSHED STONE (B)	8.00	0.00	8.00	TONS	7.40	\$56.95	\$421.4
		0001	0110	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	30.50	0.00	30.50	TONS	0.00	\$231.00	\$0.0
		0001	0120	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	61.00	0.00	61.00	TONS	0.00	\$231.00	\$0.0
		0001	0130	4039905	MISC.OPTIONAL PAVEMENT	2,478.40	0.00	2,478.40	SQYD	2,230.00	\$70.00	\$156,100.0
		0001	0140	4071005	TACK COAT	15.00	0.00	15.00	GAL	0.00	\$4.00	\$0.0
		0001	0150	6042010	ADJUSTING MANHOLE	5.00	0.00	5.00	EA	0.00	\$1,189.45	\$0.0
		0001	0160	6044011	PIPE COLLAR, TYPE A	1.00	0.00	1.00	EA	1.00	\$1,308.49	\$1,308.4
		0001	0170	6081010	CONCRETE CURB RAMP	86.00	0.00	86.00	SQYD	0.00	\$235.21	\$0.0
		0001	0180	6081012	TRUNCATED DOMES	90.00	0.00	90.00	SQFT	0.00	\$18.87	\$0.0
		0001	0190	6085008	PAVED APPROACH, 8 IN.	515.00	0.00	515.00	SQYD	0.00	\$84.60	\$0.0
		0001	0200	6089905	MISC.REINFORCED SIDEWALK	559.00	0.00	559.00	SQYD	0.00	\$51.78	\$0.0
		0001	0210	6091052	CURB AND GUTTER TYPE B	1,688.00	0.00	1,688.00	LF	452.60	\$24.79	\$11,219.9
		0001	0220	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	2.30	0.00	2.30	SQYD	2.30	\$103.53	\$238.1
		0001	0230	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	2.00	0.00	2.00	SQYD	2.00	\$70.91	\$141.8
		0001	0240	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	2.00	0.00	2.00	SQYD	2.00	\$79.53	\$159.0
		0001	0250	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	42.00	0.00	42.00	LF	42.00	\$3.00	\$126.0
		0001	0260	6161005	CONSTRUCTION SIGNS	204.00	0.00	204.00	SQFT	204.00	\$9.00	\$1,836.0
		0001	0270	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	0.00	8.00	EA	8.00	\$45.00	\$360.0
		0001	0280	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$15.00	\$90.0
		0001	0290	6161010	RELOCATED SIGNS	204.00	0.00	204.00	SQFT	0.00	\$9.00	\$0.0
		0001	0300	6161025	CHANNELIZER (TRIM LINE)	26.00	0.00	26.00	EA	26.00	\$18.00	\$468.0
		0001	0310	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	6.00	0.00	6.00	EA	6.00	\$155.00	\$930.0
		0001	0320	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	3.00	0.00	3.00	EA	3.00	\$4,500.00	\$13,500.0
		0001	0330	6169902	MISC.DETECTABLE PEDESTRIAN CHANNELIZING BARRICADE	4.00	0.00	4.00	EA	4.00	\$140.00	\$560.0
		0001	0340	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$150,000.00	\$75,000.0
		0001	0350	6200031	COLD APPLIED TAPE PAVEMENT MARKING, R/R CROSSING MARKER	1.00	0.00	1.00	EA	0.00	\$1,200.00	\$0.0
		0001	0360	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	72.00	0.00	72.00	EA	0.00	\$135.00	\$0.
		0001	0370	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	112.00	0.00	112.00	LF	0.00	\$2.00	\$0.
		0001	0380	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,855.00	0.00	1,855.00	LF	0.00	\$1.50	\$0.
		0001	0390	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.95	\$16,500.00	\$15,675.
		0001	0400	7032002	CLASS B CONCRETE (MISC)	0.50	0.00	0.50	CUYD	0.00	\$3,065.16	\$0.0
		0001	0410	7061000	REINFORCING STEEL	30.00	0.00	30.00	LB	0.00	\$2.50	\$0.0
		0001	0420	7250412	12 IN. PIPE GROUP C	39.00	0.00	39.00	LF	39.00	\$146.09	\$5,697.5
		0001	0430	7250415	15 IN. PIPE GROUP C	627.00	0.00	627.00	LF	627.00	\$50.23	\$31,494.2

Revision 4/1/2020 Page 5 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190920-B02	J2S3172	0001	0440	7250418	18 IN. PIPE GROUP C	410.00	0.00	410.00	LF	410.00	\$57.08	\$23,402.80
		0001	0450	7311030	PRECAST CONCRETE DROP INLET 3 FT X 2 FT-6 IN.	24.00	0.00	24.00	FT	24.00	\$344.67	\$8,272.08
		0001	0460	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	30.00	0.00	30.00	FT	30.00	\$420.33	\$12,609.90
		0001	0470	7320812A	12 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	5.00	0.00	5.00	EA	5.00	\$899.56	\$4,497.80
		0001	0480	7320815A	15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	3.00	0.00	3.00	EA	3.00	\$915.63	\$2,746.89
		0001	0490	8059901	MISC.SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	LS	0.00	\$440.00	\$0.00
		0001	0500	8061006	ALTERNATE DITCH CHECK	72.00	0.00	72.00	LF	72.00	\$12.00	\$864.00
		0001	0510	8061007A	CURB INLET CHECK	17.00	0.00	17.00	EA	17.00	\$100.00	\$1,700.00
		0001	0520	8061016	SEDIMENT REMOVAL	40.00	0.00	40.00	CUYD	0.00	\$55.40	\$0.00
		0001	0530	8061019	SILT FENCE	1,621.00	0.00	1,621.00	LF	1,621.00	\$3.50	\$5,673.50
		0001	0540	8069901	MISC.TEMPORARY SEEDING AND MULCHING	1.00	0.00	1.00	LS	0.00	\$800.00	\$0.00
		0040	0550	9031010	CONCRETE FOOTINGS, EMBEDDED	0.90	0.00	0.90	CUYD	0.00	\$1,750.00	\$0.00
		0040	0560	9031270A	2 IN. PSST POST - 12 GA.	137.00	0.00	137.00	LF	0.00	\$13.15	\$0.00
		0040	0570	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	30.00	0.00	30.00	LF	0.00	\$46.75	\$0.00
		0040	0580	9035069A	SHF-FLAT SHEET FLUORESCENT	88.00	0.00	88.00	SQFT	0.00	\$50.20	\$0.00
	Project J	2S3172 - To	otal Value	Posted to D	ate as of Report Generated Date							\$536,070.81
	J2S3223	0001	0590	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$60,000.00	\$0.00
		0001	0600	2031000	CLASS A EXCAVATION	375.00	0.00	375.00	CUYD	0.00	\$22.67	\$0.00
		0001	0610	2036000	COMPACTING EMBANKMENT	159.00	0.00	159.00	CUYD	0.00	\$15.36	\$0.00
		0001	0620	2063000	CLASS 3 EXCAVATION	11.00	0.00	11.00	CUYD	0.00	\$30.91	\$0.00
		0001	0630	3105002	GRAVEL (A) OR CRUSHED STONE (B)	8.00	0.00	8.00	TONS	0.00	\$56.95	\$0.00
		0001	0640	6042010	ADJUSTING MANHOLE	6.00	0.00	6.00	EA	0.00	\$1,034.00	\$0.00
		0001	0650	6081010	CONCRETE CURB RAMP	113.20	0.00	113.20	SQYD	0.00	\$205.77	\$0.00
		0001	0660	6081012	TRUNCATED DOMES	180.00	0.00	180.00	SQFT	0.00	\$16.24	\$0.00
		0001	0670	6085008	PAVED APPROACH, 8 IN.	339.80	0.00	339.80	SQYD	0.00	\$87.19	\$0.00
		0001	0680	6089905	MISC.REINFORCED SIDEWALK	896.90	0.00	896.90	SQYD	0.00	\$51.15	\$0.00
		0001	0690	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR $$ 1524 MM X 914 MM)	1.00	0.00	1.00	EA	0.00	\$2,486.22	\$0.00
		0001	0700	6161005	CONSTRUCTION SIGNS	207.00	0.00	207.00	SQFT	207.00	\$9.00	\$1,863.00
		0001	0710	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	6.00	\$45.00	\$270.00
		0001	0720	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	2.00	\$15.00	\$30.00
		0001	0730	6161010	RELOCATED SIGNS	207.00	0.00	207.00	SQFT	0.00	\$9.00	\$0.00
		0001	0740	6161025	CHANNELIZER (TRIM LINE)	32.00	0.00	32.00	EA	32.00	\$18.00	\$576.00
		0001	0750	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	4.00	0.00	4.00	EA	4.00	\$155.00	\$620.00
		0001	0760	6169902	MISC.DETECTABLE PEDESTRIAN CHANNELIZING BARRICADE	2.00	0.00	2.00	EA	2.00	\$140.00	\$280.00
		0001	0770	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$75,000.00	\$0.00
		0001	0780	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	156.00	0.00	156.00	EA	0.00	\$135.00	\$0.00
		0001	0790	6207001	PAVEMENT MARKING REMOVAL	48.00	0.00	48.00	LF	0.00	\$18.00	\$0.00
		0001	0800	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$14,200.00	\$7,100.00
		0001	0810	7032002	CLASS B CONCRETE (MISC)	0.70	0.00	0.70	CUYD	0.00	\$1,977.97	\$0.00
		0001	0820	7061000	REINFORCING STEEL	40.00	0.00	40.00	LB	0.00	\$2.50	\$0.00
		0001	0830	7250412	12 IN. PIPE GROUP C	22.00	0.00	22.00	LF	0.00	\$97.88	\$0.00
		0001	0840	7250415	15 IN. PIPE GROUP C	17.00	0.00	17.00	LF	0.00	\$118.14	\$0.00
		0001	0850	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	4.00	0.00	4.00	FT	0.00	\$494.06	\$0.00
		0001	0860	7320812A	12 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END	4.00	0.00	4.00	EA	0.00	\$899.56	\$0.00
		0001	0870	7320815A	SECTION  15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END	1.00	0.00	1.00	EA	0.00	\$915.63	\$0.00
		5501					00			0.00	÷=:5:00	\$5.50

Revision 4/1/2020 Page 6 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190920-B02	J2S3223				SECTION							
		0001	0880	8059901	MISC.SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	LS	0.00	\$4,400.00	\$0.00
		0001	0890	8061006	ALTERNATE DITCH CHECK	108.00	0.00	108.00	LF	108.00	\$12.00	\$1,296.00
		0001	0900	8061007A	CURB INLET CHECK	13.00	0.00	13.00	EA	13.00	\$100.00	\$1,300.00
		0001	0910	8061016	SEDIMENT REMOVAL	25.00	0.00	25.00	CUYD	0.00	\$63.08	\$0.00
		0001	0920	8061019	SILT FENCE	216.00	0.00	216.00	LF	216.00	\$5.50	\$1,188.00
		0001	0930	8069901	MISC.TEMPORARY SEEDING AND MULCHING	1.00	0.00	1.00	LS	0.00	\$800.00	\$0.00
		0040	0940	9031010	CONCRETE FOOTINGS, EMBEDDED	1.60	0.00	1.60	CUYD	0.00	\$1,700.00	\$0.00
		0040	0950	9031020	CONCRETE FOOTINGS, BOLT DOWN	0.40	0.00	0.40	CUYD	0.00	\$2,240.00	\$0.00
		0040	0960	9031270A	2 IN. PSST POST - 12 GA.	272.00	0.00	272.00	LF	0.00	\$9.30	\$0.00
		0040	0970	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	51.00	0.00	51.00	LF	0.00	\$34.98	\$0.00
		0040	0980	9035069A	SHF-FLAT SHEET FLUORESCENT	176.00	0.00	176.00	SQFT	0.00	\$35.50	\$0.00
	Project J	2S3223 - To	tal Value	Posted to D	ate as of Report Generated Date							\$14,523.00
90920-B02 Ove	rall - Total	Value Post	ed to Dat	te as of Repo	ort Generated Date							\$550,593.81

Revision 4/1/2020 Page 7 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 8 of 12



	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0030	COMPACTING EMBANKMENT	Material		4	Jul 15, 2020	SYSTEM	(\$2,442.78)	
				4	Jul 15, 2020	SYSTEM	\$2,442.78	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user liebhd overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Jul 30, 2020	SYSTEM	(\$2,442.78)	
				5	Jul 30, 2020	SYSTEM	\$2,442.78	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user liebhd overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Aug 12, 2020	SYSTEM	(\$2,442.78)	
				6	Aug 12, 2020	SYSTEM	\$2,442.78	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user liebhd overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0030 -	Total						\$0.00	
0060	SUBGRADE COMPACTION (6- INCH DEPTH)	Material		4	Jul 15, 2020	SYSTEM	(\$8,099.96)	
				4	Jul 15, 2020	SYSTEM	\$8,099.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Jul 30, 2020	SYSTEM	(\$8,099.96)	
				5	Jul 30, 2020	SYSTEM	\$8,099.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Aug 12, 2020	SYSTEM	(\$8,099.96)	
				6	Aug 12, 2020	SYSTEM	\$8,099.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total	6		SYSTEM	\$8,099.96	Estimate Item Adjustment (0002) due to user liebhd overridding Payment
	Material - Total		- Total	6		SYSTEM		Estimate Item Adjustment (0002) due to user liebhd overridding Payment
			- Total	6		SYSTEM	\$0.00	Estimate Item Adjustment (0002) due to user liebhd overridding Payment
0060 -		Material	- Total	5		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0002) due to user liebhd overridding Payment
0060 -	Total  GRAVEL (A) OR CRUSHED	Material	- Total		2020 Jul 30,		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0002) due to user liebhd overridding Payment
0060 - 1	Total  GRAVEL (A) OR CRUSHED	Material	- Total	5	Jul 30, 2020 Jul 30,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$421.43)	Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment
0060 -	Total  GRAVEL (A) OR CRUSHED	Material	- Total	5	Jul 30, 2020 Jul 30, 2020 Aug 12,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$421.43) \$421.43	Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment
0060 -	Total  GRAVEL (A) OR CRUSHED	Material	- Total	5 5	Jul 30, 2020 Jul 30, 2020 Jul 30, 2020 Aug 12, 2020	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$421.43) \$421.43	Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment
0060 - <sup>*</sup>	Total  GRAVEL (A) OR CRUSHED	Material		5 5	Jul 30, 2020 Jul 30, 2020 Jul 30, 2020 Aug 12, 2020	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$421.43) \$421.43 (\$421.43)	Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment
0060 - <sup>*</sup>	GRAVEL (A) OR CRUSHED STONE (B)	Material		5 5	Jul 30, 2020 Jul 30, 2020 Jul 30, 2020 Aug 12, 2020	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$421.43) \$421.43 \$421.43	Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment
0060 - · 0100	GRAVEL (A) OR CRUSHED STONE (B)			5 5	Jul 30, 2020 Jul 30, 2020 Jul 30, 2020 Aug 12, 2020	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$421.43) \$421.43 (\$421.43) \$421.43	Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment
0100 - 010	GRAVEL (A) OR CRUSHED STONE (B)  Material - Total			5 5 6 6	Jul 30, 2020 Jul 30, 2020 Aug 12, 2020 Aug 12, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$421.43) \$421.43 (\$421.43) \$421.43	Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment
0060 - · 0100	GRAVEL (A) OR CRUSHED STONE (B)  Material - Total			5 5 6 6 6	Jul 30, 2020 Jul 30, 2020 Aug 12, 2020 Aug 12, 2020 Jun 29, 2020 Jun 29,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$421.43) \$421.43 (\$421.43) \$421.43 \$0.00 \$0.00 (\$1,308.49)	Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 3 on the current Payment Estimate.
0100 - 010	GRAVEL (A) OR CRUSHED STONE (B)  Material - Total			5 5 6 6	Jul 30, 2020  Jul 30, 2020  Aug 12, 2020  Aug 12, 2020  Jun 29, 2020  Jun 29, 2020  Jul 15,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$421.43) \$421.43 (\$421.43) \$421.43 \$0.00 \$0.00 (\$1,308.49)	Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 3 on the current Payment Estimate.
0060 - 0100	GRAVEL (A) OR CRUSHED STONE (B)  Material - Total			5 5 6 6 3 3	Jul 30, 2020 Jul 30, 2020 Aug 12, 2020  Jun 29, 2020 Jun 29, 2020 Jul 15, 2020 Jul 15,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$421.43) \$421.43 (\$421.43) \$421.43 \$0.00 \$0.00 \$1,308.49 (\$1,308.49)	Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user liebhd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment
0100 - 010	GRAVEL (A) OR CRUSHED STONE (B)  Material - Total			5 5 6 6 3 3 4 4	Jul 30, 2020  Jul 30, 2020  Aug 12, 2020  Jul 29, 2020  Jul 29, 2020  Jul 15, 2020  Jul 30, 30, 30, 30, 30, 30, 30, 30, 30, 30,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$421.43) \$421.43 (\$421.43) \$421.43 \$0.00 \$0.00 \$1.308.49 (\$1,308.49) \$1,308.49	Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user liebhd overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment

Revision 4/1/2020 Page 9 of 12



PRESCRIAR TYPE A	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Material - Total	0160	PIPE COLLAR, TYPE A	Material		6		SYSTEM	\$1,308.49	Estimate Item Adjustment (0004) due to user liebhd overridding Payment
CURB AND GUTTER TYPE 8				- Total				\$0.00	
CURB AND QUITER TYPE B		Material - Total						\$0.00	
2020   3   Jul 20, SYSTEM   \$11,219.05   STEM   \$11,219.05   STE	0160 -	Total						\$0.00	
200	0210	CURB AND GUTTER TYPE B	Material		3		SYSTEM	(\$11,219.95)	
					3		SYSTEM	\$11,219.95	Estimate Item Adjustment (0002) due to user liebhd overridding Payment
2000   September					4		SYSTEM	(\$11,219.95)	
Supplementary					4		SYSTEM	\$11,219.95	Estimate Item Adjustment (0004) due to user liebhd overridding Payment
2020   System   Estimate Exception 5 on the current Payment Estimate.					5		SYSTEM	(\$11,219.95)	
2020   2020   2021   2020					5		SYSTEM	\$11,219.95	Estimate Item Adjustment (0005) due to user liebhd overridding Payment
Substitute   Sub					6		SYSTEM	(\$11,219.95)	
Material - Total   S0.00					6		SYSTEM	\$11,219.95	Estimate Item Adjustment (0005) due to user liebhd overridding Payment
D210   Total   Support   Total   Support   S				- Total				\$0.00	
Purnishing And PLACING CONCRETE MATERIAL FOR FULL		Material - Total						\$0.00	
CONCRETE MATERIAL FOR FULL   DEPTH PAVEMENT REPAIR   2020   4	0210 -	Total						\$0.00	
A   201   5   579 TEM   \$238.12   Estimate Exception 11 on the current Payment Estimate.	0220	CONCRETE MATERIAL FOR FULL	Material		4		SYSTEM	(\$238.12)	
2020					4		SYSTEM	\$238.12	Estimate Item Adjustment (0005) due to user liebhd overridding Payment
2020   Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 12 on the current Payment Estimate.					5		SYSTEM	(\$238.12)	
2020 6 Aug 12, 2020 7 Total  Subgrade Compaction (6 in. DEPTH) (PAVEMENT REPAIR)  But a company of the current Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 8 on the current Payment Payment Payment Payment Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 16 on the current Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 16 on the current Payment Estimate Exception 16 on the current Payment Estimate Exception 16 on the current Payment Estimate Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 16 on the current Payment Estimate Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 10 on the current Payment Estimate Exception					5		SYSTEM	\$238.12	Estimate Item Adjustment (0006) due to user liebhd overridding Payment
Substitute   Sub					6		SYSTEM	(\$238.12)	
Material - Total   \$0.00					6		SYSTEM	\$238.12	Estimate Item Adjustment (0006) due to user liebhd overridding Payment
SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)   SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)   SYSTEM   SYSTEM   S141.82   This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 15 on the current Payment Estimate.   SySTEM   S141.82   This adjustment offsets the original system-generated Overrun Payment Estimate Exception 15 on the current Payment Estimate.   This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 16 on the current Payment Estimate.   SySTEM								\$0.00	
SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  ### A Jul 15, 2020  ### A Jul 15, 2020  ### SYSTEM (\$141.82)  ### A Jul 15, 2020  ### SYSTEM (\$141.82)  ### A Jul 15, 2020  ### SYSTEM (\$141.82)		Material - Total						\$0.00	
DEPTH) (PAVEMENT REPAIR)  4 Jul 15, 2020 \$\frac{1}{2020}\$	0220 -	Total						\$0.00	
Estimate Item Adjustment (0006) dué to user liebhd overridding Páyment Estimate Exception 15 on the current Payment Estimate.  5 Jul 30, 2020  5 Jul 30, 2020  \$ SYSTEM \$ \$141.82 \$ This adjustment offsets the original system-generated Overrun Payment Estimate Exception 16 on the current Payment Estimate.  6 Aug 12, 2020  6 Aug 12, 2020  8 SYSTEM \$ \$141.82 \$ This adjustment (0007) due to user liebhd overridding Payment Estimate Exception 16 on the current Payment Estimate.  7 Total \$ \$0.00 \$ SYSTEM \$ \$0.00	0230		Material		4		SYSTEM	(\$141.82)	
5 Jul 30, 2020 \$\frac{1}{2}\$ \text{ 141.82 } \text{ This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 16 on the current Payment Estimate.  6 Aug 12, 2020 \$\text{ (\$141.82)}\$  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 10 on the current Payment Estimate.  - Total \$0.00  Material - Total					4		SYSTEM	\$141.82	Estimate Item Adjustment (0006) due to user liebhd overridding Payment
2020 Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 16 on the current Payment Estimate.  6 Aug 12, 2020 6 Aug 12, 2020 7 SYSTEM \$141.82 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 10 on the current Payment Estimate.  - Total \$0.00  Material - Total					5		SYSTEM	(\$141.82)	
2020 6 Aug 12, 2020 8 \$141.82 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 10 on the current Payment Estimate.  - Total \$0.00  Material - Total \$0.00					5		SYSTEM	\$141.82	Estimate Item Adjustment (0007) due to user liebhd overridding Payment
2020 Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 10 on the current Payment Estimate.  - Total \$0.00  Material - Total \$0.00					6		SYSTEM	(\$141.82)	
Material - Total \$0.00					6		SYSTEM	\$141.82	Estimate Item Adjustment (0007) due to user liebhd overridding Payment
			- Total					\$0.00	
0230 - Total \$0.00		Material - Total						\$0.00	
	0230 -	Total						\$0.00	

Revision 4/1/2020 Page 10 of 12



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0240	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT	Material		4	Jul 15, 2020	SYSTEM	(\$159.06)	
	REPAIR)			4	Jul 15, 2020	SYSTEM	\$159.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 16 on the current Payment Estimate.
				5	Jul 30, 2020	SYSTEM	(\$159.06)	
				5	Jul 30, 2020	SYSTEM	\$159.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user liebhd overridding Payment Estimate Exception 17 on the current Payment Estimate.
				6	Aug 12, 2020	SYSTEM	(\$159.06)	
				6	Aug 12, 2020	SYSTEM	\$159.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user liebhd overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0240 -	· Total						\$0.00	
0420		Material		3	Jun 29, 2020	SYSTEM	(\$5,697.51)	
				3	Jun 29, 2020	SYSTEM	\$5,697.51	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user liebhd overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0420 -	· Total						\$0.00	
0430	15 IN. PIPE GROUP C	Material		3	Jun 29, 2020	SYSTEM		
				3	Jun 29, 2020	SYSTEM	\$31,494.21	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user liebhd overridding Payment Estimate Exception 11 on the current Payment Estimate.
	- Total						\$0.00	
			- I otai				<b>\$0.00</b>	
	Material - Total		- I otal				\$0.00	
0430 -			- I otal					
<b>0430</b> - 0440		Material	- I otal	3	Jun 29, 2020	SYSTEM	\$0.00	
	· Total	Material	- I otal	3		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user liebhd overridding Payment Estimate Exception 13 on the current Payment Estimate.
	· Total	Material	- Total		2020 Jun 29,		\$0.00 \$0.00 (\$23,402.80)	Estimate Item Adjustment (0005) due to user liebhd overridding Payment
	· Total	Material			2020 Jun 29,		\$0.00 \$0.00 (\$23,402.80) \$23,402.80	Estimate Item Adjustment (0005) due to user liebhd overridding Payment
	Total  18 IN. PIPE GROUP C  Material - Total	Material			2020 Jun 29,		\$0.00 \$0.00 (\$23,402.80) \$23,402.80 \$0.00	Estimate Item Adjustment (0005) due to user liebhd overridding Payment
0440	Total  18 IN. PIPE GROUP C  Material - Total	Material Material			2020 Jun 29,		\$0.00 \$0.00 (\$23,402.80) \$23,402.80 \$0.00	Estimate Item Adjustment (0005) due to user liebhd overridding Payment
0440 -	Total  18 IN. PIPE GROUP C  Material - Total  PRECAST CONCRETE DROP			3	Jun 29, 2020  Jun 29, 2020	SYSTEM	\$0.00 \$0.00 (\$23,402.80) \$23,402.80 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user liebhd overridding Payment
0440 -	Total  18 IN. PIPE GROUP C  Material - Total  PRECAST CONCRETE DROP			3	Jun 29, 2020  Jun 29, 2020  Jun 29, 2020  Jun 29,	SYSTEM	\$0.00 \$0.00 (\$23,402.80) \$23,402.80 \$0.00 \$0.00 (\$8,272.08)	Estimate Item Adjustment (0005) due to user liebhd overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment
0440 -	Total  18 IN. PIPE GROUP C  Material - Total  PRECAST CONCRETE DROP		- Total	3	Jun 29, 2020  Jun 29, 2020  Jun 29, 2020  Jun 29,	SYSTEM	\$0.00 \$0.00 (\$23,402.80) \$23,402.80 \$0.00 \$0.00 (\$8,272.08)	Estimate Item Adjustment (0005) due to user liebhd overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment
0440 -	Total  18 IN. PIPE GROUP C  Material - Total  Total  PRECAST CONCRETE DROP INLET 3 FT X 2 FT-6 IN.  Material - Total		- Total	3	Jun 29, 2020  Jun 29, 2020  Jun 29, 2020  Jun 29,	SYSTEM	\$0.00 \$0.00 (\$23,402.80) \$23,402.80 \$0.00 \$0.00 (\$8,272.08) \$8,272.08	Estimate Item Adjustment (0005) due to user liebhd overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment
0440 - 0440 - 0450	Total  18 IN. PIPE GROUP C  Material - Total  Total  PRECAST CONCRETE DROP INLET 3 FT X 2 FT-6 IN.  Material - Total		- Total	3	Jun 29, 2020  Jun 29, 2020  Jun 29, 2020  Jun 29,	SYSTEM	\$0.00 \$0.00 (\$23,402.80) \$23,402.80 \$0.00 \$0.00 (\$8,272.08) \$8,272.08	Estimate Item Adjustment (0005) due to user liebhd overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment
0440 - 0450 -	Total  18 IN. PIPE GROUP C  Material - Total  Total  PRECAST CONCRETE DROP INLET 3 FT X 2 FT-6 IN.  Material - Total  Total  PRECAST CONCRETE DROP	Material	- Total	3 3	Jun 29, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$23,402.80) \$23,402.80 \$0.00 \$0.00 (\$8,272.08) \$8,272.08	Estimate Item Adjustment (0005) due to user liebhd overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment
0440 - 0450 -	Total  18 IN. PIPE GROUP C  Material - Total  Total  PRECAST CONCRETE DROP INLET 3 FT X 2 FT-6 IN.  Material - Total  Total  PRECAST CONCRETE DROP	Material	- Total	3 3	Jun 29, 2020  Jun 29, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$23,402.80) \$23,402.80 \$0.00 \$0.00 (\$8,272.08) \$8,272.08 \$0.00 \$0.00 \$0.00 (\$12,609.90)	Estimate Item Adjustment (0005) due to user liebhd overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment
0440 - 0450 -	Total  18 IN. PIPE GROUP C  Material - Total  Total  PRECAST CONCRETE DROP INLET 3 FT X 2 FT-6 IN.  Material - Total  Total  PRECAST CONCRETE DROP	Material	- Total	3 3	Jun 29, 2020  Jun 29, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$23,402.80) \$23,402.80 \$0.00 \$0.00 \$0.00 (\$8,272.08) \$8,272.08 \$0.00 \$0.00 \$12,609.90)	Estimate Item Adjustment (0005) due to user liebhd overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment
0440 - 0450 -	Material - Total  PRECAST CONCRETE DROP INLET 3 FT X 2 FT-6 IN.  Material - Total  PRECAST CONCRETE DROP INLET 5 FT X 3 FT  Material - Total	Material	- Total	3 3	Jun 29, 2020  Jun 29, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$23,402.80) \$23,402.80 \$0.00 \$0.00 (\$8,272.08) \$8,272.08 \$0.00 \$0.00 \$12,609.90 \$12,609.90	Estimate Item Adjustment (0005) due to user liebhd overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment
0440 - 0450 - 0450 - 0460	Material - Total  PRECAST CONCRETE DROP INLET 3 FT X 2 FT-6 IN.  Material - Total  PRECAST CONCRETE DROP INLET 5 FT X 3 FT  Material - Total	Material	- Total	3 3	Jun 29, 2020  Jun 29, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$23,402.80) \$23,402.80 \$0.00 \$0.00 (\$8,272.08) \$8,272.08 \$0.00 \$0.00 \$12,609.90) \$12,609.90	Estimate Item Adjustment (0005) due to user liebhd overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment

Revision 4/1/2020 Page 11 of 12



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0470		Material	- Total				\$0.00	
	Material - Total				\$0.00			
0470 -							\$0.00	
0480		Material		3	Jun 29, 2020	SYSTEM	(\$2,746.89)	
				3	Jun 29, 2020	SYSTEM	\$2,746.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user liebhd overridding Payment Estimate Exception 17 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
0480 -	Total						\$0.00	
0500	ALTERNATE DITCH CHECK	Material		3	Jun 29, 2020	SYSTEM	(\$864.00)	
				3	Jun 29, 2020	SYSTEM	\$864.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user liebhd overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0500 -	Total						\$0.00	
0510	CURB INLET CHECK	Material		3	Jun 29, 2020	SYSTEM	(\$1,700.00)	
				3	Jun 29, 2020	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user liebhd overridding Payment Estimate Exception 21 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
0510 -	Total						\$0.00	
0890	ALTERNATE DITCH CHECK	Material		3	Jun 29, 2020	SYSTEM	(\$1,296.00)	
				3	Jun 29, 2020	SYSTEM	\$1,296.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user liebhd overridding Payment Estimate Exception 19 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0890 -	Total						\$0.00	
0900	CURB INLET CHECK	Material		3	Jun 29, 2020	SYSTEM	(\$1,300.00)	
				3	Jun 29, 2020	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user liebhd overridding Payment Estimate Exception 20 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0900 -	Total						\$0.00	
Overall - Total							\$0.00	

Revision 4/1/2020 Page 12 of 12