

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 15, 2020

Progress Estin 2	nate Number	•		August 2, 2020 August 15, 2020	Original Contract Amount Net Change Order Amount Current Contract Amount	\$118,439.50 \$0.00 \$118,439.50			
Approval Date							By User		
August 15, 2020		t the Project Office Level by	beckeb1						
August 18, 2020		Review	wed and Approved (	and should be consid	dered Draft) at the	Resident Engineer Level by	janssm		
August 18, 2020			Revie	wed and Approved a	t the Central Office	e Controllers Office Level by	greggd1		
Original Comp	npletion Date Current Completion Date Actual Completion Date % of Current Contract Amou								
September 25, 2020 September 25, 2020 85.69%									

No Milestones Exist for Contract

Contract Total Pay	For Estimate No. 2				
		This Estimate	Previous	To Date	
190920-F02					
	Total Posted Items Pay	\$43,863.90	\$57,621.00	\$101,484.90	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$57,621.00	\$101,484.90	
<b>Contract Total Paya</b>	ble This Estimate:	\$43,863.90			

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3327	0020	6169901	MISC.TEMPORARY TRAFFIC CONTROL	LS	\$3,832.000	0.45	\$1,724.40
	0030	6181000	MOBILIZATION	LS	\$9,000.000	0.25	\$2,250.00
	0160	6233000	EPOXY POLYMER WEARING SURFACE	SQYD	\$50.750	786	\$39,889.50
Project J6S3327	- Total						\$43,863.90
Overall - Total	\$43,863.90						

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	<u>Adjust</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3327	0010	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material			-2	\$2,800.00	(\$5,600.00)
	0010	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user beckeb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	2	\$2,800.00	\$5,600.00
	0140	REMOVAL OF EXISTING DECK REPAIR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-21	\$34.00	(\$714.00)
	0140	REMOVAL OF EXISTING DECK REPAIR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user beckeb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	21	\$34.00	\$714.00
	0160	EPOXY POLYMER WEARING SURFACE	Material			-1,250	\$50.75	(\$63,437.50)
	0160	EPOXY POLYMER WEARING SURFACE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user beckeb1	1,250	\$50.75	\$63,437.50

Revision 4/1/2020 Page 1 of 8



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 15, 2020

Progress Estimate Number	Contract ID	190920-F02	Pay Period Start	August 2, 2020	Original Contract Amount	\$118,439.50
2	Prime Contractor	R. V. Wagner, Inc.	Pay Period End	August 15, 2020	Net Change Order Amount Current Contract Amount	\$0.00 \$118,439.50

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3327					overridding Payment Estimate Exception 3 on the current Payment Estimate.			
	0170	HALF-SOLE REPAIR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate.	21	\$175.00	\$3,675.00
	0170	HALF-SOLE REPAIR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-21	\$175.00	(\$3,675.00
	0170	HALF-SOLE REPAIR	Material			-31	\$175.00	(\$5,425.00
	0170	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user beckeb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	31	\$175.00	\$5,425.00
	0190	SILICONE EXPANSION JOINT SEALANT			This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 8 on the current Payment Estimate.	63	\$90.00	\$5,670.00
	0190	SILICONE EXPANSION JOINT SEALANT			Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-63	\$90.00	(\$5,670.00
	0190	SILICONE EXPANSION JOINT SEALANT				-108	\$90.00	(\$9,720.00
	0190	SILICONE EXPANSION JOINT SEALANT			This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user beckeb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	108	\$90.00	\$9,720.00
<b>Fotal</b>								\$0.00

Revision 4/1/2020 Page 2 of 8



Incentive Disincentive Liquidated Damages Other Contract Adjustments

### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Cor	ntract Project Inforr	nation
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6S3327	FAF 115-1(45)	Bridge rehabilitation	115	ST LOUIS	over Metrolink Railroad Track	s	
Totals by .	Job Number	's					
J6S3327		l Item Pay Item Adjustme		Item Pay	This Estimate \$43,863.90 \$0.00 <b>\$43,863.90</b>	Previous \$57,621.00 \$0.00 \$57,621.00	To Date \$101,484.90 \$0.00 \$101,484.90

\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00

\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 8



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3327, Item 6161098A, Project Item Line Number 0010, Material Set 6161098A, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Construction is aware of the discrepancy and is working with the contractor/MoDOT Materials to correct beckeb1 8/15/20	beckeb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3327, Item 6233000, Project Item Line Number 0160, Material Set 623300096, Material 1039AGPC - Aggregate for Epoxy Polymer Conc Overlay, Acceptance Action Generic 1039AGPC is insufficient.	Construction is aware of the discrepancy and is working with the contractor/MoDOT Materials to correct beckeb1 8/15/20	beckeb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3327, Item 6233000, Project Item Line Number 0160, Material Set 623300096, Material 1039ERPC - Epoxy Resin Mat for Polymer Conc Overlay, Acceptance Action Generic 1039ERPC is insufficient.	Construction is aware of the discrepancy and is working with the contractor/MoDOT Materials to correct beckeb1 8/15/20	beckeb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3327, Item 7040104, Project Item Line Number 0170, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Construction is aware of the discrepancy and is working with the contractor/MoDOT Materials to correct beckeb1 8/15/20	beckeb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3327, Item 7173002, Project Item Line Number 0190, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	Construction is aware of the discrepancy and is working with the contractor/MoDOT Materials to correct beckeb1 8/15/20	beckeb1	Overridden
Estimate Exception Type: Item Overrun: Contract 190920-F02, Contract Project J6S3327, Project Item Line Number 0140, Contract Line Item Number 0140, Item 2161503, Minor Item.	Item Overrun - beckeb1 8/15/20	beckeb1	Overridden
Estimate Exception Type: Item Overrun: Contract 190920-F02, Contract Project J6S3327, Project Item Line Number 0170, Contract Line Item Number 0170, Item 7040104, Minor Item.	No Remark was entered by Engineer	beckeb1	Overridden
Estimate Exception Type: Item Overrun: Contract 190920-F02, Contract Project J6S3327, Project Item Line Number 0190, Contract Line Item Number 0190, Item 7173002, Minor Item.	No Remark was entered by Engineer	beckeb1	Overridden

Revision 4/1/2020 Page 4 of 8



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
90920-F02	J6S3327	0001	0010	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	0020	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.95	\$3,832.00	\$3,640.40
		0001	0030	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$9,000.00	\$9,000.0
		0001	0040	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	0.00	\$350.00	\$0.00
		0001	0050	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	990.00	0.00	990.00	LF	0.00	\$2.00	\$0.00
		0001	0060	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	986.00	0.00	986.00	LF	0.00	\$2.00	\$0.0
		0001	0070	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,023.00	0.00	1,023.00	LF	0.00	\$2.00	\$0.00
		0001	0080	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	696.00	0.00	696.00	LF	0.00	\$2.00	\$0.0
		0001	0090	6207001	PAVEMENT MARKING REMOVAL	4,037.00	0.00	4,037.00	LF	1,604.00	\$2.00	\$3,208.0
		0001	0100	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	6.00	0.00	6.00	EA	4.00	\$100.00	\$400.0
		0001	0110	6209902	MISC.BIKE LANE SYMBOLS	2.00	0.00	2.00	EA	0.00	\$350.00	\$0.0
		0001	0120	6209902	MISC.TEMPORARY REMOVABLE MARKING TAPE, COMBINATION STRAIGHT-LT ARROW	2.00	0.00	2.00	EA	0.00	\$100.00	\$0.0
		0001	0130	6209903	MISC.24 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	57.00	0.00	57.00	LF	0.00	\$10.00	\$0.0
		0070	0140	2161503	REMOVAL OF EXISTING DECK REPAIR	10.00	0.00	10.00	SQFT	31.00	\$34.00	\$1,054.0
		0070	0150	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	85.00	0.00	85.00	LF	0.00	\$24.00	\$0.0
		0070	0160	6233000	EPOXY POLYMER WEARING SURFACE	1,358.00	0.00	1,358.00	SQYD	1,250.00	\$50.75	\$63,437.5
		0070	0170	7040104	HALF-SOLE REPAIR	10.00	0.00	10.00	SQFT	31.00	\$175.00	\$5,425.0
		0070	0180	7172054	OPEN CELL FOAM JOINT SEAL	85.00	0.00	85.00	LF	0.00	\$55.00	\$0.0
		0070	0190	7173002	SILICONE EXPANSION JOINT SEALANT	45.00	0.00	45.00	LF	108.00	\$90.00	\$9,720.0
	Project J	6S3327 - To	otal Value	Posted to D	Date as of Report Generated Date							\$101,484.9
0920-F02 Ove	rall - Total	Value Post	ed to Dat	te as of Repo	ort Generated Date							\$101,484.9

Revision 4/1/2020 Page 5 of 8



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	6169901	MISC.	8/4/20	8/15/20	0.20	LS		60+79.7		63+57.1		75% of original contract price paid
				8/15/20	0.25	LS		60+79.7		63+57.1		50% of original contract price paid
0030	6181000	MOBILIZATION	8/4/20	8/15/20	0.25	LS		60+79.7		63+57.1		50% of original contract price paid
0160	6233000	EPOXY POLYMER WEARING SURFACE	8/4/20	8/15/20	-136.00	SQYD		60+79.7		62+88.99		Retainage for Material Testing
				8/15/20	457.00	SQYD	Phase 2 Area - NB Lane	60+79.7		62+88.99		
				8/15/20	465.00	SQYD	Phase 2 Area - SB Lane	60+79.7		62+88.99		

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 6 of 8



### Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0010	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE,	Material		1	Aug 1, 2020	SYSTEM	(\$5,600.00)	
	CONTRACTOR FURNISHED, CONTRACTOR RETAINED			1	Aug 1, 2020	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user beckeb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				2	Aug 15, 2020	SYSTEM	(\$5,600.00)	
				2	Aug 15, 2020	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user beckeb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0010 -							\$0.00	
0140	REMOVAL OF EXISTING DECK REPAIR	Overrun	Overrun	1	Aug 1, 2020	SYSTEM	(\$714.00)	
				1	Aug 1, 2020	SYSTEM	\$306.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user beckeb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				1	Aug 1, 2020	SYSTEM	\$408.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user beckeb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				2	Aug 15, 2020	SYSTEM	(\$714.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				2	Aug 15, 2020	SYSTEM	\$714.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user beckeb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0140 -	- Total						\$0.00	
0160	EPOXY POLYMER WEARING SURFACE	Material		1	Aug 1, 2020	SYSTEM	(\$23,548.00)	
				1	Aug 1, 2020	SYSTEM	\$23,548.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user beckeb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				2	Aug 15, 2020	SYSTEM	(\$63,437.50)	
				2	Aug 15, 2020	SYSTEM	\$63,437.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user beckeb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0160 -	- Total						\$0.00	
0170	HALF-SOLE REPAIR	Material		1	Aug 1, 2020	SYSTEM	(\$5,425.00)	
				1	Aug 1, 2020	SYSTEM	\$5,425.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user beckeb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				2	Aug 15, 2020	SYSTEM	(\$5,425.00)	
				2	Aug 15, 2020	SYSTEM	\$5,425.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user beckeb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total		- Total				\$0.00 \$0.00	
	Material - Total  HALF-SOLE REPAIR	Overrun	- Total Overrun	1	Aug 1, 2020	SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 7 on the current Payment Estimate.

Revision 4/1/2020 Page 7 of 8



### Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0170	HALF-SOLE REPAIR	Overrun	Overrun		2020			Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 7 on the current Payment Estimate.
				1	Aug 1, 2020	SYSTEM	(\$3,675.00)	
				2	Aug 15, 2020	SYSTEM	(\$3,675.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				2	Aug 15, 2020	SYSTEM	\$3,675.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0170	- Total						\$0.00	
0190	SILICONE EXPANSION JOINT SEALANT	Material		1	Aug 1, 2020	SYSTEM	(\$9,720.00)	
				1	Aug 1, 2020	SYSTEM	\$9,720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user beckeb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				2	Aug 15, 2020	SYSTEM	(\$9,720.00)	
				2	Aug 15, 2020	SYSTEM	\$9,720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user beckeb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	SILICONE EXPANSION JOINT SEALANT	Overrun	Overrun	1	Aug 1, 2020	SYSTEM	\$5,670.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 8 on the current Payment Estimate.
				1	Aug 1, 2020	SYSTEM	(\$5,670.00)	
				2	Aug 15, 2020	SYSTEM	(\$5,670.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				2	Aug 15, 2020	SYSTEM	\$5,670.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 8 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0190	- Total					\$0.00		
Overa	all - Total						\$0.00	

Revision 4/1/2020 Page 8 of 8