

Pay Estimate Created Date: June 1, 2020

Progress Estimate Number 6		Contract ID Prime Contractor	190920-H02 Magruder Paving, LLC		May 16, 2020 June 1, 2020	Original Contract Amount Net Change Order Amount Current Contract Amount	\$2,441,948.14 \$10,310.98 \$2,452,259.12	
Approval Date							By User	
June 1, 2020			Generated and Approve	ed (and should be co	nsidered Draft)	at the Project Office Level by	WILESR	
June 2, 2020		Rev	viewed and Approved (ar	nd should be conside	red Draft) at the	e Resident Engineer Level by	PULLIA	
June 3, 2020			Review	ed and Approved at t	he Central Offic	ce Controllers Office Level by	greggd1	
Original Comp	Driginal Completion Date Current Completion Date Actual Completion Date % of Current C							
November ?	1, 2020	November	1, 2020			99.32%		

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 6				
	This Estimate	Previous	To Date	
190920-H02				
Total Posted Items Pay	\$26,520.40	\$2,409,147.12	\$2,435,667.52	
Gross Item Adjustments	\$0.00	(\$89,188.20)	(\$89,188.20)	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		\$2,319,958.92	\$2,346,479.32	
Contract Total Payable This Estimate:	\$26,520.40			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J9P3446	0280	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$25.000	30	\$750.00	
	0290	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$275.000	3	\$825.00	
	0320	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.100	132,536	\$13,253.60	
	0330	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.100	116,918	\$11,691.80	
Project J9P	3446 - Tota	I					\$26,520.40	
Overall - Total								

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3413	0030	GRAVEL (A) OR CRUSHED STONE (B)	Material			-90	\$85.48	(\$7,693.20)
	0030	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate.	90	\$85.48	\$7,693.20
	0040	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-76.2	\$63.80	(\$4,861.56)
	0040	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user wilesr overridding Payment Estimate Exception 25 on the current Payment Estimate.	76.2	\$63.80	\$4,861.56
	0110	0110 4 IN. WHITE STANDARD Mate WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS				-155,755	\$0.10	(\$15,575.50)
	0110	4 IN. WHITE STANDARD	Material		This adjustment offsets the original system-	155,755	\$0.10	\$15,575.50

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 1, 2020

Progr	ress Es	timate Number 6	Contract II Prime Con		920-H02 gruder Paving	Pay Period Start LLC Pay Period End	June 1, 2020	Original Contract Net Change Orde Current Contract	er Amount	\$2,441,948.14 \$10,310.98 \$2,452,259.12
Project Number	Line No.	Item Descri	ption	Adjustment Type	Other Item Adjustment Type	Comme	nts	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3413		WATERBORNE F MARKING PAI				generated Overrun Pa Adjustment (000 overridding Payment Esti the curren	vilesr 8 on			
	0120	4 IN. YELLOW S WATERBORNE F MARKING PAIN	PAVEMENT	Material				-155,050	\$0.10	(\$15,505.00
	0120	4 IN. YELLOW S WATERBORNE F MARKING PAI	PAVEMENT	Material		This adjustment offsets generated Overrun Pa Adjustment (000 overridding Payment Es on the curren	yment Estimate 6) due to user v	Item vilesr on 17	\$0.10	\$15,505.00
J9P3446	0180	GRAVEL (A) OR	CRUSHED STONE (B)	Material				-55	\$103.29	(\$5,680.95)
	0180	GRAVEL (A) OR	CRUSHED STONE (B)	Material		This adjustment offsets generated Overrun Pa Adjustment (000 overridding Payment Esti the curren	yment Estimate 7) due to user v	ltem vilesr 2 on	\$103.29	\$5,680.95
	0190	BITUMINOUS F MIXTUF (SURFACE	RE PG64-22	Overrun		Averaged Price Adjustm all previous payment estir		61' is	\$73.42	(\$18,942.20)
	0190	BITUMINOUS F MIXTUF (SURFACE	RE PG64-22	Material				-13,082.7	\$76.44	(\$1,000,041.59)
	0190	BITUMINOUS F MIXTUF (SURFACE	RE PG64-22	Overrun		This adjustment offsets generated Overrun Pa Adjustment (0002) Estimate Exception 26 on	yment Estimate overridding Pay	Item ment ment	\$73.42	\$18,942.20
	0190	BITUMINOUS F MIXTUF (SURFACE	RE PG64-22	Material		This adjustment offsets generated Overrun Pa Adjustment (000 overridding Payment Esti the curren	yment Estimate 3) due to user v	Item vilesr 3 on	\$76.44	\$1,000,041.59
	0280		REFORMED IOPLASTIC ARKING, 24 IN. WHITE	Material				-30	\$25.00	(\$750.00)
	0280		REFORMED IOPLASTIC ARKING, 24 IN. WHITE	Material		This adjustment offsets generated Overrun Pa Adjustment (000 overridding Payment Esti the curren	yment Estimate 8) due to user v	ltem vilesr 4 on	\$25.00	\$750.00
	0290	THERM PAVEMENT	REFORMED IOPLASTIC MARKING, HT ARROW	Material				-3	\$275.00	(\$825.00)
	0290	THERM PAVEMENT	REFORMED IOPLASTIC MARKING, HT ARROW	Material		This adjustment offsets generated Overrun Pa Adjustment (000 overridding Payment Esti the curren	yment Estimate 9) due to user v	Item vilesr 5 on	\$275.00	\$825.00
	0300	TEMPORARY RE MARKING		Material				-2,066	\$1.80	(\$3,718.80)
	0300	TEMPORARY RE MARKING		Material		This adjustment offsets generated Overrun Pa Adjustment (001 overridding Payment Esti	yment Estimate 0) due to user v	ltem vilesr	\$1.80	\$3,718.80



Pay Estimate Created Date: June 1, 2020

Progr	ess Es	timate Number 6	Contract II Prime Con	D 190 Itractor Mag	920-H02 gruder Paving		inal Contract Change Orde ent Contract	r Amount	\$2,441,948.14 \$10,310.98 \$2,452,259.12
Project Number	Line No.	Item Descrip	tion	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3446						the current Payment Estimate.			
	0310	TEMPORARY RE MARKING TA		Material			-20	\$10.00	(\$200.00
	0310	TEMPORARY RE MARKING TA		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user wilesr overridding Payment Estimate Exception 7 on the current Payment Estimate.	20	\$10.00	\$200.00
	0320	4 IN. WHITE S WATERBORNE P MARKING PAIN	AVEMENT	Material			-132,536	\$0.10	(\$13,253.60)
	0320	4 IN. WHITE S WATERBORNE P MARKING PAIN	AVEMENT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment Estimate Exception 11 on the current Payment Estimate.	132,536	\$0.10	\$13,253.60
	0330	4 IN. YELLOW S WATERBORNE P MARKING PAIN	AVEMENT	Material			-116,918	\$0.10	(\$11,691.80)
	0330	4 IN. YELLOW S WATERBORNE P MARKING PAIN	AVEMENT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user wilesr overridding Payment Estimate Exception 14 on the current Payment Estimate.	116,918	\$0.10	\$11,691.80
	0400	CABLE, LOOP DI	ETECTOR, IN DUCT	Material			-750	\$7.90	(\$5,925.00
	0400	CABLE, LOOP DI	ETECTOR, IN DUCT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user wilesr overridding Payment Estimate Exception 24 on the current Payment Estimate.	750	\$7.90	\$5,925.00
	0410	CURB B	LOCKOUT	Material			-875	\$74.00	(\$64,750.00)
	0410 CURB BLOCKOUT			Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user wilesr overridding Payment Estimate Exception 20 on the current Payment Estimate.	875	\$74.00	\$64,750.00
Total									\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work						
J9P3413	FAF 19-1(13)	Resurface	19	SHANNON	from Route A to Riverview Drive						
J9P3446	FAF 32-2(28)	Resurface	32	TEXAS	from Route 17 to Route 63						

Totals by Job Numbers

413	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$1,184,074.35	\$1,184,074.35
Gross Item Adjustments	\$0.00	(\$46,276.15)	(\$46,276.15)
Gross Item Pay	\$0.00	\$1,137,798.20	\$1,137,798.20
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
Uther Contract Adjustments			
Other Contract Adjustments	\$0.00	Φ 0.00	\$0.00
3446	This Estimate	Previous	To Date
	• • • • •		
3446	This Estimate	Previous	To Date
3446 Posted Item Pay	This Estimate \$26,520.40	Previous \$1,225,072.77	To Date \$1,251,593.17
3446 Posted Item Pay Gross Item Adjustments Gross Item Pay	This Estimate \$26,520.40 \$0.00 \$26,520.40	Previous \$1,225,072.77 (\$42,912.05) \$1,182,160.72	To Date \$1,251,593.17 (\$42,912.05) \$1,208,681.12
3446 Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive	This Estimate \$26,520.40 \$0.00 \$26,520.40 \$0.00	Previous \$1,225,072.77 (\$42,912.05) \$1,182,160.72 \$0.00	To Date \$1,251,593,17 (\$42,912.05) \$1,208,681.12 \$0.00
3446 Posted Item Pay Gross Item Adjustments Gross Item Pay	This Estimate \$26,520.40 \$0.00 \$26,520.40	Previous \$1,225,072.77 (\$42,912.05) \$1,182,160.72	To Date \$1,251,593.17 (\$42,912.05) \$1,208,681.12



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 3105002, Project Item Line Number 0030, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 3105002, Project Item Line Number 0180, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 4020520, Project Item Line Number 0190, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6200015, Project Item Line Number 0280, Material Set 6200015, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6200021, Project Item Line Number 0290, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6205301B, Project Item Line Number 0300, Material Set 6205301B96, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6205309, Project Item Line Number 0310, Material Set 620530996, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6206000C, Project Item Line Number 0320, Material Set 6206000C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6206000C, Project Item Line Number 0320, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6206000C, Project Item Line Number 0320, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6206001C, Project Item Line Number 0330, Material Set 6206001C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6206001C, Project Item Line Number 0330, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6206001C, Project Item Line Number 0330, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 7034600, Project Item Line Number 0410, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 7034600, Project Item Line Number 0410, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 7034600, Project Item Line Number 0410, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 7034600, Project Item Line Number 0410, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Material Ok	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 9028500, Project Item Line Number 0400, Material Set 902850096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic	Material Ok	WILESR	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status	
0902TSXX is insufficient.				
Estimate Exception Type: Item Overrun: Contract 190920-H02, Contract Project J9P3413, Project Item Line Number 0040, Contract Line Item Number 0040, Item 4020520, Minor Item.	acknowledged - change order in process	WILESR	Overridden	
Estimate Exception Type: Item Overrun: Contract 190920-H02, Contract Project J9P3446, Project Item Line Number 0190, Contract Line Item Number 0190, Item 4020520, Minor Item.	Override for this exception was system generated due to greater item withholding on other pay estimate exceptions.	WILESR	Overridden	

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

					eport Generated date and can differ from the posted amo							
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190920-H02	J9P3413	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,400.00	\$2,400.00
		0001	0020	2129900	MISC.MODIFIED SHAPING SLOPES, CLASS III	2.00	0.00	2.00	100F	2.00	\$1,600.00	\$3,200.00
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	90.00	0.00	90.00	TONS	90.00	\$85.48	\$7,693.20
		0001	0040	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	15,178.00	76.20	15,254.20	TONS	15,254.20	\$63.80	\$973,217.96
		0001	0050	4071005	TACK COAT	19,356.00	-2,951.00	16,405.00	GAL	16,405.00	\$1.94	\$31,825.70
		0001	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0070	6161005	CONSTRUCTION SIGNS	1,967.00	-533.00	1,434.00	SQFT	1,434.00	\$6.50	\$9,321.00
		0001	0080	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$80.00
		0001	0090	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	100.00	\$18.00	\$1,800.00
		0001	0100	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$78,300.00	\$78,300.00
		0001	0110	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	194,694.00	0.00	194,694.00	LF	155,755.00	\$0.10	\$15,575.50
		0001	0120	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	193,812.00	0.00	193,812.00	LF	155,050.00	\$0.10	\$15,505.00
		0001	0130	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	2,409.00	0.00	2,409.00	SQYD	2,409.00	\$6.20	\$14,935.80
		0001	0140	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,477.00	0.00	1,477.00	SQYD	1,477.00	\$6.47	\$9,556.19
		0010	0150	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	488.00	0.00	488.00	LF	488.00	\$28.00	\$13,664.00
		0010	0160	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
	Project J	9P3413 - To	tal Value	Posted to D	ate as of Report Generated Date							\$1,184,074.35
	J9P3446	0001	0170	2129900	MISC.MODIFIED SHAPING SLOPES, CLASS III	4.00	0.00	4.00	100F	4.00	\$1,600.00	\$6,400.00
		0001	0180	3105002	GRAVEL (A) OR CRUSHED STONE (B)	55.00	0.00	55.00	TONS	55.00	\$103.29	\$5,680.95
		0001	0190	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	12,824.70	258.00	13,082.70	TONS	13,082.70	\$76.44	\$1,000,041.59
		0001	0200	4071005	TACK COAT	15,880.00	-2,314.00	13,566.00	GAL	13,566.00	\$1.94	\$26,318.04
		0001	0210	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0220	6161005	CONSTRUCTION SIGNS	1,958.00	-489.00	1,469.00	SQFT	1,469.00	\$6.50	\$9,548.50
		0001	0230	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	6.00	\$35.00	\$210.00
		0001	0240	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$20.00	\$120.00
		0001	0250	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	100.00	\$18.00	\$1,800.00
		0001	0260	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0270	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$9,000.00	\$9,000.00
		0001	0275	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$28,800.00	\$28,800.00
		0001	0280	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	30.00	17.00	47.00	LF	30.00	\$25.00	\$750.00
		0001	0290	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	3.00	0.00	3.00	EA	3.00	\$275.00	\$825.00
		0001	0300	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	2,066.00	1,200.00	3,266.00	LF	2,066.00	\$1.80	\$3,718.80
		0001	0310	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	20.00	0.00	20.00	LF	20.00	\$10.00	\$200.00
		0001	0320	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	165,671.00	0.00	165,671.00	LF	132,536.00	\$0.10	\$13,253.60
		0001	0330	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	146,148.00	0.00	146,148.00	LF	116,918.00	\$0.10	\$11,691.80
		0001	0340	6207001	PAVEMENT MARKING REMOVAL	1,500.00	0.00	1,500.00	LF	1,500.00	\$1.00	\$1,500.00
		0001	0350	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,335.00	0.00	1,335.00	SQYD	1,335.00	\$6.63	\$8,851.05
		0001	0360	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,924.00	0.00	1,924.00	SQYD	1,924.00	\$5.41	\$10,408.84
		0010	0370	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	350.00	0.00	350.00	LF	350.00	\$32.00	\$11,200.00
		0010	0380	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.00
		0010	0390	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.00
		0030	0400	9028500	CABLE, LOOP DETECTOR, IN DUCT	750.00	0.00	750.00	LF	750.00	\$7.90	\$5,925.00
		0070	0410	7034600	CURB BLOCKOUT	875.00	0.00	875.00	LF	875.00	\$74.00	\$64,750.00
	Project J)P3446 - To	otal Value	Posted to D	late as of Report Generated Date	r						\$1,251,593.17



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTR	Project CT No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190920-H02	Overall - Tota	al Value Pos	ted to Dat	e as of Repo	rt Generated Date							\$2,435,667.52



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9P3446

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0280	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	6/1/20	6/1/20	30.00	LF	stop bars at Rte 63					
0290	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	6/1/20	6/1/20	3.00	EA	Left turn @ 63 and (2) Rt turn @ prison					
0320	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	6/1/20	6/1/20	132,536.00	LF	80% until reflectivity results					
0330	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	6/1/20	6/1/20	116,918.00	LF	80% awaiting reflectivity results					

The information below this line are details from Line Item agency views. No Agency View Details Exist



ine	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
030	GRAVEL (A) OR CRUSHED STONE (B)	Material	Туре	4	May 3, 2020	SYSTEM	(\$7,693.20)	
				4	May 3, 2020	SYSTEM	\$7,693.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$7,693.20)	Estimate Exception Fon the current Faymont Estimate.
				5	May 15, 2020	SYSTEM	\$7,693.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$7,693.20)	
				6	Jun 1, 2020	SYSTEM	\$7,693.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total	1	1		\$0.00	
	Material - Total						\$0.00	
)30 -	Total						\$0.00	
040	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	Material		2	Apr 2, 2020	SYSTEM	(\$162,581.54)	
	LEVELING)			2	Apr 2, 2020	SYSTEM	\$162,581.54	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Apr 15, 2020	SYSTEM	(\$973,217.96)	
				3	Apr 15, 2020	SYSTEM	\$973,217.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	Other Item Adjustment	ACAD	2	Apr 2, 2020	WILESR	(\$3,261.82)	AC Adjust for 2548.3 tons of surface level at 3.2% virgin oil. Mix SL20-8
	LEVELING)			3	Apr 15, 2020	WILESR	(\$16,263.55)	12,705.9 tons of surface level 3.2% virgin AC
			ACAD - Tot	al			(\$19,525.37)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		FUEL	4	May 3, 2020	WILESR	(\$2,284.30)	Fuel Adjustment for Asphalt laid on 3/31 and 4/1. Manual adjust. due to system not applying the adjust on est 002
	- ,			4	May 3, 2020	WILESR	(\$24,466.48)	Fuel Adjustment for asphalt laid 4/2 thru 4/15. system did not apply fuel adjustment on est 003
			FUEL - Tota	1			(\$26,750.78)	
	Other Item Adjustment - Total						(\$46,276.15)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun	Overrun		Apr 15, 2020	SYSTEM	(\$4,861.56)	
				3	Apr 15, 2020	SYSTEM	\$4,861.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.
				4	May 3, 2020	SYSTEM	(\$4,861.56)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	May 3, 2020	SYSTEM	\$4,861.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user wilesr overridding Payment Estimate Exception 15 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$4,861.56)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	May 15, 2020	SYSTEM	\$4,861.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Paymen Estimate Exception 17 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$4,861.56)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Jun 1, 2020	SYSTEM	\$4,861.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user wilesr overridding Payment Estimate Exception 25 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
LINE	Description	Туре	Adjustment Type		Date	By	Amount	Reflars
0050	TACK COAT	Material		2	Apr 2, 2020	SYSTEM	(\$5,794.78)	
				2	Apr 2, 2020	SYSTEM	\$5,794.78	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	Apr 15, 2020	SYSTEM	(\$31,825.70)	
				3	Apr 15, 2020	SYSTEM	\$31,825.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0050 -	Total						\$0.00	
0110	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		4	May 3, 2020	SYSTEM	(\$15,575.50)	
	BEADS			4	May 3, 2020	SYSTEM	\$15,575.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$15,575.50)	
				5	May 15, 2020	SYSTEM	\$15,575.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$15,575.50)	
				6	Jun 1, 2020	SYSTEM	\$15,575.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0110 -	Total						\$0.00	
0120	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		4	May 3, 2020	SYSTEM	(\$15,505.00)	
				4	May 3, 2020	SYSTEM	\$15,505.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$15,505.00)	
				5	May 15, 2020	SYSTEM	\$15,505.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user wilesr overridding Payment Estimate Exception 9 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$15,505.00)	
				6	Jun 1, 2020	SYSTEM	\$15,505.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0120 -	Total						\$0.00	
0180	GRAVEL (A) OR CRUSHED STONE (B)	Material		5	May 15, 2020	SYSTEM	(\$5,680.95)	
				5	May 15, 2020	SYSTEM	\$5,680.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$5,680.95)	
				6	Jun 1, 2020	SYSTEM	\$5,680.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0180 -	Total						\$0.00	
0190	BITUMINOUS PAVEMENT	Material		4	May 3,	SYSTEM	(\$969,710.20)	



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0190	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		4	May 3, 2020	SYSTEM	\$969,710.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$1,000,041.59)	
				5	May 15, 2020	SYSTEM	\$1,000,041.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$1,000,041.59)	
				6	Jun 1, 2020	SYSTEM	\$1,000,041.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	Other Item Adjustment	ACAD	4	May 3, 2020	WILESR	(\$16,237.95)	12685.9 tons of Surface Level 3.2% virgin
	LEVELING)			5	May 15, 2020	WILESR	(\$1,047.55)	396.8 tons of surface level 3.2% virgin
			ACAD - Tota	al			(\$17,285.50)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		FUEL	4	May 3, 2020	WILESR	(\$24,427.97)	Fuel Adjustment for Asphalt laid 4/16 to 5/1
			FUEL - Tota	ıl			(\$24,427.97)	
	Other Item Adjustment - Total						(\$41,713.47)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun	Overrun	5	May 15, 2020	SYSTEM	(\$18,942.20)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				5	May 15, 2020	SYSTEM	\$18,942.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 18 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$18,942.20)	Averaged Price Adjustment from this item on all previous payment estimates of '-3.02061' is applied (if non-zero).
				6	Jun 1, 2020	SYSTEM	\$18,942.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 26 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		5	May 15, 2020	SYSTEM	(\$1,198.58)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$1,198.58)	
	Price - Total						(\$1,198.58)	
0190 -							(\$42,912.05)	
0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		6	Jun 1, 2020	SYSTEM	(\$750.00)	
				6	Jun 1, 2020	SYSTEM	\$750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0280 -							\$0.00	
0290	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		6	Jun 1, 2020	SYSTEM	(\$825.00)	
				6	Jun 1, 2020	SYSTEM	\$825.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
							\$0.00	
			- Total					
	Material - Total		- Total				\$0.00	
0290 -			- Total				\$0.00 \$0.00	
0290 - 0300		Material	- Total	2	Apr 2, 2020	SYSTEM		



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0300	TEMPORARY REMOVABLE	Material						Estimate Exception 3 on the current Payment Estimate.
	MARKING TAPE 4 IN., WHITE			3	Apr 15, 2020	SYSTEM	(\$1,859.40)	
				3	Apr 15, 2020	SYSTEM	\$1,859.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	May 3, 2020	SYSTEM	(\$1,859.40)	
				4	May 3, 2020	SYSTEM	\$1,859.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$3,718.80)	
				5	May 15, 2020	SYSTEM	\$3,718.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$3,718.80)	
				6	Jun 1, 2020	SYSTEM	\$3,718.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0300 -	Total						\$0.00	
0310	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		2	Apr 2, 2020	SYSTEM	(\$200.00)	
				2	Apr 2, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.
				3	Apr 15, 2020	SYSTEM	(\$200.00)	
				3	Apr 15, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.
				4	May 3, 2020	SYSTEM	(\$200.00)	
				4	May 3, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$200.00)	
				5	May 15, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jun 1, 2020	SYSTEM	(\$200.00)
				6	Jun 1, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user wilesr overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0310 -	Total						\$0.00	
0320	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		6	Jun 1, 2020	SYSTEM	(\$13,253.60)	
	BEADS			6	Jun 1, 2020	SYSTEM	\$13,253.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0320 -	Total						\$0.00	
0330	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	Material		6	Jun 1, 2020	SYSTEM	(\$11,691.80)	
	MARKING PAINT, TYPE P BEADS			6	Jun 1, 2020	SYSTEM	\$11,691.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user wilesr overridding Payment Estimate Exception 14 on the current Payment Estimate.



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0330		Material	- Total				\$0.00	
	Material - Total						\$0.00	
0330 -	Total						\$0.00	
0400	400 CABLE, LOOP DETECTOR, IN DUCT	Material		5	May 15, 2020	SYSTEM	(\$5,925.00)	
				5	May 15, 2020	SYSTEM	\$5,925.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user wilesr overridding Payment Estimate Exception 16 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$5,925.00)	
				6	Jun 1, 2020	SYSTEM	\$5,925.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user wilesr overridding Payment Estimate Exception 24 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0400 -	Total						\$0.00	
0410	10 CURB BLOCKOUT	Material		2	Apr 2, 2020	SYSTEM	(\$32,412.00)	
				2	Apr 2, 2020	SYSTEM	\$32,412.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
				3	Apr 15, 2020	SYSTEM	(\$64,750.00)	
				3	Apr 15, 2020	SYSTEM	\$64,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
				4	May 3, 2020	SYSTEM	(\$64,750.00)	
				4	May 3, 2020	SYSTEM	\$64,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user wilesr overridding Payment Estimate Exception 11 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$64,750.00)	
				5	May 15, 2020	SYSTEM	\$64,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment Estimate Exception 12 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$64,750.00)	
				6	Jun 1, 2020	SYSTEM	\$64,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user wilesr overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0410 -	Total						\$0.00	
Overa	III - Total						(\$89,188.20)	