

Pay Estimate Created Date: June 15, 2020

					Current Contract Amount	\$2,452,259.12			
Generated and Approved (and should be considered Draft) at the Project Office Level by									
	Reviewe	ed and Approved (an	id should be conside	red Draft) at the	Resident Engineer Level by	PULLIA			
		Reviewe	ed and Approved at t	he Central Offic	e Controllers Office Level by	greggd1			
letion Date Current Completion Date Actual Completion Date % of Current Contract Amou									
mber 1, 2020 November 1, 2020 99.43%									
20		Date Current Completion	Reviewe Pate Current Completion Date Ac	Reviewed and Approved at the Actual Completion Date Actual Completion Date	Reviewed and Approved at the Central Office Date Actual Completion Date				

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 7			
	This Estimate	Previous	To Date
190920-H02			
Total Posted Items Pay	\$2,585.00	\$2,435,667.52	\$2,438,252.52
Gross Item Adjustments	\$0.00	(\$89,188.20)	(\$89,188.20)
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$2,346,479.32	\$2,349,064.32
Contract Total Payable This Estimate:	\$2,585.00		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount				
J9P3446	0280	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$25.000	17	\$425.00				
	0300	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	LF	\$1.800	1,200	\$2,160.00				
Project J9P34	oject J9P3446 - Total										
Overall - Tota											

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
9P3413	0030	GRAVEL (A) OR CRUSHED STONE (B)	Material			-90	\$85.48	(\$7,693.20)
	0030	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate.	90	\$85.48	\$7,693.20
	0110	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-155,755	\$0.10	(\$15,575.50)
	0110	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.	155,755	\$0.10	\$15,575.50
	0120	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-155,050	\$0.10	(\$15,505.00)
	0120	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 17 on the current Payment Estimate.	155,050	\$0.10	\$15,505.00



Pay Estimate Created Date: June 15, 2020

Prog	ess Es	timate Number 7	Contract II Prime Con		920-H02 Jruder Paving	LLC Pay Period End June 15, 2020 Ne	iginal Contract It Change Orde Irrent Contract	r Amount	\$2,441,948.14 \$10,310.98 \$2,452,259.12	
Project Number	Line No.	Item Descri	ption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
9P3446	0180	GRAVEL (A) OR	CRUSHED STONE (B)	Material			-55	\$103.29	(\$5,680.95	
	0180	GRAVEL (A) OR	CRUSHED STONE (B)	Material		This adjustment offsets the original syster generated Overrun Payment Estimate Ite Adjustment (0004) due to user wile overridding Payment Estimate Exception 2 o the current Payment Estimat	m sr on	\$103.29	\$5,680.95	
	0190	BITUMINOUS I MIXTUF (SURFACE	RE PG64-22	Material			-13,082.7	\$76.44	(\$1,000,041.59	
	0190	BITUMINOUS I MIXTUF (SURFACE	RE PG64-22	Material		This adjustment offsets the original syster generated Overrun Payment Estimate Ite Adjustment (0005) due to user wile overridding Payment Estimate Exception 3 o the current Payment Estimat	m sr on	\$76.44	\$1,000,041.59	
	0280		REFORMED IOPLASTIC ARKING, 24 IN. WHITE	Material			-47	\$25.00	(\$1,175.00	
	0280		REFORMED IOPLASTIC ARKING, 24 IN. WHITE	Material		This adjustment offsets the original syster generated Overrun Payment Estimate Ite Adjustment (0006) due to user wile overridding Payment Estimate Exception 4 o the current Payment Estimat	m sr on	\$25.00	\$1,175.00	
	0290	THERN PAVEMENT	REFORMED MOPLASTIC MARKING, HT ARROW	Material			-3	\$275.00	(\$825.00	
	0290	THERN PAVEMENT	REFORMED MOPLASTIC MARKING, HT ARROW	Material		This adjustment offsets the original syster generated Overrun Payment Estimate Ite Adjustment (0007) due to user wile overridding Payment Estimate Exception 5 o the current Payment Estimat	m sr on	\$275.00	\$825.00	
	0300	TEMPORARY RI MARKING	EMOVABLE TAPE 4 IN., WHITE	Material			-3,266	\$1.80	(\$5,878.80	
	0300	TEMPORARY RI MARKING	EMOVABLE TAPE 4 IN., WHITE	Material		This adjustment offsets the original syster generated Overrun Payment Estimate Ite Adjustment (0008) due to user wile overridding Payment Estimate Exception 6 o the current Payment Estimate	m sr on	\$1.80	\$5,878.80	
	0310	TEMPORARY RI MARKING TA		Material			-20	\$10.00	(\$200.00	
	0310	TEMPORARY RI MARKING TA		Material		This adjustment offsets the original syster generated Overrun Payment Estimate Ite Adjustment (0009) due to user wile overridding Payment Estimate Exception 7 o the current Payment Estimat	m sr on	\$10.00	\$200.00	
	0320 4 IN. WHITE STANDAR WATERBORNE PAVEME MARKING PAINT, TYPE BEAI		PAVEMENT	Material			-132,536	\$0.10	(\$13,253.60	
	0320	4 IN. WHITE S WATERBORNE I MARKING PAI	PAVEMENT	Material		This adjustment offsets the original syster generated Overrun Payment Estimate Ite Adjustment (0010) due to user wile overridding Payment Estimate Exception on the current Payment Estimat	m sr I1	\$0.10	\$13,253.60	
	0330	4 IN. YELLOW WATERBORNE I MARKING PAI	PAVEMENT	Material			-116,918	\$0.10	(\$11,691.80)	



Pay Estimate Created Date: June 15, 2020

Progr	ess Es		ontract ID ime Contra		920-H02 ruder Paving,	LLC Pay Period End June 15, 2020 Net (inal Contract Change Orde ent Contract	r Amount	\$2,441,948.14 \$10,310.98 \$2,452,259.12
Project Number	Line No.	Item Description	n A	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3446			BEADS						
	0330	4 IN. YELLOW STA WATERBORNE PAV MARKING PAINT,	EMENT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user wilesr overridding Payment Estimate Exception 14 on the current Payment Estimate.	116,918	\$0.10	\$11,691.80
	0400	CABLE, LOOP DETE	ECTOR, N DUCT	Material			-750	\$7.90	(\$5,925.00)
	0400	CABLE, LOOP DETE IN	ECTOR, N DUCT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment Estimate Exception 24 on the current Payment Estimate.	750	\$7.90	\$5,925.00
	0410	CURB BLO	СКОИТ	Material			-875	\$74.00	(\$64,750.00)
	0410	CURB BLO	CKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user wilesr overridding Payment Estimate Exception 20 on the current Payment Estimate.	875	\$74.00	\$64,750.00
Total									\$0.00



J9P3446

Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work						
J9P3413	FAF 19-1(13)	Resurface	19	SHANNON	from Route A to Riverview	Drive					
J9P3446	FAF 32-2(28)	Resurface	32	TEXAS	from Route 17 to Route 63	;					
Totals by 、	Job Numbe	ers									
J9P3413		ed Item Pay s Item Adjustn		s Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$1,184,074.35 (\$46,276.15) \$1,137,798.20	To Date \$1,184,074.35 (\$46,276.15) \$1,137,798.20				

\$0.00

\$0.00 \$0.00 \$0.00 \$0.00

\$0.00 \$0.00 \$0.00

\$0.00

Previous \$1,251,593.17 (\$42,912.05) \$1,208,681.12

\$0.00

\$0.00 \$0.00 \$0.00 \$0.00

\$0.00 \$0.00 \$0.00

\$0.00

To Date \$1,254,178.17 (\$42,912.05) **\$1,211,266.12**

Gross Item Pay

\$0.00

\$0.00 \$0.00 \$0.00 \$0.00

\$0.00 \$0.00 \$0.00

\$0.00

This Estimate \$2,585.00 \$0.00 **\$2,585.00**

Incentive Disincentive

Liquidated Damages Other Contract Adjustments

Posted Item Pay Gross Item Adjustments

Incentive Disincentive Liquidated Damages Other Contract Adjustments



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 3105002, Project Item Line Number 0030, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 3105002, Project Item Line Number 0180, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 4020520, Project Item Line Number 0190, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6200015, Project Item Line Number 0280, Material Set 6200015, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6200021, Project Item Line Number 0290, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6205301B, Project Item Line Number 0300, Material Set 6205301B96, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6205309, Project Item Line Number 0310, Material Set 620530996, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6206000C, Project Item Line Number 0320, Material Set 6206000C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6206000C, Project Item Line Number 0320, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6206000C, Project Item Line Number 0320, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6206001C, Project Item Line Number 0330, Material Set 6206001C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6206001C, Project Item Line Number 0330, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6206001C, Project Item Line Number 0330, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 7034600, Project Item Line Number 0410, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 7034600, Project Item Line Number 0410, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 7034600, Project Item Line Number 0410, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 7034600, Project Item Line Number 0410, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 9028500, Project Item Line Number 0400, Material Set 902850096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic	Material OK	WILESR	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status	
0902TSXX is insufficient.				

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q	uantities	and Valu	es are b	based on R	eport Generated date and can differ from the posted amo	ount at the	ime the E	stimate was	Genera	ted.	1	
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190920-H02	J9P3413	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,400.00	\$2,400.00
		0001	0020	2129900	MISC.MODIFIED SHAPING SLOPES, CLASS III	2.00	0.00	2.00	100F	2.00	\$1,600.00	\$3,200.00
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	90.00	0.00	90.00	TONS	90.00	\$85.48	\$7,693.20
		0001	0040	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	15,178.00	76.20	15,254.20	TONS	15,254.20	\$63.80	\$973,217.96
		0001	0050	4071005	TACK COAT	19,356.00	-2,951.00	16,405.00	GAL	16,405.00	\$1.94	\$31,825.70
		0001	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0070	6161005	CONSTRUCTION SIGNS	1,967.00	-533.00	1,434.00	SQFT	1,434.00	\$6.50	\$9,321.00
		0001	0080	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$80.00
		0001	0090	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	100.00	\$18.00	\$1,800.00
		0001	0100	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$78,300.00	\$78,300.00
		0001	0110	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	194,694.00	0.00	194,694.00	LF	155,755.00	\$0.10	\$15,575.50
		0001	0120	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	193,812.00	0.00	193,812.00	LF	155,050.00	\$0.10	\$15,505.00
		0001	0130	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	2,409.00	0.00	2,409.00	SQYD	2,409.00	\$6.20	\$14,935.80
		0001	0140	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,477.00	0.00	1,477.00	SQYD	1,477.00	\$6.47	\$9,556.19
		0010	0150	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	488.00	0.00	488.00	LF	488.00	\$28.00	\$13,664.00
		0010	0160	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
	Project J	9P3413 - To	tal Value	e Posted to D	ate as of Report Generated Date							\$1,184,074.35
	J9P3446	0001	0170	2129900	MISC.MODIFIED SHAPING SLOPES, CLASS III	4.00	0.00	4.00	100F	4.00	\$1,600.00	\$6,400.00
		0001	0180	3105002	GRAVEL (A) OR CRUSHED STONE (B)	55.00	0.00	55.00	TONS	55.00	\$103.29	\$5,680.95
		0001	0190	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	12,824.70	258.00	13,082.70	TONS	13,082.70	\$76.44	\$1,000,041.59
		0001	0200	4071005	TACK COAT	15,880.00	-2,314.00	13,566.00	GAL	13,566.00	\$1.94	\$26,318.04
		0001	0210	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0220	6161005	CONSTRUCTION SIGNS	1,958.00	-489.00	1,469.00	SQFT	1,469.00	\$6.50	\$9,548.50
		0001	0230	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	6.00	\$35.00	\$210.00
		0001	0240	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$20.00	\$120.00
		0001	0250	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	100.00	\$18.00	\$1,800.00
		0001	0260	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0270	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$9,000.00	\$9,000.00
		0001	0275	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$28,800.00	\$28,800.00
		0001	0280	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	30.00	17.00	47.00	LF	47.00	\$25.00	\$1,175.00
		0001	0290	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	3.00	0.00	3.00	EA	3.00	\$275.00	\$825.00
		0001	0300	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	2,066.00	1,200.00	3,266.00	LF	3,266.00	\$1.80	\$5,878.80
		0001	0310	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	20.00	0.00	20.00	LF	20.00	\$10.00	\$200.00
		0001	0320	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	165,671.00	0.00	165,671.00	LF	132,536.00	\$0.10	\$13,253.60
		0001	0330	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	146,148.00	0.00	146,148.00	LF	116,918.00	\$0.10	\$11,691.80
		0001	0340	6207001	PAVEMENT MARKING REMOVAL	1,500.00	0.00	1,500.00	LF	1,500.00	\$1.00	\$1,500.00
		0001	0350	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,335.00	0.00	1,335.00	SQYD	1,335.00	\$6.63	\$8,851.05
		0001	0360	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,924.00	0.00	1,924.00	SQYD	1,924.00	\$5.41	\$10,408.84
		0010	0370	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	350.00	0.00	350.00	LF	350.00	\$32.00	\$11,200.00
		0010	0380	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.00
		0010	0390	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.00
		0030	0400	9028500	CABLE, LOOP DETECTOR, IN DUCT	750.00	0.00	750.00	LF	750.00	\$7.90	\$5,925.00
		0070	0410	7034600	CURB BLOCKOUT	875.00	0.00	875.00	LF	875.00	\$74.00	\$64,750.00
	Project J	9P3446 - To	tal Value	e Posted to D	ate as of Report Generated Date							\$1,254,178.17



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
190920-H02 Ove	erall - Total	Value Post	ed to Dat	e as of Repo	rt Generated Date					Qty		\$2,438,252.52



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9P3446

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0280	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	6/15/20	6/15/20	17.00	LF	Stop bar at 63/32 jct.					
0300	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	6/15/20	6/15/20	1,200.00	LF	Added double yellow at each end of bridge prior to temp signal.					

The information below this line are details from Line Item agency views, No Agency View Details Exist



ie	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
30	GRAVEL (A) OR CRUSHED STONE (B)	Material		4	May 3, 2020	SYSTEM	(\$7,693.20)									
				4	May 3, 2020	SYSTEM	\$7,693.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user wilesr overridding Paymen Estimate Exception 1 on the current Payment Estimate.								
				5	May 15, 2020	SYSTEM	(\$7,693.20)									
				5	May 15, 2020	SYSTEM	\$7,693.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Paymen Estimate Exception 1 on the current Payment Estimate.								
				6	Jun 1, 2020	SYSTEM	(\$7,693.20)									
				6	Jun 1, 2020	SYSTEM	\$7,693.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Paymen Estimate Exception 1 on the current Payment Estimate.								
				7	Jun 15, 2020	SYSTEM	(\$7,693.20)									
				7	Jun 15, 2020	SYSTEM	\$7,693.20	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0001) due to user wilesr overridding Paymen Estimate Exception 1 on the current Payment Estimate.								
			- Total		1		\$0.00									
	Material - Total						\$0.00									
0 -	Total						\$0.00									
0	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	Material		2	Apr 2, 2020	SYSTEM	(\$162,581.54)									
	LEVELING)			2	Apr 2, 2020	SYSTEM	\$162,581.54	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0001) due to user wilesr overridding Payme Estimate Exception 1 on the current Payment Estimate.								
				3	Apr 15, 2020	SYSTEM	(\$973,217.96)									
				3	Apr 15, 2020	SYSTEM	\$973,217.96	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0002) due to user wilesr overridding Payme Estimate Exception 1 on the current Payment Estimate.								
			- Total				\$0.00									
	Material - Total						\$0.00									
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment		2	Apr 2, 2020	WILESR	(\$3,261.82)	AC Adjust for 2548.3 tons of surface level at 3.2% virgin oil. Mix SL20-								
				3	Apr 15, 2020	WILESR	(\$16,263.55)	12,705.9 tons of surface level 3.2% virgin AC								
			ACAD - Tot	al			(\$19,525.37)									
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		FUEL	4	May 3, 2020	WILESR	(\$2,284.30)	Fuel Adjustment for Asphalt laid on 3/31 and 4/1. Manual adjust, due the system not applying the adjust on est 002 $$								
	LEVELING)			4	May 3, 2020	WILESR	(\$24,466.48)	Fuel Adjustment for asphalt laid 4/2 thru 4/15. system did not apply fue adjustment on est 003 $$								
			FUEL - Total				(\$26,750.78)									
	Other Item Adjustment - Total						(\$46,276.15)									
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	Overrun	Overrun	3	Apr 15, 2020	SYSTEM	(\$4,861.56)									
	LEVELING)											3	Apr 15, 2020	SYSTEM	\$4,861.56	This adjustment offsets the original system-generated Overrun Paymel Estimate Item Adjustment (0001) overridding Payment Estimate Excep 9 on the current Payment Estimate.
					May 3,	SYSTEM	(\$4,861.56)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
				4	2020											
				4		SYSTEM	\$4,861.56									
					2020 May 3,	SYSTEM SYSTEM	\$4,861.56 (\$4,861.56)	Estimate Item Adjustment (0001) due to user wilesr overridding Payme								
				4	2020 May 3, 2020 May 15,			Estimate Item Adjustment (0001) due to user wilesr overridding Payme Estimate Exception 15 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment								
				4	2020 May 3, 2020 May 15, 2020 May 15,	SYSTEM	(\$4,861.56)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0005) due to user wilesr overridding Payme								



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0040		Overrun	Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0040 -	Total						(\$46,276.15)	
0050	TACK COAT	Material		2	Apr 2, 2020	SYSTEM	(\$5,794.78)	
				2	Apr 2, 2020	SYSTEM	\$5,794.78	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	Apr 15, 2020	SYSTEM	(\$31,825.70)	
				3	Apr 15, 2020	SYSTEM	\$31,825.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0050 -	Total						\$0.00	
0110	4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		4	May 3, 2020	SYSTEM	(\$15,575.50)	
	MARKING PAINT, TYPE P BEADS			4	May 3, 2020	SYSTEM	\$15,575.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$15,575.50)	
				5	May 15, 2020	SYSTEM	\$15,575.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$15,575.50)	
				6	Jun 1, 2020	SYSTEM	\$15,575.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.
				7	Jun 15, 2020	SYSTEM	(\$15,575.50)	
				7	Jun 15, 2020	SYSTEM	\$15,575.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0110 -	Total						\$0.00	
0120	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	Material		4	May 3, 2020	SYSTEM	(\$15,505.00)	
	MARKING PAINT, TYPE P BEADS			4	May 3, 2020	SYSTEM	\$15,505.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$15,505.00)	
				5	May 15, 2020	SYSTEM	\$15,505.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user wilesr overridding Payment Estimate Exception 9 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$15,505.00)	
				6	Jun 1, 2020	SYSTEM	\$15,505.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 17 on the current Payment Estimate.
				7	Jun 15, 2020	SYSTEM	(\$15,505.00)	
				7	Jun 15, 2020	SYSTEM	\$15,505.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0120 -	Total						\$0.00	
0180	GRAVEL (A) OR CRUSHED STONE (B)	Material		5	May 15, 2020	SYSTEM	(\$5,680.95)	



ne	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
80	GRAVEL (A) OR CRUSHED STONE (B)	Material	Туре	5	May 15, 2020	SYSTEM	\$5,680.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$5,680.95)	
				6	Jun 1, 2020	SYSTEM	\$5,680.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Jun 15, 2020	SYSTEM	(\$5,680.95)	
				7	Jun 15, 2020	SYSTEM	\$5,680.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
80 -	Total						\$0.00	
90	MIXTURE PG64-22 (SURFACE	Material		4	May 3, 2020	SYSTEM	(\$969,710.20)	
	LEVELING)			4	May 3, 2020	SYSTEM	\$969,710.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$1,000,041.59)	
				5	May 15, 2020	SYSTEM	\$1,000,041.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$1,000,041.59)	
				6	Jun 1, 2020	SYSTEM	\$1,000,041.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Jun 15, 2020	SYSTEM	(\$1,000,041.59)	
				7	Jun 15, 2020	SYSTEM	\$1,000,041.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	Other Item Adjustment		4	May 3, 2020	WILESR	(\$16,237.95)	12685.9 tons of Surface Level 3.2% virgin
	LEVELING)			5	May 15, 2020	WILESR	(\$1,047.55)	396.8 tons of surface level 3.2% virgin
			ACAD - Tot	al			(\$17,285.50)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		FUEL	4	May 3, 2020	WILESR	(\$24,427.97)	Fuel Adjustment for Asphalt laid 4/16 to 5/1
			FUEL - Tota	ıl			(\$24,427.97)	
	Other Item Adjustment - Total						(\$41,713.47)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	Overrun	Overrun	5	May 15, 2020	SYSTEM	(\$18,942.20)	Reference Item Price Adjustment Index Adjustment Type applied is FUE
	LEVELING)			5	May 15, 2020	SYSTEM	\$18,942.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 18 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$18,942.20)	Averaged Price Adjustment from this item on all previous payment estimates of '-3.02061' is applied (if non-zero).
				6	Jun 1, 2020	SYSTEM	\$18,942.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 26 on the current Payment Estimate.
			Overrun - Total				\$0.00	
	Overrun - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		5	May 15, 2020	SYSTEM	(\$1,198.58)	Reference Item Price Adjustment Index Adjustment Type applied is FUE
			- Total	1			(\$1,198.58)	
			Total					



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0190 -	Total		.)po				(\$42,912.05)	
0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	Material		6	Jun 1, 2020	SYSTEM	(\$750.00)	
	WHITE			6	Jun 1, 2020	SYSTEM	\$750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Jun 15, 2020	SYSTEM	(\$1,175.00)	
				7	Jun 15, 2020	SYSTEM	\$1,175.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0280 -	Total						\$0.00	
0290	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		6	Jun 1, 2020	SYSTEM	(\$825.00)	
				6	Jun 1, 2020	SYSTEM	\$825.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Jun 15, 2020	SYSTEM	(\$825.00)	
				7	Jun 15, 2020	SYSTEM	\$825.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0290 -	Total						\$0.00	
0300	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		2	Apr 2, 2020	SYSTEM	(\$1,859.40)	
				2	Apr 2, 2020	SYSTEM	\$1,859.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				3	Apr 15, 2020	SYSTEM	(\$1,859.40)	
				3	Apr 15, 2020	SYSTEM	\$1,859.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	May 3, 2020	SYSTEM	(\$1,859.40)	
				4	May 3, 2020	SYSTEM	\$1,859.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$3,718.80)	
				5	May 15, 2020	SYSTEM	\$3,718.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$3,718.80)	
				6	Jun 1, 2020	SYSTEM	\$3,718.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 6 on the current Payment Estimate.
				7	Jun 15, 2020	SYSTEM	(\$5,878.80)	
				7	Jun 15, 2020	SYSTEM	\$5,878.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user wilesr overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0300 -	Total						\$0.00	
0310	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		2	Apr 2, 2020	SYSTEM	(\$200.00)	
				2	Apr 2, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type		Date	Ву		
0310	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		3	Apr 15, 2020	SYSTEM	(\$200.00)	
				3	Apr 15, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.
				4	May 3, 2020	SYSTEM	(\$200.00)	
				4	May 3, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$200.00)	
				5	May 15, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$200.00)	
				6	Jun 1, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user wilesr overridding Payment Estimate Exception 7 on the current Payment Estimate.
				7	Jun 15, 2020	SYSTEM	(\$200.00)	
				7	Jun 15, 2020	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0310 -	Total						\$0.00	
0320	4 IN, WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		6	Jun 1, 2020	SYSTEM	(\$13,253.60)	
				6	Jun 1, 2020	SYSTEM	\$13,253.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment Estimate Exception 11 on the current Payment Estimate.
				7	Jun 15, 2020	SYSTEM	(\$13,253.60)	
				7	Jun 15, 2020	SYSTEM	\$13,253.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user wilesr overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0320 -	Total						\$0.00	
0330	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	Material		6	Jun 1, 2020	SYSTEM	(\$11,691.80)	
	MARKING PAINT, TYPE P BEADS			6	Jun 1, 2020	SYSTEM	\$11,691.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user wilesr overridding Payment Estimate Exception 14 on the current Payment Estimate.
				7	Jun 15, 2020	SYSTEM	(\$11,691.80)	
				7	Jun 15, 2020	SYSTEM	\$11,691.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user wilesr overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
)330 -	Total						\$0.00	
0400	CABLE, LOOP DETECTOR, IN DUCT	Material		5	May 15, 2020	SYSTEM	(\$5,925.00)	
				5	May 15, 2020	SYSTEM	\$5,925.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user wilesr overridding Payment Estimate Exception 16 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$5,925.00)	
				6	Jun 1, 2020	SYSTEM	\$5,925.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user wilesr overridding Payment Estimate Exception 24 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0400	CABLE, LOOP DETECTOR, IN DUCT	Material		7	Jun 15, 2020	SYSTEM	\$5,925.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment Estimate Exception 24 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0400 -	Total				_		\$0.00	
0410	CURB BLOCKOUT	Material		2	Apr 2, 2020	SYSTEM	(\$32,412.00)	
				2	Apr 2, 2020	SYSTEM	\$32,412.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
				3	Apr 15, 2020	SYSTEM	(\$64,750.00)	
				3	Apr 15, 2020	SYSTEM	\$64,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
				4	May 3, 2020	SYSTEM	(\$64,750.00)	
				4	May 3, 2020	SYSTEM	\$64,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user wilesr overridding Payment Estimate Exception 11 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$64,750.00)	
				5	May 15, 2020	SYSTEM	\$64,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment Estimate Exception 12 on the current Payment Estimate.
				6	Jun 1, 2020	SYSTEM	(\$64,750.00)	
				6	Jun 1, 2020	SYSTEM	\$64,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user wilesr overridding Payment Estimate Exception 20 on the current Payment Estimate.
				7	Jun 15, 2020	SYSTEM	(\$64,750.00)	
				7	Jun 15, 2020	SYSTEM	\$64,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user wilesr overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0410 -	Total						\$0.00	
Overa	ll - Total						(\$89,188.20)	