

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 30, 2020

Progress Estim	ate Number	Contract ID Prime Contractor	191115-B02 W. L. Miller Company		September 2, 2020 September 30, 2020	Original Contract Amount Net Change Order Amoun Current Contract Amount	\$790,384.99 t \$0.00 \$790,384.99
Approval Date							By User
September 30, 2020			Generated and Appro	oved (and should be	considered Draft) at t	he Project Office Level by	vierss
September 30, 2020		Re	viewed and Approved (	and should be cons	idered Draft) at the R	esident Engineer Level by	vierss
October 2, 2020			Revie	wed and Approved	at the Central Office (	Controllers Office Level by	greggd1
Original Comp	letion Date	Current Com	pletion Date	Actual Completion	Date % o	of Current Contract Amount	Complete
September	1, 2020	Septembe	r 1, 2020	August 20, 202	0	95.93%	

No Milestones Exist for Contract

Contract Total Pa	y For Estimate No. 10				
		This Estimate	Previous	To Date	
191115-B02					
	Total Posted Items Pay	\$4,000.00	\$754,186.42	\$758,186.42	
	Gross Item Adjustments	\$0.00	(\$29,387.08)	(\$29,387.08)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$724,799.34	\$728,799.34	
<b>Contract Total Pa</b>	yable This Estimate:	\$4,000.00			

## Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J2S3291	0190	2022010	REMOVAL OF IMPROVEMENTS	LS	\$4,000.000	1	\$4,000.00
Project J2S3291	- Total						\$4,000.00
Overall - Total							\$4,000.00

### **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract

Project	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
Number	No.	ion Boosipion	Туре	Adjustment Type	Commonic	Quantity	Adjustment Unit Price	amount
J2S3188	0010	EMULSIFIED ASPHALT, SEAL COAT	Material			-61,687	\$2.37	(\$146,198.19
	0010	EMULSIFIED ASPHALT, SEAL COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate.	61,687	\$2.37	\$146,198.19
	0080	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-131,738	\$0.11	(\$14,491.18)
	0080	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 4 on the current Payment Estimate.	131,738	\$0.11	\$14,491.18
	0090	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-89,739	\$0.11	(\$9,871.29
	0090	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 10 on the current Payment Estimate.	89,739	\$0.11	\$9,871.29
J2S3290	0100	EMULSIFIED ASPHALT,	Material			-28,233	\$2.37	(\$66,912.21

Revision 4/1/2020 Page 1 of 11



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 30, 2020

Progress Estimate Number	Contract ID	191115-B02		,	- 9	,
10	Prime Contractor	W. L. Miller Company	Pay Period End	September 30, 2020	Net Change Order Amount	
10					Current Contract Amount	\$790,384.99

								Ψ130,304.33
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2S3290		SEAL COAT						
	0100	EMULSIFIED ASPHALT, SEAL COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate.	28,233	\$2.37	\$66,912.21
	0170	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-52,530	\$0.11	(\$5,778.30)
	0170	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate.	52,530	\$0.11	\$5,778.30
	0180	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-69,138	\$0.11	(\$7,605.18)
	0180	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 12 on the current Payment Estimate.	69,138	\$0.11	\$7,605.18
J2S3291	0210	EMULSIFIED ASPHALT, SEAL COAT	Material			-49,028	\$2.37	(\$116,196.36)
	0210	EMULSIFIED ASPHALT, SEAL COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.	49,028	\$2.37	\$116,196.36
	0280	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-98,934	\$0.11	(\$10,882.74)
	0280	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 6 on the current Payment Estimate.	98,934	\$0.11	\$10,882.74
	0290	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-84,387	\$0.11	(\$9,282.57)
	0290	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate.	84,387	\$0.11	\$9,282.57
Total								\$0.00

Revision 4/1/2020 Page 2 of 11



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J2S3188	FAF-16-1(19)	Seal coat	16	LEWIS	from Route 6 to Route	B in Canton	
J2S3290	FAS- S201(083)	Seal coat	К	LEWIS	from Route E to Route	6 in LaBelle	
J2S3291	FAS S201(59)	Seal coat	С	LEWIS	from Route 6 in Ewing	to Route B in LaGrange	
Totals by .	Job Numbers						
J2S3188	Posted Ite	m Adjustments	s Gross Itel	m Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$310,307.30 (\$13,046.62) \$297,260.68	To Date \$310,307.30 (\$13,046.62) \$297,260.68
		ive d Damages ntract Adjustm	ents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J2S3290	Posted Ite Gross Ite	m Adjustments	s G <mark>ross Ite</mark> l	m Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$148,017.45 (\$5,971.19) \$142,046.26	To Date \$148,017.45 (\$5,971.19) <b>\$142,046.26</b>
		ive d Damages ntract Adjustm	ents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J2S3291	Posted Ite Gross Ite	m Adjustments	s Gross Iter	m Pay	This Estimate \$4,000.00 \$0.00 \$4,000.00	Previous \$295,861.67 (\$10,369.27) \$285,492.40	To Date \$299,861.67 (\$10,369.27) <b>\$289,492.40</b>
		ive d Damages ntract Adjustm	ients		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 11



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

**Exceptions (Discrepancies) This Estimate Period** 

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 4091048, Project Item Line Number 0100, Material Set 409104896, Material 1015EACRS2P - Emulsified Asphalt CRS-2P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 4091048, Project Item Line Number 0210, Material Set 409104896, Material 1015EACRS2P - Emulsified Asphalt CRS-2P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 4091048, Project Item Line Number 0010, Material Set 409104896, Material 1015EACRS2P - Emulsified Asphalt CRS-2P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 6206000C, Project Item Line Number 0080, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 6206000C, Project Item Line Number 0080, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 6206000C, Project Item Line Number 0280, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 6206000C, Project Item Line Number 0280, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 6206000C, Project Item Line Number 0170, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 6206000C, Project Item Line Number 0170, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 6206001C, Project Item Line Number 0090, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 6206001C, Project Item Line Number 0090, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 6206001C, Project Item Line Number 0180, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 6206001C, Project Item Line Number 0180, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 6206001C, Project Item Line Number 0290, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 6206001C, Project Item Line Number 0290, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	buckj	Overridden

Revision 4/1/2020 Page 4 of 11

\$758,186.42



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) and Values are sed on Report Generated date and can differ from the posted amount at the time the Estimate was Generated. Unit Unit Price Category Net Total Total Total Value POSTED Description Contract Nm.CONTRACT Line Bid Quantity Posted No. No Code Change Order Current To Date (See report generated date) Approved Qty Quantity 191115-B02 J2S3188 0001 0010 4091048 EMULSIFIED ASPHALT, SEAL COAT 61,819.00 0.00 61.819.00 GAL 61,687.00 \$2.37 \$146.198.19 0001 0020 4094012 SEAL COAT AGGREGATE, GRADE B2 220,782.00 0.00 220.782.00 SOYD 220.782.00 \$0.52 \$114.806.64 0001 0030 6123000A TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) 2 00 0.00 2 00 FΑ 2 00 \$1,000,00 \$2,000,00 0040 6161005 CONSTRUCTION SIGNS 2.047.00 0.00 2.047.00 SOFT 1.025.00 \$6.00 \$6.150.00 0050 6161009 FLAG ASSEMBLY 11.00 0.00 EΑ 8.00 \$20.00 \$160.00 0001 11.00 6161025 CHANNELIZER (TRIM LINE) 100.00 0.00 100.00 EΑ 12.00 \$15.00 \$180.00 0001 0060 \$16,450.00 0070 6181000 MOBILIZATION 1.00 0.00 1.00 LS 1.00 \$16,450.00 0001 0.00 0800 6206000C 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 164,672.00 164,672.00 LF 131,738.00 \$0.11 \$14,491.18 0001 0090 6206001C YELLOW STANDARD WATERBORNE PAVEMENT 112,174.00 0.00 112,174.00 89,739.00 \$0.11 \$9,871.29 0001 MARKING PAINT, TYPE P BEADS Project J2S3188 - T \$310.307.30 sted to Date as of Report Generated Dat EMULSIFIED ASPHALT, SEAL COAT 28,417.00 0.00 28,417.00 GAL 28,233.00 \$66,912.21 0100 0001 101,488.00 0115 4094012 SEAL COAT AGGREGATE, GRADE B2 101,488.00 0.00 101,488.00 SQYD \$0.52 \$52,773.76 0001 TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) ΕA \$1,000.00 \$2,000.00 0120 6123000A 0.00 0001 2.00 2.00 2.00 CONSTRUCTION SIGNS SQFT \$4,176.00 0130 6161005 876.63 0.00 876.63 696.00 \$6.00 0001 0140 6161009 FLAG ASSEMBLY EΑ \$20.00 \$80.00 0001 4.00 0.00 4.00 4.00 CHANNELIZER (TRIM LINE) 0001 0150 6161025 100.00 0.00 100.00 EΑ 12.00 \$15.00 \$180.00 0001 0160 6181000 MOBILIZATION 1.00 0.00 1.00 LS 1.00 \$8,512.00 \$8,512.00 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 0001 0170 6206000C 65.662.00 0.00 65.662.00 LF 52.530.00 \$0.11 \$5,778.30 0001 0180 6206001C 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT 86 423 00 0.00 86 423 00 ΙF 69 138 00 \$0.11 \$7,605,18 MARKING PAINT, TYPE P BEADS .1253291 0001 0190 2022010 REMOVAL OF IMPROVEMENTS 1.00 0.00 1.00 LS 1.00 \$4,000,00 \$4,000,00 0001 0200 2153000 SHAPING SLOPES, CLASS III. 11.00 0.00 11.00 100F 11.00 \$1,400.00 \$15,400.00 EMULSIFIED ASPHALT, SEAL COAT 49.028.00 0001 0210 4091048 49,028.00 0.00 GAL 49.028.00 \$2.37 \$116,196.36 0001 0220 4094012 SEAL COAT AGGREGATE, GRADE B2 175,100.00 0.00 175,100.00 SOYD 175,100.00 \$0.52 \$91,052.00 0230 6123000A TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) 2 00 0.00 2 00 FΑ 2 00 \$1,000.00 \$2,000.00 0240 6161005 CONSTRUCTION SIGNS 1,924.00 0.00 1,924.00 SQFT 968.00 \$6.00 \$5.808.00 0001 6161009 FLAG ASSEMBLY \$160.00 0.00 EΑ 8.00 \$20.00 0001 0260 6161025 CHANNELIZER (TRIM LINE) 100.00 0.00 100.00 EΑ 12.00 \$15.00 \$180.00 0001 0270 6181000 MOBILIZATION 1.00 0.00 1.00 LS 1.00 \$10,100.00 \$10,100.00 0001 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 0280 6206000C 123,668.00 0.00 123,668.00 LF 98,934.00 \$0.11 \$10,882.74 0001 0001 0290 6206001C 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT 105,484.00 0.00 105,484.00 LF 84,387.00 \$0.11 \$9,282.57 MARKING PAINT, TYPE P BEADS 6061060 MGS GUARDRAIL 0.00 LF 300.00 \$24.00 \$7,200.00 0010 0300 300.00 300.00 MGS HEIGHT AND BLOCK TRANSITION 6061074 \$2.800.00 0010 0310 4.00 0.00 4.00 EΑ 4.00 \$700.00 0010 0320 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 8.00 0.00 8.00 EΑ 8.00 \$3,100,00 \$24.800.00

Page 5 of 11 Revision 4/1/2020

Posted to Date as of Report Generated Date

191115-B02 Overall - Total Value Posted to Date as of Report Generated Date



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J2S3291

Line Number	Item Code	Description		DWR Approval Date		Units	Location	From Station/ Log Mile	Offset/ Distance		Offset/ Distance	Comments
0190	2022010	REMOVAL OF IMPROVEMENTS	9/29/20	9/30/20	1.00	LS	Guardrail Location	6.870		7.170		

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 6 of 11



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Line	Description	Туре	Adjustment Type		Date	Ву	ranount	Normalia
0010	EMULSIFIED ASPHALT, SEAL COAT	Material		7	Aug 3, 2020	SYSTEM	(\$146,198.19)	
				7	Aug 3, 2020	SYSTEM	\$146,198.19	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 15 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$146,198.19)	
				8	Aug 16, 2020	SYSTEM	\$146,198.19	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 15 on the current Payment Estimate.
				9	Sep 2, 2020	SYSTEM	(\$146,198.19)	
				9	Sep 2, 2020	SYSTEM	\$146,198.19	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user vierss overridding Payment Estimate Exception 16 on the current Payment Estimate.
				10	Sep 30, 2020	SYSTEM	(\$146,198.19)	
				10	Sep 30, 2020	SYSTEM	\$146,198.19	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	7	Aug 3, 2020	vierss	(\$13,046.62)	
			ACAD - Tot	al			(\$13,046.62)	
	Other Item Adjustment - Total						(\$13,046.62)	
0010 -	Total						(\$13,046.62)	
0020	SEAL COAT AGGREGATE, GRADE B2	Construction Stockpile		2	May 19, 2020	SYSTEM	\$35,132.08	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Aug 3, 2020	SYSTEM	(\$35,132.08)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total		- Total				\$0.00 \$0.00	
	Construction Stockpile - Total SEAL COAT AGGREGATE, GRADE B2	Material	- Total	7	Aug 3, 2020	SYSTEM		
	SEAL COAT AGGREGATE,	Material	- Total	7		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.
	SEAL COAT AGGREGATE,	Material	- Total		2020 Aug 3,	SYSTEM	<b>\$0.00</b> (\$114,806.64)	Estimate Item Adjustment (0002) due to user buckj overridding Payment
	SEAL COAT AGGREGATE,	Material	- Total	7	2020 Aug 3, 2020 Aug 16,	SYSTEM	\$0.00 (\$114,806.64) \$114,806.64	Estimate Item Adjustment (0002) due to user buckj overridding Payment
	SEAL COAT AGGREGATE,	Material	- Total	7	2020 Aug 3, 2020 Aug 16, 2020 Aug 16,	SYSTEM SYSTEM	\$0.00 (\$114,806.64) \$114,806.64 (\$114,806.64)	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment
	SEAL COAT AGGREGATE,	Material	- Total	7 8 8	2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2,	SYSTEM SYSTEM	\$0.00 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment
	SEAL COAT AGGREGATE,	Material	- Total	7 8 8	2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vierss overridding Payment
	SEAL COAT AGGREGATE,	Material		7 8 8	2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64 (\$114,806.64)	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vierss overridding Payment
0020 -	SEAL COAT AGGREGATE, GRADE B2	Material		7 8 8	2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vierss overridding Payment
<b>0020 -</b> 0080	Material - Total  Total  4 IN, WHITE STANDARD WATERBORNE PAVEMENT			7 8 8 9 9	2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vierss overridding Payment
	Material - Total  4 IN. WHITE STANDARD			7 8 8 9 9	2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vierss overridding Payment
	Material - Total  Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			7 8 8 9 9	2020 Aug 3, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Aug 3, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64 \$0.00 \$0.00 (\$14,491.18)	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vierss overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment
	Material - Total  Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			7 8 8 9 9 7 7	2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Aug 3, 2020 Aug 3, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64 \$0.00 \$0.00 \$0.00 (\$14,491.18)	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vierss overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment
	Material - Total  Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			7 8 8 9 9	2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Aug 3, 2020 Aug 3, 2020 Aug 16, 2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$114,806.64) \$114,806.64) (\$114,806.64) \$114,806.64 (\$114,806.64) \$114,806.64 \$0.00 \$0.00 (\$14,491.18) \$14,491.18	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vierss overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 29 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment

Revision 4/1/2020 Page 7 of 11



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0080	4 IN. WHITE STANDARD	Material						Estimate Exception 26 on the current Payment Estimate.
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS			10	Sep 30, 2020	SYSTEM	(\$14,491.18)	
				10	Sep 30, 2020	SYSTEM	\$14,491.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0080 -	- Total						\$0.00	
0090	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	Material		7	Aug 3, 2020	SYSTEM	(\$9,871.29)	
	MARKING PAINT, TYPE P BEADS			7	Aug 3, 2020	SYSTEM	\$9,871.29	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 33 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$9,871.29)	
				8	Aug 16, 2020	SYSTEM	\$9,871.29	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate.
				9	Sep 2, 2020	SYSTEM	(\$9,871.29)	
				9	Sep 2, 2020	SYSTEM	\$9,871.29	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user vierss overridding Payment Estimate Exception 32 on the current Payment Estimate.
				10	Sep 30, 2020	SYSTEM	(\$9,871.29)	
				10	Sep 30, 2020	SYSTEM	\$9,871.29	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						00.00	
	Materiai - Totai						\$0.00	
0090 -	· Total						\$0.00	
0090 -		Material		7	Aug 3, 2020	SYSTEM		
	- Total EMULSIFIED ASPHALT, SEAL	Material		7		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.
	- Total EMULSIFIED ASPHALT, SEAL	Material			2020 Aug 3,		<b>\$0.00</b> (\$66,912.21)	Estimate Item Adjustment (0006) due to user buckj overridding Payment
	- Total EMULSIFIED ASPHALT, SEAL	Material		7	2020 Aug 3, 2020 Aug 16,	SYSTEM	\$0.00 (\$66,912.21) \$66,912.21	Estimate Item Adjustment (0006) due to user buckj overridding Payment
	- Total EMULSIFIED ASPHALT, SEAL	Material		7	2020 Aug 3, 2020 Aug 16, 2020 Aug 16,	SYSTEM SYSTEM	\$0.00 (\$66,912.21) \$66,912.21 (\$66,912.21)	Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment
	- Total EMULSIFIED ASPHALT, SEAL	Material		7 8 8	2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2,	SYSTEM SYSTEM	\$0.00 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21	Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment
	- Total EMULSIFIED ASPHALT, SEAL	Material		7 8 8 9	2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21)	Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user vierss overridding Payment
	- Total EMULSIFIED ASPHALT, SEAL	Material		7 8 8 9 9	2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Sep 30,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21	Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user vierss overridding Payment
	- Total EMULSIFIED ASPHALT, SEAL	Material	- Total	7 8 8 9 9	2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 30, 2020 Sep 30, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21	Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment
	- Total EMULSIFIED ASPHALT, SEAL	Material	- Total	7 8 8 9 9	2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 30, 2020 Sep 30, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21)	Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment
	Total  EMULSIFIED ASPHALT, SEAL COAT	Material  Other Item Adjustment	- Total	7 8 8 9 9 10	2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 30, 2020 Sep 30, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21	Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment
	Material - Total  EMULSIFIED ASPHALT, SEAL COAT	Other Item		7 8 8 9 9 10 10	2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Sep 30, 2020 Sep 30, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21	Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment
	Material - Total  EMULSIFIED ASPHALT, SEAL COAT	Other Item	ACAD	7 8 8 9 9 10 10	2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Sep 30, 2020 Sep 30, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 \$0.00 \$0.00 (\$5,971.19)	Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment
0100	Material - Total EMULSIFIED ASPHALT, SEAL COAT	Other Item	ACAD	7 8 8 9 9 10 10	2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Sep 30, 2020 Sep 30, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 \$0.00 \$0.00 (\$5,971.19)	Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment
0100	Material - Total EMULSIFIED ASPHALT, SEAL COAT  Material - Total EMULSIFIED ASPHALT, SEAL COAT	Other Item	ACAD	7 8 8 9 9 10 10	2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Sep 30, 2020 Sep 30, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 \$66,912.21 \$0.00 \$0.00 (\$5,971.19) (\$5,971.19)	Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment
0100	Material - Total EMULSIFIED ASPHALT, SEAL COAT  Material - Total EMULSIFIED ASPHALT, SEAL COAT  Other Item Adjustment - Total Total SEAL COAT AGGREGATE,	Other Item Adjustment	ACAD	7 8 8 9 9 10 10 17 7 al	2020 Aug 16, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 30, 2020 Sep 30, 2020  Aug 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 (\$66,912.21) \$66,912.21 \$66,912.21 \$0.00 \$0.00 (\$5,971.19) (\$5,971.19) (\$5,971.19)	Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate.

Revision 4/1/2020 Page 8 of 11



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks					
20	Boostipilo	Туре	Adjustment Type		Date	Ву	7 1110 1111	· condition					
0115	Construction Stockpile - Total						\$0.00						
	SEAL COAT AGGREGATE, GRADE B2	Material		7	Aug 3, 2020	SYSTEM	(\$52,773.76)						
				7	Aug 3, 2020	SYSTEM	\$52,773.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.					
				8	Aug 16, 2020	SYSTEM	(\$52,773.76)						
				8	Aug 16, 2020	SYSTEM	\$52,773.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.					
				9	Sep 2, 2020	SYSTEM	(\$52,773.76)						
				9	Sep 2, 2020	SYSTEM	\$52,773.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user vierss overridding Payment Estimate Exception 24 on the current Payment Estimate.					
			- Total				\$0.00						
	Material - Total						\$0.00						
0115	- Total						\$0.00						
0170	4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		7	Aug 3, 2020	SYSTEM	(\$5,778.30)						
	MARKING PAINT, TYPE P BEADS			7	Aug 3, 2020	SYSTEM	\$5,778.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 25 on the current Payment Estimate.					
				8	Aug 16, 2020	SYSTEM	(\$5,778.30)						
				8	Aug 16, 2020	SYSTEM	\$5,778.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 29 on the current Payment Estimate.					
						9	Sep 2, 2020	SYSTEM	(\$5,778.30)				
												9	Sep 2, 2020
				10	Sep 30, 2020	SYSTEM	(\$5,778.30)						
				10	Sep 30, 2020	SYSTEM	\$5,778.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate.					
			- Total				\$0.00						
	Material - Total						\$0.00						
0170	- Total						\$0.00						
0180	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	Material		7	Aug 3, 2020	SYSTEM	(\$7,605.18)						
	MARKING PAINT, TYPE P BEADS			7	Aug 3, 2020	SYSTEM	\$7,605.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 31 on the current Payment Estimate.					
				8	Aug 16, 2020	SYSTEM	(\$7,605.18)						
				8	Aug 16, 2020	SYSTEM	\$7,605.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 31 on the current Payment Estimate.					
				9	Sep 2, 2020	SYSTEM	(\$7,605.18)						
				9	Sep 2, 2020	SYSTEM	\$7,605.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user vierss overridding Payment Estimate Exception 34 on the current Payment Estimate.					
				10	Sep 30, 2020	SYSTEM	(\$7,605.18)						
				10	Sep 30, 2020	SYSTEM	\$7,605.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 12 on the current Payment Estimate.					
			- Total				\$0.00						
	Material - Total						\$0.00						
0180	- Total						\$0.00						

Revision 4/1/2020 Page 9 of 11



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0210	EMULSIFIED ASPHALT, SEAL COAT	Material		7	Aug 3, 2020	SYSTEM	(\$116,196.36)	
				7	Aug 3, 2020	SYSTEM	\$116,196.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$116,196.36)	
				8	Aug 16, 2020	SYSTEM	\$116,196.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Sep 2, 2020	SYSTEM	(\$116,196.36)	
				9	Sep 2, 2020	SYSTEM	\$116,196.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user vierss overridding Payment Estimate Exception 9 on the current Payment Estimate.
				10	Sep 30, 2020	SYSTEM	(\$116,196.36)	
				10	Sep 30, 2020	SYSTEM	\$116,196.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	7	Aug 3, 2020	vierss	(\$10,369.27)	
			ACAD - Tot	al			(\$10,369.27)	
	Other Item Adjustment - Total						(\$10,369.27)	
0210 -	Total						(\$10,369.27)	
0220	SEAL COAT AGGREGATE, GRADE B2	Construction Stockpile		2	May 19, 2020	SYSTEM	\$27,866.66	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Aug 3, 2020	SYSTEM	(\$27,866.66)	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total						00.00	
			- Total				\$0.00	
	Construction Stockpile - Total		- Total				\$0.00	
	Construction Stockpile - Total  SEAL COAT AGGREGATE, GRADE B2	Material	- Total	7	Aug 3, 2020	SYSTEM		
	SEAL COAT AGGREGATE,	Material	- Total	7		SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.
	SEAL COAT AGGREGATE,	Material	- Total		2020 Aug 3,		<b>\$0.00</b> (\$91,052.00)	Estimate Item Adjustment (0013) due to user buckj overridding Payment
	SEAL COAT AGGREGATE,	Material	- Total	7	2020 Aug 3, 2020 Aug 16,	SYSTEM	\$0.00 (\$91,052.00) \$91,052.00	Estimate Item Adjustment (0013) due to user buckj overridding Payment
	SEAL COAT AGGREGATE,	Material	- Total	7	Aug 3, 2020 Aug 16, 2020 Aug 16,	SYSTEM SYSTEM	\$0.00 (\$91,052.00) \$91,052.00 (\$91,052.00)	Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment
	SEAL COAT AGGREGATE,	Material	- Total	7 8 8	Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2,	SYSTEM SYSTEM	\$0.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00	Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment
	SEAL COAT AGGREGATE,	Material	- Total	7 8 8	Aug 16, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00	Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user vierss overridding Payment
	SEAL COAT AGGREGATE,	Material		7 8 8	Aug 16, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00	Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user vierss overridding Payment
0220 -	SEAL COAT AGGREGATE, GRADE B2	Material		7 8 8	Aug 16, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00	Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user vierss overridding Payment
<b>0220</b> - <b>0280</b>	Material - Total  Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		7 8 8	Aug 16, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00	Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user vierss overridding Payment
	SEAL COAT AGGREGATE, GRADE B2  Material - Total  Total  4 IN. WHITE STANDARD			7 8 8 9 9	2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00 \$0.00 \$0.00	Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user vierss overridding Payment
	Material - Total  Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			7 8 8 9 9	2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Aug 3, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00 \$0.00 \$0.00 (\$10,882.74)	Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user vierss overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment
	Material - Total  Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			7 8 8 9 9	2020 Aug 3, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Aug 3, 2020 Aug 3, 2020 Aug 3, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00 \$0.00 \$0.00 (\$10,882.74)	Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user vierss overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment
	Material - Total  Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			7 8 8 9 9	2020 Aug 3, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Aug 3, 2020 Aug 3, 2020 Aug 16, 2020 Aug 3, 2020 Aug 16, 2020 Aug 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$91,052.00 (\$91,052.00) \$0.00 \$0.00 (\$10,882.74) (\$10,882.74)	Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user vierss overridding Payment Estimate Exception 23 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment

Revision 4/1/2020 Page 10 of 11



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0280	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material						Estimate Exception 28 on the current Payment Estimate.
				10	Sep 30, 2020	SYSTEM	(\$10,882.74)	
				10	Sep 30, 2020	SYSTEM	\$10,882.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total			\$0.00		
	Material - Total						\$0.00	
0280 -	- Total						\$0.00	
0290	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		7	Aug 3, 2020	SYSTEM	(\$9,282.57)	
				7	Aug 3, 2020	SYSTEM	\$9,282.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$9,282.57)	
				8	Aug 16, 2020	SYSTEM	\$9,282.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 33 on the current Payment Estimate.
				9	Sep 2, 2020	SYSTEM	(\$9,282.57)	
				9	Sep 2, 2020	SYSTEM	\$9,282.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user vierss overridding Payment Estimate Exception 36 on the current Payment Estimate.
				10	Sep 30, 2020	SYSTEM	(\$9,282.57)	
				10	Sep 30, 2020	SYSTEM	\$9,282.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0290 -	- Total						\$0.00	
0300	MGS GUARDRAIL	Construction Stockpile		1	Apr 13, 2020	SYSTEM	\$3,201.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				9	Sep 1, 2020	SYSTEM	(\$3,201.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total						\$0.00	
	Construction Stockpile - Total						\$0.00	
0300 -	- Total						\$0.00	
0310		Construction Stockpile		1	Apr 13, 2020	SYSTEM	\$1,104.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				9	Sep 1, 2020	SYSTEM	(\$1,104.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total						\$0.00	
	Construction Stockpile - Total						\$0.00	
0310 -	- Total						\$0.00	
0320	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	Apr 13, 2020	SYSTEM	\$12,080.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				9	Sep 1, 2020	SYSTEM	(\$12,080.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		- Total	- Total			\$0.00		
	Construction Stockpile - Total						\$0.00	
0320 -	- Total						\$0.00	
Overa	all - Total						(\$29,387.08)	

Revision 4/1/2020 Page 11 of 11