

#### Pay Estimate Created Date: September 1, 2020

Progress Estim 9	ate Number	Contract ID Prime Contractor	191115-B02 W. L. Miller Compan	Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$790,384.99 \$0.00 \$790,384.99
Approval Date							By User
September 2, 2020			Generated and App	roved (and should be	considered Draft) at	the Project Office Level by	vierss
September 2, 2020		Re	viewed and Approved	d (and should be cons	idered Draft) at the F	Resident Engineer Level by	vierss
September 3, 2020			Rev	iewed and Approved	at the Central Office	Controllers Office Level by	greggd1
Original Comp	letion Date	Current Com	pletion Date	Actual Completion	Date %	of Current Contract Amount	Complete
September	1, 2020	September	r 1, 2020			95.42%	

No Milestones Exist for Contract

			This Fating A.	D		T. D. t.	
91115-B02			This Estimate	Previous		To Date	
Contract Total I	Gross Incenti Disince Liquida Other (	entive Ited Damage Contract Adju	nents (\$16,385.00) \$0.00 \$0.00 \$0.00 \$0.00	\$703,986 (\$13,002 \$0.00 \$0.00 \$0.00 \$0.00 \$690,984	.08)	\$754,186.4 (\$29,387.0 \$0.00 \$0.00 \$0.00 \$0.00 \$724,799.3	8)
ems Paid This	Estimate Perio	<u>od</u>					
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J2S3291	0200	2153000	SHAPING SLOPES, CLASS III	100F	\$1,400.000	11	\$15,400.00
	0300	6061060	MGS GUARDRAIL	LF	\$24.000	300	\$7,200.00
	0310	6061074	MGS HEIGHT AND BLOCK TRANSITION	EA	\$700.000	4	\$2,800.00
	0320	6063014	TYPE A CRASHWORTHY END TERMINAL	EA	\$3,100.000	8	\$24,800.00
	0320		(MASH)				
Project J2S32			(MASH)				\$50,200.00

## No Contract Adjustments Exist on Contract

Line Item /	Adjustr	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2S3188	0010	EMULSIFIED ASPHALT, SEAL COAT	Material			-61,687	\$2.37	(\$146,198.19)
	0010	EMULSIFIED ASPHALT, SEAL COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0016) due to user vierss overridding Payment Estimate Exception 16 on the current Payment Estimate.	61,687	\$2.37	\$146,198.19
	0020	SEAL COAT AGGREGATE, GRADE B2	Material			-220,782	\$0.52	(\$114,806.64)
	0020	SEAL COAT AGGREGATE, GRADE B2	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0017) due to user vierss overridding Payment Estimate Exception 25 on the current Payment Estimate.	220,782	\$0.52	\$114,806.64
	0080	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-131,738	\$0.11	(\$14,491.18)
	0080	4 IN. WHITE STANDARD	Material		This adjustment offsets the original system-	131,738	\$0.11	\$14,491.18



### Pay Estimate Created Date: September 1, 2020

Progr		timate Number 9	Contract ID Prime Cont			Pay Period Start A y Pay Period End S		Original Contrac Net Change Orde Current Contrac	er Amount	\$790,384.99 \$0.00 \$790,384.99
Project Number	Line No.					Comn	nents	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2S3188		WATERBORNE MARKING PAI				overridding Payment	018) due to user vie	erss 126		
	0090	4 IN. YELLOW WATERBORNE MARKING PAI	PAVEMENT	Material				-89,739	\$0.11	(\$9,871.29
	0090	4 IN. YELLOW WATERBORNE MARKING PAI	PAVEMENT	Material		overridding Payment	Payment Estimate I 019) due to user vie	tem erss i 32	\$0.11	\$9,871.29
J2S3290	0100	EMULSIFIE	D ASPHALT, SEAL COAT	Material				-28,233	\$2.37	(\$66,912.21
	0100	EMULSIFIED	D ASPHALT, SEAL COAT	Material		overridding Payment E	Payment Estimate I 020) due to user vie	tem erss ? on	\$2.37	\$66,912.21
	0115	SEAL COAT AC	GREGATE, GRADE B2	Material				-101,488	\$0.52	(\$52,773.76
	0115	SEAL COAT AC	GREGATE, GRADE B2	Material		overridding Payment	Payment Estimate I 021) due to user vie	tem erss i 24	\$0.52	\$52,773.76
	0170	4 IN. WHITE WATERBORNE MARKING PAI	PAVEMENT	Material				-52,530	\$0.11	(\$5,778.30
	0170	4 IN. WHITE WATERBORNE MARKING PAI	PAVEMENT	Material		overridding Payment	Payment Estimate I 022) due to user vie	tem erss i 30	\$0.11	\$5,778.30
	0180	4 IN. YELLOW WATERBORNE MARKING PAI	PAVEMENT	Material				-69,138	\$0.11	(\$7,605.18
	0180	4 IN. YELLOW WATERBORNE MARKING PAI	PAVEMENT	Material		overridding Payment	Payment Estimate I 023) due to user vie	tem erss i 34	\$0.11	\$7,605.18
J2S3291	0210	EMULSIFIE	O ASPHALT, SEAL COAT	Material				-49,028	\$2.37	(\$116,196.36
	0210	EMULSIFIE	D ASPHALT, SEAL COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0024) due to user vierss overridding Payment Estimate Exception 9 on the current Payment Estimate.		tem erss ) on	\$2.37	\$116,196.36
	0220	SEAL COAT AC	GREGATE, GRADE B2	Material				-175,100	\$0.52	(\$91,052.00
	0220	SEAL COAT AC	GGREGATE, GRADE B2	Material		overridding Payment	Payment Estimate I 025) due to user vie	tem erss i 23	\$0.52	\$91,052.00
	0280	4 IN. WHITE WATERBORNE		Material				-98,934	\$0.11	(\$10,882.74



### Pay Estimate Created Date: September 1, 2020

Progress Estimate Number 9			Contract ID Prime Cont		5-B02 Miller Company	Pay Period Start Aug Pay Period End Sep		Original Contrac Net Change Ord Current Contrac	\$790,384.99 \$0.00 \$790,384.99	
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comme	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J2S3291		MARKING PA	INT, TYPE P BEADS							
	0280	4 IN. WHITE WATERBORNE MARKING PA	PAVEMENT	Material		overridding Payment E	ayment Estimate I 26) due to user vie	tem erss 1 28	\$0.11	\$10,882.74
	0290	4 IN. YELLOW WATERBORNE MARKING PA	PAVEMENT	Material				-84,387	\$0.11	(\$9,282.57)
	0290	4 IN. YELLOW WATERBORNE MARKING PA	PAVEMENT	Material		overridding Payment E	ayment Estimate I 27) due to user vie	tem erss 1 36	\$0.11	\$9,282.57
	0300	MGS	GUARDRAIL	Construction Stockpile		Payment Estimate Item A	Adjustment genera Stockpile Transac			(\$3,201.00)
	0310	MGS HEIGHT	AND BLOCK	Construction Stockpile		Payment Estimate Item A	Adjustment genera Stockpile Transac			(\$1,104.00)
	0320	TYPE A CRA END TERMI	SHWORTHY NAL (MASH)	Construction Stockpile		Payment Estimate Item A	Adjustment genera Stockpile Transac			(\$12,080.00)
Total										(\$16,385.00)



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information												
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work								
J2S3188	FAF-16-1(19)	Seal coat	16	LEWIS	om Route 6 to Route B in Canton								
J2S3290	FAS- S201(083)	Seal coat	K	LEWIS	from Route E to Route 6 in LaBelle								
J2S3291	FAS S201(59)	Seal coat	С	LEWIS	from Route 6 in Ewing to Route B in LaGrange								

## Totals by Job Numbers

J2S3188		This Estimate	Previous	To Date
	Posted Item Pay	\$0.00	\$310.307.30	\$310,307.30
	Gross Item Adjustments	\$0.00	(\$13,046.62)	(\$13,046.62)
	Gross Item Pay	\$0.00	\$297,260.68	\$297,260.68
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
1000000				
J2S3290		This Estimate	Previous	To Date
	Posted Item Pay	\$0.00	\$148,017.45	\$148,017.45
	Gross Item Adjustments	\$0.00	(\$5,971.19)	(\$5,971.19)
	Gross Item Pay	\$0.00	\$142,046.26	\$142,046.26
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
J2S3291		This Estimate	Previous	To Date
	Posted Item Pay	\$50,200.00	\$245,661.67	\$295,861.67
	Gross Item Adjustments	(\$16,385.00)	\$6,015.73	(\$10,369.27)
	Gross Item Pay	\$33,815.00	\$251,677.40	\$285,492.40
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	e anor e o na aoc r lagao anonto	<b>40.00</b>	<b>\$0.00</b>	<b>40.00</b>



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Exceeded Completion Time Exception: Contract 191115-B02, Time ID 00 DT, Time Type Completion Date, Current Completion Date 9/1/2020 12:00:00 PM.	No Remark was entered by Engineer	vierss	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 4091048, Project Item Line Number 0100, Material Set 409104896, Material 1015EACRS1 - Emulsified Asphalt CRS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 4091048, Project Item Line Number 0100, Material Set 409104896, Material 1015EACRS2 - Emulsified Asphalt CRS-2, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 4091048, Project Item Line Number 0100, Material Set 409104896, Material 1015EACRS2P - Emulsified Asphalt CRS-2P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 4091048, Project Item Line Number 0100, Material Set 409104896, Material 1015EAEA150 - Emulsified Asphalt EA-150, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 4091048, Project Item Line Number 0100, Material Set 409104896, Material 1015EAEA300 - Emulsified Asphalt EA-300, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 4091048, Project Item Line Number 0100, Material Set 409104896, Material 1015EAEA90P - Emulsified Asphalt EA-90P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 4091048, Project Item Line Number 0100, Material Set 409104896, Material 1015EARS1 - Emulsified Asphalt RS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 4091048, Project Item Line Number 0210, Material Set 409104896, Material 1015EACRS1 - Emulsified Asphalt CRS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 4091048, Project Item Line Number 0210, Material Set 409104896, Material 1015EACRS2 - Emulsified Asphalt CRS-2, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 4091048, Project Item Line Number 0210, Material Set 409104896, Material 1015EACRS2P - Emulsified Asphalt CRS-2P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 4091048, Project Item Line Number 0210, Material Set 409104896, Material 1015EAEA150 - Emulsified Asphalt EA-150, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 4091048, Project Item Line Number 0210, Material Set 409104896, Material 1015EAEA300 - Emulsified Asphalt EA-300, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 4091048, Project Item Line Number 0210, Material Set 409104896, Material 1015EAEA90P - Emulsified Asphalt EA-90P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 4091048, Project Item Line Number 0210, Material Set 409104896, Material 1015EARS1 - Emulsified Asphalt RS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 4091048, Project Item Line Number 0010, Material Set 409104896, Material 1015EACRS1 - Emulsified Asphalt CRS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 4091048, Project Item Line Number 0010, Material Set 409104896, Material 1015EACRS2 - Emulsified Asphalt CRS-2, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 4091048, Project Item Line Number 0010, Material Set 409104896, Material 1015EACRS2P - Emulsified Asphalt CRS-2P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 4091048, Project Item Line Number 0010, Material Set 409104896, Material 1015EAEA150 - Emulsified Asphalt EA-150, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 4091048, Project Item Line Number 0010, Material Set 409104896, Material 1015EAEA300 - Emulsified Asphalt EA-300, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 4091048, Project Item Line Number 0010, Material Set 409104896, Material 1015EAEA90P - Emulsified Asphalt EA-90P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 4091048, Project Item Line Number 0010, Material Set 409104896, Material 1015EARS1 - Emulsified Asphalt RS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 4094012, Project Item Line Number 0220, Material Set 409401296, Material 1003GB2 - Aggregate for Seal Coat Grade B2, Acceptance Action Generic 1003GB2 is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 4094012, Project Item Line Number 0115, Material Set 409401296, Material 1003GB2 - Aggregate for Seal Coat Grade B2, Acceptance Action Generic 1003GB2 is insufficient.	No Remark was entered by Engineer	vierss	Overridden



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 4094012, Project Item Line Number 0020, Material Set 409401296, Material 1003GB2 - Aggregate for Seal Coat Grade B2, Acceptance Action Generic 1003GB2 is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 6206000C, Project Item Line Number 0080, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 6206000C, Project Item Line Number 0080, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 6206000C, Project Item Line Number 0280, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 6206000C, Project Item Line Number 0280, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 6206000C, Project Item Line Number 0170, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 6206000C, Project Item Line Number 0170, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 6206001C, Project Item Line Number 0090, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3188, Item 6206001C, Project Item Line Number 0090, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 6206001C, Project Item Line Number 0180, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3290, Item 6206001C, Project Item Line Number 0180, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 6206001C, Project Item Line Number 0290, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	vierss	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3291, Item 6206001C, Project Item Line Number 0290, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	vierss	Overridden



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates	(Including this Estimate)
--	---------------------------

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract ONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
5-B02	J2S3188	0001	0010	4091048	EMULSIFIED ASPHALT, SEAL COAT	61,819.00	0.00	61,819.00	GAL	61,687.00	\$2.37	\$146,198.
		0001	0020	4094012	SEAL COAT AGGREGATE, GRADE B2	220,782.00	0.00	220,782.00	SQYD	220,782.00	\$0.52	\$114,806
		0001	0030	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000
		0001	0040	6161005	CONSTRUCTION SIGNS	2,047.00	0.00	2,047.00	SQFT	1,025.00	\$6.00	\$6,150
		0001	0050	6161009	FLAG ASSEMBLY	11.00	0.00	11.00	EA	8.00	\$20.00	\$160
		0001	0060	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	12.00	\$15.00	\$180
		0001	0070	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$16,450.00	\$16,450
		0001	0080	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	164,672.00	0.00	164,672.00	LF	131,738.00	\$0.11	\$14,491
		0001	0090	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	112,174.00	0.00	112,174.00	LF	89,739.00	\$0.11	\$9,871
	Project J2	2S3188 - To	otal Value	e Posted to D	ate as of Report Generated Date							\$310,307
	J2S3290	0001	0100	4091048	EMULSIFIED ASPHALT, SEAL COAT	28,417.00	0.00	28,417.00	GAL	28,233.00	\$2.37	\$66,912
		0001	0115	4094012	SEAL COAT AGGREGATE, GRADE B2	101,488.00	0.00	101,488.00	SQYD	101,488.00	\$0.52	\$52,773
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000
		0001	0130	6161005	CONSTRUCTION SIGNS	876.63	0.00	876.63	SQFT	696.00	\$6.00	\$4,176
		0001	0140	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$80
		0001	0150	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	12.00	\$15.00	\$180
		0001	0160	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$8,512.00	\$8,512
		0001	0170	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	65,662.00	0.00	65,662.00	LF	52,530.00	\$0.11	\$5,778
		0001	0180	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	86,423.00	0.00	86,423.00	LF	69,138.00	\$0.11	\$7,605
	Project J	2S3290 - To	otal Value	e Posted to D	ate as of Report Generated Date							\$148,017
	J2S3291	0001	0190	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$4,000.00	\$0
		0001	0200	2153000	SHAPING SLOPES, CLASS III	11.00	0.00	11.00	100F	11.00	\$1,400.00	\$15,400
		0001	0210	4091048	EMULSIFIED ASPHALT, SEAL COAT	49,028.00	0.00	49,028.00	GAL	49,028.00	\$2.37	\$116,196
		0001	0220	4094012	SEAL COAT AGGREGATE, GRADE B2	175,100.00	0.00	175,100.00	SQYD	175,100.00	\$0.52	\$91,052
		0001	0230	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000
		0001	0240	6161005	CONSTRUCTION SIGNS	1,924.00	0.00	1,924.00	SQFT	968.00	\$6.00	\$5,808
		0001	0250	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$20.00	\$160
		0001	0260	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	12.00	\$15.00	\$180
		0001	0270	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$10,100.00	\$10,100
		0001	0280	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	123,668.00	0.00	123,668.00	LF	98,934.00	\$0.11	\$10,882
		0001	0290	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	105,484.00	0.00	105,484.00	LF	84,387.00	\$0.11	\$9,282
		0010	0300	6061060	MGS GUARDRAIL	300.00	0.00	300.00	LF	300.00	\$24.00	\$7,200
		0010	0310	6061074	MGS HEIGHT AND BLOCK TRANSITION	4.00	0.00	4.00	EA	4.00	\$700.00	\$2,800
		0010	0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	8.00	\$3,100.00	\$24,800
		1										
	Project J	2S3291 - To	otal Value	e Posted to D	ate as of Report Generated Date							\$295,86



Project: J2S3291

# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0200	2153000	SHAPING SLOPES, CLASS III	8/25/20	8/26/20	11.00	100F		6.87		7.17		
0300	6061060	MGS GUARDRAIL	8/25/20	8/26/20	300.00	LF		6.87		7.17		
0310	6061074	MGS HEIGHT AND BLOCK TRANSITION	8/25/20	8/26/20	4.00	EA		6.87		7.17		
0320	6063014	TYPE A CRSHWTHY END TERMINAL (MASH)	8/25/20	8/26/20	8.00	EA		6.87		7.17		

The information below this line are details from Line Item agency views. No Agency View Details Exist



				1				
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0010	EMULSIFIED ASPHALT, SEAL COAT	Material		7	Aug 3, 2020	SYSTEM	(\$146,198.19)	
				7	Aug 3, 2020	SYSTEM	\$146,198.19	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 15 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$146,198.19)	
				8	Aug 16, 2020	SYSTEM	\$146,198.19	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 15 on the current Payment Estimate.
				9	Sep 2, 2020	SYSTEM	(\$146,198.19)	
				9	Sep 2, 2020	SYSTEM	\$146,198.19	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user vierss overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total		1		\$0.00	
	Material - Total						\$0.00	
	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	7	Aug 3, 2020	vierss	(\$13,046.62)	
			ACAD - Tota	al			(\$13,046.62)	
	Other Item Adjustment - Total						(\$13,046.62)	
010 -	Total						(\$13,046.62)	
020	SEAL COAT AGGREGATE, GRADE B2	Construction Stockpile		2	May 19, 2020	SYSTEM	\$35,132.08	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Aug 3, 2020	SYSTEM	(\$35,132.08)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	SEAL COAT AGGREGATE, Material GRADE B2	Material		7	Aug 3, 2020	SYSTEM	(\$114,806.64)	
			7	Aug 3, 2020	SYSTEM	\$114,806.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.	
				8	Aug 16, 2020	SYSTEM	(\$114,806.64)	
				8	Aug 16, 2020	SYSTEM	\$114,806.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.
				9	Sep 2, 2020	SYSTEM	(\$114,806.64)	
				9	Sep 2, 2020	SYSTEM	\$114,806.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user vierss overridding Payment Estimate Exception 25 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
020 -	Total						\$0.00	
080	4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		7	Aug 3, 2020	SYSTEM	(\$14,491.18)	
	MARKING PAINT, TYPE P BEADS			7	Aug 3, 2020	SYSTEM	\$14,491.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 29 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$14,491.18)	
				8	Aug 16, 2020	SYSTEM	\$14,491.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 25 on the current Payment Estimate.
				9	Sep 2, 2020	SYSTEM	(\$14,491.18)	
				9	Sep 2, 2020	SYSTEM	\$14,491.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user vierss overridding Payment Estimate Exception 26 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0090	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	Material		7	Aug 3, 2020	SYSTEM	(\$9,871.29)	
	MARKING PAINT, TYPE P BEADS			7	Aug 3, 2020	SYSTEM	\$9,871.29	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 33 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$9,871.29)	
				8	Aug 16, 2020	SYSTEM	\$9,871.29	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate.
				9	Sep 2, 2020	SYSTEM	(\$9,871.29)	
				9	Sep 2, 2020	SYSTEM	\$9,871.29	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user vierss overridding Payment Estimate Exception 32 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
090 -	Total						\$0.00	
0100	EMULSIFIED ASPHALT, SEAL COAT	Material		7	Aug 3, 2020	SYSTEM	(\$66,912.21)	
				7	Aug 3, 2020	SYSTEM	\$66,912.21	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.
			8	Aug 16, 2020	SYSTEM	(\$66,912.21)		
			8	Aug 16, 2020	SYSTEM	\$66,912.21	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.	
				9	Sep 2, 2020	SYSTEM	(\$66,912.21)	
			9	Sep 2, 2020	SYSTEM	\$66,912.21	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.	
			- Total				\$0.00	
	Material - Total				_		\$0.00	
	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	7	Aug 3, 2020	vierss	(\$5,971.19)	
			ACAD - Total				(\$5,971.19)	
	Other Item Adjustment - Total						(\$5,971.19)	
100 -	Total						(\$5,971.19)	
)115	SEAL COAT AGGREGATE, GRADE B2	Construction Stockpile		2	May 19, 2020	SYSTEM	\$16,145.40	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Aug 3, 2020	SYSTEM	(\$16,145.40)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	SEAL COAT AGGREGATE, GRADE B2	Material		7	Aug 3, 2020	SYSTEM	(\$52,773.76)	
				7	Aug 3, 2020	SYSTEM	\$52,773.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$52,773.76)	
				8	Aug 16, 2020	SYSTEM	\$52,773.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.
				9	Sep 2, 2020	SYSTEM	(\$52,773.76)	
				9 9		SYSTEM	(\$52,773.76) \$52,773.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user vierss overridding Payment Estimate Exception 24 on the current Payment Estimate.
			- Total		2020 Sep 2,			Estimate Item Adjustment (0021) due to user vierss overridding Payment
	Material - Total		- Total		2020 Sep 2,		\$52,773.76	Estimate Item Adjustment (0021) due to user vierss overridding Payment



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0170	4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		7	Aug 3, 2020	SYSTEM	(\$5,778.30)	
	MARKING PAINT, TYPE P BEADS			7	Aug 3, 2020	SYSTEM	\$5,778.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 25 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$5,778.30)	
				8	Aug 16, 2020	SYSTEM	\$5,778.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 29 on the current Payment Estimate.
				9	Sep 2, 2020	SYSTEM	(\$5,778.30)	
				9	Sep 2, 2020	SYSTEM	\$5,778.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user vierss overridding Payment Estimate Exception 30 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
170 -	- Total						\$0.00	
180	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		7	Aug 3, 2020	SYSTEM	(\$7,605.18)	
				7	Aug 3, 2020	SYSTEM	\$7,605.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 31 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$7,605.18)	
			8	Aug 16, 2020	SYSTEM	\$7,605.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 31 on the current Payment Estimate.	
				9	Sep 2, 2020	SYSTEM	(\$7,605.18)	
				9	Sep 2, 2020	SYSTEM	\$7,605.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user vierss overridding Payment Estimate Exception 34 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
180 -	- Total						\$0.00	
210	EMULSIFIED ASPHALT, SEAL COAT	Material		7	Aug 3, 2020		(\$116,196.36)	
				7	Aug 3, 2020	SYSTEM	\$116,196.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$116,196.36)	
				8	Aug 16, 2020	SYSTEM	\$116,196.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Sep 2, 2020	SYSTEM	(\$116,196.36)	
				9	Sep 2, 2020	SYSTEM	\$116,196.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user vierss overridding Payment Estimate Exception 9 on the current Payment Estimate.
	- Total			Total			\$0.00	
	Material - Total						\$0.00	
	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	7	Aug 3, 2020	vierss	(\$10,369.27)	
	ACAD - Total						(\$10,369.27)	
	Other Item Adjustment - Total						(\$10,369.27)	
<mark>210</mark> - 220	Total SEAL COAT AGGREGATE,	Construction		2	May 19,	SYSTEM	(\$10,369.27) \$27,866.66	Payment Estimate Item Adjustment generated Stockpile Transaction
-	GRADE B2	Stockpile		7	2020 Aug 3,	SYSTEM	(\$27,866.66)	Payment Estimate Item Adjustment generated Stockpile Transaction
					2020		/	
			- Total				\$0.00	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0220	SEAL COAT AGGREGATE, GRADE B2	Material		7	Aug 3, 2020	SYSTEM	(\$91,052.00)	
				7	Aug 3, 2020	SYSTEM	\$91,052.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$91,052.00)	
			8	Aug 16, 2020	SYSTEM	\$91,052.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.	
				9	Sep 2, 2020	SYSTEM	(\$91,052.00)	
				9	Sep 2, 2020	SYSTEM	\$91,052.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user vierss overridding Payment Estimate Exception 23 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0220	- Total						\$0.00	
0280	4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		7	Aug 3, 2020	SYSTEM	(\$10,882.74)	
	MARKING PAINT, TYPE P BEADS			7	Aug 3, 2020	SYSTEM	\$10,882.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment Estimate Exception 27 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$10,882.74)	
				8	Aug 16, 2020	SYSTEM	\$10,882.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 27 on the current Payment Estimate.
			9	Sep 2, 2020	SYSTEM	(\$10,882.74)		
				9	Sep 2, 2020	SYSTEM	\$10,882.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user vierss overridding Payment Estimate Exception 28 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0280	- Total						\$0.00	
0290	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		7	Aug 3, 2020	SYSTEM	(\$9,282.57)	
				7	Aug 3,	SYSTEM	\$9,282.57	This adjustment effects the evisional system reported Overway Devisions
					2020		ψ <del>3</del> ,202.37	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate.
				8	2020 Aug 16, 2020	SYSTEM	(\$9,282.57)	Estimate Item Adjustment (0015) due to user buckj overridding Payment
				8	Aug 16,	SYSTEM SYSTEM		Estimate Item Adjustment (0015) due to user buckj overridding Payment
					Aug 16, 2020 Aug 16,		(\$9,282.57)	Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment
				8	Aug 16, 2020 Aug 16, 2020 Sep 2,	SYSTEM	(\$9,282.57) \$9,282.57	Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment
			- Total	8	Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM	(\$9,282.57) \$9,282.57 (\$9,282.57)	Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user vierss overridding Payment
	Material - Total		- Total	8	Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM	(\$9,282.57) \$9,282.57 (\$9,282.57) \$9,282.57	Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user vierss overridding Payment
0290			- Total	8	Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM	(\$9,282.57) \$9,282.57 (\$9,282.57) \$9,282.57 \$9,282.57	Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user vierss overridding Payment
	Material - Total	Construction Stockpile	- Total	8	Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM	(\$9,282.57) \$9,282.57 (\$9,282.57) \$9,282.57 \$9,282.57 \$0.00 \$0.00	Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user vierss overridding Payment
	Material - Total - Total		- Total	8 9 9	Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Apr 13,	SYSTEM SYSTEM SYSTEM	(\$9,282.57) \$9,282.57 (\$9,282.57) \$9,282.57 \$9,282.57 \$0.00 \$0.00	Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user vierss overridding Payment Estimate Exception 36 on the current Payment Estimate.
	Material - Total - Total		- Total	999	Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Appr 13, 2020 Sep 1,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,282.57) \$9,282.57 (\$9,282.57) \$9,282.57 \$0.00 \$0.00 \$0.00 \$3,201.00	Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user vierss overridding Payment Estimate Exception 36 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction
0290 J 0300	Material - Total - Total			999	Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Appr 13, 2020 Sep 1,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,282.57) \$9,282.57 (\$9,282.57) \$9,282.57 \$0.00 \$0.00 \$0.00 \$3,201.00 (\$3,201.00)	Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user vierss overridding Payment Estimate Exception 36 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction
0300	Material - Total - Total MGS GUARDRAIL Construction Stockpile - Total			999	Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Appr 13, 2020 Sep 1,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,282.57) \$9,282.57 (\$9,282.57) \$9,282.57 \$0.00 \$0.00 \$3,201.00 (\$3,201.00) (\$3,201.00) \$0.00	Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user vierss overridding Payment Estimate Exception 36 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction
0300	Material - Total - Total MGS GUARDRAIL			999	Aug 16, 2020 Aug 16, 2020 Sep 2, 2020 Sep 2, 2020 Appr 13, 2020 Sep 1,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,282.57) \$9,282.57 (\$9,282.57) \$9,282.57 \$0.00 \$0.00 \$0.00 \$3,201.00 (\$3,201.00) \$\$,201.00	Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user vierss overridding Payment Estimate Exception 36 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0310	MGS HEIGHT AND BLOCK TRANSITION	Construction Stockpile			2020			
	- Total						\$0.00	
	Construction Stockpile - Total						\$0.00	
0310 -	10 - Total						\$0.00	
0320		Construction Stockpile		1	Apr 13, 2020	SYSTEM	\$12,080.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				9	Sep 1, 2020	SYSTEM	(\$12,080.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total						\$0.00	
	Construction Stockpile - Total						\$0.00	
0320 -	Total						\$0.00	
Overa	ill - Total						(\$29,387.08)	