

Progress Est	timate Number 6	Contract ID Prime Contractor	191213-C06 Ideker, Inc.	Pay Per Pay Per	iod Start iod End	June 2, 2 June 15,	2020 Net Chang	ontract Amount e Order Amount ontract Amount	\$2,130,919.51 \$0.00 \$2,130,919.51		
Approval Date									By User		
June 16, 2020		Generated and Approved (and should be considered Draft) at the Project Office Level									
June 16, 2020		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level b									
June 17, 2020				Reviewed	and Approv	ved at the (Central Office Contro	ollers Office Level by	greggd1		
Original Com	pletion Date	Current Completio	n Date	Actua	l Completi	on Date	% of Cu	rrent Contract Amou	nt Complete		
November	1, 2020)20	88.00%								
Co	ontract Informationa	I Dates					Milestones				
Date Description	Original Completion Date	Current Completion Date	Date D	Date Description		ginal tion Date	Current Completion Date	Days Remaining o Milestone	n Diary Charge Days		
Acceptance Date			Mileston	-	July 15, 2	2020	July 15, 2020		29		
Awarded Date	January 9, 2020	January 9, 2020	Calenda	r Time							
Letting Date	December 13, 2019	December 13, 2019									
Notice to Proceed Date	March 9, 2020	March 9, 2020									
Open to Traffic Date											
Work Began Date											

Contract Total Pay For Estimate No. 6										
		This Estimate	Previous	To Date						
191213-C06										
	Total Posted Items Pay	\$1,072,909.97	\$802,283.25	\$1,875,193.22						
	Gross Item Adjustments	(\$116,831.41)	(\$6,823.74)	(\$123,655.15)						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
			<mark>\$795,459.51</mark>	\$1,751,538.07						
Contract Total Pay	able This Estimate:	\$956,078.56								

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Item Description Unit Unit Current O Price Installed Qty							
J4P3276	0040	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	TONS	\$61.480	1,032.86	\$63,500.23				
	0070	4030101	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	TONS	\$60.530	15,532.22	\$940,165.28				
	0080	4071005	TACK COAT	GAL	\$2.500	10,544	\$26,360.00				
	0220	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$31.000	33	\$1,023.00				
	0230	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.140	41,830	\$5,856.20				
	0240	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.200	62,980	\$12,596.00				
	0260	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$6.690	668	\$4,468.92				
	0270	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	STA	\$16.880	686.8	\$11,593.18				
	0280	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	STA	\$18.980	387.1	\$7,347.16				
Project J4P	3276 - Tota	d					\$1,072,909.97				
Overall - To	tal						\$1,072,909.97				

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate



Pro	gress I	Estimate Number 6	Contrac Prime C		91213-C06 I eker, Inc. I	Pay Period End June 15, 2020 Net Char	Contract Amo ige Order Amo Contract Amo	ount \$0.	130,919.51 00 130,919.51
Project Number	Line No.	Item Descript	ion	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
I4P3276	0040		MISC.	Overrun		This adjustment offsets the original system generated Overrun Payment Estimate Iter Adjustment (0012) overridding Paymer Estimate Exception 18 on the current Paymer Estimate	n t	\$61.48	\$20,279.79
	0040		MISC.	Overrun		This adjustment offsets the original system generated Overrun Payment Estimate Iter Adjustment (0013) overridding Paymer Estimate Exception 18 on the current Paymer Estimate	n t	\$61.48	\$13,095.2
	0040		MISC.	Overrun			-329.86	\$61.48	(\$20,279.7
	0040		MISC.	Overrun			-213	\$61.48	(\$13,095.2
	0040		MISC.	Material			-1,032.86	\$61.48	(\$63,500.2
	0040		MISC.	Material		This adjustment offsets the original system generated Overrun Payment Estimate Iter Adjustment (0014) due to user hathak overridding Payment Estimate Exception 1 o the current Payment Estimate	n 1 n	\$61.48	\$63,500.23
	0040		MISC.	Other Item Adjustment	Overrun	Pay tp P0	-542.86	\$61.48	(\$33,375.0
	0070	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)		Price		Reference Item Price Adjustment Inde Adjustment Type applied is FUE		(\$3.39)	(\$7,963.3
	0070	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)		Price		Reference Item Price Adjustment Inde Adjustment Type applied is FUE		(\$3.39)	(\$6,316.4
	0070	ASPHALTIC CC MIXTURE PG 64-22		Price		Reference Item Price Adjustment Inde Adjustment Type applied is FUE		(\$3.39)	(\$2,638.4
	0070	ASPHALTIC CC MIXTURE PG 64-22		Price		Reference Item Price Adjustment Inde Adjustment Type applied is FUE		(\$3.39)	(\$5,286.3
	0070	ASPHALTIC CC MIXTURE PG 64-22		Price		Reference Item Price Adjustment Inde Adjustment Type applied is FUE		(\$3.39)	(\$7,097.2
	0070	ASPHALTIC CC MIXTURE PG 64-22		Price		Reference Item Price Adjustment Inde Adjustment Type applied is FUE		(\$3.39)	(\$6,872.0
	0070	ASPHALTIC CC MIXTURE PG 64-22		Price		Reference Item Price Adjustment Inde Adjustment Type applied is FUE		(\$3.39)	(\$5,820.4
	0070	ASPHALTIC CC MIXTURE PG 64-22		Price		Reference Item Price Adjustment Inde Adjustment Type applied is FUE		(\$3.39)	(\$7,026.5
	0070	ASPHALTIC CC MIXTURE PG 64-22		Price		Reference Item Price Adjustment Inde Adjustment Type applied is FUE		(\$3.39)	(\$3,577.4
	0070	ASPHALTIC CC MIXTURE PG 64-22		Material			-15,532.22	\$60.53	(\$940,165.2
	0070		MIX) ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)			This adjustment offsets the original system generated Overrun Payment Estimate Iter Adjustment (0018) due to user hathak overridding Payment Estimate Exception 2 o the current Payment Estimate	n 1 1	\$60.53	\$940,165.2
	0070	ASPHALTIC CC MIXTURE PG 64-22		Other Item Adjustment		For 15,532.22 tons of SP125C place between June 2, 2020 and June 15, 202			(\$30,579.0



Prog	gress E				Pay Period End June 15, 2020 Net Chang	ontract Amo je Order Amo ontract Amo	ount \$0.	2,130,919.51).00 2,130,919.51	
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
4P3276	0080	TACK CO	AT MaterialCredit			9,000	\$2.50	\$22,500.00	
	0080	TACK CO	AT Material			-19,544	\$2.50	(\$48,860.00	
	0080	TACK CO	AT Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	19,544	\$2.50	\$48,860.00	
	0080	TACK CO		Material Discrepancy Payment Adjustment	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.			(\$22,500.00	
	0100	FURNISHING AND PLACH CONCRETE MATERIAL FO FULL DEPTH PAVEME REPA	DR NT			306.7	\$443.15	\$135,914.10	
	0100	FURNISHING AND PLACH CONCRETE MATERIAL FO FULL DEPTH PAVEME REPA	DR NT			-306.7	\$443.15	(\$135,914.10)	
	0100	FURNISHING AND PLACIN CONCRETE MATERIAL FO FULL DEPTH PAVEME REPA	DR NT		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0022) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	306.7	\$443.15	\$135,914.10	
	0100	FURNISHING AND PLACH CONCRETE MATERIAL FO FULL DEPTH PAVEME REPA	R Adjustment	Material Discrepancy Payment Adjustment	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.			(\$135,914.10	
	0140	DOWEL BAR (DRILLIN FURNISHING AI INSTALLATION) FOR FU DEPTH PAVEMENT REPA				566	\$5.45	\$3,084.70	
	0140	DOWEL BAR (DRILLIN FURNISHING AI INSTALLATION) FOR FU DEPTH PAVEMENT REPA	ID LL			-566	\$5.45	(\$3,084.70	
	0140	DOWEL BAR (DRILLIN FURNISHING AI INSTALLATION) FOR FU DEPTH PAVEMENT REPA			This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0024) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	566	\$5.45	\$3,084.70	
	0140	DOWEL BAR (DRILLIN FURNISHING AI INSTALLATION) FOR FU DEPTH PAVEMENT REPA	ID Adjustment	Material Discrepancy Payment Adjustment	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.			(\$3,084.70	
	0170	CONSTRUCTION SIG	NS MaterialCredit			559.5	\$6.00	\$3,357.00	
	0170	CONSTRUCTION SIG	IS Material			-559.5	\$6.00	(\$3,357.00	
	0170	CONSTRUCTION SIG	IS Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0026) due to user hathak1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	559.5	\$6.00	\$3,357.00	
	0170	CONSTRUCTION SIG		Material Discrepancy Payment Adjustment	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.			(\$3,357.00	
	0180	FLAG ASSEMB	Y MaterialCredit			12	\$25.00	\$300.00	
	0180	FLAG ASSEMB	Y Material			-12	\$25.00	(\$300.00	
	0180	FLAG ASSEMB	Y Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item	12	\$25.00	\$300.00	

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pro	gress E	Estimate Number 6	Contrac Prime C			Pay Period End June 15, 2020 Net C	nal Contract Amo Change Order Amo ent Contract Amo	ount \$0.	\$2,130,919.51 \$0.00 \$2,130,919.51	
Project Number	Line No.	Item Descriptio	on	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J4P3276						Adjustment (0028) due to user hat overridding Payment Estimate Exceptic on the current Payment Estir	on 10			
	0180	FLAG AS	SEMBLY	Other Item Adjustment	Material Discrepancy Payment Adjustment	This adjustment is to offset the Material C provided on this estimate, as a ma adjustment was made previously on Esti 0005 by Hati	anual mate		(\$300.00	
	0190	CHANNELIZER (TR	IM LINE)	MaterialCredit			163	\$12.00	\$1,956.00	
	0190	CHANNELIZER (TR	IM LINE)	Material			-163	\$12.00	(\$1,956.00	
	0190	CHANNELIZER (TR	IM LINE)	Material		This adjustment offsets the original sys generated Overrun Payment Estimate Adjustment (0030) due to user hat overridding Payment Estimate Exceptio on the current Payment Estir	Item hak1 on 11	\$12.00	\$1,956.00	
	0190	CHANNELIZER (TR	IM LINE)	Other Item Adjustment	Material Discrepancy Payment Adjustment	This adjustment is to offset the Material C provided on this estimate, as a ma adjustment was made previously on Esti 0005 by Hatt	anual mate		(\$1,956.00	
	0200	COMMUN INTERFACE, CONTE FURNISHED, CONTE	VITHOUT ICATION RACTOR	MaterialCredit			2	\$2,500.00	\$5,000.00	
	0200			Material			-2	\$2,500.00	(\$5,000.00	
	0200	COMMUN INTERFACE, CONTE FURNISHED, CONTE	VITHOUT ICATION RACTOR	Material		This adjustment offsets the original sys generated Overrun Payment Estimate Adjustment (0032) due to user hat overridding Payment Estimate Exceptio on the current Payment Estim	ltem hak1 on 12	\$2,500.00	\$5,000.00	
	0200	COMMUN INTERFACE, CONTE FURNISHED, CONTE	VITHOUT ICATION RACTOR	Other Item Adjustment	Material Discrepancy Payment Adjustment	This adjustment is to offset the Material C provided on this estimate, as a ma adjustment was made previously on Esti 0005 by Hat	anual mate		(\$5,000.00	
	0220	THERMOR PAVEMENT MARI		Overrun		This adjustment offsets the original sys generated Overrun Payment Estimate Adjustment (0016) overridding Pay Estimate Exception 21 on the current Pay Estim	Item ment	\$31.00	\$279.00	
	0220	THERMOR PAVEMENT MARI		Overrun			-9	\$31.00	(\$279.00	
	0220	THERMOR PAVEMENT MARI		Material			-33	\$31.00	(\$1,023.00	
	0220	THERMOR PAVEMENT MARI		Material		This adjustment offsets the original sys generated Overrun Payment Estimate Adjustment (0017) due to user hat overridding Payment Estimate Exceptio on the current Payment Estir	Item hak1 on 13	\$31.00	\$1,023.00	
	0220	PREF THERMOR	ORMED	Other Item Adjustment	Overrun	Pay t	o PQ -9	\$31.00	(\$279.00	



Progress Estimate Number 6		Contrac Prime C	• -= ·	191213-C06 deker, Inc.	Pay Period Start Pay Period End	Pay Period End June 15, 2020			ount \$0.	\$2,130,919.51 \$0.00 \$2,130,919.51	
Project Number	Line No.	Item Descript	ion	Adjustment Type	Other Item Adjustment Type		Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J4P3276		PAVEMENT MAF	RKING, 24 N. WHITE								
	0230	4 IN. YELLOW HIG WATERBORNE PA MARKING PAIN	VEMENT	Material					-41,830	\$0.14	(\$5,856.20)
	0230	4 IN. YELLOW HIG WATERBORNE PA MARKING PAIN	VEMENT	Material		generated O Adjustme overridding Pa	ent offsets the orig verrun Payment E ent (0033) due to u ayment Estimate E the current Payme	stimate Item Iser hathak1 Exception 14	41,830	\$0.14	\$5,856.20
	0240	6 IN. WHITE HI WATERBORNE PA MARKING PAIN	VEMENT	Material					-62,980	\$0.20	(\$12,596.00)
	0240	6 IN. WHITE HI WATERBORNE PA MARKING PAIN	VEMENT	Material		generated O Adjustme overridding Pa	ent offsets the orig verrun Payment E ent (0034) due to u ayment Estimate E the current Payme	stimate Item Iser hathak1 Exception 16	62,980	\$0.20	\$12,596.00
Total											(\$116,831.41



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Con	tract Project Informati	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4P3276	FAS S301(93)	Coldmill and resurface	92	PLATTE	from MO River to Route 273		
Totals by J	Job Numbe	rs					
J4P3276		d Item Pay Item Adjustm		s Item Pay	This Estimate \$1,072,909.97 (\$116,831.41) \$956,078.56	Previous \$802,283.25 (\$6,823.74) \$795,459.51	To Date \$1,875,193.22 (\$123,655.15) \$1,751,538.07
	Liquid	tive centive lated Damage Contract Adju		i	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Ferrou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 3049910, Project Item Line Number 0040, Material Set 304991096, Material 0619PET - Material for Pavement Edge Treatment, Acceptance Action Generic 0619PET is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 4030101, Project Item Line Number 0070, Material Set 403010196, Material 0403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 4071005, Project Item Line Number 0080, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6131015, Project Item Line Number 0140, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6131015, Project Item Line Number 0140, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6161005, Project Item Line Number 0170, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6161009, Project Item Line Number 0180, Material Set 616100996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6161025, Project Item Line Number 0190, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6161098A, Project Item Line Number 0200, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6200015, Project Item Line Number 0220, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6205901A, Project Item Line Number 0230, Material Set 6205901A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6205901A, Project Item Line Number 0230, Material Set 6205901A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6205902A, Project Item Line Number 0240, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6205902A, Project Item Line Number 0240, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C06, Contract Project J4P3276, Project Item Line Number 0040, Contract Line Item Number 0040, Item 3049910, Minor Item.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C06, Contract Project J4P3276, Project Item Line Number 0060, Contract Line Item Number 0060, Item 4030015, Minor Item.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C06, Contract Project J4P3276, Project Item Line Number 0150, Contract Line Item Number 0150, Item 6133020, Minor Item.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C06, Contract Project J4P3276, Project Item Line Number 0220, Item 6200015, Minor Item.	No Remark was entered by Engineer	hathak1	Overridden

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

d date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project CONTRACT No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
213-C06 J4P3276	0001	0010	1099901	MISC.ELECTRONIC TICKETING	1.00	0.00	1.00	LS	0.00	\$1,000.00	\$0.00
	0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$9,200.00	\$0.00
	0001	0030	2153000	SHAPING SLOPES, CLASS III	4.00	0.00	4.00	100F	0.00	\$1,400.00	\$0.0
	0001	0040	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	490.00	0.00	490.00	TONS	1,032.86	\$61.48	\$63,500.2
	0001	0050	3105002	GRAVEL (A) OR CRUSHED STONE (B)	68.00	0.00	68.00	TONS	0.00	\$133.27	\$0.0
	0001	0060	4030015	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP048F MIX)	4,983.00	0.00	4,983.00	TONS	5,015.03	\$72.01	\$361,132.3
	0001	0070	4030101	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	16,619.00	0.00	16,619.00	TONS	15,532.22	\$60.53	\$940,165.2
	0001	0080	4071005	TACK COAT	23,264.00	0.00	23,264.00	GAL	19,544.00	\$2.50	\$48,860.0
	0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.0
	0001	0100	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	320.00	0.00	320.00	SQYD	306.70	\$443.15	\$135,914.1
	0001	0110	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	32.00	0.00	32.00	SQYD	0.00	\$1.20	\$0.0
0001 0120 613		6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	32.00	0.00	32.00	SQYD	0.00	\$1.20	\$0.0	
	0001	0130	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,200.00	0.00	1,200.00	LF	1,123.00	\$1.50	\$1,684.5
	0001	0140	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	800.00	0.00	800.00	EA	566.00	\$5.45	\$3,084.7
	0001	0150	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	363.90	0.00	363.90	TONS	447.10	\$94.22	\$42,125.7
	0001	0160	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	2,202.10	0.00	2,202.10	SQYD	2,179.10	\$49.12	\$107,037.3
	0001	0170	6161005	CONSTRUCTION SIGNS	1,429.00	0.00	1,429.00	SQFT	559.50	\$6.00	\$3,357.0
	0001	0180	6161009	FLAG ASSEMBLY	13.00	0.00	13.00	EA	12.00	\$25.00	\$300.0
	0001	0190	6161025	CHANNELIZER (TRIM LINE)	163.00	0.00	163.00	EA	163.00	\$12.00	\$1,956.0
	0001	0200	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.0
	0001	0210	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$124,822.36	\$62,411.1
	0001	0220	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	24.00	0.00	24.00	LF	33.00	\$31.00	\$1,023.0
	0001	0230	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	59,369.00	0.00	59,369.00	LF	41,830.00	\$0.14	\$5,856.2
	0001	0240	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	85,346.00	0.00	85,346.00	LF	62,980.00	\$0.20	\$12,596.0
	0001	0250	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	109,447.00	0.00	109,447.00	SQYD	72,974.00	\$0.74	\$54,000.7
	0001	0260	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	4,153.00	0.00	4,153.00	SQYD	934.00	\$6.69	\$6,248.4
	0001	0270	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	814.10	0.00	814.10	STA	686.80	\$16.88	\$11,593.1
	0001	0280	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	407.00	0.00	407.00	STA	387.10	\$18.98	\$7,347.1
	0010	0290	6061060	MGS GUARDRAIL	1,476.00	0.00	1,476.00	LF	0.00	\$24.00	\$0.0
	0010	0300	6061074	MGS HEIGHT AND BLOCK TRANSITION	8.00	0.00	8.00	EA	0.00	\$604.00	\$0.0
	0010	0310	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	0.00	\$2,900.00	\$0.0
			Destad to D	Date as of Report Generated Date							\$1,875,193.2



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3276

Line lumber	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0040	3049910	MISC. AGGREGATE FOR BASE	6/7/20	6/15/20	329.86	TONS	WB Route 92 from log mile 31.650 log mile 35.887 EB Route 92 from log mile 3.694 to log mile 6.155	See location				Edge treatment was placed at various locations as marked by the inspector at the log miles as specified above.
			6/14/20	6/16/20	703.00	TONS	EB and WB Route 92 edge wedge from Beverly Bridge to the Missouri River Bridge. This also includes driveways in the area.	0.218		3.539		
0070	4030101	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP1	6/2/20	6/15/20	2,351.57	TONS	WB Route 92. Placed 12' lane and 4' shoulder	31.650		34.039		
			6/3/20	6/15/20	1,865.25	TONS	WB Route 92. Completed up to Beverly Bridge	34.039		35.887		
			6/4/20	6/15/20	779.13	TONS	EB Route 92. Began at Beverly bridge	3.694		4.520		
			6/5/20	6/15/20	1,561.05	TONS	EB Route 92	4.520		6.155		
			6/6/20	6/15/20	2,095.80	TONS	EB Route 92 LM 6.155 to LM 8.055 WB Route 92 LM 31.549 to LM 31.652	6.155		8.055		
			6/9/20	6/15/20	2,029.30	TONS	WB Route 92	36.084		38.151		
			6/10/20	6/15/20	1,718.78	TONS	EB Route 92	0.218		1.926		
			6/11/20	6/15/20	2,074.93	TONS	WB Route 92 LM 38.151 to LM 39.378 EB Route 92 LM 1.926 to LM 2.823	See locations				
			6/12/20	6/16/20	1,056.41	TONS	EB Route 92	3.539		2.823		
0080	4071005	TACK COAT	6/2/20	6/15/20	1,840.00	GAL	WB Route 92 mainline and shoulder	31.650		34.039		
			6/3/20	6/15/20	1,550.00	GAL	WB Route 92	34.039		35.887		
			6/4/20	6/15/20	387.00	GAL	EB Route 92 beginning at Beverly bridge	3.694		4.520		
			6/5/20	6/15/20	678.00	GAL	EB Route 92	4.520		6.155		
			6/6/20	6/15/20	1,259.00	GAL	EB Route 92 LM 6.155 to LM 8.055 WB Route 92 LM 31.549 to LM 31.652	6.155		8.055		
			6/9/20	6/15/20	1,259.00	GAL	WB Route 92	36.084		38.151		
			6/10/20	6/15/20	1,162.00	GAL	EB Route 92	0.218		1.926		
			6/11/20	6/15/20	1,259.00	GAL	WB Route 92 LM 38.151 to LM 39.378 EB Route 92 LM 1.926 to LM 2.823	See location				
			6/12/20	6/16/20	1,150.00	GAL	EB Route 92	3.539		2.823		
0220	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	6/13/20	6/16/20	33.00	LF	Route 45 Spur and Route 92 spur.	See Location				75% payment made until test results are completed
0230	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAINT	6/13/20	6/16/20	41,830.00	LF	Route 92 centerline pavement marking	0.218		8.082		75% payment made until test results are completed
0240	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	6/13/20	6/16/20	62,980.00	LF	EB and WB Route 92 edge lines	0.218		8.082		75% payment made until test results are completed
0260	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	6/2/20	6/15/20	269.00	SQYD	Beverly Drive - 192 sq yds Ode Road - 1925 sq yds Fulk Lane - 19.25 sq yds Farley Road - 19.25 sq yds Hackberry Lane - 19.25 sq yds	See Location		0		
			6/9/20	6/15/20	399.00	SQYD	Cut both headers on east side LM 3.539 and west side LM 3.694 of Beverly bridge. Cut headers at Missouri River bridge LM 0218	See Location				
0270	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	6/13/20	6/16/20	686.80	STA	EB and WB Route 92 shoulder rumble.	0.218		8.082		
0280	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	6/13/20	6/16/20	387.10	STA	Route 92 centerline rumble stripe	0.218		8.082		

The information below this line are details from Line Item agency views. No Agency View Details Exist



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		6	Jun 16, 2020	SYSTEM	(\$63,500.23)	
				6	Jun 16, 2020	SYSTEM	\$63,500.23	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Other Item Adjustment	OVRN	6	Jun 16, 2020	wilsor2	(\$33,375.03)	Pay tp PQ
			OVRN - Tota	al			(\$33,375.03)	
	Other Item Adjustment - Total						(\$33,375.03)	
	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Overrun	Overrun	6	Jun 16, 2020	SYSTEM	\$20,279.79	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 18 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	\$13,095.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 18 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$33,375.03)	
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0040 -	Total						(\$33,375.03)	
0060	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP048F MIX)	Other Item Adjustment	ACAD	5	Jun 2, 2020	hathak1	(\$8,462.87)	A/C Adjustment for 5015.03 tons of SP048 placed between May 16, 2020 and June 1, 2020.
			ACAD - Tota	al			(\$8,462.87)	
	Other Item Adjustment - Total						(\$8,462.87)	
	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP048F MIX)	Overrun	Overrun		Jun 2, 2020	SYSTEM	(\$2,187.38)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Overrun - T	otal			(\$2,187.38)	
	Overrun - Total						(\$2,187.38)	
	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP048F MIX)	Price		5	Jun 2, 2020	SYSTEM	(\$18,647.89)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$18,647.89)	
	Price - Total						(\$18,647.89)	
0060 -							(\$29,298.14)	
0070	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	Material		6	Jun 16, 2020	SYSTEM	(\$940,165.28)	
				6	Jun 16, 2020	SYSTEM	\$940,165.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	Other Item Adjustment	ACAD		Jun 16, 2020	hathak1	(\$30,579.06)	For 15,532.22 tons of SP125C placed between June 2, 2020 and June 15, 2020
			ACAD - Tota	al			(\$30,579.06)	
	Other Item Adjustment - Total						(\$30,579.06)	
	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	Price		6	Jun 16, 2020	SYSTEM	(\$52,598.32)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$52,598.32)	
	Price - Total						(\$52,598.32)	
0070 -	Total			_			(\$83,177.38)	
0080	TACK COAT	Material		5	Jun 2, 2020	SYSTEM	(\$22,500.00)	
				6	Jun 16, 2020	SYSTEM	(\$48,860.00)	
				6	Jun 16, 2020	SYSTEM	\$48,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0800		Material	- Total				(\$22,500.00)		
	Material - Total						(\$22,500.00)		
	TACK COAT	MaterialCredit		6	Jun 16, 2020	SYSTEM	\$22,500.00		
			- Total				\$22,500.00		
	MaterialCredit - Total						\$22,500.00		
	TACK COAT	Other Item Adjustment	MDPA	5	Jun 2, 2020	hathak1	\$22,500.00	Inspector needs to enter material report for this item.	
				6	Jun 16, 2020	wilsor2	(\$22,500.00)	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.	
			MDPA - Tot	al			\$0.00		
	Other Item Adjustment - Total						\$0.00		
080 -	Total						\$0.00		
0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH	Material		4	May 18, 2020	SYSTEM	(\$135,914.10)		
	PAVEMENT REPAIR			4	May 18, 2020	SYSTEM	\$135,914.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				5	Jun 2, 2020	SYSTEM	(\$135,914.10)		
				6	Jun 16, 2020	SYSTEM	(\$135,914.10)		
				6	Jun 16, 2020	SYSTEM	\$135,914.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
			- Total				(\$135,914.10)		
	Material - Total						(\$135,914.10)		
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		6	Jun 16, 2020	SYSTEM	\$135,914.10		
			- Total				\$135,914.10		
	MaterialCredit - Total						\$135,914.10		
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Other Item Adjustment	MDPA	5	Jun 2, 2020	hathak1	\$135,914.10	Inspector needs to enter material report for this item.	
				6	Jun 16, 2020	wilsor2	(\$135,914.10)	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.	
			MDPA - Tot	al	MDPA - Total				
	Other Item Adjustment - Total	Other Item Adjustment - Total							
							\$0.00 \$0.00		
0100 -	Total								
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		4	May 18, 2020	SYSTEM	\$0.00		
0 100 - 0140	DOWEL BAR (DRILLING, FURNISHING	Material		4		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material			2020 May 18,		\$0.00 \$0.00 (\$3,084.70)	Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current	
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		4	2020 May 18, 2020 Jun 2,	SYSTEM	\$0.00 \$0.00 (\$3,084.70) \$3,084.70	Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current	
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		4	2020 May 18, 2020 Jun 2, 2020 Jun 16,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,084.70) \$3,084.70 (\$3,084.70)	Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current	
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material	- Total	4 5 6	2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,084.70) \$3,084.70 (\$3,084.70) (\$3,084.70)	Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user hathak1 overridding Payment Estimate Exception 7 on the current	
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material	- Total	4 5 6	2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,084.70) \$3,084.70 (\$3,084.70) (\$3,084.70) \$3,084.70	Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user hathak1 overridding Payment Estimate Exception 7 on the current	
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material	- Total	4 5 6	2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,084.70) \$3,084.70 (\$3,084.70) (\$3,084.70) \$3,084.70 (\$3,084.70)	Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user hathak1 overridding Payment Estimate Exception 7 on the current	



Line	Description	Adjustersent	Other	Est.	Created	Created	Amenumt	Demesice
Line	Description	Adjustment Type	Adjustment Type	Number	Date	By	Amount	Remarks
0140	MaterialCredit - Total						\$3,084.70	
		Other Item Adjustment	MDPA	5	Jun 2, 2020	hathak1	\$3,084.70	Inspector needs to enter material report for this item.
				6	Jun 16, 2020	wilsor2	(\$3,084.70)	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.
			MDPA - Tot	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0140 -	Total						\$0.00	
0150	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Overrun	Overrun	4	May 18, 2020	SYSTEM	(\$7,839.10)	
			Overrun - T	otal			(\$7,839.10)	
	Overrun - Total						(\$7,839.10)	
0150 -	Total						(\$7,839.10)	
0170	CONSTRUCTION SIGNS	Material		4	May 18, 2020	SYSTEM	(\$3,357.00)	
				4	May 18, 2020	SYSTEM	\$3,357.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$3,357.00)	
				6	Jun 16, 2020	SYSTEM	(\$3,357.00)	
				6	Jun 16, 2020	SYSTEM	\$3,357.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user hathak1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				(\$3,357.00)	
	Material - Total						(\$3,357.00)	
	CONSTRUCTION SIGNS	MaterialCredit		6	Jun 16, 2020	SYSTEM	\$3,357.00	
			- Total				\$3,357.00	
	MaterialCredit - Total					\$3,357.00		
	CONSTRUCTION SIGNS	Other Item Adjustment	MDPA	5	Jun 2, 2020	hathak1	\$3,357.00	Inspector needs to enter material report for this item.
				6	Jun 16, 2020	wilsor2	(\$3,357.00)	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.
	MDPA - Total						\$0.00	
	Other Item Adjustment - Total						\$0.00	
0170 -	Total						\$0.00	
0180	FLAG ASSEMBLY	Material		4	May 18, 2020	SYSTEM	(\$300.00)	
				4	May 18, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hathak1
								overridding Payment Estimate Exception 7 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$300.00)	overridding Payment Estimate Exception 7 on the current
				5		SYSTEM SYSTEM	(\$300.00)	overridding Payment Estimate Exception 7 on the current
					2020 Jun 16,		, ,	overridding Payment Estimate Exception 7 on the current
			- Total	6	2020 Jun 16, 2020 Jun 16,	SYSTEM	(\$300.00)	overridding Payment Estimate Exception 7 on the current Payment Estimate.
	Material - Total		- Total	6	2020 Jun 16, 2020 Jun 16,	SYSTEM	(\$300.00)	overridding Payment Estimate Exception 7 on the current Payment Estimate.
	Material - Total FLAG ASSEMBLY	MaterialCredit	- Total	6	2020 Jun 16, 2020 Jun 16,	SYSTEM	(\$300.00) \$300.00 (\$300.00)	overridding Payment Estimate Exception 7 on the current Payment Estimate.
		MaterialCredit	- Total	6	2020 Jun 16, 2020 Jun 16, 2020 Jun 16,	SYSTEM SYSTEM	(\$300.00) \$300.00 (\$300.00) (\$300.00)	overridding Payment Estimate Exception 7 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0180		Other Item Adjustment	MDPA	5	Jun 2, 2020	hathak1	\$300.00	Inspector needs to enter material report for this item.
				6	Jun 16, 2020	wilsor2	(\$300.00)	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.
			MDPA - Tot	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0180 -	- Total						\$0.00	
0190	CHANNELIZER (TRIM LINE)	Material		4	May 18, 2020	SYSTEM	(\$1,956.00)	
				4	May 18, 2020	SYSTEM	\$1,956.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$1,956.00)	
				6	Jun 16, 2020	SYSTEM	(\$1,956.00)	
				6	Jun 16, 2020	SYSTEM	\$1,956.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user hathak1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				(\$1,956.00)	
	Material - Total						(\$1,956.00)	
	CHANNELIZER (TRIM LINE)	MaterialCredit		6	Jun 16, 2020	SYSTEM	\$1,956.00	
			- Total				\$1,956.00	
	MaterialCredit - Total						\$1,956.00	
	CHANNELIZER (TRIM LINE) Other Item Adjustment		MDPA	5	Jun 2, 2020	hathak1	\$1,956.00	Inspector needs to enter material report for this item.
				6	Jun 16, 2020	wilsor2	(\$1,956.00)	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.
			MDPA - Tot	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0190 -	- Total						\$0.00	
0200	CHANGEABLE MESSAGE SIGN Material WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		4	May 18, 2020		(\$5,000.00)	
				4	May 18, 2020	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$5,000.00)	
				6	Jun 16, 2020	SYSTEM	(\$5,000.00)	
				6	Jun 16, 2020	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user hathak1 overridding Payment Estimate Exception 12 on the current
								Payment Estimate.
			- Total				(\$5,000.00)	Payment Estimate.
	Material - Total		- Total				(\$5,000.00) (\$5,000.00)	Payment Estimate.
	Material - Total CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit	- Total	6	Jun 16, 2020	SYSTEM		Payment Estimate.
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	MaterialCredit	- Total	6		SYSTEM	(\$5,000.00)	Payment Estimate.
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	MaterialCredit		6		SYSTEM	(\$5,000.00) \$5,000.00	Payment Estimate.
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED MaterialCredit - Total CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	MaterialCredit Other Item Adjustment				SYSTEM hathak1	(\$5,000.00) \$5,000.00 \$5,000.00	Payment Estimate.
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED MaterialCredit - Total CHANGEABLE MESSAGE SIGN	Other Item	- Total		2020 Jun 2,		(\$5,000.00) \$5,000.00 \$5,000.00 \$5,000.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0200	Other Item Adjustment - Total						\$0.00	
0200 -	- Total						\$0.00	
0220	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		6	Jun 16, 2020	SYSTEM	(\$1,023.00)	
				6	Jun 16, 2020	SYSTEM	\$1,023.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user hathak1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Other Item Adjustment	OVRN	6	Jun 16, 2020	wilsor2	(\$279.00)	Pay to PQ
		OVRN - Tot	al			(\$279.00)		
	Other Item Adjustment - Total						(\$279.00)	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Overrun	Overrun	6	Jun 16, 2020	SYSTEM	\$279.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) overridding Payment Estimate Exception 21 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$279.00)	
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0220 -	- Total						(\$279.00)	
0230	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		6	Jun 16, 2020	SYSTEM	(\$5,856.20)	
				6	Jun 16, 2020	SYSTEM	\$5,856.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user hathak1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0230 -	- Total						\$0.00	
0240	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		6	Jun 16, 2020	SYSTEM	(\$12,596.00)	
				6	Jun 16, 2020	SYSTEM	\$12,596.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user hathak1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0240	- Total						\$0.00	
0290	MGS GUARDRAIL	L Construction Stockpile		1	Apr 2, 2020	SYSTEM	\$15,841.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$15,841.50	
	Construction Stockpile - Total						\$15,841.50	
0290	- Total						\$15,841.50	
0300	MGS HEIGHT AND BLOCK TRANSITION	Construction		1	Apr 2, 2020	SYSTEM	\$2,224.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		Stockpile						
		Stockpile	- Total				\$2,224.00	
	Construction Stockpile - Total	Stockpile	- Total				\$2,224.00	
	- Total		- Total				\$2,224.00 \$2,224.00	
0300 - 0310	· ·	Stockpile Construction Stockpile		1	Apr 2, 2020	SYSTEM	\$2,224.00 \$2,224.00 \$12,248.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	Total TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction	- Total	1		SYSTEM	\$2,224.00 \$2,224.00 \$12,248.00 \$12,248.00	
0310	Total TYPE A CRASHWORTHY END TERMINAL (MASH) Construction Stockpile - Total	Construction		1		SYSTEM	\$2,224.00 \$2,224.00 \$12,248.00 \$12,248.00 \$12,248.00	
0310 0310 -	Total TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction		1		SYSTEM	\$2,224.00 \$2,224.00 \$12,248.00 \$12,248.00	