

Pay Estimate Created Date: July 15, 2020

Progress Estimate Number 3		Contract ID Prime Contractor	191213-C09 Ideker, Inc.	Pay Period Start Pay Period End	July 1, 2020 July 15, 2020	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,233,592.84 \$0.00 \$1,233,592.84		
Approval Date									
July 16, 2020		Ger	nerated and App	proved (and should b	oe considered Dr	raft) at the Project Office Level by	scarpm1		
July 16, 2020		Reviewe	ed and Approve	ed (and should be co	nsidered Draft) a	at the Resident Engineer Level by	karlic1		
July 17, 2020	Reviewed and Approved at the Central Office Controllers Office Level by								

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete				
November 1, 2020	November 1, 2020		119.38%				

Contract Informational Dates

Date Description	Original Completion Date	Current Completion Date
Acceptance Date		
Awarded Date	January 9, 2020	January 9, 2020
Letting Date	December 13, 2019	December 13, 2019
Notice to Proceed Date	February 10, 2020	February 10, 2020
Open to Traffic Date		
Work Began Date	June 15, 2020	June 15, 2020

Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
Milestone - Calendar Time - J4S3254 - Calendar Days - 38 Days JSP B 2.1	July 23, 2020	July 23, 2020	7	
Milestone - Calendar Time - J4S3336 - Calendar Days - 36 Days JSP B 2.1	July 21, 2020	July 21, 2020	5	
Milestone - Completion Date - J4S3254	November 1, 2020	November 1, 2020	108	
Milestone - Completion Date - J4S3336	November 1, 2020	November 1, 2020	108	

Milestones

Contract Total Pay For Estimate No. 3

191213-C09	
	Total Posted Items Pay
	Gross Item Adjustments
	Incentive
	Disincentive
	Liquidated Damage
	Other Contract Adjustments

This Estimate	Previous	To Date
\$67,797.32	\$1,404,893.16	\$1,472,690.48
(\$27,840.56)	(\$362,432.65)	(\$390,273.21)
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
	\$1,042,460.51	\$1,082,417.27

Contract Total Payable This Estimate: \$39,956.76

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4S3254	0010	1099901	MISC.ELECTRONIC TICKETING	LS	\$1,000.000	0.75	\$750.00
	0160	6191000	PAVEMENT EDGE TREATMENT	LF	\$1.050	445	\$467.25
Project J4S3	254 - Total						\$1,217.25
I4S3336	0300	2022010	REMOVAL OF IMPROVEMENTS	LS	\$8,390.000	1	\$8,390.00
	0310	2071000	LINEAR GRADING CLASS 1	STA	\$552.000	3.6	\$1,987.20
	0320	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$24.000	338	\$8,112.00
	0330	3049910	MISC.TYPE 1 AGGREGATE FOR BASE (EDGE DROP OFF)	TONS	\$32.200	350.8	\$11,295.76
	0340	4019905	MISC.OPTIONAL PAVEMENT (BUS STOP)	SQYD	\$98.000	337.7	\$33,094.60
	0350	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$64.480	57.39	\$3,700.51
Project J4S3	336 - Total						\$66,580.07

Contract Adjustments This Estimate

Overall - Total

\$67,797.32



Pay Estimate Created Date: July 15, 2020

Progress Estimate Number
3
Contract ID Prime Contractor Ideker, Inc. Pay Period Start Pay Period End July 1, 2020 Original Contract Amount Net Change Order Amount Current Contract Amount S1,233,592.84

Project	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
lumber	No.	item Bescription	Туре	Adjustment Type	Comments	Quantity	Adjustment Unit Price	amount
4S3254	0030	TACK COAT	Material			-1,967	\$2.50	(\$4,917.50
	0030	TACK COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0060) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	1,967	\$2.50	\$4,917.50
	0050	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0024) overridding Payment Estimate Exception 25 on the current Payment Estimate.	28	\$1,500.00	\$42,000.00
	0050	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-28	\$1,500.00	(\$42,000.00)
	0050	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-44	\$1,500.00	(\$66,000.00)
	0050	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0025) due to user scarpm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	44	\$1,500.00	\$66,000.00
	0090	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0027) overridding Payment Estimate Exception 27 on the current Payment Estimate.	17	\$9.00	\$153.00
	0090	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-17	\$9.00	(\$153.00)
	0090	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-57	\$9.00	(\$513.00)
	0090	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0028) due to user scarpm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	57	\$9.00	\$513.00
	0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-20	\$4.00	(\$80.00)
	0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	Other Item Adjustment	Overrun	Line item adjustment to payback the amount withheld on pervious adjustment over plan quantity. Material exception resolved. 20 LF at \$4.00 per LF = \$80.00			\$80.00
	0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN YELLOW	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-39	\$4.00	(\$156.00)
	0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN YELLOW	Other Item Adjustment	Overrun	Line item adjustment to payback the amount withheld on pervious adjustment over plan quantity. Material exception resolved. 39 LF at \$4.00 per LF = \$156.00			\$156.00
	0190	PREFORMED	Overrun		Averaged Price Adjustment from this item on	-211	\$14.00	(\$2,954.00)

Revision 4/1/2020 Page 2 of 22



Pay Estimate Created Date: July 15, 2020

Prog	gress E				191213-C09 Ideker, Inc.	Pay Period Start Pay Period End	July 1, 2020 July 15, 2020	Net Chan	Contract Amo ge Order Amo contract Amo	ount \$0.	233,592.84 00 233,592.84
Project Number	Line No.	Item Description		Adjustment Type	Other Item Adjustment Type	С	omments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3254		THERMOPLAS PAVEMENT MARKING IN. WI	G, 24			all previous payme		0.00000' is non-zero).			
	0190	PREFORI THERMOPLAS PAVEMENT MARKING IN. WI	STIC G, 24	Other Item Adjustment	Overrun	quantity. Material	rvious adjustmen	t over plan ed. 211 LF			\$2,954.00
	0220	4 IN. WHITE STAND, WATERBORNE PAVEM MARKING PAINT, TYP BE	IENT	Material					-25,362	\$0.06	(\$1,521.72)
	0220	4 IN. WHITE STAND. WATERBORNE PAVEM MARKING PAINT, TYP BE	IENT	Material		Adjustment (overridding Payn	run Payment Est (0061) due to use	imate Item er scarpm1 ception 16	25,362	\$0.06	\$1,521.72
	0230	4 IN. YELLOW STAND, WATERBORNE PAVEM MARKING PAINT, TYP BE	IENT	Material					-11,730	\$0.06	(\$703.80)
	0230	4 IN. YELLOW STAND, WATERBORNE PAVEM MARKING PAINT, TYP BE.	IENT	Material		Adjustment (overridding Payn	run Payment Est (0062) due to use	imate Item er scarpm1 cception 22	11,730	\$0.06	\$703.80
	0310	LINEAR GRADING CLASS 1		Overrun					-0.3	\$552.00	(\$165.60)
	0320	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)		Price			tem Price Adjusti ment Type appli		338	(\$0.11)	(\$38.53)
	0320	TYPE 1 AGGREGATE BASE (4 IN. TH		Overrun			run Payment Est 0036) overriddin	imate Item g Payment	193	\$23.89	\$4,610.00
	0320	TYPE 1 AGGREGATE BASE (4 IN. TH		Overrun			tem Price Adjusti ment Type appli		-193	\$23.89	(\$4,610.00)
	0320	TYPE 1 AGGREGATE BASE (4 IN. TH		Material					-338	\$24.00	(\$8,112.00)
	0320	TYPE 1 AGGREGATE BASE (4 IN. TH		Material		overridding Payme	run Payment Est (0037) due to use	imate Item er scarpm1 eption 1 on	338	\$24.00	\$8,112.00
	0320	TYPE 1 AGGREGATE BASE (4 IN. TH		Other Item Adjustment	Overrun	Line Item adjustn	over pla QYD at \$24.00 p	n quantity.			(\$4,632.00)
	0330	M	IISC.	Material					-350.8	\$32.20	(\$11,295.76)
	0330	М	IISC.	Material		Adjustment (overridding Payme	run Payment Est (0063) due to use	imate Item er scarpm1 eption 2 on	350.8	\$32.20	\$11,295.76
	0340	MISC.		Overrun			run Payment Est 0039) overriddin	imate Item g Payment	192.7	\$98.00	\$18,884.60
	0340	M	IISC.	Overrun					-192.7	\$98.00	(\$18,884.60)
	0340	M	IISC.	Material					-337.7	\$98.00	(\$33,094.60)

Revision 4/1/2020 Page 3 of 22



Pay Estimate Created Date: July 15, 2020

Prog	Progress Estimate Number Contract Prime C				191213-C09 Ideker, Inc.	Pay Period Start Pay Period End	July 1, 2020 July 15, 2020	Net Chan	Contract Amo ge Order Am ontract Amo	ount \$0.	233,592.84 00 233,592.84
Project Number	Line No.	Item Description	on	Adjustment Type	Other Item Adjustment Type	Comments			Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3336	0340	MISC		Material		Adjustment overridding Payme	run Payment Es (0040) due to use	timate Item er scarpm1 eption 3 on	337.7	\$98.00	\$33,094.60
	0340		MISC.	Other Item Adjustment	Overrun	Line Item adjustn	over pla QYD at \$98.00 p	an quantity.			(\$18,884.60)
	0340			Other Item Adjustment	Fuel Price		= 8 IN Concrete installed between	Pavement			(\$153.99)
	0350	BITUMINOUS PA MIXTURE (SURFACE LE	PG64-22	Price			tem Price Adjust ment Type appli		57.39	(\$2.52)	(\$144.81)
	0350	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) BITUMINOUS PAVEMENT		Overrun			run Payment És (0043) overriddin	timate Item g Payment	57.39	\$61.96	\$3,555.70
	0350	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		Overrun			run Payment És (0044) overriddin	timate Item g Payment	483.61	\$61.09	\$29,545.48
	0350	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		Overrun		Reference Item Price Adjustment Index Adjustment Type applied is FUEL			-57.39	\$61.96	(\$3,555.70)
	0350	BITUMINOUS PA MIXTURE (SURFACE LE	PG64-22	Overrun		Averaged Price A all previous payme	nt estimates of '-		-483.61	\$61.09	(\$29,545.48)
	0350	BITUMINOUS PA MIXTURE (SURFACE LE	PG64-22	Material					-4,894.5	\$64.48	(\$315,597.36)
	0350	BITUMINOUS PA MIXTURE (SURFACE LE	PG64-22	Material		Adjustment overridding Payme	run Payment És (0045) due to us	timate Item er scarpm1 eption 6 on	4,894.5	\$64.48	\$315,597.36
	0350	BITUMINOUS PA MIXTURE (SURFACE LE	PG64-22	Other Item Adjustment	Overrun	Line Item adjustn 57.39 Tons at \$6	over pla	an quantity.			(\$3,700.51)
	0350	BITUMINOUS PA' MIXTURE (SURFACE LE	PG64-22	Other Item Adjustment	Asphalt Cement Price Adjustment	AC adjustments 57.39 tons placed		ŠL 18-7.			(\$120.52)
	0360	TAC	CK COAT	Overrun			run Payment Es (0047) overriddin	timate Item g Payment	656	\$2.50	\$1,640.00
	0360	TAC	CK COAT	Overrun		Averaged Price A all previous payme	ent estimates of '		-656	\$2.50	(\$1,640.00)
	0360	TAC	CK COAT	Material					-5,686	\$2.50	(\$14,215.00)
	0360	TAC	CK COAT	Material			run Payment Es (0048) due to us	timate Item er scarpm1	5,686	\$2.50	\$14,215.00

Revision 4/1/2020 Page 4 of 22



Pay Estimate Created Date: July 15, 2020

Prog	gress E	stimate Number 3		Contract ID 191213-C Prime Contractor Ideker, Inc		Pay Period End July 15, 2020 Net Char			Contract Amo ge Order Amo contract Amo	ount \$0.	\$1,233,592.84 \$0.00 \$1,233,592.84	
Project umber	Line No.	Item Descript	tion	Adjustment Type	Other Item Adjustment Type	C	omments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
S3336						the	current Paymer	t Estimate.				
	0380	FURNISHING AND CONCRETE MATE FULL DEPTH PA	RIAL FOR	Overrun			run Payment Es 0050) overriddin	timate Item g Payment	22	\$1,500.00	\$33,000.00	
	0380	FURNISHING AND CONCRETE MATE FULL DEPTH PA	RIAL FOR	Overrun		Averaged Price A all previous payme	ent estimates of '		-22	\$1,500.00	(\$33,000.00	
	0380	FURNISHING AND CONCRETE MATE FULL DEPTH PA	RIAL FOR	Material					-30	\$1,500.00	(\$45,000.00	
	0380	FURNISHING AND CONCRETE MATE FULL DEPTH PA	RIAL FOR	Material		overridding Payr	run Payment Es (0051) due to us	timate Item er scarpm1 cception 11	30	\$1,500.00	\$45,000.00	
	0420	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR		Overrun			run Payment Es 0053) overriddin	timate Item g Payment	23	\$9.00	\$207.00	
	0420	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR		Overrun		Averaged Price A all previous payme	ent estimates of		-23	\$9.00	(\$207.00	
	0420	DOWEL BAR (FUR AND INSTALLAT BASKETS) F DEPTH PAVEMEN	ION WITH	Material					-47	\$9.00	(\$423.00	
	0420	DOWEL BAR (FUF AND INSTALLAT BASKETS) F DEPTH PAVEMEN	ION WITH FOR FULL	Material		Adjustment (overridding Payr	run Payment Es (0054) due to us	timate Item er scarpm1 (ception 14	47	\$9.00	\$423.00	
	0520	THERMO PAVEMENT MAR	FORMED OPLASTIC RKING, 24 YELLOW	Overrun		Averaged Price A all previous payme	ent estimates of '		-125	\$14.00	(\$1,750.00	
	0520	THERMO PAVEMENT MAR	FORMED OPLASTIC RKING, 24 YELLOW	Other Item Adjustment	Overrun	quantity. Material	rvious adjustmer	nt over plan red. 125 LF			\$1,750.00	
	0550	4 IN. WHITE ST WATERBORNE PA MARKING PAIN	AVEMENT	Overrun		This adjustment generated Over Adjustment (Estimate Exception	run Payment Es 0030) overriddin	timate Item g Payment	1,121	\$0.07	\$78.47	
	0550	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS		Overrun		Averaged Price A all previous payme	ent estimates of		-1,121	\$0.07	(\$78.47	
	0550 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS		Material					-27,721	\$0.07	(\$1,940.47		
	0550	4 IN. WHITE ST WATERBORNE PA		Material		This adjustment generated Over			27,721	\$0.07	\$1,940.47	

Revision 4/1/2020 Page 5 of 22



Pay Estimate Created Date: July 15, 2020

Prog	Progress Estimate Number 3 Contra Prime				191213-C09 Ideker, Inc.	Pay Period Start Pay Period End	Contract Amo ge Order Am contract Amo	233,592.84 00 233,592.84			
Project Number	Line No.	Item Descripti	on	Adjustment Type	Other Item Adjustment Type	Comments			Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3336		MARKING PAINT	TYPE P BEADS			Adjustment (0031) due to user scarpm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.					
	0560	4 IN. YELLOW ST. WATERBORNE PA MARKING PAINT	VEMENT	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0033) overridding Payment Estimate Exception 33 on the current Payment Estimate.			462	\$0.07	\$32.34
	0560	4 IN. YELLOW ST. WATERBORNE PA MARKING PAINT	VEMENT	Overrun		Averaged Price A all previous paymo	ent estimates of '		-462	\$0.07	(\$32.34)
	0560	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE F BEADS		Material					-14,021	\$0.07	(\$981.47)
	0560	4 IN. YELLOW ST. WATERBORNE PA MARKING PAINT	Material		generated Over Adjustment overridding Payr	offsets the originarun Payment Esi (0034) due to usi ment Estimate Ex current Paymen	timate Item er scarpm1 (ception 20	14,021	\$0.07	\$981.47	
Total											(\$27,840.56)

Revision 4/1/2020 Page 6 of 22



					Con	ntract Project Information	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4S3254	FAS S302(77)	Resurface	9	PLATTE	from Barry Road to Route 45		
J4S3336	FAS S302(84)	Resurface	Prairie View	PLATTE	from Route 9 to 56th Street		
Γotals by .	Job Numbe	rs					
J4S3254		d Item Pay Item Adjustm		Item Pay	This Estimate \$1,217.25 \$0.00 \$1,217.25	Previous \$744,885.55 (\$135,526.08) \$609,359.47	To Date \$746,102.80 (\$135,526.08) \$610,576.72
	Liquid	tive centive lated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J4S3336		d Item Pay Item Adjustm		item Pay	This Estimate \$66,580.07 (\$27,840.56) \$38,739.51	Previous \$660,007.61 (\$226,906.57) \$433,101.04	To Date \$726,587.68 (\$254,747.13) \$471,840.55
	Liquid	tive centive dated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 7 of 22



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 3040143, Project Item Line Number 0320, Material Set 304014396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 3049910, Project Item Line Number 0330, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 4019905, Project Item Line Number 0340, Material Set 401990596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 4019905, Project Item Line Number 0340, Material Set 401990596, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 4019905, Project Item Line Number 0340, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 4020520, Project Item Line Number 0350, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 4071005, Project Item Line Number 0360, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3254, Item 4071005, Project Item Line Number 0030, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3254, Item 6131010, Project Item Line Number 0050, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3254, Item 6131010, Project Item Line Number 0050, Material Set 613101096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 6131010, Project Item Line Number 0380, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 6131010, Project Item Line Number 0380, Material Set 613101096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3254, Item 6131015, Project Item Line Number 0090, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 6131017, Project Item Line Number 0420, Material Set 613101796, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 6131017, Project Item Line Number 0420, Material Set 613101796, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3254, Item 6206000C, Project Item Line Number 0220, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3254, Item 6206000C, Project Item Line Number 0220, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 6206000C, Project Item Line Number 0550, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 6206000C, Project Item Line Number 0550, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 6206001C, Project Item Line Number 0560, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3336, Item 6206001C, Project Item Line Number 0560, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3254, Item 6206001C, Project Item Line Number 0230, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3254, Item 6206001C, Project Item Line Number 0230, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3254, Project Item Line Number 0020, Contract Line Item Number 0020, Item 4011209, Minor Item.	No Remark was entered by Engineer	scarpm1	Acknowledged

Revision 4/1/2020 Page 8 of 22



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3254, Project Item Line Number 0050, Contract Line Item Number 0050, Item 6131010, Minor Item.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3254, Project Item Line Number 0080, Contract Line Item Number 0080, Item 6131014, Minor Item.	No Remark was entered by Engineer	scarpm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3254, Project Item Line Number 0090, Contract Line Item Number 0090, Item 6131015, Minor Item.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3254, Project Item Line Number 0170, Contract Line Item Number 0170, Item 6200003, Minor Item.	No Remark was entered by Engineer	scarpm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3254, Project Item Line Number 0180, Contract Line Item Number 0180, Item 6200006, Minor Item.	No Remark was entered by Engineer	scarpm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3254, Project Item Line Number 0190, Contract Line Item Number 0190, Item 6200015, Minor Item.	No Remark was entered by Engineer	scarpm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3254, Project Item Line Number 0280, Contract Line Item Number 0280, Item 6224010, Minor Item.	No Remark was entered by Engineer	scarpm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3336, Project Item Line Number 0550, Contract Line Item Number 0550, Item 6206000C, Minor Item.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3336, Project Item Line Number 0560, Contract Line Item Number 0560, Item 6206001C, Minor Item.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3336, Project Item Line Number 0310, Contract Line Item Number 0310, Item 2071000, Minor Item.	No Remark was entered by Engineer	scarpm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3336, Project Item Line Number 0320, Contract Line Item Number 0320, Item 3040143, Minor Item.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3336, Project Item Line Number 0340, Contract Line Item Number 0340, Item 4019905, Minor Item.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3336, Project Item Line Number 0350, Contract Line Item Number 0350, Item 4020520, Minor Item.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3336, Project Item Line Number 0360, Contract Line Item Number 0360, Item 4071005, Minor Item.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3336, Project Item Line Number 0380, Contract Line Item Number 0380, Item 6131010, Minor Item.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3336, Project Item Line Number 0410, Contract Line Item Number 0410, Item 6131014, Minor Item.	No Remark was entered by Engineer	scarpm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3336, Project Item Line Number 0420, Item 6131017, Minor Item.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3336, Project Item Line Number 0440, Contract Line Item Number 0440, Item 6133019, Minor Item.	No Remark was entered by Engineer	scarpm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-C09, Contract Project J4S3336, Project Item Line Number 0520, Contract Line Item Number 0520, Item 6200018, Minor Item.	No Remark was entered by Engineer	scarpm1	Acknowledged

Revision 4/1/2020 Page 9 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ract TRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
09	J4S3254	0001	0010	1099901	MISC.ELECTRONIC TICKETING	1.00	0.00	1.00	LS	0.75	\$1,000.00	\$750.00
		0001	0020	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	7,367.50	0.00	7,367.50	TONS	7,953.67	\$58.39	\$464,414.79
		0001	0030	4071005	TACK COAT	6,367.00	0.00	6,367.00	GAL	1,967.00	\$2.50	\$4,917.50
		0001	0040	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	1.00	\$550.00	\$550.00
		0001	0050	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	16.00	0.00	16.00	SQYD	44.00	\$1,500.00	\$66,000.00
		0001	0060	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	2.00	0.00	2.00	SQYD	0.00	\$2.00	\$0.00
		0001	0070	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	2.00	0.00	2.00	SQYD	0.00	\$2.00	\$0.00
		0001	0080	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	72.00	0.00	72.00	LF	198.00	\$5.00	\$990.00
		0001	0090	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	40.00	0.00	40.00	EA	57.00	\$9.00	\$513.00
		0001	0100	6161005	CONSTRUCTION SIGNS	2,397.00	0.00	2,397.00	SQFT	1,697.00	\$1.00	\$1,697.00
		0001	0110	6161009	FLAG ASSEMBLY	32.00	0.00	32.00	EA	8.00	\$25.00	\$200.00
		0001	0120	6161025	CHANNELIZER (TRIM LINE)	250.00	0.00	250.00	EA	163.00	\$1.00	\$163.00
		0001	0130	6161040	FLASHING ARROW PANEL	1.00	0.00	1.00	EA	1.00	\$300.00	\$300.00
		0001	0140	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	3.00	0.00	3.00	EA	3.00	\$2,500.00	\$7,500.00
		0001	0150	6181000	RETAINED MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$81,901.44	\$81,901.44
		0001	0160	6191000	PAVEMENT EDGE TREATMENT	4,784.00	0.00	4,784.00	LF	445.00	\$1.05	\$467.25
					PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN.,	78.00	0.00	78.00	LF	98.00	\$4.00	\$392.00
		0001	0180	6200006	WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN	47.00	0.00	47.00	LF	86.00	\$4.00	\$344.00
		0001	0190	6200015	YELLOW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	167.00	0.00	167.00	LF	378.00	\$14.00	\$5,292.00
		0001	0200	6200021	WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING,	21.00	0.00	21.00	EA	18.00	\$180.00	\$3,240.00
		0001	0210	6200036	LEFT/RIGHT ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN	18.00	0.00	18.00	EA	17.00	\$125.00	\$2,125.00
		0001	0220	6206000C	WHITE MIDBLOCK 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	32,255.00	0.00	32,255.00	LF	25,362.00	\$0.06	\$1,521.72
		0001	0230	6206001C	PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	15,365.00	0.00	15,365.00	LF	11,730.00	\$0.06	\$703.80
		0001	0240	6206124A	MARKING PAINT, TYPE P BEADS 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	222.00	0.00	222.00	LF	0.00	\$2.00	\$0.00
		0001	0250	6206125A	PAINT, TYPE P BEADS 24 IN. YELLOW STANDARD WATERBORNE PAVEMENT	455.00	0.00	455.00	LF	0.00	\$2.00	\$0.00
		0001	0260	6221001	MARKING PAINT, TYPE P BEADS COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	4,876.00	0.00	4,876.00	SQYD	3,520.00	\$4.09	\$14,396.80
		0001	0270	6221003	SURFACING (3 IN. THICK OR LESS) COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	8,727.00	0.00	8,727.00	SQYD	8,727.00	\$5.50	\$47,998.50
		0001	0280	6224010	SURFACING (GREATER THAN 3 IN. THICK) MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,433.00	0.00	2,433.00	SQYD	4,466.00	\$7.90	\$35,281.40
		0030	0290	9028500	CABLE, LOOP DETECTOR, IN DUCT	1,960.00	0.00	1,960.00	LF	644.00	\$6.90	\$4,443.60
	Project J4	1S3254 - To	tal Value	Posted to D	ate as of Report Generated Date							\$746,102.80
	J4S3336	0001	0300	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$8,390.00	\$8,390.00
		0001	0310	2071000	LINEAR GRADING CLASS 1	3.30	0.00	3.30	STA	3.60	\$552.00	\$1,987.20
		0001	0320	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	145.00	0.00	145.00	SQYD	338.00	\$24.00	\$8,112.00
		0001	0330	3049910	MISC.TYPE 1 AGGREGATE FOR BASE (EDGE DROP OFF)	1,097.60	0.00	1,097.60	TONS	350.80	\$32.20	\$11,295.76
		0001	0340	4019905	MISC.OPTIONAL PAVEMENT (BUS STOP)	145.00	0.00	145.00	SQYD	337.70	\$98.00	\$33,094.60
		0001	0350	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	4,353.50	0.00	4,353.50	TONS	4,894.50	\$64.48	\$315,597.36
		0001	0360	4071005	TACK COAT	5,030.00	0.00	5,030.00	GAL	5,686.00	\$2.50	\$14,215.00
		0001	0370	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	1.00	\$500.00	\$500.00
		0001	0380	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	8.00	0.00	8.00	SQYD	30.00	\$1,500.00	\$45,000.00
		0001	0390	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	1.00	0.00	1.00	SQYD	0.00	\$2.00	\$0.00
		0001	0400	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)	1.00	0.00	1.00	SQYD	0.00	\$2.00	\$0.00

Revision 4/1/2020 Page 10 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
91213-C09	J4S3336	0001	0410	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	30.00	0.00	30.00	LF	144.00	\$5.00	\$720.00
		0001	0420	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	24.00	0.00	24.00	EA	47.00	\$9.00	\$423.00
		0001	0430	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	72.00	0.00	72.00	TONS	42.70	\$81.95	\$3,499.26
		0001	0440	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	12.00	0.00	12.00	SQYD	181.90	\$781.72	\$142,194.87
		0001	0450	6161005	CONSTRUCTION SIGNS	1,615.00	0.00	1,615.00	SQFT	1,194.00	\$1.00	\$1,194.00
		0001	0460	6161009	FLAG ASSEMBLY	19.00	0.00	19.00	EA	8.00	\$50.00	\$400.00
		0001	0470	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	60.00	\$1.00	\$60.00
		0001	0480	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,300.00	\$6,600.00
		0001	0490	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$93,556.04	\$93,556.04
		0001	0500	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	879.00	0.00	879.00	LF	0.00	\$3.00	\$0.00
		0001	0510	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	141.00	0.00	141.00	LF	134.00	\$14.00	\$1,876.00
		0001	0520	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	154.00	0.00	154.00	LF	279.00	\$14.00	\$3,906.0
		0001	0530	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	11.00	0.00	11.00	EA	7.00	\$180.00	\$1,260.00
		0001	0540	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	19.00	0.00	19.00	EA	17.00	\$125.00	\$2,125.00
		0001	0550	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	26,600.00	0.00	26,600.00	LF	27,721.00	\$0.07	\$1,940.4
		0001	0560	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	13,559.00	0.00	13,559.00	LF	14,021.00	\$0.07	\$981.47
		0001	0570	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	378.00	0.00	378.00	SQYD	0.00	\$30.36	\$0.0
		0001	0580	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,972.00	0.00	2,972.00	SQYD	2,972.00	\$7.72	\$22,943.8
		0030	0590	9028500	CABLE, LOOP DETECTOR, IN DUCT	1,680.00	0.00	1,680.00	LF	646.00	\$7.30	\$4,715.8
	Project J	4S3336 - To	tal Value	Posted to D	ate as of Report Generated Date							\$726,587.6
1213-C09 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$1,472,690.4

Revision 4/1/2020 Page 11 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J4S3254

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	1099901	MISC.	7/9/20	7/15/20	0.75		Electronic Ticketing (1-0.25 Electronic Ticketing needs adjusted and additional information added to match the requirements of JSP J = .75)	0.00		3.06		
0160	6191000	PAVEMENT EDGE TREATMENT	7/9/20	7/15/20	445.00		Bus Stop Locations at 80th Terrace Log Mile 0.560 to 0.578, 61st Street Log Mile 4.017 to 4.054, and 56th Street Log Mile 5.002 to 5.036 (7/9&10/20)	0.560		5.036		

Project: J4S3336

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0300	2022010	REMOVAL OF IMPROVEMENTS	7/9/20	7/15/20	1.00	LS	Removal of Improvements for Bus Stop at 61st Street Log Mile 4.017 to 4.054 (7/9/20)	4.017		4.054		
0310	2071000	LINEAR GRADING CLASS 1	7/9/20	7/15/20	3.60	STA	Linear Grading for Bus Stops at 61st Street Log Mile 4.017 to 4.054 and 56th Street Log Mile 5.002 to 5.036 (7/9&10/20)	4.017		5.036		
0320	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	7/9/20	7/15/20	338.00	SQYD	Aggregate Base for Bus Stops at 61st Street Log Mile 4.017 to 4.054 and 56th Street Log Mile 5.002 to 5.036 (7/9&10/20)	4.017		5.036		
0330	3049910	MISC. AGGREGATE FOR BASE	7/9/20	7/15/20	350.80	TONS	Pavement Edge Treatment Prairie View Road Log Mile 1.733 to 5.045, NW Meadowvale Drive Log Mile 0.00 to 0.026, and NW Houston Lake Drive Log Mile 0.009 to 0.190 (7/10&13/20)	1.733		5.045		
0340	4019905	MISC.	7/9/20	7/15/20	337.70	SQYD	Concrete Pavement for Bus Stops at 61st Street Log Mile 4.017 to 4.054 and 56th Street Log Mile 5.002 to 5.036 (7/11/20)	4.017		5.036		
0350	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	7/9/20	7/15/20	-0.02	TONS	Rounding Total	1.760		5.045		
				7/15/20	57.41	TONS	Sub Outs on Side Street Between Rte. 9 and Rte. 45 Log Mile 1.760 to 3.396 (7/10/20)	1.760		3.396		

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 12 of 22



	_					_		_
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	2	Jul 1, 2020	scarpm1	(\$14,316.61)	AC adjustments for BP-1 Mix ID BP1 20-57. 7,953.67 tons placed between 6/16/20 – 6/30/20 = (\$14,316.61)
			ACAD - Tota	al			(\$14,316.61)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)		FUEL	2	Jul 1, 2020	scarpm1	\$0.01	Line item adjustment to payback the amount in difference between system fuel price and price adjustment for fuel index spreadsheet.
			FUEL - Tota	ıl			\$0.01	
	Other Item Adjustment - Total						(\$14,316.60)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	(\$32,241.46)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Overrun - T	otal			(\$32,241.46)	
	Overrun - Total						(\$32,241.46)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Price		2	Jul 1, 2020	SYSTEM	(\$26,934.32)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$26,934.32)	
	Price - Total						(\$26,934.32)	
0020 -	· Total						(\$73,492.38)	
0030	TACK COAT	Material		2	Jul 1, 2020	SYSTEM	(\$4,917.50)	
				2	Jul 1, 2020	SYSTEM	\$4,917.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$4,917.50)	
				3	Jul 15, 2020	SYSTEM	\$4,917.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0060) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0030 -	· Total						\$0.00	
0040	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material		2	Jul 1, 2020	SYSTEM	(\$550.00)	
				2	Jul 1, 2020	SYSTEM	\$550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0040 -	- Total						\$0.00	
0050	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Material		2	Jul 1, 2020	SYSTEM	(\$66,000.00)	
	REPAIR			2	Jul 1, 2020	SYSTEM	\$66,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$66,000.00)	
				3	Jul 15,	SYSTEM	\$66,000.00	This adjustment offsets the original system-generated Overrun
					2020			Payment Estimate Item Adjustment (0025) due to user scarpm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total		2020		\$0.00	overridding Payment Estimate Exception 9 on the current Payment
	Material - Total		- Total		2020		\$0.00 \$0.00	overridding Payment Estimate Exception 9 on the current Payment
	Material - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Other Item Adjustment	- Total		Jul 1, 2020	scarpm1		overridding Payment Estimate Exception 9 on the current Payment
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT			2	Jul 1,	scarpm1	\$0.00	overridding Payment Estimate Exception 9 on the current Payment Estimate. Line Item adjustment to withhold the amount over plan quantity.
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR		OVRN	2	Jul 1,	scarpm1	\$0.00 (\$42,000.00) (\$42,000.00)	overridding Payment Estimate Exception 9 on the current Payment Estimate. Line Item adjustment to withhold the amount over plan quantity.
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT		OVRN	2 al	Jul 1,	scarpm1	\$0.00 (\$42,000.00)	overridding Payment Estimate Exception 9 on the current Payment Estimate. Line Item adjustment to withhold the amount over plan quantity.

Revision 4/1/2020 Page 13 of 22



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050	FURNISHING AND PLACING CONCRETE	Overrun	Overrun					Estimate Exception 35 on the current Payment Estimate.
	MATERIAL FOR FULL DEPTH PAVEMENT REPAIR			3	Jul 15, 2020	SYSTEM	(\$42,000.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Jul 15, 2020	SYSTEM	\$42,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) overridding Payment Estimate Exception 25 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0050 -								
		0	0	0	tot 4	OVOTEM	(\$42,000.00)	
0800	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	(\$630.00)	
			Overrun - T	otal			(\$630.00)	
	Overrun - Total						(\$630.00)	
0080 -	· Total						(\$630.00)	
0090	DOWEL BAR (DRILLING, FURNISHING	Material		2	Jul 1,	SYSTEM	(\$513.00)	
	AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR			2	2020 Jul 1,	SYSTEM	\$513.00	This adjustment offsets the original system-generated Overrun
					2020	OTOTEM	ψο το.σσ	Payment Estimate Item Adjustment (0012) due to user scarpm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$513.00)	
				3	Jul 15, 2020	SYSTEM	\$513.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user scarpm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Other Item Adjustment	OVRN	2	Jul 1, 2020	scarpm1	(\$153.00)	Line Item adjustment to withhold the amount over plan quantity. 17 EA at \$9.00 per EA = (\$153.00)
			OVRN - Tot	al			(\$153.00)	
	Other Item Adjustment - Total						(\$153.00)	
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	(\$153.00)	
	PAVEMENT REPAIR			2	Jul 1, 2020	SYSTEM	\$153.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 37 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$153.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Jul 15, 2020	SYSTEM	\$153.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) overridding Payment Estimate Exception 27 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0090 -	Total						(\$153.00)	
0140	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE,	Material		1	Jun 16, 2020	SYSTEM	(\$7,500.00)	
	CONTRACTOR FURNISHED, CONTRACTOR RETAINED			1	Jun 16, 2020	SYSTEM	\$7,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0140 -	Total						\$0.00	
0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	Material		2	Jul 1, 2020	SYSTEM	(\$392.00)	
				2	Jul 1, 2020	SYSTEM	\$392.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user scarpm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	

Revision 4/1/2020 Page 14 of 22



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	Other Item Adjustment	OVRN	2	Jul 1, 2020	scarpm1	(\$80.00)	Line Item adjustment to withhold the amount over plan quantity. 20 LF at \$4.00 per LF = (\$80.00)
				3	Jul 16, 2020	scarpm1	\$80.00	Line item adjustment to payback the amount withheld on pervious adjustment over plan quantity. Material exception resolved. 20 LF at \$4.00 per LF = \$80.00
			OVRN - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	(\$80.00)	
				2	Jul 1, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 38 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$80.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
			Overrun - T	otal			(\$80.00)	
	Overrun - Total						(\$80.00)	
0170 -	- Total						(\$80.00)	
0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN YELLOW	Material		2	Jul 1, 2020	SYSTEM	(\$344.00)	
				2	Jul 1, 2020	SYSTEM	\$344.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user scarpm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN YELLOW	Other Item Adjustment	OVRN	2	Jul 1, 2020	scarpm1	(\$156.00)	Line Item adjustment to withhold the amount over plan quantity. 39 LF at \$4.00 per LF = (\$156.00)
				3	Jul 16, 2020	scarpm1	\$156.00	Line item adjustment to payback the amount withheld on pervious adjustment over plan quantity. Material exception resolved. 39 LF at \$4.00 per LF = \$156.00
			OVRN - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN YELLOW	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	(\$156.00)	
				2	Jul 1, 2020	SYSTEM	\$156.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) overridding Payment Estimate Exception 39 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$156.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
			Overrun - T	otal			(\$156.00)	
	Overrun - Total						(\$156.00)	
0180 -	- Total						(\$156.00)	
0190	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		2	Jul 1, 2020	SYSTEM	(\$5,292.00)	
				2	Jul 1, 2020	SYSTEM	\$5,292.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user scarpm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
			OVRN	2	Jul 1,	scarpm1	(\$2,954.00)	Line Item adjustment to withhold the amount over plan quantity.
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Other Item Adjustment	OVRIN		2020			211 LF at \$14.00 per LF = (\$2,954.00)
				3	2020 Jul 16, 2020	scarpm1	\$2,954.00	211 LF at \$14.00 per LF = (\$2,954.00) Line item adjustment to payback the amount withheld on pervious adjustment over plan quantity. Material exception resolved. 211 LF at \$14.00 per LF = \$2,954.00
			OVRN - Tota	3	Jul 16,	scarpm1	\$2,954.00 \$0.00	Line item adjustment to payback the amount withheld on pervious adjustment over plan quantity. Material exception resolved. 211 LF
				3	Jul 16,	scarpm1	, ,,,,	Line item adjustment to payback the amount withheld on pervious adjustment over plan quantity. Material exception resolved. 211 LF
	PAVEMENT MARKING, 24 IN. WHITE			3 al	Jul 16,	scarpm1	\$0.00	Line item adjustment to payback the amount withheld on pervious adjustment over plan quantity. Material exception resolved. 211 LF
	PAVEMENT MARKING, 24 IN. WHITE Other Item Adjustment - Total PREFORMED THERMOPLASTIC	Adjustment	OVRN - Tota	3 al	Jul 16, 2020 Jul 1,		\$0.00 \$0.00	Line item adjustment to payback the amount withheld on pervious adjustment over plan quantity. Material exception resolved. 211 LF

Revision 4/1/2020 Page 15 of 22



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0100	DDEFORMED THERMODI ACTIO	Overrun	Туре			_,		antimates of 10 000001 is applied (if you may)
0190	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Overrun	Overrun		2020			estimates of '0.00000' is applied (if non-zero).
			Overrun - T	otal			(\$2,954.00)	
	Overrun - Total						(\$2,954.00)	
0190 -	Total						(\$2,954.00)	
0200	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		2	Jul 1, 2020	SYSTEM	(\$3,240.00)	
	Autow			2	Jul 1, 2020	SYSTEM	\$3,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user scarpm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0200 -	Total						\$0.00	
0210	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material		2	Jul 1, 2020	SYSTEM	(\$2,125.00)	
	MIDDLOOK			2	Jul 1, 2020	SYSTEM	\$2,125.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user scarpm1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0210 -	Total						\$0.00	
0220	PAVEMENT MARKING PAINT, TYPE P	Material		2	Jul 1, 2020	SYSTEM	(\$1,521.72)	
	BEADS			2	Jul 1, 2020	SYSTEM	\$1,521.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user scarpm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$1,521.72)	
				3	Jul 15, 2020	SYSTEM	\$1,521.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0061) due to user scarpm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0220 -	Total						\$0.00	
0230	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		2	Jul 1, 2020	SYSTEM	(\$703.80)	
	BEADS			2	Jul 1, 2020	SYSTEM	\$703.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user scarpm1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$703.80)	
				3	Jul 15, 2020	SYSTEM	\$703.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0062) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0230 -	Total						\$0.00	
0280	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	(\$16,060.70)	
			Overrun - T	otal			(\$16,060.70)	
	Overrun - Total						(\$16,060.70)	
0280 -	Total						(\$16,060.70)	
0290	CABLE, LOOP DETECTOR, IN DUCT	Material		2	Jul 1, 2020	SYSTEM	(\$4,443.60)	
				2	Jul 1, 2020	SYSTEM	\$4,443.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user scarpm1 overridding Payment Estimate Exception 33 on the current Payment Estimate.

Revision 4/1/2020 Page 16 of 22



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0290		Material	- Total				\$0.00	
	Material - Total						\$0.00	
0290 -	- Total						\$0.00	
0310	LINEAR GRADING CLASS 1	Overrun	Overrun	3	Jul 15, 2020	SYSTEM	(\$165.60)	
			Overrun - T	otal			(\$165.60)	
	Overrun - Total						(\$165.60)	
0310 -	- Total						(\$165.60)	
0320	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material		3	Jul 15, 2020	SYSTEM	(\$8,112.00)	
				3	Jul 15, 2020	SYSTEM	\$8,112.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Other Item Adjustment	OVRN	3	Jul 16, 2020	scarpm1	(\$4,632.00)	Line Item adjustment to withhold the amount over plan quantity. 193.0 SQYD at \$24.00 per SQYD = (\$4,632.00)
			OVRN - Tota	al			(\$4,632.00)	
	Other Item Adjustment - Total						(\$4,632.00)	
	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Overrun	Overrun	3	Jul 15, 2020	SYSTEM	(\$4,610.00)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				3	Jul 15, 2020	SYSTEM	\$4,610.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 35 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Price		3	Jul 15, 2020	SYSTEM	(\$38.53)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$38.53)	
	Price - Total						(\$38.53)	
0320 -	- Total						(\$4,670.53)	
0330	MISC. TYPE 1 AGGREGATE FOR BASE (EDGE DROP OFF)	Material		3	Jul 15, 2020	SYSTEM	(\$11,295.76)	
				3	Jul 15, 2020	SYSTEM	\$11,295.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0063) due to user scarpm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0330 -	- Total						\$0.00	
0340	MISC. OPTIONAL PAVEMENT (BUS STOP)	Material		3	Jul 15, 2020	SYSTEM	(\$33,094.60)	
				3	Jul 15, 2020	SYSTEM	\$33,094.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Material - Total MISC. OPTIONAL PAVEMENT (BUS STOP)	Other Item Adjustment	FUEL	3	Jul 16, 2020	scarpm1	\$0.00 (\$153.99)	Fuel adjustment for Misc. Optional Pavement (Bus Stop) = 8 IN Concrete Pavement 337.7 SQYD installed between 7/1/20 – 7/15/20 = (\$153.99)
			FUEL - Tota			scarpm1		Concrete Pavement
				ıl		scarpm1	(\$153.99)	Concrete Pavement 337.7 SQYD installed between 7/1/20 – 7/15/20 = (\$153.99)
	MISC. OPTIONAL PAVEMENT (BUS STOP)		FUEL - Tota	3	2020 Jul 16,		(\$153.99) (\$153.99)	Concrete Pavement 337.7 SQYD installed between 7/1/20 – 7/15/20 = (\$153.99) Line Item adjustment to withhold the amount over plan quantity.
	MISC. OPTIONAL PAVEMENT (BUS STOP)		FUEL - Tota	3	2020 Jul 16,		(\$153.99) (\$153.99) (\$18,884.60) (\$18,884.60)	Concrete Pavement 337.7 SQYD installed between 7/1/20 – 7/15/20 = (\$153.99) Line Item adjustment to withhold the amount over plan quantity.
	MISC. OPTIONAL PAVEMENT (BUS STOP) MISC. OPTIONAL PAVEMENT (BUS STOP)	Adjustment	FUEL - Tota	al	2020 Jul 16,		(\$153.99) (\$153.99) (\$18,884.60)	Concrete Pavement 337.7 SQYD installed between 7/1/20 – 7/15/20 = (\$153.99) Line Item adjustment to withhold the amount over plan quantity.

Revision 4/1/2020 Page 17 of 22



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0340	MISC. OPTIONAL PAVEMENT (BUS STOP)	Overrun	Type		2020	_,		
0340	MISC. OPTIONAL PAVEMENT (BUS STOP)	Overrun			2020		00.00	
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
	- Total						(\$19,038.59)	
0350	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		2	Jul 1, 2020	SYSTEM	(\$311,896.85)	
				2	Jul 1, 2020	SYSTEM	\$311,896.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$315,597.36)	
				3	Jul 15, 2020	SYSTEM	\$315,597.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0045) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	ACAD	2	Jul 1, 2020	scarpm1	(\$9,250.97)	AC adjustments for Surface Leveling Mix ID SL 20-22. 4,837.11 tons placed between 6/16/20 – 6/30/20 = (\$9,250.97)
				3	Jul 16, 2020	scarpm1	(\$120.52)	AC adjustments for Surface Leveling Mix ID SL 18-7. 57.39 tons placed between 7/1/20 – 7/15/20 = (\$120.52)
			ACAD - Tota	al			(\$9,371.49)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		FUEL	2	Jul 1, 2020	scarpm1	\$0.01	Line item adjustment to payback the amount in difference between system fuel price and price adjustment for fuel index spreadsheet.
			FUEL - Tota	ıl			\$0.01	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		OVRN	2	Jul 1, 2020	scarpm1	(\$31,183.17)	Line Item adjustment to withhold the amount over plan quantity. 483.61 Tons at \$64.48 per Ton = (\$31,183.17)
				3	Jul 16, 2020	scarpm1	(\$3,700.51)	Line Item adjustment to withhold the amount over plan quantity. 57.39 Tons at \$64.48 per Ton = (\$3,700.51)
			OVRN - Tota	al			(\$34,883.68)	
	Other Item Adjustment - Total						(\$44,255.16)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	(\$29,545.48)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				2	Jul 1, 2020	SYSTEM	\$29,545.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate.
				3		SYSTEM	\$29,545.48 (\$29,545.48)	Payment Estimate Item Adjustment (0036) overridding Payment
					2020 Jul 15,			Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment
				3	Jul 15, 2020 Jul 15,	SYSTEM	(\$29,545.48)	Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '-3.38640' is applied (if non-zero). Reference Item Price Adjustment Index Adjustment Type applied
				3	Jul 15, 2020 Jul 15, 2020 Jul 15, 2020	SYSTEM SYSTEM	(\$29,545.48) (\$3,555.70)	Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '-3.38640' is applied (if non-zero). Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment
			Overrun - To	3 3 3	Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15,	SYSTEM SYSTEM	(\$29,545.48) (\$3,555.70) \$3,555.70	Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '-3.38640' is applied (if non-zero). Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment
	Overrun - Total		Overrun - To	3 3 3	Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15,	SYSTEM SYSTEM	(\$29,545.48) (\$3,555.70) \$3,555.70 \$29,545.48	Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '-3.38640' is applied (if non-zero). Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment
	Overrun - Total BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price	Overrun - To	3 3 3	Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15,	SYSTEM SYSTEM	(\$29,545.48) (\$3,555.70) \$3,555.70 \$29,545.48	Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '-3.38640' is applied (if non-zero). Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment
	BITUMINOUS PAVEMENT MIXTURE	Price	Overrun - To	3 3 3 3 ootal	2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020	SYSTEM SYSTEM SYSTEM	(\$29,545.48) (\$3,555.70) \$3,555.70 \$29,545.48 \$0.00	Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '-3.38640' is applied (if non-zero). Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 37 on the current Payment Estimate. Reference Item Price Adjustment Index Adjustment Type applied
	BITUMINOUS PAVEMENT MIXTURE	Price	Overrun - To	3 3 3 3 otal	2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$29,545.48) (\$3,555.70) \$3,555.70 \$29,545.48 \$0.00 \$0.00 (\$16,380.40)	Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '-3.38640' is applied (if non-zero). Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 37 on the current Payment Estimate. Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied
	BITUMINOUS PAVEMENT MIXTURE	Price		3 3 3 3 otal	2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$29,545.48) (\$3,555.70) \$3,555.70 \$29,545.48 \$0.00 \$0.00 (\$16,380.40) (\$144.81)	Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '-3.38640' is applied (if non-zero). Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 37 on the current Payment Estimate. Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied
0350	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		3 3 3 3 otal	2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$29,545.48) (\$3,555.70) \$3,555.70 \$29,545.48 \$0.00 \$16,380.40) (\$144.81)	Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '-3.38640' is applied (if non-zero). Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 37 on the current Payment Estimate. Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied
0350 - 0360	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) Price - Total	Price Material		3 3 3 3 otal	2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$29,545.48) (\$3,555.70) \$3,555.70 \$29,545.48 \$0.00 \$0.00 (\$16,380.40) (\$144.81) (\$16,525.21)	Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '-3.38640' is applied (if non-zero). Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 37 on the current Payment Estimate. Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) Price - Total - Total			3 3 3 3 3 otal 2 2 3 3	2020 Jul 15, 2020 Jul 17, 2020 Jul 15, 2020 Jul 15, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$29,545.48) (\$3,555.70) \$3,555.70 \$29,545.48 \$0.00 \$0.00 (\$16,380.40) (\$144.81) (\$16,525.21) (\$60,780.37)	Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 44 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '-3.38640' is applied (if non-zero). Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 37 on the current Payment Estimate. Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied

Revision 4/1/2020 Page 18 of 22



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0360	TACK COAT	Material	, ,,		2020			
				3	Jul 15, 2020	SYSTEM	\$14,215.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0048) due to user scarpm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TACK COAT	Other Item Adjustment	OVRN		Jul 1, 2020	scarpm1	(\$1,640.00)	Line Item adjustment to withhold the amount over plan quantity. 656 Gallons at \$2.50 per Gallon = (\$1,640.00)
			OVRN - Tot	al			(\$1,640.00)	
	Other Item Adjustment - Total						(\$1,640.00)	
	TACK COAT	Overrun	Overrun		Jul 1, 2020	SYSTEM	(\$1,640.00)	
				2	Jul 1, 2020	SYSTEM	\$1,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) overridding Payment Estimate Exception 45 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$1,640.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Jul 15, 2020	SYSTEM	\$1,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0047) overridding Payment Estimate Exception 38 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0360 -	· Total						(\$1,640.00)	
0370	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material		2	Jul 1, 2020	SYSTEM	(\$500.00)	
				2	Jul 1, 2020	SYSTEM	\$500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user scarpm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0370 -	Total						\$0.00	
0380	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material						
		Material		2	Jul 1, 2020	SYSTEM	(\$45,000.00)	
	MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		2		SYSTEM	(\$45,000.00) \$45,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		Material			2020 Jul 1,			Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment
		Material		2	2020 Jul 1, 2020 Jul 15,	SYSTEM	\$45,000.00 (\$45,000.00) \$45,000.00	Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment
	REPAIR	Material	- Total	3	Jul 15, 2020 Jul 15, 2020 Jul 15,	SYSTEM	\$45,000.00 (\$45,000.00) \$45,000.00	Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user scarpm1 overridding Payment Estimate Exception 11 on the current
		Material	- Total	3	Jul 15, 2020 Jul 15, 2020 Jul 15,	SYSTEM	\$45,000.00 (\$45,000.00) \$45,000.00	Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user scarpm1 overridding Payment Estimate Exception 11 on the current
	REPAIR	Other Item Adjustment	- Total OVRN	3 3	Jul 15, 2020 Jul 15, 2020 Jul 15,	SYSTEM	\$45,000.00 (\$45,000.00) \$45,000.00	Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user scarpm1 overridding Payment Estimate Exception 11 on the current
	Material - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Other Item		3 3	2020 Jul 1, 2020 Jul 15, 2020 Jul 15, 2020	SYSTEM SYSTEM	\$45,000.00 (\$45,000.00) \$45,000.00 \$0.00	Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user scarpm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. Line Item adjustment to withhold the amount over plan quantity.
	Material - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Other Item	OVRN	3 3	2020 Jul 1, 2020 Jul 15, 2020 Jul 15, 2020	SYSTEM SYSTEM	\$45,000.00 (\$45,000.00) \$45,000.00 \$0.00 (\$33,000.00)	Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user scarpm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. Line Item adjustment to withhold the amount over plan quantity.
	Material - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR Other Item Adjustment - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Other Item	OVRN	2 3 3	2020 Jul 1, 2020 Jul 15, 2020 Jul 15, 2020	SYSTEM SYSTEM	\$45,000.00 (\$45,000.00) \$45,000.00 \$0.00 (\$33,000.00)	Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user scarpm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. Line Item adjustment to withhold the amount over plan quantity.
	Material - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR Other Item Adjustment - Total FURNISHING AND PLACING CONCRETE	Other Item Adjustment	OVRN - Tot	2 3 3	2020 Jul 1, 2020 Jul 15, 2020 Jul 15, 2020 Jul 11, 2020	SYSTEM SYSTEM SYSTEM scarpm1	\$45,000.00 (\$45,000.00) \$45,000.00 \$0.00 (\$33,000.00) (\$33,000.00)	Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user scarpm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. Line Item adjustment to withhold the amount over plan quantity.
	Material - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR Other Item Adjustment - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Other Item Adjustment	OVRN - Tot	2 3 3 2	Jul 1, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 11, 2020 Jul 1, 2020 Jul 1, 2020	SYSTEM SYSTEM SYSTEM scarpm1	\$45,000.00 (\$45,000.00) \$45,000.00 \$0.00 (\$33,000.00) (\$33,000.00) (\$33,000.00)	Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user scarpm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. Line Item adjustment to withhold the amount over plan quantity. 22.0 SQYD at \$1,500.00 per SQYD = (\$33,000.00)
	Material - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR Other Item Adjustment - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Other Item Adjustment	OVRN - Tot	2 3 3 2 2 2	Jul 1, 2020 Jul 1, 2020 Jul 15, 2020 Jul 11, 2020 Jul 11, 2020 Jul 11, 2020 Jul 15, 3020	SYSTEM SYSTEM scarpm1 SYSTEM SYSTEM	\$45,000.00 (\$45,000.00) \$45,000.00 \$0.00 \$0.00 (\$33,000.00) (\$33,000.00) (\$33,000.00) \$33,000.00)	Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user scarpm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. Line Item adjustment to withhold the amount over plan quantity. 22.0 SQYD at \$1,500.00 per SQYD = (\$33,000.00) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) overridding Payment Estimate Exception 46 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment
	Material - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR Other Item Adjustment - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Other Item Adjustment	OVRN - Tot	2 3 3 2 2 2 3 3	Jul 1, 2020 Jul 1, 2020 Jul 15, 2020 Jul 11, 2020 Jul 11, 2020 Jul 11, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020 Jul 15, 2020	SYSTEM SYSTEM scarpm1 SYSTEM SYSTEM SYSTEM	\$45,000.00 (\$45,000.00) \$45,000.00 \$0.00 \$0.00 (\$33,000.00) (\$33,000.00) (\$33,000.00) (\$33,000.00)	Payment Estimate Item Adjustment (0042) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user scarpm1 overridding Payment Estimate Exception 11 on the current Payment Estimate. Line Item adjustment to withhold the amount over plan quantity. 22.0 SQYD at \$1,500.00 per SQYD = (\$33,000.00) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) overridding Payment Estimate Exception 46 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0050) overridding Payment

Revision 4/1/2020 Page 19 of 22



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0380 -	· Total						(\$33,000.00)	
0410	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	(\$570.00)	
			Overrun - T	otal			(\$570.00)	
	Overrun - Total						(\$570.00)	
0410 -	· Total						(\$570.00)	
0420	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		2	Jul 1, 2020	SYSTEM	(\$423.00)	
				2	Jul 1, 2020	SYSTEM	\$423.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0045) due to user scarpm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$423.00)	
				3	Jul 15, 2020	SYSTEM	\$423.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0054) due to user scarpm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Other Item Adjustment	OVRN	2	Jul 1, 2020	scarpm1	(\$207.00)	Line Item adjustment to withhold the amount over plan quantity. 23 EA at \$9.00 per EA = (\$207.00)
			OVRN - Tota	al			(\$207.00)	
	Other Item Adjustment - Total						(\$207.00)	
	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	(\$207.00)	
	TOLE DEPTITE AVENUENT REPAIR			2	Jul 1, 2020	SYSTEM	\$207.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 48 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$207.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Jul 15, 2020	SYSTEM	\$207.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0053) overridding Payment Estimate Exception 41 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0420 -	· Total						(\$207.00)	
0440	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	(\$132,814.23)	
		Overrun - T	otal			(\$132,814.23)		
	Overrun - Total						(\$132,814.23)	
0440 -	Total						(\$132,814.23)	
0480	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED,	Material		1	Jun 16, 2020	SYSTEM	(\$6,600.00)	
	CONTRACTOR RETAINED			1	Jun 16, 2020	SYSTEM	\$6,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0480 -	Total						\$0.00	
0510	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		2	Jul 1, 2020	SYSTEM	(\$1,876.00)	
				2	Jul 1, 2020	SYSTEM	\$1,876.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0047) due to user scarpm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0510 -	Total						\$0.00	
0520	PREFORMED THERMOPLASTIC	Material		2	Jul 1,	SYSTEM	(\$3,906.00)	

Revision 4/1/2020 Page 20 of 22



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0520	PAVEMENT MARKING, 24 IN. YELLOW	Material			2020			
				2	Jul 1, 2020	SYSTEM	\$3,906.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0049) due to user scarpm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Other Item Adjustment	OVRN	2	Jul 1, 2020	scarpm1	(\$1,750.00)	Line Item adjustment to withhold the amount over plan quantity. 125 LF at \$14.00 per LF = (\$1,750.00)
				3	Jul 16, 2020	scarpm1	\$1,750.00	Line item adjustment to payback the amount withheld on pervious adjustment over plan quantity. Material exception resolved. 125 LF at \$14.00 per LF = \$1,750.00
		OVRN - Total				\$0.00		
	Other Item Adjustment - Total					\$0.00		
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	(\$1,750.00)	
				2	Jul 1, 2020	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0048) overridding Payment Estimate Exception 50 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$1,750.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
			Overrun - T	otal			(\$1,750.00)	
	Overrun - Total						(\$1,750.00)	
0520 -	- Total						(\$1,750.00)	
0530	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		2	Jul 1, 2020	SYSTEM	(\$1,260.00)	
				2	Jul 1, 2020	SYSTEM	\$1,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user scarpm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0530 -	- Total						\$0.00	
0540	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material		2	Jul 1, 2020	SYSTEM	(\$2,125.00)	
				2	Jul 1, 2020	SYSTEM	\$2,125.00	This adjustment offsets the original system-generated Overrun
					2020			Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
			- Total		2020		\$0.00	Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current
	Material - Total		- Total		2020		\$0.00 \$0.00	Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current
0540 -	Material - Total - Total		- Total		2020			Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current
0540 - 0550	- Total	Material	- Total	2	Jul 1, 2020	SYSTEM	\$0.00 \$0.00 (\$1,940.47)	Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
	- Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material	- Total	2	Jul 1,	SYSTEM	\$0.00 \$0.00	Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current
	- Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material	- Total	2	Jul 1, 2020 Jul 1, 2020 Jul 15, 2020	SYSTEM	\$0.00 \$0.00 (\$1,940.47) \$1,940.47	Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user scarpm1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
	- Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material	- Total	2	Jul 1, 2020 Jul 1, 2020 Jul 15,	SYSTEM	\$0.00 \$0.00 (\$1,940.47) \$1,940.47	Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user scarpm1 overridding Payment Estimate Exception 26 on the current
	- Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material	- Total	2	Jul 1, 2020 Jul 1, 2020 Jul 15, 2020 Jul 15,	SYSTEM	\$0.00 \$0.00 (\$1,940.47) \$1,940.47	Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user scarpm1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user scarpm1 overridding Payment Estimate Exception 18 on the current
	- Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		2	Jul 1, 2020 Jul 1, 2020 Jul 15, 2020 Jul 15,	SYSTEM	\$0.00 \$0.00 (\$1,940.47) \$1,940.47 (\$1,940.47)	Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user scarpm1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user scarpm1 overridding Payment Estimate Exception 18 on the current
	- Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material - Total	Material Other Item Adjustment		3 3	Jul 1, 2020 Jul 1, 2020 Jul 15, 2020 Jul 15,	SYSTEM	\$0.00 \$0.00 (\$1,940.47) \$1,940.47 (\$1,940.47) \$1,940.47	Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user scarpm1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user scarpm1 overridding Payment Estimate Exception 18 on the current
	- Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material - Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Other Item	- Total	3 3 2	Jul 1, 2020 Jul 1, 2020 Jul 15, 2020 Jul 15, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,940.47) \$1,940.47 (\$1,940.47) \$1,940.47	Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user scarpm1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user scarpm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
	- Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material - Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Other Item	- Total OVRN	3 3 2	Jul 1, 2020 Jul 1, 2020 Jul 15, 2020 Jul 15, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,940.47) \$1,940.47 (\$1,940.47) \$1,940.47 \$0.00 \$0.00 (\$78.47)	Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user scarpm1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user scarpm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.

Revision 4/1/2020 Page 21 of 22



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0550	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	\$78.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) overridding Payment Estimate Exception 42 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$78.47)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Jul 15, 2020	SYSTEM	\$78.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) overridding Payment Estimate Exception 32 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total					\$0.00		
0550 -	Total						(\$78.47)	
0560	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		2	Jul 1, 2020	SYSTEM	(\$981.47)	
	BEADS			2	Jul 1, 2020	SYSTEM	\$981.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user scarpm1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$981.47)	
				3	Jul 15, 2020	SYSTEM	\$981.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user scarpm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	OVRN	2	Jul 1, 2020	scarpm1	(\$32.34)	Line Item adjustment to withhold the amount over plan quantity. 462 LF at \$0.07 per LF = (\$32.34)
			OVRN - Tota	al			(\$32.34)	
	Other Item Adjustment - Total						(\$32.34)	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Overrun	Overrun	2	Jul 1, 2020	SYSTEM	(\$32.34)	
	BEADS			2	Jul 1, 2020	SYSTEM	\$32.34	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) overridding Payment Estimate Exception 43 on the current Payment Estimate.
				3	Jul 15, 2020	SYSTEM	(\$32.34)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Jul 15, 2020	SYSTEM	\$32.34	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) overridding Payment Estimate Exception 33 on the current Payment Estimate.
	Overrun - Total						\$0.00	
	Overrun - Total						\$0.00	
0560 -							(\$32.34)	
0590	CABLE, LOOP DETECTOR, IN DUCT	Material		2	Jul 1, 2020	SYSTEM	(\$4,715.80)	
				2	Jul 1, 2020	SYSTEM	\$4,715.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0050) due to user scarpm1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0590 -	Total						\$0.00	
Overa	II - Total						(\$390,273.21)	

Revision 4/1/2020 Page 22 of 22