Progress Estimate Number 12		Contract ID Prime Contractor	191213-F02 KCI Construction C	Pay Period Start J ompany Pay Period End A		Original Contract Amount Net Change Order Amount Current Contract Amount	\$32,975,925.00 (\$730,090.79) \$32,245,834.21	
Approval Date								
August 3, 2020		Generated and Approved (and should be considered Draft) at the Project Office Level by						
August 3, 2020		Re	eviewed and Approv	ed (and should be considered	d Draft) at the	Resident Engineer Level by	janssm	
August 5, 2020			Re	eviewed and Approved at the	Central Office	e Controllers Office Level by	greggd1	
Original Completion Date Current Con		npletion Date	Actual Completion Date	%	6 of Current Contract Amour	nt Complete		
December ?	December 1, 2021 December					57.75%		

#### No Milestones Exist for Contract

Contract Total Pay	y For Estimate No. 12			
		This Estimate	Previous	To Date
191213-F02				
	Total Posted Items Pay	\$1,007,042.52	\$17,613,696.61	\$18,620,739.13
	Gross Item Adjustments	(\$1,884.00)	(\$69,079.77)	(\$70,963.77)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	-		\$17,544,616.84	\$18,549,775.36
Contract Total Pay	yable This Estimate:	\$1,005,158.52		

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3225	0080	6122020	REPLACEMENT SAND BARREL	EA	\$208.000	2	\$416.00
	0090	6122030	IMPACT ATTENUATOR (RELOCATION)	EA	\$942.000	2	\$1,884.00
	0230	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	LF	\$10.730	4,500	\$48,285.00
	0245	6199901	MISC.MAINTENANCE OF TRAFFIC CONTROL DEVICES	LS	\$850,000.000	0.03	\$25,500.00
	0250	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	LF	\$1.250	3,782	\$4,727.50
	0260	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	LF	\$1.250	1,318	\$1,647.50
	0300	6207001	PAVEMENT MARKING REMOVAL	LF	\$0.750	14,083	\$10,562.25
	0360	6209903	MISC.6" WHITE TEMPORARY PAVEMENT MARKING PAINT	LF	\$0.110	13,284	\$1,461.24
	0380	6209903	MISC.6" YELLOW TEMPORARY PAVEMENT MARKING PAINT	LF	\$0.110	6,593	\$725.23
	0640	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	LF	\$2,250.000	106.02	\$238,545.00
	0650	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	LF	\$25.000	83.24	\$2,081.00
	0660	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	LF	\$950.000	37.02	\$35,169.00
	0700	7039903	MISC.BARRIER CURB MODIFICATION	LF	\$250.000	409.8	\$102,450.00
	0730	7040104	HALF-SOLE REPAIR	SQFT	\$35.000	59.88	\$2,095.80
	0800	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	LS	\$7,986,500.000	0.018	\$143,757.00
	0840	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	SQFT	\$10.000	3,570	\$35,700.00
	0850	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	SQFT	\$2.000	12,356	\$24,712.00
	0910	7129902	MISC.APPROACH GIRDER CRACK REPAIRS	EA	\$1,850.000	7	\$12,950.00
	0920	7129902	MISC.APPROACH SPAN RETROFIT - LATERAL BRACING SHELF	EA	\$7,500.000	1.8	\$13,500.00
	0930	7129902	MISC.APPROACH SPAN RETROFIT - STIFFENING CONNECTION	EA	\$4,000.000	23.2	\$92,800.00
	0990	7129902	MISC.TRUSS CRACK REPAIR	EA	\$2,250.000	2	\$4,500.00
	1000	7129902	MISC.TRUSS PLATED RETROFIT - FLOORBEAMS	EA	\$3,500.000	1	\$3,500.00
	1010	7129902	MISC.TRUSS PLATED RETROFIT - LATERAL BRACING MEMBERS	EA	\$3,500.000	2.9	\$10,150.00



Progress	Estimate 12	Number	Contract ID 191213-F02 Prime Contractor KCI Constru	Pay Period Start Jo ction Company Pay Period End A		2020 Net Change		
Project Number	Line Number	Item Code	Item [	Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3225	1040	7129902	MISC.TRUSS PLATED RETRO BRACING GUSSET PLATE	OFIT - UPPER & LOWER LATERAL	EA	\$4,000.000	12.3	\$49,200.00
	1050	7129902	MISC.TRUSS PLATED RETRO	OFIT - VERTICALS & DIAGONALS	EA	\$22,500.000	4.6	\$103,500.00
	1070	7174002	PREFORMED SILICONE OR E	PDM EXPANSION JOINT SEAL	LF	\$50.000	82.44	\$4,122.00
	5003	7125115	FINISHED FIELD COAT (SYST	EM I)	LS	\$919,500.000	0.036	\$33,102.00
Project J6I3225 - Total								
Overall - T	otal							\$1,007,042.52

#### Contract Adjustments This Estimate

## No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
1613225	0030	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-1,278.5	\$8.00	(\$10,228.00
	0030	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user kuehnb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,278.5	\$8.00	\$10,228.00
	0060	CONCRETE APPROACH PAVEMENT	Material			-103.1	\$160.00	(\$16,496.00
	0060	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user kuehnb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	103.1	\$160.00	\$16,496.00
	0090	IMPACT ATTENUATOR (RELOCATION)	Overrun			-2	\$942.00	(\$1,884.00
	0360	MISC.	Material			-66,822	\$0.11	(\$7,350.42
	0360	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user kuehnb1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	66,822	\$0.11	\$7,350.42
	0380	MISC.	Material			-32,829	\$0.11	(\$3,611.19
	0380	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	32,829	\$0.11	\$3,611.19
	0480	ROCK DITCH CHECK	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-200	\$60.00	(\$12,000.00
	0480	ROCK DITCH CHECK	Material			-225	\$60.00	(\$13,500.00
	0480	ROCK DITCH CHECK	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 50 on the current Payment Estimate.	200	\$60.00	\$12,000.00
	0480	ROCK DITCH CHECK	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user kuehnb1 overridding Payment Estimate Exception 46 on the current Payment Estimate.	225	\$60.00	\$13,500.00



Progr		imate Number 12	Contract ID Prime Contr	19121 actor KCI Co		ompany Pay Period End August 1, 2020 Net	Change Orde	Amount \$3 r Amount (\$ Amount \$3	730,090.79)
Project Number	Line No.	Item Desc	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3225	0670	BRIDGE APPR (M/	ROACH SLAB AJOR ROAD)	Material			-167.8	\$275.00	(\$46,145.00
	0670	BRIDGE APPR (M/	ROACH SLAB AJOR ROAD)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user kuehnb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	167.8	\$275.00	\$46,145.00
	0690	CLASS B-2	CONCRETE	Material			-159.7	\$2,250.00	(\$359,325.00
	0690	CLASS B-2	CONCRETE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user kuehnb1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	159.7	\$2,250.00	\$359,325.00
	0730	HALF-S	OLE REPAIR	Material			-274.57	\$35.00	(\$9,609.95
	0730	HALF-S	OLE REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user kuehnb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	274.57	\$35.00	\$9,609.95
	0770		CING STEEL XY COATED)	Material			-27,209	\$1.13	(\$30,746.17
	0770	REINFORCING STEEL (EPOXY COATED)		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user kuehnb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	27,209	\$1.13	\$30,746.17
	0850	FIELD APPL INORGANIC Z	LICATION OF	Material			-156,783	\$2.00	(\$313,566.00
	0850	FIELD APPL INORGANIC Z	LICATION OF	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user kuehnb1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	156,783	\$2.00	\$313,566.00
	0910		MISC.	Material			-9	\$1,850.00	(\$16,650.00
	0910		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user kuehnb1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	9	\$1,850.00	\$16,650.00
	0920		MISC.	Material			-47.8	\$7,500.00	(\$358,500.00
	0920		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user kuehnb1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	47.8	\$7,500.00	\$358,500.00
	0930		MISC.	Material			-153.2	\$4,000.00	(\$612,800.00
	0930		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user kuehnb1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	153.2	\$4,000.00	\$612,800.00
	0990		MISC.	Material			-2	\$2,250.00	(\$4,500.00
	0990		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0016) due to user kuehnb1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	2	\$2,250.00	\$4,500.00
	1000		MISC.	Material			-1	\$3,500.00	(\$3,500.00



Progr		timate Number 12	Contract ID Prime Contr	19121: ractor KCI Co		mpany Pay Period End August 1, 2020 Net	inal Contract Change Orde ent Contract	r Amount (\$	730,090.79)
Project Number	Line No.	Item Desc	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
1613225	1000		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0017) due to user kuehnb1 overridding Payment Estimate Exception 42 on the current Payment Estimate.	1	\$3,500.00	\$3,500.00
	1010		MISC.	Material			-4.9	\$3,500.00	(\$17,150.00
	1010		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	4.9	\$3,500.00	\$17,150.00
	1020		MISC.	Material			-5	\$8,000.00	(\$40,000.00
	1020		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0019) due to user kuehnb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	5	\$8,000.00	\$40,000.00
	1030		MISC.	Material			-1	\$2,500.00	(\$2,500.00
	1030		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	1	\$2,500.00	\$2,500.00
	1040		MISC.	Material			-16.3	\$4,000.00	(\$65,200.00
	1040		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0021) due to user kuehnb1 overridding Payment Estimate Exception 44 on the current Payment Estimate.	16.3	\$4,000.00	\$65,200.00
	1050		MISC.	Material			-29	\$22,500.00	(\$652,500.00
	1050		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0022) due to user kuehnb1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	29	\$22,500.00	\$652,500.00
	1060		MISC.	Material			-0.6	\$30,000.00	(\$18,000.00
	1060		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0023) due to user kuehnb1 overridding Payment Estimate Exception 43 on the current Payment Estimate.	0.6	\$30,000.00	\$18,000.00
	1070	PREFORMED S EPDM EXPAN		Material			-605	\$50.00	(\$30,250.00
	1070	PREFORMED S EPDM EXPAN		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0024) due to user kuehnb1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	605	\$50.00	\$30,250.00
	5005	TEMPORARY RUN	LONG-TERM IBLE STRIPS	Material			-12	\$1,050.00	(\$12,600.00
	5005	TEMPORARY RUM	LONG-TERM IBLE STRIPS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0025) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	12	\$1,050.00	\$12,600.00
	5006		ARY RAISED	Material			-180	\$3.15	(\$567.00

Progr		imate Number 12	Contract ID Prime Contr			Pay Period Start July 16, 2020 Origi ompany Pay Period End August 1, 2020 Net C Curr		r Amount (\$7	2,975,925.00 730,090.79) 2,245,834.21
Project Number	Line No.	Item Descr	iption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3225	5006		RY RAISED IT MARKER	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0026) due to user kuehnb1 overridding Payment Estimate Exception 22 on the current Payment Estimate.		\$3.15	\$567.00
Total									(\$1,884.00)



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	ontract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6I3225	l 70-4(204)	Bridge rehabilitation	I-70	ST CHARLES	over Missouri River		
Totals by	Job Numbe	rs					
J6I3225	J6/3225 Posted Item Pay Gross Item Adjustments Gross Item Pay		This Estimate \$1,007,042.52 (\$1,884.00) <b>\$1,005,158.52</b>	Previous \$17,613,696.61 (\$69,079.77) <b>\$17,544,616.84</b>	To Date \$18,620,739.13 (\$70,963.77) <b>\$18,549,775.36</b>		
	Liquid	tive centive lated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 3040504, Project Item Line Number 0030, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3225, Item 5031010A, Project Item Line Number 0670, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5031010A, Project Item Line Number 0670, Material Set 5031010A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5031010A, Project Item Line Number 0670, Material Set 5031010A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5031010A, Project Item Line Number 0670, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5031010A, Project Item Line Number 0670, Material Set 5031010A96, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5031010A, Project Item Line Number 0670, Material Set 5031010A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5031010A, Project Item Line Number 0670, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5031010A, Project Item Line Number 0670, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5031010A, Project Item Line Number 0670, Material Set 5031010A96, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5031010A, Project Item Line Number 0670, Material Set 5031010A96, Material 1036RSDFEC42M25 - Rein Steel EC No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3225, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 6162002, Project Item Line Number 5005, Material Set 616200296, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 6208064A, Project Item Line Number 5006, Material Set 6208064A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 6209903, Project Item Line Number 0380, Material Set 620990396, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 6209903, Project Item Line Number 0360, Material Set 620990396, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7034214, Project Item Line Number 0690, Material Set 703421496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7034214, Project Item Line Number 0690, Material Set 703421496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7034214, Project Item Line Number 0690, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7040104, Project Item Line Number 0730, Material Set 704010496, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7101000, Project Item Line Number 0770, Material Set 710100096, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7101000, Project Item Line Number 0770, Material Set 710100096, Material 1036RSDFEC42M25 - Rein Steel EC No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7101000, Project Item Line Number 0770, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7101000, Project Item Line Number 0770, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7125210, Project Item Line Number 0850, Material Set 712521096, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7129902, Project Item Line Number 0910, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7129902, Project Item Line Number 1020, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7129902, Project Item Line Number 1050, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7129902, Project Item Line Number 0930, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7129902, Project Item Line Number 1030, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7129902, Project Item Line Number 1010, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7129902, Project Item Line Number 0990, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7129902, Project Item Line Number 0920, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7129902, Project Item Line Number 1000, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7129902, Project Item Line Number 1060, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7129902, Project Item Line Number 1040, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3225, Item 7174002, Project Item Line Number 1070, Material Set 717400296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3225, Item 8061005, Project Item Line Number 0480, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-F02, Contract Project J6I3225, Project Item Line Number 0210, Contract Line Item Number 0210, Item 6173600D, Minor Item.	No Remark was entered by Engineer	KUEHNB1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-F02, Contract Project J6I3225, Project Item Line Number 0100, Contract Line Item Number 0100, Item 6123000A, Minor Item.	No Remark was entered by Engineer	KUEHNB1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-F02, Contract Project J6I3225, Project Item Line Number 0130, Contract Line Item Number 0130, Item 6161008, Minor Item.	No Remark was entered by Engineer	KUEHNB1	Acknowledged



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Item Overrun: Contract 191213-F02, Contract Project J6I3225, Project Item Line Number 0480, Contract Line Item Number 0480, Item 8061005, Minor Item.	No Remark was entered by Engineer	KUEHNB1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-F02, Contract Project J6I3225, Project Item Line Number 0090, Contract Line Item Number 0090, Item 6122030, Minor Item.	No Remark was entered by Engineer	KUEHNB1	Acknowledged
Estimate Exception Type: Pending Or Draft Daily Work Request: Contract 191213-F02, Inspector abrahm1, DWR Date 7/5/2020, DWR Status Pending Approval.	No Remark was entered by Engineer	KUEHNB1	Acknowledged
Estimate Exception Type: Pending Or Draft Daily Work Request: Contract 191213-F02, Inspector abrahm1, DWR Date 7/6/2020, DWR Status Pending Approval.	No Remark was entered by Engineer	KUEHNB1	Acknowledged
Estimate Exception Type: Pending Or Draft Daily Work Request: Contract 191213-F02, Inspector abrahm1, DWR Date 7/7/2020, DWR Status Pending Approval.	No Remark was entered by Engineer	KUEHNB1	Acknowledged

#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q	uantities	and Val	ues are	based on F	Report Generated date and can differ from the posted am	ount at the	time the Est	imate was (	Generate	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-F02	J613225	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$350,000.00	\$175,000.00
		0001	0020	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	340.00	0.00	340.00	SQFT	340.00	\$125.00	\$42,500.00
		0001	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,283.00	164.50	1,447.50	SQYD	1,278.50	\$8.00	\$10,228.00
		0001	0040	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	18.20	0.00	18.20	TONS	11.60	\$450.00	\$5,220.00
		0001	0050	4019905	MISC.OPTIONAL PAVEMENT	1,268.70	164.50	1,433.20	SQYD	1,311.50	\$60.00	\$78,690.00
		0001	0060	5041000	CONCRETE APPROACH PAVEMENT	202.70	0.00	202.70	SQYD	103.10	\$160.00	\$16,496.00
		0001	0070	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARRELS)	10.00	0.00	10.00	EA	4.00	\$2,678.00	\$10,712.00
		0001	0080	6122020	REPLACEMENT SAND BARREL	64.00	0.00	64.00	EA	31.00	\$208.00	\$6,448.00
		0001	0090	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	5.00	\$942.00	\$4,710.00
		0001	0100	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	5.00	\$1.00	\$5.00
		0001	0110	6159901	MISC.OFFICE FOR ENGINEER	1.00	0.00	1.00	LS	1.00	\$30,000.00	\$30,000.00
		0001	0120	6161005	CONSTRUCTION SIGNS	4,764.00	0.00	4,764.00	SQFT	4,072.11	\$12.00	\$48,865.32
		0001	0130	6161008	ADVANCED WARNING RAIL SYSTEM	24.00	0.00	24.00	EA	35.00	\$35.00	\$1,225.00
		0001	0140	6161009	FLAG ASSEMBLY	15.00	0.00	15.00	EA	15.00	\$20.00	\$300.00
		0001	0150	6161025	CHANNELIZER (TRIM LINE)	730.00	0.00	730.00	EA	376.00	\$18.00	\$6,768.00
		0001	0160	6161030	TYPE III MOVEABLE BARRICADE	31.00	0.00	31.00	EA	18.00	\$95.00	\$1,710.00
		0001	0170	6161033	DIRECTIONAL INDICATOR BARRICADE	106.00	0.00	106.00	EA	106.00	\$65.00	\$6,890.00
		0001	0180	6161040	FLASHING ARROW PANEL	7.00	0.00	7.00	EA	7.00	\$1,000.00	\$7,000.00
		0001	0190	6169901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	0.50	\$26,460.00	\$13,230.00
		0001	0200	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	315.00	0.00	315.00	LF	0.00	\$105.00	\$0.00
		0001	0210	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	4,220.00	0.00	4,220.00	LF	8,437.50	\$19.93	\$168,159.38
		0001	0220	6173700B	RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR	10,975.00	0.00	10,975.00	LF	5,603.50	\$26.28	\$147,259.98
		0001	0230	6175010A	FURNISHED / RETAINED RELOCATING TEMPORARY TRAFFIC BARRIER	9,454.00	0.00	9,454.00	LF	8,050.00	\$10.73	\$86,376.50
		0001	0240	6181000	MOBILIZATION	1.00	-1.00	0.00	LS		\$3,294,650.66	\$0.00
		0001	0241	6181000	MOBILIZATION	0.00	1.00	1.00	LS		\$3,032,453.66	\$3,032,453.66
		0001	0245	6199901	MISC.MAINTENANCE OF TRAFFIC CONTROL DEVICES	1.00	0.00	1.00	LS	0.26	\$850,000.00	\$221,000.00
		0001	0250	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	8,035.00	0.00	8,035.00	LF	6,276.00	\$1.25	\$7,845.00
		0001	0260	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	4,020.00	0.00	4,020.00	LF	1,318.00	\$1.25	\$1,647.50
		0001	0270	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	39,227.00	0.00	39,227.00	LF	10,159.00	\$0.23	\$2,336.57
		0001	0280	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	16,614.00	0.00	16,614.00	LF	0.00	\$0.23	\$0.00
		0001	0290	6205906A	MARKING PAINT, TYPE L BEADS 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,717.00	0.00	4,717.00	LF	3,782.00	\$0.50	\$1,891.00
		0001	0300	6207001	PAVEMENT MARKING REMOVAL	180,849.00	0.00	180,849.00	LF	86,422.60	\$0.75	\$64,816.95
		0001	0310	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	6.00	0.00	6.00	EA	0.00	\$100.00	\$0.00
		0001	0320	6209901	MISC.INLAID PAVEMENT MARKER REMOVAL	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0001	0330	6209902	MISC.INLAID PAVEMENT MARKER (INSTALLATION)	1,330.00	0.00	1,330.00	EA	0.00	\$28.00	\$0.00
		0001	0340	6209902	MISC.LANE REDUCTION ARROW (WHITE)	6.00	0.00	6.00	EA	3.00	\$1,000.00	\$3,000.00
		0001	0350	6209903	MISC.12" WHITE TEMPORARY PAVEMENT MARKING PAINT	610.00	0.00	610.00	LF	48.00	\$0.17	\$8.16
		0001	0360	6209903	MISC.6" WHITE TEMPORARY PAVEMENT MARKING PAINT	107,506.00	0.00	107,506.00	LF	66,822.00	\$0.11	\$7,350.42
		0001	0370	6209903	MISC.6" WHITE TEMPORARY PAVEMENT MARKING PAINT	9,988.00	0.00	9,988.00	LF	0.00	\$0.11	\$0.00
		0001	0380	6209903	MISC.6" YELLOW TEMPORARY PAVEMENT MARKING PAINT	34,195.00	0.00	34,195.00	LF	32,829.00	\$0.11	\$3,611.19
		0001	0390	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	168.00	0.00	168.00	SQYD	108.90	\$50.00	\$5,445.00
		0001	0400	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	7.60	0.00	7.60	STA	0.00	\$1,350.00	\$0.00
		0001	0410	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.75	\$150,000.00	\$112,500.00
		0001	0420	7261012	12 IN. PIPE GROUP A	330.00	0.00	330.00	LF	330.00	\$85.00	\$28,050.00
		0001	0430	7309901	MISC.REMOVE STORE RE-ERECT EXIT SIGN 229B	1.00	0.00	1.00	LS	0.00	\$2,100.00	\$0.00
		0001	0440	7309901	MISC.TRENCH DRAIN	1.00	0.00	1.00	LS	1.00	\$65,000.00	\$65,000.00
		5001				1.00	5.00	1.00	20	1.00	- 30,000.00	\$35,000.00



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

differ from the posted amount at the time the Estimate was Generated

Note: Posted Q					Report Generated date and can differ from the posted am	ount at the	time the Est	timate was C	Generate	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-F02	J6I3225	0001	0450	7309901	MISC.WELD DRAINAGE GATES	1.00	0.00	1.00	LS	0.50	\$25,000.00	\$12,500.00
		0001	0460	7320612A	12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$300.00	\$600.00
		0001	0470	8051000A	SEEDING - COOL SEASON MIXTURES	0.50	0.00	0.50	ACRE	0.00	\$7,500.00	\$0.00
		0001	0480	8061005	ROCK DITCH CHECK	25.00	0.00	25.00	LF	225.00	\$60.00	\$13,500.00
		0001	0490	8061016	SEDIMENT REMOVAL	29.00	0.00	29.00	CUYD	0.00	\$70.00	\$0.00
		0001	0500	8061019	SILT FENCE	2,690.00	0.00	2,690.00	LF	2,115.00	\$3.00	\$6,345.00
		0010	0510	6061060	MGS GUARDRAIL	2,063.00	0.00	2,063.00	LF	355.50	\$24.00	\$8,532.00
		0010	0520	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	5.00	0.00	5.00	EA	2.00	\$3,100.00	\$6,200.00
		0010	0530	6061080	MGS END ANCHOR	5.00	0.00	5.00	EA	1.00	\$1,200.00	\$1,200.00
		0010	0540	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	1.00	\$2,950.00	\$2,950.00
		0010	0550	6069901	MISC.RELAP GUARDRAIL	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0040	0560	6169901	MISC.TEMPORARY MEDIAN CROSSOVER - EAST	1.00	0.00	1.00	LS	1.00	\$150,000.00	\$150,000.00
		0040	0570	6169901	MISC.TEMPORARY MEDIAN CROSSOVER - WEST	1.00	0.00	1.00	LS	1.00	\$275,000.00	\$275,000.00
		0040	0580	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	17.00	0.00	17.00	EA	14.00	\$3,200.00	\$44,800.00
		0040	0590	9031010	CONCRETE FOOTINGS, EMBEDDED	0.70	0.00	0.70	CUYD	0.00	\$2,400.00	\$0.00
		0040	0600	9031220	PIPE POSTS	480.00	0.00	480.00	LB	0.00	\$5.00	\$0.00
		0040	0610	9035069A	SHF-FLAT SHEET FLUORESCENT	74.00	0.00	74.00	SQFT	0.00	\$26.00	\$0.00
		0040	0620	9039902	MISC.ADJUST OVERHEAD SIGNS	13.00	0.00	13.00	EA	13.00	\$2,000.00	\$26,000.00
		0070	0630	2162000	REMOVAL AND STORAGE OF EXISTING BRIDGE RAIL	7,577.00	0.00	7,577.00	LF	7,577.00	\$6.00	\$45,462.00
		0070	0640	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	696.00	0.00	696.00	LF	535.82	\$2,250.00	\$1,205,595.00
		0070	0650	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	612.00	0.00	612.00	LF	612.00	\$25.00	\$15,300.00
		0070	0660	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	221.00	0.00	221.00	LF	172.52	\$950.00	\$163,894.00
		0070	0670	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	321.00	0.00	321.00	SQYD	167.80	\$275.00	\$46,145.00
		0070	0680	6229905	MISC.METHYLMETHACRYLATE SLURRY PLOYMER CONCRETE OVERLAY	28,476.00	-28,476.00	0.00	SQYD	0.00	\$75.00	\$0.00
		0070	0690	7034214	CLASS B-2 CONCRETE	229.50	0.00	229.50	CUYD	159.70	\$2,250.00	\$359,325.00
		0070	0700	7039903	MISC.BARRIER CURB MODIFICATION	7,360.00	0.00	7,360.00	LF	4,086.70	\$250.00	\$1,021,675.00
		0070	0710	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	200.00	0.00	200.00	SQFT	0.00	\$200.00	\$0.00
		0070	0720	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	2,700.00	0.00	2,700.00	SQFT	124.84	\$140.00	\$17,477.60
		0070	0730	7040104	HALF-SOLE REPAIR	600.00	0.00	600.00	SQFT	274.57	\$35.00	\$9,609.95
		0070	0740	7040107	SLAB EDGE REPAIR (BRIDGES)	860.00	0.00	860.00	LF	340.24	\$140.00	\$47,633.60
		0070	0750	7049903	MISC.BARRIER CURB REPAIR	1,600.00	0.00	1,600.00	LF	122.07	\$85.00	\$10,375.95
		0070	0760	7079903	MISC.CONDUIT SYSTEM (NAVIGATION LIGHTING)	3,644.00	0.00	3,644.00	LF	0.00	\$35.00	\$0.00
		0070	0770	7101000	REINFORCING STEEL (EPOXY COATED)	50,180.00	0.00	50,180.00	LB	27,209.00	\$1.13	\$30,746.17
		0070	0780	7110100	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (URETHANE)	1.00	0.00	1.00	LS	0.00	\$106,000.00	\$0.00
		0070	0790	7119901	MISC.CLEARANCE GAUGE	1.00	0.00	1.00	LS	0.00	\$16,000.00	\$0.00
		0070	0800	7125100	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	1.00	0.00	1.00	LS	0.56	\$7,986,500.00	\$4,456,467.00
		0070	0810	7125110	FIELD APPLICATION OF INORGANIC ZINC PRIMER	1.00	-1.00	0.00	LS	0.00	\$919,500.00	\$0.00
		0070	0820	7125111	INTERMEDIATE FIELD COAT (SYSTEM G)	1.00	-1.00	0.00	LS	0.00	\$1.00	\$0.00
		0070	0830	7125112	FINISH FIELD COAT (SYSTEM G)	1.00	-1.00	0.00	LS	0.00	\$919,500.00	\$0.00
		0070	0840	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	350,900.00	0.00	350,900.00	SQFT	204,131.00	\$10.00	\$2,041,310.00
		0070	0850	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	350,900.00	0.00	350,900.00	SQFT	156,783.00	\$2.00	\$313,566.00
		0070	0860	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	102,600.00	-102,600.00	0.00	SQFT	0.00	\$0.01	\$0.00
		0070	0870	7125370A	FINISH FIELD COAT (SYSTEM G)	102,600.00	-102,600.00	0.00	SQFT	0.00	\$2.00	\$0.00
		0070	0880	7129901	MISC.ACCESS LADDER MODIFICATION	1.00	0.00	1.00	LS	0.00	\$88,000.00	\$0.00
		0070	0890	7129901	MISC.CLEANING SLAB DRAINS	1.00	0.00	1.00	LS	1.00	\$25,000.00	\$25,000.00
		0070	0900	7129901	MISC.LADDER AND RAILING MODIFICATIONS	1.00	0.00	1.00	LS	0.00	\$55,000.00	\$0.00
Devision 4/1/200												Dege 11 of 21



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

ntract NTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
-F02	J613225	0070	0910	7129902	MISC.APPROACH GIRDER CRACK REPAIRS	29.00	0.00	29.00	EA	20.00	\$1,850.00	\$37,000.0
		0070	0920	7129902	MISC.APPROACH SPAN RETROFIT - LATERAL BRACING SHELF	86.00	0.00	86.00	EA	54.40	\$7,500.00	\$408,000.
		0070	0925	7129902	MISC.TRUSS RETROFIT - STRINGER DIAPHRAGM	1.00	0.00	1.00	EA	0.00	\$5,000.00	\$0.
		0070	0930	7129902	MISC.APPROACH SPAN RETROFIT - STIFFENING CONNECTION	258.00	0.00	258.00	EA	164.50	\$4,000.00	\$658,000.
		0070	0940	7129902	MISC.REHABILITATE BEARINGS (EXTERIOR STRINGERS AT L15' & L19)	8.00	0.00	8.00	EA	0.00	\$3,000.00	\$0
		0070	0950	7129902	MISC.REHABILITATE BEARINGS (NEAR PIER 9)	3.00	0.00	3.00	EA	0.00	\$25,000.00	\$0
		0070	0960	7129902	MISC.SPECIAL SURFACE TREATMENT - LOWER HANGER JOINT GUSSET PLATE	36.00	0.00	36.00	EA	22.00	\$80.00	\$1,760
		0070	0970	7129902	MISC.SPECIAL SURFACE TREATMENT - LOWER SPLICE JOINT GUSSET PLATE	84.00	0.00	84.00	EA	22.00	\$390.00	\$8,580
		0070	0980	7129902	MISC.SPECIAL SURFACE TREATMENT - TRUSS MEMBERS	88.00	0.00	88.00	EA	44.00	\$800.00	\$35,200
		0070	0990	7129902	MISC.TRUSS CRACK REPAIR	34.00	0.00	34.00	EA	16.00	\$2,250.00	\$36,000
		0070	1000	7129902	MISC.TRUSS PLATED RETROFIT - FLOORBEAMS	1.00	0.00	1.00	EA	1.00	\$3,500.00	\$3,500
		0070	1010	7129902	MISC.TRUSS PLATED RETROFIT - LATERAL BRACING MEMBERS	5.00	0.00	5.00	EA	4.90	\$3,500.00	\$17,150
		0070	1020	7129902	MISC.TRUSS PLATED RETROFIT - LOWER SPLICE JOINT GUSSET PLATE	18.00	0.00	18.00	EA	5.00	\$8,000.00	\$40,000
		0070	1030	7129902	MISC.TRUSS PLATED RETROFIT - SWAY BRACING	1.00	0.00	1.00	EA	1.00	\$2,500.00	\$2,500
		0070	1040	7129902	MISC.TRUSS PLATED RETROFIT - UPPER & LOWER LATERAL BRACING GUSSET PLATE	17.00	0.00	17.00	EA	16.30	\$4,000.00	\$65,200
		0070	1050	7129902	MISC.TRUSS PLATED RETROFIT - VERTICALS & DIAGONALS IN SPLASH ZONE	58.00	0.00	58.00	EA	29.00	\$22,500.00	\$652,500
		0070	1060	7129902	MISC.UPPER GUIDE PIN RETROFIT	4.00	0.00	4.00	EA	0.60	\$30,000.00	\$18,00
		0070	1070	7174002	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	605.00	0.00	605.00	LF	605.00	\$50.00	\$30,25
		0070	1080	7179903	MISC.MODULAR EXPANSION JOINT SYSTEM - L12	67.00	0.00	67.00	LF	37.00	\$2,050.00	\$75,85
		0070	1090	7179903	MISC.MODULAR EXPANSION JOINT SYSTEM - L12'	67.00	0.00	67.00	LF	37.00	\$2,850.00	\$105,45
		0070	1100	7179903	MISC.MODULAR EXPANSION JOINT SYSTEM - PIER 14	67.00	0.00	67.00	LF	37.00	\$2,850.00	\$105,45
		0070	1110	7179903	MISC.MODULAR EXPANSION JOINT SYSTEM - PIER 17	67.00	0.00	67.00	LF	37.00	\$1,500.00	\$55,50
		0070	1120	7179903	MISC.MODULAR EXPANSION JOINT SYSTEM - PIER 9	67.00	0.00	67.00	LF	37.00	\$1,500.00	\$55,50
		0070	1130	7179903	MISC.STRIP SEAL EXPANSION JOINT SYSTEM - PIER 19	67.00	0.00	67.00	LF	37.00	\$450.00	\$16,65
		0070	1140	7179903	MISC.STRIP SEAL EXPANSION JOINT SYSTEM - ABUTMENT 1	76.00	0.00	76.00	LF	37.00	\$450.00	\$16,65
		0070	1150	7179903	MISC.STRIP SEAL EXPANSION JOINT SYSTEM - ABUTMENT 20	68.00	0.00	68.00	LF	37.00	\$450.00	\$16,65
		0070	1160	7179903	MISC.STRIP SEAL EXPANSION JOINT SYSTEM - PEIR 6	67.00	0.00	67.00	LF	37.00	\$450.00	\$16,65
		0070	1170 1180	7179903 9019300	MISC.STRIP SEAL EXPANSION JOINT SYSTEM - PIER 3 NAVIGATION LIGHTING SYSTEM	75.00	0.00	75.00	LF	37.00 0.00	\$450.00	\$16,65
		0101	1190	6189916	MISC.ACCELERATING THE COMPLETION OF CLOSE WORK	8,800.00	0.00	8,800.00	DLR	0.00	\$0.00	\$
		0001	5001	6189901	(INCENTIVE/DISINCENTIVE) MISC.Contract Bond Adjusted Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$262,197.00	\$262,19
		0070	5002	7129901	MISC.Field Application of Organic Zinc Primer	0.00	1.00	1.00	LS	0.49	\$919,500.00	\$454,23
		0070	5003	7125115	FINISHED FIELD COAT (SYSTEM I)	0.00	1.00	1.00	LS	0.45	\$919,500.00	\$417,45
		0070	5004	7125396	FINISHED FIELD COAT (SYSTEM I)	0.00	102,600.00	102,600.00	SQFT	0.00	\$2.00	\$
		0001	5005	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	0.00	12.00	12.00	EA	12.00	\$1,050.00	\$12,60
		0001	5006	6208064A	TEMPORARY RAISED PAVEMENT MARKER	0.00	180.00	180.00	EA	180.00	\$3.15	\$56
		0001	5007	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	0.00	1,000.00	1,000.00	LF	800.00	\$16.62	\$13,29
		0001	5008	6209902	MISC.CONTRAST LANE REDUCTION ARROW	0.00	3.00	3.00	EA	3.00	\$1,785.00	\$5,35
		0001	5009	4039902	MISC.REBUILD SHOULDER	0.00	1.00	1.00	EA	1.00	\$12,681.51	\$12,68
		0070	5010	6239905	MISC.EPOXY POLYMER CONCRETE OVERLAY WITH HEALER/SEALER AND BAUXITE	0.00	28,476.00	28,476.00	SQYD	5,327.00	\$38.10	\$202,95
		0070	5011	1046002	VALUE ENGINEERING	0.00	262,691.10	262,691.10	EA	0.00	\$1.00	\$0
	Proiect J	6 3225 - To	otal Value	Posted to D	Date as of Report Generated Date							\$18,672,939



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

6122030 (175010A) 175010A 16199001 2005301B 2005303B 6207001	REPLACEMENT SAND BARREL IMPACT ATTENUATOR (RELOCATION) RELOCATING TEMPORARY TRAFFIC BARRIER MISC. TEMPORARY REMOVABLE MARKING TAPE 4 IN., TEMPORARY REMOVABLE MARKING TAPE PAVEMENT MARKING REMOVAL	7/31/20 7/21/20 7/18/20 7/18/20 7/18/20 7/18/20 7/18/20 7/18/20 7/18/20 7/18/20 7/17/20 7/12/1/20		2.00 2.00 4,500.00 0.03 3,782.00 1,318.00 2,596.00 11,487.00	EA EA LF LS LF	Stage 2 West Approach (STA 1375+00 to STA 6+00): 1955 1957	1380+00 00 1375+00	28.77	Log Mile 1378+50 60 45+00 00 58+00 6+00	50.00	West Crossover STAGE 2 Stage 2 3% earned this pay period
1750104 (6199001 (1000)) 6199001 (1000) 22053038 (2000) 6207001 (1000)	RELOCATING TEMPORARY TRAFFIC BARRIER MISC. TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	7/18/20 7/30/20 7/18/20 7/18/20 7/18/20	7/30/20 7/31/20 7/30/20 7/30/20 7/30/20	4,500.00 0.03 3,782.00 1,318.00 2,596.00	LF LS LF LF	Stage 2 West Approach (STA 1375+00 to STA 6+00): 1955 1957	1380+00 00 1375+00 1375+00	28.77	45+00 00 58+00	50.00	
6199901 205301B 6207001	MISC. TEMPORARY REMOVABLE MARKING TAPE 4 IN., TEMPORARY REMOVABLE MARKING TAPE	7/30/20 7/18/20 7/18/20 7/18/20 7/17/20	7/31/20 7/30/20 7/30/20 7/30/20 7/28/20	0.03 3,782.00 1,318.00 2,596.00	LS LF LF	Stage 2 West Approach (STA 1375+00 to STA 6+00): 1955 1957	00 1375+00 1375+00		00		
2053018	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	7/18/20 7/18/20 7/17/20	7/30/20 7/30/20 7/28/20	3,782.00 1,318.00 2,596.00	LF	1935 - Sth Street Ramp: 347 - Outside Stripe: 287 - Middle Stripe: 1036' - Redo Partial Middle Stripe: 265' - Stage 2 East Approach (STA 44+00 to STA 58+00): 1847' - Middle Stripe: 503' - Outside Stripe: 1344' - Stage 2 West Approach (STA 1375+00 to STA 6+00): 1318' - Sth Street Ramp: 254' - Mainline: 1064' East Side and West Side of Bridge in Tapers - Paint and Tape Removals from Stage 1 for Stage 2	1375+00		58+00		3% earned this pay period
6207001	TEMPORARY REMOVABLE MARKING TAPE	7/18/20	7/30/20 7/28/20	1,318.00	LF	1935 - Sth Street Ramp: 347 - Outside Stripe: 287 - Middle Stripe: 1036' - Redo Partial Middle Stripe: 265' - Stage 2 East Approach (STA 44+00 to STA 58+00): 1847' - Middle Stripe: 503' - Outside Stripe: 1344' - Stage 2 West Approach (STA 1375+00 to STA 6+00): 1318' - Sth Street Ramp: 254' - Mainline: 1064' East Side and West Side of Bridge in Tapers - Paint and Tape Removals from Stage 1 for Stage 2	1375+00				
6207001		7/17/20	7/28/20	2,596.00	LF	- Middle Stripe: 503'     - Outside Stripe: 1344' Slage 2 West Approach (STA 1375+00 to STA 6+00): 1318'     - Sih Street Ramp: 254'     - Mainline: 1064' East Side and West Side of Bridge in Tapers - Paint and Tape Removals from Stage 1 for Stage 2	1375+00		6+00		
6207001		7/17/20	7/28/20	2,596.00	LF	1318 - 5th Street Ramp: 254' - Mainline: 1064' East Side and West Side of Bridge in Tapers - Paint and Tape Removals from Stage 1 for Stage 2			6+00		
	PAVEMENT MARKING REMOVAL					East Side and West Side of Bridge in Tapers - Paint and Tape Removals from Stage 1 for Stage 2	1375				
						Tape Removals from Stage 1 for Stage 2	1375				
6209903		7/21/20	7/22/20	11,487.00	LF	Pavement Marking Removals	1375				
6209903						East Approach (44+00 - 58+00) - Yellow = 260' - Temporary Stage 1 Yellow = 785' - Intermittent White (SKIPS) = 550' Bridge (6+0-0-44+00) - Yellow = 2068' - Intermittent White (SKIPS) = 510' - Redo White (SKIPS) = 510'	1070	00	58	00	Pavement Marking Removals East Approach (4+00 - 58+00) - Yellow = 260' - Temporary Stage 1 Yellow = 785' - Intermittent White (SKIPS) = 550' Bridge (6+0 - 44+00) - Yellow = 2068' - Intermittent White (SKIPS) = 510' - Redo White Middle Stripe = 3826'
6209903						West Approach (1375+00 - 6+00) - Redo White Middle = 265' - Yellow = 66'6' (SUPS) = 240' - Intermittent White (SKPS) = 240' - Stage 1 Yellow Temporary = 1122' (989' - Mainline, 133' - 5th Street Ramp) - Stage 1 White Temporary = 1195' (1008' - Mainline, 133' - 5th Street Ramp)					West Approach (1375+00 - 6+00) - Redo White Middle = 265' - Yellow = 66(6 (SKIPS) = 240' - Intermittent White (SKIPS) = 240' - Stage 1 Yellow Temporary = 1122' (989' - Mainline, 1 - 5th Street Ramp) - Stage 1 White Temporary = 1195' (1008' - Mainline, 1 - 5th Street Ramp)
	MISC. PAVEMENT MARKINGS	7/17/20	7/28/20	934.00	LF	East Side of Bridge in Taper					Need to check quantities with TraMar and Inspector to see how much was striped incorrectly and removed in
		7/18/20	7/30/20	12,350.00	LF	Stage 2 Bridge (STA 6+00 to STA 44+00):11478' - Middle Stripe: 3826' - Redo Middle Stripe: 3826' - Outside Stripe: 3826'	6+00		58+00		Lane 1 (too narrow)
						Stage 2 East Approach (STA 44+00 to STA 58+00): 1367 - Outside Stripe: 1367'					
6209903	MISC. PAVEMENT MARKINGS	7/17/20	7/28/20	1,400.00	LF	Stage 2 Traffic Switch - East Side of the Bridge through taper to put them in Lane 4 & 5					
		7/18/20	7/30/20	5,193.00	LF		1375+00		58+00		
2164500	REMOVAL OF EXISTING EXPANSION JOINT &	7/28/20	7/29/20	17.67	LF		0				Hydro demolition
	ADJACENT CONCRETE		7/29/20	17.67			0				Hydro Demolition
			7/29/20	17.67	LF	Joint L12' Stage 2	0				Hydro Demolition
			7/29/20	17.67			0				Hydro Demolition
		0/4/00									Hydro Demolition
2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL										Hydro Demolition
2100000		TEGILO	7/29/20	41.62			0				
2169903	MISC. REMOVALS	7/28/20	7/29/20	2.00			0				Concrete Removal
			7/29/20	2.00	LF	Pier 20 Stage 2	0				Concrete Removal
			7/29/20	2.50	LF	Pier 19 Stage 2	0				Concrete Removal
			7/29/20	2.50			0				Concrete Removal
											Concrete Removal Concrete Removal
						÷					Concrete Removal
			7/29/20	3.13							Concrete Removal
			7/29/20	3.13	LF	Pier 9 Stage 2	0				Concrete Removal
			7/29/20	3.63		÷					Concrete Removal
		7/00/00						75.44		57.00	Concrete Replacement
7039903	MISC. CONCRETE CONSTRUCTION	7/28/20	7/29/20	409.80	LF	- Spans 14,15,16	24	75.14	38	57.00	
		7/24/20	7/27/20		SQFT	Across entire bridge - Inlaid Pavement Markers		28.77		50.00	Across entire bridge - Inlaid Pavement Markers
		7/30/20	7/31/20	0.02	LS	Truss Spans	00		00		ST2 SP14 QT4 - 0.006 (15% of 0.03875 for containme ST2 SP15 QT1+4 - 0.006 (15% of 0 for containment) ST2 SP16 QT1 - 0.006 (15% of 0.03875 for containme
							00		00		Span 1 - 50% Completed (100% Complete) @ 3570 SQFT Span 1 - Done (Withhold 10% for touch up) @ 11332
				7.00			1375+28.77		60+50		Span 2 - Done (Withhold 10% for touch up) @ 1024 - Span 19: G3S
7129902	MISC.	7/29/20	7/29/20	0.90	FA	Span 10	1375+28 77		60+50		- Span 8: G5N, G6S, G6N, G1S, and G1N - Span 7: G4N G3FB3(2) (finished = 90%)
				0.90			1375+28.77		60+50		G3FB3(1) (finished = 90%)
7129902	MISC.	7/21/20	7/22/20	1.80	EA	Span 7	1375+28.77		60+50		G6D3In (finished = 90% with G6D3Ex completed in pha 1 construction) and G6D2In (finished = 90% with G6D2 completed in phase 1 construction)
		7/22/20	7/23/20	1.80	EA	Span 7	1375+28.77		60+50		G6D1In (finished = 90% with G6D1Ex completed in pha 1 construction) and G9D1Ex (finished = 90%)
		7/24/20	7/24/20	13.30	EA	Span 7 and Span 6	1375+28.77		60+50		- Span 7: G9D2Ex (finished and torqued = 100%), G9D3Ex (finished and torqued = 100%), G8D3In (finish and torqued = 100% with G8D5Ex on 07/22020), G8D2Ex/in (finished and torqued = 100%), G8D1Ex/in (finished and torqued = 100%), G7D2In (finished = 90%) with G7D2Ex on 07/21/2020, G7D3In (finished = 90%) with G7D2Ex on 07/21/2020, G7D3In (finished = 90%)
211 211 211 70: 70: 71: 71: 71: 71: 71:	39903 40104 25200 25220 29902	ADJACENT CONCRETE 35000 REMOVAL OF EXISTING EXPANSION JOINT SEAL 39903 MISC. REMOVALS 39903 MISC. CONCRETE CONSTRUCTION 40104 HALF-SOLE REPAIR 25100 SURFACE PREPARATION FOR RECOATING STRUC	34500         REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE         7/28/20           35000         REMOVAL OF EXISTING EXPANSION JOINT SEAL         7/28/20           35000         REMOVAL OF EXISTING EXPANSION JOINT SEAL         7/28/20           35000         MISC. REMOVALS         7/28/20           39903         MISC. CONCRETE CONSTRUCTION         7/28/20           39904         MISC. CONCRETE CONSTRUCTION         7/28/20           39905         MISC. CONCRETE CONSTRUCTION         7/28/20           39906         MISC. CONCRETE CONSTRUCTION         7/28/20           39907         MISC. CONCRETE CONSTRUCTION         7/28/20           39908         MISC. CONCRETE CONSTRUCTION         7/28/20           39909         MISC. CONCRETE CONSTRUCTION         7/28/20           39900         SURFACE PREPARATION FOR RECOATING STRUC         7/30/20           325200         SURFACE PREPARATION OF INORGANIC ZINC         7/30/20           39902         MISC.         7/29/20         7/31/20           39902         MISC.         7/29/20         7/31/20           39902         MISC.         7/21/20         7/22/20	34500         REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE         7/29/20 7/29/20 7/29/20 7/29/20 7/29/20 8/102           35000         REMOVAL OF EXISTING EXPANSION JOINT SEAL         7/28/20 7/29	34500         ADJACENT CONCRETE         728/20         22.00         778/20         2.200         778/20         2.250         729/20         2.50         729/20         2.50         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13         729/20         3.13	34500         REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE         728120         712920         71.67         I.F.           72920         71.67         I.F.         72920         71.61         I.F.           72920         71.61         I.F.         72920         2.50         I.F.           72920         71.61         I.F.         72920         3.13         I.F.           72920         3.13         I.F.         72920         3.13	REMOVAL OF EXISTING EXPANSION JOINT & ADACENT CONCRETE         71820	File         71820         71920         51930         File         8tage 2 East Approach (STA 44-00 to STA 58-00): 1367         1375+00           NMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE         772200         7767         File         Joint 112 Stage 2         0           772800         7767         File         Joint 112 Stage 2         0         0           772800         7767         File         Joint 112 Stage 2         0         0           772800         7767         File         Per 70 Stage 2         0         0           772800         7767         File         Per 17 Stage 2         0         0           772800         7787         File         Per 10 Stage 1         0         0           772800         4168         File         Location 3 Stage 1         0         0           772800         4168         File         Der 10 Stage 2         0         0         0           772800         4168         File         Per 10 Stage 2         0         0         0         0         0           772800         4168         File         Per 10 Stage 2         0         0         0         0         0         0         0         0	Final Probability         Final Probability	APPORT         71822         73020         7302         73020         7302         73020         7302         73020         73020         7302         73020         73020         73020         73020         73020         73	Product of Expansion Joint A         Product OF Expansion Joint A <th< td=""></th<>



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval	Quantity Posted	Units	Location	From Station/Log	Offset/ Distance	To Station/	Offset/ Distance	Comments
Number	Code		Date	Date	Posted			Mile	Distance	Log Mile	Distance	
0930	7129902	MISC.										90% with G6D1Ex on construction phase 1), G6D2In (finished and torqued = 100% with G6D2Ex on construction phase 1), and G6D3n (finished and torqued = 100% with G6D3Ex on construction phase 1).
			7/28/20	7/28/20	6.30	EA	Span 6 and Span 5	1375+28.77		60+50		<ul> <li>Span 6: G7D2In (finished = 90% with G7D2Ex on 07/24/2020), 68D2Ex (finished = 90% with G8D2In on 07/24/2020), G7D3in (finished = 90% with G8D3Ex (finished = 90%).</li> <li>Span 5: G6D3in (finished = 90%, with G6D3Ex (finished on phase 1 construction) and G7D3Ex/In (finished = 90%).</li> </ul>
0990	7129902	MISC.	7/29/20	7/29/20	2.00	EA	Span 15 and Span 16	1375+28.77		60+50		*NOTE: These repairs were NOT in the plans. The cracks completed up after the truss method 1 repairs were completed on the members." - Span 15: L16U16 a 28" crack at the height of the barrier wall (about the middle) on the NE corner - Span 16: L14U14" a 14" crack at the bottom of the member on the NE corner
1000	7129902	MISC.	7/17/20	7/19/20	1.00	EA	Span 14	1375+28.77		60+50		L8 (caulked/finished/torqued = 100%)
1010	7129902	MISC.	7/21/20	7/22/20	0.90	EA	Span 16	1375+28.77		60+50		L5' (finished = 90%)
			7/22/20	7/23/20	0.10	EA	Span 16	1375+28.77		60+50		L5' (torqued = 10%)
			7/23/20	7/23/20	0.90	EA	Span 14	1375+28.77		60+50		L7 (finished = 90%)
			7/24/20	7/24/20	1.00	EA	Span 15	1375+28.77		60+50		L22 (finished and torqued = 100%)
1040	7129902	MISC.	7/22/20	7/23/20	2.00	EA	Span 16	1375+28.77		60+50		L3'L (finished and torqued = 100%) and L13'L (finished and torqued = 100%)
			7/23/20	7/23/20	7.40	EA	Span 16, Span 15, and Span 14	1375+28.77		60+50		- Span 16: L14'L (finished and torqued = 100%), and L14'U (finished and torqued = 100%) - Span 15: L221 (finished = 90%), L23L (finished = 90%), L22L (finished = 90%), and L17L (finished = 90%) - Span 14: L11U (finished = 90%) and L9L (finished = 90%)
			7/24/20	7/24/20	2.90	EA	Span 15 and Span 14	1375+28.77		60+50		- Span 15: L19'L (finished and torqued = 100%) and L22' (torqued = 10%) - Span 14: L4L (finished = 90%) and L3L (finished = 90%)
1050	7129902	MISC.	7/16/20	7/19/20	4.50	EA	Span 14, Span 15, and Span 16	1375+28.77		60+50		$\label{eq:2.1} \begin{array}{l} -\text{Span 14:} L4U4 (painted = 10%), L6U8 (painted = 10%), L6U8 (painted = 10%), L6U8 (painted = 10%), L6U8 (painted = 10%), L7U17 (painted = 10%), and L13U13 (painted = 10%), L19U19 (painted = 10%), and L21U21 (painted = 10%), L19U19 (painted/minshed/torqued = 70%), L19U19 (painted/minshed/torqued = 70%), L6U6 (painted = 10%), L6U6 (painted = 10%), L10U10 (painted = 10%), L6U6 (painted = 10%), L10U10 (painted = 10%), L6U6 (painted = 10%), L10U10 (painted/minshed/torqued = 70%), L10U10 (painted/minshed/minshed/torqued = 70%), L10U10 (painted/minshed/minshed/minshed/minshed/minshed/minshed/minshed/minshed/minshed/minshe$
			7/17/20	7/19/20	0.10	EA	North truss span	1375+28.77		60+50		the remaining truss method 1 repairs on the bridge that weren't painted were painted
1070	7174002	PREFORMED SILICONE OR EPDM EXP. JOINT SEAL	7/28/20	7/29/20	41.22	LF	Location 3 Stage 1	0				
				7/29/20	41.22	LF	Location 7 Stage 1	0				
5003	7125115	FINISHED FIELD COAT (SYSTEM I)	7/30/20	7/31/20	0.04	LS	Truss Spans	00		00		10% for touch up above bridge deck for each quarter: STI SP14 QT1 STI SP14 QT3 STI SP14 QT3 STI SP15 QT2 STI SP15 QT2 STI SP15 QT3 STI SP15 QT4 STI SP16 QT3 STI SP16 QT3

The information below this line are details from Line Item agency views. No Agency View Details Exist



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0030	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material	1390	3	Mar 16, 2020	SYSTEM	(\$8,912.00)	
				3	Mar 16, 2020	SYSTEM	\$8,912.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kuehnb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	Apr 2, 2020	SYSTEM	(\$8,912.00)	
				4	Apr 2, 2020	SYSTEM	\$8,912.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kuehnb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Apr 16, 2020	SYSTEM	(\$8,912.00)	
				5	Apr 16, 2020	SYSTEM	\$8,912.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kuehnb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	May 3, 2020	SYSTEM	(\$8,912.00)	
				6	May 3, 2020	SYSTEM	\$8,912.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kuehnb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	May 18, 2020	SYSTEM	(\$8,912.00)	
				7	May 18, 2020	SYSTEM	\$8,912.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kuehnb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$10,228.00)	
				8	Jun 2, 2020	SYSTEM	\$10,228.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kuehnb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$10,228.00)	
				9	Jun 16, 2020	SYSTEM	\$10,228.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kuehnb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$10,228.00)	
				10	Jul 2, 2020	SYSTEM	\$10,228.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kuehnb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$10,228.00)	
				11	Jul 16, 2020	SYSTEM	\$10,228.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kuehnb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$10,228.00)	
				12	Aug 3, 2020	SYSTEM	\$10,228.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kuehnb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		8	Jun 2, 2020	SYSTEM	(\$27.64)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$27.64)	
	Price - Total						(\$27.64)	
0030 - 0060	Total CONCRETE APPROACH	Material		8	Jun 2,	SYSTEM	(\$27.64)	
	PAVEMENT			8	2020 Jun 2, 2020	SYSTEM	\$16,496.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kuehnb1 overridding
				9	Jun 16,	SYSTEM	(\$16,496.00)	Payment Estimate Exception 15 on the current Payment Estimate.
				9	2020 Jun 16, 2020	SYSTEM	\$16,496.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kuehnb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
060	CONCRETE APPROACH PAVEMENT	Material	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	10	Jul 2, 2020	SYSTEM	(\$16,496.00)	
				10	Jul 2, 2020	SYSTEM	\$16,496.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0005) due to user kuehnb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$16,496.00)	
				11	Jul 16, 2020	SYSTEM	\$16,496.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0002) due to user kuehnb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$16,496.00)	
				12	Aug 3, 2020	SYSTEM	\$16,496.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0005) due to user kuehnb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
060 -	Total						\$0.00	
090	IMPACT ATTENUATOR (RELOCATION)	Overrun	Overrun	3	Mar 16, 2020	SYSTEM	(\$942.00)	
				12	Aug 3, 2020	SYSTEM	(\$1,884.00)	
			Overrun - To	otal			(\$2,826.00)	
	Overrun - Total						(\$2,826.00)	
090 -	Total						(\$2,826.00)	
100	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Overrun	Overrun	2	Mar 3, 2020	SYSTEM	(\$1.00)	
			Overrun - To	otal			(\$1.00)	
	Overrun - Total						(\$1.00)	
100 -	Total						(\$1.00)	
130	ADVANCED WARNING RAIL SYSTEM	Overrun	Overrun	2	Mar 3, 2020	SYSTEM	(\$280.00)	
				4	Apr 2, 2020	SYSTEM	(\$105.00)	
			Overrun - To	otal			(\$385.00)	
	Overrun - Total						(\$385.00)	
130 -	Total						(\$385.00)	
210	TEMPORARY TRAFFIC BARRIER, CONTRACTOR	Overrun	Overrun	2	Mar 3, 2020	SYSTEM	(\$2,590.90)	
	FURNISHED / RETAINED			10	Jul 2, 2020	SYSTEM	(\$81,463.88)	
			Overrun - T	otal			(\$84,054.78)	
	Overrun - Total						(\$84,054.78)	
210 -	Total						(\$84,054.78)	
250	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		3	Mar 16, 2020	SYSTEM	(\$3,117.50)	
				3	Mar 16, 2020	SYSTEM	\$3,117.50	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0006) due to user kuehnb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	Apr 2, 2020	SYSTEM	(\$3,117.50)	
				4	Apr 2, 2020	SYSTEM	\$3,117.50	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0006) due to user kuehnb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Apr 16, 2020	SYSTEM	(\$3,117.50)	
				5	Apr 16, 2020	SYSTEM	\$3,117.50	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0004) due to user kuehnb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	May 3, 2020	SYSTEM	(\$3,117.50)	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0250	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material						Payment Estimate Exception 3 on the current Payment Estimate.
				7	May 18, 2020	SYSTEM	(\$3,117.50)	
				7	May 18, 2020	SYSTEM	\$3,117.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kuehnb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0250 -	· Total						\$0.00	
0270	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	Material		2	Mar 3, 2020	SYSTEM	(\$2,336.57)	
	MARKING PAINT, TYPE L BEADS			2	Mar 3, 2020	SYSTEM	\$2,336.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kuehnb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Mar 16, 2020	SYSTEM	(\$2,336.57)	
				3	Mar 16, 2020	SYSTEM	\$2,336.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kuehnb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				4	Apr 2, 2020	SYSTEM	(\$2,336.57)	
				4	Apr 2, 2020	SYSTEM	\$2,336.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kuehnb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				5	Apr 16, 2020	SYSTEM	(\$2,336.57)	
				5	Apr 16, 2020	SYSTEM	\$2,336.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kuehnb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	May 3, 2020	SYSTEM	(\$2,336.57)	
				6	May 3, 2020	SYSTEM	\$2,336.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kuehnb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	May 18, 2020	SYSTEM	(\$2,336.57)	
				7	May 18, 2020	SYSTEM	\$2,336.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kuehnb1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0270 -	· Total						\$0.00	
0290	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	Material		2	Mar 3, 2020	SYSTEM	(\$1,891.00)	
	MARKING PAINT, TYPE L BEADS			2	Mar 3, 2020	SYSTEM	\$1,891.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kuehnb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				3	Mar 16, 2020	SYSTEM	(\$1,891.00)	
				3	Mar 16, 2020	SYSTEM	\$1,891.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kuehnb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				4	Apr 2, 2020	SYSTEM	(\$1,891.00)	
				4	Apr 2, 2020	SYSTEM	\$1,891.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kuehnb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				5	Apr 16, 2020	SYSTEM	(\$1,891.00)	
				5	Apr 16, 2020	SYSTEM	\$1,891.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kuehnb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	May 3, 2020	SYSTEM	(\$1,891.00)	
				6	May 3, 2020	SYSTEM	\$1,891.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kuehnb1 overridding



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0290	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Material		7	May 18, 2020	SYSTEM	(\$1,891.00)	Payment Estimate Exception 7 on the current Payment Estimate.
	BEADS			7	May 18, 2020	SYSTEM	\$1,891.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kuehnb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				\$0.00	a aymont Edunate Exception to on the duront raymont Edunate.
	Material - Total						\$0.00	
0290 -	Total						\$0.00	
0360	MISC. 6" WHITE TEMPORARY PAVEMENT MARKING PAINT	Material		12	Aug 3, 2020	SYSTEM	(\$7,350.42)	
				12	Aug 3, 2020	SYSTEM	\$7,350.42	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kuehnb1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0360 -	Total						\$0.00	
0380	MISC. 6" YELLOW TEMPORARY PAVEMENT MARKING PAINT	Material		12	Aug 3, 2020	SYSTEM	(\$3,611.19)	
				12	Aug 3, 2020	SYSTEM	\$3,611.19	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0380 -	Total						\$0.00	
0420	12 IN. PIPE GROUP A	Material		2	Mar 3, 2020	SYSTEM	(\$28,050.00)	
			- Total				(\$28,050.00)	
	Material - Total						(\$28,050.00)	
	12 IN. PIPE GROUP A	MaterialCredit		3	Mar 16, 2020	SYSTEM	\$28,050.00	
			- Total				\$28,050.00	
0420 -	MaterialCredit - Total						\$28,050.00	
0420 -	ROCK DITCH CHECK	Material		2	Mar 3, 2020	SYSTEM	\$0.00 (\$4,560.00)	
				2	Mar 3, 2020	SYSTEM	\$4,560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kuehnb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				3	Mar 16, 2020	SYSTEM	(\$9,060.00)	
				3	Mar 16, 2020	SYSTEM	\$9,060.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kuehnb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				4	Apr 2, 2020	SYSTEM	(\$13,500.00)	
				4	Apr 2, 2020	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user kuehnb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				5	Apr 16, 2020	SYSTEM	(\$13,500.00)	
				5	Apr 16, 2020	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kuehnb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				6	May 3, 2020	SYSTEM	(\$13,500.00)	
				6	May 3, 2020	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kuehnb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				7	May 18, 2020	SYSTEM	(\$13,500.00)	
				7	May 18, 2020	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kuehnb1 overridding



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
0480	ROCK DITCH CHECK	Material						Payment Estimate Exception 44 on the current Payment Estimate.									
				8	Jun 2, 2020	SYSTEM	(\$13,500.00)										
				8	Jun 2, 2020	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kuehnb1 overridding Payment Estimate Exception 45 on the current Payment Estimate.									
				9	Jun 16, 2020	SYSTEM	(\$13,500.00)										
				9	Jun 16, 2020	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kuehnb1 overridding Payment Estimate Exception 42 on the current Payment Estimate.									
				10	Jul 2, 2020	SYSTEM	(\$13,500.00)										
				10	Jul 2, 2020	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user kuehnb1 overridding Payment Estimate Exception 39 on the current Payment Estimate.									
				11	Jul 16, 2020	SYSTEM	(\$13,500.00)										
				11	Jul 16, 2020	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kuehnb1 overridding Payment Estimate Exception 42 on the current Payment Estimate.									
				12	Aug 3, 2020	SYSTEM	(\$13,500.00)										
				12	Aug 3, 2020	SYSTEM	\$13,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user kuehnb1 overridding Payment Estimate Exception 46 on the current Payment Estimate.									
			- Total				\$0.00										
	Material - Total						\$0.00										
	ROCK DITCH CHECK	Other Item Adjustment	OVRN	4	Apr 2, 2020	KUEHNB1	(\$12,000.00)	Correction for over payment due to override of item overrun. Quantity will be corrected on change order.									
			OVRN - Tot	al			(\$12,000.00)										
	Other Item Adjustment - Total						(\$12,000.00)										
	ROCK DITCH CHECK	Overrun	Overrun	2	Mar 3, 2020	SYSTEM	(\$3,060.00)										
				2	Mar 3, 2020	SYSTEM	\$3,060.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 12 on the current Payment Estimate.									
				3	Mar 16, 2020	SYSTEM	(\$3,060.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
				3	Mar 16, 2020	SYSTEM	(\$4,500.00)										
				3	Mar 16, 2020	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 13 on the current Payment Estimate.									
				3	Mar 16, 2020	SYSTEM	\$3,060.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 13 on the current Payment Estimate.									
				4	Apr 2, 2020	SYSTEM	(\$7,560.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
				4	Apr 2, 2020	SYSTEM	(\$4,440.00)										
							4	Apr 2, 2020	SYSTEM	\$4,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 16 on the current Payment Estimate.						
										4	Apr 2, 2020	SYSTEM	\$7,560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 16 on the current Payment Estimate.			
		5	5	5	5	5	5	5	5	5	5	5	5	Apr 16, 2020	SYSTEM	(\$12,000.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
			5	5	Apr 16, 2020	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 16 on the current Payment Estimate.									
				6	May 3, 2020	SYSTEM	(\$12,000.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
				6	May 3, 2020	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 19 on the current Payment Estimate.									



					-			
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0480	ROCK DITCH CHECK	Overrun	Overrun	7	May 18, 2020	SYSTEM	(\$12,000.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	May 18, 2020	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 48 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$12,000.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Jun 2, 2020	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 49 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$12,000.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Jun 16, 2020	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 46 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$12,000.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Jul 2, 2020	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 43 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$12,000.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				11	Jul 16, 2020	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 46 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$12,000.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Aug 3, 2020	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 50 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0480 -	Total						(\$12,000.00)	
0500	SILT FENCE	Material		2	Mar 3, 2020	SYSTEM	(\$5,340.00)	
				2	Mar 3, 2020	SYSTEM	\$5,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kuehnb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
)500 -	- Total							
							\$0.00	
0510	MGS GUARDRAIL	Construction Stockpile		2	Mar 3, 2020	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
0510	MGS GUARDRAIL			2 11		SYSTEM SYSTEM	<b>\$0.00</b> \$21,496.46	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0510	MGS GUARDRAIL		- Total		2020 Jul 16,		<b>\$0.00</b> \$21,496.46	
0510	MGS GUARDRAIL		- Total		2020 Jul 16,		\$0.00 \$21,496.46 (\$3,704.31)	
			- Total		2020 Jul 16,		\$0.00 \$21,496.46 (\$3,704.31) \$17,792.15	
0510 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION		- Total		2020 Jul 16,		\$0.00 \$21,496.46 (\$3,704.31) \$17,792.15 \$17,792.15	
0510 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH	Stockpile	- Total	11	2020 Jul 16, 2020 Mar 3,	SYSTEM	\$0.00 \$21,496.46 (\$3,704.31) \$17,792.15 \$17,792.15 \$17,792.15	Payment Estimate Item Adjustment generated Stockpile Transaction
0510 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION	Stockpile	- Total	2	2020 Jul 16, 2020 Mar 3, 2020 Jul 16,	SYSTEM	\$0.00 \$21,496.46 (\$3,704.31) \$17,792.15 \$17,792.15 \$17,792.15 \$6,467.50	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0510 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION	Stockpile		2	2020 Jul 16, 2020 Mar 3, 2020 Jul 16,	SYSTEM	\$0.00 \$21,496.46 (\$3,704.31) \$17,792.15 \$17,792.15 \$17,792.15 \$6,467.50 (\$2,587.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0510 - 0520	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Stockpile		2	2020 Jul 16, 2020 Mar 3, 2020 Jul 16,	SYSTEM	\$0.00 \$21,496.46 (\$3,704.31) \$17,792.15 \$17,792.15 \$6,467.50 (\$2,587.00) \$3,880.50	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0520	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Stockpile		2	2020 Jul 16, 2020 Mar 3, 2020 Jul 16,	SYSTEM	\$0.00 \$21,496.46 (\$3,704.31) \$17,792.15 \$17,792.15 \$6,467.50 (\$2,587.00) \$3,880.50	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0510 - 0520 0520 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total Total	Stockpile Construction Stockpile Construction		11 2 11	2020 Jul 16, 2020 Mar 3, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$21,496.46 (\$3,704.31) \$17,792.15 \$17,792.15 \$6,467.50 (\$2,587.00) \$3,880.50 \$3,880.50 \$3,880.50	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0510 - 0520 0520 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total Total	Stockpile Construction Stockpile Construction		11 2 11 2	2020 Jul 16, 2020 Mar 3, 2020 Jul 16, 2020 Mar 3, 2020 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$21,496.46 (\$3,704.31) \$17,792.15 \$17,792.15 \$6,467.50 (\$2,587.00) (\$2,587.00) \$3,880.50 \$3,880.50 \$3,880.50 \$3,880.50	Payment Estimate Item Adjustment generated Stockpile Transaction
0510 - 0520 0520 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total Total	Stockpile Construction Stockpile Construction	- Total	11 2 11 2	2020 Jul 16, 2020 Mar 3, 2020 Jul 16, 2020 Mar 3, 2020 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$21,496.46 (\$3,704.31) \$17,792.15 \$17,792.15 \$6,467.50 (\$2,587.00) (\$2,587.00) \$3,880.50 \$3,880.50 \$3,880.50 \$3,880.50 \$3,880.50 (\$532.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
0510 - 0520 - 0520 -	Construction Stockpile - Total Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total Total MGS END ANCHOR	Stockpile Construction Stockpile Construction	- Total	11 2 11 2	2020 Jul 16, 2020 Mar 3, 2020 Jul 16, 2020 Mar 3, 2020 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$21,496.46 (\$3,704.31) \$17,792.15 \$17,792.15 \$6,467.50 (\$2,587.00) (\$2,587.00) \$3,880.50 \$3,880.50 \$3,880.50 \$3,880.50 \$3,880.50 (\$532.00) (\$532.00)	Payment Estimate Item Adjustment generated Stockpile Transaction



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0540	TERMINAL (MASH)	Stockpile			2020			
				11	Jul 16, 2020	SYSTEM	(\$1,510.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$4,530.00	
	Construction Stockpile - Total						\$4,530.00	
540	- Total						\$4,530.00	
)560	MISC. TEMPORARY MEDIAN CROSSOVER - EAST	Material		3	Mar 16, 2020	SYSTEM	(\$150,000.00)	
				3	Mar 16, 2020	SYSTEM	\$150,000.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0010) due to user kuehnb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				4	Apr 2, 2020	SYSTEM	(\$150,000.00)	
				4	Apr 2, 2020	SYSTEM	\$150,000.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0009) due to user kuehnb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Apr 16, 2020	SYSTEM	(\$150,000.00)	
				5	Apr 16, 2020	SYSTEM	\$150,000.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0007) due to user kuehnb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	May 3, 2020	SYSTEM	(\$150,000.00)	
				6	May 3, 2020	SYSTEM	\$150,000.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0007) due to user kuehnb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
560	- Total						\$0.00	
670	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		7	May 18, 2020	SYSTEM	(\$23,072.50)	
				7	May 18, 2020	SYSTEM	\$23,072.50	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0007) due to user kuehnb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$46,145.00)	
				8	Jun 2, 2020	SYSTEM	\$46,145.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0004) due to user kuehnb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$46,145.00)	
				9	Jun 16, 2020	SYSTEM	\$46,145.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user kuehnb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$46,145.00)	
				10	Jul 2, 2020	SYSTEM	\$46,145.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0006) due to user kuehnb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$46,145.00)	
				11	Jul 16, 2020	SYSTEM	\$46,145.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0003) due to user kuehnb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$46,145.00)	
				12	Aug 3, 2020	SYSTEM	\$46,145.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0006) due to user kuehnb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
670	- Total						\$0.00	
)690	CLASS B-2 CONCRETE	Material		7	May 18, 2020	SYSTEM	(\$72,450.00)	
				7	May 18,	SYSTEM	\$72,450.00	This adjustment offsets the original system-generated Overrun Paymen



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0690	CLASS B-2 CONCRETE	Material			2020			Estimate Item Adjustment (0008) due to user kuehnb1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$116,100.00)	
				8	Jun 2, 2020	SYSTEM	\$116,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kuehnb1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$164,925.00)	
				9	Jun 16, 2020	SYSTEM	\$164,925.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$309,375.00)	
				10	Jul 2, 2020	SYSTEM	\$309,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$359,325.00)	
				11	Jul 16, 2020	SYSTEM	\$359,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$359,325.00)	
				12	Aug 3, 2020	SYSTEM	\$359,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kuehnb1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0690 -	Total						\$0.00	
0720	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		4	Apr 2, 2020	SYSTEM	(\$1,960.00)	
				4	Apr 2, 2020	SYSTEM	\$1,960.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kuehnb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				5	Apr 16, 2020	SYSTEM	(\$11,830.00)	
				5	Apr 16, 2020	SYSTEM	\$11,830.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kuehnb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				6	May 3, 2020	SYSTEM	(\$17,477.60)	
				6	May 3, 2020	SYSTEM	\$17,477.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kuehnb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				7	May 18, 2020	SYSTEM	(\$17,477.60)	
				7	May 18, 2020	SYSTEM	\$17,477.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kuehnb1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0720 -	Total						\$0.00	
0730	HALF-SOLE REPAIR	Material		4	Apr 2, 2020	SYSTEM	(\$1,592.50)	
				4	Apr 2, 2020	SYSTEM	\$1,592.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kuehnb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				5	Apr 16, 2020	SYSTEM	(\$1,592.50)	
				5	Apr 16, 2020	SYSTEM	\$1,592.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kuehnb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				6	May 3, 2020	SYSTEM	(\$2,756.25)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0730	HALF-SOLE REPAIR	Material			2020			Estimate Item Adjustment (0009) due to user kuehnb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				7	May 18, 2020	SYSTEM	(\$2,756.25)	
				7	May 18, 2020	SYSTEM	\$2,756.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kuehnb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$2,756.25)	
				8	Jun 2, 2020	SYSTEM	\$2,756.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kuehnb1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$4,931.15)	
				9	Jun 16, 2020	SYSTEM	\$4,931.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user kuehnb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$7,514.15)	
				10	Jul 2, 2020	SYSTEM	\$7,514.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kuehnb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$7,514.15)	
				11	Jul 16, 2020	SYSTEM	\$7,514.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kuehnb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$9,609.95)	
				12	Aug 3, 2020	SYSTEM	\$9,609.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kuehnb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total					01/0751/	\$0.00	
0740	SLAB EDGE REPAIR (BRIDGES)	Material		4	Apr 2, 2020	SYSTEM	(\$8,190.00)	
				4	Apr 2, 2020	SYSTEM	\$8,190.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kuehnb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				5	Apr 16, 2020	SYSTEM	(\$35,840.00)	
				5	Apr 16, 2020	SYSTEM	\$35,840.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kuehnb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				6	May 3, 2020	SYSTEM	(\$47,633.60)	
				6	May 3, 2020	SYSTEM	\$47,633.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kuehnb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				7	May 18, 2020	SYSTEM	(\$47,633.60)	
				7	May 18, 2020	SYSTEM	\$47,633.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kuehnb1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$47,633.60)	
				8	Jun 2, 2020	SYSTEM	\$47,633.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kuehnb1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$47,633.60)	
					2020			
				9	Jun 16, 2020	SYSTEM	\$47,633.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user kuehnb1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
			- Total	9	Jun 16,	SYSTEM	\$47,633.60 \$0.00	Estimate Item Adjustment (0008) due to user kuehnb1 overridding



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0740 -	Total						\$0.00	
0770	REINFORCING STEEL (EPOXY COATED)	Material		7	May 18, 2020	SYSTEM	(\$6,001.43)	
				7	May 18, 2020	SYSTEM	\$6,001.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kuehnb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$9,805.01)	
				8	Jun 2, 2020	SYSTEM	\$9,805.01	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kuehnb1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$13,984.88)	
				9	Jun 16, 2020	SYSTEM	\$13,984.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kuehnb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$26,578.73)	
				10	Jul 2, 2020	SYSTEM	\$26,578.73	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user kuehnb1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$30,746.17)	
				11	Jul 16, 2020	SYSTEM	\$30,746.17	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kuehnb1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$30,746.17)	
				12	Aug 3, 2020	SYSTEM	\$30,746.17	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kuehnb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0770 -	Total						\$0.00	
0800	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	Material		2	Mar 3, 2020	SYSTEM	(\$503,149.50)	
				2	Mar 3, 2020	SYSTEM	\$503,149.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kuehnb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					Mar 16, 2020	SYSTEM	(\$798,650.00)	
				3	Mar 16, 2020	SYSTEM	\$798,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kuehnb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0800 -							\$0.00	
0810	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material		6	May 3, 2020	SYSTEM	(\$135,166.50)	
				6	May 3, 2020	SYSTEM	\$135,166.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kuehnb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0810 -							\$0.00	
0850	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material		4	Apr 2, 2020	SYSTEM	(\$19,576.00)	
				4	Apr 2, 2020	SYSTEM	\$19,576.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kuehnb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				5	Apr 16, 2020	SYSTEM	(\$25,594.00)	
				5	Apr 16, 2020	SYSTEM	\$25,594.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kuehnb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0850	FIELD APPLICATION OF INORGANIC ZINC PRIMER	Material	51	6	May 3, 2020	SYSTEM	(\$62,660.00)	
				6	May 3, 2020	SYSTEM	\$62,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kuehnb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				7	May 18, 2020	SYSTEM	(\$79,519.00)	
				7	May 18, 2020	SYSTEM	\$79,519.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kuehnb1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$152,630.00)	
				8	Jun 2, 2020	SYSTEM	\$152,630.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user kuehnb1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$178,828.00)	
				9	Jun 16, 2020	SYSTEM	\$178,828.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kuehnb1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$263,516.00)	
				10	Jul 2, 2020	SYSTEM	\$263,516.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user kuehnb1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$288,854.00)	
				11	Jul 16, 2020	SYSTEM	\$288,854.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kuehnb1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$313,566.00)	
				12	Aug 3, 2020	SYSTEM	\$313,566.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kuehnb1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
	- Total						\$0.00	
0050	Material - Total						\$0.00	
0850 -	- Total MISC. APPROACH GIRDER CRACK REPAIRS	Material		11	Jul 16, 2020	SYSTEM	\$0.00 (\$3,700.00)	
				11	Jul 16, 2020	SYSTEM	\$3,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kuehnb1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$16,650.00)	
				12	Aug 3, 2020	SYSTEM	\$16,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kuehnb1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0910 - 0920	- Total MISC. APPROACH SPAN	Material		6	May 3,	SYSTEM	\$0.00 (\$51,000.00)	
-	RETROFIT - LATERAL BRACING SHELF			6	2020 May 3,	SYSTEM	\$51,000.00	This adjustment offsets the original system-generated Overrun Payment
					2020		. ,	Estimate Item Adjustment (0013) due to user kuehnb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				7	May 18, 2020	SYSTEM	(\$265,500.00)	
				7	May 18, 2020	SYSTEM	\$265,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kuehnb1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$327,000.00)	
				8	Jun 2, 2020	SYSTEM	\$327,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kuehnb1 overridding Payment Estimate Exception 41 on the current Payment Estimate.



_ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
920	MISC. APPROACH SPAN RETROFIT - LATERAL BRACING	Material	51	9	Jun 16, 2020	SYSTEM	(\$345,000.00)	
	SHELF			9	Jun 16, 2020	SYSTEM	\$345,000.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0011) due to user kuehnb1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$345,000.00)	
				10	Jul 2, 2020	SYSTEM	\$345,000.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0011) due to user kuehnb1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$345,000.00)	
				11	Jul 16, 2020	SYSTEM	\$345,000.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0017) due to user kuehnb1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$358,500.00)	
				12	Aug 3, 2020	SYSTEM	\$358,500.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0014) due to user kuehnb1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
20	- Total						\$0.00	
930	MISC. APPROACH SPAN RETROFIT - STIFFENING CONNECTION	Material		6	May 3, 2020	SYSTEM	(\$16,000.00)	
				6	May 3, 2020	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0014) due to user kuehnb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				7	May 18, 2020	SYSTEM	(\$140,400.00)	
				7	May 18, 2020	SYSTEM	\$140,400.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0015) due to user kuehnb1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$228,400.00)	
				8	Jun 2, 2020	SYSTEM	\$228,400.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0015) due to user kuehnb1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$460,000.00)	
				9	Jun 16, 2020	SYSTEM	\$460,000.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0012) due to user kuehnb1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$520,000.00)	
				10	Jul 2, 2020	SYSTEM	\$520,000.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0012) due to user kuehnb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$520,000.00)	
				11	Jul 16, 2020	SYSTEM	\$520,000.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0016) due to user kuehnb1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$612,800.00)	
				12	Aug 3, 2020	SYSTEM	\$612,800.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0015) due to user kuehnb1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	
960	MISC. SPECIAL SURFACE TREATMENT - LOWER HANGER JOINT GUSSET	Material		7	May 18, 2020	SYSTEM	(\$480.00)	
	PLATE			7	May 18, 2020	SYSTEM	\$480.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0016) due to user kuehnb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0960	MISC. SPECIAL SURFACE TREATMENT - LOWER	Material		8	Jun 2, 2020	SYSTEM	(\$480.00)	
	HANGER JOINT GUSSET PLATE			8	Jun 2, 2020	SYSTEM	\$480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kuehnb1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$960.00)	
				9	Jun 16, 2020	SYSTEM	\$960.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kuehnb1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
960 -	Total						\$0.00	
0970	MISC. SPECIAL SURFACE TREATMENT - LOWER SPLICE JOINT GUSSET PLATE	Material		7	May 18, 2020	SYSTEM	(\$2,730.00)	
	JUINT GUSSET FLATE			7	May 18, 2020	SYSTEM	\$2,730.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user kuehnb1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$2,730.00)	
				8	Jun 2, 2020	SYSTEM	\$2,730.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kuehnb1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$5,070.00)	
				9	Jun 16, 2020	SYSTEM	\$5,070.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kuehnb1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
970 -	Total						\$0.00	
0980	MISC. SPECIAL SURFACE TREATMENT - TRUSS	Material		7	May 18, 2020	SYSTEM	(\$12,800.00)	
	MEMBERS		7	May 18, 2020	SYSTEM	\$12,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	
				8	Jun 2, 2020	SYSTEM	(\$12,800.00)	
				8	Jun 2, 2020	SYSTEM	\$12,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user kuehnb1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$22,400.00)	
				9	Jun 16, 2020	SYSTEM	\$22,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user kuehnb1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0980 -	Total						\$0.00	
0990	MISC. TRUSS CRACK REPAIR	Material		12	Aug 3, 2020	SYSTEM	(\$4,500.00)	
				12	Aug 3, 2020	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kuehnb1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
) <mark>990</mark> - 1000		Material		12	Aug 3,	SYSTEM	<b>\$0.00</b> (\$3,500.00)	
	RETROFIT - FLOORBEAMS			12	2020 Aug 3,	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment
					2020			Estimate Item Adjustment (0017) due to user kuehnb1 overridding
								Payment Estimate Exception 42 on the current Payment Estimate.
	Material - Total		- Total				\$0.00 \$0.00	Payment Estimate Exception 42 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1000 ·	· Total						\$0.00	
1010	MISC. TRUSS PLATED RETROFIT - LATERAL BRACING	Material		7	May 18, 2020	SYSTEM	(\$7,000.00)	
	MEMBERS			7	May 18, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kuehnb1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$7,000.00)	
				8	Jun 2, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kuehnb1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$7,000.00)	
				9	Jun 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user kuehnb1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$7,000.00)	
				10	Jul 2, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user kuehnb1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$7,000.00)	
				11	Jul 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kuehnb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$17,150.00)	
				12	Aug 3, 2020	SYSTEM	\$17,150.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1010 ·	Total						\$0.00	
1020	MISC. TRUSS PLATED Mate RETROFIT - LOWER SPLICE JOINT GUSSET PLATE	Material		10	Jul 2, 2020	SYSTEM	(\$16,000.00)	
				10	Jul 2, 2020	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user kuehnb1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$40,000.00)	
				11	Jul 16, 2020	SYSTEM	\$40,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kuehnb1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$40,000.00)	
				12	Aug 3, 2020	SYSTEM	\$40,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kuehnb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1020	Total						\$0.00	
1030	MISC. TRUSS PLATED RETROFIT - SWAY BRACING	Material		11	Jul 16, 2020	SYSTEM	(\$2,500.00)	
				11	Jul 16, 2020	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user kuehnb1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$2,500.00)	
				12	Aug 3, 2020	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	



Line	Description	Adjustment	Other	Est. Number	Created Date	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
1040	MISC. TRUSS PLATED RETROFIT - UPPER & LOWER	Material		7	May 18, 2020	SYSTEM	(\$16,000.00)	
	LATERAL BRACING GUSSET PLATE			7	May 18, 2020	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$16,000.00)	
				8	Jun 2, 2020	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$16,000.00)	
				9	Jun 16, 2020	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0017) due to user kuehnb1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$16,000.00)	
				10	Jul 2, 2020	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0015) due to user kuehnb1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$16,000.00)	
				11	Jul 16, 2020	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$65,200.00)	
				12	Aug 3, 2020	SYSTEM	\$65,200.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0021) due to user kuehnb1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
040 -	Total						\$0.00	
050	MISC. TRUSS PLATED RETROFIT - VERTICALS & DIAGONALS IN SPLASH ZONE	Material		8	Jun 2, 2020	SYSTEM	(\$36,000.00)	
				8	Jun 2, 2020	SYSTEM	\$36,000.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0017) due to user kuehnb1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$81,000.00)	
				9	Jun 16, 2020	SYSTEM	\$81,000.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$360,000.00)	
				10	Jul 2, 2020	SYSTEM	\$360,000.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0016) due to user kuehnb1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$549,000.00)	
				11	Jul 16, 2020	SYSTEM	\$549,000.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$652,500.00)	
				12	Aug 3, 2020	SYSTEM	\$652,500.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0022) due to user kuehnb1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
050 -	Total						\$0.00	
060	MISC. UPPER GUIDE PIN RETROFIT	Material		11	Jul 16, 2020	SYSTEM	(\$18,000.00)	
				11	Jul 16, 2020	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0015) due to user kuehnb1 overridding Payment Estimate Exception 39 on the current Payment Estimate.



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
060	MISC. UPPER GUIDE PIN RETROFIT	Material		12	Aug 3, 2020	SYSTEM	(\$18,000.00)	
				12	Aug 3, 2020	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0023) due to user kuehnb1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
060 -	- Total						\$0.00	
070	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	Material		9	Jun 16, 2020	SYSTEM	(\$10,305.00)	
				9	Jun 16, 2020	SYSTEM	\$10,305.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0019) due to user kuehnb1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$14,432.00)	
				10	Jul 2, 2020	SYSTEM	\$14,432.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0017) due to user kuehnb1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$26,128.00)	
				11	Jul 16, 2020	SYSTEM	\$26,128.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0023) due to user kuehnb1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$30,250.00)	
				12	Aug 3, 2020	SYSTEM	\$30,250.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0024) due to user kuehnb1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
070	- Total						\$0.00	
005	TEMPORARY LONG-TERM Ma RUMBLE STRIPS	Material		8	Jun 2, 2020	SYSTEM	(\$12,600.00)	
					2020			
				8	Jun 2, 2020	SYSTEM	\$12,600.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				8 9	Jun 2,	SYSTEM	\$12,600.00	Estimate Item Adjustment (0020) due to user kuehnb1 overridding
					Jun 2, 2020 Jun 16,			Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				9	Jun 2, 2020 Jun 16, 2020 Jun 16,	SYSTEM	(\$12,600.00)	Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding
				9 9	Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2,	SYSTEM SYSTEM	(\$12,600.00) \$12,600.00	Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				9 9 10	Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2,	SYSTEM SYSTEM SYSTEM	(\$12,600.00) \$12,600.00 (\$12,600.00)	Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kuehnb1 overridding
				9 9 10 10	2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020 Jul 2, 2020 Jul 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,600.00) \$12,600.00 (\$12,600.00) \$12,600.00	Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				9 9 10 10 11	2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020 Jul 2, 2020 Jul 2, 2020 Jul 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,600.00) \$12,600.00 (\$12,600.00) \$12,600.00 (\$12,600.00) (\$12,600.00)	Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymert Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymert Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymert Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymert Estimate Item Adjustment (0024) due to user kuehnb1 overridding
				9 9 10 10 11 11	2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,600.00) \$12,600.00) (\$12,600.00) \$12,600.00) (\$12,600.00) \$12,600.00	Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
			- Total	9 9 10 10 11 11 12	Jun 2,           Jun 16,           2020           Jun 16,           2020           Jul 2,           2020           Jul 2,           2020           Jul 4,           2020           Jul 2,           2020           Jul 4,           2020           Jul 16,           2020           Jul 16,           2020           Jul 16,           2020           Jul 16,           2020           Jul 3,           Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,600.00) \$12,600.00) (\$12,600.00) \$12,600.00) (\$12,600.00) \$12,600.00	Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0024) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	Material - Total		- Total	9 9 10 10 11 11 12	Jun 2,           Jun 16,           2020           Jun 16,           2020           Jul 2,           2020           Jul 2,           2020           Jul 4,           2020           Jul 2,           2020           Jul 4,           2020           Jul 16,           2020           Jul 16,           2020           Jul 16,           2020           Jul 16,           2020           Jul 3,           Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,600.00) \$12,600.00 (\$12,600.00) \$12,600.00 (\$12,600.00) \$12,600.00 (\$12,600.00) (\$12,600.00)	Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
005 -			- Total	9 9 10 10 11 11 12	Jun 2,           Jun 16,           2020           Jun 16,           2020           Jul 2,           2020           Jul 2,           2020           Jul 4,           2020           Jul 2,           2020           Jul 4,           2020           Jul 16,           2020           Jul 16,           2020           Jul 16,           2020           Jul 16,           2020           Jul 3,           Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,600.00) \$12,600.00 (\$12,600.00) \$12,600.00 (\$12,600.00) \$12,600.00 (\$12,600.00) \$12,600.00	Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	Material - Total	Material	- Total	9 9 10 10 11 11 12	Jun 2,           Jun 16,           2020           Jun 16,           2020           Jul 2,           2020           Jul 2,           2020           Jul 4,           2020           Jul 2,           2020           Jul 4,           2020           Jul 16,           2020           Jul 16,           2020           Jul 16,           2020           Jul 16,           2020           Jul 3,           Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,600.00) \$12,600.00) (\$12,600.00) \$12,600.00) (\$12,600.00) (\$12,600.00) (\$12,600.00) \$12,600.00] \$12,600.00	Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0024) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	Material - Total - Total - Total	Material	- Total	9 9 10 10 11 11 12 12	2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Jul 16, 2020 Jul 16, 2020 Jul 3, 2020 Aug 3, 2020 Aug 3, 2020 Jul 2, 2020 Jul 2, 20 Jul 2, 20 J	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,600.00) \$12,600.00) (\$12,600.00) (\$12,600.00) (\$12,600.00) (\$12,600.00) (\$12,600.00) (\$12,600.00) (\$12,600.00] (\$12,600.00] (\$12,600.00] (\$12,600.00]	Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0018) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0024) due to user kuehnb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5006	TEMPORARY RAISED PAVEMENT MARKER	Material		9	Jun 16, 2020	SYSTEM	\$567.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user kuehnb1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				10	Jul 2, 2020	SYSTEM	(\$567.00)	
				10	Jul 2, 2020	SYSTEM	\$567.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user kuehnb1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$567.00)	
				11	Jul 16, 2020	SYSTEM	\$567.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user kuehnb1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				12	Aug 3, 2020	SYSTEM	(\$567.00)	
				12	Aug 3, 2020	SYSTEM	\$567.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user kuehnb1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5006 -	Total						\$0.00	
Overal	ll - Total						(\$70,963.77)	