

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 4, 2020

Progress Estimate Number   Contract ID	191213-F03	Pay Period Start July 16, 2020	Original Contract Amount \$8,245,000.00
10 Prime Contr	ractor N.B. West Contracting	g Company Pay Period End August 1, 202	0 Net Change Order Amount \$213,048.55
10			Current Contract Amount \$8,458,048.55

Approval Date		By User
August 4, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by	gummer1
August 4, 2020	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	janssm
August 5, 2020	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete				
October 31, 2021	October 31, 2021		66.24%				

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 10			
	This Estimate	Previous	To Date
191213-F03			
Total Posted Items Pay	\$532,569.74	\$5,070,382.35	\$5,602,952.09
Gross Item Adjustments	\$144,111.13	(\$343,778.41)	(\$199,667.28)
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$4,726,603.94	\$5,403,284.81
Contract Total Payable This Estimate:	\$676,680.87		

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3263	0800	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	TONS	\$90.000	2,062.39	\$185,615.10
	0110	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	TONS	\$100.000	1,638.27	\$163,827.00
	0130	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	TONS	\$104.000	678.58	\$70,572.32
	0150	4071005	TACK COAT	GAL	\$2.000	2,887	\$5,774.00
	0230	6116010A	SLOPE PROTECTION	SQYD	\$160.000	76	\$12,160.00
	0690	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$3.000	31,540.44	\$94,621.32

 Project J6i3263 - Total
 \$532,569.74

 Overall - Total
 \$532,569.74

## Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		stments Exist on Contract						
Line Item	Adjust	tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3263	0800	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	Asphalt Cement Price Adjustment	Asphalt for second period of July-20 Tons laid was 2062.39tons at 3.9% AC%			(\$4,825.99)
	0110	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	Overrun			-439.15	\$100.00	(\$43,915.00)
	0110	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	Other Item Adjustment	Asphalt Cement Price Adjustment	Deduction on Second Period July - 2020 Total Tons equal 2316.85 Tons layed at 3.9% AC			(\$5,421.43)
	0120	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Material			-9,660.49	\$95.00	(\$917,746.55)
	0120	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	9,660.49	\$95.00	\$917,746.55

Revision 4/1/2020 Page 1 of 17

## **Missouri Department of Transportation Contractor's Pay Estimate Summary**

Pay Estimate Created Date: August 4, 2020

Contract ID 191213-F03 Pay Period Start July 16, 2020 Original Contract Amount \$8,245,000.00 Prime Contractor N.B. West Contracting Company Pay Period End August 1, 2020 Net Change Order Amount \$213,048.55 Current Contract Amount \$8,458,048.55 **Progress Estimate Number** 10

.4	Line	Itom Docarintian	A dimeter and	Othor Item	Comments	A divetor of	Line Herr	A divistres and
er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3	0120	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Other Item Adjustment	Overrun Re- adjustment	Readjusting dollar amount from Change Order 1 previous deduction on override. Estimate no 7 and 8, from CO 1			\$198,273.55
	0170	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	Material			-1,296.7	\$90.00	(\$116,703.00
	0170	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user gummer1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1,296.7	\$90.00	\$116,703.00
	0180	CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-122.25	\$102.00	(\$12,469.50
	0180	CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	122.25	\$102.00	\$12,469.50
	0230	SLOPE PROTECTION	Overrun			-76	\$160.00	(\$12,160.00
	0230	SLOPE PROTECTION	Material			-90	\$160.00	(\$14,400.00)
	0230	SLOPE PROTECTION Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 19 on the current Payment Estimate.	76	\$160.00	\$12,160.00	
0	0230	SLOPE PROTECTION	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	90	\$160.00	\$14,400.00
	0280	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-110.7	\$520.00	(\$57,564.00
	0280	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user gummer1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	110.7	\$520.00	\$57,564.00
	0320	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-233	\$3.00	(\$699.00)
	0320	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user gummer1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	233	\$3.00	\$699.00
	0440	CONCRETE TRAFFIC BARRIER, TYPE D	Material			-263	\$180.00	(\$47,340.00)
	0440	CONCRETE TRAFFIC BARRIER, TYPE D	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user gummer1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	263	\$180.00	\$47,340.00
1	0450	CONCRETE TRAFFIC BARRIER, TYPE D (MODIFIED)	Material			-1,030	\$118.00	(\$121,540.00)

Revision 4/1/2020 Page 2 of 17



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 4, 2020

Progress Estimate Number
10 Contract ID 191213-F03 Pay Period Start July 16, 2020 Original Contract Amount \$8,245,000.00
Prime Contractor N.B. West Contracting Company Pay Period End August 1, 2020 Net Change Order Amount \$213,048.55
Current Contract Amount \$8,458,048.55

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount										
J6l3263	0450	CONCRETE TRAFFIC BARRIER, TYPE D (MODIFIED)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user gummer1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	1,030	\$118.00	\$121,540.00										
	0960	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	Material			-2,620	\$3.45	(\$9,039.00)										
	0960	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user gummer1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	2,620	\$3.45	\$9,039.00										
Total								\$144,111.13										

Revision 4/1/2020 Page 3 of 17



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Со	ntract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6I3263	I 270-5(357)	Coldmill and resurface	I-270	ST LOUIS	from I-70 to Page Avenue		
Totals by	Job Numbers	5					
J6I3263					This Estimate	Previous	To Date
		Item Pay			\$532,569.74	\$5,070,382.35	\$5,602,952.09
	Gross I	tem Adjustme			\$144,111.13	(\$343,778.41)	(\$199,667.28)
			Gross	Item Pay	\$676,680.87	\$4,726,603.94	\$5,403,284.81
		ve .			\$0.00	\$0.00	\$0.00
	Incentiv				\$0.00	\$0.00	\$0.00
	Disince	ntive			\$0.00	φ0.00	ψ0.00
	Disince	ntive ited Damages			\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 4 of 17



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

**Exceptions (Discrepancies) This Estimate Period** 

Exceptions / Discrepencies	Evalenation		
Exceptions / Blossoperioles	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 4030116, Project Item Line Number 0120, Material Set 403011696, Material 0403SP125B - Superpave 12.5 mm, Des B, Acceptance Action Generic AspHigh is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 5021310, Project Item Line Number 0170, Material Set 502131096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 5021310, Project Item Line Number 0170, Material Set 502131096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 5021310, Project Item Line Number 0170, Material Set 502131096, Material 0501CCPAQCQA - Concrete, Payment contractor mit or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 5021331, Project Item Line Number 0180, Material Set 502133196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 5021331, Project Item Line Number 0180, Material Set 502133196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 6116010A, Project Item Line Number 0230, Material Set 6116010A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 6116010A, Project Item Line Number 0230, Material Set 6116010A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 6116010A, Project Item Line Number 0230, Material Set 6116010A96, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 6116010A, Project Item Line Number 0230, Material Set 6116010A96, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6i3263, Item 6116010A, Project Item Line Number 0230, Material Set 6116010A96, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 6131010, Project Item Line Number 0280, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6i3263, Item 6131015, Project Item Line Number 0320, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 6173100, Project Item Line Number 0440, Material Set 617310096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 6173101, Project Item Line Number 0450, Material Set 617310196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 6173101, Project Item Line Number 0450, Material Set 617310196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3263, Item 6173101, Project Item Line Number 0450, Material Set 617310196, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3263, Item 9017404, Project Item Line Number 0960, Material Set 901740496, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-F03, Contract Project J6l3263, Project Item Line Number 0230, Contract Line Item Number 0230, Item 6116010A, Minor Item.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-F03, Contract Project J6l3263, Project Item Line Number 0240, Contract Line Item Number 0240, Item 6122019, Minor Item.	No Remark was entered by Engineer	gummer1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-F03, Contract Project J6l3263, Project Item Line Number 0110, Contract Line Item Number 0110, Item 4030109, Minor Item.	No Remark was entered by Engineer	gummer1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-F03, Contract Project J6l3263, Project Item Line Number 0140, Contract Line Item Number 0140, Item 4039910, Minor Item.	No Remark was entered by Engineer	gummer1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-F03, Contract Project J6l3263, Project Item Line Number 0360, Contract Line Item Number 0360, Item 6161008, Minor Item.	No Remark was entered by Engineer	gummer1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-F03, Contract Project J6l3263, Project Item Line Number 0750, Contract Line Item Number 0750, Item 6262000A, Minor Item.	No Remark was entered by Engineer	gummer1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-F03, Contract Project J6i3263, Project Item Line Number 0860, Contract Line Item Number 0860, Item 6061060, Minor Item.	No Remark was entered by Engineer	gummer1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-F03, Contract Project J6l3263, Project Item Line Number 0910, Contract Line Item Number 0910, Item 6061080, Minor Item.	No Remark was entered by Engineer	gummer1	Acknowledged

Revision 4/1/2020 Page 5 of 17



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-F03	J6I3263	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.58	\$290,000.00	\$169,650.00
		0001	0020	2031000	CLASS A EXCAVATION	768.00	0.00	768.00	CUYD	749.30	\$18.00	\$13,487.40
		0001	0030	2036000	COMPACTING EMBANKMENT	27.00	0.00	27.00	CUYD	27.00	\$68.00	\$1,836.00
		0001	0040	2037075	COMPACTING IN CUT	14.10	0.00	14.10	STA	12.50	\$120.00	\$1,500.00
		0001	0050	2063000	CLASS 3 EXCAVATION	26.00	0.00	26.00	CUYD	26.00	\$25.00	\$650.00
		0001	0060	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	3,500.00	0.00	3,500.00	LF	3,000.00	\$9.00	\$27,000.00
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,768.00	0.00	1,768.00	SQYD	1,768.00	\$8.50	\$15,028.00
		0001	0800	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	4,365.20	0.00	4,365.20	TONS	2,784.60	\$90.00	\$250,614.00
		0001	0090	4019901	MISC.INFRARED SCANNING	1.00	0.00	1.00	LS	0.66	\$10,000.00	\$6,600.00
		0001	0100	4019901	MISC.INTELLIGENT COMPACTION	1.00	0.00	1.00	LS	0.66	\$10,000.00	\$6,600.00
		0001	0110	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	2,590.50	0.00	2,590.50	TONS	3,029.65	\$100.00	\$302,965.00
		0001	0120	4030116	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	7,573.40	2,087.09	9,660.49	TONS	9,660.49	\$95.00	\$917,746.55
		0001	0130	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	13,249.80	0.00	13,249.80	TONS	6,934.08	\$104.00	\$721,144.32
		0001	0140	4039910	MISC.HIGH TENSILE STRENGTH SYNTHETIC FIBER ASPHALTIC PAVEMENT PG 76-22 (SP125BSM)	7,863.70	0.00	7,863.70	TONS	8,291.78	\$115.00	\$953,554.70
		0001	0150	4071005	TACK COAT	38,394.00	0.00	38,394.00	GAL	18,655.00	\$2.00	\$37,310.00
		0001	0160	4079912	MISC.POLYMER MODIFIED EMULSION MEMBRANE (PEM OR CPEM)	7,799.00	0.00	7,799.00	GAL	0.00	\$2.35	\$0.00
		0001	0170	5021310	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	1,296.70	0.00	1,296.70	SQYD	1,296.70	\$90.00	\$116,703.00
		0001	0180	5021331	CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	453.20	0.00	453.20	SQYD	122.25	\$102.00	\$12,469.50
		0001	0190	6049902	MISC.ADJUSTING MANHOLES, VALVES AND PULL BOXES	8.00	0.00	8.00	EA	0.00	\$250.00	\$0.00
		0001	0200	6091060	PAVED DITCH	73.00	0.00	73.00	SQYD	0.00	\$62.00	\$0.00
		0001	0210	6097000	ROCK LINING	15.00	0.00	15.00	CUYD	0.00	\$90.00	\$0.00
		0001	0220	6099903	MISC.CONCRETE CURB	33.00	197.00	230.00	LF	201.00	\$75.00	\$15,075.00
		0001	0230	6116010A	SLOPE PROTECTION	14.00	0.00	14.00	SQYD	90.00	\$160.00	\$14,400.00
		0001	0240	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARRELS)	2.00	0.00	2.00	EA	3.00	\$3,000.00	\$9,000.00
		0001	0250	6122020	REPLACEMENT SAND BARREL	19.00	0.00	19.00	EA	0.00	\$400.00	\$0.00
		0001	0260	6122030	IMPACT ATTENUATOR (RELOCATION)	4.00	0.00	4.00	EA	1.00	\$1,500.00	\$1,500.00
		0001	0270	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	2.00	\$5,000.00	\$10,000.00
		0001	0280	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	132.00	0.00	132.00	SQYD	110.70	\$520.00	\$57,564.00
		0001	0290	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	132.00	0.00	132.00	SQYD	0.00	\$5.00	\$0.00
		0001	0300	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	132.00	0.00	132.00	SQYD	0.00	\$10.00	\$0.00
		0001	0310	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	666.00	0.00	666.00	LF	403.46	\$9.00	\$3,631.14
		0001	0320	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	372.00	0.00	372.00	EA	233.00	\$3.00	\$699.00
		0001	0330	6139911	MISC.REMOVAL, FURNISHING AND PLACING HOT POLYMER CONCRETE PATCHING MATERIAL, CLASS A PARTIAL REPAIRS	24,380.00	0.00	24,380.00	LB	0.00	\$3.65	\$0.00
		0001	0340	6149902	MISC.PARALLEL BAR GRATE AND BEARING PLATE (2 FT. X 4 FT.)	2.00	0.00	2.00	EA	2.00	\$2,100.00	\$4,200.00
		0001	0350	6161005	CONSTRUCTION SIGNS	2,000.00	0.00	2,000.00	SQFT	1,700.00	\$5.00	\$8,500.00
		0001	0360	6161008	ADVANCED WARNING RAIL SYSTEM	24.00	0.00	24.00	EA	26.00	\$45.00	\$1,170.00
		0001	0370	6161009	FLAG ASSEMBLY	14.00	0.00	14.00	EA	4.00	\$20.00	\$80.00
		0001	0380	6161025	CHANNELIZER (TRIM LINE)	520.00	0.00	520.00	EA	350.00	\$23.00	\$8,050.00
		0001	0390	6161030	TYPE III MOVEABLE BARRICADE	12.00	0.00	12.00	EA	6.00	\$125.00	\$750.00
		0001	0400	6161033	DIRECTIONAL INDICATOR BARRICADE	84.00	0.00	84.00	EA	84.00	\$18.00	\$1,512.00
		0001	0410	6161040	FLASHING ARROW PANEL	6.00	0.00	6.00	EA	6.00	\$750.00	\$4,500.00
		0001	0420	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED & RETAINED)	8.00	0.00	8.00	EA	8.00	\$2,500.00	\$20,000.00
		0001	0430	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	3,442.00	0.00	3,442.00	LF	0.00	\$78.00	\$0.00
		0001	0440	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	263.00	0.00	263.00	LF	263.00	\$180.00	\$47,340.00

Revision 4/1/2020 Page 6 of 17



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	ies are	based on I	Report Generated date and can differ from the posted an	nount at the	time the	Estimate wa	s Gener	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-F03	J6I3263	0001	0450	6173101	CONCRETE TRAFFIC BARRIER, TYPE D (MODIFIED)	1,030.00	0.00	1,030.00	LF	1,030.00	\$118.00	\$121,540.00
		0001	0460	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	7,444.00	0.00	7,444.00	LF	1,348.00	\$27.00	\$36,396.00
		0001	0470	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	2,104.00	0.00	2,104.00	LF	475.00	\$15.00	\$7,125.00
		0001	0480	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$447,923.86	\$447,923.86
		0001	0490	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	436.00	0.00	436.00	LF	0.00	\$7.00	\$0.00
		0001	0500	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	816.00	0.00	816.00	LF	0.00	\$18.00	\$0.00
		0001	0510	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	35.00	0.00	35.00	EA	0.00	\$325.00	\$0.00
		0001	0520	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	29.00	0.00	29.00	EA	0.00	\$300.00	\$0.00
		0001	0530	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	4.00	0.00	4.00	EA	0.00	\$500.00	\$0.00
		0001	0540	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	15.00	0.00	15.00	EA	0.00	\$200.00	\$0.00
		0001	0550	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	9.00	0.00	9.00	EA	0.00	\$50.00	\$0.00
		0001	0560	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	106,005.00	0.00	106,005.00	LF	0.00	\$0.30	\$0.00
	0001	0001	0570	6205903A		57,103.00	0.00	57,103.00	LF	0.00	\$0.25	\$0.00
		0001	0580	6205906A		17,385.00	0.00	17,385.00	LF	0.00	\$1.00	\$0.00
		0001	0590	6207001	MARKING PAINT, TYPE L BEADS PAVEMENT MARKING REMOVAL	40.701.00	0.00	40.701.00	LF	0.00	\$0.49	\$0.00
		0001	0600	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	2.00	0.00	2.00	EA	0.00	\$30.00	\$0.00
		0001	0610	6209902	MISC.INLAID PAVEMENT MARKER INSTALLATION	1,302.00	0.00	1,302.00	EA	0.00	\$25.00	\$0.00
		0001	0620	6209902	MISC.INTERSTATE SHIELD PAVEMENT MARKINGS	2.00	0.00	2.00	EA	0.00	\$2,800.00	\$0.00
		0001	0630	6209902	MISC.LANE REDUCTION ARROW	4.00	0.00	4.00	EA	0.00	\$1,200.00	\$0.00
		0001	0640	6209902	MISC.'LOOK LEFT' PAVEMENT MARKINGS	2.00	0.00	2.00	EA	0.00	\$700.00	\$0.00
		0001	0650	6209902	MISC.'LOOK RIGHT' PAVEMENT MARKINGS	2.00	0.00	2.00	EA	0.00	\$700.00	\$0.00
		0001	0660	6209903	MISC.24 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	1,310.00	0.00	1,310.00	LF	0.00	\$5.00	\$0.00
		0001			MARKING PAINT, TYPE L BEADS							
		0001	0670	6209903	MISC.TEMPORARY REMOVABLE MARKING TAPE, 6" BLACK	20,614.00	0.00	20,614.00	LF	0.00	\$1.35	\$0.00
		0001	0680	6209903	MISC.TEMPORARY REMOVABLE MARKING TAPE, 6" WHITE	20,086.00	0.00	20,086.00	LF	1,700.00	\$1.35	\$2,295.00
		0001	0690	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	215,478.00	0.00	215,478.00	SQYD	126,772.42	\$3.00	\$380,317.26
		0001	0700	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	79,732.00	0.00	79,732.00	SQYD	78,642.93	\$1.50	\$117,964.40
		0001	0710	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,500.00	0.00	2,500.00	SQYD	0.00	\$0.01	\$0.00
		0001	0720	6229905	MISC.LONGITUDINAL PAVEMENT GROOVING	13,066.10	0.00	13,066.10	SQYD	0.00	\$4.50	\$0.00
		0001	0730	6229905	MISC.TRANSVERSE PAVEMENT GROOVING	13,843.60	0.00	13,843.60	SQYD	0.00	\$6.50	\$0.00
		0001	0740	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	232.80	0.00	232.80	STA	45.46	\$48.00	\$2,182.08
		0001	0750	6262000A	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP	10.30	0.00	10.30	STA	12.15	\$100.00	\$1,215.00
		0001	0760	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.75	\$3,000.00	\$2,250.00
		0001	0770	7261015	15 IN. PIPE GROUP A	30.00	0.00	30.00	LF	30.00	\$175.00	\$5,250.00
		0001	0780	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	7.00	0.00	7.00	FT	7.00	\$610.00	\$4,270.00
		0001	0790	7319902	MISC.REPLACE INLET TOP TO NEW GRADE	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.00
		0001	0800	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,400.00	\$2,800.00
		0001	0810	8059919	MISC.SEEDING: WARM OR COOL SEASON MIXTURES	0.50	0.00	0.50	ACRE	0.00	\$9,700.00	\$0.00
		0001	0820	8061005	ROCK DITCH CHECK	102.00	0.00	102.00	LF	0.00	\$13.50	\$0.00
		0001	0830	8061010A	TYPE B BERM	1,030.00	0.00	1,030.00	LF	0.00	\$0.01	\$0.00
		0001	0840	8061016	SEDIMENT REMOVAL	25.00	0.00	25.00	CUYD	0.00	\$0.01	\$0.00
		0001	0850	8061019	SILT FENCE	871.00	0.00	871.00	LF	0.00	\$2.60	\$0.00
		0010	0860	6061060	MGS GUARDRAIL	14,068.00	0.00	14,068.00	LF	14,568.00	\$20.00	\$291,360.00
		0010	0870	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	4,575.00	0.00	4,575.00	LF	4,462.50	\$24.00	\$107,100.00

Revision 4/1/2020 Page 7 of 17



## Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bid Net Total Unit Total Unit Price Total Value POSTED

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-F03	J6I3263	0010	0880	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	150.00	0.00	150.00	LF	150.00	\$36.00	\$5,400.00
		0010	0890	6061065	MGS GUARDRAIL, 6 FT. POSTS, 1 FT 6.75 IN. SPACING	325.00	0.00	325.00	LF	325.00	\$50.00	\$16,250.00
		0010	0900	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	25.00	0.00	25.00	EA	24.00	\$3,000.00	\$72,000.00
		0010	0910	6061080	MGS END ANCHOR	26.00	0.00	26.00	EA	27.00	\$1,000.00	\$27,000.00
		0010	0920	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	34.00	0.00	34.00	EA	34.00	\$2,800.00	\$95,200.00
		0020	0930	9015010	TRENCHING TYPE I	2,169.00	0.00	2,169.00	LF	2,169.00	\$2.90	\$6,290.10
		0020	0940	9015020	TRENCHING TYPE II	241.00	0.00	241.00	LF	241.00	\$3.75	\$903.75
		0020	0950	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	90.00	0.00	90.00	LF	0.00	\$1.20	\$0.00
		0020	0960	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	2,620.00	0.00	2,620.00	LF	2,620.00	\$3.45	\$9,039.00
		0020	0970	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	1.00	0.00	1.00	EA	0.00	\$1,372.00	\$0.00
		0020	0980	9019902	MISC.45' TOP MOUNT LUMINAIRE POST	1.00	0.00	1.00	EA	0.00	\$4,530.00	\$0.00
		0020	0990	9019902	MISC.TOP MOUNT LED-C LUMINAIRE	1.00	0.00	1.00	EA	0.00	\$760.00	\$0.00
		0030	1000	9029903	MISC.CABLE, DET. LOOP, #14 GAUGE, 1 COND. W/ TUBE JACKET (IN SAWED SLOT)	1,310.00	0.00	1,310.00	LF	0.00	\$6.00	\$0.00
		0030	1010	9029903	MISC.CABLE, DETECTOR LOOP, #14 GAUGE, 1 COND. W/ TUBE JACKET (IN CONDUIT & PB)	382.00	0.00	382.00	LF	0.00	\$1.40	\$0.00
		0030	1020	9029903	MISC.CONDUIT, 1 IN.	243.00	0.00	243.00	LF	0.00	\$7.20	\$0.00
		0040	1030	2169902	MISC.REMOVE LOOSE GROUT	8.00	0.00	8.00	EA	0.00	\$250.00	\$0.00
		0040	1040	7040101	SUBSTRUCTURE REPAIR (FORMED)	5.00	0.00	5.00	SQFT	0.00	\$250.00	\$0.00
		0040	1050	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	10.00	0.00	10.00	SQFT	0.00	\$200.00	\$0.00
		0040	1060	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$1,200.00	\$0.00
		0040	1070	9031010	CONCRETE FOOTINGS, EMBEDDED	4.00	0.00	4.00	CUYD	0.00	\$1,400.00	\$0.00
		0040	1080	9031020	CONCRETE FOOTINGS, BOLT DOWN	93.60	0.00	93.60	CUYD	0.00	\$1,950.00	\$0.00
		0040	1090	9031210	STRUCTURAL STEEL POSTS	2,630.00	0.00	2,630.00	LB	0.00	\$4.00	\$0.00
		0040	1100	9035004A	SH-FLAT SHEET	62.00	0.00	62.00	SQFT	7.50	\$22.00	\$165.00
		0040	1110	9035011A	ST-STRUCTURAL	5,153.00	0.00	5,153.00	SQFT	2,589.00	\$26.00	\$67,314.00
		0040	1120	9035069A	SHF-FLAT SHEET FLUORESCENT	80.00	0.00	80.00	SQFT	60.00	\$25.00	\$1,500.00
		0040	1130	9035071A	STF-STRUCTURAL FLUORESCENT	630.00	0.00	630.00	SQFT	324.00	\$28.00	\$9,072.00
		0040	1140	9039901	MISC.125 FT. SPAN SIGN TRUSS, SIGN #5	1.00	0.00	1.00	LS	0.00	\$70,000.00	\$0.00
		0040	1150	9039901	MISC.30 FT. CANTILEVER SIGN TRUSS, SIGN #20	1.00	0.00	1.00	LS	0.00	\$29,000.00	\$0.00
		0040	1160	9039901	MISC.80 FT. SPAN SIGN TRUSS, SIGN #3	1.00	0.00	1.00	LS	0.00	\$51,000.00	\$0.00
		0040	1170	9039901	MISC.93 FT. SPAN SIGN TRUSS, SIGN #8	1.00	0.00	1.00	LS	0.00	\$57,000.00	\$0.00
		0040	1180	9039901	MISC.98 FT. SPAN SIGN TRUSS, SIGN #6	1.00	0.00	1.00	LS	0.00	\$60,000.00	\$0.00
		0040	1190	9039902	MISC.RELOCATE EXISTING OVERHEAD SIGN ASSEMBLIES	25.00	0.00	25.00	EA	0.00	\$2,000.00	\$0.00
		0040	1200	9039902	MISC.REMOVE SIGN TRUSS CATWALKS & LIGHTING	8.00	0.00	8.00	EA	0.00	\$2,400.00	\$0.00
		0040	1210	9039902	MISC.REPAIR WELD	3.00	0.00	3.00	EA	0.00	\$10,000.00	\$0.00
		0050	1220	9109901	MISC.FIBER MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$1,022.00	\$0.00
		0050	1230	9109901	MISC.REMOVE SIDE RADAR DETECTOR ASSEMBLY	1.00	0.00	1.00	LS	0.00	\$1,870.00	\$0.00
		0050	1240	9109903	MISC.MODOT ITS ASSETS RELOCATION	1,500.00	0.00	1,500.00	LF	0.00	\$9.20	\$0.00
					late as of Report Generated Date							\$5,602,952.06
191213-F03 Ove	rall - Tota	I Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$5,602,952.06

Revision 4/1/2020 Page 8 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6l3263

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0080	4011209	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	7/22/20	7/24/20	367.80	TONS	I-270 outside shoulders Latitude: 38.62573 Longitude: -90.24791 Accuracy: 3000m	130		169		Coverage information I-270SB 130+00 - 169+36.2 outside shoulder I-270SB 130+00 - Ramp to Dorsett ~135+75 Left Shoulder
			7/23/20	7/24/20	666.17	TONS	I-270SB and NB outside shoulders Latitude: 38.62888 Longitude: -90.25402 Accuracy: 65m	195		122+00		Coverage information I-270SB 177+42.2 - 195+00 I-270NB
			7/24/20	7/31/20	1,028.42	TONS	I-270NB outside shoulders Latitude: 38.62860 Longitude: -90.25403 Accuracy: 65m	122		20		173+38.9 - 122+00  I-270NB Shoulder Outside shoulder against lane 5 122+00 - 29+75 Outside shoulder against lane 3 at I-70 gore 28+80 - 20+99.7
0110	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP1	7/16/20	7/24/20	728.81	TONS	Dorsett and I-270 Latitude: 38.62877 Longitude: -90.25404 Accuracy: 65m					Coverage information Dorsett EB to I-270SB ramp lane, Dorsett to I-270SB ramp, I-270NB to Dorsett ramp excluding right lane on Dorsett EB, dead areas.
			7/17/20	7/24/20	567.18	TONS	Dorsett Intersection at I-270 Latitude: 38.62871 Longitude: -30.25995 Accuracy: 65in					Coverage information Right lane on ramp from I-270NB to DorsettEB to correct leads from the properties of the control leads of the cont
			7/20/20	7/24/20	650.85	TONS	Dorsett intersections at I-270 Latitude: 38.62878					deduct appropriate amount if necessary after confirming with Modot.  Coverage information  Dorset WB lanes completed (east end of job to western
							Longitude: -90.25398 Accuracy: 65m					most traffic switch, remainder already paved), Dorsett lane 2 complete(west end of job to concrete head)
			7/22/20	7/24/20	370.01	TONS	Dorsett Interchanges Latitude: 38.62882 Longitude: -90.25403 Accuracy: 69m					Coverage information Dorsett EB lane 1 entire length. Dorsett EB left turn lane onto Progress Parkway Suicide lane between Dorsett EB and WB lanes from Progress Parkway to east end of job.
			7/29/20	8/3/20	-678.58	TONS	I-270SB Lane 5 and 6 Latitude: 38.62868 Longitude: -90.25407 Accuracy: 65m	35		136		Lane 5 35+00 - 58+00 128+84.3 - 136+00 (Dorsett pavement change) Lane 6 35+50 - 40+82.7 120+84.3 - 136+00 (Dorsett pavement change)
0130	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP1	7/29/20	8/3/20	678.58	TONS	I-270SB Lane 5 and 6 Latitude: 38.62868 Longitude: 90.25407 Accuracy: 65m	35		136		Lane 5 35+00 - 58+00 128+84.3 - 136+00 (Dorsett pavement change) Lane 6 35+50 - 40+82.7 120+84.3 - 136+00 (Dorsett pavement change)
0150	4071005	TACK COAT	7/16/20	7/24/20	466.00	GAL	Dorsett and I-270 Latitude: 38.62876 Lorintude: -90.25399 Accuracy: 65m					Dorsett and I-270 interchanges.
			7/17/20	7/24/20	376.00	GAL	Dorset Intersection at I-270 Latitude: 38.62875 Longitude: -90.25401 Accuracy: 65m					Coverage information Right lane on rump from I-270NB to DorsettEB to concrete head, entire ramp lane from DorsettWB to I-270NB and dead area. Dorsett WB lanes and suicide lane west of I-270 overpass to west end of job. Also repaved on mainline 270NB rumble strip 740LF approximately 100 tons. Paying in this quantity, will deduct appropriate amount if necessary after confirmit with Modot.
			7/20/20	7/24/20	410.00	GAL	Dorsett intersections at I-270 Latitude: 38.62878 Longitude: -90.25398 Accuracy: 65m					Coverage information Dorset WB lanes completed(east end of job to western most traffic switch, remainder already paved), Dorsett lane 2 complete(west end of job to concrete head)
			7/22/20	7/24/20	244.00	GAL	Dorsett Interchanges Latitude: 38.62573 Longitude: -90.24791 Accuracy: 3000m					Coverage information Dorsett EB lane 1 entire length. Dorsett EB left turn lane onto Progress Parkway Suicide lane between Dorsett EB and WB lanes from Progress Parkway to east end of job.
				7/24/20	267.00	GAL	I-270 outside shoulders Latitude: 38.62573 Longitude: -90.24791 Accuracy: 3000m	130		169		Coverage information 1-270SB 130+00 - 169+36.2 outside shoulder 1-270SB 130+00 - Ramp to Dorsett ~135+75 Left Shoulder
			7/23/20	7/24/20	444.00	GAL	I-270SB and NB outside shoulders Latitude: 38.62888 Longitude: -90.25402 Accuracy: 65m	195		122+00		Coverage information I-270SB 177+42.2 - 195+00 I-270NB 173+38.9 - 122+00
			7/24/20	7/31/20	680.00	GAL	I-270NB outside shoulders Latitude: 38.62860 Longitude: -90.25403 Accuracy: 65m	122		20		I-270NB Shoulder Outside shoulder against lane 5 122+00 - 29+75 Outside shoulder against lane 3 at I-70 gore 28+80 - 20+99.7
		SLOPE PROTECTION	7/17/20				SB 270					Guard rail damaged existing slope Protection
0460	6173600D	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	7/23/20	8/3/20 8/3/20	-514.50 514.50		NB I-270 270					
0690	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	7/16/20				Dorsett Ramps 3&4					
			7/47/00	7/21/20			Dorsett Road					Donalda akin
			7/17/20	7/24/20	1,167.00 4,016.28		NB 270 Dorsett Road	75		80		Rumble strip
			7/22/20	7/24/20	2,016.26							Shoulders
			7/23/20	7/24/20 8/3/20	8,036.62 1,010.00		Dorsett Road SR 270					Marine- End of Job
			120120	8/3/20	4,000.00							
			7/24/20	7/31/20	5,000.00	SQYD	NB 270					Dorsett- End of Job

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 9 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		3	Apr 16, 2020	SYSTEM	(\$1,039.12)	
				3	Apr 16, 2020	SYSTEM	\$1,039.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	May 4, 2020	SYSTEM	(\$13,519.68)	
				4	May 4, 2020	SYSTEM	\$13,519.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stgemr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0070 -	Total						\$0.00	
0080	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	6	Jun 2, 2020	gummer1	(\$1,056.23)	May 2020 - Second Period
				10	Aug 4, 2020	gummer1	(\$4,825.99)	Asphalt for second period of July-20 Tons laid was 2062.39tons at 3.9% AC%
			ACAD - Tota	al			(\$5,882.22)	
	Other Item Adjustment - Total						(\$5,882.22)	
0080 -	Total						(\$5,882.22)	
0110	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	Other Item Adjustment	ACAD	9	Jul 17, 2020	gummer1	(\$1,667.95)	line 110 asphalt of 712.8 Tons at 3.9%
				10	Aug 4, 2020	gummer1	(\$5,421.43)	Deduction on Second Period July - 2020 Total Tons equal 2316.85 Tons layed at 3.9% AC
			ACAD - Tota	al			(\$7,089.38)	
	Other Item Adjustment - Total						(\$7,089.38)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	Overrun	Overrun	10	Aug 4, 2020	SYSTEM	(\$43,915.00)	
			Overrun - T	otal			(\$43,915.00)	
	Overrun - Total						(\$43,915.00)	
0110 -	Total						(\$51,004.38)	
0120	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Material		7	Jun 16, 2020	SYSTEM	(\$917,746.55)	
				7	Jun 16, 2020	SYSTEM	\$917,746.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$917,746.55)	
				8	Jul 1, 2020	SYSTEM	\$917,746.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stgemr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Jul 17, 2020	SYSTEM	(\$917,746.55)	
				9	Jul 17, 2020	SYSTEM	\$917,746.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Aug 4, 2020	SYSTEM	(\$917,746.55)	
				10	Aug 4, 2020	SYSTEM	\$917,746.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Other Item Adjustment	ACAD	6	Jun 2, 2020	gummer1	(\$3,148.31)	May 2020 Second Period
				7	Jun 16, 2020	stgemr1	(\$17,557.04)	Mix laid between June 2nd and June 15th 2020. SP125B Mix Mix ID: SP125 20-8 Virgin AC = 4.1% Tons = 7612.81 Current Index = 401,25 Base Index: 457.5 Difference: 56.25
			ACAD - Tota	al			(\$20,705.35)	

Revision 4/1/2020 Page 10 of 17



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0120	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Other Item Adjustment	Type	10	Aug 4, 2020	gummer1	\$198,273.55	Readjusting dollar amount from Change Order 1 previous deduction on override.
	1 0 70 22 (O1 1205 WIIX)	rajuotinont			2020			Estimate no 7 and 8, from CO 1
			OADJ - Tota				\$198,273.55	
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)		SUBI	7	Jun 16, 2020	stgemr1	(\$6,022.76)	Deduction due to low density on Unconfined Joint Cores: Mix: SP125B Mix ID: SP125 20-8 SB I-270 Lane 1 Sta. 20+57.9 to Sta. 39+09.7 Density: 88.3% 1,752' x 12'W /9 = 2336 SY 2336 SY x 2" (depth) x 1.954 = 253.59 tons \$95.00/ton x 253.59 = \$24,091.05 x -25% = -(\$6022.76). stgemr1 06/16/2020
			SUBI - Tota				(\$6,022.76)	
	Other Item Adjustment - Total						\$171,545.44	
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Overrun	Overrun	7	Jun 16, 2020	SYSTEM	\$111,872.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 20 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	\$86,400.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 20 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$198,273.55)	
				7	Jun 16, 2020	stgemr1	(\$111,872.95)	Change order will be fort coming.
				8	Jul 1, 2020	SYSTEM	(\$198,273.55)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Jul 1, 2020	SYSTEM	\$198,273.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 21 on the current Payment Estimate.
				8	Jul 1, 2020	stgemr1	(\$86,400.60)	Overpayment on Estimate #07 for overrun. Waiting on change order
			Overrun - T	otal			(\$198,273.55)	
	Overrun - Total						(\$198,273.55)	
0120 -		Oth on those	4040	0	bol 47		(\$26,728.11)	Assistant 0004 00 Terra at 0.0 %
0130	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Other Item Adjustment	ACAD - Tota		Jul 17, 2020	gummer1	(\$24,962.69)	Asphalt 6934.08 Tons at 6.0 %
	Other Item Adjustment - Total		ACAD - TOO	aı			(\$24,962.69)	
0130 -	•						(\$24,962.69)	
0140	MISC. HIGH TENSILE STRENGTH SYNTHETIC FIBER ASPHALTIC PAVEMENT PG 76-22 (SP125BSM)	Other Item Adjustment	ACAD	7	Jun 16, 2020	stgemr1	(\$3,486.38)	Mix laid between June 2nd and June 15th 2020. SP125BSM Mix ID: SP125 19-100 Tons: 1033.00 Virgin AC=6.0% Base Index: 457.5 Current Index: 401.25 Difference: -56.25 stgemr1 06/16/2020
				8	Jul 1, 2020	stgemr1	(\$24,498.38)	Asphalt mix laid between June 16th and June 30th 2020 (End of MoDOT physical year) Mix ID: SP125 19-100 AC % = 6.0 Tons Laid = 7258.78 Current Factor = 401.25 Base Factor = 457.5 Difference = -56.25 Adjustment = \$24,498.38 stdemt 107/01/2020
			ACAD - Tota	al			(\$27,984.76)	
	Other Item Adjustment - Total  MISC. HIGH TENSILE STRENGTH SYNTHETIC FIBER ASPHALTIC	Overrun	ACAD - Tota		Jul 1, 2020	SYSTEM	(\$27,984.76) (\$27,984.76) (\$49,229.20)	
	MISC. HIGH TENSILE STRENGTH	Overrun		8		SYSTEM	(\$27,984.76)	
	MISC. HIGH TENSILE STRENGTH SYNTHETIC FIBER ASPHALTIC	Overrun	Overrun	8		SYSTEM	(\$27,984.76) (\$49,229.20)	
0140 -	MISC. HIGH TENSILE STRENGTH SYNTHETIC FIBER ASPHALTIC PAVEMENT PG 76-22 (SP125BSM) Overrun - Total	Overrun	Overrun	8		SYSTEM	(\$27,984.76) (\$49,229.20) (\$49,229.20)	

Revision 4/1/2020 Page 11 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0170	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	Material	Туре	4	May 4, 2020	SYSTEM	\$116,703.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stgemr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
				5	May 18, 2020	SYSTEM	(\$116,703.00)	,			
				5	May 18, 2020	SYSTEM	\$116,703.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stgemr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
				6	Jun 2, 2020	SYSTEM	(\$116,703.00)				
					6	Jun 2, 2020	SYSTEM	\$116,703.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
									7	Jun 16, 2020	SYSTEM
				7	Jun 16, 2020	SYSTEM	\$116,703.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stgemr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					8	Jul 1, 2020	SYSTEM	(\$116,703.00)			
				8	Jul 1, 2020	SYSTEM	\$116,703.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user stgemr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
				9	Jul 17, 2020	SYSTEM	(\$116,703.00)				
					9	Jul 17, 2020	SYSTEM	\$116,703.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
				10	Aug 4, 2020	SYSTEM	(\$116,703.00)				
				10	Aug 4, 2020	SYSTEM	\$116,703.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gummer1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
							00.00				
			- Total				\$0.00				
0470	Material - Total		- Total				\$0.00				
<b>0170</b> -		Material	- Total	3	Apr 16,	SYSTEM	\$0.00 \$0.00				
	- Total	Material	- Total	3	Apr 16, 2020 Apr 16, 2020	SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washaj1 overridding			
	Total  CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT.	Material	- Total		2020 Apr 16,		\$0.00 \$0.00 (\$12,469.50)				
	Total  CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT.	Material	- Total	3	2020 Apr 16, 2020 May 4, 2020 May 4,	SYSTEM	\$0.00 \$0.00 (\$12,469.50) \$12,469.50	Estimate Item Adjustment (0004) due to user washaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment			
	Total  CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT.	Material	- Total	3 4 4	2020 Apr 16, 2020 May 4, 2020 May 4, 2020	SYSTEM SYSTEM	\$0.00 \$0.00 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50	Estimate Item Adjustment (0004) due to user washaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
	Total  CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT.	Material	- Total	3 4 4 5	2020 Apr 16, 2020 May 4, 2020 May 4, 2020 May 18, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50	Estimate Item Adjustment (0004) due to user washaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
	Total  CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT.	Material	- Total	3 4 4	2020 Apr 16, 2020 May 4, 2020 May 4, 2020	SYSTEM SYSTEM	\$0.00 \$0.00 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50	Estimate Item Adjustment (0004) due to user washaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stgemr1 overridding			
	Total  CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT.	Material	- Total	3 4 4 5	2020 Apr 16, 2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50	Estimate Item Adjustment (0004) due to user washaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stgemr1 overridding			
	Total  CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT.	Material	- Total	3 4 4 5 5	2020 Apr 16, 2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50	Estimate Item Adjustment (0004) due to user washaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stgemr1 overridding			
	Total  CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT.	Material	- Total	3 4 4 5 5 6	2020 Apr 16, 2020 May 4, 2020 May 4, 2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50 (\$12,469.50) (\$12,469.50)	Estimate Item Adjustment (0004) due to user washaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stgemr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding			
	Total  CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT.	Material	- Total	3 4 4 5 5 6 6 6	2020 Apr 16, 2020 May 4, 2020 May 4, 2020 May 18, 2020 Jun 2, 2020 Jun 16, 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50 (\$12,469.50) (\$12,469.50) \$12,469.50	Estimate Item Adjustment (0004) due to user washaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stgemr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding			
	Total  CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT.	Material	- Total	3 4 4 5 5 6 6 7 7	2020 Apr 16, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50 (\$12,469.50)	Estimate Item Adjustment (0004) due to user washaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stgemr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding			
	Total  CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT.	Material	- Total	3 4 4 5 5 5 6 6 7 7 7	2020 Apr 16, 2020 May 4, 2020 May 4, 2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50 (\$12,469.50) \$12,469.50 (\$12,469.50)	Estimate Item Adjustment (0004) due to user washaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stgemr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding			

Revision 4/1/2020 Page 12 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0180	CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		9	Jul 17, 2020	SYSTEM	\$12,469.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gummer1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				10	Aug 4, 2020	SYSTEM	(\$12,469.50)	
				10	Aug 4, 2020	SYSTEM	\$12,469.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0180 -	Total						\$0.00	
0220	MISC. CONCRETE CURB	Overrun	Overrun	3	Apr 16, 2020	SYSTEM	(\$12,600.00)	
				9	Jul 17, 2020	SYSTEM	\$12,600.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',75.00000 - 75.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0220 -	Total						\$0.00	
0230	SLOPE PROTECTION	Material		7	Jun 16, 2020	SYSTEM	(\$2,240.00)	
				7	Jun 16, 2020	SYSTEM	\$2,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user stgemr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$2,240.00)	
				8	Jul 1, 2020	SYSTEM	\$2,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				9	Jul 17, 2020	SYSTEM	(\$2,240.00)	
				9	Jul 17, 2020	SYSTEM	\$2,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user gummer1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				10	Aug 4, 2020	SYSTEM	(\$14,400.00)	
				10	Aug 4, 2020	SYSTEM	\$14,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	SLOPE PROTECTION	Overrun	Overrun	10	Aug 4, 2020	SYSTEM	(\$12,160.00)	
				10	Aug 4, 2020	SYSTEM	\$12,160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 19 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0230 -	Total						\$0.00	
0240	IMPACT ATTENUATOR 70 MPH (SAND BARRELS)	Overrun	Overrun	2	Apr 2, 2020	SYSTEM	(\$3,000.00)	
			Overrun - T	otal			(\$3,000.00)	
	Overrun - Total						(\$3,000.00)	
0240 - 0280	FURNISHING AND PLACING	Material		3	Apr 16,	SYSTEM	(\$3,000.00) (\$57,564.00)	
	CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR			3	2020 Apr 16, 2020	SYSTEM	\$57,564.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washaj1 overridding
				4	May 4,	SYSTEM	(\$57,564.00)	Payment Estimate Exception 10 on the current Payment Estimate.
					2020			
				4	May 4, 2020	SYSTEM	\$57,564.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stgemr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.

Revision 4/1/2020 Page 13 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0280	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	Material	,,,	5	May 18, 2020	SYSTEM	(\$57,564.00)		
	DEPTH PAVEMENT REPAIR			5	May 18, 2020	SYSTEM	\$57,564.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stgemr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
				6	Jun 2, 2020	SYSTEM	(\$57,564.00)		
				6	Jun 2, 2020	SYSTEM	\$57,564.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gummer1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					7	Jun 16, 2020	SYSTEM	(\$57,564.00)	
				7	Jun 16, 2020	SYSTEM	\$57,564.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
				8	Jul 1, 2020	SYSTEM	(\$57,564.00)		
				8	Jul 1, 2020	SYSTEM	\$57,564.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stgemr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
				9	Jul 17, 2020	SYSTEM	(\$57,564.00)		
				9	Jul 17, 2020	SYSTEM	\$57,564.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user gummer1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
				10	Aug 4, 2020	SYSTEM	(\$57,564.00)		
				10	Aug 4, 2020	SYSTEM	\$57,564.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user gummer1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0280	- Total						\$0.00		
0320	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT	Material		3	Apr 16, 2020	SYSTEM	(\$699.00)		
	REPAIR				3	Apr 16, 2020	SYSTEM	\$699.00	This adjustment offsets the original system-generated Overrun Payment
					2020			Estimate Item Adjustment (0007) due to user washaj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
				4	May 4, 2020	SYSTEM	(\$699.00)		
				4	May 4,	SYSTEM SYSTEM	(\$699.00) \$699.00		
					May 4, 2020 May 4,			Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding	
				4	May 4, 2020 May 4, 2020 May 18,	SYSTEM	\$699.00	Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding	
				5	May 4, 2020 May 4, 2020 May 18, 2020 May 18,	SYSTEM	\$699.00 (\$699.00)	Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding	
				5	May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2,	SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00	Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding	
				<ul><li>4</li><li>5</li><li>5</li><li>6</li><li>6</li><li>7</li></ul>	May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00	Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding	
				5 5 6 6	May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00 (\$699.00)	Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding	
				<ul><li>4</li><li>5</li><li>5</li><li>6</li><li>6</li><li>7</li></ul>	May 4, 2020 May 4, 2020 May 18, 2020  May 18, 2020  Jun 2, 2020  Jun 16, 2020  Jun 16, 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00 (\$699.00)	Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user stgemr1 overridding	
				5 5 6 6 7	May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00 (\$699.00) \$699.00 (\$699.00)	Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user stgemr1 overridding	
				4 5 5 6 6 7 7	May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00 (\$699.00) \$699.00 (\$699.00)	Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user stgemr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user stgemr1 overridding	

Revision 4/1/2020 Page 14 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0320	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT	Material		10	Aug 4, 2020	SYSTEM	(\$699.00)	
	REPAIR			10	Aug 4, 2020	SYSTEM	\$699.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user gummer1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0320 -	· Total						\$0.00	
0360	ADVANCED WARNING RAIL SYSTEM	Overrun	Overrun	3	Apr 16, 2020	SYSTEM	(\$90.00)	
				3	Apr 16, 2020	SYSTEM	\$90.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washaj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				4	May 4, 2020	SYSTEM	(\$90.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
			Overrun - T	otal			(\$90.00)	
	Overrun - Total						(\$90.00)	
0360 -	Total						(\$90.00)	
0440	CONCRETE TRAFFIC BARRIER, TYPE D	Material		3	Apr 16, 2020	SYSTEM	(\$47,340.00)	
				3	Apr 16, 2020	SYSTEM	\$47,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washaj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				4	May 4, 2020	SYSTEM	(\$47,340.00)	
				4	May 4, 2020	SYSTEM	\$47,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$47,340.00)	
				5	May 18, 2020	SYSTEM	\$47,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stgemr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$47,340.00)	
				6	Jun 2, 2020	SYSTEM	\$47,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$47,340.00)	
				7	Jun 16, 2020	SYSTEM	\$47,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user stgemr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$47,340.00)	
				8	Jul 1, 2020	SYSTEM	\$47,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user stgemr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				9	Jul 17, 2020	SYSTEM	(\$47,340.00)	
				9	Jul 17, 2020	SYSTEM	\$47,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				10	Aug 4, 2020	SYSTEM	(\$47,340.00)	
				10	Aug 4, 2020	SYSTEM	\$47,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user gummer1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0440 -	·Total						\$0.00	
0450	CONCRETE TRAFFIC BARRIER, TYPE D (MODIFIED)	Material		7	Jun 16, 2020	SYSTEM	(\$121,540.00)	
				7	Jun 16, 2020	SYSTEM	\$121,540.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user stgemr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.

Revision 4/1/2020 Page 15 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0450	CONCRETE TRAFFIC BARRIER, TYPE D (MODIFIED)	Material		8	Jul 1, 2020	SYSTEM	(\$121,540.00)	
				8	Jul 1, 2020	SYSTEM	\$121,540.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user stgemr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				9	Jul 17, 2020	SYSTEM	(\$121,540.00)	
				9	Jul 17, 2020	SYSTEM	\$121,540.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user gummer1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				10	Aug 4, 2020	SYSTEM	(\$121,540.00)	
				10	Aug 4, 2020	SYSTEM	\$121,540.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user gummer1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0450 -	Total						\$0.00	
0490	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN.	Material		3	Apr 16, 2020	SYSTEM	(\$1,190.00)	
	WHITE			3	Apr 16, 2020	SYSTEM	\$1,190.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user washaj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				4	May 4, 2020	SYSTEM	(\$1,190.00)	
				4	May 4, 2020	SYSTEM	\$1,190.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user stgemr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0490 -	Total						\$0.00	
0750	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP	Overrun	Overrun	9	Jul 17, 2020	SYSTEM	(\$185.00)	
			Overrun - T	otal			(\$185.00)	
	Overrun - Total						(\$185.00)	
0750 -	Total						(\$185.00)	
0860	MGS GUARDRAIL	Overrun	Overrun		Jul 1, 2020	SYSTEM	(\$10,000.00)	
			Overrun - T	otal			(\$10,000.00)	
	Overrun - Total						(\$10,000.00)	
0860 -							(\$10,000.00)	
0910	MGS END ANCHOR	Overrun	Overrun	6	Jun 2, 2020	SYSTEM	(\$1,000.00)	
			Overrun - T	otal			(\$1,000.00)	
	Overrun - Total						(\$1,000.00)	
0910 -	Total						(\$1,000.00)	
0960	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	Material		7	Jun 16, 2020	SYSTEM	(\$3,298.20)	
	NEUTRAL, 6 AWG			7	Jun 16, 2020	SYSTEM	\$3,298.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user stgemr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				8	Jul 1, 2020	SYSTEM	(\$9,039.00)	
				8	Jul 1, 2020	SYSTEM	\$9,039.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user stgemr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				9	Jul 17, 2020	SYSTEM	(\$9,039.00)	
				9	Jul 17, 2020	SYSTEM	\$9,039.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user gummer1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				10	Aug 4, 2020	SYSTEM	(\$9,039.00)	

Revision 4/1/2020 Page 16 of 17



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	23337	Туре	Adjustment Type	Number	Date	Ву		
0960	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	Material		10	Aug 4, 2020	SYSTEM	\$9,039.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user gummer1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0960 -	- Total						\$0.00	
1100	SH-FLAT SHEET	Construction Stockpile		8	Jul 1, 2020	SYSTEM	\$489.80	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$489.80	
	Construction Stockpile - Total						\$489.80	
1100 -	- Total						\$489.80	
1110	ST-STRUCTURAL	Construction Stockpile		8	Jul 1, 2020	SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1110 -	- Total						\$0.00	
1120	SHF-FLAT SHEET FLUORESCENT	Construction Stockpile		8	Jul 1, 2020	SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	SHF-FLAT SHEET FLUORESCENT	Material		5	May 18, 2020	SYSTEM	(\$1,000.00)	
				5	May 18, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stgemr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1120 -	- Total						\$0.00	
1130	STF-STRUCTURAL FLUORESCENT	Construction Stockpile		8	Jul 1, 2020	SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1130 -	- Total						\$0.00	
4440	MISC. 125 FT. SPAN SIGN TRUSS,	Other Item	OTHR	6	Jun 2, 2020	gummer1	(\$90.72)	Adjustment for sign inspection materials on job per Section 1042.3.3.1 for all line items on job pertaining to signing See Letter dated May 21, 2020 in files from Sam Marshall /
1140	SIGN #5	Adjustment						Environmental Chemist
1140		Adjustment	OTHR - Tota	al			(\$90.72)	
1140		Adjustment	OTHR - Tota	al			(\$90.72) (\$90.72)	
	SIGN #5	Adjustment	OTHR - Tota	al			, · · /	

Revision 4/1/2020 Page 17 of 17