

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 2, 2020

Progress Estimate Number	<b>Contract ID</b> 191213-F03	Pay Period Start May 16, 2020 Original Contract Amount \$8,245,000.00
6	Prime Contractor N.B. West Contracting Compar	ny Pay Period End June 1, 2020 Net Change Order Amount \$0.00
9		Current Contract Amount \$8,245,000.00

Approval Date		By User
June 2, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by	gummer1
June 3, 2020	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	janssm
June 4, 2020	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
October 31, 2021	October 31, 2021		19.91%

No Milestones Exist for Contract

Contract Total Pay	For Estimate No. 6			
		This Estimate	Previous	To Date
191213-F03				
	Total Posted Items Pay	\$354,424.90	\$1,286,850.76	\$1,641,275.66
	Gross Item Adjustments	(\$5,295.26)	(\$15,690.00)	(\$20,985.26)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$ <mark>1,271,160.76</mark>	\$1,620,290.40
Contract Total Paya	able This Estimate:	\$349,129.64		

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3263	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$290,000.000	0.091	\$26,390.00
Number	0060	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	LF	\$9.000	700	\$6,300.00
	0800	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	TONS	\$90.000	722.21	\$64,998.90
	0120	4030116	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	TONS	\$95.000	870.07	\$82,656.65
	0150	4071005	TACK COAT	GAL	\$2.000	1,134	\$2,268.00
	0690	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$3.000	8,248	\$24,744.00
	0700	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	SQYD	\$1.500	8,276.9	\$12,415.35
	0860	6061060	MGS GUARDRAIL	LF	\$20.000	2,350	\$47,000.00
	0870	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	LF	\$24.000	450	\$10,800.00
	0900	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$3,000.000	3	\$9,000.00
	0910	6061080	MGS END ANCHOR	EA	\$1,000.000	6	\$6,000.00
	0920	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$2,800.000	7	\$19,600.00
	1100	9035004A	SH-FLAT SHEET	SQFT	\$22.000	7.5	\$165.00
	1110	9035011A	ST-STRUCTURAL	SQFT	\$26.000	1,347.5	\$35,035.00
	1120	9035069A	SHF-FLAT SHEET FLUORESCENT	SQFT	\$25.000	20	\$500.00
	1130	9035071A	STF-STRUCTURAL FLUORESCENT	SQFT	\$28.000	234	\$6,552.00
roject J	613263 - To	otal					\$354,424.90
Overall -	Total						\$354,424.90

## Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	ne Item Adjustments This Estimate														
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount							
J6I3263	0800	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)			May 2020 - Second Period			(\$1,056.23)							

Revision 4/1/2020 Page 1 of 13



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 2, 2020

Progress Estimate Number
6
Contract ID 191213-F03 Pay Period Start May 16, 2020 Original Contract Amount \$8,245,000.00 Prime Contractor N.B. West Contracting Company Pay Period End June 1, 2020 Net Change Order Amount \$0.00 Current Contract Amount \$8,245,000.00

			1		- Cul	Tone Goneral	or Amount V	8,245,000.00
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3263				Price Adjustment				
	0120	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Other Item Adjustment	Asphalt Cement Price Adjustment	May 2020 Second Period			(\$3,148.31)
	0170	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	Material			-1,296.7	\$90.00	(\$116,703.00)
	0170	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,296.7	\$90.00	\$116,703.00
	0180	CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-122.25	\$102.00	(\$12,469.50)
	0180	CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	122.25	\$102.00	\$12,469.50
	0280	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-110.7	\$520.00	(\$57,564.00)
	0280	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user gummer1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	110.7	\$520.00	\$57,564.00
	0320	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-233	\$3.00	(\$699.00)
	0320	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	233	\$3.00	\$699.00
	0440	CONCRETE TRAFFIC BARRIER, TYPE D	Material			-263	\$180.00	(\$47,340.00)
	0440	CONCRETE TRAFFIC BARRIER, TYPE D	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	263	\$180.00	\$47,340.00
	0910	MGS END ANCHOR	Overrun			-1	\$1,000.00	(\$1,000.00)
	1140	MISC.	Other Item Adjustment	Other	Adjustment for sign inspection materials on job per Section 1042.3.3.1 for all line items on job pertaining to signing See Letter dated May 21, 2020 in files from Sam Marshall / Environmental Chemist			(\$90.72)
Total								(\$5,295.26)

Revision 4/1/2020 Page 2 of 13



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J6I3263	I 270-5(357)	Coldmill and resurface	I-270	ST LOUIS	from I-70 to Page Avenue							

J6I3263 I	70-5(357)	Coldmill and resurface	I-270	LOUIS	from I-70 to Page Avenue		
Totals by Jol	b Numbers	5					
J6I3263		Item Pay tem Adjustme		tem Pay	This Estimate \$354,424.90 (\$5,295.26) \$349,129.64	Previous \$1,286,850.76 (\$15,690.00) \$1,271,160.76	To Date \$1,641,275.66 (\$20,985.26) \$1,620,290.40
				,	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 13



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 5021310, Project Item Line Number 0170, Material Set 502131096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	waiting 28 day break	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 5021310, Project Item Line Number 0170, Material Set 502131096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	waiting 28 day break	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 5021331, Project Item Line Number 0180, Material Set 502133196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	waiting on 28 day break	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 5021331, Project Item Line Number 0180, Material Set 502133196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	waiting on 28 day break	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 6131010, Project Item Line Number 0280, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	waiting on items on material sheet to be taken off	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3263, Item 6131015, Project Item Line Number 0320, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	waiting on items on material sheet to be taken off	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3263, Item 6173100, Project Item Line Number 0440, Material Set 617310096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	waiting on items on material sheet to be taken off	gummer1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-F03, Contract Project J6l3263, Project Item Line Number 0220, Contract Line Item Number 0220, Item 6099903, Minor Item.	Waiting on Change order for job	gummer1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-F03, Contract Project J6l3263, Project Item Line Number 0240, Contract Line Item Number 0240, Item 6122019, Minor Item.	Waiting on Change order for job	gummer1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-F03, Contract Project J6l3263, Project Item Line Number 0360, Contract Line Item Number 0360, Item 6161008, Minor Item.	Waiting on Change order for job	gummer1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191213-F03, Contract Project J6l3263, Project Item Line Number 0910, Contract Line Item Number 0910, Item 6061080, Minor Item.	Waiting on Change order for job	gummer1	Acknowledged

Revision 4/1/2020 Page 4 of 13



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-F03	J6I3263	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$290,000.00	\$165,880.00
		0001	0020	2031000	CLASS A EXCAVATION	768.00	0.00	768.00	CUYD	632.60	\$18.00	\$11,386.80
		0001	0030	2036000	COMPACTING EMBANKMENT	27.00	0.00	27.00	CUYD	22.40	\$68.00	\$1,523.20
		0001	0040	2037075	COMPACTING IN CUT	14.10	0.00	14.10	STA	10.60	\$120.00	\$1,272.00
		0001	0050	2063000	CLASS 3 EXCAVATION	26.00	0.00	26.00	CUYD	26.00	\$25.00	\$650.00
		0001	0060	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	3,500.00	0.00	3,500.00	LF	2,900.00	\$9.00	\$26,100.00
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,768.00	0.00	1,768.00	SQYD	1,590.55	\$8.50	\$13,519.68
		0001	0800	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	4,365.20	0.00	4,365.20	TONS	722.21	\$90.00	\$64,998.90
		0001	0090	4019901	MISC.INFRARED SCANNING	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0001	0100	4019901	MISC.INTELLIGENT COMPACTION	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0001	0110	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	2,590.50	0.00	2,590.50	TONS	0.00	\$100.00	\$0.00
		0001	0120	4030116	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	7,573.40	0.00	7,573.40	TONS	4,497.97	\$95.00	\$427,307.15
		0001	0130	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	13,249.80	0.00	13,249.80	TONS	0.00	\$104.00	\$0.00
		0001	0140	4039910	MISC.HIGH TENSILE STRENGTH SYNTHETIC FIBER ASPHALTIC PAVEMENT PG 76-22 (SP125BSM)	7,863.70	0.00	7,863.70	TONS	0.00	\$115.00	\$0.00
		0001	0150	4071005	TACK COAT	38,394.00	0.00	38,394.00	GAL	2,958.00	\$2.00	\$5,916.00
		0001	0160	4079912	MISC.POLYMER MODIFIED EMULSION MEMBRANE (PEM OR	7,799.00	0.00	7,799.00	GAL	0.00	\$2.35	\$0.00
		0001	0170	5021310	CPEM)  CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	1,296.70	0.00	1,296.70	SQYD	1,296.70	\$90.00	\$116,703.00
		0001	0180	5021331	CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	453.20	0.00	453.20	SQYD	122.25	\$102.00	\$12,469.50
		0001	0190	6049902	MISC.ADJUSTING MANHOLES, VALVES AND PULL BOXES	8.00	0.00	8.00	EA	0.00	\$250.00	\$0.00
		0001	0200	6091060	PAVED DITCH	73.00	0.00	73.00	SQYD	0.00	\$62.00	\$0.00
		0001	0210	6097000	ROCK LINING	15.00	0.00	15.00	CUYD	0.00	\$90.00	\$0.00
		0001	0220	6099903	MISC.CONCRETE CURB	33.00	0.00	33.00	LF	201.00	\$75.00	\$15,075.00
		0001	0230	6116010A	SLOPE PROTECTION	14.00	0.00	14.00	SQYD	0.00	\$160.00	\$0.00
		0001	0240	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARRELS)	2.00	0.00	2.00	EA	3.00	\$3,000.00	\$9,000.00
		0001	0250	6122020	REPLACEMENT SAND BARREL	19.00	0.00	19.00	EA	0.00	\$400.00	\$0.00
		0001	0260	6122030	IMPACT ATTENUATOR (RELOCATION)	4.00	0.00	4.00	EA	1.00	\$1,500.00	\$1,500.00
		0001	0270	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	2.00	\$5,000.00	\$10,000.00
		0001	0280	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	132.00	0.00	132.00	SQYD	110.70	\$520.00	\$57,564.00
		0001	0290	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	132.00	0.00	132.00	SQYD	0.00	\$5.00	\$0.00
		0001	0300	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	132.00	0.00	132.00	SQYD	0.00	\$10.00	\$0.00
		0001	0310	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	666.00	0.00	666.00	LF	403.46	\$9.00	\$3,631.14
		0001	0320	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	372.00	0.00	372.00	EA	233.00	\$3.00	\$699.00
		0001	0330	6139911	MISC.REMOVAL, FURNISHING AND PLACING HOT POLYMER CONCRETE PATCHING MATERIAL, CLASS A PARTIAL REPAIRS	24,380.00	0.00	24,380.00	LB	0.00	\$3.65	\$0.00
		0001	0340	6149902	MISC.PARALLEL BAR GRATE AND BEARING PLATE (2 FT. X 4 FT.)	2.00	0.00	2.00	EA	0.00	\$2,100.00	\$0.00
		0001	0350	6161005	CONSTRUCTION SIGNS	2,000.00	0.00	2,000.00	SQFT	1,700.00	\$5.00	\$8,500.00
		0001	0360	6161008	ADVANCED WARNING RAIL SYSTEM	24.00	0.00	24.00	EA	26.00	\$45.00	\$1,170.00
		0001	0370	6161009	FLAG ASSEMBLY	14.00	0.00	14.00	EA	4.00	\$20.00	\$80.00
		0001	0380	6161025	CHANNELIZER (TRIM LINE)	520.00	0.00	520.00	EA	350.00	\$23.00	\$8,050.00
		0001	0390	6161030	TYPE III MOVEABLE BARRICADE	12.00	0.00	12.00	EA	6.00	\$125.00	\$750.00
		0001	0400	6161033	DIRECTIONAL INDICATOR BARRICADE	84.00	0.00	84.00	EA	84.00	\$18.00	\$1,512.00
		0001	0410	6161040	FLASHING ARROW PANEL	6.00	0.00	6.00	EA	6.00	\$750.00	\$4,500.00
		0001	0420	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED & RETAINED)	8.00	0.00	8.00	EA	8.00	\$2,500.00	\$20,000.00
		0001	0430	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	3,442.00	0.00	3,442.00	LF	0.00	\$78.00	\$0.00
		0001	0440	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	263.00	0.00	263.00	LF	263.00	\$180.00	\$47,340.00

Page 5 of 13 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

		and valu	es ale i	baseu on r	Report Generated date and can differ from the posted an	iount at the	une me	Estimate wa	as Gene	ialcu.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-F03	J6I3263	0001	0450	6173101	CONCRETE TRAFFIC BARRIER, TYPE D (MODIFIED)	1,030.00	0.00	1,030.00	LF	0.00	\$118.00	\$0.00
		0001	0460	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	7,444.00	0.00	7,444.00	LF	1,348.00	\$27.00	\$36,396.00
		0001	0470	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	2,104.00	0.00	2,104.00	LF	475.00	\$15.00	\$7,125.00
		0001	0480	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$447,923.86	\$223,961.93
		0001	0490	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	436.00	0.00	436.00	LF	0.00	\$7.00	\$0.00
		0001	0500	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	816.00	0.00	816.00	LF	0.00	\$18.00	\$0.00
		0001	0510	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	35.00	0.00	35.00	EA	0.00	\$325.00	\$0.00
		0001	0520	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	29.00	0.00	29.00	EA	0.00	\$300.00	\$0.00
	0001	0001	0530	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	4.00	0.00	4.00	EA	0.00	\$500.00	\$0.00
		0001	0540	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	15.00	0.00	15.00	EA	0.00	\$200.00	\$0.00
	0001	0001	0550	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE. YIELD LINE TRIANGLES	9.00	0.00	9.00	EA	0.00	\$50.00	\$0.00
		0001	0560	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	106,005.00	0.00	106,005.00	LF	0.00	\$0.30	\$0.00
		0001	0570	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	57,103.00	0.00	57,103.00	LF	0.00	\$0.25	\$0.00
	0001 0001 0001	0001	0580	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	17,385.00	0.00	17,385.00	LF	0.00	\$1.00	\$0.00
		0001	0590	6207001	PAVEMENT MARKING REMOVAL	40,701.00	0.00	40,701.00	LF	0.00	\$0.49	\$0.00
		0001	0600	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	2.00	0.00	2.00	EA	0.00	\$30.00	\$0.00
		0001	0610	6209902	MISC.INLAID PAVEMENT MARKER INSTALLATION	1,302.00	0.00	1,302.00	EA	0.00	\$25.00	\$0.00
		0001	0620	6209902	MISC.INTERSTATE SHIELD PAVEMENT MARKINGS	2.00	0.00	2.00	EA	0.00	\$2,800.00	\$0.00
		0001	0630	6209902	MISC.LANE REDUCTION ARROW	4.00	0.00	4.00	EA	0.00	\$1,200.00	\$0.00
		0001	0640	6209902	MISC.'LOOK LEFT' PAVEMENT MARKINGS	2.00	0.00	2.00	EA	0.00	\$700.00	\$0.00
		0001	0650	6209902	MISC.'LOOK RIGHT' PAVEMENT MARKINGS	2.00	0.00	2.00	EA	0.00	\$700.00	\$0.00
		0001	0660	6209903	MISC.24 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,310.00	0.00	1,310.00	LF	0.00	\$5.00	\$0.00
		0001	0670	6209903	MISC.TEMPORARY REMOVABLE MARKING TAPE, 6" BLACK	20,614.00	0.00	20,614.00	LF	0.00	\$1.35	\$0.00
		0001	0680	6209903	MISC.TEMPORARY REMOVABLE MARKING TAPE, 6" WHITE	20,086.00	0.00	20,086.00	LF	170.00	\$1.35	\$229.50
		0001	0690	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	215,478.00	0.00	215,478.00	SQYD	8,614.00	\$3.00	\$25,842.00
		0001	0700	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	79,732.00	0.00	79,732.00	SQYD	44,297.33	\$1.50	\$66,446.00
		0001	0710	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,500.00	0.00	2,500.00	SQYD	0.00	\$0.01	\$0.00
		0001	0720	6229905	MISC.LONGITUDINAL PAVEMENT GROOVING	13,066.10	0.00	13,066.10	SQYD	0.00	\$4.50	\$0.00
		0001	0730	6229905	MISC.TRANSVERSE PAVEMENT GROOVING	13,843.60	0.00	13,843.60	SQYD	0.00	\$6.50	\$0.00
		0001	0740	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	232.80	0.00	232.80	STA	0.00	\$48.00	\$0.00
		0001	0750	6262000A	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP	10.30	0.00	10.30	STA	0.00	\$100.00	\$0.00
		0001	0760	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.25	\$3,000.00	\$750.00
		0001	0770	7261015	15 IN. PIPE GROUP A	30.00	0.00	30.00	LF	30.00	\$175.00	\$5,250.00
		0001	0780	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	7.00	0.00	7.00	FT	7.00	\$610.00	\$4,270.00
		0001	0790	7319902	MISC.REPLACE INLET TOP TO NEW GRADE	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.00
		0001	0800	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,400.00	\$2,800.00
		0001	0810	8059919	MISC.SEEDING: WARM OR COOL SEASON MIXTURES	0.50	0.00	0.50	ACRE	0.00	\$9,700.00	\$0.00
		0001	0820	8061005	ROCK DITCH CHECK	102.00	0.00	102.00	LF	0.00	\$13.50	\$0.00
		0001	0830	8061010A	TYPE B BERM	1,030.00	0.00	1,030.00	LF	0.00	\$0.01	\$0.00
		0001	0840	8061016	SEDIMENT REMOVAL	25.00	0.00	25.00	CUYD	0.00	\$0.01	\$0.00
		0001	0850	8061019	SILT FENCE	871.00	0.00	871.00	LF	0.00	\$2.60	\$0.00
		0010	0860	6061060	MGS GUARDRAIL	14,068.00	0.00	14,068.00	LF	13,655.50	\$20.00	\$273,110.00
		0010	0870	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	4,575.00	0.00	4,575.00	LF	4,462.50	\$24.00	\$107,100.00

Page 6 of 13 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bid Net Total Unit Total Unit Price Total Value POSTED

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-F03	J6I3263	0010	0880	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	150.00	0.00	150.00	LF	150.00	\$36.00	\$5,400.00
		0010	0890	6061065	MGS GUARDRAIL, 6 FT. POSTS, 1 FT 6.75 IN. SPACING	325.00	0.00	325.00	LF	325.00	\$50.00	\$16,250.00
		0010	0900	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	25.00	0.00	25.00	EA	23.00	\$3,000.00	\$69,000.00
		0010	0910	6061080	MGS END ANCHOR	26.00	0.00	26.00	EA	27.00	\$1,000.00	\$27,000.00
		0010	0920	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	34.00	0.00	34.00	EA	33.00	\$2,800.00	\$92,400.00
		0020	0930	9015010	TRENCHING TYPE I	2,169.00	0.00	2,169.00	LF	0.00	\$2.90	\$0.00
		0020	0940	9015020	TRENCHING TYPE II	241.00	0.00	241.00	LF	0.00	\$3.75	\$0.00
		0020	0950	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	90.00	0.00	90.00	LF	0.00	\$1.20	\$0.00
		0020	0960	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	2,620.00	0.00	2,620.00	LF	0.00	\$3.45	\$0.00
		0020	0970	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	1.00	0.00	1.00	EA	0.00	\$1,372.00	\$0.00
		0020	0980	9019902	MISC.45' TOP MOUNT LUMINAIRE POST	1.00	0.00	1.00	EA	0.00	\$4,530.00	\$0.00
		0020	0990	9019902	MISC.TOP MOUNT LED-C LUMINAIRE	1.00	0.00	1.00	EA	0.00	\$760.00	\$0.00
		0030	1000	9029903	MISC.CABLE, DET. LOOP, #14 GAUGE, 1 COND. W/ TUBE JACKET (IN SAWED SLOT)	1,310.00	0.00	1,310.00	LF	0.00	\$6.00	\$0.00
		0030	1010	9029903	MISC.CABLE, DETECTOR LOOP, #14 GAUGE, 1 COND. W/ TUBE JACKET (IN CONDUIT & PB)	382.00	0.00	382.00	LF	0.00	\$1.40	\$0.00
		0030	1020	9029903	MISC.CONDUIT, 1 IN.	243.00	0.00	243.00	LF	0.00	\$7.20	\$0.00
		0040	1030	2169902	MISC.REMOVE LOOSE GROUT	8.00	0.00	8.00	EA	0.00	\$250.00	\$0.00
		0040	1040	7040101	SUBSTRUCTURE REPAIR (FORMED)	5.00	0.00	5.00	SQFT	0.00	\$250.00	\$0.00
		0040	1050	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	10.00	0.00	10.00	SQFT	0.00	\$200.00	\$0.00
		0040	1060	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$1,200.00	\$0.00
		0040	1070	9031010	CONCRETE FOOTINGS, EMBEDDED	4.00	0.00	4.00	CUYD	0.00	\$1,400.00	\$0.00
		0040	1080	9031020	CONCRETE FOOTINGS, BOLT DOWN	93.60	0.00	93.60	CUYD	0.00	\$1,950.00	\$0.00
		0040	1090	9031210	STRUCTURAL STEEL POSTS	2,630.00	0.00	2,630.00	LB	0.00	\$4.00	\$0.00
		0040	1100	9035004A	SH-FLAT SHEET	62.00	0.00	62.00	SQFT	7.50	\$22.00	\$165.00
		0040	1110	9035011A	ST-STRUCTURAL	5,153.00	0.00	5,153.00	SQFT	2,589.00	\$26.00	\$67,314.00
		0040	1120	9035069A	SHF-FLAT SHEET FLUORESCENT	80.00	0.00	80.00	SQFT	60.00	\$25.00	\$1,500.00
		0040	1130	9035071A	STF-STRUCTURAL FLUORESCENT	630.00	0.00	630.00	SQFT	324.00	\$28.00	\$9,072.00
		0040	1140	9039901	MISC.125 FT. SPAN SIGN TRUSS, SIGN #5	1.00	0.00	1.00	LS	0.00	\$70,000.00	\$0.00
		0040	1150	9039901	MISC.30 FT. CANTILEVER SIGN TRUSS, SIGN #20	1.00	0.00	1.00	LS	0.00	\$29,000.00	\$0.00
		0040	1160	9039901	MISC.80 FT. SPAN SIGN TRUSS, SIGN #3	1.00	0.00	1.00	LS	0.00	\$51,000.00	\$0.00
		0040	1170	9039901	MISC.93 FT. SPAN SIGN TRUSS, SIGN #8	1.00	0.00	1.00	LS	0.00	\$57,000.00	\$0.00
		0040	1180	9039901	MISC.98 FT. SPAN SIGN TRUSS, SIGN #6	1.00	0.00	1.00	LS	0.00	\$60,000.00	\$0.00
		0040	1190	9039902	MISC.RELOCATE EXISTING OVERHEAD SIGN ASSEMBLIES	25.00	0.00	25.00	EA	0.00	\$2,000.00	\$0.00
		0040	1200	9039902	MISC.REMOVE SIGN TRUSS CATWALKS & LIGHTING	8.00	0.00	8.00	EA	0.00	\$2,400.00	\$0.00
		0040	1210	9039902	MISC.REPAIR WELD	3.00	0.00	3.00	EA	0.00	\$10,000.00	\$0.00
		0050	1220	9109901	MISC.FIBER MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$1,022.00	\$0.00
		0050	1230	9109901	MISC.REMOVE SIDE RADAR DETECTOR ASSEMBLY	1.00	0.00	1.00	LS	0.00	\$1,870.00	\$0.00
	0050 1240 9109903 MISC.MODOT ITS ASSETS RELOCATION 1,500.00								LF	0.00	\$9.20	\$0.00
					ate as of Report Generated Date							\$2,078,478.79
191213-F03 Ove	rall - Tota	I Value Pos	ted to Da	ite as of Rep	ort Generated Date							\$2,078,478.79

Revision 4/1/2020 Page 7 of 13



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6l3263

riojeci.	00.0200											
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	5/18/20	5/21/20	0.01	LS	I-270NB At Dorsett exit Latitude: 38.62883 Longitude: -90.25400 Accuracy: 65m	147	LT	152	LT	Remove 417L.F. existing guardrail
			5/19/20	5/21/20	0.01	LS	I-270NB south end of Dorsett bridge Latitude: 38.62871 Longitude: -90.25404 Accuracy: 65m	140	LT	144	LT	Remove 431L.F. existing guardrail
			5/21/20	5/27/20	0.01	LS	I-270NB north end of Dorsett bridge Latitude: 38.72959 Longitude: -90.44357 Accuracy: 65m	133	LT	137	LT	Remove 394L.F. existing guardrail
			5/28/20	5/31/20	0.01	LS	I-270NB at I-70 Gore Point Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m	11	LT	14	LT	Remove 267L.F. existing guardrail
				5/31/20	0.01	LS	I-270NB north of Dorsett Latitude: 38.74379 Longitude: -90.44049 Accuracy: 65m	74	LT	81	LT	Remove 692L.F. existing guardrail
				5/31/20	0.01	LS	I-270NB to I-70EB Ramp 7 Latitude: 38.75231 Longitude: -90.44723 Accuracy: 1418m		LT		LT	Remove 348L.F. existing guardrail
				5/31/20	0.01	LS	I-70WB to I-270 Ramp 8 Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m		LT		LT	Remove 233L.F. existing guardrail
0060	2159903	MISC. SHAPING SLOPES	5/18/20	5/21/20	100.00	LF	I-270NB At Dorsett exit Latitude: 38.62883 Longitude: -90.25400 Accuracy: 65m	147	LT	152	LT	Pad for MASH
			5/19/20	5/21/20	100.00	LF	I-270NB south end of Dorsett bridge Latitude: 38.62880 Longitude: >90.25408 Accuracy: 200m	140	LT	144	LT	Pad for MASH
				5/27/20	100.00		I-270NB at new Barrier wall brown Dorsett and McKelvey Latitude: 38.72929 Longitude: -90.44361 Accuracy: 486m		LT	57		Pad for MASH
			5/28/20	5/31/20	100.00		I-270NB at I-70 Gore Point Latitude: 38.74635 Longitude: -90.43997 Accuracy: 165m		LT		LT	Pad for MASH
				5/31/20	100.00		I-270NB north of Dorsett Latitude: 38.75300 Longitude: -90.44807 Accuracy: 1418m	74	LT	81	LT	Pad for MASH
				5/31/20	100.00		I-270NB to I-70EB Ramp 7 Latitude: 38.75231 Longitude: -90.44723 Accuracy: 1418m		LT		LT	Pad for MASH
0000	4044000	DIT DAY FATALITA WATER TOOM OF DRAW	5/04/00	5/31/20	100.00		I-70WB to I-270 Ramp 8 Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m	04.57.0	LT	0.47	LT	Pad for MASH
0080		BIT. PAVEMENT MIXTURE PG64-22 (BP-1)		5/27/20	722.21		SB I-270 Rt Shoulder to Dorsett Road	21+57.9		9+17		
0120 0150		ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP1 TACK COAT		5/31/20	870.07 583.00		I-270SB Lanes 1 and 2 SB I-270 Rt Shoulder to Dorsett Road	21+57.9 21+57.9		62+70.0 9+17		
0130	407 1003	TAGIC GOAT		5/31/20	551.00	GAL		21		62		Tack calculated from Roadway Report
							Latitude: 38.62885 Longitude: -90.25393 Accuracy: 1002m					SB270 Lane 1 STA 21+57.9 - 39+09.7 SB270 Lane 2 STA21+57.9 - 62+70
0690	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.		5/27/20			SB I-270 Rt Shoulder to Dorsett Road	21+57.9		9+17		
			5/29/20	5/31/20		SQYD	I-270SB south of I-70 inside shoulder Latitude: 38.62884 Longitude: -90.25404 Accuracy: 65m	21+57.9		39+09.7		I-270SB inside shoulder.
0700	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REM	5/29/20	5/31/20	8,276.90	SQYD	I-270SB south of I-70 Lane 1&2 Latitude: 38.62885 Longitude: -90.25393 Accuracy: 1002m	21+57.9		62+70.0		SB270 Lane 1 STA 21+57.9 - 39+09.7 SB270 Lane 2 STA21+57.9 - 62+70
0860	6061060	MGS GUARDRAIL		5/21/20	350.00		I-270NB south end of Dorsett bridge Latitude: 38.62880 Longitude: -90.25408 Accuracy: 241m	140		144		New MGS rail
			5/21/20	5/27/20	25.00		I-270NB at new Barrier wall brown Dorsett and McKelvey Latitude: 38.72929 Longitude: -90.44361 Accuracy: 486m		LT		LT	New MGS rail
				5/27/20	362.50		I-270NB north end of Dorsett bridge Latitude: 38.714844 Longitude: -90.45295 Accuracy: 1429m	133		137		New MGS rail
			5/28/20	5/31/20	212.50		I-270NB at I-70 Gore Point Latitude: 38.74635 Longitude: -90.43997 Accuracy: 165m	11	LT	14	LT	New MGS rail
				5/31/20	325.00		I-70WB to I-270 Ramp 8 Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m		LT		LT	New MGS rail
				5/31/20	387.50		I-270NB to I-70EB Ramp 7 Latitude: 38.75231 Longitude: -90.44723 Accuracy: 1418m		LT		LT	New MGS rail
				5/31/20	687.50		I-270NB north of Dorsett Latitude: 38,75300 Longitude: -90.44807 Accuracy: 1418m		LT		LT	New MGS rail
0870		MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN		5/21/20	450.00		I-270NB At Dorsett exit Latitude: 38.62884 Longitude: -90.25403 Accuracy: 65m	147		152		New MGS rail 8ft post
0900	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	5/19/20	5/21/20	1.00	EA	I-270NB south end of Dorsett bridge Latitude: 38.62880 Longitude: -90.25408 Accuracy: 200m	140	LT	144	LT	BAS

Revision 4/1/2020 Page 8 of 13



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line	Item	Description	DWR	DWR	Quantity		Location and quantity of work.	From	Offset/	To	Offset/	Comments
Number	Code	Description	Date	Approval Date	Posted	Onits	LUCABUII	Station/ Log Mile	Distance	Station/ Log Mile	Distance	Connens
0900	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	5/21/20	5/27/20	1.00	EA	I-270NB at new Barrier wall brown Dorsett and McKelvey Latitude: 38.72929 Longitude: -90.44361 Accuracy: 486m	57	LT	57	LT	BAS
				5/27/20	1.00	EA	I-270NB north end of Dorsett bridge Latitude: 38.72929 Longitude: -90.44361 Accuracy: 165m	133	LT	137	LT	BAS
0910	6061080	MGS END ANCHOR	5/18/20	5/21/20	1.00	EA	I-270NB At Dorsett exit Latitude: 38.62884 Longitude: -90.25403 Accuracy: 65m	147	LT	152	LT	BEA
			5/21/20	5/27/20	1.00	EA	I-270NB north end of Dorsett bridge Latitude: 38.72929 Longitude: -90.44361 Accuracy: 165m	133	LT	137	LT	BEA
			5/28/20	5/31/20	1.00	EA	I-270NB at I-70 Gore Point Latitude: 38.74635 Longitude: -90.43997 Accuracy: 165m	11	LT	14	LT	BEA
				5/31/20	1.00	EA	I-270NB north of Dorsett Latitude: 38.75300 Longitude: -90.44807 Accuracy: 1418m	74	LT	81	LT	BEA
				5/31/20	1.00	EA	I-270NB to I-70EB Ramp 7 Latitude: 38.75231 Longitude: -90.44723 Accuracy: 1418m		LT		LT	BEA
				5/31/20	1.00	EA	I-70WB to I-270 Ramp 8 Latitude: 38.75301 Longitude: 90.44807 Accuracy: 1418m		LT		LT	BEA
0920	6063014	TYPE A CRSHWTHY END TERMINAL (MASH)	5/18/20	5/21/20	1.00	EA	I-270NB At Dorsett exit Latitude: 36.62884 Longitude: -90.25403 Accuracy: 65m	147	LT	152	LT	MASH
			5/19/20	5/21/20	1.00	EA	I-270NB south end of Dorsett bridge Latitude: 38.62880 Longitude: -90.25408 Accuracy: 200m	140	LT	144	LT	MASH
			5/21/20	5/27/20	1.00	EA	I-270NB at new Barrier wall brown Dorsett and McKelvey Latitude: 38.72929 Longitude: -90.44361 Accuracy: 486m	57	LT	57	LT	MASH
			5/28/20	5/31/20	1.00	EA	I-270NB at I-70 Gore Point Latitude: 38.74635 Longitude: 904.3997 Accuracy: 165m	11	LT	14	LT	MASH
				5/31/20	1.00	EA	I-270NB north of Dorsett Latitude: 38.75300 Longitude: -90.44807 Accuracy: 1418m	74	LT	81	LT	MASH
				5/31/20	1.00	EA	I-270NB to I-70EB Ramp 7 Latitude: 38.75231 Longitude: -90.44723 Accuracy: 1418m		LT		LT	MASH
				5/31/20	1.00	EA	I-70WB to I-270 Ramp 8 Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m		LT		LT	MASH
1100	9035004A	SH-FLAT SHEET	5/28/20	5/31/20	7.50	SQFT	I-270NB Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m	80	LT		LT	Sign #10b Airport
1110	9035011A	ST-STRUCTURAL	5/18/20	5/21/20	22.50	SQFT	I-270SB between Dorsett and Page Latitude: 38.62885 Longitude: -90.25399 Accuracy: 65m	172	RT	172	RT	Sign #18a Exit 16B
				5/21/20	25.00	SQFT	I-270NB north of Dorsett Latitude: 38.62880 Longitude: -90.25403 Accuracy: 65m	128	CL	128	CL	Sign #14 a Exit 20A
				5/21/20	104.00	SQFT	I-270NB between Dorsett and McKelvey Latitude: 38.62875 Longitude: -90.25400 Accuracy: 65m	116	CL	116	CL	Sign #12 a 270 North Chicago
				5/21/20	112.00	SQFT	I-270SB between Dorsett and Page Latitude: 38.62874 Longitude: -90.25404 Accuracy: 65m	172	RT	172	RT	Sign #18 b/c West 364 Exit Only
				5/21/20	180.00	SQFT	I-270NB north of Dorsett Latitude: 38.62880 Longitude: -90.25403 Accuracy: 65m	128	CL	128	CL	Sign #14b To exit 1-1/2 Miles
			5/28/20	5/31/20	20.00	SQFT	I-270NB Dorsett exit Latitude: 38.74165 Longitude: 90.43375 Accuracy: 1418m	101	LT		LT	Sign #13a Exit 17
				5/31/20	20.00	SQFT	I-270NB Dorsett exit Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m	148	LT		LT	Sign #15a Exit 17
				5/31/20	20.00	SQFT	I-270NB Dorsett exit Latitude: 38.75301 Longitude: >90.44807 Accuracy: 1418m	161	LT		LT	Sign #16a Exit 17
				5/31/20	25.00		I-270NB Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m	80	LT		LT	Sign #10 c Exit 20A
				5/31/20			Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m	20	LT		LT	Sign #1a Exit 20B
				5/31/20			I-270NB Dorsett exit Latitude: 38.75016 Longitude: >90.44556 Accuracy: 1418m	101			LT	Sign #13b/c Dorsett Road Exit Only
				5/31/20	56.00	SQFT	I-270NB Dorsett exit Latitude: 38.75159 Longitude: -90.44629 Accuracy: 1418m	161	LT		LT	Sign #16b/c Dorsett Road Exit Only

Revision 4/1/2020 Page 9 of 13



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1110	9035011A	A ST-STRUCTURAL 5/28/20 5/31/20 56.00 SQFT 1-270NB Dorsett exit Latitude: 38,75301 Longitude: -90,44807 Accuracy; 1418m		148	LT		LT	Sign #15b/c Dorsett Road Exit Only				
				5/31/20	130.00	SQFT	I-270NB Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m	80	LT		LT	Sign #10a Crossing Double White Line Prohibited
				5/31/20	220.00	SQFT	I-270NB Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m	80	LT		LT	Sign #10d/e Exit only (down arrows)
				5/31/20	276.00	SQFT	I-270NB north of I-70 gore point Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m	20	LT		LT	Sign #1b RTE. 180 1/2 Mile
1120	9035069A	SHF-FLAT SHEET FLUORESCENT	5/28/20	5/31/20	20.00	SQFT	I-270NB Dorsett exit Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m	148	LT		LT	Sign #15d 40 MPH Exit Advisory Sign (W13-2)
1130	9035071A	STF-STRUCTURAL FLUORESCENT	5/18/20	5/21/20	42.00	SQFT	I-270SB between Dorsett and Page Latitude: 38.62874 Longitude: -90.25404 Accuracy: 65m	172	RT	172	RT	Sign #18 b/c West 364 Exit Only
			5/28/20	5/31/20	42.00	SQFT	I-270NB Dorsett exit Latitude: 38.75266 Longitude: -90.44776 Accuracy: 1418m	101	LT		LT	Sign #13b/c Dorsett Road Exit Only
				5/31/20	42.00	SQFT	I-270NB Dorsett exit Latitude: 38.75283 Longitude: -90.44785 Accuracy: 1418m	161	LT		LT	Sign #16b/c Dorsett Road Exit Only
				5/31/20	42.00	SQFT	I-270NB Dorsett exit Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m	148	LT		LT	Sign #15b/c Dorsett Road Exit Only
				5/31/20	66.00	SQFT	I-270NB Latitude: 38.75301 Longitude: -90.44807 Accuracy: 1418m	80	LT		LT	Sign #10d/e Exit only (down arrows)

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 10 of 13



## Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		3	Apr 16, 2020	SYSTEM	(\$1,039.12)	
				3	Apr 16, 2020	SYSTEM	\$1,039.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	May 4, 2020	SYSTEM	(\$13,519.68)	
				4	May 4, 2020	SYSTEM	\$13,519.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stgemr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0070 -	Total						\$0.00	
0800	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	6	Jun 2, 2020	gummer1	(\$1,056.23)	May 2020 - Second Period
			ACAD - Tota	al			(\$1,056.23)	
	Other Item Adjustment - Total						(\$1,056.23)	
0080 -	Total						(\$1,056.23)	
0120	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Other Item Adjustment	ACAD	6	Jun 2, 2020	gummer1	(\$3,148.31)	May 2020 Second Period
			ACAD - Tota	al			(\$3,148.31)	
	Other Item Adjustment - Total						(\$3,148.31)	
0120 -	Total						(\$3,148.31)	
0170	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	Material		4	May 4, 2020	SYSTEM	(\$116,703.00)	
				4	May 4, 2020	SYSTEM	\$116,703.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stgemr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$116,703.00)	
				5	May 18, 2020	SYSTEM	\$116,703.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stgemr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$116,703.00)	
				6	Jun 2, 2020	SYSTEM	\$116,703.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0170 -	Total						\$0.00	
0180	CONCRETE PAVEMENT (7 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		3	Apr 16, 2020	SYSTEM	(\$12,469.50)	
				3	Apr 16, 2020	SYSTEM	\$12,469.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	May 4, 2020	SYSTEM	(\$12,469.50)	
				4	May 4, 2020	SYSTEM	\$12,469.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$12,469.50)	
				5	May 18, 2020	SYSTEM	\$12,469.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stgemr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$12,469.50)	
				6	Jun 2, 2020	SYSTEM	\$12,469.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0180 -	Total						\$0.00	

Revision 4/1/2020 Page 11 of 13



## Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0220	MISC. CONCRETE CURB	Overrun	Overrun	3	Apr 16, 2020	SYSTEM	(\$12,600.00)	
			Overrun - To	otal			(\$12,600.00)	
	Overrun - Total						(\$12,600.00)	
0220 -	· Total						(\$12,600.00)	
0240	IMPACT ATTENUATOR 70 MPH (SAND BARRELS)	Overrun	Overrun		Apr 2, 2020	SYSTEM	(\$3,000.00)	
			Overrun - To	otal			(\$3,000.00)	
	Overrun - Total						(\$3,000.00)	
0240 -	· Total						(\$3,000.00)	
0280	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		3	Apr 16, 2020	SYSTEM	(\$57,564.00)	
				3	Apr 16, 2020	SYSTEM	\$57,564.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washaj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				4	May 4, 2020	SYSTEM	(\$57,564.00)	
				4	May 4, 2020	SYSTEM	\$57,564.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stgemr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$57,564.00)	
				5	May 18, 2020	SYSTEM	\$57,564.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stgemr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$57,564.00)	
				6	Jun 2, 2020	SYSTEM	\$57,564.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gummer1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0280 -	· Total						\$0.00	
0320	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT	Material		3	Apr 16, 2020	SYSTEM	(\$699.00)	
	REPAIR			3	Apr 16, 2020	SYSTEM	\$699.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washaj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
								rayment Estimate exception 14 on the current rayment estimate.
				4	May 4, 2020	SYSTEM	(\$699.00)	rayment Estimate Exception 14 on the current rayment Estimate.
				4		SYSTEM	(\$699.00) \$699.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					2020 May 4,		· , ,	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding
				4	2020 May 4, 2020 May 18,	SYSTEM	\$699.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding
				<ul><li>4</li><li>5</li><li>5</li><li>6</li></ul>	2020 May 4, 2020 May 18, 2020 May 18,	SYSTEM SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding
				5	2020 May 4, 2020 May 18, 2020 May 18, 2020	SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00 (\$699.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgem1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgem1 overridding
			- Total	<ul><li>4</li><li>5</li><li>5</li><li>6</li></ul>	2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding
	Material - Total		- Total	<ul><li>4</li><li>5</li><li>5</li><li>6</li></ul>	2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00 (\$699.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding
0320 -			- Total	<ul><li>4</li><li>5</li><li>5</li><li>6</li></ul>	2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00 \$699.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding
0320 - 0360		Overrun	- Total	<ul><li>4</li><li>5</li><li>5</li><li>6</li><li>6</li></ul>	2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00 (\$699.00) \$699.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding
	Total  ADVANCED WARNING RAIL	Overrun		<ul><li>4</li><li>5</li><li>5</li><li>6</li><li>6</li></ul>	2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00 (\$699.00) \$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgemr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgemr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding
	Total  ADVANCED WARNING RAIL	Overrun		4 5 5 6 6	2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Apr 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$699.00 (\$699.00) \$699.00 (\$699.00) \$0.00 \$0.00 (\$90.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stgern1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stgern1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user gummer1 overridding Payment Estimate Exception 6 on the current Payment Estimate.

Revision 4/1/2020 Page 12 of 13



## Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

2020   Estimate liters Adjustment (005) due to user washall overriding Payment Estimate Exception 15 on the current Payment Estimate 2020   SYSTEM   \$47,340.00   This adjustment offsets the original system-generated Overrun Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment offsets the original system-generated Overrun Payment Estimate Exception 12 on the current Payment Estimate Exception 13 on the current Payment Estimate Exception 14 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 17 on the curre	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
Output				Туре				(400.00)	
CONCRETE TRAFFIC DARRIUR, TYPED   Park								<u> </u>	
PATE									
Part	0440		Material		3		SYSTEM	(\$47,340.00)	
					3		SYSTEM	\$47,340.00	
					4		SYSTEM	(\$47,340.00)	
					4		SYSTEM	\$47,340.00	
Page					5		SYSTEM	(\$47,340.00)	
Part					5		SYSTEM	\$47,340.00	
Section   Content   Cont					6		SYSTEM	(\$47,340.00)	
Material - Total   S0.00					6		SYSTEM	\$47,340.00	
Octobal   PREFORMED THERMOPLASTIC   Material   PAVEMENT MARKING, 6 IN. WHITE   PAVEMENT MARK				- Total				\$0.00	
PREFORMED THERMOPLASTIC   PAVEMENT MARKING, 6 IN, WHITE   Waterial   Support		Material - Total						\$0.00	
PAVEMENT MARKING, 6 IN. WHITE	0440 -	- Total						\$0.00	
2020   Estimate Item Adjustment (0008) due to user washalf overridding Payment Estimate Exception 21 on the current Payment Estimate.   4	0490		Material		3		SYSTEM	(\$1,190.00)	
2020					3		SYSTEM	\$1,190.00	
Substitute   Estimate   Exception 17 on the current   Payment   Payment   Estimate   Exception 17 on the current   Payment   P					4		SYSTEM	(\$1,190.00)	
Material - Total   S0.00					4		SYSTEM	\$1,190.00	
O490				- Total				\$0.00	
MGS END ANCHOR   Overrun   Overrun   6		Material - Total						\$0.00	
2020   Structure   Control   Coverrun - Total   C	0490 -	- Total						\$0.00	
Overrun - Total  Overrun - Total  OshF-FLAT SHEET FLUORESCENT  Material  SHF-FLAT SHEET FLUORESCENT  Material  SHF-FLAT SHEET FLUORESCENT  Material  Total  - Total  Total  Naterial  - Total  Naterial - Total  MISC. 125 FT. SPAN SIGN TRUSS, SIGN #5  OTHR - Total  OTHR - Total  OTHR - Total  (\$1,000.00)  (\$1,000.00)  SYSTEM  \$1,000.00  This adjustment offsets the original system-generated Overrun Payre Estimate Item Adjustment (0006) due to user stgemr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  S0.00  1120 - Total  S0.00  MISC. 125 FT. SPAN SIGN TRUSS, SIGN #5  OTHR - Total  OTHR - Total  OTHR - Total  (\$90.72)  Other Item Adjustment - Total  (\$90.72)  Other Item Adjustment - Total	0910	MGS END ANCHOR	Overrun	Overrun	6		SYSTEM	(\$1,000.00)	
SHF-FLAT SHEET FLUORESCENT   Material				Overrun - To	otal			(\$1,000.00)	
1120 SHF-FLAT SHEET FLUORESCENT Material  5 May 18, 2020  5 May 18, 2020  5 May 18, 2020  5 May 18, 2020  This adjustment offsets the original system-generated Overrun Payre Estimate Item Adjustment (0006) due to user stgemr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  1120 - Total  1140 MISC. 125 FT. SPAN SIGN TRUSS, SIGN #5  OTHR 6 Jun 2, 2020  Other Item Adjustment - Total  (\$90.72)  Other Item Adjustment - Total  (\$90.72)  Other Item Adjustment - Total		Overrun - Total						(\$1,000.00)	
2020  5 May 18, 2020  5 SYSTEM  \$ 1,000.00  This adjustment offsets the original system-generated Overrun Payre Estimate Item Adjustment (0006) due to user stgemr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  50.00  1120 - Total  1140  MISC. 125 FT. SPAN SIGN TRUSS, SIGN #5 SIGN #5  OTHR - Total  OTHR - Total  OTHR - Total  (\$90.72)  Other Item Adjustment - Total  (\$90.72)  Other Item Adjustment - Total	0910 -	- Total						(\$1,000.00)	
Estimate Item Adjustment (0006) due to user stgemr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  **Total**  **So.00**  **Material - Total**  **So.00**  **Material - Total**  **So.00**  **India	1120	SHF-FLAT SHEET FLUORESCENT	Material		5		SYSTEM	(\$1,000.00)	
Material - Total \$0.00  1120 - Total \$0.00  1140 MISC. 125 FT. SPAN SIGN TRUSS, SIGN #5 Adjustment OTHR 6 Jun 2, 2020 gummer1 (\$90.72) Adjustment for sign inspection materials on job per Section 1042.3.3 for all line items on job pertaining to signing See Letter dated May 21, 2020 in files from Sam Marshall / Environmental Chemist  OTHR - Total (\$90.72)  Other Item Adjustment - Total (\$90.72)					5		SYSTEM	\$1,000.00	
1120 - Total  1140 MISC. 125 FT. SPAN SIGN TRUSS, SIGN #5 Other Item Adjustment OTHR 6 Jun 2, 2020 gummer1 (\$90.72) Adjustment for sign inspection materials on job per Section 1042.3.3 for all line items on job pertaining to signing See Letter dated May 21, 2020 in files from Sam Marshall / Environmental Chemist  OTHR - Total (\$90.72)  Other Item Adjustment - Total (\$90.72)				- Total				\$0.00	
1140 MISC. 125 FT. SPAN SIGN TRUSS, SIGN #5 SIGN #5 Other Item Adjustment - Total  OTHR - Total  OTHR 6 Jun 2, 2020 gummer1 (\$90.72) Adjustment for sign inspection materials on job per Section 1042.3.3 for all line items on job pertaining to signing See Letter dated May 21, 2020 in files from Sam Marshall / Environmental Chemist  OTHR - Total (\$90.72)		Material - Total						\$0.00	
SIGN #5 Adjustment  OTHR - Total  Other Item Adjustment - Total  SIGN #5 Adjustment  OTHR - Total	1120 -	- Total						\$0.00	
Other Item Adjustment - Total (\$90.72)	1140			OTHR	6		gummer1	(\$90.72)	See Letter dated May 21, 2020 in files from Sam Marshall /
				OTHR - Tota	al			(\$90.72)	
1140 - Total (\$90.72)		Other Item Adjustment - Total						(\$90.72)	
	1140 -	- Total						(\$90.72)	
Overall - Total (\$20,985.26)	Overa	all - Total							

Revision 4/1/2020 Page 13 of 13