18.98%



Missouri Department of Transportation Contractor's Pay Estimate Summary

November 1, 2021

Pay Estimate Created Date: August 17, 2020

Progress	s Estimate Number	Contract ID	191213-H02	Pay Period Start	August 2, 2020	Original Contract Amou	nt \$11,971,234.56
10		Prime Contractor	Capital Paving & Con LLC	struction, Pay Period End	August 15, 2020	Net Change Order Amount Current Contract Amou	\$134,248.16 nt \$12,105,482.72
Approval Date	al Date						
August 17, 2020			Generated and A	pproved (and should be consid	dered Draft) at th	e Project Office Level by	pinkle1
August 17, 2020			Reviewed and Approv	ved (and should be considered	Draft) at the Re	sident Engineer Level by	dowdyd
August 19, 2020 Reviewed and Approved at the Central Office Controllers Office Level by							
Original Comp	letion Date	Current	Completion Date	Actual Completion Date	% o	Current Contract Amou	nt Complete

No Milestones Exist for Contract

November 1, 2021

Contract Total Pa	y For Estimate No. 10			
		This Estimate	Previous	To Date
191213-H02				
	Total Posted Items Pay	\$216,168.44	\$2,081,430.05	\$2,297,598.49
	Gross Item Adjustments	(\$26,567.51)	\$184,818.51	\$158,251.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	(\$96,739.46)	(\$96,739.46)
	·		\$2,169,509.10	\$2,359,110.03
Contract Total Pa	yable This Estimate:	\$189,600.93		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3310	0020	2159903	MISC.Modified Shaping Slopes, Class III	LF	\$9.000	960	\$8,640.00
	0480	6061060	MGS GUARDRAIL	LF	\$20.000	1,425	\$28,500.00
	0490	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$2,800.000	2	\$5,600.00
	0510	6061080	MGS END ANCHOR	EA	\$1,000.000	2	\$2,000.00
	0520	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$2,700.000	4	\$10,800.00
	0770	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	LF	\$238.640	54	\$12,886.56
	0850	2169903	MISC.Remove and Replace Curb and Parapet	LF	\$255.690	8.5	\$2,173.37
	0860	7034214	CLASS B-2 CONCRETE	CUYD	\$2,669.200	5.75	\$15,347.90
	0870	7034600	CURB BLOCKOUT	LF	\$78.210	301.5	\$23,580.32
	0890	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$1.820	415	\$755.30
	0900	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	LF	\$418.130	68	\$28,432.84
	0910	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	LF	\$271.730	38	\$10,325.74
	0990	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	LF	\$271.730	38	\$10,325.74
	1000	2169903	MISC.Remove and Replace Curb and Parapet	LF	\$362.980	6	\$2,177.88
	1010	7034214	CLASS B-2 CONCRETE	CUYD	\$2,609.040	4.3	\$11,218.87
	1020	7034600	CURB BLOCKOUT	LF	\$80.220	310	\$24,868.20
	1040	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$1.820	665	\$1,210.30
	1050	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	LF	\$450.210	38	\$17,107.98
	5003	7061070	MECHANICAL BAR SPLICE	EA	\$27.180	8	\$217.44
Project J9I33	310 - Total						\$216,168.44
Overall - Tot	al						\$216,168.44

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Revision 4/1/2020 Page 1 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 17, 2020

Progress Estimate Number 10 Contract ID 191213-H02 Prime Contractor LLC Prime Contractor LLC Pay Period Start Pay Period End August 2, 2020 Original Contract Amount \$11,971,234.56 Pay Period End August 15, 2020 Net Change Order Amount \$134,248.16 Current Contract Amount \$12,105,482.72

<u>Line item</u>	Aujusi	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3310	0330	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-4,657	\$1.00	(\$4,657.00)
	0330	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user pinkle1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	4,657	\$1.00	\$4,657.00
	0340	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-516	\$1.00	(\$516.00)
	0340	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	516	\$1.00	\$516.00
	0480	MGS GUARDRAIL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$15,627.50)
	0490	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$3,206.67)
	0510	MGS END ANCHOR	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$1,084.45)
	0520	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$6,648.89)
	0530	CURB BLOCKOUT	Material			-432	\$86.25	(\$37,260.00)
	0530	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	432	\$86.25	\$37,260.00
	0550	CURB BLOCKOUT	Material			-432	\$81.23	(\$35,091.36)
	0550	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	432	\$81.23	\$35,091.36
	0700	CURB BLOCKOUT	Material			-525	\$86.23	(\$45,270.75)
	0700	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	525	\$86.23	\$45,270.75
	0730	MISC.	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 21 on the current Payment Estimate.	278.1	\$68.18	\$18,960.86
	0730	MISC.	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-278.1	\$68.18	(\$18,960.86)
	0730	MISC.	Material			-328.1	\$68.18	(\$22,369.86)
	0730	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user pinkle1	328.1	\$68.18	\$22,369.86

Revision 4/1/2020 Page 2 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 17, 2020

Progress Estimate Number 10 Contract ID 191213-H02 Prime Contractor LLC Prime Contractor LLC Pay Period Start Pay Period End August 2, 2020 Original Contract Amount \$11,971,234.56 Pay Period End August 15, 2020 Net Change Order Amount \$134,248.16 Current Contract Amount \$12,105,482.72

ct er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
10					overridding Payment Estimate Exception 17 on the current Payment Estimate.			
	0800	CURB BLOCKOUT	Material			-301.5	\$78.21	(\$23,580.32
	0800	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	301.5	\$78.21	\$23,580.32
	0870	CURB BLOCKOUT	Material			-603	\$78.21	(\$47,160.63
	0870	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	603	\$78.21	\$47,160.63
	0940	CURB BLOCKOUT	Material			-310	\$80.22	(\$24,868.2
1	0940	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0017) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	310	\$80.22	\$24,868.20
	1020	CURB BLOCKOUT	Material			-620	\$80.22	(\$49,736.40
1	1020	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	620	\$80.22	\$49,736.40
	1070	CURB BLOCKOUT	Material			-287	\$120.32	(\$34,531.8
	1070	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	287	\$120.32	\$34,531.84
	1100	CURB BLOCKOUT	Material			-309	\$117.32	(\$36,251.8
	1100	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	309	\$117.32	\$36,251.88
	1110	CURB BLOCKOUT	Material			-255	\$117.32	(\$29,916.60
	1110	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0021) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	255	\$117.32	\$29,916.60
	1140	CURB BLOCKOUT	Material			-265	\$116.31	(\$30,822.1
	1140	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0022) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	265	\$116.31	\$30,822.15
	1380	CURB BLOCKOUT	Material			-539	\$83.22	(\$44,855.58
1	1380	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0023) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	539	\$83.22	\$44,855.58

Revision 4/1/2020 Page 3 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 17, 2020

Progress Estimate Number	Contract ID	191213-H02	Pay Period Start	August 2, 2020	Original Contract Amount	\$11,971,234.56
10	Prime Contractor	Capital Paving & Construction, LLC	Pay Period End	2020	Net Change Order Amount Current Contract Amount	\$134,248.16 \$12,105,482.72

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3310	1430	SILICONE EXPANSION JOINT SEALANT	Material			-56	\$71.19	(\$3,986.64)
	1430	SILICONE EXPANSION JOINT SEALANT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0024) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	56	\$71.19	\$3,986.64
Total								(\$26,567.51)

Revision 4/1/2020 Page 4 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information							
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work							
J9I3310	I 55-2(115)	Resurface and bridge replacement I-55 STE GENEVIEVE replacement GENEVIEVE											
Totals by .	Job Numbe	rs											
J9I3310		d Item Pay Item Adjustm		i Item Pay	This Estimate \$216,168.44 (\$26,567.51) \$189,600.93	Previous \$2,081,430.05 \$184,818.51 \$2,266,248.56	To Date \$2,297,598.49 \$158,251.00 \$2,455,849.49						
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 (\$96,739.46)	\$0.00 \$0.00 \$0.00 (\$96,739.46)						

Revision 4/1/2020 Page 5 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9I3310, Item 7034600, Project Item Line Number 1020, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb has not been sealed.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3310, Item 7034600, Project Item Line Number 0530, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb was sealed with the incorrect spec of sealant.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3310, Item 7034600, Project Item Line Number 1100, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb was sealed with the incorrect spec of sealant.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3310, Item 7034600, Project Item Line Number 1380, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb was sealed with the incorrect spec of sealant.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3310, Item 7034600, Project Item Line Number 0800, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Curb blockout has not been sealed.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3310, Item 7034600, Project Item Line Number 0940, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on QC concrete test results. None have been received.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3310, Item 7034600, Project Item Line Number 0940, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb has not been sealed.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3310, Item 7034600, Project Item Line Number 0550, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb was sealed with the incorrect spec of sealant.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3310, Item 7034600, Project Item Line Number 1110, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb was sealed with the incorrect spec of sealant.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3310, Item 7034600, Project Item Line Number 1140, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb was sealed with the incorrect spec of sealant.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3310, Item 7034600, Project Item Line Number 0700, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Concrete testing in progress. Waiting on 28 day strength.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 0700, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb has not been sealed.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 1070, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb was sealed with the incorrect spec of sealant.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 0870, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb has not been sealed.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7049904, Project Item Line Number 0730, Material Set 7049904, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Aggregate test results have been received from QC. Tests need to be entered by MoDOT QA.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7049904, Project Item Line Number 0730, Material Set 7049904, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Aggregate test results have been received from QC. Tests need to be entered by MoDOT QA.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7049904, Project Item Line Number 0730, Material Set 7049904, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Need concrete test results from QC. None have been received.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7173002, Project Item Line Number 1430, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	Contractor has uploaded PAL ID to sharepoint, but it has not been entered into AWP.	pinkle1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-H02, Contract Project J9l3310, Project Item Line Number 0330, Contract Line Item Number 0330, Item 6205301B, Minor Item.	Change order in progress.	pinkle1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-H02, Contract Project J9I3310, Project Item Line Number 0340, Contract Line Item Number 0340, Item 6205303B, Minor Item.	Change order in progress.	pinkle1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-H02, Contract Project J9I3310, Project Item Line Number 0730, Contract Line Item Number 0730, Item 7049904, Minor Item.	Change order in progress.	pinkle1	Overridden

Revision 4/1/2020 Page 6 of 29



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H02	J9I3310	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.64	\$80,000.00	\$51,200.00
		0001	0020	2159903	MISC.Modified Shaping Slopes, Class III	16,911.00	0.00	16,911.00	LF	10,493.50	\$9.00	\$94,441.50
		0001	0030	3049910	MISC.Permanent Aggregate Edge Treatment	6,234.20	0.00	6,234.20	TONS	0.00	\$31.53	\$0.00
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	485.00	0.00	485.00	TONS	0.00	\$27.08	\$0.00
		0001	0050	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	21,372.90	0.00	21,372.90	TONS	0.00	\$55.86	\$0.00
		0001	0060	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	85,624.80	0.00	85,624.80	TONS	0.00	\$74.25	\$0.00
		0001	0070	4071005	TACK COAT	84,430.00	0.00	84,430.00	GAL	0.00	\$1.97	\$0.00
		0001	0800	4134000	BITUMINOUS FOG SEAL	30,480.00	0.00	30,480.00	GAL	0.00	\$3.04	\$0.00
		0001	0090	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARRELS)	2.00	0.00	2.00	EA	2.00	\$5,750.00	\$11,500.00
		0001	0100	6122020	REPLACEMENT SAND BARREL	5.00	0.00	5.00	EA	0.00	\$300.00	\$0.00
		0001	0110	6122030	IMPACT ATTENUATOR (RELOCATION)	11.00	11.00	22.00	EA	18.00	\$672.00	\$12,096.00
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$750.00	\$1,500.00
		0001	0130	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	168.00	48.00	216.00	SQYD	216.00	\$181.05	\$39,106.80
		0001	0140	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	17.00	179.00	196.00	SQYD	196.00	\$7.18	\$1,407.28
		0001	0150	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	17.00	179.00	196.00	SQYD	196.00	\$5.40	\$1,058.40
		0001	0160	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	516.00	132.00	648.00	LF	648.00	\$8.85	\$5,734.80
		0001	0170	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	80.00	11.00	91.00	EA	91.00	\$6.44	\$586.04
		0001	0180	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	170.00	-134.00	36.00	EA	36.00	\$8.27	\$297.72
		0001	0190	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	16.00	11.00	27.00	EA	27.00	\$2.67	\$72.09
		0001	0200	6161005	CONSTRUCTION SIGNS	3,321.00	0.00	3,321.00	SQFT	2,996.00	\$8.00	\$23,968.00
		0001	0210	6161008	ADVANCED WARNING RAIL SYSTEM	18.00	10.00	28.00	EA	28.00	\$45.00	\$1,260.00
		0001	0220	6161009	FLAG ASSEMBLY	26.00	2.00	28.00	EA	28.00	\$20.00	\$560.00
		0001	0230	6161010	RELOCATED SIGNS	2,276.00	0.00	2,276.00	SQFT	624.00	\$7.00	\$4,368.00
		0001	0240	6161025	CHANNELIZER (TRIM LINE)	552.00	0.00	552.00	EA	230.00	\$18.00	\$4,140.00
		0001	0250	6161033	DIRECTIONAL INDICATOR BARRICADE	72.00	0.00	72.00	EA	56.00	\$65.00	\$3,640.00
		0001	0260	6161040	FLASHING ARROW PANEL	5.00	0.00	5.00	EA	4.00	\$850.00	\$3,400.00
		0001	0270	6161055	SEQUENTIAL FLASHING WARNING LIGHT	54.00	2.00	56.00	EA	56.00	\$50.00	\$2,800.00
		0001	0280	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$2,000.00	\$8,000.00
		0001	0290	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	2.00	0.00	2.00	EA	1.00	\$16,800.00	\$16,800.00
		0001	0300	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,188.00	0.00	1,188.00	LF	1,050.00	\$28.25	\$29,662.50
		0001	0310	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	13,068.00	0.00	13,068.00	LF	9,550.00	\$8.50	\$81,175.00
		0001	0320	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$623,256.10	\$311,628.05
		0001	0330	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	25,760.00	0.00	25,760.00	LF	32,966.00	\$1.00	\$32,966.00
		0001	0340	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	31,740.00	0.00	31,740.00	LF	32,256.00	\$1.00	\$32,256.00
		0001	0350	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	224.00	0.00	224.00	LF	56.00	\$10.00	\$560.00
		0001	0360	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	309,366.00	0.00	309,366.00	LF	0.00	\$0.25	\$0.00
		0001	0370	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	250,800.00	0.00	250,800.00	LF	0.00	\$0.19	\$0.00
		0001	0380	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	10,120.00	0.00	10,120.00	LF	0.00	\$1.00	\$0.00
		0001	0390	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,118.00	0.00	5,118.00	LF	0.00	\$0.30	\$0.00
		0001	0400	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,795.00	0.00	5,795.00	LF	0.00	\$0.30	\$0.00
		0001	0410	6207001	PAVEMENT MARKING REMOVAL	184,786.00	0.00	184,786.00	LF	45,062.00	\$0.25	\$11,265.50
		0001	0420	6209901	MISC.Temporary Pavement Marking Paint	1.00	0.00	1.00	LS	0.00	\$0.01	\$0.00
			0430	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	9,901.00	0.00	9,901.00	SQYD	0.00	\$3.32	\$0.00

Page 7 of 29 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H02	J9I3310	0001	0440	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	966.00	0.00	966.00	SQYD	0.00	\$9.28	\$0.00
		0001	0450	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	29,408.00	0.00	29,408.00	SQYD	0.00	\$2.94	\$0.00
		0001	0460	6229905	MISC.Smoothness Correction	29,567.90	0.00	29,567.90	SQYD	0.00	\$1.76	\$0.00
		0001	0470	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	4,316.00	0.00	4,316.00	STA	0.00	\$15.68	\$0.00
		0010	0480	6061060	MGS GUARDRAIL	11,925.00	0.00	11,925.00	LF	6,650.00	\$20.00	\$133,000.00
		0010	0490	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	40.00	0.00	40.00	EA	26.00	\$2,800.00	\$72,800.00
		0010	0500	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	2.00	0.00	2.00	EA	0.00	\$2,700.00	\$0.00
		0010	0510	6061080	MGS END ANCHOR	13.00	0.00	13.00	EA	5.00	\$1,000.00	\$5,000.00
		0010	0520	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	45.00	0.00	45.00	EA	25.00	\$2,700.00	\$67,500.00
		0070	0530	7034600	CURB BLOCKOUT	432.00	0.00	432.00	LF	432.00	\$86.25	\$37,260.00
		0070	0540	7040113	CLEANING AND EPOXY COATING	346.00	0.00	346.00	SQFT	346.00	\$8.22	\$2,844.12
		0071	0550	7034600	CURB BLOCKOUT	432.00	0.00	432.00	LF	432.00	\$81.23	\$35,091.36
		0071	0560	7040113	CLEANING AND EPOXY COATING	346.00	0.00	346.00	SQFT	346.00	\$8.22	\$2,844.12
		0072	0570	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	69.00	0.00	69.00	LF	0.00	\$298.86	\$0.00
		0072	0580	2169903	MISC.Remove and Replace Curb and Parapet	12.00	0.00	12.00	LF	0.00	\$362.98	\$0.00
		0072	0590	7034214	CLASS B-2 CONCRETE	6.10	0.00	6.10	CUYD	0.00	\$3,608.74	\$0.00
		0072	0600	7034600	CURB BLOCKOUT	529.00	0.00	529.00	LF	0.00	\$79.21	\$0.00
		0072	0610	7040104	HALF-SOLE REPAIR	200.00	0.00	200.00	SQFT	0.00	\$101.27	\$0.00
		0072	0620	7040113	CLEANING AND EPOXY COATING	611.00	0.00	611.00	SQFT	611.00	\$12.03	\$7,350.33
		0072	0630	7049904	MISC.Repairing Concrete Wearing Surface	50.00	0.00	50.00	SQFT	0.00	\$68.18	\$0.00
		0072	0640	7101000	REINFORCING STEEL (EPOXY COATED)	560.00	0.00	560.00	LB	0.00	\$1.82	\$0.00
		0072	0650	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	69.00	0.00	69.00	LF	0.00	\$473.28	\$0.00
		0072	0660	7172054	OPEN CELL FOAM JOINT SEAL	69.00	0.00	69.00	LF	0.00	\$106.29	\$0.00
		0073	0670	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	68.00	0.00	68.00	LF	68.00	\$302.82	\$20,591.76
		0073	0680	2169903	MISC.Remove and Replace Curb and Parapet	12.00	0.00	12.00	LF	12.00	\$362.98	\$4,355.76
		0073	0690	7034214	CLASS B-2 CONCRETE	7.40	0.00	7.40	CUYD	7.40	\$3,005.11	\$22,237.81
		0073	0700	7034600	CURB BLOCKOUT	525.00	0.00	525.00	LF	525.00	\$86.23	\$45,270.75
		0073	0710	7040104	HALF-SOLE REPAIR	200.00	0.00	200.00	SQFT	103.70	\$101.27	\$10,501.70
		0073	0720	7040113	CLEANING AND EPOXY COATING	677.00	0.00	677.00	SQFT	677.00	\$12.03	\$8,144.31
		0073	0730	7049904	MISC.Repairing Concrete Wearing Surface	50.00	0.00	50.00	SQFT	328.10	\$68.18	\$22,369.86
		0073	0740	7101000	REINFORCING STEEL (EPOXY COATED)	1,210.00	0.00	1,210.00	LB	1,210.00	\$1.73	\$2,093.30
		0073	0750	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	68.00	0.00	68.00	LF	68.00	\$469.27	\$31,910.36
		0073	0760	7172054	OPEN CELL FOAM JOINT SEAL	68.00	0.00	68.00	LF	68.00	\$107.29	\$7,295.72
		0074	0770	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	108.00	0.00	108.00	LF	108.00	\$238.64	\$25,773.12
		0074	0780	2169903	MISC.Remove and Replace Curb and Parapet	17.00	0.00	17.00	LF	8.50	\$255.69	\$2,173.36
		0074	0790	7034214	CLASS B-2 CONCRETE	11.50	0.00	11.50	CUYD	5.75	\$2,669.20	\$15,347.90
		0074	0800	7034600	CURB BLOCKOUT	603.00	0.00	603.00	LF	301.50	\$78.21	\$23,580.32
		0074	0810	7040113	CLEANING AND EPOXY COATING	2,214.00	0.00	2,214.00	SQFT	2,214.00	\$8.22	\$18,199.08
		0074	0820	7101000	REINFORCING STEEL (EPOXY COATED)	830.00	0.00	830.00	LB	415.00	\$1.82	\$755.30
		0074	0830	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	108.00	0.00	108.00	LF	54.00	\$418.13	\$22,579.02
		0075	0840	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	108.00	0.00	108.00	LF	108.00	\$238.64	\$25,773.12
		0075	0850	2169903	CONCRETE MISC.Remove and Replace Curb and Parapet	17.00	0.00	17.00	LF	17.00	\$255.69	\$4,346.73
		0075	0860	7034214	CLASS B-2 CONCRETE	11.50	0.00	11.50	CUYD	11.50	\$2,669.20	\$30,695.80
		0075	0870	7034600	CURB BLOCKOUT	603.00	0.00	603.00	LF	603.00	\$78.21	\$47,160.63
		0075	0880	7040113	CLEANING AND EPOXY COATING	2,214.00	0.00	2,214.00	SQFT	2,214.00	\$8.22	\$18,199.08

Revision 4/1/2020 Page 8 of 29



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and valu	ies are	based on	Report Generated date and can differ from the posted am	ount at the	time the I	≘stimate wa	s Genei	rated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H02	J9I3310	0075	0890	7101000	REINFORCING STEEL (EPOXY COATED)	830.00	0.00	830.00	LB	830.00	\$1.82	\$1,510.60
		0075	0900	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	108.00	0.00	108.00	LF	108.00	\$418.13	\$45,158.04
		0076	0910	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	76.00	0.00	76.00	LF	76.00	\$271.73	\$20,651.48
		0076	0920	2169903	MISC.Remove and Replace Curb and Parapet	12.00	0.00	12.00	LF	6.00	\$362.98	\$2,177.88
		0076	0930	7034214	CLASS B-2 CONCRETE	8.60	0.00	8.60	CUYD	4.30	\$2,609.04	\$11,218.87
		0076	0940	7034600	CURB BLOCKOUT	620.00	0.00	620.00	LF	310.00	\$80.22	\$24,868.20
		0076	0950	7040113	CLEANING AND EPOXY COATING	2,304.00	0.00	2,304.00	SQFT	2,304.00	\$9.20	\$21,196.80
		0076	0960	7101000	REINFORCING STEEL (EPOXY COATED)	1,330.00	0.00	1,330.00	LB	665.00	\$1.82	\$1,210.30
		0076	0970	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	76.00	0.00	76.00	LF	38.00	\$450.21	\$17,107.98
		0076	0980	7172054	OPEN CELL FOAM JOINT SEAL	76.00	0.00	76.00	LF	38.00	\$98.27	\$3,734.26
		0077	0990	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	76.00	0.00	76.00	LF	76.00	\$271.73	\$20,651.48
		0077	1000	2169903	MISC.Remove and Replace Curb and Parapet	12.00	0.00	12.00	LF	12.00	\$362.98	\$4,355.76
		0077	1010	7034214	CLASS B-2 CONCRETE	8.60	0.00	8.60	CUYD	8.60	\$2,609.04	\$22,437.74
		0077	1020	7034600	CURB BLOCKOUT	620.00	0.00	620.00	LF	620.00	\$80.22	\$49,736.40
		0077	1030	7040113	CLEANING AND EPOXY COATING	2,304.00	0.00	2,304.00	SQFT	2,304.00	\$9.20	\$21,196.80
		0077	1040	7101000	REINFORCING STEEL (EPOXY COATED)	1,330.00	0.00	1,330.00	LB	1,330.00	\$1.82	\$2,420.60
		0077	1050	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	76.00	0.00	76.00	LF	76.00	\$450.21	\$34,215.96
		0077	1060	7172054	OPEN CELL FOAM JOINT SEAL	76.00	0.00	76.00	LF	38.00	\$98.27	\$3,734.26
		0078	1070	7034600	CURB BLOCKOUT	287.00	0.00	287.00	LF	287.00	\$120.32	\$34,531.84
		0078	1080	7040104	HALF-SOLE REPAIR	50.00	-50.00	0.00	SQFT	0.00	\$150.41	\$0.00
		0078	1090	7049904	MISC.Reparing Concrete Wearing Surface	50.00	-50.00	0.00	SQFT	0.00	\$68.18	\$0.00
		0079	1100	7034600	CURB BLOCKOUT	309.00	0.00	309.00	LF	309.00	\$117.32	\$36,251.88
		0800	1110	7034600	CURB BLOCKOUT	255.00	0.00	255.00	LF	255.00	\$117.32	\$29,916.60
		0800	1120	7039904	MISC.Reparing Concrete Wearing Surface	100.00	-30.00	70.00	SQFT	70.00	\$58.16	\$4,071.20
		0800	1130	7040104	HALF-SOLE REPAIR	100.00	-100.00	0.00	SQFT	0.00	\$145.39	\$0.00
		0081	1140	7034600	CURB BLOCKOUT	265.00	0.00	265.00	LF	265.00	\$116.31	\$30,822.15
		0082	1150	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	136.00	-136.00	0.00	LF	0.00	\$227.61	\$0.00
		0082	1160	2169903	MISC.Remove and Replace Curb and Parapet	19.00	-19.00	0.00	LF	0.00	\$228.62	\$0.00
		0082	1170	7034214	CLASS B-2 CONCRETE	13.70	-13.70	0.00	CUYD	0.00	\$2,550.88	\$0.00
		0082	1180	7034600	CURB BLOCKOUT	797.00	-797.00	0.00	LF	0.00	\$71.19	\$0.00
		0082	1190	7040104	HALF-SOLE REPAIR	50.00	-50.00	0.00	SQFT	0.00	\$155.42	\$0.00
		0082	1200	7040113	CLEANING AND EPOXY COATING	853.00	-853.00	0.00	SQFT	0.00	\$11.03	\$0.00
		0082	1210	7049904	MISC.Reparing Concrete Wearing Surface	50.00	-50.00	0.00	SQFT	0.00	\$68.18	\$0.00
		0082	1220	7101000	REINFORCING STEEL (EPOXY COATED)	960.00	-960.00	0.00	LB	0.00	\$1.82	\$0.00
		0082	1230	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	136.00	-136.00	0.00	LF	0.00	\$407.10	\$0.00
		0083	1240	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	76.00	0.00	76.00	LF	0.00	\$235.64	\$0.00
		0083	1250	2169903	MISC.Remove and Replace Curb and Parapet	12.00	0.00	12.00	LF	0.00	\$362.98	\$0.00
		0083	1260	7034214	CLASS B-2 CONCRETE	8.10	0.00	8.10	CUYD	0.00	\$3,238.74	\$0.00
		0083	1270	7034600	CURB BLOCKOUT	535.00	0.00	535.00	LF	0.00	\$75.20	\$0.00
		0083	1280	7040113	CLEANING AND EPOXY COATING	1,692.00	0.00	1,692.00	SQFT	0.00	\$8.22	\$0.00
		0083	1290	7101000	REINFORCING STEEL (EPOXY COATED)	1,330.00	0.00	1,330.00	LB	0.00	\$1.82	\$0.00
		0083	1300	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	76.00	0.00	76.00	LF	0.00	\$450.21	\$0.00
		0084	1310	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	76.00	0.00	76.00	LF	0.00	\$271.73	\$0.00
		0084	1320	2169903	MISC.Remove and Replace Curb and Parapet	12.00	0.00	12.00	LF	0.00	\$362.98	\$0.00
		0084	1330	7034214	CLASS B-2 CONCRETE	8.10	0.00	8.10	CUYD	0.00	\$3,238.74	\$0.00

Page 9 of 29 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H02	J9I3310	0084	1340	7034600	CURB BLOCKOUT	535.00	0.00	535.00	LF	0.00	\$75.20	\$0.00
		0084	1350	7040113	CLEANING AND EPOXY COATING	1,692.00	0.00	1,692.00	SQFT	0.00	\$8.22	\$0.00
		0084	1360	7101000	REINFORCING STEEL (EPOXY COATED)	1,330.00	0.00	1,330.00	LB	0.00	\$1.82	\$0.00
		0084	1370	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	76.00	0.00	76.00	LF	0.00	\$450.21	\$0.00
		0085	1380	7034600	CURB BLOCKOUT	539.00	0.00	539.00	LF	539.00	\$83.22	\$44,855.58
		0085	1390	7040104	HALF-SOLE REPAIR	150.00	-150.00	0.00	SQFT	0.00	\$102.28	\$0.00
		0085	1400	7040113	CLEANING AND EPOXY COATING	535.00	0.00	535.00	SQFT	535.00	\$12.03	\$6,436.05
		0085	1410	7049904	MISC.Repairing Concrete Wearing Surface	50.00	-7.00	43.00	SQFT	43.00	\$68.18	\$2,931.74
		0085	1420	7172054	OPEN CELL FOAM JOINT SEAL	56.00	0.00	56.00	LF	56.00	\$74.20	\$4,155.20
		0085	1430	7173002	SILICONE EXPANSION JOINT SEALANT	56.00	0.00	56.00	LF	56.00	\$71.19	\$3,986.64
		0001	5001	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	0.00	250.00	250.00	LF	250.00	\$41.22	\$10,305.00
		0001	5002	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	0.00	1,250.00	1,250.00	LF	750.00	\$19.16	\$14,370.00
		0001	5003	7061070	MECHANICAL BAR SPLICE	0.00	135.00	135.00	EA	56.00	\$27.18	\$1,522.08
		0081	5004	7039904	MISC.Misc. Repairing Concrete Wearing Surface - BR A24053	0.00	142.00	142.00	SQFT	142.00	\$58.16	\$8,258.72
		0001	5005	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	0.00	6,133.00	6,133.00	SQYD	4,088.00	\$7.43	\$30,373.84
		0001	5006	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	0.00	2,787.00	2,787.00	TONS	1,759.52	\$94.76	\$166,732.12
		0001	5007	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.00	\$7,034.55	\$0.00
	Project .	J9I3310 - To	tal Value	e Posted to D	ate as of Report Generated Date							\$2,297,598.45
191213-H02 Ove	erall - Tota	I Value Pos	ted to Da	ate as of Rep	ort Generated Date							\$2,297,598.45

Revision 4/1/2020 Page 10 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J9I3310

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2159903	MISC. SHAPING SLOPES	8/10/20	8/13/20	280.00	LF	A22672 SW corner					120 feet was paid on previous estimate. total paid for location is 400 feet
				8/13/20	300.00	LF	Rte Y SB off-ramp RT					
				8/13/20	380.00	LF	A22672 NW corner					120 feet was paid on previous estimate. total paid for location is 500 feet
0480	6061060	MGS GUARDRAIL	8/10/20	8/13/20	212.50	LF	Rte Y SB off-ramp RT					
				8/13/20	325.00	LF	A22672 SW corner					
				8/13/20	387.50	LF	A22672 NW corner					
			8/15/20	8/17/20	250.00	LF	BR A22693 SBPL @ MM 157					
				8/17/20	250.00	LF	BR A22703 SBPL @ MM 156.4					
0490	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	8/15/20	8/17/20	1.00	EA	BR A22693 SBPL @ MM 157					
				8/17/20	1.00	EA	BR A22703 SBPL @ MM 156.4					
0510	6061080	MGS END ANCHOR	8/10/20	8/13/20	1.00	EA	A22672 SW corner on Rte Y SB on-ramp LT					
				8/13/20	1.00	EA	Rte Y SB off-ramp RT					
0520	6063014	TYPE A CRSHWTHY END TERMINAL (MASH)	8/10/20	8/13/20	1.00	EA	A22672 NW corner					
				8/13/20	1.00	EA	Rte Y SB off-ramp RT					
			8/15/20	8/17/20	1.00	EA	BR A22693 SBPL @ MM 157					
				8/17/20	1.00	EA	BR A22703 SBPL @ MM 156.4					
0770	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	8/14/20	8/17/20	54.00	LF	NBPL of BR A22692					
0850	2169903	MISC. REMOVALS	8/13/20	8/13/20	8.50	LF	BR A22693 MM 157.2 SBPL					
0860	7034214	CLASS B-2 CONCRETE	8/6/20	8/13/20	5.75	CUYD	MM 157 SBPL - BR A22693					
0870	7034600	CURB BLOCKOUT	8/14/20	8/17/20	301.50	LF	BR A22693 SBPL					
0890	7101000	REINFORCING STEEL (EPOXY COATED)	8/4/20	8/5/20	415.00	LB	MM 157 SBPL - BR A22693					
0900	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	8/4/20	8/5/20	68.00	LF	MM 157 SBPL - BR A22693					
0910	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	8/5/20	8/6/20	38.00	LF	MM 156.4 NBPL - BR A22702					
0980	7172054	OPEN CELL FOAM JOINT SEAL	8/14/20	8/17/20	0.00	LF	NBPL of BR A22702					Plan qty was incorrect. Total should be 38 LF.
0990	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	8/4/20	8/5/20	38.00	LF	MM 156.4 SBPL - BR A22703					
1000	2169903	MISC. REMOVALS	8/14/20	8/17/20	6.00	LF	BR A22703 @ MM 156.6 SBPL					
1010	7034214	CLASS B-2 CONCRETE	8/7/20	8/13/20	4.30	CUYD	BR A22703 SBPL					
1020	7034600	CURB BLOCKOUT	8/14/20	8/17/20	310.00	LF	BR A22703 @ MM 156.6 SBPL					
1040	7101000	REINFORCING STEEL (EPOXY COATED)	8/6/20	8/13/20	665.00	LB	MM 156.4 SBPL - BR A22703					
1050	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	8/5/20	8/6/20	38.00	LF	MM 156.4 SBPL - BR A22703					
5003	7061070	MECHANICAL BAR SPLICE	8/14/20	8/17/20	8.00	EA	A22692 NB bridge @ MM 157					4 bar splices per backwall for 8 total splices

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 11 of 29



	-		2.1					
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0110	IMPACT ATTENUATOR (RELOCATION)	Overrun	Overrun	5	Jun 2, 2020	SYSTEM	(\$2,016.00)	
				6	Jun 16, 2020	SYSTEM	\$2,016.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',672.00000 - 672.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0110 -	·Total						\$0.00	
0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Material		3	May 5, 2020	SYSTEM	(\$39,106.80)	
	REPAIR			3	May 5, 2020	SYSTEM	\$39,106.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Overrun	Overrun	3	May 5, 2020	SYSTEM	(\$8,690.40)	
	NEI 7 III			3	May 5, 2020	SYSTEM	\$5,793.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 21 on the current Payment Estimate.
				3	May 5, 2020	SYSTEM	\$2,896.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 21 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$8,690.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Jun 16, 2020	SYSTEM	\$8,690.40	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',181.05000 - 181.05000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0130 -	Total						\$0.00	
0140	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Overrun	Overrun	3	May 5, 2020	SYSTEM	(\$1,285.22)	
				6	Jun 16, 2020	SYSTEM	\$1,285.22	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',7.18000 - 7.18000, 'is applied (if non-zero).
			Overrun - T			SYSTEM	\$1,285.22 \$0.00	quantity on all previous payment estimates. Price Adjustments of
	Overrun - Total		Overrun - T			SYSTEM		quantity on all previous payment estimates. Price Adjustments of
0140 -			Overrun - T			SYSTEM	\$0.00	quantity on all previous payment estimates. Price Adjustments of
0140 - 0150		Overrun	Overrun - T	otal		SYSTEM	\$0.00 \$0.00	quantity on all previous payment estimates. Price Adjustments of
	Total TYPE 1 OR 5 AGGREGATE FOR BASE (4	Overrun	Overrun	3	2020 May 5,		\$0.00 \$0.00 \$0.00 (\$966.60)	quantity on all previous payment estimates. Price Adjustments of
	Total TYPE 1 OR 5 AGGREGATE FOR BASE (4	Overrun		3	May 5, 2020 Jun 16,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$966.60)	quantity on all previous payment estimates. Price Adjustments of ',7.18000 - 7.18000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
	Total TYPE 1 OR 5 AGGREGATE FOR BASE (4	Overrun	Overrun	3	May 5, 2020 Jun 16,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$966.60) \$966.60	quantity on all previous payment estimates. Price Adjustments of ',7.18000 - 7.18000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
	Total TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) Overrun - Total	Overrun	Overrun	3	May 5, 2020 Jun 16,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$966.60) \$966.60	quantity on all previous payment estimates. Price Adjustments of ',7.18000 - 7.18000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
0150	Total TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) Overrun - Total Total FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL	Overrun	Overrun	3 6	May 5, 2020 Jun 16,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$966.60) \$966.60	quantity on all previous payment estimates. Price Adjustments of ',7.18000 - 7.18000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
0150	Total TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) Overrun - Total Total FULL DEPTH PAVEMENT REPAIR SAW		Overrun - T	3 6	May 5, 2020 May 5, 2020 May 5,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$966.60) \$966.60 \$0.00 \$0.00	quantity on all previous payment estimates. Price Adjustments of ',7.18000 - 7.18000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
0150	Total TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) Overrun - Total Total FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL		Overrun - T	3 6 otal	May 5, 2020 May 5, 2020 May 5, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$966.60) \$966.60 \$0.00 \$0.00 (\$1,168.20)	quantity on all previous payment estimates. Price Adjustments of ',7.18000 - 7.18000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.40000 - 5.40000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
0150	Total TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) Overrun - Total Total FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL		Overrun - T	3 6 otal	May 5, 2020 May 5, 2020 May 5, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$966.60) \$966.60 \$0.00 \$0.00 (\$1,168.20)	quantity on all previous payment estimates. Price Adjustments of ',7.18000 - 7.18000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.40000 - 5.40000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
0150	Total TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) Overrun - Total Total FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) Overrun - Total		Overrun - T	3 6 otal	May 5, 2020 May 5, 2020 May 5, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$966.60) \$966.60 \$0.00 \$0.00 (\$1,168.20) \$1,168.20	quantity on all previous payment estimates. Price Adjustments of ',7.18000 - 7.18000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.40000 - 5.40000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of quantity on all previous payment estimates.
0150 - 0150 - 0160	Total TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) Overrun - Total Total FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) Overrun - Total Total DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Overrun	Overrun - T	3 6 otal	May 5, 2020 May 5, 2020 May 5, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$966.60) \$966.60 \$0.00 \$0.00 (\$1,168.20) \$1,168.20 \$0.00	quantity on all previous payment estimates. Price Adjustments of ',7.18000 - 7.18000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.40000 - 5.40000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of quantity on all previous payment estimates.
0150 - 0150 - 0160 -	Total TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) Overrun - Total Total FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) Overrun - Total Total DOWEL BAR (DRILLING, FURNISHING	Overrun	Overrun - T	3 6 otal	May 5, 2020 May 5, 2020 May 5, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$966.60) \$966.60 \$0.00 \$0.00 (\$1,168.20) \$1,168.20 \$0.00 \$0.00	quantity on all previous payment estimates. Price Adjustments of ',7.18000 - 7.18000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.40000 - 5.40000, 'is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of

Revision 4/1/2020 Page 12 of 29



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
Lille	Description	Type	Adjustment Type		Date	By	Amount	Remarks	
0170	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		4	May 15, 2020	SYSTEM	\$586.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Overrun	Overrun	3	May 5, 2020	SYSTEM	(\$70.84)		
	PAVEMENT REPAIR			3	May 5, 2020	SYSTEM	\$70.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 25 on the current Payment Estimate.	
				4	May 15, 2020	SYSTEM	(\$70.84)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
				4	May 15, 2020	SYSTEM	\$70.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 19 on the current Payment Estimate.	
				5	Jun 2, 2020	SYSTEM	(\$70.84)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
				6	Jun 16, 2020	SYSTEM	\$70.84	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',6.44000 - 6.44000, 'is applied (if non-zero).	
			Overrun - T	otal			\$0.00		
	Overrun - Total						\$0.00		
0170 -	Total						\$0.00		
0180	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR	Material		3	May 5, 2020	SYSTEM	(\$297.72)		
	FULL DEPTH PAVEMENT REPAIR			3	May 5, 2020	SYSTEM	\$297.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
				4	May 15, 2020	SYSTEM	(\$297.72)		
				4	May 15, 2020	SYSTEM	\$297.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0180 -	Total						\$0.00		
0190	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		3	May 5, 2020	SYSTEM	(\$72.09)		
	FAVENENT REPAIR (TIPE ESSINTS)			3	May 5, 2020	SYSTEM	\$72.09	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
				4	May 15, 2020	SYSTEM	(\$72.09)		
				4	May 15, 2020	SYSTEM	\$72.09	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Overrun	Overrun	3	May 5, 2020	SYSTEM	(\$29.37)		
	PAVEMENT REPAIR (TYPE L JOINTS)			3	May 5, 2020	SYSTEM	\$29.37	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 26 on the current Payment Estimate.	
				4	May 15, 2020	SYSTEM	(\$29.37)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
					4	May 15, 2020	SYSTEM	\$29.37	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 20 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$29.37)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
				6	Jun 16,	SYSTEM	\$29.37	Unit price based on averaged overrun adjustments for installed	

Revision 4/1/2020 Page 13 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0190	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Overrun	Overrun		2020			quantity on all previous payment estimates. Price Adjustments of ',2.67000 - 2.67000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0190 -	Total						\$0.00	
0210	ADVANCED WARNING RAIL SYSTEM	Overrun	Overrun	1	Apr 3, 2020	SYSTEM	(\$270.00)	
				6	Jun 16, 2020	SYSTEM	\$270.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',45.00000 - 45.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0210 -	Total						\$0.00	
0220	FLAG ASSEMBLY	Overrun	Overrun	3	May 5, 2020	SYSTEM	(\$40.00)	
				6	Jun 16, 2020	SYSTEM	\$40.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',20.00000 - 20.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0220 -	Total						\$0.00	
0270	SEQUENTIAL FLASHING WARNING LIGHT	Overrun	Overrun		Apr 3, 2020	SYSTEM	(\$100.00)	
				6	Jun 16, 2020	SYSTEM	\$100.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',50.00000 - 50.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0270 -				-			\$0.00	
0280	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED,	Overrun	Overrun		Jul 15, 2020	SYSTEM	(\$4,000.00)	
	CONTRACTOR RETAINED			9	Aug 3, 2020	SYSTEM	\$4,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2000.00000 - 2000.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0280 -	Total						\$0.00	
0300	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		1	Apr 3, 2020	SYSTEM	(\$33,561.00)	
				1	Apr 3, 2020	SYSTEM	\$33,561.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0300 -							\$0.00	
0330	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		1	Apr 3, 2020	SYSTEM	(\$9,496.00)	
				1	Apr 3, 2020	SYSTEM	\$9,496.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Overrun	Overrun	8	Jul 15, 2020	SYSTEM	(\$2,549.00)	
				9	Aug 3, 2020	SYSTEM	(\$4,657.00)	
				9	Aug 3, 2020	SYSTEM	\$4,657.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user pinkle1 overridding Payment Estimate Exception 24 on the current Payment Estimate.

Revision 4/1/2020 Page 14 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0330	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Overrun	Overrun	10	Aug 17, 2020	SYSTEM	(\$4,657.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Aug 17, 2020	SYSTEM	\$4,657.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user pinkle1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			Overrun - T	otal			(\$2,549.00)	
	Overrun - Total						(\$2,549.00)	
0330 -	- Total						(\$2,549.00)	
0340	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		1	Apr 3, 2020	SYSTEM	(\$2,374.00)	
				1	Apr 3, 2020	SYSTEM	\$2,374.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Overrun	Overrun	9	Aug 3, 2020	SYSTEM	(\$516.00)	
				9	Aug 3, 2020	SYSTEM	\$516.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user pinkle1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$516.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Aug 17, 2020	SYSTEM	\$516.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0340 -	- Total						\$0.00	
0480	MGS GUARDRAIL	Construction Stockpile		3	May 5, 2020	SYSTEM	\$112,353.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	May 15, 2020	SYSTEM	(\$11,789.17)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jun 30, 2020	SYSTEM	(\$6,305.83)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Jul 15, 2020	SYSTEM	(\$6,305.83)	Payment Estimate Item Adjustment generated Stockpile Transaction
				9	Aug 3, 2020	SYSTEM	\$2,467.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Aug 17, 2020	SYSTEM	(\$15,627.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$74,792.67	
	Construction Stockpile - Total						\$74,792.67	
	MGS GUARDRAIL	Material		1	Apr 3, 2020	SYSTEM	(\$18,500.00)	
				1	Apr 3, 2020	SYSTEM	\$18,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total		- Total				\$0.00 \$0.00	
0480 -	Material - Total - Total		- Total					
0480 -		Construction Stockpile	- Total	3	May 5, 2020	SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	Total MGS BRIDGE APPROACH TRANSITION		- Total	3		SYSTEM SYSTEM	\$0.00 \$74,792.67	
	Total MGS BRIDGE APPROACH TRANSITION		- Total		2020 May 15,		\$0.00 \$74,792.67 \$54,513.33	Transaction Payment Estimate Item Adjustment generated Stockpile
	Total MGS BRIDGE APPROACH TRANSITION		- Total	4	2020 May 15, 2020 Jun 30,	SYSTEM	\$0.00 \$74,792.67 \$54,513.33 (\$3,206.66)	Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile

Revision 4/1/2020 Page 15 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0490	MGS BRIDGE APPROACH TRANSITION	Construction			2020			Transaction
	SECTION (REGULAR/NO CURB)	Stockpile		10	Aug 17, 2020	SYSTEM	(\$3,206.67)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$35,273.33	
	Construction Stockpile - Total						\$35,273.33	
	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Material		1	Apr 3, 2020	SYSTEM	(\$11,200.00)	
				1	Apr 3, 2020	SYSTEM	\$11,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0490	- Total						\$35,273.33	
0500	MGS VERTICAL CONCRETE BARRIER TRANSITION	Construction Stockpile		3	May 5, 2020	SYSTEM	\$2,510.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$2,510.00	
	Construction Stockpile - Total						\$2,510.00	
0500	- Total						\$2,510.00	
0510	MGS END ANCHOR	Construction Stockpile		3	May 5, 2020	SYSTEM	\$5,801.78	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	May 15, 2020	SYSTEM	(\$1,084.45)	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Jun 2, 2020	SYSTEM	\$542.23	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Aug 17, 2020	SYSTEM	(\$1,084.45)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$4,175.11	
	Construction Stockpile - Total						\$4,175.11	
0510	- Total						\$4,175.11	
0520	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		3	May 5, 2020	SYSTEM	\$65,657.78	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	May 15, 2020	SYSTEM	(\$6,648.89)	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Jun 2, 2020	SYSTEM	(\$1,662.22)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jun 30, 2020	SYSTEM	(\$3,324.45)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Jul 15, 2020	SYSTEM	(\$3,324.44)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Aug 17, 2020	SYSTEM	(\$6,648.89)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$44,048.89	
	Construction Stockpile - Total						044000	
							\$44,048.89	
	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		1	Apr 3, 2020	SYSTEM	(\$10,800.00)	
		Material		1		SYSTEM SYSTEM	(\$10,800.00) \$10,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	(MASH)	Material	- Total		2020 Apr 3,		(\$10,800.00)	Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 3 on the current
		Material	- Total		2020 Apr 3,		(\$10,800.00) \$10,800.00	Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 3 on the current
0520	(MASH)	Material	- Total		2020 Apr 3,		(\$10,800.00) \$10,800.00 \$0.00	Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 3 on the current
0520 0530	(MASH) Material - Total	Material Material	- Total		2020 Apr 3,		(\$10,800.00) \$10,800.00 \$0.00	Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 3 on the current
	(MASH) Material - Total - Total		- Total	1	2020 Apr 3, 2020 Apr 3,	SYSTEM	(\$10,800.00) \$10,800.00 \$0.00 \$44,048.89	Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 3 on the current
	(MASH) Material - Total - Total		- Total	1	Apr 3, 2020 Apr 3, 2020 Apr 3, 2020	SYSTEM	\$10,800.00) \$10,800.00 \$0.00 \$0.00 \$44,048.89 (\$18,630.00)	Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user pinkle1 overridding Payment Estimate Exception 19 on the current

Revision 4/1/2020 Page 16 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0530	CURB BLOCKOUT	Material	,,		2020			Payment Estimate Item Adjustment (0001) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				3	May 5, 2020	SYSTEM	(\$37,260.00)	
				3	May 5, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$37,260.00)	
				4	May 15, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$37,260.00)	
				5	Jun 2, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$37,260.00)	
				6	Jun 16, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$37,260.00)	
				7	Jul 1, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$37,260.00)	
				8	Jul 16, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user lashIh1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$37,260.00)	
				9	Aug 3, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$37,260.00)	
				10	Aug 17, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
0500	Material - Total						\$0.00	
0530 - 0540	CLEANING AND EPOXY COATING	Material		1	Apr 3,	SYSTEM	\$0.00 (\$1,422.06)	
				1	2020 Apr 3,	SYSTEM	\$1,422.06	This adjustment offsets the original system-generated Overrun
					2020			Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0540 -	Total						\$0.00	
0550	CURB BLOCKOUT	Material		1	Apr 3, 2020	SYSTEM	(\$17,545.68)	
				1	Apr 3, 2020	SYSTEM	\$17,545.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user pinkle1 overridding Payment Estimate Exception 25 on the current Payment Estimate.

Revision 4/1/2020 Page 17 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0550	CURB BLOCKOUT	Material		2	Apr 16, 2020	SYSTEM	(\$35,091.36)	
				2	Apr 16, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	May 5, 2020	SYSTEM	(\$35,091.36)	
				3	May 5, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$35,091.36)	
				4	May 15, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$35,091.36)	
				5	Jun 2, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$35,091.36)	
				6	Jun 16, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$35,091.36)	
				7	Jul 1, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$35,091.36)	
				8	Jul 16, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user lashlh1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$35,091.36)	
				9	Aug 3, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$35,091.36)	
				10	Aug 17, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
0550	Material - Total						\$0.00	
0560	- Total CLEANING AND EPOXY COATING	Material		1	Apr 3,	SYSTEM	\$0.00 (\$1,422.06)	
5500	SEL WING AND EFOXT COATING	Matorial			2020			
				1	Apr 3, 2020	SYSTEM	\$1,422.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0560 - 0690	- Total CLASS B-2 CONCRETE	Material		9	Aug 3,	SYSTEM	\$0.00 (\$22,237.81)	
					2020			
				9	Aug 3,	SYSTEM	\$22,237.81	This adjustment offsets the original system-generated Overrun

Revision 4/1/2020 Page 18 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0690	CLASS B-2 CONCRETE	Material			2020			Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0690 -	Total						\$0.00	
0700	CURB BLOCKOUT	Material		9	Aug 3, 2020	SYSTEM	(\$45,270.75)	
				9	Aug 3, 2020	SYSTEM	\$45,270.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$45,270.75)	
				10	Aug 17, 2020	SYSTEM	\$45,270.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0700 -	Total						\$0.00	
0710	HALF-SOLE REPAIR	Material		9	Aug 3, 2020	SYSTEM	(\$10,501.70)	
				9	Aug 3, 2020	SYSTEM	\$10,501.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0710 -	· Total						\$0.00	
0730	MISC. Repairing Concrete Wearing Surface	Material		9	Aug 3, 2020	SYSTEM	(\$22,369.86)	
				9	Aug 3, 2020	SYSTEM	\$22,369.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$22,369.86)	
				10	Aug 17, 2020	SYSTEM	\$22,369.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user pinkle1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	MISC. Repairing Concrete Wearing Surface	Overrun	Overrun	9	Aug 3, 2020	SYSTEM	(\$18,960.86)	
				9	Aug 3, 2020	SYSTEM	\$18,960.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) overridding Payment Estimate Exception 26 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$18,960.86)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Aug 17, 2020	SYSTEM	\$18,960.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 21 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0730 -	Total						\$0.00	
0790	CLASS B-2 CONCRETE	Material		8	Jul 15, 2020	SYSTEM	(\$15,347.90)	
				8	Jul 16, 2020	SYSTEM	\$15,347.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user lashlh1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	

Revision 4/1/2020 Page 19 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0790 -	Total						\$0.00	
0800	CURB BLOCKOUT	Material		8	Jul 15, 2020	SYSTEM	(\$23,580.32)	
				8	Jul 16, 2020	SYSTEM	\$23,580.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user lashlh1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$23,580.32)	
				9	Aug 3, 2020	SYSTEM	\$23,580.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$23,580.32)	
				10	Aug 17, 2020	SYSTEM	\$23,580.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0800 -	Total						\$0.00	
0820	REINFORCING STEEL (EPOXY COATED)	Material		7	Jun 30, 2020	SYSTEM	(\$755.30)	
				7	Jul 1, 2020	SYSTEM	\$755.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0820 -	Total						\$0.00	
0830	STRIP SEAL EXPANSION JOINT SYSTEM	Material		7	Jun 30, 2020	SYSTEM	(\$22,579.02)	
				7	Jul 1, 2020	SYSTEM	\$22,579.02	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$22,579.02)	
				8	Jul 16, 2020	SYSTEM	\$22,579.02	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user lashlh1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0830 -	Total						\$0.00	
0850	MISC. Remove and Replace Curb and Parapet	Other Item Adjustment	MDPA	7	Jul 1, 2020	pinkle1	(\$2,173.37)	The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.
				8	Jul 15, 2020	SYSTEM	\$2,173.37	The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.
				8	Jul 16, 2020	lashlh1	(\$2,173.37)	The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when sufficient strength is met.
				9	Aug 3, 2020	pinkle1	\$2,173.37	The deficient concrete has been removed and repaired to the satisfaction of the engineer, therefore payment is being made.
			MDPA - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0850 -	Total						\$0.00	
0860	CLASS B-2 CONCRETE	Material		6	Jun 16, 2020	SYSTEM	(\$15,347.90)	
				6	Jun 16, 2020	SYSTEM	\$15,347.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.

Revision 4/1/2020 Page 20 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0860	CLASS B-2 CONCRETE	Material		7	Jun 30, 2020	SYSTEM	(\$15,347.90)	
				7	Jul 1, 2020	SYSTEM	\$15,347.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$15,347.90)	
				8	Jul 16, 2020	SYSTEM	\$15,347.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user lashIh1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0860 -							\$0.00	
0870	CURB BLOCKOUT	Material		7	Jun 30, 2020	SYSTEM	(\$23,580.32)	
				7	Jul 1, 2020	SYSTEM	\$23,580.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$23,580.32)	
				8	Jul 16, 2020	SYSTEM	\$23,580.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user lashlh1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$23,580.32)	
				9	Aug 3, 2020	SYSTEM	\$23,580.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$47,160.63)	
				10	Aug 17, 2020	SYSTEM	\$47,160.63	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0870 - 0890	Total REINFORCING STEEL (EPOXY COATED)	Material		6	Jun 16,	SYSTEM	\$0.00 (\$755.30)	
					2020		(*******)	
				6	Jun 16, 2020	SYSTEM	\$755.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$755.30)	
				7	Jul 1, 2020	SYSTEM	\$755.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0890 -						2)12==	\$0.00	
0900	STRIP SEAL EXPANSION JOINT SYSTEM	Material		6	Jun 16, 2020	SYSTEM	(\$16,725.20)	
				6	Jun 16, 2020	SYSTEM	\$16,725.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$16,725.20)	
				7	Jul 1, 2020	SYSTEM	\$16,725.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user pinkle1 overridding Payment Estimate Exception 33 on the current

Revision 4/1/2020 Page 21 of 29



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0900	STRIP SEAL EXPANSION JOINT SYSTEM	Material						Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$16,725.20)	
				8	Jul 16, 2020	SYSTEM	\$16,725.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user lashlh1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0900 -	Total						\$0.00	
0930	CLASS B-2 CONCRETE	Material		7	Jun 30, 2020	SYSTEM	(\$11,218.87)	
				7	Jul 1, 2020	SYSTEM	\$11,218.87	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$11,218.87)	
				8	Jul 16, 2020	SYSTEM	\$11,218.87	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user lashlh1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0930 -	Total						\$0.00	
0940	CURB BLOCKOUT	Material		8	Jul 15, 2020	SYSTEM	(\$24,868.20)	
				8	Jul 16, 2020	SYSTEM	\$24,868.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user lashIh1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$24,868.20)	
				9	Aug 3, 2020	SYSTEM	\$24,868.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$24,868.20)	
				10	Aug 17, 2020	SYSTEM	\$24,868.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0940 -	Total						\$0.00	
0960	REINFORCING STEEL (EPOXY COATED)	Material		7	Jun 30, 2020	SYSTEM	(\$1,210.30)	
				7	Jul 1, 2020	SYSTEM	\$1,210.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0960 -	Total						\$0.00	
0970	STRIP SEAL EXPANSION JOINT SYSTEM	Material		7	Jun 30, 2020	SYSTEM	(\$17,107.98)	
				7	Jul 1, 2020	SYSTEM	\$17,107.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$17,107.98)	
				8	Jul 16, 2020	SYSTEM	\$17,107.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user lashlh1 overridding Payment Estimate Exception 21 on the current

Revision 4/1/2020 Page 22 of 29



Total	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Misc. Review and Registers Curb and Other Interest			Туре	Adjustment Type	Number	Date	Ву		
MISC. Review and Replace Curb and Other Beam Planged Adjustment Plan	0970	STRIP SEAL EXPANSION JOINT SYSTEM	Material						Payment Estimate.
MISC. Remove and Replace Cuth and Offen flow Adjustment Offen flow Offen				- Total					
MISC, Renove and Regissor Curb and Other Items March Facing Adjustment March March Adjustment March Adjustment March									
Persignet Adjustment	0970 -	Total						\$0.00	
2000	1000			MDPA	7		pinkle1	(\$2,177.88)	The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.
					8		SYSTEM	\$2,177.88	The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.
MDPA - Total					8		lashlh1	(\$2,177.88)	deficient and had to be removed. Payment will be made when
Total CLASS B-2 CONCRETE Material					9		pinkle1	\$2,177.88	The deficient concrete has been removed and repaired to the satisfaction of the engineer, therefore payment is being made.
1010 Total				MDPA - Tot	al			\$0.00	
CLASS B-2 CONCRETE		Other Item Adjustment - Total						\$0.00	
Page	1000 -	Total						\$0.00	
2020 Payment Estimate hem Adjustment (0021) due to user private overriding Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 6 on	1010	CLASS B-2 CONCRETE	Material		7		SYSTEM	(\$11,218.87)	
2020 SYSTEM S11,218.87 This adjustment offsets the original system-generated Overn Payment Estimate Item Adjustment (0025) due to user lashing overdiding Payment Estimate Estimate Estimate Exception 3 on the current Payment Estimate Estimate Estimate Exception 3 on the current Payment Estimate Estimate Exception 3 on the current Payment Estimate Estimate Exception 3 on the current Payment Estimate Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 5 on the current Payment Estimate					7		SYSTEM	\$11,218.87	
2020 Payment Estimate Item Adjustment (0226) due to user lashift coverriding Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0220) due to user pinkle overridding Payment Estimate Item Adjustment (0220) due to user pinkle overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 5 on the current Payment Estimate Estimate Exception 5 on the current Payment Estimate Item Adjustment (0007) due to user pinkle overridding Payment Estimate Exception 5 on the current Payment Estimate Item Adjustment (0113) due to user pinkle overridding Payment Estimate Item Adjustment (0101) due to user pinkle overridding Payment Estimate Item Adjustment (0101) due to user pinkle overridding Payment Estimate Item Adjustment (0116) due to user pinkle overridding Payment Estimate Item Adjustment (0116) due to user pinkle overridding Payment Estimate Item Adjustment (0116) due to user pinkle overridding Payment Estimate Item Adjustment (0116) due to user pinkle overridding Payment Estimate Item Adjustment (0116) due to user pinkle overridding Payment Estimate Item Adjustment (0116) due to user pinkle overridding Payment Estimate Item Adjustment (0116) due to user pinkle overridding Payment Estimate Item					8		SYSTEM	(\$11,218.87)	
2020 9 Aug 3, 2020 9 Aug 17, 2020 9 Aug 17, 2020 9 Aug 17, 2020 10 Aug 17, 2020 Aug 3, 2020					8		SYSTEM	\$11,218.87	
2020 Payment Estimate Item Adjustment (0020) due to user pinkle overridding Payment Estimate Exception 1 on the current Payment Estimate. So.00					9		SYSTEM	(\$11,218.87)	
Naterial - Total S0.00					9		SYSTEM	\$11,218.87	
1010 Total				- Total				\$0.00	
1020 CURB BLOCKOUT Material		Material - Total						\$0.00	
2020	1010 -	Total						\$0.00	
Payment Estimate Item Adjustment (0007) due to user pinkle overridding Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Item Adjustment (0013) due to user lashlin overridding Payment Estimate Item Adjustment (0013) due to user lashlin overridding Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Item Adjustment (0010) due to user lashlin overridding Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0010) due to user pinkle overridding Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0010) due to user pinkle overridding Payment Estimate Item Adjustment (0010) due to user pinkle overridding Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Item Adjustment (0018) due to user pinkle ov	1020	CURB BLOCKOUT	Material		7		SYSTEM	(\$24,868.20)	
2020 8 Jul 16, 2020 8 Jul 16, 2020 9 Aug 3, 2020 9 Aug 3, 2020 9 Aug 3, 2020 9 Aug 3, 2020 10 Aug 17, 2020 10 SYSTEM \$49,736.40 10 Aug 17, 2020 10 Aug 17, 2020 10 SYSTEM \$49,736.40 10 Aug 17, 2020 10 SYSTEM \$49,736.40 10 Aug 17, 2020 10 Aug 17, 2020 10 SYSTEM \$49,736.40 10 Aug 17, 2020 10 Aug 17, 2020 10 SYSTEM \$49,736.40 10 Aug 17, 2020 10 SYSTEM \$49,736.40 10 Aug 17, 2020 10 Aug 17, 2020 10 Aug 17, 2020 10 SYSTEM \$49,736.40 10 Aug 17, 2020 10 Aug 17, 2020 10 Aug 17, 2020 10 SYSTEM \$49,736.40 10 Aug 17, 2020 10 Aug 17, 2020 10 Aug 17, 2020 10 SYSTEM \$49,736.40 10 Aug 17, 2020 10 Aug 17, 2020					7		SYSTEM	\$24,868.20	
Payment Estimate Item Adjustment (0013) due to user lashly overridding Payment Estimate Exception 5 on the current Payment Estimate. 9 Aug 3, 2020 9 Aug 3, 2020 10 Aug 17, 2					8		SYSTEM	(\$24,868.20)	
9 Aug 3, 2020 SYSTEM \$24,868.20 This adjustment offsets the original system-generated Overrupayment Estimate Item Adjustment (0010) due to user pinkle overridding Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate. 10 Aug 17, 2020 SYSTEM \$49,736.40 This adjustment offsets the original system-generated Overrupayment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Exception 1 on the current Payment Estimate. - Total \$0.00 Material - Total					8		SYSTEM	\$24,868.20	
Payment Estimate Item Adjustment (0010) due to user pinkle overridding Payment Estimate Exception 3 on the current Payment Estimate. 10 Aug 17, 2020 10 Aug 17, 2020 10 Aug 17, 2020 10 Aug 17, 2020 10 SYSTEM \$49,736.40 10 This adjustment offsets the original system-generated Overrup Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Exception 1 on the current Payment Estimate. - Total \$0.00 Material - Total					9		SYSTEM	(\$24,868.20)	
2020 10 Aug 17, 2020 10 Aug 17, 2020 10 SYSTEM \$49,736.40 This adjustment offsets the original system-generated Overrup ayment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Exception 1 on the current payment Estimate. - Total \$0.00 Material - Total					9		SYSTEM	\$24,868.20	
Payment Estimate Item Adjustment (0018) due to user pinkle overridding Payment Estimate Exception 1 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00					10		SYSTEM	(\$49,736.40)	
Material - Total \$0.00					10		SYSTEM	\$49,736.40	
				- Total				\$0.00	
1020 - Total \$0.00		Material - Total						\$0.00	
	1020 -	Total						\$0.00	

Revision 4/1/2020 Page 23 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1040	REINFORCING STEEL (EPOXY COATED)	Material		7	Jun 30, 2020	SYSTEM	(\$1,210.30)		
				7	Jul 1, 2020	SYSTEM	\$1,210.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user pinkle1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
	·Total						\$0.00		
1050	STRIP SEAL EXPANSION JOINT SYSTEM	Material		7	Jun 30, 2020	SYSTEM	(\$17,107.98)		
				7	Jul 1, 2020	SYSTEM	\$17,107.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user pinkle1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	
				8	Jul 15, 2020	SYSTEM	(\$17,107.98)		
				8	Jul 16, 2020	SYSTEM	\$17,107.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user lashih1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
1050 -	·Total						\$0.00		
1070	CURB BLOCKOUT	Material		1	Apr 3, 2020	SYSTEM	(\$17,205.76)		
					1	Apr 3, 2020	SYSTEM	\$17,205.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				2	Apr 16, 2020	SYSTEM	(\$34,531.84)		
				2	Apr 16, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
				3	May 5, 2020	SYSTEM	(\$34,531.84)		
				3	May 5, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
				4	May 15, 2020	SYSTEM	(\$34,531.84)		
				4	May 15, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
				5	Jun 2, 2020	SYSTEM	(\$34,531.84)		
				5	Jun 2, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				6	Jun 16, 2020	SYSTEM	(\$34,531.84)		
				6	Jun 16, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
				7	Jun 30, 2020	SYSTEM	(\$34,531.84)		
				7	Jul 1, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
				8	Jul 15, 2020	SYSTEM	(\$34,531.84)		
				8	Jul 16,	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun	

Revision 4/1/2020 Page 24 of 29



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks			
		Туре	Adjustment Type	Number	Date	Ву					
1070	CURB BLOCKOUT	Material			2020			Payment Estimate Item Adjustment (0014) due to user lashlh1 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
				9	Aug 3, 2020	SYSTEM	(\$34,531.84)				
				9	Aug 3, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
				10	Aug 17, 2020	SYSTEM	(\$34,531.84)				
				10	Aug 17, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 13 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
	- Total						\$0.00				
1100	CURB BLOCKOUT	Material		2	Apr 16, 2020	SYSTEM	(\$36,251.88)				
				2	Apr 16, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				3	May 5, 2020	SYSTEM	(\$36,251.88)				
				3	May 5, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user pinkle1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
				4	May 15, 2020	SYSTEM	(\$36,251.88)				
				4	May 15, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
				5	Jun 2, 2020	SYSTEM	(\$36,251.88)				
				5	Jun 2, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
				6	Jun 16, 2020	SYSTEM	(\$36,251.88)				
							6	Jun 16, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$36,251.88)				
				7	Jul 1, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
				8	Jul 15, 2020	SYSTEM	(\$36,251.88)				
				8	Jul 16, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user lashIh1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
				9	Aug 3, 2020	SYSTEM	(\$36,251.88)				
				9	Aug 3, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
				10	Aug 17, 2020	SYSTEM	(\$36,251.88)				
				10	Aug 17, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user pinkle1			

Revision 4/1/2020 Page 25 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
1100	CURB BLOCKOUT	Material						overridding Payment Estimate Exception 3 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
1100 -	- Total						\$0.00				
1110	CURB BLOCKOUT	Material		1	Apr 3, 2020	SYSTEM	(\$18,067.28)				
				1	Apr 3, 2020	SYSTEM	\$18,067.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 13 on the current Payment Estimate.			
				2	Apr 16, 2020	SYSTEM	(\$14,899.64)				
				2	Apr 16, 2020	SYSTEM	\$14,899.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
				3	May 5, 2020	SYSTEM	(\$29,916.60)				
				3	May 5, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
				4	May 15, 2020	SYSTEM	(\$29,916.60)				
				4	May 15, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
				5	Jun 2, 2020	SYSTEM	(\$29,916.60)				
				5	Jun 2, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
							6	Jun 16, 2020	SYSTEM	(\$29,916.60)	
				6	Jun 16, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
				7	Jun 30, 2020	SYSTEM	(\$29,916.60)				
				7	Jul 1, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
				8	Jul 15, 2020	SYSTEM	(\$29,916.60)				
						8	Jul 16, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user lashlh1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
				9	Aug 3, 2020	SYSTEM	(\$29,916.60)				
				9	Aug 3, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
				10	Aug 17, 2020	SYSTEM	(\$29,916.60)				
				10	Aug 17, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
1110 -	- Total						\$0.00				
1140	CURB BLOCKOUT	Material		2	Apr 16,	SYSTEM	(\$15,352.92)				

Revision 4/1/2020 Page 26 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1140	CURB BLOCKOUT	Material			2020			
				2	Apr 16, 2020	SYSTEM	\$15,352.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				3	May 5, 2020	SYSTEM	(\$30,822.15)	
				3	May 5, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user pinkle1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$30,822.15)	
				4	May 15, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$30,822.15)	
				5	Jun 2, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$30,822.15)	
				6	Jun 16, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$30,822.15)	
				7	Jul 1, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$30,822.15)	
				8	Jul 16, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user lashlh1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$30,822.15)	
				9	Aug 3, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$30,822.15)	
				10	Aug 17, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
14.10	Material - Total						\$0.00	
	- Total	Material		2	Mey F	CVCTEN	\$0.00 (\$44,855.58)	
1380	CURB BLOCKOUT	iviatellal		3	May 5, 2020	SYSTEM	,	This adjustment offs to the spirits of the second of the s
				3	May 5, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user pinkle1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$44,855.58)	
				4	May 15, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$44,855.58)	

Revision 4/1/2020 Page 27 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1380	CURB BLOCKOUT	Material	J1	5	Jun 2, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$44,855.58)	
				6	Jun 16, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$44,855.58)	
				7	Jul 1, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$44,855.58)	
				8	Jul 16, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user lashlh1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$44,855.58)	
				9	Aug 3, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$44,855.58)	
				10	Aug 17, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
			rotui					
	Material - Total		Total				\$0.00	
1380 -	Material - Total Total OPEN CELL FOAM JOINT SEAL	Material	Total	3	May 5,	SYSTEM		
	- Total	Material	1 3 1 1	3	May 5, 2020 May 5, 2020	SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
	- Total	Material	10141		2020 May 5,		\$0.00 \$0.00 (\$4,155.20)	Payment Estimate Item Adjustment (0029) due to user pinkle1
	- Total	Material		3	2020 May 5, 2020 May 15,	SYSTEM	\$0.00 \$0.00 (\$4,155.20) \$4,155.20	Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 18 on the current
	- Total	Material		3	2020 May 5, 2020 May 15, 2020 May 15,	SYSTEM	\$0.00 \$0.00 (\$4,155.20) \$4,155.20	Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 12 on the current
	- Total	Material		4	2020 May 5, 2020 May 15, 2020 May 15, 2020	SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,155.20) \$4,155.20 (\$4,155.20)	Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 12 on the current
	OPEN CELL FOAM JOINT SEAL	Material	- Total	4 4 5	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,155.20) \$4,155.20 (\$4,155.20) \$4,155.20 (\$4,155.20) \$4,155.20	Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 8 on the current
1420	OPEN CELL FOAM JOINT SEAL	Material		4 4 5	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,155.20) \$4,155.20 (\$4,155.20) \$4,155.20 (\$4,155.20) \$4,155.20	Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 8 on the current
1420	OPEN CELL FOAM JOINT SEAL	Material		4 4 5	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,155.20) \$4,155.20 (\$4,155.20) \$4,155.20 (\$4,155.20) \$4,155.20	Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 8 on the current
1420	OPEN CELL FOAM JOINT SEAL OPEN CELL FOAM JOINT SEAL Material - Total Total			3 4 4 5 5	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,155.20) \$4,155.20 (\$4,155.20) \$4,155.20 (\$4,155.20) \$4,155.20 \$0.00 \$0.00	Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 8 on the current
1420	OPEN CELL FOAM JOINT SEAL OPEN CELL FOAM JOINT SEAL Material - Total Total			3 4 4 5 5	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2, 2020 Jun 2, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$4,155.20) \$4,155.20 (\$4,155.20) \$4,155.20 (\$4,155.20) \$4,155.20 \$0.00 \$0.00 (\$3,986.64)	Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate.

Revision 4/1/2020 Page 28 of 29



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
1430	SILICONE EXPANSION JOINT SEALANT	Material						Payment Estimate.			
				5	Jun 2, 2020	SYSTEM	(\$3,986.64)				
				5	Jun 2, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
				6	Jun 16, 2020	SYSTEM	(\$3,986.64)				
				6	Jun 16, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user pinkle1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
				7	Jun 30, 2020	SYSTEM	(\$3,986.64)				
				7	Jul 1, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user pinkle1 overridding Payment Estimate Exception 35 on the current Payment Estimate.			
						8	Jul 15, 2020	SYSTEM	(\$3,986.64)		
				8	Jul 16, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user lashlh1 overridding Payment Estimate Exception 22 on the current Payment Estimate.			
				9	Aug 3, 2020	SYSTEM	(\$3,986.64)				
				9	Aug 3, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user pinkle1 overridding Payment Estimate Exception 23 on the current Payment Estimate.			
							10	Aug 17, 2020	SYSTEM	(\$3,986.64)	
				10	Aug 17, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
1430 -	Total						\$0.00				
Overal	II - Total				\$158,251.00						

Revision 4/1/2020 Page 29 of 29