

Pay Estimate Created Date: September 16, 2020

Progress Estimate Number	Contract ID	191213-H02	Pay Period Start	September 2, 2020	Original Contract Amoun	<b>t</b> \$11,971,234.56
12	Prime Contractor	Capital Paving & Construction, LLC	Pay Period End	September 15, 2020	Net Change Order Amount Current Contract Amount	\$134,248.16 : \$12,105,482.72

Approval Date					By User				
September 16, 2020		Generated and	Approved (and should be considered	ed Draft) at the Project Office Level by	pinkle1				
September 16, 2020		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by dowdyd							
September 17, 2020		Reviewed and Approved at the Central Office Controllers Office Level by							
Original Completion Date		Current Completion Date	Actual Completion Date	Actual Completion Date % of Current Contract Amo					
November 1, 2021 Novemb		November 1, 2021							

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 12			
	This Estimate	Previous	To Date
191213-H02			
Total Posted Items Pay	\$1,695,470.69	\$2,554,576.71	\$4,250,047.40
Gross Item Adjustments	(\$136,587.65)	\$140,056.70	\$3,469.05
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustment	\$52,288.51	(\$117,192.81)	(\$64,904.30)
•		\$2,577,440.60	\$4,188,612.15
Contract Total Payable This Estimate:	\$1 611 171 55		

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3310	0020	2159903	MISC.Modified Shaping Slopes, Class III	LF	\$9.000	2,040.25	\$18,362.25
	0060	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	TONS	\$74.250	16,657.73	\$1,236,836.45
	0070	4071005	TACK COAT	GAL	\$1.970	16,635	\$32,770.95
	0110	6122030	IMPACT ATTENUATOR (RELOCATION)	EA	\$672.000	2	\$1,344.00
	0230	6161010	RELOCATED SIGNS	SQFT	\$7.000	128	\$896.00
	0310	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	LF	\$8.500	950	\$8,075.00
	0320	6181000	MOBILIZATION	LS	\$623,256.100	0.25	\$155,814.03
	0430	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$3.320	89	\$295.48
	0450	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$2.940	4,043	\$11,886.42
	0480	6061060	MGS GUARDRAIL	LF	\$20.000	1,700	\$34,000.00
	0490	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$2,800.000	2	\$5,600.00
	0510	6061080	MGS END ANCHOR	EA	\$1,000.000	2	\$2,000.00
	0520	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$2,700.000	6	\$16,200.00
	1250	2169903	MISC.Remove and Replace Curb and Parapet	LF	\$362.980	6	\$2,177.88
	1260	7034214	CLASS B-2 CONCRETE	CUYD	\$3,238.740	4	\$12,954.96
	1270	7034600	CURB BLOCKOUT	LF	\$75.200	267.5	\$20,116.00
	1290	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$1.820	665	\$1,210.30
	1300	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	LF	\$450.210	38	\$17,107.98
	1320	2169903	MISC.Remove and Replace Curb and Parapet	LF	\$362.980	6	\$2,177.88
	1340	7034600	CURB BLOCKOUT	LF	\$75.200	267.5	\$20,116.00
	5002	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	LF	\$19.160	250	\$4,790.00
	5003	7061070	MECHANICAL BAR SPLICE	EA	\$27.180	20	\$543.60
	5005	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	SQYD	\$7.430	2,045	\$15,194.35

Revision 4/1/2020 Page 1 of 36



Pay Estimate Created Date: September 16, 2020

Progress Estimate Number	Contract ID	191213-H02	Pay Period Start	September 2, 2020	Original Contract Amoun	t \$11,971,234.56
12	Prime Contractor	Capital Paving & Construction, LLC	Pay Period End	September 15, 2020	Net Change Order Amount Current Contract Amount	\$134,248.16 \$12,105,482.72

Project Number	Line Number	Item Code	Item Description  Unit Unit Price Current Installed Qty				
J9I3310			SURFACING (GREATER THAN 3 IN. THICK)				
	5006	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	TONS	\$94.760	717.25	\$67,966.61
	5007	6181000	MOBILIZATION	LS	\$7,034.550	1	\$7,034.55
Project J9l3310 - Total							
Overall - 1	Γotal						\$1,695,470.69

#### Contract Adjustments This Estimate

Adj Type	Entered By	Comments	Time Units	Rate	Amount
OTHROther Contract Adjustment	· ·	1.) LI 1100 - 10% of \$36251.88 due to deficient cylinder breaks (3625.18)			(\$3,625.18)
OTHROther Contract Adjustment	pinkle1	This adjustment was created to adjust the \$55913.69 withheld on EST 0011 back to the contractor. A new adjustment will be created based on current conditions.			\$55,913.69

Overall - Total

These amounts are listed in the Incentive, Disincentive, Liquidated Damages or Other Contract Adjustments

\$52,288.51

ine Item	Adjustr	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3310	0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,226	(\$2.46)	(\$3,012.04
	0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	741.89	(\$2.46)	(\$1,822.68
	0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,868.52	(\$2.46)	(\$4,590.58
	0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	2,284.18	(\$2.46)	(\$5,611.77
	0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	297.32	(\$2.46)	(\$730.46
	0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	5,807.02	(\$2.46)	(\$14,266.69
	0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	4,432.8	(\$2.46)	(\$10,890.50
	0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Material			-16,657.73	\$74.25	(\$1,236,836.45
	0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0024) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	16,657.73	\$74.25	\$1,236,836.45
	0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Other Item Adjustment	Asphalt Cement Price	See attached AC adjustment sheet "191213- H02 AC ADJ LI 0060 20200908 to 20200915 EST 0012" for details.			(\$63,507.60

Revision 4/1/2020 Page 2 of 36

Adjustment



Pay Estimate Created Date: September 16, 2020

**Progress Estimate Pay Period** Contract ID 191213-H02 September 2, 2020 Original Contract Amount \$11,971,234.56 Start Number Pay Period End September 15, 2020 Prime Capital Paving & Construction, **Net Change Order** 12 \$134,248.16 Contractor LLĊ Amount Current Contract Amount \$12,105,482.72

er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
10 0	0070	TACK COAT	Material			-16,635	\$1.97	(\$32,770.95)
C	0070	TACK COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0025) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	16,635	\$1.97	\$32,770.95
C	0200	CONSTRUCTION SIGNS	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-691	\$8.00	(\$5,528.00
C	0200	CONSTRUCTION SIGNS	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0021) due to user pinkle1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	691	\$8.00	\$5,528.00
C	0330	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-10,817	\$1.00	(\$10,817.00)
C	0330	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0022) due to user pinkle1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	10,817	\$1.00	\$10,817.00
C	0340	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-516	\$1.00	(\$516.00)
C	0340	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0023) due to user pinkle1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	516	\$1.00	\$516.00
C	0480	MGS GUARDRAIL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$18,643.34)
C	0490	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$3,206.67)
C	0510	MGS END ANCHOR	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$1,084.45
C	0520	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$9,973.33)
C	0530	CURB BLOCKOUT	Material			-432	\$86.25	(\$37,260.00
C	0530	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0026) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	432	\$86.25	\$37,260.00
C	0550	CURB BLOCKOUT	Material			-432	\$81.23	(\$35,091.36
	0550	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0027) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	432	\$81.23	\$35,091.36
C	0700	CURB BLOCKOUT	Material			-525	\$86.23	(\$45,270.75)
C	0700	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0028) due to user pinkle1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	525	\$86.23	\$45,270.75

Revision 4/1/2020 Page 3 of 36



Pay Estimate Created Date: September 16, 2020

**Pay Period Progress Estimate Contract ID** 191213-H02 September 2, 2020 Original Contract Amount \$11,971,234.56 Start Number Pay Period End September 15, 2020 Capital Paving & Construction, Prime **Net Change Order** 12 \$134,248.16 Contractor LLĊ Amount Current Contract Amount \$12,105,482.72

		urrent Contr						
Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.	Project Number
\$15,551.86	\$68.18	228.1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 21 on the current Payment Estimate.		Material	MISC.	0730	J9I3310
(\$18,960.86)	\$68.18	-278.1	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		Overrun	MISC.	0730	
(\$15,551.86)	\$68.18	-228.1			Material	MISC.	0730	
\$18,960.86	\$68.18	278.1	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 26 on the current Payment Estimate.		Overrun	MISC.	0730	
(\$47,160.63)	\$78.21	-603			Material	CURB BLOCKOUT	0800	
\$47,160.63	\$78.21	603	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 20 on the current Payment Estimate.		Material	CURB BLOCKOUT	0800	
(\$47,160.63)	\$78.21	-603			Material	CURB BLOCKOUT	0870	
\$47,160.63	\$78.21	603	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0030) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		Material	CURB BLOCKOUT	0870	
(\$49,736.40)	\$80.22	-620			Material	CURB BLOCKOUT	0940	
\$49,736.40	\$80.22	620	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0031) due to user pinkle1 overridding Payment Estimate Exception 15 on the current Payment Estimate.		Material	CURB BLOCKOUT	0940	
(\$49,736.40)	\$80.22	-620			Material	CURB BLOCKOUT	1020	
\$49,736.40	\$80.22	620	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0032) due to user pinkle1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		Material	CURB BLOCKOUT	1020	
(\$34,531.84)	\$120.32	-287			Material	CURB BLOCKOUT	1070	
\$34,531.84	\$120.32	287	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0033) due to user pinkle1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		Material	CURB BLOCKOUT	1070	
(\$36,251.88)	\$117.32	-309			Material	CURB BLOCKOUT	1100	
\$36,251.88	\$117.32	309	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0034) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate.		Material	CURB BLOCKOUT	1100	
(\$29,916.60)	\$117.32	-255			Material	CURB BLOCKOUT	1110	
\$29,916.60	\$117.32	255	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0035) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		Material	CURB BLOCKOUT	1110	
(\$30,822.15)	\$116.31	-265			Material	CURB BLOCKOUT	1140	

Revision 4/1/2020 Page 4 of 36



Pay Estimate Created Date: September 16, 2020

**Pay Period Progress Estimate** Contract ID 191213-H02 September 2, 2020 Original Contract Amount \$11,971,234.56 Start Number Pay Period End September 15, 2020 Capital Paving & Construction, Prime **Net Change Order** 12 \$134,248.16 Contractor LLĊ Amount Current Contract Amount \$12,105,482.72

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9l3310	1140	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0036) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	265	\$116.31	\$30,822.15
	1260	CLASS B-2 CONCRETE	Material			-4	\$3,238.74	(\$12,954.96)
	1260	CLASS B-2 CONCRETE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0040) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	4	\$3,238.74	\$12,954.96
	1270	CURB BLOCKOUT	Material			-267.5	\$75.20	(\$20,116.00)
	1270	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0037) due to user pinkle1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	267.5	\$75.20	\$20,116.00
	1330	CLASS B-2 CONCRETE	Material			-4.05	\$3,238.74	(\$13,116.90)
	1330	CLASS B-2 CONCRETE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0041) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	4.05	\$3,238.74	\$13,116.90
	1340	CURB BLOCKOUT	Material			-267.5	\$75.20	(\$20,116.00)
	1340	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0038) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	267.5	\$75.20	\$20,116.00
	1380	CURB BLOCKOUT	Material			-539	\$83.22	(\$44,855.58)
	1380	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0039) due to user pinkle1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	539	\$83.22	\$44,855.58
	1430	SILICONE EXPANSION JOINT SEALANT	Material			-56	\$71.19	(\$3,986.64)
	1430	SILICONE EXPANSION JOINT SEALANT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0042) due to user pinkle1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	56	\$71.19	\$3,986.64
	5006	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	717.25	\$1.26	\$904.88
	5006	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment		See attached AC adjustment sheet "191213- H02 AC ADJ LI 5006 20200903 EST 0012" for details.			(\$152.42)
Total								(\$136,587.65)

Revision 4/1/2020 Page 5 of 36



	Contract Project Information								
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work				
J9I3310	I 55-2(115)	Resurface and bridge replacement	I-55	STE GENEVIEVE	from Jefferson County Line to 0.4 miles south of Rte M overpass in Ozora				

Totals by Job Numbers				
J9I3310		This Estimate	Previous	To Date
Posted Item Pay		\$1,695,470.69	\$2,554,576.71	\$4,250,047.40
Gross Item Adjust	tments	(\$136,587.65)	\$140,056.70	\$3,469.05
	Gross Item Pay	\$1,558,883.04	\$2,694,633.41	\$4,253,516.45
Incentive		\$0.00	\$0.00	\$0.00
Disincentive		\$0.00	\$0.00	\$0.00
Liquidated Damag	jes	\$0.00	\$0.00	\$0.00
Other Contract Ac	ljustments	\$52,288.51	(\$117,192.81)	(\$64,904.30)

Revision 4/1/2020 Page 6 of 36



**Exceptions (Discrepancies) This Estimate Period** 

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 4030132, Project Item Line Number 0060, Material Set 403013296, Material 0403SP125BSM - Superpave 12.5 mm, Des B SM, Acceptance Action Generic AspHigh is insufficient.	Testing in progress. CRE2O sheets not working. Tests results have been received.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 4071005, Project Item Line Number 0070, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Contractor is currently using SS-1H oil.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034214, Project Item Line Number 1260, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Testing in progress. Strength has been obtained.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034214, Project Item Line Number 1330, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Testing in progress. Strength has been obtained.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 0550, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier has been sealed. PAL ID has been submitted by contractor. Waiting on PAL to be reported to AWP by MoDOT.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 0870, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier has been sealed. PAL ID has been submitted by contractor. Waiting on PAL to be reported to AWP by MoDOT.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 1110, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier has been sealed. PAL ID has been submitted by contractor. Waiting on PAL to be reported to AWP by MoDOT.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 1140, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier has been sealed. PAL ID has been submitted by contractor. Waiting on PAL to be reported to AWP by MoDOT.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 0530, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier has been sealed. PAL ID has been submitted by contractor. Waiting on PAL to be reported to AWP by MoDOT.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 1340, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Testing in progress.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 1340, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb in progress. Not sealed yet.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 1100, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier has been sealed. PAL ID has been submitted by contractor. Waiting on PAL to be reported to AWP by MoDOT.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 0700, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier has been sealed. PAL ID has been submitted by contractor. Waiting on PAL to be reported to AWP by MoDOT.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 1020, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier has been sealed. PAL ID has been submitted by contractor. Waiting on PAL to be reported to AWP by MoDOT.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 0940, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier has been sealed. PAL ID has been submitted by contractor. Waiting on PAL to be reported to AWP by MoDOT.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 1380, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier has been sealed. PAL ID has been submitted by contractor. Waiting on PAL to be reported to AWP by MoDOT.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 1270, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Testing in progress.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913310, Item 7034600, Project Item Line Number 1270, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier curb still under construction. Not yet sealed.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 1070, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier has been sealed. PAL ID has been submitted by contractor. Waiting on PAL to be reported to AWP by MoDOT.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7034600, Project Item Line Number 0800, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Barrier has been sealed. PAL ID has been submitted by contractor. Waiting on PAL to be reported to AWP by MoDOT.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7049904, Project Item Line Number 0730, Material Set 7049904, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Concrete testing in progress.	pinkle1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3310, Item 7173002, Project Item Line Number 1430, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	Contractor has uploaded PAL ID to sharepoint, but it has not been entered into AWP.	pinkle1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-H02, Contract Project J9l3310, Project Item Line Number 0200, Contract Line Item Number 0200, Item 6161005, Minor Item.	Change order in progress.	pinkle1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-H02, Contract Project J9I3310, Project Item Line Number 0330, Contract Line Item Number 0330, Item 6205301B, Minor Item.	Change order in progress.	pinkle1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-H02, Contract Project J9I3310, Project Item Line	Change order in progress.	pinkle1	Overridden  Page 7 of 26

Revision 4/1/2020 Page 7 of 36



**Exceptions (Discrepancies) This Estimate Period** 

Exceptions / Discrepencies	Explanation	Entered By	Status
Number 0340, Contract Line Item Number 0340, Item 6205303B, Minor Item.			
Estimate Exception Type: Item Overrun: Contract 191213-H02, Contract Project J9I3310, Project Item Line Number 0730, Contract Line Item Number 0730, Item 7049904, Minor Item.	Change order in progress.	pinkle1	Overridden

Revision 4/1/2020 Page 8 of 36



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
91213-H02	J9I3310	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.69	\$80,000.00	\$55,200.00
		0001	0020	2159903	MISC.Modified Shaping Slopes, Class III	16,911.00	0.00	16,911.00	LF	12,958.75	\$9.00	\$116,628.7
		0001	0030	3049910	MISC.Permanent Aggregate Edge Treatment	6,234.20	0.00	6,234.20	TONS	0.00	\$31.53	\$0.0
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	485.00	0.00	485.00	TONS	0.00	\$27.08	\$0.0
		0001	0050	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	21,372.90	0.00	21,372.90	TONS	0.00	\$55.86	\$0.0
		0001	0060	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	85,624.80	0.00	85,624.80	TONS	16,657.73	\$74.25	\$1,236,836.4
		0001	0070	4071005	TACK COAT	84,430.00	0.00	84,430.00	GAL	16,635.00	\$1.97	\$32,770.9
		0001	0080	4134000	BITUMINOUS FOG SEAL	30,480.00	0.00	30,480.00	GAL	0.00	\$3.04	\$0.0
		0001	0090	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARRELS)	2.00	0.00	2.00	EA	2.00	\$5,750.00	\$11,500.0
		0001	0100	6122020	REPLACEMENT SAND BARREL	5.00	0.00	5.00	EA	0.00	\$300.00	\$0.0
		0001	0110	6122030	IMPACT ATTENUATOR (RELOCATION)	11.00	11.00	22.00	EA	22.00	\$672.00	\$14,784.0
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$750.00	\$1,500.0
		0001	0130	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	168.00	48.00	216.00	SQYD	216.00	\$181.05	\$39,106.8
		0001	0140	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	17.00	179.00	196.00	SQYD	196.00	\$7.18	\$1,407.2
		0001	0150	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)	17.00	179.00	196.00	SQYD	196.00	\$5.40	\$1,058.4
		0001	0160	6131014	(PAVEMENT REPAIR)  FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	516.00	132.00	648.00	LF	648.00	\$8.85	\$5,734.8
		0001	0170	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	80.00	11.00	91.00	EA	91.00	\$6.44	\$586.0
		0001	0180	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	170.00	-134.00	36.00	EA	36.00	\$8.27	\$297.7
		0001	0190	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	16.00	11.00	27.00	EA	27.00	\$2.67	\$72.0
		0001	0200	6161005	CONSTRUCTION SIGNS	3,321.00	0.00	3,321.00	SQFT	4,012.00	\$8.00	\$32,096.0
		0001	0210	6161008	ADVANCED WARNING RAIL SYSTEM	18.00	10.00	28.00	EA	28.00	\$45.00	\$1,260.0
		0001	0220	6161009	FLAG ASSEMBLY	26.00	2.00	28.00	EA	28.00	\$20.00	\$560.0
		0001	0230	6161010			0.00	2,276.00	SQFT	752.00	\$7.00	\$5,264.0
		0001	0240	6161025	CHANNELIZER (TRIM LINE)	552.00	0.00	552.00	EA	230.00	\$18.00	\$4,140.0
		0001	0250	6161033	DIRECTIONAL INDICATOR BARRICADE	72.00	0.00	72.00	EA	56.00	\$65.00	\$3,640.0
		0001	0260	6161040	FLASHING ARROW PANEL	5.00	0.00	5.00	EA	4.00	\$850.00	\$3,400.0
		0001	0270	6161055	SEQUENTIAL FLASHING WARNING LIGHT	54.00	2.00	56.00	EA	56.00	\$50.00	\$2,800.0
		0001	0280	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$2,000.00	\$8,000.0
		0001	0290	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	2.00	0.00	2.00	EA	1.00	\$16,800.00	\$16,800.0
		0001	0300	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,188.00	0.00	1,188.00	LF	1,050.00	\$28.25	\$29,662.5
		0001	0310	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	13,068.00	0.00	13,068.00	LF	11,450.00	\$8.50	\$97,325.0
		0001	0320	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$623,256.10	\$467,442.0
		0001	0330	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	25,760.00	0.00	25,760.00	LF	39,126.00	\$1.00	\$39,126.0
		0001	0340	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	31,740.00	0.00	31,740.00	LF	32,256.00	\$1.00	\$32,256.0
		0001	0350	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	224.00	0.00	224.00	LF	56.00	\$10.00	\$560.0
		0001	0360	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	309,366.00	0.00	309,366.00	LF	0.00	\$0.25	\$0.0
		0001	0370	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	250,800.00	0.00	250,800.00	LF	0.00	\$0.19	\$0.0
		0001	0380	6205906A	12 IN, WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	10,120.00	0.00	10,120.00	LF	0.00	\$1.00	\$0.0
		0001	0390	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,118.00	0.00	5,118.00	LF	0.00	\$0.30	\$0.0
		0001	0400	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,795.00	0.00	5,795.00	LF	0.00	\$0.30	\$0.0
		0001	0410	6207001	PAVEMENT MARKING REMOVAL	184,786.00	0.00	184,786.00	LF	55,142.00	\$0.25	\$13,785.5
		0001	0420	6209901	MISC.Temporary Pavement Marking Paint	1.00	0.00	1.00	LS	0.00	\$0.01	\$0.0
		0001	0430	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	9,901.00	0.00	9,901.00	SQYD	89.00	\$3.32	\$295.4

Page 9 of 36 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted a Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H02	J9I3310	0001	0440	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	966.00	0.00	966.00	SQYD	0.00	\$9.28	\$0.00
		0001	0450	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	29,408.00	0.00	29,408.00	SQYD	4,043.00	\$2.94	\$11,886.42
		0001	0460	6229905	MISC.Smoothness Correction	29,567.90	0.00	29,567.90	SQYD	0.00	\$1.76	\$0.00
		0001	0470	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	4,316.00	0.00	4,316.00	STA	0.00	\$15.68	\$0.00
		0010	0480	6061060	MGS GUARDRAIL	11,925.00	0.00	11,925.00	LF	9,212.50	\$20.00	\$184,250.00
		0010	0490	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	40.00	0.00	40.00	EA	30.00	\$2,800.00	\$84,000.00
		0010	0500	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	2.00	0.00	2.00	EA	0.00	\$2,700.00	\$0.00
		0010	0510	6061080	MGS END ANCHOR	13.00	0.00	13.00	EA	8.00	\$1,000.00	\$8,000.00
		0010	0520	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	45.00	0.00	45.00	EA	34.00	\$2,700.00	\$91,800.00
		0070	0530	7034600	CURB BLOCKOUT	432.00	0.00	432.00	LF	432.00	\$86.25	\$37,260.00
		0070	0540	7040113	CLEANING AND EPOXY COATING	346.00	0.00	346.00	SQFT	346.00	\$8.22	\$2,844.12
		0071	0550	7034600	CURB BLOCKOUT	432.00	0.00	432.00	LF	432.00	\$81.23	\$35,091.36
		0071	0560	7040113	CLEANING AND EPOXY COATING	346.00	0.00	346.00	SQFT	346.00	\$8.22	\$2,844.12
		0072	0570	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	69.00	0.00	69.00	LF	0.00	\$298.86	\$0.00
		0072	0580	2169903	MISC.Remove and Replace Curb and Parapet	12.00	0.00	12.00	LF	0.00	\$362.98	\$0.00
		0072	0590	7034214	CLASS B-2 CONCRETE	6.10	0.00	6.10	CUYD	0.00	\$3,608.74	\$0.00
		0072	0600	7034600	CURB BLOCKOUT	529.00	0.00	529.00	LF	0.00	\$79.21	\$0.00
		0072	0610	7040104	HALF-SOLE REPAIR	200.00	0.00	200.00	SQFT	0.00	\$101.27	\$0.00
		0072	0620	7040113	CLEANING AND EPOXY COATING	611.00	0.00	611.00	SQFT	611.00	\$12.03	\$7,350.33
		0072	0630	7049904	MISC.Repairing Concrete Wearing Surface	50.00	0.00	50.00	SQFT	0.00	\$68.18	\$0.00
		0072	0640	7101000	REINFORCING STEEL (EPOXY COATED)	560.00	0.00	560.00	LB	0.00	\$1.82	\$0.00
		0072	0650	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	69.00	0.00	69.00	LF	0.00	\$473.28	\$0.00
		0072	0660	7172054	OPEN CELL FOAM JOINT SEAL	69.00	0.00	69.00	LF	0.00	\$106.29	\$0.00
		0073	0670	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	68.00	0.00	68.00	LF	68.00	\$302.82	\$20,591.76
		0073	0680	2169903	MISC.Remove and Replace Curb and Parapet	12.00	0.00	12.00	LF	12.00	\$362.98	\$4,355.76
		0073	0690	7034214	CLASS B-2 CONCRETE	7.40	0.00	7.40	CUYD	7.40	\$3,005.11	\$22,237.81
		0073	0700	7034600	CURB BLOCKOUT	525.00	0.00	525.00	LF	525.00	\$86.23	\$45,270.75
		0073	0710	7040104	HALF-SOLE REPAIR	200.00	0.00	200.00	SQFT	103.70	\$101.27	\$10,501.70
		0073	0720	7040113	CLEANING AND EPOXY COATING	677.00	0.00	677.00	SQFT	677.00	\$12.03	\$8,144.31
		0073	0730	7049904	MISC.Repairing Concrete Wearing Surface	50.00	0.00	50.00	SQFT	328.10	\$68.18	\$22,369.86
		0073	0740	7101000	REINFORCING STEEL (EPOXY COATED)	1,210.00	0.00	1,210.00	LB	1,210.00	\$1.73	\$2,093.30
		0073	0750	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	68.00	0.00	68.00	LF	68.00	\$469.27	\$31,910.36
		0073	0760	7172054	OPEN CELL FOAM JOINT SEAL	68.00	0.00	68.00	LF	68.00	\$107.29	\$7,295.72
		0074	0770	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	108.00	0.00	108.00	LF	108.00	\$238.64	\$25,773.12
		0074	0780	2169903	MISC.Remove and Replace Curb and Parapet	17.00	0.00	17.00	LF	17.00	\$255.69	\$4,346.73
		0074	0790	7034214	CLASS B-2 CONCRETE	11.50	0.00	11.50	CUYD	11.50	\$2,669.20	\$30,695.80
		0074	0800	7034600	CURB BLOCKOUT	603.00	0.00	603.00	LF	603.00	\$78.21	\$47,160.63
		0074	0810	7040113	CLEANING AND EPOXY COATING	2,214.00	0.00	2,214.00	SQFT	2,214.00	\$8.22	\$18,199.08
		0074	0820	7101000	REINFORCING STEEL (EPOXY COATED)	830.00	0.00	830.00	LB	830.00	\$1.82	\$1,510.60
		0074	0830	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	108.00	0.00	108.00	LF	108.00	\$418.13	\$45,158.04
		0075	0840	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	108.00	0.00	108.00	LF	108.00	\$238.64	\$25,773.12
	CONCRETE           0075         0850         2169903         MISC.Remove and Replace Curb and Parapet				17.00	0.00	17.00	LF	17.00	\$255.69	\$4,346.73	
	0075 0860 7034214 CLASS B-2 CONCRETE				11.50	0.00	11.50	CUYD	11.50	\$2,669.20	\$30,695.80	
	0075 0870 7034600 CURB BLOCKOUT				603.00	0.00	603.00	LF	603.00	\$78.21	\$47,160.63	
		0075	0880	7040113	CLEANING AND EPOXY COATING	2,214.00	0.00	2,214.00	SQFT	2,214.00	\$8.22	\$18,199.08

Revision 4/1/2020 Page 10 of 36



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu		based on	Report Generated date and can differ from the posted am							
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H02	J9I3310	0075	0890	7101000	REINFORCING STEEL (EPOXY COATED)	830.00	0.00	830.00	LB	830.00	\$1.82	\$1,510.60
		0075	0900	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	108.00	0.00	108.00	LF	108.00	\$418.13	\$45,158.04
		0076	0910	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	76.00	0.00	76.00	LF	76.00	\$271.73	\$20,651.48
		0076	0920	2169903	MISC.Remove and Replace Curb and Parapet	12.00	0.00	12.00	LF	12.00	\$362.98	\$4,355.76
		0076	0930	7034214	CLASS B-2 CONCRETE	8.60	0.00	8.60	CUYD	8.60	\$2,609.04	\$22,437.74
		0076	0940	7034600	CURB BLOCKOUT	620.00	0.00	620.00	LF	620.00	\$80.22	\$49,736.40
		0076	0950	7040113	CLEANING AND EPOXY COATING	2,304.00	0.00	2,304.00	SQFT	2,304.00	\$9.20	\$21,196.80
		0076	0960	7101000	REINFORCING STEEL (EPOXY COATED)	1,330.00	0.00	1,330.00	LB	1,330.00	\$1.82	\$2,420.60
		0076	0970	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	76.00	0.00	76.00	LF	76.00	\$450.21	\$34,215.96
		0076	0980	7172054	OPEN CELL FOAM JOINT SEAL	76.00	0.00	76.00	LF	38.00	\$98.27	\$3,734.26
		0077	0990	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	76.00	0.00	76.00	LF	76.00	\$271.73	\$20,651.48
		0077	1000	2169903	MISC.Remove and Replace Curb and Parapet	12.00	0.00	12.00	LF	12.00	\$362.98	\$4,355.76
		0077	1010	7034214	CLASS B-2 CONCRETE	8.60	0.00	8.60	CUYD	8.60	\$2,609.04	\$22,437.74
		0077	1020	7034600	CURB BLOCKOUT	620.00	0.00	620.00	LF	620.00	\$80.22	\$49,736.40
		0077	1030	7040113	CLEANING AND EPOXY COATING	2,304.00	0.00	2,304.00	SQFT	2,304.00	\$9.20	\$21,196.80
		0077	1040	7101000	REINFORCING STEEL (EPOXY COATED)	1,330.00	0.00	1,330.00	LB	1,330.00	\$1.82	\$2,420.60
		0077	1050	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	76.00	0.00	76.00	LF	76.00	\$450.21	\$34,215.96
		0077	1060	7172054	OPEN CELL FOAM JOINT SEAL	76.00	0.00	76.00	LF	38.00	\$98.27	\$3,734.26
		0078	1070	7034600	CURB BLOCKOUT	287.00	0.00	287.00	LF	287.00	\$120.32	\$34,531.84
		0078	1080	7040104	HALF-SOLE REPAIR	50.00	-50.00	0.00	SQFT	0.00	\$150.41	\$0.00
		0078	1090	7049904	MISC.Reparing Concrete Wearing Surface	50.00	-50.00	0.00	SQFT	0.00	\$68.18	\$0.00
		0079	1100	7034600	CURB BLOCKOUT	309.00	0.00	309.00	LF	309.00	\$117.32	\$36,251.88
		0800	1110	7034600	CURB BLOCKOUT	255.00	0.00	255.00	LF	255.00	\$117.32	\$29,916.60
		0800	1120	7039904	MISC.Reparing Concrete Wearing Surface	100.00	-30.00	70.00	SQFT	70.00	\$58.16	\$4,071.20
				7040104	HALF-SOLE REPAIR	100.00	-100.00	0.00	SQFT	0.00	\$145.39	\$0.00
		0081	1140	7034600	CURB BLOCKOUT	265.00	0.00	265.00	LF	265.00	\$116.31	\$30,822.15
		0082	1150	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	136.00	-136.00	0.00	LF	0.00	\$227.61	\$0.00
		0082	1160	2169903	MISC.Remove and Replace Curb and Parapet	19.00	-19.00	0.00	LF	0.00	\$228.62	\$0.00
		0082	1170	7034214	CLASS B-2 CONCRETE	13.70	-13.70	0.00	CUYD	0.00	\$2,550.88	\$0.00
		0082	1180	7034600	CURB BLOCKOUT	797.00	-797.00	0.00	LF	0.00	\$71.19	\$0.00
		0082	1190	7040104	HALF-SOLE REPAIR	50.00	-50.00	0.00	SQFT	0.00	\$155.42	\$0.00
		0082	1200	7040113	CLEANING AND EPOXY COATING	853.00	-853.00	0.00	SQFT	0.00	\$11.03	\$0.00
		0082	1210	7049904	MISC.Reparing Concrete Wearing Surface	50.00	-50.00	0.00	SQFT	0.00	\$68.18	\$0.00
		0082	1220	7101000	REINFORCING STEEL (EPOXY COATED)	960.00	-960.00	0.00	LB	0.00	\$1.82	\$0.00
		0082	1230	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	136.00	-136.00	0.00	LF	0.00	\$407.10	\$0.00
		0083	1240	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	76.00	0.00	76.00	LF	38.00	\$235.64	\$8,954.32
		0083	1250	2169903	MISC.Remove and Replace Curb and Parapet	12.00	0.00	12.00	LF	6.00	\$362.98	\$2,177.88
		0083	1260	7034214	CLASS B-2 CONCRETE	8.10	0.00	8.10	CUYD	4.00	\$3,238.74	\$12,954.96
		0083	1270	7034600	CURB BLOCKOUT	535.00	0.00	535.00	LF	267.50	\$75.20	\$20,116.00
		0083	1280	7040113	CLEANING AND EPOXY COATING	1,692.00	0.00	1,692.00	SQFT	846.00	\$8.22	\$6,954.12
		0083	1290	7101000	REINFORCING STEEL (EPOXY COATED)	1,330.00	0.00	1,330.00	LB	665.00	\$1.82	\$1,210.30
		0083	1300	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	76.00	0.00	76.00	LF	38.00	\$450.21	\$17,107.98
		0084	1310	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	76.00	0.00	76.00	LF	38.00	\$271.73	\$10,325.74
		0084	1320	2169903	CONCRETE  MISC.Remove and Replace Curb and Parapet	12.00	0.00	12.00	LF	6.00	\$362.98	\$2,177.88
		0084	1330	7034214	CLASS B-2 CONCRETE	8.10	0.00	8.10	CUYD	4.05	\$3,238.74	\$13,116.90
		0004	1000	7 0042 14	SE ISS SE CONCILE	0.10	0.00	0.10	0010	4.00	ψυ,200.14	φ13,110.90

Revision 4/1/2020 Page 11 of 36



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
213-H02	J9I3310	0084	1340	7034600	CURB BLOCKOUT	535.00	0.00	535.00	LF	267.50	\$75.20	\$20,116.00
		0084	1350	7040113	CLEANING AND EPOXY COATING	1,692.00	0.00	1,692.00	SQFT	846.00	\$8.22	\$6,954.12
		0084	1360	7101000	REINFORCING STEEL (EPOXY COATED)	1,330.00	0.00	1,330.00	LB	665.00	\$1.82	\$1,210.30
		0084	1370	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	76.00	0.00	76.00	LF	38.00	\$450.21	\$17,107.98
		0085	1380	7034600	CURB BLOCKOUT	539.00	0.00	539.00	LF	539.00	\$83.22	\$44,855.58
		0085	1390	7040104	HALF-SOLE REPAIR	150.00	-150.00	0.00	SQFT	0.00	\$102.28	\$0.00
		0085	1400	7040113	CLEANING AND EPOXY COATING	535.00	0.00	535.00	SQFT	535.00	\$12.03	\$6,436.05
		0085	1410	7049904	MISC.Repairing Concrete Wearing Surface	50.00	-7.00	43.00	SQFT	43.00	\$68.18	\$2,931.74
		0085	1420	7172054	OPEN CELL FOAM JOINT SEAL	56.00	0.00	56.00	LF	56.00	\$74.20	\$4,155.20
		0085	1430	7173002	SILICONE EXPANSION JOINT SEALANT	56.00	0.00	56.00	LF	56.00	\$71.19	\$3,986.64
		0001	5001	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	0.00	250.00	250.00	LF	250.00	\$41.22	\$10,305.00
		0001	5002	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	0.00	1,250.00	1,250.00	LF	1,250.00	\$19.16	\$23,950.00
		0001	5003	7061070	MECHANICAL BAR SPLICE	0.00	135.00	135.00	EA	96.00	\$27.18	\$2,609.28
		0081	5004	7039904	MISC.Misc. Repairing Concrete Wearing Surface - BR A24053	0.00	142.00	142.00	SQFT	142.00	\$58.16	\$8,258.72
		0001	5005	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	0.00	6,133.00	6,133.00	SQYD	6,133.00	\$7.43	\$45,568.19
		0001	5006	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	0.00	2,787.00	2,787.00	TONS	2,476.77	\$94.76	\$234,698.73
		0001	5007	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$7,034.55	\$7,034.55
	Project J	J9I3310 - To	tal Value	e Posted to D	ate as of Report Generated Date							\$4,250,047.35
13-H02 Ove	erall - Tota	I Value Pos	ted to Da	ate as of Rep	oort Generated Date							\$4,250,047.35

Revision 4/1/2020 Page 12 of 36



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9I3310

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2159903	MISC. SHAPING SLOPES	9/3/20	9/15/20	242.50	LF	SE corner of A22672					Previously paid 120 LF on 7/29/20
				9/15/20	269.25	LF	NE corner of A22672					Previously paid 120 LF on 7/29/20
				9/15/20	414.25	LF	Rte Y NB off-ramp RT					
				9/15/20	426.75	LF	Rte Y NB on-ramp RT					
			9/9/20	9/15/20	287.50	LF	MM 145 NBDL - BR A2419					
				9/15/20	400.00	LF	MM 145 SBDL - BR A2419					
0060	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP1	9/8/20	9/15/20	1,226.00	TONS	SBPL - LM 44.817 to near LM 46.2					SP 125 20-47 @ 16 ft wide and 1.75" thick
			9/9/20	9/15/20	741.89	TONS	SBPL near LM 46.2 to near DD/OO					SBPL @ 16 ft wide and 1.75" thick
			9/10/20	9/15/20	1,868.52	TONS	Near DD/OO to near weigh station SBPL					SP125 20-47 @ 16 ft wide and 1.75" thick
			9/11/20	9/15/20	2,284.18	TONS	SBPL from near weigh station to near Rte Y					SP125 20-47 @ 16 ft wide and 1.75" thick
			9/12/20	9/15/20	297.32	TONS	SBPL from Near Rte Y to near Rte Y					SP125 20-47 @ 16 ft wide and 1.75" thick
			9/14/20	9/16/20	5,807.02	TONS	SBPL from near Rte Y to UPRR					SP125 20-47 in the SBPL @ 16 ft wide and 1.75" thick
			9/15/20	9/16/20	4,432.80	TONS	SBDL from near LM 44.817 to near Bloomsdale weigh station					SP125 20-47 @ 14 ft wide and 1.75" thick
0070	4071005	TACK COAT	9/3/20	9/15/20	233.00	GAL	MM 145 NB/SB bridges - 8" shoulder mill/fill					540' before and 380' after bridges A24192/3
			9/8/20	9/15/20	1,595.00	GAL	SBPL from LM 44.817 to near LM 46.5					
			9/9/20	9/15/20	972.00	GAL	SBPL near LM 46.2 to near DD/OO					
			9/10/20	9/15/20	1,458.00	GAL	SBPL near DD/OO to near weigh station					
			9/11/20	9/15/20	2,139.00	GAL	SBPL from near weigh station to near Rte Y					
			9/12/20	9/15/20	535.00	GAL	SBPL from Near Rte Y to near Rte Y					
			9/14/20	9/16/20	5,785.00	GAL	SBPL from near Rte Y to UPRR bridge					
			9/15/20	9/16/20	3,918.00	GAL	SBDL from near LM 44.817 to near Bloomsdale weigh station					
0110	6122030	IMPACT ATTENUATOR (RELOCATION)	9/14/20	9/16/20	2.00	EA	MM 145 NB/SB bridge work - phase 2					
0230	6161010	RELOCATED SIGNS	9/14/20	9/16/20	128.00	SQFT	MM 145 NB/SB Bridges - phase 2					NB MM 145 Bridge WZ
												RLCA x2 > LLCA x2 RLC x1 > LLC x1 MRG Lx 1 > MRG R x1 = 64 SF SB MM 145 Bridge WZ RLCA x2 > LLCA x2 RLC x1 > LLC x1 MRG Lx 1 > MRG R x1 = 64 SF See 20200819 DWR for log miles
0310	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	9/14/20	9/16/20	475.00	LF	MM 145.2 NBDL - BR A24192 - phase 2					See 20200619 DWK for log fillies
				9/16/20	475.00	LF	MM 145.4 SBDL - BR A24193 - phase 2					
0320	6181000	MOBILIZATION	9/14/20	9/16/20	0.25	LS	Job is more than 25% complete					
0330	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	9/14/20	9/16/20	0.00	LF	MM 145 NB/SB Bridge WZ					Total not yet measured.
0340	6205303B	TEMPORARY REMOVABLE MARKING TAPE	9/14/20	9/16/20	0.00	LF	MM 145 NB/SB Bridge WZ					Total not yet measured.
0430	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	9/14/20	9/16/20	89.00	SQYD	SBPL @ LM 48.88					16 ft wide x 50 ft long
0450	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	9/14/20		4,043.00	SQYD	SBPL LM 44.817, 46.512, 46.583, 48.290, 48.369, 48.797, 48.891, 52.666, 52.753, 53.119, 53.208, 54.824, 54.883					All locations are 16 ft wide x 175 ft long
0480	6061060	MGS GUARDRAIL	9/3/20	9/15/20	250.00	1 F	A22672 SE Corner					
				9/15/20	312.50		A22672 NE Corner					
				9/15/20	337.50		Rte Y NB off-ramp RT					
				9/15/20	337.50		Rte Y NB on-ramp RT					
			9/12/20		175.00		BR A2419 RT - MM 145 NBDL					
			0112720	9/15/20	287.50		BR A2419 RT - MM 145 SBDL					
0490	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	9/12/20		2.00		BR A2419 RT - near MM 145 SBDL					1 - SBDL 1 - NBDL
0510	6061080	MGS END ANCHOR	9/3/20	9/15/20	1.00	FΔ	NF Corner of BR A22672					- NBBE
0010	0001000	mod End / monor	0/0/20	9/15/20	1.00		Rte Y (Exit 157) NB on-ramp RT					
0520	6063014	TYPE A CRSHWTHY END TERMINAL (MASH)	9/3/20	9/15/20	4.00		1 @ A22672 SE Corner 2 @ Rte Y (Exit 157) NB off-ramp RT					
			9/12/20	9/15/20	2.00	EA	1 @ Rte Y (Exit 157) NB on-ramp RT  BR A2419 RT - near MM 145 SBDL					1 - SBDL 1 - NBDL
1250	2160002	MISC. REMOVALS	9/11/20	0/15/20	6.00	1.5	MM 145 NBDL - BR A24192					I - INDUL
1260		CLASS B-2 CONCRETE	9/4/20		4.00		MM 145 NBDL - BR A24192					
1270			9/11/20		267.50		MM 145 NBDL - BR A24192					
1290		REINFORCING STEEL (EPOXY COATED)	9/4/20		665.00		MM 145 NBDL - BR A24192					
1300			9/4/20		38.00		MM 145 NBDL - BR A24192					
1320	2169903			9/15/20	6.00		MM 145 SBDL - BR A24193					
1340		CURB BLOCKOUT		9/15/20	267.50		MM 145 SBDL - BR A24193					
		RELOC TEMPORARY TRAFFIC BARRIER ANCHORED	9/14/20		250.00		MM 145 NB/SB bridge WZs - phase 2					
5003 5005		MECHANICAL BAR SPLICE  COLDMILLING BITUMINOUS PAVEMENT FOR REM	9/4/20	9/9/20 9/15/20	20.00		MM 145 NBDL - BR A24192  MM 145 NB/SB RT Shoulder					540' before and 380' after bridge ends, 10' shoulder m
5006		BIT. PAVEMENT MIXTURE PG64-22 (BP-1)		9/15/20	717.25		MM 145 NB/SB RT Shoulder					@ 8" depth 540' before and 380' after bridge ends, 10' shoulder
5007		MOBILIZATION		9/15/20	1.00	LS	MM 145, 156, 157 NB/SB RT shoulders					paving @ 8" depth shoulder reinforcement

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 13 of 36



			1					
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0060	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Material		12	Sep 16, 2020	SYSTEM	(\$1,236,836.45)	
				12	Sep 16, 2020	SYSTEM	\$1,236,836.45	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Other Item Adjustment	ACAD	12	Sep 16, 2020	pinkle1	(\$63,507.60)	See attached AC adjustment sheet "191213-H02 AC ADJ LI 0060 20200908 to 20200915 EST 0012" for details.
			ACAD - Tot	al			(\$63,507.60)	
	Other Item Adjustment - Total						(\$63,507.60)	
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Price		12	Sep 16, 2020	SYSTEM	(\$40,924.72)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$40,924.72)	
	Price - Total						(\$40,924.72)	
0060 -	Total						(\$104,432.32)	
0070	TACK COAT	Material		12	Sep 16, 2020	SYSTEM	(\$32,770.95)	
				12	Sep 16, 2020	SYSTEM	\$32,770.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0070 -	Total						\$0.00	
0110	IMPACT ATTENUATOR (RELOCATION)	Overrun	Overrun	5	Jun 2, 2020	SYSTEM	(\$2,016.00)	
				6	Jun 16, 2020	SYSTEM	\$2,016.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',672.00000 - 672.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0110 -	Total						\$0.00	
0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		3	May 5, 2020	SYSTEM	(\$39,106.80)	
	TAVENTALIAN			3	May 5, 2020	SYSTEM	\$39,106.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Overrun	Overrun	3	May 5, 2020	SYSTEM	(\$8,690.40)	
	17WEMENT NEI 7MN			3	May 5, 2020	SYSTEM	\$5,793.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 21 on the current Payment Estimate.
				3	May 5, 2020	SYSTEM	\$2,896.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 21 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$8,690.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Jun 16, 2020	SYSTEM	\$8,690.40	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',181.05000 - 181.05000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0130 -	Total						\$0.00	
0140	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Overrun	Overrun	3	May 5, 2020	SYSTEM	(\$1,285.22)	
				6	Jun 16, 2020	SYSTEM	\$1,285.22	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',7.18000 - 7.18000, 'is applied (if non-zero).

Revision 4/1/2020 Page 14 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0140		Overrun	Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0140 -	Total						\$0.00	
0150	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Overrun	Overrun	3	May 5, 2020	SYSTEM	(\$966.60)	
				6	Jun 16, 2020	SYSTEM	\$966.60	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.40000 - 5.40000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0150 -							\$0.00	
0160	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	Overrun	Overrun		May 5, 2020	SYSTEM	(\$1,168.20)	
	,			6	Jun 16, 2020	SYSTEM	\$1,168.20	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',8.85000 - 8.85000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0160 -	Total						\$0.00	
0170	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		3	May 5, 2020	SYSTEM	(\$586.04)	
	TAVENDATIVETAIN			3	May 5, 2020	SYSTEM	\$586.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$586.04)	
				4	May 15, 2020	SYSTEM	\$586.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
			_					
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Overrun	Overrun	3	May 5, 2020	SYSTEM	(\$70.84)	
		Overrun	Overrun	3		SYSTEM	(\$70.84) \$70.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 25 on the current Payment Estimate.
	AND INSTALLATION) FOR FULL DEPTH	Overrun	Overrun		2020 May 5,		` ′	Payment Estimate Item Adjustment (0009) overridding Payment
	AND INSTALLATION) FOR FULL DEPTH	Overrun	Overrun	3	2020 May 5, 2020 May 15,	SYSTEM	\$70.84	Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 25 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous
	AND INSTALLATION) FOR FULL DEPTH	Overrun	Overrun	3	2020 May 5, 2020 May 15, 2020 May 15,	SYSTEM	\$70.84 (\$70.84) \$70.84	Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 25 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment
	AND INSTALLATION) FOR FULL DEPTH	Overrun	Overrun	3 4 4	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2,	SYSTEM SYSTEM	\$70.84 (\$70.84) \$70.84	Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 25 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 19 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous
	AND INSTALLATION) FOR FULL DEPTH	Overrun	Overrun - T	3 4 4 5 6	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM	\$70.84 (\$70.84) \$70.84	Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 25 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 19 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments
	AND INSTALLATION) FOR FULL DEPTH	Overrun		3 4 4 5 6	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM	\$70.84 (\$70.84) \$70.84 (\$70.84)	Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 25 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 19 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments
0170 -	AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR  Overrun - Total	Overrun		3 4 4 5 6	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM	\$70.84 (\$70.84) \$70.84 (\$70.84) \$70.84	Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 25 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 19 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments
0170 - 0180	Overrun - Total  Total  DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR	Overrun		3 4 4 5 6	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM	\$70.84 (\$70.84) \$70.84 (\$70.84) \$70.84	Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 25 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 19 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments
	Overrun - Total  Total  DOWEL BAR (FURNISHING AND			3 4 4 5 6 6 otal	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$70.84 (\$70.84) \$70.84 (\$70.84) \$70.84 \$0.00 \$0.00	Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 25 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 19 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments
	Overrun - Total  Total  DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR			3 4 4 5 6 6 otal	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2, 2020 Jun 16, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$70.84 (\$70.84) \$70.84 (\$70.84) \$70.84 \$0.00 \$0.00 (\$297.72)	Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 25 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 19 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',6.44000 - 6.44000, 'is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 3 on the current
	Overrun - Total  Total  DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR			3 4 4 5 6 6 otal 3 3 3	2020 May 5, 2020 May 15, 2020 May 15, 2020 Jun 2, 2020 Jun 16, 2020 May 5, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$70.84 (\$70.84) \$70.84 (\$70.84) \$70.84 \$0.00 \$0.00 (\$297.72)	Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 25 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 19 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',6.44000 - 6.44000, 'is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 3 on the current

Revision 4/1/2020 Page 15 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0180	Material - Total		75-				\$0.00	
0180 -	Total						\$0.00	
0190	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		3	May 5, 2020	SYSTEM	(\$72.09)	
	PAVEMENT REPAIR (TYPE L JOINTS)			3	May 5, 2020	SYSTEM	\$72.09	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$72.09)	
				4	May 15, 2020	SYSTEM	\$72.09	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Overrun	Overrun	3	May 5, 2020	SYSTEM	(\$29.37)	
	TAVENERY RELAIR (THE ESSINTS)			3	May 5, 2020	SYSTEM	\$29.37	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 26 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$29.37)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	May 15, 2020	SYSTEM	\$29.37	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 20 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$29.37)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Jun 16, 2020	SYSTEM	\$29.37	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.67000 - 2.67000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0190 -	Total						\$0.00	
0200	CONSTRUCTION SIGNS	Overrun	Overrun	11	Sep 1, 2020	SYSTEM	(\$5,528.00)	
				11	Sep 1, 2020	SYSTEM	\$2,752.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	\$2,776.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$5,528.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Sep 16, 2020	SYSTEM	\$5,528.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user pinkle1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0200 -	Total						\$0.00	
0210	ADVANCED WARNING RAIL SYSTEM	Overrun	Overrun		Apr 3, 2020	SYSTEM	(\$270.00)	
				6	Jun 16, 2020	SYSTEM	\$270.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',45.00000 - 45.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0210 -							\$0.00	
0220	FLAG ASSEMBLY	Overrun	Overrun		May 5, 2020	SYSTEM	(\$40.00)	
				6	Jun 16, 2020	SYSTEM	\$40.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',20.00000 - 20.00000, 'is applied (if non-zero).

Revision 4/1/2020 Page 16 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0220		Overrun	Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0220 -	· Total						\$0.00	
0270	SEQUENTIAL FLASHING WARNING LIGHT	Overrun	Overrun	1	Apr 3, 2020	SYSTEM	(\$100.00)	
				6	Jun 16, 2020	SYSTEM	\$100.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',50.00000 - 50.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0270 -	· Total						\$0.00	
0280	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	Overrun	Overrun	8	Jul 15, 2020	SYSTEM	(\$4,000.00)	
	FURNISHED, CONTRACTOR RETAINED			9	Aug 3, 2020	SYSTEM	\$4,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2000.00000 - 2000.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0280 -	Total						\$0.00	
0300	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		1	Apr 3, 2020	SYSTEM	(\$33,561.00)	
				1	Apr 3, 2020	SYSTEM	\$33,561.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0300 -	· Total						\$0.00	
0330	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		1	Apr 3, 2020	SYSTEM	(\$9,496.00)	
				1	Apr 3, 2020	SYSTEM	\$9,496.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Overrun	Overrun	8	Jul 15, 2020	SYSTEM	(\$2,549.00)	
				9	Aug 3, 2020	SYSTEM	(\$4,657.00)	
				9	Aug 3, 2020	SYSTEM	\$4,657.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user pinkle1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$4,657.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Aug 17, 2020	SYSTEM	\$4,657.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user pinkle1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	(\$4,657.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				11	Sep 1, 2020	SYSTEM	(\$6,160.00)	
				11	Sep 1, 2020	SYSTEM	\$6,160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user pinkle1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	\$4,657.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$10,817.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Sep 16,	SYSTEM	\$10,817.00	This adjustment offsets the original system-generated Overrun

Revision 4/1/2020 Page 17 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0330	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Overrun	Overrun		2020			Payment Estimate Item Adjustment (0022) due to user pinkle1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
			Overrun - To	otal			(\$2,549.00)	
	Overrun - Total						(\$2,549.00)	
0330 -	Total						(\$2,549.00)	
0340	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		1	Apr 3, 2020	SYSTEM	(\$2,374.00)	
				1	Apr 3, 2020	SYSTEM	\$2,374.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Overrun	Overrun		Aug 3, 2020	SYSTEM	(\$516.00)	
				9	Aug 3, 2020	SYSTEM	\$516.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user pinkle1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$516.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Aug 17, 2020	SYSTEM	\$516.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	(\$516.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				11	Sep 1, 2020	SYSTEM	\$516.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$516.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Sep 16, 2020	SYSTEM	\$516.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user pinkle1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	
0340 -	Total						\$0.00	
0480	MGS GUARDRAIL	Construction Stockpile		3	May 5, 2020	SYSTEM	\$112,353.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	May 15, 2020	SYSTEM	(\$11,789.17)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jun 30, 2020	SYSTEM	(\$6,305.83)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Jul 15, 2020	SYSTEM	(\$6,305.83)	Payment Estimate Item Adjustment generated Stockpile Transaction
				9	Aug 3, 2020	SYSTEM	\$2,467.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Aug 17, 2020	SYSTEM	(\$15,627.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 1, 2020	SYSTEM	(\$9,458.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Total	12	Sep 16, 2020	SYSTEM	(\$18,643.34)	Payment Estimate Item Adjustment generated Stockpile Transaction
	Company of the Standard Total		- Total				\$46,690.58	
	Construction Stockpile - Total  MGS GUARDRAIL	Material		1	Apr 3, 2020	SYSTEM	\$46,690.58 (\$18,500.00)	
				1	Apr 3, 2020	SYSTEM	\$18,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	

Revision 4/1/2020 Page 18 of 36



0480	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0-100	Material - Total		71				\$0.00	
0480 - T	otal						\$46,690.58	
0490	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		3	May 5, 2020	SYSTEM	\$54,513.33	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	May 15, 2020	SYSTEM	(\$3,206.66)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jun 30, 2020	SYSTEM	(\$3,206.67)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Jul 15, 2020	SYSTEM	(\$3,206.67)	Payment Estimate Item Adjustment generated Stockpile Transaction
				9	Aug 3, 2020	SYSTEM	(\$6,413.33)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Aug 17, 2020	SYSTEM	(\$3,206.67)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 1, 2020	SYSTEM	(\$3,206.66)	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Sep 16, 2020	SYSTEM	(\$3,206.67)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$28,860.00	
C	Construction Stockpile - Total						\$28,860.00	
	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Material		1	Apr 3, 2020	SYSTEM	(\$11,200.00)	
				1	Apr 3, 2020	SYSTEM	\$11,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
N	Material - Total						\$0.00	
0490 - T	otal						\$28,860.00	
0500	MGS VERTICAL CONCRETE BARRIER TRANSITION	Construction Stockpile		3	May 5, 2020	SYSTEM	\$2,510.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$2,510.00	
C	Construction Stockpile - Total						\$2,510.00	
0500 - T	otal						\$2,510.00	
0510	MGS END ANCHOR	Construction Stockpile		3	May 5, 2020	SYSTEM	\$5,801.78	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	May 15, 2020	SYSTEM	(\$1,084.45)	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Jun 2, 2020	SYSTEM	\$542.23	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Aug 17, 2020	SYSTEM	(\$1,084.45)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 1, 2020	SYSTEM	(\$542.22)	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Sep 16, 2020	SYSTEM	(\$1,084.45)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$2,548.44	
	Construction Stockpile - Total						\$2,548.44	
0510 - T	otal						\$2,548.44	
0520	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		3	May 5, 2020	SYSTEM	\$65,657.78	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	May 15, 2020	SYSTEM	(\$6,648.89)	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Jun 2, 2020	SYSTEM	(\$1,662.22)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jun 30,	SYSTEM	(\$3,324.45)	Payment Estimate Item Adjustment generated Stockpile
					2020			Transaction
				8	Jul 15, 2020	SYSTEM	(\$3,324.44)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Jul 15,	SYSTEM	(\$3,324.44) (\$6,648.89)	Payment Estimate Item Adjustment generated Stockpile

Revision 4/1/2020 Page 19 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0520	TYPE A CRASHWORTHY END	Construction			2020			Transaction
	TERMINAL (MASH)	Stockpile		12	Sep 16, 2020	SYSTEM	(\$9,973.33)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$29,088.89	
	Construction Stockpile - Total						\$29,088.89	
	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		1	Apr 3, 2020	SYSTEM	(\$10,800.00)	
				1	Apr 3, 2020	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0520 -	- Total						\$29,088.89	
0530	CURB BLOCKOUT	Material		1	Apr 3, 2020	SYSTEM	(\$18,630.00)	
				1	Apr 3, 2020	SYSTEM	\$18,630.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user pinkle1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				2	Apr 16, 2020	SYSTEM	(\$37,260.00)	
				2	Apr 16, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				3	May 5, 2020	SYSTEM	(\$37,260.00)	
				3	May 5, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$37,260.00)	
				4	May 15, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$37,260.00)	
				5	Jun 2, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$37,260.00)	
				6	Jun 16, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$37,260.00)	
				7	Jul 1, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$37,260.00)	
				8	Jul 16, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user lashlh1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$37,260.00)	
				9	Aug 3, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				10	Aug 17,	SYSTEM	(\$37,260.00)	

Revision 4/1/2020 Page 20 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0530	CURB BLOCKOUT	Material			2020			
				10	Aug 17, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	(\$37,260.00)	
				11	Sep 1, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$37,260.00)	
				12	Sep 16, 2020	SYSTEM	\$37,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0530 -	· Total						\$0.00	
0540	CLEANING AND EPOXY COATING	Material		1	Apr 3, 2020	SYSTEM	(\$1,422.06)	
				1	Apr 3, 2020	SYSTEM	\$1,422.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0540 -	·Total						\$0.00	
0550	CURB BLOCKOUT	Material		1	Apr 3, 2020	SYSTEM	(\$17,545.68)	
				1	Apr 3, 2020	SYSTEM	\$17,545.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user pinkle1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				2	Apr 16, 2020	SYSTEM	(\$35,091.36)	
				2	Apr 16, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	May 5, 2020	SYSTEM	(\$35,091.36)	
				3	May 5, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$35,091.36)	
				4	May 15, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$35,091.36)	
				5	Jun 2, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$35,091.36)	
				6	Jun 16, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$35,091.36)	
				7	Jul 1, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1

Revision 4/1/2020 Page 21 of 36



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	2-2-2	Туре	Adjustment Type	Number	Date	Ву		
0550	CURB BLOCKOUT	Material						overridding Payment Estimate Exception 9 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$35,091.36)	
				8	Jul 16, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user lashIh1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$35,091.36)	
				9	Aug 3, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$35,091.36)	
				10	Aug 17, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	(\$35,091.36)	
				11	Sep 1, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$35,091.36)	
				12	Sep 16, 2020	SYSTEM	\$35,091.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0550 -	Material - Total Total						\$0.00 \$0.00	
<b>0550</b> -		Material		1	Apr 3, 2020	SYSTEM		
	Total	Material		1		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
	Total	Material	- Total		2020 Apr 3,		\$0.00 (\$1,422.06)	Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current
	Total	Material	- Total		2020 Apr 3,		\$0.00 (\$1,422.06) \$1,422.06	Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current
0560	Total  CLEANING AND EPOXY COATING	Material	- Total		2020 Apr 3,		\$0.00 (\$1,422.06) \$1,422.06	Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current
0560	Total  CLEANING AND EPOXY COATING  Material - Total		- Total		2020 Apr 3,		\$0.00 (\$1,422.06) \$1,422.06 \$0.00	Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current
0560	Total  CLEANING AND EPOXY COATING  Material - Total  Total			1	2020 Apr 3, 2020	SYSTEM	\$0.00 (\$1,422.06) \$1,422.06 \$0.00 \$0.00	Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current
0560 -	Total  CLEANING AND EPOXY COATING  Material - Total  CLASS B-2 CONCRETE		- Total	9	2020 Apr 3, 2020 Aug 3, 2020 Aug 3,	SYSTEM	\$0.00 (\$1,422.06) \$1,422.06 \$0.00 \$0.00 \$0.00 (\$22,237.81)	Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 2 on the current
0560 -	Total  CLEANING AND EPOXY COATING  Material - Total  Total			9	2020 Apr 3, 2020 Aug 3, 2020 Aug 3,	SYSTEM	\$0.00 (\$1,422.06) \$1,422.06 \$0.00 \$0.00 \$0.00 (\$22,237.81) \$22,237.81	Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 2 on the current
0560 - 0560 - 0690	Total  CLEANING AND EPOXY COATING  Material - Total  CLASS B-2 CONCRETE			9	2020 Apr 3, 2020 Aug 3, 2020 Aug 3,	SYSTEM	\$0.00 (\$1,422.06) \$1,422.06 \$0.00 \$0.00 (\$22,237.81) \$22,237.81	Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 2 on the current
0560 - 0560 - 0690	Total  CLEANING AND EPOXY COATING  Material - Total  CLASS B-2 CONCRETE			9	2020 Apr 3, 2020 Aug 3, 2020 Aug 3,	SYSTEM	\$0.00 (\$1,422.06) \$1,422.06 \$0.00 \$0.00 (\$22,237.81) \$22,237.81	Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 2 on the current
0560 - 0690 - 06	Total  CLEANING AND EPOXY COATING  Material - Total  CLASS B-2 CONCRETE  Material - Total  Total	Material		9 9	2020 Apr 3, 2020 Aug 3, 2020 Aug 3, 2020	SYSTEM SYSTEM	\$0.00 (\$1,422.06) \$1,422.06 \$0.00 \$0.00 (\$22,237.81) \$22,237.81 \$0.00 \$0.00	Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 2 on the current
0560 - 0690 - 06	Total  CLEANING AND EPOXY COATING  Material - Total  CLASS B-2 CONCRETE  Material - Total  Total	Material		9 9	Aug 3, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$1,422.06) \$1,422.06 \$0.00 \$0.00 (\$22,237.81) \$22,237.81 \$0.00 \$0.00 (\$45,270.75)	Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Exception 14 on the current
0560 - 0690 - 06	Total  CLEANING AND EPOXY COATING  Material - Total  CLASS B-2 CONCRETE  Material - Total  Total	Material		9 9	Aug 3, 2020  Aug 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$1,422.06) \$1,422.06 \$0.00 \$0.00 (\$22,237.81) \$22,237.81 \$0.00 \$0.00 (\$45,270.75)	Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Exception 14 on the current

Revision 4/1/2020 Page 22 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0700	CURB BLOCKOUT	Material		11	Sep 1, 2020	SYSTEM	\$45,270.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$45,270.75)	
				12	Sep 16, 2020	SYSTEM	\$45,270.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user pinkle1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0700	- Total						\$0.00	
0710	HALF-SOLE REPAIR	Material		9	Aug 3, 2020	SYSTEM	(\$10,501.70)	
				9	Aug 3, 2020	SYSTEM	\$10,501.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0710	- Total						\$0.00	
0730	MISC. Repairing Concrete Wearing Surface	Material		9	Aug 3, 2020	SYSTEM	(\$22,369.86)	
				9	Aug 3, 2020	SYSTEM	\$22,369.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$22,369.86)	
				10	Aug 17, 2020	SYSTEM	\$22,369.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user pinkle1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	\$15,551.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 14 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	(\$15,551.86)	
				12	Sep 16, 2020	SYSTEM	\$15,551.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 21 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$15,551.86)	
			- Total				\$0.00	
	Material - Total						\$0.00	
	MISC. Repairing Concrete Wearing Surface	Overrun	Overrun	9	Aug 3, 2020	SYSTEM	(\$18,960.86)	
				9	Aug 3, 2020	SYSTEM	\$18,960.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) overridding Payment Estimate Exception 26 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$18,960.86)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Aug 17, 2020	SYSTEM	\$18,960.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 21 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	(\$18,960.86)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				11	Sep 1, 2020	SYSTEM	\$18,960.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$18,960.86)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Sep 16, 2020	SYSTEM	\$18,960.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 26 on the current Payment Estimate.

Revision 4/1/2020 Page 23 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0730		Overrun	Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0730 -	Total						\$0.00	
0790	CLASS B-2 CONCRETE	Material		8	Jul 15,	SYSTEM	(\$15,347.90)	
					2020			
				8	Jul 16, 2020	SYSTEM	\$15,347.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user lashih1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0790 -	Total						\$0.00	
0800	CURB BLOCKOUT	Material		8	Jul 15, 2020	SYSTEM	(\$23,580.32)	
				8	Jul 16, 2020	SYSTEM	\$23,580.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user lashlh1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$23,580.32)	
				9	Aug 3, 2020	SYSTEM	\$23,580.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$23,580.32)	
				10	Aug 17, 2020	SYSTEM	\$23,580.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	(\$47,160.63)	
				11	Sep 1, 2020	SYSTEM	\$47,160.63	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$47,160.63)	
				12	Sep 16, 2020	SYSTEM	\$47,160.63	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0800 -	Total						\$0.00	
0820	REINFORCING STEEL (EPOXY COATED)	Material		7	Jun 30, 2020	SYSTEM	(\$755.30)	
				7	Jul 1, 2020	SYSTEM	\$755.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0820 -	Total						\$0.00	
0830	STRIP SEAL EXPANSION JOINT SYSTEM	Material		7	Jun 30, 2020	SYSTEM	(\$22,579.02)	
				7	Jul 1, 2020	SYSTEM	\$22,579.02	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$22,579.02)	
				8	Jul 16, 2020	SYSTEM	\$22,579.02	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user lashlh1 overridding Payment Estimate Exception 18 on the current Payment Estimate.

Revision 4/1/2020 Page 24 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0830		Material	- Total				\$0.00		
	Material - Total						\$0.00		
0830 -	Total						\$0.00		
0850	MISC. Remove and Replace Curb and Parapet	Other Item Adjustment	MDPA	7	Jul 1, 2020	pinkle1	(\$2,173.37)	The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.	
				8	Jul 15, 2020	SYSTEM	\$2,173.37	The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.	
				8	Jul 16, 2020	lashlh1	(\$2,173.37)	The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when sufficient strength is met.	
				9	Aug 3, 2020	pinkle1	\$2,173.37	The deficient concrete has been removed and repaired to the satisfaction of the engineer, therefore payment is being made.	
			MDPA - Tot	al			\$0.00		
	Other Item Adjustment - Total						\$0.00		
0850 -		84-4 11		0	l., 72	OVOTE	\$0.00		
0860	CLASS B-2 CONCRETE	Material		6	Jun 16, 2020	SYSTEM	(\$15,347.90)		
				6	Jun 16, 2020	SYSTEM	\$15,347.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				7	Jun 30, 2020	SYSTEM	(\$15,347.90)		
				7	Jul 1, 2020	SYSTEM	\$15,347.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
				8	Jul 15, 2020	SYSTEM	(\$15,347.90)		
				8	Jul 16, 2020	SYSTEM	\$15,347.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user lashlh1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0860 -							\$0.00		
0870	CURB BLOCKOUT	Material		7	Jun 30, 2020	SYSTEM	(\$23,580.32)		
				7	Jul 1, 2020	SYSTEM	\$23,580.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
				8	Jul 15, 2020	SYSTEM	(\$23,580.32)		
				8	Jul 16, 2020	SYSTEM	\$23,580.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user lashIh1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
				9	Aug 3, 2020	SYSTEM	(\$23,580.32)		
					9	Aug 3, 2020	SYSTEM	\$23,580.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$47,160.63)		
				10	Aug 17, 2020	SYSTEM	\$47,160.63	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
				11	Sep 1, 2020	SYSTEM	(\$47,160.63)		
				11	Sep 1, 2020	SYSTEM	\$47,160.63	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user pinkle1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	

Revision 4/1/2020 Page 25 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0870	CURB BLOCKOUT	Material		12	Sep 16, 2020	SYSTEM	(\$47,160.63)	
				12	Sep 16, 2020	SYSTEM	\$47,160.63	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0870 -	Total						\$0.00	
0890	REINFORCING STEEL (EPOXY COATED)	Material		6	Jun 16, 2020	SYSTEM	(\$755.30)	
				6	Jun 16, 2020	SYSTEM	\$755.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$755.30)	
				7	Jul 1, 2020	SYSTEM	\$755.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0890 -	Total						\$0.00	
0900	STRIP SEAL EXPANSION JOINT SYSTEM	Material		6	Jun 16, 2020	SYSTEM	(\$16,725.20)	
				6	Jun 16, 2020	SYSTEM	\$16,725.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$16,725.20)	
				7	Jul 1, 2020	SYSTEM	\$16,725.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user pinkle1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$16,725.20)	
				8	Jul 16, 2020	SYSTEM	\$16,725.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user lashIh1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0900 -	Total						\$0.00	
0930	CLASS B-2 CONCRETE	Material		7	Jun 30, 2020	SYSTEM	(\$11,218.87)	
				7	Jul 1, 2020	SYSTEM	\$11,218.87	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$11,218.87)	
				8	Jul 16, 2020	SYSTEM	\$11,218.87	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user lashlh1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0930 -	Total						\$0.00	
0940	CURB BLOCKOUT	Material		8	Jul 15, 2020	SYSTEM	(\$24,868.20)	
				8	Jul 16, 2020	SYSTEM	\$24,868.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user lashlh1 overridding Payment Estimate Exception 11 on the current Payment Estimate.

Revision 4/1/2020 Page 26 of 36



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0940	CURB BLOCKOUT	Material		9	Aug 3, 2020	SYSTEM	(\$24,868.20)	
				9	Aug 3, 2020	SYSTEM	\$24,868.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$24,868.20)	
				10	Aug 17, 2020	SYSTEM	\$24,868.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	(\$49,736.40)	
				11	Sep 1, 2020	SYSTEM	\$49,736.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$49,736.40)	
				12	Sep 16, 2020	SYSTEM	\$49,736.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user pinkle1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0940 -	- Total						\$0.00	
0960	REINFORCING STEEL (EPOXY COATED)	Material		7	Jun 30, 2020	SYSTEM	(\$1,210.30)	
				7	Jul 1, 2020	SYSTEM	\$1,210.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0960 -	Material - Total - Total						\$0.00 \$0.00	
<b>0960</b> -		Material		7	Jun 30, 2020	SYSTEM	\$0.00 (\$17,107.98)	
	- Total	Material		7		SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
	- Total	Material			2020 Jul 1,		\$0.00 (\$17,107.98)	Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current
	- Total	Material		7	2020 Jul 1, 2020 Jul 15,	SYSTEM	\$0.00 (\$17,107.98) \$17,107.98	Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current
	- Total	Material	- Total	7	Jul 15, 2020 Jul 15, 2020 Jul 16,	SYSTEM	\$0.00 (\$17,107.98) \$17,107.98	Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user lashIh1 overridding Payment Estimate Exception 21 on the current
0970	Total STRIP SEAL EXPANSION JOINT SYSTEM  Material - Total	Material	- Total	7	Jul 15, 2020 Jul 15, 2020 Jul 16,	SYSTEM	\$0.00 (\$17,107.98) \$17,107.98 (\$17,107.98) \$17,107.98 \$0.00	Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user lashlh1 overridding Payment Estimate Exception 21 on the current
0970	Total STRIP SEAL EXPANSION JOINT SYSTEM	Material	- Total	7	Jul 15, 2020 Jul 15, 2020 Jul 16,	SYSTEM	\$0.00 (\$17,107.98) \$17,107.98 (\$17,107.98) \$17,107.98	Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user lashlh1 overridding Payment Estimate Exception 21 on the current
0970	Total STRIP SEAL EXPANSION JOINT SYSTEM  Material - Total	Material  Other Item Adjustment	- Total	7 8 8	Jul 15, 2020 Jul 15, 2020 Jul 16,	SYSTEM	\$0.00 (\$17,107.98) \$17,107.98 (\$17,107.98) \$17,107.98 \$0.00	Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user lashlh1 overridding Payment Estimate Exception 21 on the current
0970	Total  STRIP SEAL EXPANSION JOINT SYSTEM  Material - Total  MISC. Remove and Replace Curb and	Other Item		7 8 8	2020 Jul 1, 2020 Jul 15, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$17,107.98) \$17,107.98 (\$17,107.98) \$17,107.98 \$0.00 \$0.00	Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user lashlh1 overridding Payment Estimate Exception 21 on the current Payment Estimate.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when
0970	Total  STRIP SEAL EXPANSION JOINT SYSTEM  Material - Total  MISC. Remove and Replace Curb and	Other Item		7 8 8	2020 Jul 1, 2020 Jul 15, 2020 Jul 16, 2020 Jul 17, 2020 Jul 17, 2020 Jul 15,	SYSTEM SYSTEM SYSTEM pinkle1	\$0.00 (\$17,107.98) \$17,107.98 (\$17,107.98) \$17,107.98 \$0.00 \$0.00 (\$2,177.88)	Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user lashlh1 overridding Payment Estimate Exception 21 on the current Payment Estimate.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when
0970	Total  STRIP SEAL EXPANSION JOINT SYSTEM  Material - Total  MISC. Remove and Replace Curb and	Other Item		7 8 8	2020 Jul 1, 2020 Jul 15, 2020 Jul 16, 2020 Jul 17, 2020 Jul 15, 2020 Jul 15, 2020 Jul 16,	SYSTEM SYSTEM  pinkle1  SYSTEM	\$0.00 (\$17,107.98) \$17,107.98 (\$17,107.98) \$17,107.98 \$0.00 \$0.00 (\$2,177.88)	Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user lashlh1 overridding Payment Estimate Exception 21 on the current Payment Estimate.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.
0970	Material - Total  Total  MISC. Remove and Replace Curb and Parapet	Other Item		7 8 8 9	Jul 15, 2020  Jul 16, 2020  Aug 3,	SYSTEM SYSTEM  pinkle1 SYSTEM  lashlh1	\$0.00 (\$17,107.98) \$17,107.98 (\$17,107.98) \$17,107.98 \$0.00 \$0.00 (\$2,177.88) \$2,177.88	Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user lashlh1 overridding Payment Estimate Exception 21 on the current Payment Estimate.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when sufficient strength is met.
0970 - 1000	Total  STRIP SEAL EXPANSION JOINT SYSTEM  Material - Total  Total  MISC. Remove and Replace Curb and Parapet  Other Item Adjustment - Total	Other Item	MDPA	7 8 8 9	Jul 15, 2020  Jul 16, 2020  Aug 3,	SYSTEM SYSTEM  pinkle1 SYSTEM  lashlh1	\$0.00 (\$17,107.98) \$17,107.98 (\$17,107.98) \$17,107.98 \$0.00 \$0.00 \$0.00 (\$2,177.88) \$2,177.88 \$2,177.88	Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user lashlh1 overridding Payment Estimate Exception 21 on the current Payment Estimate.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when sufficient strength is met.
0970 - 1000	Material - Total  Total  MISC. Remove and Replace Curb and Parapet	Other Item Adjustment	MDPA	7 8 8 9	Jul 15, 2020  Jul 16, 2020  Aug 3,	SYSTEM SYSTEM  pinkle1 SYSTEM  lashlh1	\$0.00 (\$17,107.98) \$17,107.98 (\$17,107.98) \$17,107.98 \$0.00 \$0.00 (\$2,177.88) \$2,177.88 (\$2,177.88)	Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 34 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user lashlh1 overridding Payment Estimate Exception 21 on the current Payment Estimate.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when the work is sufficient.  The concrete poured to replace the existing parapet curb was deficient and had to be removed. Payment will be made when sufficient strength is met.

Revision 4/1/2020 Page 27 of 36



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
4040	OLAGO DA CONODETE	Material	Туре		0000			
1010	CLASS B-2 CONCRETE	Material		7	Jul 1, 2020	SYSTEM	\$11,218.87	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$11,218.87)	
				8	Jul 16, 2020	SYSTEM	\$11,218.87	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user lashlh1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$11,218.87)	
				9	Aug 3, 2020	SYSTEM	\$11,218.87	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1010 -	· Total						\$0.00	
1020	CURB BLOCKOUT	Material		7	Jun 30, 2020	SYSTEM	(\$24,868.20)	
				7	Jul 1, 2020	SYSTEM	\$24,868.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$24,868.20)	
				8	Jul 16, 2020	SYSTEM	\$24,868.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user lashlh1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$24,868.20)	
				9	Aug 3, 2020	SYSTEM	\$24,868.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$49,736.40)	
				10	Aug 17, 2020	SYSTEM	\$49,736.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	(\$49,736.40)	
				11	Sep 1, 2020	SYSTEM	\$49,736.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$49,736.40)	
				12	Sep 16, 2020	SYSTEM	\$49,736.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user pinkle1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
<b>1020</b> -	Total  REINFORCING STEEL (EPOXY COATED)	Material		7	Jun 30,	SYSTEM	\$0.00 (\$1,210.30)	
1040	ONOMO OTELE (EL ONT GONTED)	Jaconai			2020			This adjustment affects the original custom generated Custom
				7	Jul 1, 2020	SYSTEM	\$1,210.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user pinkle1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1040 -	· Total						\$0.00	

Revision 4/1/2020 Page 28 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1050	STRIP SEAL EXPANSION JOINT SYSTEM	Material		7	Jun 30, 2020	SYSTEM	(\$17,107.98)	
				7	Jul 1, 2020	SYSTEM	\$17,107.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user pinkle1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$17,107.98)	
				8	Jul 16, 2020	SYSTEM	\$17,107.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user lashlh1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	
1070	CURB BLOCKOUT	Material		1	Apr 3, 2020	SYSTEM	(\$17,205.76)	
				1	Apr 3, 2020	SYSTEM	\$17,205.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				2	Apr 16, 2020	SYSTEM	(\$34,531.84)	
				2	Apr 16, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				3	May 5, 2020	SYSTEM	(\$34,531.84)	
				3	May 5, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$34,531.84)	
				4	May 15, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$34,531.84)	
				5	Jun 2, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$34,531.84)	
				6	Jun 16, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$34,531.84)	
				7	Jul 1, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$34,531.84)	
				8	Jul 16, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user lashlh1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$34,531.84)	
				9	Aug 3, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				10	Aug 17,	SYSTEM	(\$34,531.84)	

Revision 4/1/2020 Page 29 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1070	CURB BLOCKOUT	Material			2020				
				10	Aug 17, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
				11	Sep 1, 2020	SYSTEM	(\$34,531.84)		
				11	Sep 1, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user pinkle1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
				12	Sep 16, 2020	SYSTEM	(\$34,531.84)		
				12	Sep 16, 2020	SYSTEM	\$34,531.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user pinkle1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
1070 -	- Total						\$0.00		
1100	CURB BLOCKOUT	Material		2	Apr 16, 2020	SYSTEM	(\$36,251.88)		
				2	Apr 16, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					3	May 5, 2020	SYSTEM	(\$36,251.88)	
				3	May 5, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user pinkle1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
				4	May 15, 2020	SYSTEM	(\$36,251.88)		
				4	May 15, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
				5	Jun 2, 2020	SYSTEM	(\$36,251.88)		
				5	Jun 2, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
				6	Jun 16, 2020	SYSTEM	(\$36,251.88)		
					6	Jun 16, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$36,251.88)		
					7	Jul 1, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$36,251.88)		
				8	Jul 16, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user lashlh1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
				9	Aug 3, 2020	SYSTEM	(\$36,251.88)		
				9	Aug 3, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
				10	Aug 17, 2020	SYSTEM	(\$36,251.88)		

Revision 4/1/2020 Page 30 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1100	CURB BLOCKOUT	Material		10	Aug 17, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
				11	Sep 1, 2020	SYSTEM	(\$36,251.88)		
				11	Sep 1, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
				12	Sep 16, 2020	SYSTEM	(\$36,251.88)		
				12	Sep 16, 2020	SYSTEM	\$36,251.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
1100 -	Total						\$0.00		
1110	CURB BLOCKOUT	Material		1	Apr 3, 2020	SYSTEM	(\$18,067.28)		
				1	Apr 3, 2020	SYSTEM	\$18,067.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
				2	Apr 16, 2020	SYSTEM	(\$14,899.64)		
				2	Apr 16, 2020	SYSTEM	\$14,899.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
				3	May 5, 2020	SYSTEM	(\$29,916.60)		
				3	May 5, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
				4	May 15, 2020	SYSTEM	(\$29,916.60)		
				4	May 15, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
				5	Jun 2, 2020	SYSTEM	(\$29,916.60)		
					5	Jun 2, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jun 16, 2020	SYSTEM	(\$29,916.60)	
					6	Jun 16, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$29,916.60)		
					7	Jul 1, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$29,916.60)		
					8	Jul 16, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user lashlh1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$29,916.60)		
				9	Aug 3,	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun	

Revision 4/1/2020 Page 31 of 36



1.50	D	A all: 4	CH	F-/	Cr	0	A	Dd.:
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1110	CURB BLOCKOUT Materia	Material			2020			Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$29,916.60)	
				10	Aug 17, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	(\$29,916.60)	
				11	Sep 1, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$29,916.60)	
				12	Sep 16, 2020	SYSTEM	\$29,916.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1110	- Total						\$0.00	
1140	CURB BLOCKOUT	Material		2	Apr 16, 2020	SYSTEM	(\$15,352.92)	
				2	Apr 16, 2020	SYSTEM	\$15,352.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				3	May 5, 2020	SYSTEM	(\$30,822.15)	
				3	May 5, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user pinkle1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$30,822.15)	
				4	May 15, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$30,822.15)	
				5	Jun 2, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$30,822.15)	
				6	Jun 16, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$30,822.15)	
				7	Jul 1, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$30,822.15)	
				8	Jul 16, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user lashih1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$30,822.15)	
				9	Aug 3, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user pinkle1

Revision 4/1/2020 Page 32 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1140	CURB BLOCKOUT	Material						overridding Payment Estimate Exception 13 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$30,822.15)	
				10	Aug 17, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	(\$30,822.15)	
				11	Sep 1, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$30,822.15)	
				12	Sep 16, 2020	SYSTEM	\$30,822.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1140 -	Total						\$0.00	
1260	CLASS B-2 CONCRETE	Material		12	Sep 16, 2020	SYSTEM	(\$12,954.96)	
				12	Sep 16, 2020	SYSTEM	\$12,954.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user pinkle1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1260 -	Total						\$0.00	
1270	CURB BLOCKOUT	Material		12	Sep 16, 2020	SYSTEM	(\$20,116.00)	
				12	Sep 16, 2020	SYSTEM	\$20,116.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user pinkle1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1270 -	Total						\$0.00	
1330	CLASS B-2 CONCRETE	Material		11	Sep 1, 2020	SYSTEM	(\$13,116.90)	
				11	Sep 1, 2020	SYSTEM	\$13,116.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$13,116.90)	
				12	Sep 16, 2020	SYSTEM	\$13,116.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1330 -	Total						\$0.00	
1340	CURB BLOCKOUT	Material		12	Sep 16, 2020	SYSTEM	(\$20,116.00)	
				12	Sep 16, 2020	SYSTEM	\$20,116.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1340 -	Total						\$0.00	

Revision 4/1/2020 Page 33 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1380	CURB BLOCKOUT	Material		3	May 5, 2020	SYSTEM	(\$44,855.58)	
				3	May 5, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user pinkle1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				4	May 15, 2020	SYSTEM	(\$44,855.58)	
				4	May 15, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$44,855.58)	
				5	Jun 2, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$44,855.58)	
				6	Jun 16, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				7	Jun 30, 2020	SYSTEM	(\$44,855.58)	
				7	Jul 1, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$44,855.58)	
				8	Jul 16, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user lashlh1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$44,855.58)	
				9	Aug 3, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$44,855.58)	
				10	Aug 17, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				11	Sep 1, 2020	SYSTEM	(\$44,855.58)	
				11	Sep 1, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				12	Sep 16, 2020	SYSTEM	(\$44,855.58)	
				12	Sep 16, 2020	SYSTEM	\$44,855.58	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user pinkle1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
	Material - Total		- Total				\$0.00	
1380	Total						\$0.00 \$0.00	
1420	OPEN CELL FOAM JOINT SEAL	Material		3	May 5, 2020	SYSTEM	(\$4,155.20)	
				3	May 5, 2020	SYSTEM	\$4,155.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				4	May 15,	SYSTEM	(\$4,155.20)	

Revision 4/1/2020 Page 34 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1420	OPEN CELL FOAM JOINT SEAL	Material			2020				
				4	May 15, 2020	SYSTEM	\$4,155.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user pinkle1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
				5	Jun 2, 2020	SYSTEM	(\$4,155.20)		
				5	Jun 2, 2020	SYSTEM	\$4,155.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user pinkle1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
1420 -	- Total						\$0.00		
1430	SILICONE EXPANSION JOINT SEALANT	Material		3	May 5, 2020	SYSTEM	(\$3,986.64)		
				3	May 5, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user pinkle1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
				4	May 15, 2020	SYSTEM	(\$3,986.64)		
					4	May 15, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user pinkle1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$3,986.64)		
				5	Jun 2, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user pinkle1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
				6	Jun 16, 2020	SYSTEM	(\$3,986.64)		
				6	Jun 16, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user pinkle1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
				7	Jun 30, 2020	SYSTEM	(\$3,986.64)		
				7	Jul 1, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user pinkle1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	
				8	Jul 15, 2020	SYSTEM	(\$3,986.64)		
				8	Jul 16, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user lashlh1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
				9	Aug 3, 2020	SYSTEM	(\$3,986.64)		
				9	Aug 3, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user pinkle1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
				10	Aug 17, 2020	SYSTEM	(\$3,986.64)		
				10	Aug 17, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user pinkle1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
				11	Sep 1, 2020	SYSTEM	(\$3,986.64)		
				11	Sep 1, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user pinkle1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
				12	Sep 16, 2020	SYSTEM	(\$3,986.64)		

Revision 4/1/2020 Page 35 of 36



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1430	SILICONE EXPANSION JOINT SEALANT	Material		12	Sep 16, 2020	SYSTEM	\$3,986.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user pinkle1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total					\$0.00		
1430 -	Total						\$0.00	
5006	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	12	Sep 16, 2020	pinkle1	(\$152.42)	See attached AC adjustment sheet "191213-H02 AC ADJ LI 5006 20200903 EST 0012" for details.
			ACAD - Tota	al			(\$152.42)	
	Other Item Adjustment - Total						(\$152.42)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Price		12	Sep 16, 2020	SYSTEM	\$904.88	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				\$904.88	
	Price - Total				\$904.88			
5006 -	Total				\$752.46			
Overa	III - Total				\$3,469.05			

Revision 4/1/2020 Page 36 of 36