

#### Pay Estimate Created Date: September 1, 2020

Progress Esti 1		Contract ID 2001 Prime Contractor Parki	17-F06 ng Lot Mainten		Period Start August 1 Period End Septemb	per 1, 2020 Net Ch	al Contract Amount	60.00				
Approval Date								By User				
September 2, 202	20		Generated and	Approved (and s	hould be considered	Draft) at the Projec	t Office Level by	dukesm1				
September 2, 202	20	Revi	ewed and App	ewed and Approved (and should be considered Draft) at the Resident Engineer Level by								
September 3, 202	20			Reviewed and Approved at the Central Office Controllers Office Level by								
Original Co	npletion Date	Current Comple	tion Date	Actual Cor	npletion Date	% of Curren	t Contract Amount Co	omplete				
Decemb	er 1, 2020	December 1,	2020	100.18%								
Co	ntract Information	al Dates		Milestones								
Date Description	Original Completion Dat	Current Completion Date	Date	Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge				
Acceptance Date			Milestone - C	Calendar Time	July 21, 2020	July 21, 2020 Milestone Comp		Days				
Awarded Date	February 5, 2020	February 5, 2020	Total days al	llowed once								
Letting Date	January 17, 2020	January 17, 2020	bridge work I									
Notice to Proceed Date	April 6, 2020	April 6, 2020										
Open to Traffic Date												
Work Began Date												

Contract Total Pa	ay For Estimate No. 10				
		This Estimate	Previous	To Date	
200117-F06					
	Total Posted Items Pay	\$612,610.50	\$2,629,121.42	\$3,241,731.92	
	Gross Item Adjustments	(\$482,269.90)	(\$371,258.30)	(\$853,528.20)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$2,257,863.12	\$2,388,203.72	
Contract Total Pa	ayable This Estimate:	\$130,340.60			

## Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J6S3319	0130	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$165.000	3,536	\$583,440.00		
	0160	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$3.000	3,996	\$11,988.00		
	0170	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$5.750	2,860	\$16,445.00		
	0180	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$3.750	17	\$63.75		
	0190	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	EA	\$2.450	275	\$673.75		
Project J6	<mark>S3319 - T</mark> o	otal					\$612,610.5		
Overall - Total									

Contract Adjustments This Estimate

#### No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3319	0040	CONCRETE APPROACH PAVEMENT	MaterialCredit			920.3	\$75.00	\$69,022.50



#### Pay Estimate Created Date: September 1, 2020

Progre		mate Number 0	Contract ID Prime Contra	200117-F0 ctor Parking Lo		e, LLC Pay Period End September 1, 2020 Net	Change Ord	der Amount	\$3,235,828.41 \$0.00 \$3,235,828.41
Project Number	Line No.	Item Des	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
6S3319	0040	CONCRET	E APPROACH PAVEMENT	Material			-920.3	\$75.00	(\$69,022.50
	0080	SLOPE	PROTECTION	MaterialCredit			112	\$110.00	\$12,320.00
	0080	SLOPE	PROTECTION	Material			-112	\$110.00	(\$12,320.0
	0130	FURNISHING / CONCRETE M FULL DEPT		Material			-3,536	\$165.00	(\$583,440.00
	0170	FUR	AR (DRILLING, NISHING AND N) FOR FULL MENT REPAIR	MaterialCredit			1,720	\$5.75	\$9,890.00
	0170	FUR	AR (DRILLING, NISHING AND N) FOR FULL MENT REPAIR	Material			-4,450	\$5.75	(\$25,587.50
	0170	FUR	AR (DRILLING, NISHING AND N) FOR FULL MENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	4,450	\$5.75	\$25,587.50
	0180	AND INSTAL	(FURNISHING LATION WITH TS) FOR FULL MENT REPAIR	MaterialCredit			12	\$3.75	\$45.00
	0180	AND INSTAL	(FURNISHING LATION WITH TS) FOR FULL MENT REPAIR	Material			-28	\$3.75	(\$105.00
	0180	AND INSTAL	(FURNISHING LATION WITH TS) FOR FULL MENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	28	\$3.75	\$105.00
	0190	FUR INSTALLATIO DEPTH PAVE	AR (DRILLING, NISHING AND DN) FOR FULL MENT REPAIR (PE L JOINTS)	MaterialCredit			198	\$2.45	\$485.1
	0190	FUR INSTALLATIO DEPTH PAVE	AR (DRILLING, NISHING AND DN) FOR FULL MENT REPAIR (PE L JOINTS)	Material			-451	\$2.45	(\$1,104.9
	0190	FUR INSTALLATIO DEPTH PAVE	AR (DRILLING, NISHING AND DN) FOR FULL MENT REPAIR (PE L JOINTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	451	\$2.45	\$1,104.9
	0540		ROACH SLAB MAJOR ROAD)	MaterialCredit			330	\$275.00	\$90,750.0
	0540		ROACH SLAB MAJOR ROAD)	Material			-330	\$275.00	(\$90,750.0
	0540		ROACH SLAB IAJOR ROAD)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	330	\$275.00	\$90,750.0
	0550		EX MODIFIED TE WEARING SURFACE	Material			-1,201.198	\$85.00	(\$102,101.83

Pay Estimate Created Date: September 1, 2020

Progre	ss Esti 1	mate Number 0	Contract ID Prime Contra	200117-F0 ctor Parking Lo	-	Pay Period Start August 16, 2020         Original Contract Amount         \$3,235,828.           e, LLC Pay Period End September 1, 2020         Net Change Order Amount         \$0.00           Current Contract Amount         \$3,235,828.						
Project Number	Line No.	Item Description		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
J6S3319	0550		LATEX MODIFIED CONCRETE WEARING SURFACE			This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.		\$85.00	\$102,101.83			
Total									(\$482,269.90)			



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work						
J6S3319		Resurface and bridge rehabilitation	A	ST CHARLES	from Route 61 to I-70						
Totolo by	lob Numbo										

#### Totals by Job Numbers

J6S3319		This Estimate	Previous	To Date
Posted Item Pa	У	\$612,610.50	\$2,629,121.42	\$3,241,731.92
Gross Item Adj	ustments	(\$482,269.90)	(\$371,258.30)	(\$853,528.20)
	Gross Item Pay	\$130,340.60	\$2,257,863.12	\$2,388,203.72
Incentive		\$0.00	\$0.00	\$0.00
Disincentive		\$0.00	\$0.00	\$0.00
Liquidated Dan	nages	\$0.00	\$0.00	\$0.00
Other Contract	Adjustments	\$0.00	\$0.00	\$0.00



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5031010A, Project Item Line Number 0540, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5031010A, Project Item Line Number 0540, Material Set 5031010A96, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Working with a material rep to resolve the exception.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5031010A, Project Item Line Number 0540, Material Set 5031010A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with a material rep to resolve the exception.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5031010A, Project Item Line Number 0540, Material Set 5031010A96, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5031010A, Project Item Line Number 0540, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5031010A, Project Item Line Number 0540, Material Set 5031010A96, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5041000, Project Item Line Number 0040, Material Set 504100096, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5041000, Project Item Line Number 0040, Material Set 504100096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on the QC CRE20 report to resolve the exception.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5041000, Project Item Line Number 0040, Material Set 504100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on the QC CRE20 report to resolve the exception.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5041000, Project Item Line Number 0040, Material Set 504100096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	.Waiting on PAL approval from Jeff City.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5041000, Project Item Line Number 0040, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5052000, Project Item Line Number 0550, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Working with a material rep to resolve the exception.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6116010A, Project Item Line Number 0080, Material Set 6116010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6116010A, Project Item Line Number 0080, Material Set 6116010A96, Material 100510OPTLD1 - PCCP 1" Max LS/DO, Acceptance Action Generic 100510OPTLD1 is insufficient.	Waiting on the QC CRE20 report to resolve the exception.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6116010A, Project Item Line Number 0080, Material Set 6116010A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on the QC CRE20 report to resolve the exception.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6116010A, Project Item Line Number 0080, Material Set 6116010A96, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on the QC CRE20 report to resolve the exception.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131010, Project Item Line Number 0130, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on the QC CRE20 report to resolve the exception.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131010, Project Item Line Number 0130, Material Set 613101096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131015, Project Item Line Number 0170, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131015, Project Item Line Number 0170, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131017, Project Item Line Number 0180, Material Set 613101796, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131017, Project Item Line Number 0180, Material Set 613101796, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131017, Project Item Line Number 0180, Material Set 613101796, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131018, Project Item Line Number 0190, Material Set 613101896, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels,	Waiting on PAL approval from Jeff City.	dukesm1	Overridden



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 1039ERDBEP is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131018, Project Item Line Number 0190, Material Set 613101896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131018, Project Item Line Number 0190, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Item Overrun: Contract 200117-F06, Contract Project J6S3319, Project Item Line Number 0200, Contract Line Item Number 0200, Item 6139911, Minor Item.	Currently working on a change order to resolve the exception.	dukesm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200117-F06, Contract Project J6S3319, Project Item Line Number 0520, Contract Line Item Number 0520, Item 2169903, Minor Item.	Currently working on a change order to resolve the exception.	dukesm1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200117-F06, Contract Project J6S3319, Project Item Line Number 0620, Contract Line Item Number 0620, Item 7040117, Minor Item.	Currently working on a change order to resolve the exception.	dukesm1	Acknowledged

### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at the	time the I	Estimate wa	s Gener	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-F06	J6S3319	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$56,000.00	\$56,000.00
		0001	0020	2063000	CLASS 3 EXCAVATION	12.00	0.00	12.00	CUYD	4.00	\$75.00	\$300.00
		0001	0030	2153000	SHAPING SLOPES, CLASS III	5.00	0.00	5.00	100F	5.00	\$900.00	\$4,500.00
		0001	0040	5041000	CONCRETE APPROACH PAVEMENT	920.30	0.00	920.30	SQYD	920.30	\$75.00	\$69,022.50
		0001	0050	6094010	DRAIN BASIN	2.00	0.00	2.00	EA	0.00	\$4,400.00	\$0.00
		0001	0060	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	7.00	0.00	7.00	CUYD	0.00	\$27.00	\$0.00
		0001	0070	6096041	PLACING TYPE 1 ROCK DITCH LINER	7.00	0.00	7.00	CUYD	0.00	\$105.00 \$110.00	\$0.00
		0001	0080	6116010A	SLOPE PROTECTION	222.00	0.00	222.00	SQYD			\$12,320.00
		0001	0090	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARRELS)	2.00	0.00	2.00	EA	2.00	\$3,010.00	\$6,020.00
		0001	0100	6122020	REPLACEMENT SAND BARREL	3.00	0.00	3.00	EA	0.00	\$396.00	\$0.00
		0001	0110	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	2.00	\$687.00	\$1,374.00
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$6,000.00	\$12,000.00
		0001	0130	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	3,536.00	0.00	3,536.00	SQYD	3,536.00	\$165.00	\$583,440.00
		0001	0140	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	444.00	0.00	444.00	SQYD	0.00	\$20.00	\$0.00
		0001	0150	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	354.00	0.00	354.00	SQYD	0.00	\$2.50	\$0.00
		0001	0160	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	14,694.00	0.00	14,694.00	LF	14,694.00	\$3.00	\$44,082.00
		0001	0170	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	4,450.00	0.00	4,450.00	EA	4,450.00	\$5.75	\$25,587.50
		0001	0180	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	28.00	0.00	28.00	EA	28.00	\$3.75	\$105.00
		0001	0190	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	451.00	0.00	451.00	EA	451.00	\$2.45	\$1,104.95
		0001	0200	6139911	MISC.REMOVAL, FURNISHING AND PLACING HOT POLYMER CONCRETE PATCHING FOR CLASS A PARTIAL DEPTH PVMT REPAIR	401,792.00	0.00	401,792.00	LB	451,134.00	\$3.35	\$1,511,298.90
		0001	0210	6161005	CONSTRUCTION SIGNS	798.00	0.00	798.00	SQFT	619.43	\$8.00	\$4,955.44
		0001	0220	6161008	ADVANCED WARNING RAIL SYSTEM	22.00	0.00	22.00	EA	16.00	\$35.00	\$560.00
		0001 0230 6	6161009	FLAG ASSEMBLY	15.00	0.00	15.00	EA	0.00	\$25.00	\$0.00	
		0001	0240	6161025		364.00	0.00	364.00	EA	364.00	\$20.00	\$7,280.00
		0001	0250	6161030		8.00	0.00	8.00	EA	0.00	\$100.00	\$0.00
		0001	0260	6161033	DIRECTIONAL INDICATOR BARRICADE	44.00	0.00	44.00	EA	44.00	\$65.00	\$2,860.00
		0001	0270	6161040	FLASHING ARROW PANEL	3.00	0.00	3.00	EA	3.00	\$850.00	\$2,550.00
		0001	0280	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	0290	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,050.00	0.00	1,050.00	LF	0.00	\$21.94	\$0.00
		0001	0300	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,050.00	0.00	1,050.00	LF	1,050.00	\$7.02	\$7,369.95
		0001	0310	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$168,321.54	\$126,241.16
		0001	0320	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	3.00	0.00	3.00	EA	0.00	\$350.00	\$0.00
		0001	0330	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	5,511.00	0.00	5,511.00	LF	5,511.00	\$1.00	\$5,511.00
		0001	0340	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	8,663.00	0.00	8,663.00	LF	8,663.00	\$1.00	\$8,663.00
		0001	0350	6205440A	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	1.00	\$300.00	\$300.00
		0001	0360	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,220.00	0.00	6,220.00	LF	0.00	\$0.25	\$0.00
		0001	0370	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	9,952.00	0.00	9,952.00	LF	0.00	\$0.25	\$0.00
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	25,370.00	0.00	25,370.00	LF	15,858.00	\$0.75	\$11,893.50
		0001	0390	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	5.00	0.00	5.00	EA	5.00	\$100.00	\$500.00
		0001	0400	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$1,500.00	\$0.00
		0001	0410	8051000A	SEEDING - COOL SEASON MIXTURES	0.10	0.00	0.10	ACRE	0.00	\$10,000.00	\$0.00
		0001	0420	8061005	ROCK DITCH CHECK	60.00	0.00	60.00	LF	0.00	\$50.00	\$0.00
		0001	0430	8061016	SEDIMENT REMOVAL	8.00	0.00	8.00	CUYD	0.00	\$31.25	\$0.00



## Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-F06	J6S3319	0001	0440	8061019	SILT FENCE	405.00	0.00	405.00	LF	0.00	\$2.26	\$0.00
		0010	0450	6061060	MGS GUARDRAIL	213.00	0.00	213.00	LF	213.00	\$21.00	\$4,473.00
		0010	0460	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	2,650.00	0.00	2,650.00	LF	2,650.00	\$23.00	\$60,950.00
		0010	0470	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0010	0480	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,000.00	\$1,000.00
		0010	0490	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	5.00	0.00	5.00	EA	5.00	\$2,800.00	\$14,000.00
		0070	0500	2161000	SCARIFICATION OF BRIDGE DECK	3,003.00	0.00	3,003.00	SQYD	3,003.00	\$6.67	\$20,030.01
		0070	0510	2161503	REMOVAL OF EXISTING DECK REPAIR	25.00	0.00	25.00	SQFT	12.00	\$71.00	\$852.00
		0070	0520	2169903	MISC.Remove and Replace Barrier Curb	10.00	0.00	10.00	LF	11.00	\$350.00	\$3,850.00
		0070	0530	2169904	MISC.Removal of Existing Approach Slab	4,784.00	0.00	4,784.00	SQFT	4,784.00	\$6.00	\$28,704.00
		0070	0540	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	330.00	0.00	330.00	SQYD	330.00	\$275.00	\$90,750.00
		0070	0550	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	3,003.00	0.00	3,003.00	SQYD	3,003.00	\$85.00	\$255,255.00
		0070	0560	7031004	DIAMOND GRINDING	3,003.00	0.00	3,003.00	SQYD	0.00	\$6.32	\$0.00
		0070	0570	7039902	MISC.Pile Encasement	25.00	0.00	25.00	EA	25.00	\$2,300.00	\$57,500.00
		0070	0580	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	200.00	0.00	200.00	SQFT	0.00	\$15.00	\$0.00
		0070	0590	7040106	FULL DEPTH REPAIR	200.00	0.00	200.00	SQFT	0.00	\$40.00	\$0.00
		0070	0600	7040109	TOTAL SURFACE HYDRO DEMOLITION	3,003.00	0.00	3,003.00	SQYD	3,003.00	\$43.00	\$129,129.00
		0070	0610	7040113	CLEANING AND EPOXY COATING	2,116.00	0.00	2,116.00	SQFT	0.00	\$15.00	\$0.00
		0070	0620	7040117	MONOLITHIC DECK REPAIR	41.00	0.00	41.00	CUYD	74.00	\$700.00	\$51,800.00
	Project J	6S3319 - To	otal Value	Posted to D	Date as of Report Generated Date							\$3,241,731.90
200117-F06 Ove	erall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$3,241,731.90



Project: J6S3319

# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

## The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0130	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	8/28/20	8/31/20	3,536.00	SQYD		6+34		148+00		
0160	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	8/17/20	8/17/20	432.00	LF	Route A	112+00		120+00		
			8/18/20	9/1/20	495.00	LF		6+34		148+00		
			8/19/20	9/1/20	495.00	LF		6+34		148+00		
			8/24/20	8/31/20	828.00	LF		6+34		148+00		
			8/27/20	8/31/20	1,746.00	LF		120+00		148+00		
0170	6131015	5 DOWEL BAR (DRILLING, FURNISHING AND INST	8/17/20	8/17/20	130.00	EA	Route A	112+00		120+00		
			8/18/20	9/1/20	975.00	EA		6+34		148+00		
			8/19/20	9/1/20	975.00	EA		6+34		148+00		
			8/24/20	8/31/20	250.00	EA		6+34		148+00		
			8/27/20	8/31/20	530.00	EA		120+00		148+00		
0180	6131017	DOWEL BAR (FURNISH AND INSTALL WITH BASK	8/17/20	8/17/20	1.00	EA	Route A	112+00		120+00		
			8/18/20	9/1/20	5.00	EA		6+34		148+00		
			8/19/20	9/1/20	6.00	EA		6+34		148+00		
			8/24/20	8/31/20	2.00	EA		6+34		148+00		
			8/27/20	8/31/20	3.00	EA		120+00		148+00		
0190	6131018	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	8/17/20	8/17/20	22.00	EA	Route A	112+00		120+00		
			8/18/20	9/1/20	94.00	EA		6+34		148+00		
			8/19/20	9/1/20	93.00	EA		6+34		148+00		
			8/24/20	8/31/20	33.00	EA		6+34		148+00		
			8/27/20	8/31/20	33.00	EA		120+00	148+00			

 B/27/20
 8/

 The information below this line are details from Line Item agency views.
 No Agency View Details Exist



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0040	CONCRETE APPROACH PAVEMENT	Material	Туре	5	Jun 15, 2020	SYSTEM	(\$34,509.75)	
				6	Jul 1, 2020	SYSTEM	(\$34,509.75)	
				7	Jul 16, 2020	SYSTEM	(\$69,022.50)	
				8	Aug 4, 2020	SYSTEM	(\$69,022.50)	
				9	Aug 18, 2020	SYSTEM	(\$69,022.50)	
				10	Sep 2, 2020	SYSTEM	(\$69,022.50)	
			- Total				(\$345,109.50)	
	Material - Total						(\$345,109.50)	
	CONCRETE APPROACH PAVEMENT	MaterialCredit		6	Jul 1, 2020	SYSTEM	\$34,509.75	
				7	Jul 16, 2020	SYSTEM	\$34,509.75	
				8	Aug 4, 2020	SYSTEM	\$69,022.50	
				9	Aug 18, 2020	SYSTEM	\$69,022.50	
			- Total	10	Sep 2, 2020	SYSTEM	\$69,022.50 \$276,087.00	
			- 10(a)					
	MaterialCredit - Total						\$276,087.00	
0040 -	Total						(\$69,022.50)	
0080	SLOPE PROTECTION	Material		8	Aug 4, 2020	SYSTEM	(\$12,320.00)	
				9	Aug 18, 2020	SYSTEM	(\$12,320.00)	
			- Total	10	Sep 2, 2020	SYSTEM	(\$12,320.00)	
			- 10(d)				(\$36,960.00)	
	Material - Total			1	1		(\$36,960.00)	
	SLOPE PROTECTION	MaterialCredit		9	Aug 18, 2020	SYSTEM	\$12,320.00	
			- Total	10	Sep 2, 2020	SYSTEM	\$12,320.00	
			- Total				\$24,640.00	
	MaterialCredit - Total						\$24,640.00	
0080 -							(\$12,320.00)	
0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		10	Sep 2, 2020	SYSTEM	(\$583,440.00)	
			- Total				(\$583,440.00)	
	Material - Total						(\$583,440.00)	
0130 -	Total						(\$583,440.00)	
0170	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		9	Aug 18, 2020	SYSTEM	(\$9,890.00)	
	PAVEMENT REPAIR			10	Sep 2, 2020	SYSTEM	(\$25,587.50)	
				10	Sep 2, 2020	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				(\$9,890.00)	
	Material - Total						(\$9,890.00)	
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	MaterialCredit		10	Sep 2, 2020	SYSTEM	\$9,890.00	
	PAVEMENT REPAIR		- Total				\$9,890.00	
			- Fotan				\$3,030.00	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Line	Description	Adjustment Type	Adjustment Type		Date	By	Amount	reliidiks
0170	MaterialCredit - Total						\$9,890.00	
0170 -	Total						\$0.00	
0180	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR	Material		9	Aug 18, 2020	SYSTEM	(\$45.00)	
	FULL DEPTH PAVEMENT REPAIR			10	Sep 2, 2020	SYSTEM	(\$105.00)	
				10	Sep 2, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
			- Total				(\$45.00)	
	Material - Total						(\$45.00)	
	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		10	Sep 2, 2020	SYSTEM	\$45.00	
			- Total				\$45.00	
	MaterialCredit - Total						\$45.00	
0180 -	Total						\$0.00	
0190	TIE BAR (DRILLING, FURNISHING AND	Material		9	Aug 18,	SYSTEM	(\$485.10)	
	INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)			10	2020 Sep 2,	SYSTEM	(\$1,104.95)	
				10	2020 Sep 2,	SYSTEM	\$1,104.95	This adjustment offsets the original system-generated Overrun
					2020			Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
			- Total				(\$485.10)	
	Material - Total						(\$485.10)	
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	MaterialCredit		10	Sep 2, 2020	SYSTEM	\$485.10	
	- Total						\$485.10	
	MaterialCredit - Total						\$485.10	
0190 -	Total						\$0.00	
0200	MISC. REMOVAL, FURNISHING AND		Overrun	8	Aug 4,	SYSTEM	(\$117,819.50)	
	PLACING HOT POLYMER CONCRETE PATCHING FOR CLASS A PARTIAL DEPTH PVMT REPAIR			9	2020 Aug 18,	SYSTEM	(\$47,476.20)	
				a fa l	2020		(\$405.005.70)	
			Overrun - T	οται			(\$165,295.70)	
	Overrun - Total						(\$165,295.70)	
0200 - 0330	Total TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		3	May 18, 2020	SYSTEM	(\$165,295.70) (\$2,591.00)	
			- Total		2020		(\$2,591.00)	
	Material - Total		Total				(\$2,591.00)	
	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	MaterialCredit		4	Jun 2, 2020	SYSTEM	\$2,591.00	
			- Total				\$2,591.00	
	MaterialCredit - Total						\$2,591.00	
0330 -							\$0.00	
0330 -	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		3	May 18, 2020	SYSTEM	(\$4,163.00)	
	,		- Total				(\$4,163.00)	
	Material - Total						(\$4,163.00)	
	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	MaterialCredit		4	Jun 2, 2020	SYSTEM	\$4,163.00	
			- Total				\$4,163.00	
	MaterialCredit - Total						\$4,163.00	
0340 -							\$0.00	
		Motorial		2	Mey 10	OVOTEN		
0350	TEMPORARY NON-REMOVABLE	watella		3	May 18,	SYSTEM	(\$300.00)	



	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0350	MARKING TAPE LEFT/RIGHT ARROW	Material	Туре		2020			
13:50	WARKING TAFE LEFT/RIGHT ARROW	Waterial	- Total		2020		(\$300.00)	
	Material - Total		- 10(a)		(\$300.00)			
	TEMPORARY NON-REMOVABLE	MaterialCredit		4	Jun 2,	SYSTEM	\$300.00	
	MARKING TAPE LEFT/RIGHT ARROW	Watenaicredit		4	2020	STOTEM	\$300.00	
			- Total				\$300.00	
	MaterialCredit - Total						\$300.00	
0350 -	Total				_		\$0.00	
0450	MGS GUARDRAIL	Construction Stockpile		2	May 4, 2020	SYSTEM	\$2,270.58	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 4, 2020	SYSTEM	(\$2,270.58)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
_	Construction Stockpile - Total						\$0.00	
	- Total			-			\$0.00	
)460	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Construction Stockpile		2	May 4, 2020	SYSTEM	\$33,204.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Jun 15, 2020	SYSTEM	(\$11,602.78)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jul 16, 2020	SYSTEM	(\$20,048.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		- Total	0	Aug 4, 2020	STSTEM	(\$1,553.72) \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
	Construction Stockpile - Total		- 10141			\$0.00		
1460	· Total						\$0.00	
0460 -	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)			2	May 4,	SYSTEM	\$6,200.00	Payment Estimate Item Adjustment generated Stockpile
		Stockpile		5	2020 Jun 15, 2020	SYSTEM	(\$3,100.00)	Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jul 16, 2020	SYSTEM	(\$3,100.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total				\$0.00			
0470	- Total						\$0.00	
0480	MGS END ANCHOR	Construction Stockpile		2	May 4, 2020	SYSTEM	\$535.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jul 16, 2020	SYSTEM	(\$535.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total	7		SYSTEM	(\$535.00) \$0.00	Payment Estimate Item Adjustment generated Stockpile
	Construction Stockpile - Total		- Total	7		SYSTEM	(, , ,	Payment Estimate Item Adjustment generated Stockpile
0480 -	Construction Stockpile - Total Total		- Total	7		SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile
		Construction Stockpile	- Total	2		SYSTEM	\$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile
	Total TYPE A CRASHWORTHY END TERMINAL		- Total	2 5	2020 May 4, 2020 Jun 15, 2020	SYSTEM	\$0.00 \$0.00 \$7,550.00 (\$1,510.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	Total TYPE A CRASHWORTHY END TERMINAL			2	2020 May 4, 2020 Jun 15,	SYSTEM	\$0.00 \$0.00 \$7,550.00 (\$1,510.00) (\$6,040.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile
	Total TYPE A CRASHWORTHY END TERMINAL (MASH)		- Total	2 5	2020 May 4, 2020 Jun 15, 2020 Aug 4,	SYSTEM	\$0.00 \$0.00 \$7,550.00 (\$1,510.00) (\$6,040.00) \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0490	Total TYPE A CRASHWORTHY END TERMINAL (MASH)			2 5	2020 May 4, 2020 Jun 15, 2020 Aug 4,	SYSTEM	\$0.00 \$0.00 \$7,550.00 (\$1,510.00) (\$6,040.00) \$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0490	Total TYPE A CRASHWORTHY END TERMINAL (MASH)			2 5	2020 May 4, 2020 Jun 15, 2020 Aug 4, 2020	SYSTEM	\$0.00 \$0.00 \$7,550.00 (\$1,510.00) (\$6,040.00) \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
0490 0490 -	Total TYPE A CRASHWORTHY END TERMINAL (MASH) Construction Stockpile - Total Total	Stockpile	- Total	2 5 8	2020 May 4, 2020 Jun 15, 2020 Aug 4, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$7,550.00 (\$1,510.00) (\$6,040.00) \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm overridding Payment Estimate Exception 5 on the current
0490	Total TYPE A CRASHWORTHY END TERMINAL (MASH) Construction Stockpile - Total Total	Stockpile	- Total	2 5 8	2020 May 4, 2020 Jun 15, 2020 Aug 4, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$7,550.00 (\$1,510.00) (\$6,040.00) \$0.00 \$0.00 \$0.00 (\$350.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm



ine.	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
520	Overrun - Total						(\$350.00)	
520 -	Total						(\$350.00)	
540	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		5	Jun 15, 2020	SYSTEM	(\$45,375.00)	
				6	Jul 1, 2020	SYSTEM	(\$45,375.00)	
				7	Jul 16, 2020	SYSTEM	(\$90,750.00)	
				8	Aug 4, 2020	SYSTEM	(\$90,750.00)	
				9	Aug 18, 2020	SYSTEM	(\$90,750.00)	
				10	Sep 2, 2020	SYSTEM	(\$90,750.00)	
				10	Sep 2, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrur Payment Estimate Item Adjustment (0013) due to user dukesn overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				(\$363,000.00)	
	Material - Total						(\$363,000.00)	
	BRIDGE APPROACH SLAB (MAJOR ROAD)	MaterialCredit		6	Jul 1, 2020	SYSTEM	\$45,375.00	
				7	Jul 16, 2020	SYSTEM	\$45,375.00	
				8	Aug 4, 2020	SYSTEM	\$90,750.00	
				9	Aug 18, 2020	SYSTEM	\$90,750.00	
			- Total	10	Sep 2, 2020	SYSTEM	\$90,750.00	
	MaterialCredit - Total		- TOLAI				\$363,000.00	
540	Total						\$363,000.00 \$0.00	
550	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		4	Jun 2, 2020	SYSTEM	(\$127,627.50)	
				5	Jun 15, 2020	SYSTEM	(\$127,627.50)	
				6	Jul 1, 2020	SYSTEM	(\$255,255.00)	
				7	Jul 16, 2020	SYSTEM	(\$102,101.83)	
				8	Aug 4, 2020		(\$102,101.83)	
				8	Aug 4, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesr overridding Payment Estimate Exception 17 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$102,101.83)	
				9	Aug 18, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrur Payment Estimate Item Adjustment (0011) due to user brookw overridding Payment Estimate Exception 16 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$102,101.83)	
				10	Sep 2, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overru Payment Estimate Item Adjustment (0014) due to user dukes overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				(\$612,611.83)	
	Material - Total						(\$612,611.83)	
	LATEX MODIFIED CONCRETE WEARING	MaterialCredit		5	Jun 15, 2020	SYSTEM	\$127,627.50	
	SURFACE				2020			



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0550	LATEX MODIFIED CONCRETE WEARING SURFACE	MaterialCredit		7	Jul 16, 2020	SYSTEM	\$255,255.00	
				8	Aug 4, 2020	SYSTEM	\$102,101.83	
			- Total			\$612,611.83		
	MaterialCredit - Total						\$612,611.83	
0550 -	Total						\$0.00	
0620	MONOLITHIC DECK REPAIR	Overrun	Overrun	8	Aug 4, 2020	SYSTEM	(\$23,100.00)	
			Overrun - T	otal			(\$23,100.00)	
	Overrun - Total				(\$23,100.00)			
0620 -	Total				(\$23,100.00)			
Overa	ıll - Total				(\$853,528.20)			