

Pay Estimate Created Date: October 1, 2020

Progress Estimate Number 12		Contract ID Prime Contractor	200117-H07 Apex Paving Co.	Pay Period Start Pay Period End	September 16, 2020 September 30, 2020		\$8,709,119.25 \$262,087.35 \$8,971,206.60
Approval Date	Date						By User
October 1, 2020			Generated and Ap	proved (and should	be considered Draft	at the Project Office Level by	woodsk1
October 1, 2020		Rev	iewed and Approv	ed (and should be c	onsidered Draft) at th	e Resident Engineer Level by	plottk1
October 2, 2020			Re	eviewed and Approv	ed at the Central Off	ce Controllers Office Level by	greggd1
Original Comp	pletion Date Current Completion Date Actual Completion Date % of Current Contract Amou					nt Complete	
July 1, 2021 July 1, 2021						30.05%	

No Milestones Exist for Contract

Contract Total Pag	y For Estimate No. 12			
		This Estimate	Previous	To Date
200117-H07				
	Total Posted Items Pay	\$284,903.32	\$2,411,034.41	\$2,695,937.73
	Gross Item Adjustments	(\$27,474.75)	\$198,616.45	\$171,141.70
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$2,609,650.86	\$2,867,079.43
Contract Total Pay	yable This Estimate:	\$257,428.57		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3553	0100	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$185.160	31.1	\$5,758.48
	0130	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$6.000	156	\$936.00
	0140	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$10.000	74	\$740.00
	0180	6161005	CONSTRUCTION SIGNS	SQFT	\$6.500	222	\$1,443.00
	0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$7.250	2,956	\$21,431.00
	0350	6061060	MGS GUARDRAIL	LF	\$20.000	1,425	\$28,500.00
	0370	6061080	MGS END ANCHOR	EA	\$1,000.000	6	\$6,000.00
	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$2,700.000	6	\$16,200.00
	0430	7040104	HALF-SOLE REPAIR	SQFT	\$97.740	65	\$6,353.10
	0480	7040104	HALF-SOLE REPAIR	SQFT	\$96.760	8	\$774.08
	0530	7040104	HALF-SOLE REPAIR	SQFT	\$97.740	613	\$59,914.62
	0580	7040104	HALF-SOLE REPAIR	SQFT	\$98.900	545	\$53,900.50
	0780	7040104	HALF-SOLE REPAIR	SQFT	\$107.410	112	\$12,029.92
	0820	7040104	HALF-SOLE REPAIR	SQFT	\$107.410	372	\$39,956.52
	5002	6161010	RELOCATED SIGNS	SQFT	\$6.830	268	\$1,830.44
Project J9	3553 - Tot	al					\$255,767.66
J9S3571	0850	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	TONS	\$35.590	458.13	\$16,304.85
	0900	4134000	BITUMINOUS FOG SEAL	GAL	\$4.150	2,267	\$9,408.05
	1150	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	SQFT	\$311.160	11	\$3,422.76
Project J9	S3571 - To	tal					\$29,135.66
Overall - T	otal						\$284,903.32

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item Adjustments This Estimate

Revision 4/1/2020 Page 1 of 49



Pay Estimate Created Date: October 1, 2020

Progress Estimate Number	Contract ID	200117-H07	Pay Period Start	September 16, 2020	Original Contract Amount	\$8,709,119.25
12	Prime Contractor	Apex Paving Co.	Pay Period End	September 30, 2020	Net Change Order Amount	
					Current Contract Amount	\$8,971,206.60

	1.5	H D	A disease	041	0	A .!!	1 30 - 11	A .II 1
roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
13553	0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-489.9	\$185.16	(\$90,709.88)
	0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	489.9	\$185.16	\$90,709.88
	0110	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-10	\$10.00	(\$100.00)
	0110	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	10	\$10.00	\$100.00
	0120	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material			-10	\$10.00	(\$100.00)
	0120	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	10	\$10.00	\$100.00
	0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-822	\$10.00	(\$8,220.00)
	0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	822	\$10.00	\$8,220.00
	0150	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			-1	\$10.00	(\$10.00)
	0150	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	1	\$10.00	\$10.00
	0350	MGS GUARDRAIL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$15,204.75)
	0370	MGS END ANCHOR	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$3,210.00)
	0380	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$9,060.00)
	0410	SEAL COAT AGGREGATE, GRADE B1	Material			-265	\$5.00	(\$1,325.00)
	0410	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	265	\$5.00	\$1,325.00
	0420	CURB BLOCKOUT	Material			-170	\$196.14	(\$33,343.80)
	0420	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item	170	\$196.14	\$33,343.80

Revision 4/1/2020 Page 2 of 49



Pay Estimate Created Date: October 1, 2020

	Contract ID				Original Contract Amount	
12	Prime Contractor	Apex Paving Co.	Pay Period End	September 30, 2020	Net Change Order Amount	\$262,087.35
12					Current Contract Amount	\$8,971,206.60

oject mber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3553					Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.			
	0430	HALF-SOLE REPAIR	Material			-755	\$97.74	(\$73,793.70
	0430	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	755	\$97.74	\$73,793.70
	0460	SEAL COAT AGGREGATE, GRADE B1	Material			-288	\$5.00	(\$1,440.00
	0460	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	288	\$5.00	\$1,440.00
	0470	CURB BLOCKOUT	Material			-185	\$193.61	(\$35,817.85
	0470	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	185	\$193.61	\$35,817.85
	0480	HALF-SOLE REPAIR	Material			-723	\$96.76	(\$69,957.48
	0480	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	723	\$96.76	\$69,957.48
	0520	CURB BLOCKOUT	Material			-170	\$196.14	(\$33,343.80
	0520	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	170	\$196.14	\$33,343.80
	0530	HALF-SOLE REPAIR	Material			-853	\$97.74	(\$83,372.22
	0530	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.	853	\$97.74	\$83,372.22
	0570	CURB BLOCKOUT	Material			-155	\$199.15	(\$30,868.25
	0570	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	155	\$199.15	\$30,868.25
	0780	HALF-SOLE REPAIR	Material			-136	\$107.41	(\$14,607.76
	0780	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.	136	\$107.41	\$14,607.76
	0820	HALF-SOLE REPAIR	Material			-400	\$107.41	(\$42,964.00
	0820	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.	400	\$107.41	\$42,964.00

Revision 4/1/2020 Page 3 of 49



Pay Estimate Created Date: October 1, 2020

Progress Estimate Number	Contract ID				Original Contract Amount	, ,
12	Prime Contractor	Apex Paving Co.	Pay Period End	September 30, 2020	Net Change Order Amount	\$262,087.35
12					Current Contract Amount	\$8,971,206.60

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3571	0850	MISC.	Material			-1,817.86	\$35.59	(\$64,697.64)
	0850	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,817.86	\$35.59	\$64,697.64
	0900	BITUMINOUS FOG SEAL	Material			-4,800	\$4.15	(\$19,920.00)
	0900	BITUMINOUS FOG SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	4,800	\$4.15	\$19,920.00
	0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material			-1,212	\$2.00	(\$2,424.00)
	0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	1,212	\$2.00	\$2,424.00
	1000	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material			-2,000	\$2.00	(\$4,000.00)
	1000	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	2,000	\$2.00	\$4,000.00
	1010	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material			-24	\$10.00	(\$240.00)
	1010	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	24	\$10.00	\$240.00
	1020	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-114,312	\$0.11	(\$12,574.32)
	1020	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	114,312	\$0.11	\$12,574.32
	1030	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-31,999	\$0.11	(\$3,519.89)
	1030	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	31,999	\$0.11	\$3,519.89
	1140	SEAL COAT AGGREGATE, GRADE B1	Material			-287	\$5.00	(\$1,435.00)
	1140	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 3 on	287	\$5.00	\$1,435.00

Revision 4/1/2020 Page 4 of 49



Pay Estimate Created Date: October 1, 2020

Progr		timate Number 12	Contract ID Prime Cont	ractor Apex Paving Co. Pay Period End September 30, 2020 Net			inal Contract Amount \$8,709,119.25 Change Order Amount \$262,087.35 ent Contract Amount \$8,971,206.60		
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3571						the current Payment Estimate.			
	1150 SUPERSTRUCTURE REPAIR (UNFORMED)		Material			-31	\$311.16	(\$9,645.96	
	1150		STRUCTURE JNFORMED)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 43 on the current Payment Estimate.	31	\$311.16	\$9,645.96
	1160	SLAB EDGE REPAIR (BRIDGES)		Material			-60	\$245.39	(\$14,723.40
	1160	SLAB E	OGE REPAIR (BRIDGES)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 54 on the current Payment Estimate.	60	\$245.39	\$14,723.40
Total									(\$27 474 7

Revision 4/1/2020 Page 5 of 49



					Co	ontract Project Information	ו
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9I3553	FAF 60-4(86)	Resurface	60	SCOTT	from I-57 to Spring Cree	ek	
J9S3571	FAS S703(31)	Resurface	69	MISSISSIPPI	from I-57 to Bridge K09	50	
Γotals by .	Job Numbe	rs					
J9I3553		d Item Pay Item Adjustm		s Item Pay	This Estimate \$255,767.66 (\$27,474.75) \$228,292.91	Previous \$766,086.34 \$128,168.50 \$894,254.84	To Date \$1,021,854.00 \$100,693.75 \$1,122,547.75
	Liquid	tive centive lated Damages Contract Adju		r	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J9S3571		d Item Pay Item Adjustm		s Item Pay	This Estimate \$29,135.66 \$0.00 \$29,135.66	Previous \$1,644,948.07 \$70,447.95 \$1,715,396.02	To Date \$1,674,083.73 \$70,447.95 \$1,744,531.68
	Liquid	tive centive lated Damages Contract Adiu			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 6 of 49



Exceptions (Discrepancies) This Estimate Period

Fyrantiana / Diagramanaiaa			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 3049910, Project Item Line Number 0850, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 4094011, Project Item Line Numbe 0410, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.		woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 4094011, Project Item Line Number 1140, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 4094011, Project Item Line Numbo 0460, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.		woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 4134000, Project Item Line Number 0900, Material Set 413400096, Material 1015EACSS1H - Emulsified Asphalt CSS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.		woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	er No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131010, Project Item Line Numbe 0100, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	er No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131012, Project Item Line Number 0110, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Property No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131013, Project Item Line Numbe 0120, Material Set 613101396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131015, Project Item Line Numbe 0140, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 6131017, Project Item Line Numbe 0150, Material Set 613101796, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6205301B, Project Item Line Number 0990, Material Set 6205301B96, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6205303B, Project Item Line Number 1000, Material Set 6205303B96, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6205309, Project Item Line Number 1010, Material Set 620530996, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6206000C, Project Item Line Number 1020, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6206000C, Project Item Line Number 1020, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6206001C, Project Item Line Number 1030, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 6206001C, Project Item Line Number 1030, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Numbo 0570, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.		woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @		woodsk1	Overridden

Revision 4/1/2020 Page 7 of 49



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 1055CMMLDST1D is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0420, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0520, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J913553, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 7040103, Project Item Line Number 1150, Material Set 704010396, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number 0780, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0430, Material Set 704010496, Material 0500XX - Concrete Plant Inspection Review, Acceptance Action Generic 0500XX is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3553, Item 7040104, Project Item Line Number	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 8 of 49



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
0820, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0530, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 0500XX - Concrete Plant Inspection Review, Acceptance Action Generic 0500XX is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3553, Item 7040104, Project Item Line Number 0480, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3571, Item 7040107, Project Item Line Number 1160, Material Set 704010796, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 9 of 49



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H07	J9I3553	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.26	\$36,000.00	\$9,504.00
		0001	0020	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	6,032.50	0.00	6,032.50	TONS	0.00	\$32.62	\$0.00
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	17.00	0.00	17.00	TONS	0.00	\$18.91	\$0.00
		0001	0040	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	16,232.80	0.00	16,232.80	TONS	0.00	\$56.39	\$0.00
		0001	0050	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	62,977.90	0.00	62,977.90	TONS	0.00	\$57.84	\$0.00
		0001	0060	4071005	TACK COAT	60,125.00	0.00	60,125.00	GAL	0.00	\$2.14	\$0.00
		0001	0070	4134000	BITUMINOUS FOG SEAL	5,508.00	0.00	5,508.00	GAL	0.00	\$5.11	\$0.00
		0001	0800	6083003	3 IN. CONCRETE MEDIAN STRIP	2,330.00	0.00	2,330.00	SQYD	0.00	\$67.62	\$0.00
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0100	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	642.70	0.00	642.70	SQYD	566.80	\$185.16	\$104,948.69
		0001	0110	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	64.00	0.00	64.00	SQYD	10.00	\$10.00	\$100.00
		0001	0120	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	64.00	0.00	64.00	SQYD	10.00	\$10.00	\$100.00
		0001	0130	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	2,204.00	0.00	2,204.00	LF	1,665.00	\$6.00	\$9,990.00
		0001	0140	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,180.00	0.00	1,180.00	EA	822.00	\$10.00	\$8,220.00
		0001	0150	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	10.00	0.00	10.00	EA	1.00	\$10.00	\$10.00
		0001	0160	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	13.10	0.00	13.10	TONS	0.00	\$532.33	\$0.00
		0001	0170	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	28.00	0.00	28.00	SQYD	0.00	\$103.80	\$0.00
		0001	0180	6161005	CONSTRUCTION SIGNS	3,888.00	0.00	3,888.00	SQFT	1,778.00	\$6.50	\$11,557.00
		0001	0190	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$45.00	\$0.00
		0001	0200	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	0.00	\$20.00	\$0.00
		0001	0210	6161025	CHANNELIZER (TRIM LINE)	712.00	0.00	712.00	EA	262.00	\$15.00	\$3,930.00
		0001	0220	6161030	TYPE III MOVEABLE BARRICADE	45.00	0.00	45.00	EA	0.00	\$100.00	\$0.00
		0001	0230	6161033	DIRECTIONAL INDICATOR BARRICADE	133.00	0.00	133.00	EA	76.00	\$35.00	\$2,660.00
		0001	0240	6161040	FLASHING ARROW PANEL	8.00	0.00	8.00	EA	4.00	\$400.00	\$1,600.00
		0001	0250	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0260	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$208,790.05	\$104,395.02
		0001	0270	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	205,637.00	0.00	205,637.00	LF	0.00	\$0.23	\$0.00
		0001	0280	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	161,998.00	0.00	161,998.00	LF	0.00	\$0.23	\$0.00
		0001	0290	6205906A	12 IN, WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,400.00	0.00	2,400.00	LF	0.00	\$1.00	\$0.00
		0001	0300	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$15,000.00	\$0.00
		0001	0310	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	18,810.00	0.00	18,810.00	SQYD	1,954.00	\$6.49	\$12,681.46
		0001	0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	22,495.00	0.00	22,495.00	SQYD	11,824.00	\$7.25	\$85,724.00
		0001	0330	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	3,038.00	0.00	3,038.00	STA	0.00	\$18.75	\$0.00
		0001	0340	7034001	CLASS B-1 CONCRETE	3.30	0.00	3.30	CUYD	0.00	\$2,400.00	\$0.00
		0010	0350	6061060	MGS GUARDRAIL	8,050.00	0.00	8,050.00	LF	3,125.00	\$20.00	\$62,500.00
		0010	0360	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	24.00	0.00	24.00	EA	8.00	\$2,900.00	\$23,200.00
		0010	0370	6061080	MGS END ANCHOR	6.00	0.00	6.00	EA	6.00	\$1,000.00	\$6,000.00
		0010	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	30.00	0.00	30.00	EA	14.00	\$2,700.00	\$37,800.00
		0040	0390	9031220	PIPE POSTS	820.00	0.00	820.00	LB	0.00	\$6.00	\$0.00
		0070	0400	4091048	EMULSIFIED ASPHALT, SEAL COAT	106.00	0.00	106.00	GAL	106.00	\$5.00	\$530.00
		0070	0410	4094011	SEAL COAT AGGREGATE, GRADE B1	265.00	0.00	265.00	SQYD	265.00	\$5.00	\$1,325.00
		0070	0420	7034600	CURB BLOCKOUT	170.00	0.00	170.00	LF	170.00	\$196.14	\$33,343.80
		0070	0430	7040104	HALF-SOLE REPAIR	240.00	515.00	755.00	SQFT	755.00	\$97.74	\$73,793.70
		0070	0440	7040113	CLEANING AND EPOXY COATING	584.00	0.00	584.00	SQFT	584.00	\$13.00	\$7,592.00

Revision 4/1/2020 Page 10 of 49



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ct Proje RACT No.			Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
7 J9I355	3 0071	0450	4091048	EMULSIFIED ASPHALT, SEAL COAT	115.00	0.00	115.00	GAL	115.00	\$5.00	\$575.00
	0071	0460	4094011	SEAL COAT AGGREGATE, GRADE B1	288.00	0.00	288.00	SQYD	288.00	\$5.00	\$1,440.00
	0071	0470	7034600	CURB BLOCKOUT	185.00	0.00	185.00	LF	185.00	\$193.61	\$35,817.85
	0071	0480	7040104	HALF-SOLE REPAIR	260.00	463.00	723.00	SQFT	723.00	\$96.76	\$69,957.48
	0071	0490	7040113	CLEANING AND EPOXY COATING	628.00	0.00	628.00	SQFT	628.00	\$13.00	\$8,164.00
	0072	0500	4091048	EMULSIFIED ASPHALT, SEAL COAT	106.00	0.00	106.00	GAL	0.00	\$5.00	\$0.00
	0072	0510	4094011	SEAL COAT AGGREGATE, GRADE B1	265.00	0.00	265.00	SQYD	0.00	\$5.00	\$0.00
	0072	0520	7034600	CURB BLOCKOUT	170.00	0.00	170.00	LF	170.00	\$196.14	\$33,343.80
	0072	0530	7040104	HALF-SOLE REPAIR	240.00	613.00	853.00	SQFT	853.00	\$97.74	\$83,372.22
	0072	0540	7040113	CLEANING AND EPOXY COATING	584.00	0.00	584.00	SQFT	0.00	\$13.00	\$0.00
	0073	0550	4091048	EMULSIFIED ASPHALT, SEAL COAT	96.00	0.00	96.00	GAL	0.00	\$5.00	\$0.00
	0073	0560	4094011	SEAL COAT AGGREGATE, GRADE B1	241.00	0.00	241.00	SQYD	0.00	\$5.00	\$0.00
	0073	0570	7034600	CURB BLOCKOUT	155.00	0.00	155.00	LF	155.00	\$199.15	\$30,868.25
	0073	0580	7040104	HALF-SOLE REPAIR	220.00	545.00	765.00	SQFT	765.00	\$98.90	\$75,658.50
	0073	0590	7040113	CLEANING AND EPOXY COATING	534.00	0.00	534.00	SQFT	0.00	\$13.00	\$0.00
	0073	0600	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	56.00	0.00	56.00	LF	0.00	\$325.00	\$0.00
	0074			CONCRETE							
	0074	0610	2169903	MISC.Remove and Replace Curb	16.00	0.00	16.00	LF	0.00	\$300.00	\$0.00
	0074	0620	4091048	EMULSIFIED ASPHALT, SEAL COAT	348.00	0.00	348.00	GAL	0.00	\$5.00	\$0.00
	0074	0630	4094011	SEAL COAT AGGREGATE, GRADE B1	870.00	0.00	870.00	SQYD	0.00	\$5.00	\$0.00
	0074	0640	7034214	CLASS B-2 CONCRETE	5.60	0.00	5.60	CUYD	0.00	\$5,218.44	\$0.00
	0074	0650	7034600	CURB BLOCKOUT	560.00	0.00	560.00	LF	0.00	\$181.01	\$0.00
	0074	0660	7040104	HALF-SOLE REPAIR	230.00	0.00	230.00	SQFT	0.00	\$98.30	\$0.00
	0074	0670	7040113	CLEANING AND EPOXY COATING	1,971.00	0.00	1,971.00	SQFT	0.00	\$13.00	\$0.00
	0074	0680	7101000	REINFORCING STEEL (EPOXY COATED)	1,820.00	0.00	1,820.00	LB	0.00	\$5.00	\$0.00
	0074	0690	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
	0074	0700	7174001	PREFORMED SILICONE OR EPDM EXPANSION JOINT SYSTEM	56.00	0.00	56.00	LF	0.00	\$75.00	\$0.00
	0075	0710	4091048	EMULSIFIED ASPHALT, SEAL COAT	162.00	0.00	162.00	GAL	0.00	\$5.00	\$0.00
	0075	0720	4094011	SEAL COAT AGGREGATE, GRADE B1	406.00	0.00	406.00	SQYD	0.00	\$5.00	\$0.00
	0075	0730	7034600	CURB BLOCKOUT	261.00	0.00	261.00	LF	0.00	\$189.97	\$0.00
	0075	0740	7040104	HALF-SOLE REPAIR	370.00	0.00	370.00	SQFT	0.00	\$98.22	\$0.00
	0075	0750	7040113	CLEANING AND EPOXY COATING	1,100.00	0.00	1,100.00	SQFT	0.00	\$13.00	\$0.00
	0076	0760	4091048	EMULSIFIED ASPHALT, SEAL COAT	185.00	0.00	185.00	GAL	0.00	\$5.00	\$0.00
	0076	0770	4094011	SEAL COAT AGGREGATE, GRADE B1	463.00	0.00	463.00	SQYD	0.00	\$5.00	\$0.00
	0076	0780	7040104	HALF-SOLE REPAIR	400.00	0.00	400.00	SQFT	136.00	\$107.41	\$14,607.76
	0076	0790	7040113	CLEANING AND EPOXY COATING	989.00	0.00	989.00	SQFT	0.00	\$13.00	\$0.00
	0077	0800	4091048	EMULSIFIED ASPHALT, SEAL COAT	185.00	0.00	185.00	GAL	0.00	\$5.00	\$0.00
	0077	0810	4094011	SEAL COAT AGGREGATE, GRADE B1	463.00	0.00	463.00	SQYD	0.00	\$5.00	\$0.00
	0077	0820	7040104	HALF-SOLE REPAIR	400.00	0.00	400.00	SQFT	400.00	\$107.41	\$42,964.00
	0077	0830	7040113	CLEANING AND EPOXY COATING	989.00	0.00	989.00	SQFT	0.00	\$13.00	\$0.00
	0001	5001	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	0.00	4.00	4.00	EA	0.00	\$2,362.50	\$0.00
	0001	5002	6161010	RELOCATED SIGNS	0.00	268.00	268.00	SQFT	268.00	\$6.83	\$1,830.44
	0001	5003	6129902	MISC.TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)		22,800.00	22,800.00	EA	14,750.00	\$1.00	\$14,750.00
Proied				ate as of Report Generated Date							\$1,021,853.97
J9S35		0840	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,600.00	\$2,600.00
	0001	0850	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	2,161.00	0.00	2,161.00	TONS	1,817.86	\$35.59	\$64,697.64

Revision 4/1/2020 Page 11 of 49



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-H07	J9S3571	0001	0870	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	3,194.60	0.00	3,194.60	TONS	3,194.60	\$56.26	\$179,728.20
		0001	0880	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	17,210.20	0.00	17,210.20	TONS	17,169.60	\$60.51	\$1,038,932.50
		0001	0890	4071005	TACK COAT	14,965.00	0.00	14,965.00	GAL	12,730.00	\$2.14	\$27,242.20
		0001	0900	4134000	BITUMINOUS FOG SEAL	2,033.00	3,767.00	5,800.00	GAL	4,800.00	\$4.15	\$19,920.00
		0001	0910	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	4.00	\$250.00	\$1,000.00
		0001	0920	6161005	CONSTRUCTION SIGNS	2,364.00	0.00	2,364.00	SQFT	2,364.00	\$6.50	\$15,366.00
		0001	0930	6161009	FLAG ASSEMBLY	7.00	0.00	7.00	EA	7.00	\$20.00	\$140.00
		0001	0940	6161025	CHANNELIZER (TRIM LINE)	186.00	0.00	186.00	EA	40.00	\$15.00	\$600.00
		0001	0950	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0960	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$8,400.00	\$8,400.00
		0001	0970	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	2.00	0.00	2.00	EA	2.00	\$1,800.00	\$3,600.00
		0001	0980	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$107,079.93	\$107,079.93
		0001	0990	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,212.00	0.00	1,212.00	LF	1,212.00	\$2.00	\$2,424.00
		0001	1000	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,000.00	0.00	2,000.00	LF	2,000.00	\$2.00	\$4,000.00
		0001	1010	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	24.00	0.00	24.00	LF	24.00	\$10.00	\$240.00
		0001	1020	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	114,312.00	0.00	114,312.00	LF	114,312.00	\$0.11	\$12,574.32
		0001	1030	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	31,999.00	0.00	31,999.00	LF	31,999.00	\$0.11	\$3,519.89
		0001	1040	6207001	PAVEMENT MARKING REMOVAL	4,006.00	0.00	4,006.00	LF	4,006.00	\$2.00	\$8,012.00
		0001	1050	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0001	1060	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	266.00	0.00	266.00	SQYD	266.00	\$8.76	\$2,330.16
		0001	1070	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	3,431.00	0.00	3,431.00	SQYD	3,431.00	\$9.00	\$30,879.00
		0010	1080	6061060	MGS GUARDRAIL	140.00	0.00	140.00	LF	140.00	\$22.00	\$3,080.00
		0010	1090	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0010	1100	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,900.00	\$11,600.00
		0070	1110	2169902	MISC.Removal of Existing End Post	4.00	0.00	4.00	EA	4.00	\$1,250.00	\$5,000.00
		0070	1120	2169903	MISC.Removal of Existing Curb and Guardrail	166.00	0.00	166.00	LF	166.00	\$125.00	\$20,750.00
		0070	1130	4091048	EMULSIFIED ASPHALT, SEAL COAT	115.00	0.00	115.00	GAL	115.00	\$5.00	\$575.00
		0070	1140	4094011	SEAL COAT AGGREGATE, GRADE B1	287.00	0.00	287.00	SQYD	287.00	\$5.00	\$1,435.00
		0070	1150	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	20.00	11.00	31.00	SQFT	31.00	\$311.16	\$9,645.96
		0070	1160	7040107	SLAB EDGE REPAIR (BRIDGES)	60.00	0.00	60.00	LF	60.00	\$245.39	\$14,723.40
		0070	1170	7040113	CLEANING AND EPOXY COATING	308.00	0.00	308.00	SQFT	308.00	\$13.00	\$4,004.00
		0070	1180	7134000	BRIDGE GUARDRAIL (THRIE BEAM)	178.00	0.00	178.00	LF	178.00	\$286.43	\$50,984.54
	Project J	9S3571 - To	otal Value	Posted to D	Pate as of Report Generated Date							\$1,674,083.73
200117-H07 Ove	erall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$2,695,937.70

Revision 4/1/2020 Page 12 of 49



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9I3553

roject:	J9I3553											
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0100	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	9/16/20	9/28/20	7.40	SQYD	Passing Lane 12.08 x 5.50 = 66.44 SF / 9 = 7.38 SY, Pay = 7.4 SY	36.254		36.254		
				9/28/20	7.40	SQYD	Passing Lane	37.816		37.816		
				9/28/20	8.30	SQYD	12.42 x 5.33 = 66.20 SF / 9 = 7.36SY, Pay = 7.4 SY Passing Lane	37.592		37.592		
			0/47/00				12.54 x 5.92 = 74.24 SF / 9 = 8.25 SY, Pay = 8.3 SY					
			9/1//20	9/29/20			Driving Lane 5.79 x 6.04 = 34.97 SF / 9 = 3.9 SY	36.571		36.571		
				9/29/20	4.10	SQYD	Driving Lane 6.34 x 5.88 = 37.28 SF / 9 = 4.1 SY	37.295		37.295		
0130	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	9/16/20	9/28/20	35.00	LF	Passing Lane 12.16 12.10 5.42 5.58 Total = 35.16 LF, Pay = 35.00 LF	36.254		36.254		
				9/28/20	36.00	LF	Passing Lane 12.42 12.42 5.50 5.16 Total = 35.50 LF, Pay = 36.00 LF	37.816		37.816		
				9/28/20	37.00	LF	Passing Lane 12.58 12.50 5.83	37.592		37.592		
							6.00 Total = 36.91 LF, Pay = 37.00 LF					
			9/17/20	9/29/20	24.00	LF	Driving Lane 5.75 5.83 6.00 6.08 Total = 23.66 LF, Pay = 24 LF	36.571		36.571		
				9/29/20	24.00	LF	Driving Lane 6.42 6.25 5.83 5.92 Total = 24.42 LF, Pay = 24 LF	37.295		37.295		
0140	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	9/16/20	9/28/20	14.00	EA	Passing Lane	37.816		37.816		
				9/28/20	20.00		Passing Lane	36.254		36.254		
			0/17/20	9/28/20	20.00		Passing Lane Driving Lane	37.592 36.571		37.592 36.571		
			9/1//20	9/29/20	10.00		Driving Lane	37.295		37.295		
0180	6161005	CONSTRUCTION SIGNS	9/23/20	9/30/20	222.00	SQFT	Rte FF, Bridge B0548 and Bridge A0030	43.085		43.085		
0320	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	9/23/20	9/30/20	739.00			46.507		46.540		
				9/30/20	739.00 739.00		East of Bridge B0548. West of Bridge A0030.	45.896 46.579		45.929 46.613		
				9/30/20	739.00		West of Bridge 80548.	45.940		45.974		
0350	6061060	MGS GUARDRAIL	9/22/20	9/30/20	237.50		EBL at One Mile Rd	49.160		49.160		
				9/30/20	237.50		EBL at Rte 25	47.535		47.535		
				9/30/20	237.50 237.50		EBL at Rte AD WBL at One Mile Rd	50.704 49.160		50.704 49.160		
				9/30/20	237.50		WBL at Rte 25.	47.535		47.535		
				9/30/20	237.50		WBL at Rte AD	50.704		50.704		
0370	6061080	MGS END ANCHOR	9/22/20	9/30/20	1.00		EBL at One Mile Rd	49.160		49.160		
				9/30/20	1.00		EBL at Rte 25	47.535		47.535		
				9/30/20	1.00		EBL at Rte AD WBL at One Mile Rd	50.704 49.160		50.704 49.160		
				9/30/20	1.00		WBL at Rte 25	47.535		47.535		
				9/30/20	1.00	EA	WBL at Rte AD	50.704		50.704		
0380	6063014	TYPE A CRSHWTHY END TERMINAL (MASH)	9/22/20	9/30/20	1.00		EBL at One Mile Rd	49.106		49.106		
				9/30/20	1.00		EBL at Rte 25	47.535		47.535		
				9/30/20	1.00		EBL at Rte AD WBL at One Mile Rd	50.704 49.160		50.704 49.160		
				9/30/20	1.00		WBL at Rte 25	47.535		47.535		
				9/30/20	1.00	EA	WBL at Rte AD	50.704		50.704		
0430	7040104	HALF-SOLE REPAIR	9/30/20	10/1/20	65.00	SQFT		1		2		
0480		HALF-SOLE REPAIR HALF-SOLE REPAIR	9/30/20	10/1/20	8.00 613.00			1		2		
0530		HALF-SOLE REPAIR HALF-SOLE REPAIR		10/1/20	613.00 545.00			1		2		
0780		HALF-SOLE REPAIR		9/29/20	112.00			31.168		31.168		
0820	7040104	HALF-SOLE REPAIR	9/16/20	9/28/20	240.00	SQFT	Zone B Passing Lane Half-Sole, Zone B	29.461		29.461		
			9/25/20		454.00		Bridge L0956 Passing Lane	29.461		29.461		
			9/30/20				non-special, span 1 and 2. Bridge L0956 Passing Lane	29.461		29.461		
				10/1/20			Non-Special, Span 3. Route 60.	29.461		29.461	Thi	is Line Item entry addresses overpayment from
							Bridge L0956 Passing Lane Non-Special, Span 3.				(Br	coks, S.) ange order will address additional line item quantity. dge L0956 Passing Lane n-Special, Span 3.
5002	6161010	RELOCATED SIGNS	9/30/20	10/1/20	268.00	SQFT	Route 60	53.962		24.622	Em Ch:	n-special, span 3. nail From 9-22-2020: lange order 1 included line 5002 for relocation of signs the bridge work.

Revision 4/1/2020 Page 13 of 49



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3571

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0850	3049910	MISC. AGGREGATE FOR BASE	9/30/20	10/1/20	458.13	TONS	Route 60/62	331		340		5-05-2020 date.
0900	4134000	BITUMINOUS FOG SEAL	9/30/20	10/1/20	2,267.00	GAL	Route 60/62	331		340		5-04-2020 & 5-07-2020 dates.
1150	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	9/30/20	10/1/20	11.00	SQFT		1		2		

The information below this line are details from Line Item agency views.

Contract ID: 200117-H07

DWR Date: September 23, 2020

Line Number: 0180

Description: CONSTRUCTION SIGNS

Quantity Posted: 222

Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
West of Rte FF (Stoddard)	43.085		WO8-1 48x48 16.00 BUMP		2.00		16	32
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
West of Rte FF (Stoddard)	43.085		WO8-15 48x48 16.00 GROOVED PAVEMENT		2.00		16	32
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
West of Rte FF (Stoddard)	43.085		WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		2.00		5	10
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
East of Bridge B0548	45.896		WO8-1 48x48 16.00 BUMP		2.00		16	32
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
East of Bridge B0548	45.896		WO8-15 48x48 16.00 GROOVED PAVEMENT		2.00		16	32
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
East of Bridge B0548	45.896		WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		2.00		5	10
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
East of Bridge A0030	46.507		WO8-1 48x48 16.00 BUMP		2.00		16	32
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
East of A0030	46.507		WO8-15 48x48 16.00 GROOVED PAVEMENT		2.00		16	32
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
East of A0030	46.507		WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		2.00		5	10
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
			No Data Available		0.00			

Description: CONSTRUCTION SIGNS

Quantity Posted: 222

Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
Vest of Rte FF Stoddard)	43.085		WO8-1 48x48 16.00 BUMP		2.00		16	32
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
West of Rte FF (Stoddard)	43.085		WO8-15 48x48 16.00 GROOVED PAVEMENT		2.00		16	32
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
West of Rte FF (Stoddard)	43.085		WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		2.00		5	10
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
East of Bridge B0548	45.896		WO8-1 48x48 16.00 BUMP		2.00		16	32
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
East of Bridge B0548	45.896		WO8-15 48x48 16.00 GROOVED PAVEMENT		2.00		16	32
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
East of Bridge B0548	45.896		WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		2.00		5	10
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
East of Bridge A0030	46.507		WO8-1 48x48 16.00 BUMP		2.00		16	32
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
East of A0030	46.507		WO8-15 48x48 16.00 GROOVED PAVEMENT		2.00		16	32
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
East of A0030	46.507		WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		2.00		5	10
Location	Log Mile	Station	Sign Number	Special Sign	Number of Items	SF Special Sign	Units Each	Total SF Pay
			No Data Available		0.00			

Revision 4/1/2020 Page 14 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH	Material		6	Jul 2, 2020	SYSTEM	(\$46,901.03)	
	PAVEMENT REPAIR			6	Jul 2, 2020	SYSTEM	\$46,901.03	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$69,305.39)	
				7	Jul 16, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$69,305.39)	
				8	Aug 3, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$69,305.39)	
				9	Aug 18, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$69,305.39)	
				10	Sep 3, 2020	SYSTEM	\$69,305.39	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$84,951.41)	
				11	Sep 16, 2020	SYSTEM	\$84,951.41	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$90,709.88)	
				12	Oct 1, 2020	SYSTEM	\$90,709.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0100 -							\$0.00	
0110	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		6	Jul 2, 2020	SYSTEM	(\$16.00)	
				6	Jul 2, 2020	SYSTEM	\$16.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$100.00)	
				7	Jul 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$100.00)	
				8	Aug 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$100.00)	
				9	Aug 18, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				10	Sep 3,	SYSTEM	(\$100.00)	

Revision 4/1/2020 Page 15 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0110	SUBGRADE COMPACTION (6 IN.	Material	71		2020			
	DEPTH) (PAVEMENT REPAIR)			10	Sep 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$100.00)	
				11	Sep 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$100.00)	
				12	Oct 1, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0110	- Total						\$0.00	
0120	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		6	Jul 2, 2020	SYSTEM	(\$16.00)	
				6	Jul 2, 2020	SYSTEM	\$16.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$100.00)	
				7	Jul 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$100.00)	
				8	Aug 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$100.00)	
				9	Aug 18, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$100.00)	
				10	Sep 3, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$100.00)	
				11	Sep 16, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$100.00)	
				12	Oct 1, 2020	SYSTEM	\$100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0120	- Total						\$0.00	
0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		6	Jul 2, 2020	SYSTEM	(\$2,000.00)	
	PAVEMENT REPAIR			6	Jul 2, 2020	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1

Revision 4/1/2020 Page 16 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material	,					overridding Payment Estimate Exception 13 on the current Payment Estimate.
	PAVEMENT REPAIR			7	Jul 16, 2020	SYSTEM	(\$5,650.00)	
				7	Jul 16, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$5,650.00)	
				8	Aug 3, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$5,650.00)	
				9	Aug 18, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$5,650.00)	
				10	Sep 3, 2020	SYSTEM	\$5,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$7,480.00)	
				11	Sep 16, 2020	SYSTEM	\$7,480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$8,220.00)	
				12	Oct 1, 2020	SYSTEM	\$8,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
0140 -	Material - Total						\$0.00	
0150	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR	Material		7	Jul 16, 2020	SYSTEM	\$0.00 (\$10.00)	
	FULL DEPTH PAVEMENT RÉPAIR			7	Jul 16, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$10.00)	
				8	Aug 3, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$10.00)	
				9	Aug 18, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$10.00)	
				10	Sep 3, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$10.00)	
				11	Sep 16, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 23 on the current

Revision 4/1/2020 Page 17 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
0150	DOWEL BAR (FURNISHING AND	Material						Payment Estimate.													
	INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR			12	Oct 1, 2020	SYSTEM	(\$10.00)														
				12	Oct 1, 2020	SYSTEM	\$10.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.													
			- Total				\$0.00														
	Material - Total						\$0.00														
	- Total						\$0.00														
0180	CONSTRUCTION SIGNS	Material		1	Apr 16, 2020	SYSTEM	(\$2,450.50)														
				2	May 4, 2020	SYSTEM	(\$3,861.00)														
				2	May 4, 2020	SYSTEM	\$3,861.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.													
				3	May 19, 2020	SYSTEM	(\$3,861.00)														
				3	May 19, 2020	SYSTEM	\$3,861.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.													
				4	Jun 3, 2020	SYSTEM	(\$3,939.00)														
				4	Jun 3, 2020	SYSTEM	\$3,939.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.													
				5	Jun 16, 2020	SYSTEM	(\$3,939.00)														
				5	Jun 16, 2020	SYSTEM	\$3,939.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.													
				6	Jul 2, 2020	SYSTEM	(\$6,389.50)														
				6	Jul 2, 2020	SYSTEM	\$6,389.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.													
				7	Jul 16, 2020	SYSTEM	(\$6,389.50)														
				7	Jul 16, 2020	SYSTEM	\$6,389.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.													
				8	Aug 3, 2020	SYSTEM	(\$9,360.00)														
													8	Aug 3, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
									9	Aug 18, 2020	SYSTEM	(\$9,360.00)									
				10	Sep 3, 2020	SYSTEM	(\$9,360.00)														
				10	Sep 3, 2020	SYSTEM	\$9,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.													
			- Total				(\$2,450.50)														
	Material - Total						(\$2,450.50)														
	CONSTRUCTION SIGNS	MaterialCredit		2	May 4,	SYSTEM	\$2,450.50														

Revision 4/1/2020 Page 18 of 49



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks															
		Туре	Type	Number	Date	Бу																	
0180		MaterialCredit			2020																		
			- Total				\$2,450.50																
	MaterialCredit - Total						\$2,450.50																
	CONSTRUCTION SIGNS	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$2,450.50																
				2	May 4, 2020	woodsk1	(\$2,450.50)	This adjustment is being added to balance line item 0180 discrepancy amount.															
			MDPA - Tota	al			\$0.00																
	Other Item Adjustment - Total						\$0.00																
0180 -	Total						\$0.00																
0210	CHANNELIZER (TRIM LINE) Material	Material		1	Apr 16, 2020	SYSTEM	(\$1,215.00)																
				2	May 4, 2020	SYSTEM	(\$1,215.00)																
				2	May 4, 2020	SYSTEM	\$1,215.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.															
								3	May 19, 2020	SYSTEM	(\$1,215.00)												
						3	May 19, 2020	SYSTEM	\$1,215.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.													
						4	Jun 3, 2020	SYSTEM	(\$1,980.00)														
				4	Jun 3, 2020	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.															
				5	Jun 16, 2020	SYSTEM	(\$1,980.00)																
				5	Jun 16, 2020	SYSTEM	\$1,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.															
				6	Jul 2, 2020	SYSTEM	(\$3,930.00)																
						6	Jul 2, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.													
											7	Jul 16, 2020	SYSTEM	(\$3,930.00)									
							7	Jul 16, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.												
																			8	Aug 3, 2020	SYSTEM	(\$3,930.00)	
															8	Aug 3, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.				
															9	Aug 18, 2020	SYSTEM	(\$3,930.00)					
											9	Aug 18, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.								
																		10	Sep 3, 2020	SYSTEM	(\$3,930.00)		
				10	Sep 3, 2020	SYSTEM	\$3,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.															
			- Total				(\$1,215.00)																
	Material - Total						(\$1,215.00)																

Revision 4/1/2020 Page 19 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0210	CHANNELIZER (TRIM LINE)	MaterialCredit	Туре	2	May 4, 2020	SYSTEM	\$1,215.00		
			- Total				\$1,215.00		
	MaterialCredit - Total						\$1,215.00		
	CHANNELIZER (TRIM LINE)	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$1,215.00		
				2	May 4, 2020	woodsk1	(\$1,215.00)	This adjustment is being added to balance line item 0220 discrepancy amount.	
			MDPA - Tot	al			\$0.00		
	Other Item Adjustment - Total						\$0.00		
0210 -							\$0.00		
0230	DIRECTIONAL INDICATOR BARRICADE	Material		1	Apr 16, 2020	SYSTEM	(\$665.00)		
				2	May 4, 2020	SYSTEM	(\$665.00)		
				2	May 4, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
				3	May 19, 2020	SYSTEM	(\$665.00)		
				3	May 19, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
				4	Jun 3, 2020	SYSTEM	(\$665.00)		
					4	Jun 3, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$665.00)		
				5	Jun 16, 2020	SYSTEM	\$665.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
				6	Jul 2, 2020	SYSTEM	(\$1,995.00)		
				6	Jul 2, 2020	SYSTEM	\$1,995.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
				7	Jul 16, 2020	SYSTEM	(\$2,660.00)		
				7	Jul 16, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
				8	Aug 3, 2020	SYSTEM	(\$2,660.00)		
				8	Aug 3, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
				9	Aug 18, 2020	SYSTEM	(\$2,660.00)		
				9	Aug 18, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	
				10	Sep 3, 2020	SYSTEM	(\$2,660.00)		
				10	Sep 3, 2020	SYSTEM	\$2,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	
			- Total				(\$665.00)		

Revision 4/1/2020 Page 20 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
0230	Material - Total						(\$665.00)																
	DIRECTIONAL INDICATOR BARRICADE	MaterialCredit		2	May 4, 2020	SYSTEM	\$665.00																
			- Total				\$665.00																
	MaterialCredit - Total						\$665.00																
	DIRECTIONAL INDICATOR BARRICADE	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$665.00																
				2	May 4, 2020	woodsk1	(\$665.00)	This adjustment is being added to balance line item 0230 discrepancy amount.															
			MDPA - Tot	al			\$0.00																
	Other Item Adjustment - Total						\$0.00																
0230 -	Total						\$0.00																
0240	FLASHING ARROW PANEL	Material		1	Apr 16, 2020	SYSTEM	(\$400.00)																
				2	May 4, 2020	SYSTEM	(\$400.00)																
				2	May 4, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.															
								3	May 19, 2020	SYSTEM	(\$400.00)												
				3	May 19, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.															
				4	Jun 3, 2020	SYSTEM	(\$400.00)																
				4	Jun 3, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.															
				5	Jun 16, 2020	SYSTEM	(\$400.00)																
				5	Jun 16, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.															
				6	Jul 2, 2020	SYSTEM	(\$1,200.00)																
				6	Jul 2, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.															
																			7	Jul 16, 2020	SYSTEM	(\$1,600.00)	
																		7	Jul 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
				8	Aug 3, 2020	SYSTEM	(\$1,600.00)																
													8	Aug 3, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.						
				9	Aug 18, 2020	SYSTEM	(\$1,600.00)																
				9	Aug 18, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate.															
				10	Sep 3, 2020	SYSTEM	(\$1,600.00)																
				10	Sep 3, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.															

Revision 4/1/2020 Page 21 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
0240		Material	- Total				(\$400.00)											
	Material - Total						(\$400.00)											
	FLASHING ARROW PANEL	MaterialCredit		2	May 4, 2020	SYSTEM	\$400.00											
			- Total				\$400.00											
	MaterialCredit - Total						\$400.00											
	FLASHING ARROW PANEL	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$400.00											
				2	May 4, 2020	woodsk1	(\$400.00)	This adjustment is being added to balance line item 0240 discrepancy amount.										
			MDPA - Tot	al			\$0.00											
	Other Item Adjustment - Total						\$0.00											
0240 -	Total						\$0.00											
0250	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Material		1	Apr 16, 2020	SYSTEM	(\$3,500.00)											
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			2	May 4, 2020	SYSTEM	(\$3,500.00)											
									2	May 4, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.					
				3	May 19, 2020	SYSTEM	(\$3,500.00)											
				3	May 19, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.										
				4	Jun 3, 2020	SYSTEM	(\$3,500.00)											
				4	Jun 3, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.										
												5	Jun 16, 2020	SYSTEM	(\$3,500.00)			
				5	Jun 16, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.										
				6	Jul 2, 2020	SYSTEM	(\$3,500.00)											
				6	Jul 2, 2020	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
				7	Jul 16, 2020	SYSTEM	(\$7,000.00)											
														7	Jul 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$7,000.00)											
									8	Aug 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.					
				9	Aug 18, 2020	SYSTEM	(\$7,000.00)											
								\$	5			9	Aug 18, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.		
				10	Sep 3, 2020	SYSTEM	(\$7,000.00)											
				10	Sep 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 34 on the current										

Revision 4/1/2020 Page 22 of 49



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0250	CHANGEABLE MESSAGE SIGN	Material	Туре					Payment Estimate.
0230	WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	iviaterial						rayment Estimate.
	FURNISHED, CONTRACTOR RETAINED							
			- Total				(\$3,500.00)	
	Material - Total						(\$3,500.00)	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	MaterialCredit		2	May 4, 2020	SYSTEM	\$3,500.00	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED							
			- Total				\$3,500.00	
	MaterialCredit - Total						\$3,500.00	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$3,500.00	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Aujustinent		2	May 4,	woodsk1	(\$3,500.00)	This adjustment is being added to balance line item 0250
	TOTATIONED, GOTATIVIOTOTALENINED				2020			discrepancy amount.
			MDPA - Tot	al			\$0.00	
0250 -	Other Item Adjustment - Total						\$0.00	
0250 -	MGS GUARDRAIL	Construction		1	Apr 16,	SYSTEM	\$0.00 \$85,893.50	Payment Estimate Item Adjustment generated Stockpile
5550	WIGG GOANDRAIL	Stockpile			2020		ψυυ,υσυ.υυ	Transaction
				4	Jun 3, 2020	SYSTEM	(\$5,068.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 2, 2020	SYSTEM	(\$4,001.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Sep 3, 2020	SYSTEM	(\$5,068.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 16, 2020	SYSTEM	(\$4,001.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Oct 1, 2020	SYSTEM	(\$15,204.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$52,549.75	
	Construction Stockpile - Total						\$52,549.75	
0350 -						0) (0 = = 1	\$52,549.75	
0360	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$35,976.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Jun 3, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 2, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Sep 3, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 16, 2020	SYSTEM	(\$2,998.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$23,984.00	
	Construction Stockpile - Total						\$23,984.00	
0360 -	Total						\$23,984.00	
0370	MGS END ANCHOR	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$3,210.00	Payment Estimate Item Adjustment generated Stockpile Transaction
0370	MGS END ANCHOR			12		SYSTEM SYSTEM	(\$3,210.00)	
0370			- Total		2020 Oct 1,		(\$3,210.00) \$0.00	Transaction Payment Estimate Item Adjustment generated Stockpile
	Construction Stockpile - Total		- Total		2020 Oct 1,		(\$3,210.00) \$0.00 \$0.00	Transaction Payment Estimate Item Adjustment generated Stockpile
0370 -	Construction Stockpile - Total Total	Stockpile	- Total	12	2020 Oct 1, 2020	SYSTEM	(\$3,210.00) \$0.00 \$0.00 \$0.00	Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	Construction Stockpile - Total		- Total		2020 Oct 1,		(\$3,210.00) \$0.00 \$0.00	Transaction Payment Estimate Item Adjustment generated Stockpile
0370 -	Construction Stockpile - Total Total TYPE A CRASHWORTHY END	Stockpile	- Total	12	2020 Oct 1, 2020 Apr 16,	SYSTEM	(\$3,210.00) \$0.00 \$0.00 \$0.00	Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile
0370 -	Construction Stockpile - Total Total TYPE A CRASHWORTHY END	Stockpile	- Total	12	2020 Oct 1, 2020 Apr 16, 2020 Jun 3,	SYSTEM	(\$3,210.00) \$0.00 \$0.00 \$0.00 \$45,300.00	Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction

Revision 4/1/2020 Page 23 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0380	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		11	Sep 16, 2020	SYSTEM	(\$3,020.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Oct 1, 2020	SYSTEM	(\$9,060.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$24,160.00	
	Construction Stockpile - Total						\$24,160.00	
0380 -	- Total						\$24,160.00	
0400	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 18, 2020	SYSTEM	(\$265.00)	
				9	Aug 18, 2020	SYSTEM	\$265.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0400 -	- Total						\$0.00	
0410	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	(\$662.50)	
				9	Aug 18, 2020	SYSTEM	\$662.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$1,325.00)	
				10	Sep 3, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$1,325.00)	
				11	Sep 16, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$1,325.00)	
				12	Oct 1, 2020	SYSTEM	\$1,325.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0410 -	- Total						\$0.00	
0420	CURB BLOCKOUT	Material		2	May 4, 2020	SYSTEM	(\$11,278.05)	
				2	May 4, 2020	SYSTEM	\$11,278.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$16,671.90)	
				3	May 19, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$16,671.90)	
				4	Jun 3, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$16,671.90)	
				5	Jun 16, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.

Revision 4/1/2020 Page 24 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0420	CURB BLOCKOUT	Material		6	Jul 2, 2020	SYSTEM	(\$33,343.80)	
				6	Jul 2, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$33,343.80)	
				7	Jul 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$33,343.80)	
				8	Aug 3, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$33,343.80)	
				9	Aug 18, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$33,343.80)	
				10	Sep 3, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$33,343.80)	
				11	Sep 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$33,343.80)	
				12	Oct 1, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0420 - 0430	HALF-SOLE REPAIR	Material		3		SYSTEM	\$0.00 (\$12,412.98)	
				3	2020 May 19, 2020	SYSTEM	\$12,412.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$23,457.60)	
				4	Jun 3, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$37,727.64)	
				5	Jun 16, 2020	SYSTEM	\$37,727.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$67,440.60)	
				6	Jul 2, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
				7	Jul 16,	SYSTEM	(\$67,440.60)	

Revision 4/1/2020 Page 25 of 49



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0430	HALF-SOLE REPAIR	Material			2020			
				7	Jul 16, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$67,440.60)	
				8	Aug 3, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$67,440.60)	
				9	Aug 18, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 87 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$67,440.60)	
				10	Sep 3, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$67,440.60)	
				11	Sep 16, 2020	SYSTEM	\$67,440.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$73,793.70)	
				12	Oct 1, 2020	SYSTEM	\$73,793.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
								· - / · · · · · · · · · · · · · · · · ·
			- Total				\$0.00	
	Material - Total		- Total				\$0.00 \$0.00	
0430 -			- Total					
0430 - 0450		Material	- Total	9	Aug 18, 2020	SYSTEM	\$0.00	
	Total	Material	- Total	9		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	Total	Material	- Total		2020 Aug 18,		\$0.00 \$0.00 (\$287.50)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
	Total	Material			2020 Aug 18,		\$0.00 \$0.00 (\$287.50) \$287.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
	Total EMULSIFIED ASPHALT, SEAL COAT	Material			2020 Aug 18,		\$0.00 \$0.00 (\$287.50) \$287.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
0450	Total EMULSIFIED ASPHALT, SEAL COAT				2020 Aug 18,		\$0.00 \$0.00 (\$287.50) \$287.50 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
0450	Total EMULSIFIED ASPHALT, SEAL COAT Material - Total Total			9	2020 Aug 18, 2020	SYSTEM	\$0.00 \$0.00 (\$287.50) \$287.50 \$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
0450	Total EMULSIFIED ASPHALT, SEAL COAT Material - Total Total			9	Aug 18, 2020 Aug 18, 2020 Aug 18, 2020 Aug 18,	SYSTEM	\$0.00 \$0.00 (\$287.50) \$287.50 \$0.00 \$0.00 (\$720.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 27 on the current
0450	Total EMULSIFIED ASPHALT, SEAL COAT Material - Total Total			9 9	2020 Aug 18, 2020 Aug 18, 2020 Aug 18, 2020 Sep 3,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$287.50) \$287.50 \$0.00 \$0.00 \$720.00 \$720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 27 on the current
0450	Total EMULSIFIED ASPHALT, SEAL COAT Material - Total Total			9 9 9 10	Aug 18, 2020 Aug 18, 2020 Aug 18, 2020 Sep 3, 2020 Sep 3,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$287.50) \$287.50 \$0.00 \$0.00 (\$720.00) \$720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 13 on the current
0450	Total EMULSIFIED ASPHALT, SEAL COAT Material - Total Total			9 9 9 10 10	Aug 18, 2020 Aug 18, 2020 Aug 18, 2020 Aug 18, 2020 Sep 3, 2020 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$287.50) \$287.50 \$0.00 \$0.00 (\$720.00) \$720.00 (\$1,440.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 13 on the current
0450	Total EMULSIFIED ASPHALT, SEAL COAT Material - Total Total			9 9 9 10 10	Aug 18, 2020 Aug 18, 2020 Aug 18, 2020 Aug 18, 2020 Sep 3, 2020 Sep 16, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$287.50) \$287.50 \$0.00 \$0.00 \$720.00 \$720.00 \$1,440.00 \$1,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.

Revision 4/1/2020 Page 26 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0460	SEAL COAT AGGREGATE, GRADE B1	Material						overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0460 -	Total						\$0.00	
0470	CURB BLOCKOUT	Material		3	May 19, 2020	SYSTEM	(\$12,100.62)	
				3	May 19, 2020	SYSTEM	\$12,100.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$17,908.92)	
				4	Jun 3, 2020	SYSTEM	\$17,908.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$17,908.92)	
				5	Jun 16, 2020	SYSTEM	\$17,908.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$35,817.85)	
				6	Jul 2, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$35,817.85)	
				7	Jul 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$35,817.85)	
				8	Aug 3, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$35,817.85)	
				9	Aug 18, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 64 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$35,817.85)	
				10	Sep 3, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$35,817.85)	
				11	Sep 16, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$35,817.85)	
				12	Oct 1, 2020	SYSTEM	\$35,817.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0470 -	Total						\$0.00	
0480	HALF-SOLE REPAIR	Material		3	May 19,	SYSTEM	(\$4,160.68)	

Revision 4/1/2020 Page 27 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
0480	HALF-SOLE REPAIR	Material	. , , , ,		2020																		
				3	May 19, 2020	SYSTEM	\$4,160.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.															
				4	Jun 3, 2020	SYSTEM	(\$25,157.60)																
				4	Jun 3, 2020	SYSTEM	\$25,157.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.															
				5	Jun 16, 2020	SYSTEM	(\$41,510.04)																
					5	Jun 16, 2020	SYSTEM	\$41,510.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.														
									6	Jul 2, 2020	SYSTEM	(\$69,183.40)											
						6	Jul 2, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 45 on the current Payment Estimate.													
				7	Jul 16, 2020	SYSTEM	(\$69,183.40)																
				7	Jul 16, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.															
							8	Aug 3, 2020	SYSTEM	(\$69,183.40)													
						8	Aug 3, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.													
						9	Aug 18, 2020	SYSTEM	(\$69,183.40)														
					9	Aug 18, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 83 on the current Payment Estimate.														
				10	Sep 3, 2020	SYSTEM	(\$69,183.40)																
				10	Sep 3, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 69 on the current Payment Estimate.															
				11	Sep 16, 2020	SYSTEM	(\$69,183.40)																
				11	Sep 16, 2020	SYSTEM	\$69,183.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 58 on the current Payment Estimate.															
																			12	Oct 1, 2020	SYSTEM	(\$69,957.48)	
				12	Oct 1, 2020	SYSTEM	\$69,957.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.															
			- Total				\$0.00																
	Material - Total						\$0.00																
0480 -	Total						\$0.00																
0520	CURB BLOCKOUT	Material		9	Aug 18, 2020	SYSTEM	(\$16,671.90)																
				9	Aug 18, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 70 on the current Payment Estimate.															
				10	Sep 3, 2020	SYSTEM	(\$16,671.90)																

Revision 4/1/2020 Page 28 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0520	CURB BLOCKOUT	Material	, ,,	10	Sep 3, 2020	SYSTEM	\$16,671.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$33,343.80)	
				11	Sep 16, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$33,343.80)	
				12	Oct 1, 2020	SYSTEM	\$33,343.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0520 -	·Total						\$0.00	
0530	HALF-SOLE REPAIR	Material		7	Jul 16, 2020	SYSTEM	(\$8,503.38)	
				7	Jul 16, 2020	SYSTEM	\$8,503.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$8,503.38)	
				8	Aug 3, 2020	SYSTEM	\$8,503.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$23,457.60)	
				9	Aug 18, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 82 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$23,457.60)	
				10	Sep 3, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$23,457.60)	
				11	Sep 16, 2020	SYSTEM	\$23,457.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$83,372.22)	
				12	Oct 1, 2020	SYSTEM	\$83,372.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total						\$0.00	
0570	CURB BLOCKOUT	Material		9	Aug 18, 2020	SYSTEM	(\$15,434.12)	
				9	Aug 18, 2020	SYSTEM	\$15,434.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$15,434.12)	
				10	Sep 3, 2020	SYSTEM	\$15,434.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 44 on the current

Revision 4/1/2020 Page 29 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0570	CURB BLOCKOUT	Material	71					Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$30,868.25)	,
				11	Sep 16, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$30,868.25)	
				12	Oct 1, 2020	SYSTEM	\$30,868.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0570 -	- Total						\$0.00	
0580	HALF-SOLE REPAIR	Material		7	Jul 16, 2020	SYSTEM	(\$21,758.00)	
				7	Jul 16, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$21,758.00)	
				8	Aug 3, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$21,758.00)	
				9	Aug 18, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 90 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$21,758.00)	
				10	Sep 3, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$21,758.00)	
				11	Sep 16, 2020	SYSTEM	\$21,758.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0580	- Total						\$0.00	
0780	HALF-SOLE REPAIR	Material		11	Sep 16, 2020	SYSTEM	(\$2,577.84)	
				11	Sep 16, 2020	SYSTEM	\$2,577.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$14,607.76)	
				12	Oct 1, 2020	SYSTEM	\$14,607.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0780	- Total						\$0.00	
0820	HALF-SOLE REPAIR	Material		11	Sep 16, 2020	SYSTEM	(\$3,007.48)	
				11	Sep 16,	SYSTEM	\$3,007.48	This adjustment offsets the original system-generated Overrun

Revision 4/1/2020 Page 30 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0820	HALF-SOLE REPAIR	Material			2020			Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 66 on the current Payment Estimate.			
				12	Oct 1, 2020	SYSTEM	(\$42,964.00)				
				12	Oct 1, 2020	SYSTEM	\$42,964.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 48 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
0820 -	- Total						\$0.00				
0850	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		2	May 4, 2020	SYSTEM	(\$17,901.77)				
				2	May 4, 2020	SYSTEM	\$17,901.77	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				3	May 19, 2020	SYSTEM	(\$42,591.62)				
				3	May 19, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				4	Jun 3, 2020	SYSTEM	(\$42,591.62)				
				4	Jun 3, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				5	Jun 16, 2020	SYSTEM	(\$42,591.62)				
				5	Jun 16, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
							6	Jul 2, 2020	SYSTEM	(\$42,591.62)	
				6	Jul 2, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					7	Jul 16, 2020	SYSTEM	(\$42,591.62)			
				7	Jul 16, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				8	Aug 3, 2020	SYSTEM	(\$42,591.62)				
				8	Aug 3, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				9	Aug 18, 2020	SYSTEM	(\$42,591.62)				
				9	Aug 18, 2020	SYSTEM	\$42,591.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				10	Sep 3, 2020	SYSTEM	(\$48,392.79)				
				10	Sep 3, 2020	SYSTEM	\$48,392.79	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				11	Sep 16, 2020	SYSTEM	(\$48,392.79)				
				11	Sep 16, 2020	SYSTEM	\$48,392.79	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1			

Revision 4/1/2020 Page 31 of 49



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks						
LINE	υσσοτιμιστ	Type	Adjustment Type		Date	By	Amount	rondins						
0850	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material						overridding Payment Estimate Exception 1 on the current Payment Estimate.						
				12	Oct 1, 2020	SYSTEM	(\$64,697.64)							
				12	Oct 1, 2020	SYSTEM	\$64,697.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
			- Total				\$0.00							
	Material - Total						\$0.00							
0850 -	· Total						\$0.00							
0870	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	2	May 4, 2020	woodsk1	\$460.98							
			ACAD - Tot	al			\$460.98							
	Other Item Adjustment - Total						\$460.98							
0870 -	· Total						\$460.98							
0880	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		2	May 4, 2020	SYSTEM	(\$456,638.72)							
				2	May 4, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
				3	May 19, 2020	SYSTEM	(\$456,638.72)							
				3	May 19, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
				4	Jun 3, 2020	SYSTEM	(\$456,638.72)							
				4	Jun 3, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					5	Jun 16, 2020	SYSTEM	(\$456,638.72)						
				5	Jun 16, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
				6	Jul 2, 2020	SYSTEM	(\$456,638.72)							
						6	Jul 2, 2020	SYSTEM	\$456,638.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
										7	Jul 16, 2020	SYSTEM	(\$940,718.72)	
									7	Jul 16, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
				8	Aug 3, 2020	SYSTEM	(\$940,718.72)							
				8	Aug 3, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
				9	Aug 18, 2020	SYSTEM	(\$940,718.72)							
				9	Aug 18, 2020	SYSTEM	\$940,718.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
				10	Sep 3, 2020	SYSTEM	(\$1,038,932.50)							
				10	Sep 3, 2020	SYSTEM	\$1,038,932.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 2 on the current						

Revision 4/1/2020 Page 32 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0880	ASPHALTIC CONCRETE MIXTURE PG	Material						Payment Estimate.
	70-22 (SP125C MIX)			11	Sep 16, 2020	SYSTEM	(\$1,038,932.50)	
				11	Sep 16, 2020	SYSTEM	\$1,038,932.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	1	Apr 16, 2020	woodsk1	\$1,227.35	
				2	May 4, 2020	woodsk1	\$1,493.29	
			ACAD - Tota	al			\$2,720.64	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)		ВІТМ	8	Aug 3, 2020	woodsk1	\$66,845.91	TSR #001 Payment Adjustment. Lot #001 \$18,153.00 TSR #002 Payment Adjustment. Lot #004 \$10,068.56 Lot 1 Bonus Payment Adjustment \$12,102.00 Lot 2 Bonus Payment Adjustment \$6,051.00 Lot 3 Bonus Payment Adjustment \$12,102.00 Lot 4 Bonus Payment Adjustment \$8,369.35 Total Bituminous Pay Factor Adjustment For Line Item Posting
			BITM - Tota				000 045 04	#0880 \$66,845.91
	Other Item Adjustment - Total		BITIM - TOLA	<u>'</u>			\$66,845.91 \$69,566.55	
0880 -	·						\$69,566.55	
0890	TACK COAT	Material		1	Apr 16, 2020	SYSTEM	(\$10,486.00)	
				2	May 4, 2020	SYSTEM	(\$24,460.20)	
				2	May 4, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				3	May 19, 2020	SYSTEM	(\$24,460.20)	
				3	May 19, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$24,460.20)	
				4	Jun 3, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$24,460.20)	
				5	Jun 16, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$24,460.20)	
				6	Jul 2, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$24,460.20)	
				7	Jul 16, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.

Revision 4/1/2020 Page 33 of 49



Line	B	A 11	011		0	0		D 1
	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0890	TACK COAT	Material		8	Aug 3, 2020	SYSTEM	(\$24,460.20)	
				8	Aug 3, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$24,460.20)	
				9	Aug 18, 2020	SYSTEM	\$24,460.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$27,242.20)	
				10	Sep 3, 2020	SYSTEM	\$27,242.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$27,242.20)	
				11	Sep 16, 2020	SYSTEM	\$27,242.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				(\$10,486.00)	
	Material - Total						(\$10,486.00)	
	TACK COAT	MaterialCredit		2	May 4, 2020	SYSTEM	\$10,486.00	
			- Total				\$10,486.00	
	MaterialCredit - Total						\$10,486.00	
	TACK COAT	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$10,486.00	
				2	May 4, 2020	woodsk1	(\$10,486.00)	This adjustment is being added to balance line item 0890 discrepancy amount.
			MDPA - Tot	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0890	Other Item Adjustment - Total - Total						\$0.00 \$0.00	
0890		Material		2	May 4, 2020	SYSTEM		
	- Total	Material		2		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	- Total	Material			2020 May 4,	SYSTEM	\$0.00 (\$4,565.00)	Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
	- Total	Material		2	2020 May 4, 2020 May 19,	SYSTEM	\$0.00 (\$4,565.00) \$4,565.00	Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
	- Total	Material		2	2020 May 4, 2020 May 19, 2020 May 19,	SYSTEM	\$0.00 (\$4,565.00) \$4,565.00 (\$8,436.95)	Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
	- Total	Material		3 3	2020 May 4, 2020 May 19, 2020 May 19, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$4,565.00) \$4,565.00 (\$8,436.95) \$8,436.95	Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
	- Total	Material		3 3 4	2020 May 4, 2020 May 19, 2020 May 19, 2020 Jun 3, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$4,565.00) \$4,565.00 (\$8,436.95) \$8,436.95	Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
	- Total	Material		3 3 4 4	2020 May 4, 2020 May 19, 2020 May 19, 2020 Jun 3, 2020 Jun 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$4,565.00) \$4,565.00 (\$8,436.95) \$8,436.95 (\$8,436.95)	Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
	- Total	Material		2 3 3 4 4	2020 May 4, 2020 May 19, 2020 May 19, 2020 Jun 3, 2020 Jun 3, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$4,565.00) \$4,565.00 (\$8,436.95) \$8,436.95 (\$8,436.95) (\$8,436.95)	Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current
	- Total	Material		2 3 3 4 4 5 5	2020 May 4, 2020 May 19, 2020 May 19, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$4,565.00) \$4,565.00 (\$8,436.95) \$8,436.95 (\$8,436.95) (\$8,436.95) \$8,436.95	Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 5 on the current

Revision 4/1/2020 Page 34 of 49



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
0900	BITUMINOUS FOG SEAL	Material	, ,,		2020								
				7	Jul 16, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
									8	Aug 3, 2020	SYSTEM	(\$8,436.95)	
				8	Aug 3, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
				9	Aug 18, 2020	SYSTEM	(\$8,436.95)						
				9	Aug 18, 2020	SYSTEM	\$8,436.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.					
				10	Sep 3, 2020	SYSTEM	(\$10,511.95)						
				10	Sep 3, 2020	SYSTEM	\$10,511.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.					
				11	Sep 16, 2020	SYSTEM	(\$10,511.95)						
					11	Sep 16, 2020	SYSTEM	\$10,511.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
				12	Oct 1, 2020	SYSTEM	(\$19,920.00)						
				12	Oct 1, 2020	SYSTEM	\$19,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
			- Total				\$0.00						
	Material - Total		- Total				\$0.00						
	- Total		- Total				\$0.00 \$0.00						
0900 · 0910		Material	- Total	4	Jun 3, 2020	SYSTEM	\$0.00						
	- Total TRUCK OR TRAILER MOUNTED	Material	- Total	4		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
	- Total TRUCK OR TRAILER MOUNTED	Material	- Total		2020 Jun 3,		\$0.00 \$0.00 (\$1,000.00)	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current					
	- Total TRUCK OR TRAILER MOUNTED	Material	- Total	4	2020 Jun 3, 2020 Jun 16,	SYSTEM	\$0.00 \$0.00 (\$1,000.00) \$1,000.00	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current					
	- Total TRUCK OR TRAILER MOUNTED	Material	- Total	5	Jun 16, 2020 Jun 16, 2020 Jun 16,	SYSTEM	\$0.00 \$0.00 (\$1,000.00) \$1,000.00	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current					
	- Total TRUCK OR TRAILER MOUNTED	Material	- Total	5	Jun 16, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,000.00) \$1,000.00 (\$1,000.00)	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current					
	- Total TRUCK OR TRAILER MOUNTED	Material	- Total	5 5 6	2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,000.00) \$1,000.00 (\$1,000.00) \$1,000.00	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 7 on the current					
	- Total TRUCK OR TRAILER MOUNTED	Material	- Total	5 5 6 6	2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,000.00) \$1,000.00 (\$1,000.00) \$1,000.00 (\$1,000.00)	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 7 on the current					
	- Total TRUCK OR TRAILER MOUNTED	Material	- Total	455667	2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,000.00) \$1,000.00 (\$1,000.00) \$1,000.00 (\$1,000.00)	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 7 on the current					
	- Total TRUCK OR TRAILER MOUNTED	Material	- Total	4556677	2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,000.00) \$1,000.00 (\$1,000.00) \$1,000.00 (\$1,000.00) \$1,000.00	Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 7 on the current					

Revision 4/1/2020 Page 35 of 49



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks			
		.,,,	Туре			_,					
0910	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material		9	Aug 18, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 31 on the current Payment Estimate.			
				10	Sep 3, 2020	SYSTEM	(\$1,000.00)				
				10	Sep 3, 2020	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
0910 -	- Total						\$0.00				
0920	CONSTRUCTION SIGNS	Material		1	Apr 16, 2020	SYSTEM	(\$15,366.00)				
				2	May 4, 2020	SYSTEM	(\$15,366.00)				
				2	May 4, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
				3	May 19, 2020	SYSTEM	(\$15,366.00)				
				3	May 19, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
				4	Jun 3, 2020	SYSTEM	(\$15,366.00)				
				4	Jun 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
				5	Jun 16, 2020	SYSTEM	(\$15,366.00)				
			5	Jun 16, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
				6	Jul 2, 2020	SYSTEM	(\$15,366.00)				
				6	Jul 2, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
				7	Jul 16, 2020	SYSTEM	(\$15,366.00)				
						7	Jul 16, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
				8	Aug 3, 2020	SYSTEM	(\$15,366.00)				
							8	Aug 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$15,366.00)				
				9	Aug 18, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 41 on the current Payment Estimate.			
				10	Sep 3, 2020	SYSTEM	(\$15,366.00)				
				10	Sep 3, 2020	SYSTEM	\$15,366.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.			
			- Total				(\$15,366.00)				

Revision 4/1/2020 Page 36 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
0920	Material - Total						(\$15,366.00)								
	CONSTRUCTION SIGNS	MaterialCredit		2	May 4, 2020	SYSTEM	\$15,366.00								
			- Total				\$15,366.00								
	MaterialCredit - Total						\$15,366.00								
	CONSTRUCTION SIGNS	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$15,366.00								
				2	May 4, 2020	woodsk1	(\$15,366.00)	This adjustment is being added to balance line item 0920 discrepancy amount.							
			MDPA - Tot	al			\$0.00								
	Other Item Adjustment - Total						\$0.00								
0920 -	- Total						\$0.00								
0930	FLAG ASSEMBLY	Material		1	Apr 16, 2020	SYSTEM	(\$140.00)								
				2	May 4, 2020	SYSTEM	(\$140.00)								
				2	May 4, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.							
				3	May 19, 2020	SYSTEM	(\$140.00)								
				3	May 19, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.							
				4	Jun 3, 2020	SYSTEM	(\$140.00)								
				4	Jun 3, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
								5	Jun 16, 2020	SYSTEM	(\$140.00)				
				5	Jun 16, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
				6	Jul 2, 2020	SYSTEM	(\$140.00)								
				6	Jul 2, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.							
				7	Jul 16, 2020	SYSTEM	(\$140.00)								
											7	Jul 16, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$140.00)								
					8	Aug 3, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.						
				9	Aug 18, 2020	SYSTEM	(\$140.00)								
				9	Aug 18, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 42 on the current Payment Estimate.							
				10	Sep 3, 2020	SYSTEM	(\$140.00)								
				10	Sep 3, 2020	SYSTEM	\$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.							

Revision 4/1/2020 Page 37 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0930		Material	- Total				(\$140.00)	
	Material - Total						(\$140.00)	
	FLAG ASSEMBLY	MaterialCredit		2	May 4, 2020	SYSTEM	\$140.00	
			- Total				\$140.00	
	MaterialCredit - Total						\$140.00	
	FLAG ASSEMBLY	Other Item Adjustment	MDPA	1	Apr 16, 2020	woodsk1	\$140.00	
				2	May 4, 2020	woodsk1	(\$140.00)	This adjustment is being added to balance line item 0180 discrepancy amount.
			MDPA - Tot	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0930 -	Total						\$0.00	
0940	CHANNELIZER (TRIM LINE)	Material		4	Jun 3, 2020	SYSTEM	(\$600.00)	
				4	Jun 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$600.00)	
				5	Jun 16, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$600.00)	
				6	Jul 2, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$600.00)	
				7	Jul 16, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$600.00)	
				8	Aug 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$600.00)	
				9	Aug 18, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$600.00)	
				10	Sep 3, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0940 -	· Total						\$0.00	
0950	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Material		1	Apr 16, 2020	SYSTEM	(\$7,000.00)	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			2	May 4, 2020	SYSTEM	(\$7,000.00)	
				2	May 4, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.

Revision 4/1/2020 Page 38 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0950	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Material	, , , , , , , , , , , , , , , , , , ,	3	May 19, 2020	SYSTEM	(\$7,000.00)	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			3	May 19, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				4	Jun 3, 2020	SYSTEM	(\$7,000.00)	
				4	Jun 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$7,000.00)	
				5	Jun 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$7,000.00)	
				6	Jul 2, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$7,000.00)	
				7	Jul 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$7,000.00)	
				8	Aug 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$7,000.00)	
				9	Aug 18, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$7,000.00)	
				10	Sep 3, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
			- Total				(\$7,000.00)	
	Material - Total					0)40==:	(\$7,000.00)	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit		2	May 4, 2020	SYSTEM	\$7,000.00	
			- Total				\$7,000.00	
	MaterialCredit - Total	Oth and	N.D.D.	4	Ann 10		\$7,000.00	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	Other Item Adjustment	MDPA		Apr 16, 2020	woodsk1	\$7,000.00	
	FURNISHED, CONTRACTOR RETAINED			2	May 4, 2020	woodsk1	(\$7,000.00)	This adjustment is being added to balance line item 0950 discrepancy amount.
			MDPA - Tot	al			\$0.00	
0000	Other Item Adjustment - Total						\$0.00	
0950 -							\$0.00	
0960	WORK ZONE TRAFFIC SIGNAL SYSTEM	Material		4	Jun 3, 2020	SYSTEM	(\$8,400.00)	
				4	Jun 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.

Revision 4/1/2020 Page 39 of 49



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
		Туре	Adjustment Type	Number	Date	Ву			
0960	WORK ZONE TRAFFIC SIGNAL SYSTEM	Material		5	Jun 16, 2020	SYSTEM	(\$8,400.00)		
				5	Jun 16, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
				6	Jul 2, 2020	SYSTEM	(\$8,400.00)		
				6	Jul 2, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
				7	Jul 16, 2020	SYSTEM	(\$8,400.00)		
					7	Jul 16, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$8,400.00)		
				8	Aug 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
				9	Aug 18, 2020	SYSTEM	(\$8,400.00)		
				9	Aug 18, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 49 on the current Payment Estimate.	
				10	Sep 3, 2020	SYSTEM	(\$8,400.00)		
				10	Sep 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun	
					2020			Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	
			- Total		2020		\$0.00	overridding Payment Estimate Exception 35 on the current	
	Material - Total		- Total		2020		\$0.00 \$0.00	overridding Payment Estimate Exception 35 on the current	
	Total		- Total				\$0.00 \$0.00	overridding Payment Estimate Exception 35 on the current	
0960 - 0970		Material	- Total	4	Jun 3, 2020	SYSTEM	\$0.00	overridding Payment Estimate Exception 35 on the current	
	Total TEMPORARY LONG-TERM RUMBLE	Material	- Total	4	Jun 3,	SYSTEM	\$0.00 \$0.00	overridding Payment Estimate Exception 35 on the current	
	Total TEMPORARY LONG-TERM RUMBLE	Material	- Total		Jun 3, 2020 Jun 3,		\$0.00 \$0.00 (\$3,600.00)	overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current	
	Total TEMPORARY LONG-TERM RUMBLE	Material	- Total	4	Jun 3, 2020 Jun 3, 2020 Jun 16,	SYSTEM	\$0.00 \$0.00 (\$3,600.00) \$3,600.00	overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current	
	Total TEMPORARY LONG-TERM RUMBLE	Material	- Total	5	Jun 3, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16,	SYSTEM	\$0.00 \$0.00 (\$3,600.00) \$3,600.00	overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 18 on the current	
	Total TEMPORARY LONG-TERM RUMBLE	Material	- Total	5 5	Jun 3, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,600.00) \$3,600.00 (\$3,600.00)	overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 18 on the current	
	Total TEMPORARY LONG-TERM RUMBLE	Material	- Total	5 5	Jun 3, 2020 Jun 3, 2020 Jun 16, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,600.00) \$3,600.00 (\$3,600.00) (\$3,600.00)	overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 24 on the current	
	Total TEMPORARY LONG-TERM RUMBLE	Material	- Total	5 5 6 6	Jun 3, 2020 Jun 3, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,600.00) \$3,600.00 (\$3,600.00) \$3,600.00 \$3,600.00	overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 24 on the current	
	Total TEMPORARY LONG-TERM RUMBLE	Material	- Total	455667	Jun 3, 2020 Jun 3, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,600.00) \$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00)	overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	
	Total TEMPORARY LONG-TERM RUMBLE	Material	- Total	4556677	Jun 3, 2020 Jun 3, 2020 Jun 16, 2020 Jul 2, 2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,600.00) \$3,600.00 (\$3,600.00) \$3,600.00 (\$3,600.00) \$3,600.00	overridding Payment Estimate Exception 35 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	

Revision 4/1/2020 Page 40 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
0970	TEMPORARY LONG-TERM RUMBLE	Material			2020														
	STRIPS			9	Aug 18, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 50 on the current Payment Estimate.											
				10	Sep 3, 2020	SYSTEM	(\$3,600.00)												
				10	Sep 3, 2020	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user woodsk1 overridding Payment Estimate Exception 36 on the current Payment Estimate.											
			- Total				\$0.00												
	Material - Total						\$0.00												
0970 -	- Total						\$0.00												
0990	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		4	Jun 3, 2020	SYSTEM	(\$2,424.00)												
				4	Jun 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.											
				5	Jun 16, 2020	SYSTEM	(\$2,424.00)												
				5	Jun 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk1 overridding Payment Estimate Exception 19 on the current Payment Estimate.											
				6	Jul 2, 2020	SYSTEM	(\$2,424.00)												
				6	Jul 2, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.											
				7	Jul 16, 2020	SYSTEM	(\$2,424.00)												
				7	Jul 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.											
															8	Aug 3, 2020	SYSTEM	(\$2,424.00)	
				8	Aug 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.											
				9	Aug 18, 2020	SYSTEM	(\$2,424.00)												
				9	Aug 18, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 51 on the current Payment Estimate.											
				10	Sep 3, 2020	SYSTEM	(\$2,424.00)												
														10	Sep 3, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	
				11	Sep 16, 2020	SYSTEM	(\$2,424.00)												
				11	Sep 16, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.											
			12	Oct 1, 2020	SYSTEM	(\$2,424.00)													
				12	Oct 1, 2020	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.											
			- Total				\$0.00												

Revision 4/1/2020 Page 41 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0990	Material - Total						\$0.00		
0990 -	Total						\$0.00		
1000	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		4	Jun 3, 2020	SYSTEM	(\$4,000.00)		
				4	Jun 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
				5	Jun 16, 2020	SYSTEM	(\$4,000.00)		
				5	Jun 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
				6	Jul 2, 2020	SYSTEM	(\$4,000.00)		
				6	Jul 2, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
				7	Jul 16, 2020	SYSTEM	(\$4,000.00)		
				7	Jul 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	
				8	Aug 3, 2020	SYSTEM	(\$4,000.00)		
				8	Aug 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	
					9	Aug 18, 2020	SYSTEM	(\$4,000.00)	
				9	Aug 18, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	
				10	Sep 3, 2020	SYSTEM	(\$4,000.00)		
				10	Sep 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	
				11	Sep 16, 2020	SYSTEM	(\$4,000.00)		
				11	Sep 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	
				12	Oct 1, 2020	SYSTEM	(\$4,000.00)		
				12	Oct 1, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
1000 -	Total						\$0.00		
1010	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		4	Jun 3, 2020	SYSTEM	(\$240.00)		
				4	Jun 3, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
				5	Jun 16, 2020	SYSTEM	(\$240.00)		
				5	Jun 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user woodsk1	

Revision 4/1/2020 Page 42 of 49



Line	Description	Adjustment	Other	Est.	Crooted	Created	Amount	Domarka																																				
Line	Description	Adjustment Type	Adjustment Type	Number	Created Date	By	Amount	Remarks																																				
1010	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material						overridding Payment Estimate Exception 21 on the current Payment Estimate.																																				
				6	Jul 2, 2020	SYSTEM	(\$240.00)																																					
				6	Jul 2, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk1 overridding Payment Estimate Exception 27 on the current Payment Estimate.																																				
				7	Jul 16, 2020	SYSTEM	(\$240.00)																																					
				7	Jul 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk overridding Payment Estimate Exception 29 on the current Payment Estimate.																																				
				8	Aug 3, 2020	SYSTEM	(\$240.00)																																					
						8	Aug 3, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk overridding Payment Estimate Exception 29 on the current Payment Estimate.																																		
				9	Aug 18, 2020	SYSTEM	(\$240.00)																																					
				9	Aug 18, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk overridding Payment Estimate Exception 53 on the current Payment Estimate.																																				
				10	Sep 3, 2020	SYSTEM	(\$240.00)																																					
				10	Sep 3, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk overridding Payment Estimate Exception 39 on the current Payment Estimate.																																				
				11	Sep 16, 2020	SYSTEM	(\$240.00)																																					
				11	Sep 16, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user woodsk overridding Payment Estimate Exception 27 on the current Payment Estimate.																																				
				12	Oct 1, 2020	SYSTEM	(\$240.00)																																					
				12	Oct 1, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user woodsk overridding Payment Estimate Exception 15 on the current Payment Estimate.																																				
			- Total				\$0.00																																					
	Material - Total						\$0.00																																					
1010 -							\$0.00																																					
1020	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		3	May 19, 2020	SYSTEM	(\$6,270.00)																																					
	BEADO			3	May 19, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user woodsk- overridding Payment Estimate Exception 15 on the current Payment Estimate.																																				
				4	Jun 3, 2020	SYSTEM	(\$6,270.00)																																					
				4	Jun 3, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk overridding Payment Estimate Exception 22 on the current Payment Estimate.																																				
				5	Jun 16, 2020	SYSTEM	(\$6,270.00)																																					
				5	Jun 16, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user woodsk overridding Payment Estimate Exception 22 on the current Payment Estimate.																																				
					f	6	6																				(•			((((1			6	Jul 2, 2020	SYSTEM	(\$6,270.00)	
				6	Jul 2, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 28 on the current																																				

Revision 4/1/2020 Page 43 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1020	4 IN. WHITE STANDARD WATERBORNE	Material	Туре					Payment Estimate.
.020	PAVEMENT MARKING PAINT, TYPE P BEADS	material		7	Jul 16, 2020	SYSTEM	(\$6,270.00)	T Cymru Louinaus.
				7	Jul 16, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$6,270.00)	
				8	Aug 3, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$6,270.00)	
				9	Aug 18, 2020	SYSTEM	\$6,270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$12,574.32)	
				10	Sep 3, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$12,574.32)	
				11	Sep 16, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$12,574.32)	
				12	Oct 1, 2020	SYSTEM	\$12,574.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			T-4-1					
			- Total				\$0.00	
	Material - Total						\$0.00	
	Material - Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	10	Sep 3, 2020	woodsk1		Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105%
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100%
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89 Total Adjustment = \$267.21
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89 Total Adjustment = \$267.21 White: 92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89 Total Adjustment = \$267.21 White: 92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74 7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay)
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = \$91.89 Total Adjustment = \$267.21 White: 92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74 7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89 Total Adjustment = \$267.21 White: 92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74 7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay)
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			10		woodsk1	\$0.00	63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105% Pay Adjustment) = (65,290.9 x .0055) = \$359.10 32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89 Total Adjustment = \$267.21 White: 92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74 7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes 2nd Mobilization & Application) 0.52%@ 80 = (30,488 x .0052) = (158.5' @ 80% Pay

Revision 4/1/2020 Page 44 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																						
1020		Other Item Adjustment	REFL - Tota				\$153.21																							
	Other Item Adjustment - Total						\$153.21																							
1020 -	Total						\$153.21																							
1030	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		3	May 19, 2020	SYSTEM	(\$1,760.00)																							
	PAINT, TIPE P BEADS			3	May 19, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																						
				4	Jun 3, 2020	SYSTEM	(\$1,760.00)																							
				4	Jun 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																						
				5	Jun 16, 2020	SYSTEM	(\$1,760.00)																							
				5	Jun 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user woodsk1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																						
				6	Jul 2, 2020	SYSTEM	(\$1,760.00)																							
				6	Jul 2, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.																						
				7	Jul 16, 2020	SYSTEM	(\$1,760.00)																							
				7	Jul 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																						
										8	Aug 3, 2020	SYSTEM	(\$1,760.00)																	
				8	Aug 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																						
				9	Aug 18, 2020	SYSTEM	(\$1,760.00)																							
				9	Aug 18, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.																						
				10	Sep 3, 2020	SYSTEM	(\$3,519.89)																							
				10	Sep 3, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user woodsk1 overridding Payment Estimate Exception 42 on the current Payment Estimate.																						
																										11	Sep 16, 2020	SYSTEM	(\$3,519.89)	
				11	Sep 16, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 30 on the current Payment Estimate.																						
				12	Oct 1, 2020	SYSTEM	(\$3,519.89)																							
				12	Oct 1, 2020	SYSTEM	\$3,519.89	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																						
			- Total				\$0.00																							
	Material - Total						\$0.00																							
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	10	Sep 3, 2020	woodsk1	\$267.21	Yellow: 63.78% @ 105 = (102,369 x .6378) = (65,290.9' @ 105%																						
	aivi, i ii E i DEADO							Pay Adjustment) = (65,290.9 x .0055) = \$359.10																						

Revision 4/1/2020 Page 45 of 49



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			Type					
1030		Other Item Adjustment						32.14% @ 100 = (102,369 x .3214) = (32,901.4' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)
								4.08% @ 80 = (102,369 x .0408) = (4,176.7' @ 80% Pay Adjustment) = (4,176.7 x .088) = -\$91.89
								Total Adjustment = \$267.21
								White:
								92.28%@ 105 = (30,488 x .9228) = (28,134.3' @ 105% Pay Adjustment) = (28,134.3 x .0055) = \$154.74
								7.2%@ 100 = (30,488 x .0720) = (2,195.1' @ 100% Pay) *(Also Includes 2nd Mobilization & Application)
								0.52%@80 = (30,488 x .0052) = (158.5' @ 80% Pay Adjustment) = (158.5 x .088) = -\$1.53
								Total Adjustment = \$153.21
								* Remaining Quantity From 2nd Mobilization & Application Paid @ 100%
			REFL - Tota	ıl			\$267.21	
	Other Item Adjustment - Total						\$267.21	
1030 -							\$267.21	
1080	MGS GUARDRAIL	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$1,493.80	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 3, 2020	SYSTEM	(\$1,493.80)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1080 -	Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$0.00 \$5,996.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	,	·		8	Aug 3, 2020	SYSTEM	(\$5,996.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1090 -							\$0.00	
1100	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	Apr 16, 2020	SYSTEM	\$6,040.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 3, 2020	SYSTEM	(\$6,040.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1100 -		Meterici		0	Aug 40	CVCTE!	\$0.00	
1130	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 18, 2020	SYSTEM	(\$575.00)	
				9	Aug 18, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$575.00)	
				10	Sep 3, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				11	Sep 16,	SYSTEM	(\$575.00)	

Revision 4/1/2020 Page 46 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1130	EMULSIFIED ASPHALT, SEAL COAT	Material		11	2020 Sep 16, 2020	SYSTEM	\$575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	Taymon Estimate.
	Material - Total						\$0.00	
1130 -	· Total						\$0.00	
1140	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 18, 2020	SYSTEM	(\$1,435.00)	
				9	Aug 18, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user woodsk1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$1,435.00)	
				10	Sep 3, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$1,435.00)	
				11	Sep 16, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$1,435.00)	
				12	Oct 1, 2020	SYSTEM	\$1,435.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1140 -	·Total						\$0.00 \$0.00	
1140 - 1150		Material		6	Jul 2, 2020	SYSTEM	\$0.00 \$0.00 (\$3,111.60)	
	Total SUPERSTRUCTURE REPAIR	Material		6		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
	Total SUPERSTRUCTURE REPAIR	Material			2020 Jul 2,		\$0.00 \$0.00 (\$3,111.60)	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6	2020 Jul 2, 2020 Jul 16,	SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6	Jul 16, 2020 Jul 16, 2020 Jul 16,	SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20)	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6 7 7	Jul 16, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20) \$6,223.20	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6 7 7 8 8	2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20) \$6,223.20	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 46 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6 7 7 8 8	2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20) \$6,223.20 (\$6,223.20) \$6,223.20	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 46 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6 7 7 8 8 8	2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 18, 2020 Aug 18,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20) \$6,223.20 (\$6,223.20) \$6,223.20	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Exception 81 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6 7 7 8 8 8	2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 18, 2020 Aug 18, 2020 Sep 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20) \$6,223.20 (\$6,223.20) \$6,223.20 (\$6,223.20)	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Exception 81 on the current
	Total SUPERSTRUCTURE REPAIR	Material		6 7 7 8 8 8 9 9	2020 Jul 2, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 18, 2020 Aug 18, 2020 Sep 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,111.60) \$3,111.60 (\$6,223.20) \$6,223.20 (\$6,223.20) \$6,223.20 (\$6,223.20) \$6,223.20	Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user woodsk1 overridding Payment Estimate Exception 46 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user woodsk1 overridding Payment Estimate Exception 81 on the current Payment Estimate.

Revision 4/1/2020 Page 47 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1150	SUPERSTRUCTURE REPAIR (UNFORMED)	Material						overridding Payment Estimate Exception 55 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$9,645.96)	
				12	Oct 1, 2020	SYSTEM	\$9,645.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user woodsk1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1150 -	Total						\$0.00	
1160	SLAB EDGE REPAIR (BRIDGES)	Material		5	Jun 16, 2020	SYSTEM	(\$7,361.70)	
				5	Jun 16, 2020	SYSTEM	\$7,361.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user woodsk1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				6	Jul 2, 2020	SYSTEM	(\$7,361.70)	
				6	Jul 2, 2020	SYSTEM	\$7,361.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$14,723.40)	
				7	Jul 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$14,723.40)	
				8	Aug 3, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user woodsk1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$14,723.40)	
				9	Aug 18, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user woodsk1 overridding Payment Estimate Exception 91 on the current Payment Estimate.
				10	Sep 3, 2020	SYSTEM	(\$14,723.40)	
				10	Sep 3, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user woodsk1 overridding Payment Estimate Exception 77 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$14,723.40)	
				11	Sep 16, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user woodsk1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$14,723.40)	
				12	Oct 1, 2020	SYSTEM	\$14,723.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user woodsk1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1160 -	Total						\$0.00	
1180	BRIDGE GUARDRAIL (THRIE BEAM)	Construction Stockpile		2	May 4, 2020	SYSTEM	\$29,370.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 2, 2020	SYSTEM	(\$14,685.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 3, 2020	SYSTEM	(\$14,685.00)	Payment Estimate Item Adjustment generated Stockpile Transaction

Revision 4/1/2020 Page 48 of 49



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1180		Construction Stockpile	- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1180 - Total						\$0.00		
Overall - Total						\$171,141.70		

Revision 4/1/2020 Page 49 of 49