

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 16, 2020

Progress Estimate Number	Contract ID 200221-F08	Pay Period Start October 1, 2020 Original Contract Amount \$2,496,782.69
10	Prime Contractor N.B. West Contract	ing Company Pay Period End October 15, 2020 Net Change Order Amount \$106,474.90
		Current Contract Amount \$2,603,257.59

Approval Date		By User
October 19, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by	HAYSB
October 19, 2020	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	vancef1
October 19, 2020	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 2, 2020	November 2, 2020		51.22%

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 10										
		This Estimate	Previous	To Date						
200221-F08										
	Total Posted Items Pay	\$560,265.43	\$773,111.20	\$1,333,376.63						
	Gross Item Adjustments	(\$24,219.91)	\$19,927.87	(\$4,292.04)						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
			\$793,039.07	\$1,329,084.59						
Contract Total Pa	ayable This Estimate:	\$536,045.52								

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3387	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$110,095.000	0.6	\$66,057.00
	0030	2079909	MISC.MODIFIED LINEAR GRADING, CLASS II	STA	\$489.500	151	\$73,914.50
	0033	2142000	FURNISHING ROCK FILL	CUYD	\$18.000	293.9	\$5,290.20
	0037	2143000	PLACING ROCK FILL	CUYD	\$10.250	293.9	\$3,012.48
	0070	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	TONS	\$74.900	2,084.7	\$156,144.03
	0100	4071005	TACK COAT	GAL	\$2.350	2,489	\$5,849.15
	0150	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	SQYD	\$5.900	409.6	\$2,416.64
	0320	8061005	ROCK DITCH CHECK	LF	\$11.500	2,240	\$25,760.00
	0350	8061019	SILT FENCE	LF	\$1.550	2,714	\$4,206.70
	5001	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$62.100	3,394.57	\$210,802.80
	5002	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	TONS	\$99.750	68.29	\$6,811.93

 Project J6S3387 - Total
 \$560,265.43

 Overall - Total
 \$560,265.43

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	<u>Adjustr</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3387	0033	FURNISHING ROCK FILL	Overrun			-293.9	\$18.00	(\$5,290.20)
	0033	FURNISHING ROCK FILL	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user haysb overridding Payment Estimate Exception 12 on the current Payment Estimate.	293.9	\$18.00	\$5,290.20
	0033	FURNISHING ROCK FILL	Overrun	Overrun	Will be on next change order.			(\$5,290.20)
	0037	PLACING ROCK FILL	Overrun			-293.9	\$10.25	(\$3,012.48)
	0037	PLACING ROCK FILL	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item	293.9	\$10.25	\$3,012.48

Revision 4/1/2020 Page 1 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 16, 2020

Progress Estimate Number
10 Contract ID 200221-F08 Pay Period Start October 1, 2020 Original Contract Amount \$2,496,782.69
Prime Contractor N.B. West Contracting Company Pay Period End October 15, 2020 Net Change Order Amount \$106,474.90
Current Contract Amount \$2,603,257.59

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
6S3387					Adjustment (0002) due to user haysb overridding Payment Estimate Exception 13 on the current Payment Estimate.			
	0037	PLACING ROCK FILL	Overrun	Overrun	Will be on next change order.			(\$3,012.48
	0040	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-725	\$11.40	(\$8,265.00
	0040	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user haysb overridding Payment Estimate Exception 1 on the current Payment Estimate.	725	\$11.40	\$8,265.00
	0070	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Other Item Adjustment	Asphalt Cement Price Adjustment				(\$5,206.54
	0100	TACK COAT	Material			-2,489	\$2.35	(\$5,849.15
	0100	TACK COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user haysb overridding Payment Estimate Exception 3 on the current Payment Estimate.	2,489	\$2.35	\$5,849.15
	0120	PAVED APPROACH, 8 IN.	Material			-725	\$70.00	(\$50,750.00
	0120	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user haysb overridding Payment Estimate Exception 5 on the current Payment Estimate.	725	\$70.00	\$50,750.00
	5001	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material			-3,394.57	\$62.10	(\$210,802.80
	5001	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user haysb overridding Payment Estimate Exception 2 on the current Payment Estimate.	3,394.57	\$62.10	\$210,802.80
	5001	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	Asphalt Cement Price Adjustment				(\$10,540.14)
	5002	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Other Item Adjustment	Asphalt Cement Price Adjustment				(\$170.55)
otal								(\$24,219.91)

Revision 4/1/2020 Page 2 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informati	on				
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J6S3387	FAS S502(6)	Resurface and add shoulders	TT	FRANKLIN	from Commercial Ave. to Mill Hill Road						
Totals by J	Job Numb	ers									
J6S3387	Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive Liquidated Damages Other Contract Adjustments		This Estimate \$560,265.43 (\$24,219.91) \$536,045.52	Previous \$773,111.20 \$19,927.87 \$793,039.07	To Date \$1,333,376.63 (\$4,292.04) \$1,329,084.59						
			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00							

Revision 4/1/2020 Page 3 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3387, Item 3040504, Project Item Line Number 0040, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with SL District material to resolve this exception.	HAYSB	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3387, Item 4020520, Project Item Line Number 5001, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	Working with SL District material to resolve this exception.	HAYSB	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3387, Item 4071005, Project Item Line Number 0100, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Working with SL District material to resolve this exception.	HAYSB	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3387, Item 4071005, Project Item Line Number 0100, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with SL District material to resolve this exception.	HAYSB	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3387, Item 6085008, Project Item Line Number 0120, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Working with SL District material to resolve this exception.	HAYSB	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3387, Item 6085008, Project Item Line Number 0120, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with SL District material to resolve this exception.	HAYSB	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3387, Item 6085008, Project Item Line Number 0120, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with SL District material to resolve this exception.	HAYSB	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3387, Item 6085008, Project Item Line Number 0120, Material Set 608500896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with SL District material to resolve this exception.	HAYSB	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3387, Item 6085008, Project Item Line Number 0120, Material Set 608500896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Working with SL District material to resolve this exception.	HAYSB	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3387, Item 6085008, Project Item Line Number 0120, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with SL District material to resolve this exception.	HAYSB	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3387, Item 6085008, Project Item Line Number 0120, Material Set 608500896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with SL District material to resolve this exception.	HAYSB	Overridden
Estimate Exception Type: Item Overrun: Contract 200221-F08, Contract Project J6S3387, Project Item Line Number 0033, Contract Line Item Number 0033, Item 2142000, Minor Item.	Will be on next change order.	HAYSB	Overridden
Estimate Exception Type: Item Overrun: Contract 200221-F08, Contract Project J6S3387, Project Item Line Number 0037, Contract Line Item Number 0037, Item 2143000, Minor Item.	Will be on next change order.	HAYSB	Overridden

Revision 4/1/2020 Page 4 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change	Total Current	Unit	Total Posted	Unit Price	Total Value POSTEI To Date (See report
OOMITOTO	140.		140.	Code		Quantity	Order	Quantity		Approved Qty		generated date)
221-F08	J6S3387	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.90	\$110,095.00	\$99,085.50
		0001	0020	2063000	CLASS 3 EXCAVATION	692.00	0.00	692.00	CUYD	692.00	\$15.40	\$10,656.8
		0001	0030	2079909	MISC.MODIFIED LINEAR GRADING, CLASS II	504.00	0.00	504.00	STA	403.00	\$489.50	\$197,268.5
		0001	0033	2142000	FURNISHING ROCK FILL	1,500.00	0.00	1,500.00	CUYD	1,793.90	\$18.00	\$32,290.2
		0001	0037	2143000	PLACING ROCK FILL	1,500.00	0.00	1,500.00	CUYD	1,793.90	\$10.25	\$18,387.4
		0001	0040	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,850.00	0.00	1,850.00	SQYD	725.00	\$11.40	\$8,265.0
		0001	0050	3102003	CRUSHED STONE (B)	2,170.00	0.00	2,170.00	SQYD	0.00	\$8.70	\$0.0
		0001	0060	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	304.00	0.00	304.00	TONS	0.00	\$207.45	\$0.0
		0001	0070	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	2,126.00	0.00	2,126.00	TONS	2,084.70	\$74.90	\$156,144.0
		0001	0080	4030006	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095B MIX)	5,299.00	-5,299.00	0.00	TONS	0.00	\$69.25	\$0.0
		0001	0090	4039910	MISC.2" FIBER REINFORCED SP125CLP W/ PG 76-22	8,345.00	0.00	8,345.00	TONS	0.00	\$77.30	\$0.0
		0001	0100	4071005	TACK COAT	10,866.00	0.00	10,866.00	GAL	2,489.00	\$2.35	\$5,849.1
		0001	0110	6042020	ADJUSTING BASIN OR INLET	2.00	0.00	2.00	EA	0.00	\$1,430.00	\$0.0
		0001	0120	6085008	PAVED APPROACH, 8 IN.	725.00	0.00	725.00	SQYD	725.00	\$70.00	\$50,750.0
		0001	0130	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.0
		0001	0140	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	196.00	-196.00	0.00	TONS	0.00	\$149.50	\$0.0
		0001	0150	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	10,553.00	0.00	10,553.00	SQYD	10,154.30	\$5.90	\$59,910.3
		0001	0160	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.25	\$29,000.00	\$7,250.0
		0001	0170	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED/RETAINED	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.0
		0001	0180	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$282,500.00	\$211,875.0
		0001	0190	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	60.00	0.00	60.00	LF	0.00	\$25.00	\$0.0
		0001	0200	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	2.00	0.00	2.00	EA	0.00	\$900.00	\$0.0
		0001	0210	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	56,052.00	0.00	56,052.00	LF	0.00	\$0.11	\$0.
		0001	0220	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	56,052.00	0.00	56,052.00	LF	0.00	\$0.11	\$0.
		0001	0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	5,161.00	0.00	5,161.00	SQYD	0.00	\$4.00	\$0.0
		0001	0240	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	387.00	0.00	387.00	STA	0.00	\$15.00	\$0.0
		0001	0250	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	252.00	0.00	252.00	STA	0.00	\$24.00	\$0.0
		0001	0260	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$3,575.00	\$0.0
		0001	0270	7250415	15 IN. PIPE GROUP C	1,274.00	0.00	1,274.00	LF	1,141.00	\$36.25	\$41,361.2
		0001	0280	7320815A	15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	74.00	0.00	74.00	EA	70.00	\$220.00	\$15,400.
		0001	0290	8051000A	SEEDING - COOL SEASON MIXTURES	19.00	0.00	19.00	ACRE	0.00	\$1,800.00	\$0.
		0001	0300	8061003	SEDIMENT TRAP EXCAVATION	105.00	0.00	105.00	CUYD	0.00	\$33.00	\$0.
		0001	0310	8061004	SEDIMENT TRAP ROCK	29.00	0.00	29.00	CUYD	0.00	\$55.00	\$0.
		0001	0320	8061005	ROCK DITCH CHECK	3,028.00	0.00	3,028.00	LF	2,489.00	\$11.50	\$28,623.
		0001	0330	8061016	SEDIMENT REMOVAL	442.00	0.00	442.00	CUYD	0.00	\$2.00	\$0.
		0001	0340	8061017	TEMPORARY SEEDING AND MULCHING	11.00	0.00	11.00	ACRE	0.00	\$1,100.00	\$0.
		0001	0350	8061019	SILT FENCE	50,474.00	0.00	50,474.00	LF	2,854.00	\$1.55	\$4,423.
		0010	0360	6061060	MGS GUARDRAIL	574.00	0.00	574.00	LF	0.00	\$24.00	\$0.
		0010	0370	6061075	MGS LONG SPAN GUARDRAIL SECTION	4.00	0.00	4.00	EA	0.00	\$2,950.00	\$0.
		0010	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	0.00	\$2,800.00	\$0.
		0001	5001	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	0.00		5,299.00	TONS	3,394.57	\$62.10	\$210,802
		0001	5002	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	0.00	1,741.00	1,741.00	TONS	1,734.67	\$99.75	\$173,033.
					ate as of Report Generated Date							\$1,333,376.6

Page 5 of 9 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	10/12/20	10/16/20	0.60	LS		0+00		286+00		
0030	2079909	MISC. GRADING	10/12/20	10/16/20	151.00	STA	East and west bound.	0+00		286+10		
0033	2142000	FURNISHING ROCK FILL	10/12/20	10/16/20	293.90	CUYD	East bound	27+00		30+80		
0037	2143000	PLACING ROCK FILL	10/12/20	10/16/20	293.90	CUYD	East bound.	27+00		30+80		
0070	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS	10/6/20	10/16/20	678.74	TONS	East bound	0+43		205+00		
			10/7/20	10/16/20	283.50	TONS	East bound.	205+00		255+00		
			10/8/20	10/16/20	112.25	TONS	East bound.	255+00		286+10		
				10/16/20	1,010.21	TONS	West bound.	286+10		0+00		
0100	4071005	TACK COAT	10/14/20	10/16/20	1,426.00	GAL	West bound lane	0+43		230+00		
			10/15/20	10/16/20	419.00	GAL	West bound	230+00		285+80		
				10/16/20	644.00	GAL	East bound	285+80		200+00		
0150	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVT REPAIR	10/13/20	10/16/20	409.60	SQYD	East and west bound	18+00		22+00		
0320	8061005	ROCK DITCH CHECK	10/12/20	10/16/20	2,240.00	LF	Various locations.	0+00		286+10		
0350	8061019	SILT FENCE	10/12/20	10/16/20	2,714.00	LF	Various locations.	0+00		286+10		
5001	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	10/14/20	10/16/20	1,691.09	TONS	West bound lane	0+43		230+00		
			10/15/20	10/16/20	671.17	TONS	West bound	230+00		285+80		
				10/16/20	1,032.31	TONS	East bound	285+80		200+00		
5002	6133020	FURN & PLACE BIT. MATL FOR CL C PARTIAL	10/13/20	10/16/20	68.29	TONS	East and west bound lanes.	19+00		22+00		

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 6 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0033	FURNISHING ROCK FILL	Material		6	Aug 17, 2020	SYSTEM	(\$15,942.60)	
				6	Aug 17, 2020	SYSTEM	\$15,942.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user haysb overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Sep 1, 2020	SYSTEM	(\$15,942.60)	
				7	Sep 2, 2020	SYSTEM	\$15,942.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user haysb overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Sep 16, 2020	SYSTEM	(\$26,611.20)	
				8	Sep 16, 2020	SYSTEM	\$26,611.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user haysb overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	FURNISHING ROCK FILL	Overrun	Overrun	10	Oct 16, 2020	SYSTEM	(\$5,290.20)	
				10	Oct 16, 2020	SYSTEM	\$5,290.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user haysb overridding Payment Estimate Exception 12 on the current Payment Estimate.
				10	Oct 19, 2020	HAYSB	(\$5,290.20)	Will be on next change order.
			Overrun - To	otal			(\$5,290.20)	
	Overrun - Total						(\$5,290.20)	
0033 -	· Total						(\$5,290.20)	
0037	PLACING ROCK FILL	Overrun	Overrun	10	Oct 16, 2020	SYSTEM	(\$3,012.48)	
				10	Oct 16, 2020	SYSTEM	\$3,012.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user haysb overridding Payment Estimate Exception 13 on the current Payment Estimate.
				10	Oct 19, 2020	HAYSB	(\$3,012.48)	Will be on next change order.
			Overrun - To	otal			(\$3,012.48)	
	Overrun - Total						(\$3,012.48)	
0037 -	·Total						(\$3,012.48)	
0040	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		8	Sep 16, 2020	SYSTEM	(\$8,217.12)	
				8	Sep 16, 2020	SYSTEM	\$8,217.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user haysb overridding Payment Estimate Exception 2 on the current Payment Estimate.
				9	Oct 2, 2020	SYSTEM	(\$8,265.00)	
				9	Oct 2, 2020	SYSTEM	\$8,265.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user haysb overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Oct 16, 2020	SYSTEM	(\$8,265.00)	
				10	Oct 16, 2020	SYSTEM	\$8,265.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user haysb overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	·Total						\$0.00	
0070	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Other Item Adjustment	ACAD		Oct 16, 2020	HAYSB	(\$5,206.54)	
			ACAD - Tota	al			(\$5,206.54)	

Revision 4/1/2020 Page 7 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0070	Other Item Adjustment - Total						(\$5,206.54)	
0070 -	Total						(\$5,206.54)	
0100	TACK COAT	Material		10	Oct 16, 2020	SYSTEM	(\$5,849.15)	
				10	Oct 16, 2020	SYSTEM	\$5,849.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user haysb overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
0400	Material - Total - Total						\$0.00	
		Matarial			0 10	OVOTEM	\$0.00	
0120	PAVED APPROACH, 8 IN.	Material		8	Sep 16, 2020	SYSTEM	(\$50,449.00)	
				8	Sep 16, 2020	SYSTEM	\$50,449.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user haysb overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Oct 2, 2020	SYSTEM	(\$50,750.00)	
				9	Oct 2, 2020	SYSTEM	\$50,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user haysb overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Oct 16, 2020	SYSTEM	(\$50,750.00)	
				10	Oct 16, 2020	SYSTEM	\$50,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user haysb overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0120 -	Total						\$0.00	
0280	15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	Material		7	Sep 1, 2020	SYSTEM	(\$14,960.00)	
				7	Sep 2, 2020	SYSTEM	\$14,960.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user haysb overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Sep 16, 2020	SYSTEM	(\$15,400.00)	
				8	Sep 16, 2020	SYSTEM	\$15,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user haysb overridding Payment Estimate Exception 10 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0280 - 0320	ROCK DITCH CHECK Material	Material		6	Aug 17,	SYSTEM	\$0.00 (\$943.00)	
				6	2020 Aug 17, 2020	SYSTEM	\$943.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user haysb overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Sep 1, 2020	SYSTEM	(\$2,346.00)	Estimate.
				7	Sep 2, 2020	SYSTEM	\$2,346.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user haysb overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Sep 16, 2020	SYSTEM	(\$2,863.50)	
				8	Sep 16, 2020	SYSTEM	\$2,863.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user haysb overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	

Revision 4/1/2020 Page 8 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0320	Material - Total						\$0.00	
0320 -	Total						\$0.00	
0350	SILT FENCE	Material		7	Sep 1, 2020	SYSTEM	(\$217.00)	
				7	Sep 2, 2020	SYSTEM	\$217.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user haysb overridding Payment Estimate Exception 4 on the current Payment Estimate.
				8	Sep 16, 2020	SYSTEM	(\$217.00)	
				8	Sep 16, 2020	SYSTEM	\$217.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user haysb overridding Payment Estimate Exception 12 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0350 -	Total						\$0.00	
0360	MGS GUARDRAIL	Construction Stockpile		1	Jun 3, 2020	SYSTEM	\$6,118.84	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total						\$6,118.84	
	Construction Stockpile - Total						\$6,118.84	
0360 -	Total						\$6,118.84	
0370	MGS LONG SPAN GUARDRAIL SECTION	Construction Stockpile		1	Jun 3, 2020	SYSTEM	\$4,733.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$4,733.00	
	Construction Stockpile - Total						\$4,733.00	
0370 -	Total						\$4,733.00	
0380	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	Jun 3, 2020	SYSTEM	\$12,080.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total						\$12,080.00	
	Construction Stockpile - Total						\$12,080.00	
0380 -	Total						\$12,080.00	
5001	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		10	Oct 16, 2020	SYSTEM	(\$210,802.80)	
				10	Oct 16, 2020	SYSTEM	\$210,802.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user haysb overridding Payment Estimate Exception 2 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		ACAD	10	Oct 16, 2020	HAYSB	(\$10,540.14)	
	ACAD - Total						(\$10,540.14)	
	Other Item Adjustment - Total						(\$10,540.14)	
5001 -							(\$10,540.14)	
5002	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Other Item Adjustment	ACAD		Jul 16, 2020	HAYSB	(\$3,003.97)	
			1015	10	Oct 16, 2020	HAYSB	(\$170.55)	
	ACAD - Total						(\$3,174.52)	
	Other Item Adjustment - Total					(\$3,174.52)		
	Total					(\$3,174.52)		
Overa	II - Total					(\$4,292.04)		

Revision 4/1/2020 Page 9 of 9