

# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2020

· ·	timate Number 11	Contract ID Prime Contractor	200221-H05 Phillips Hardy, Ind	Pay Period Star c. Pay Period End			Net Change	ontract Amount e Order Amount entract Amount	\$1,481,739.65 \$4,515.00 \$1,486,254.65	
Approval Date									By User	
October 1, 2020			Generated and A	Office Level by	ROTHEL					
October 1, 2020		Re	viewed and Approv	gineer Level by	PULLIA					
October 2, 2020			R	Office Level by	greggd <sup>2</sup>					
Original Co	mpletion Date	Current Comp	oletion Date	Actual Comple	tion Date	%	of Current	Contract Amoun	t Complete	
Septemb	per 1, 2020	September	20, 2020	September 19	9, 2020			99.81%		
Con	tract Information	al Dates	Milestones							
Date Description	Original Completion Date	Current Completion Date	Date D	escription	Original Completion Date		Current ompletion Date	Days Remainin on Milestone	g Diary Charge Days	
Acceptance Date			Milestone - Con JSP-13-01B J9		September 1, 2020	Sept 2020	ember 1,	-	30	
Awarded Date	March 4, 2020	March 4, 2020								
Letting Date	February 21, 2020	February 21, 2020								
Notice to Proceed Date	April 6, 2020	April 6, 2020								
Open to Traffic Date	September 16, 2020	September 16, 2020								
Work Began Date	April 27, 2020	April 27, 2020								

Contract Total Pay	y For Estimate No. 11			
		This Estimate	Previous	To Date
200221-H05				
	Total Posted Items Pay	\$96,337.70	\$1,387,100.60	\$1,483,438.30
	Gross Item Adjustments	(\$131.70)	(\$3,066.14)	(\$3,197.84)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	(\$25,200.00)	(\$25,200.00)
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$ <mark>1,358,834.46</mark>	\$1,455,040.46
Contract Total Pay	yable This Estimate:	\$96,206.00		

## Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3385	0030	2031000	CLASS A EXCAVATION	CUYD	\$17.500	100	\$1,750.00
	0040	2035500	EMBANKMENT IN PLACE	CUYD	\$30.000	500	\$15,000.00
	0050	2036000	COMPACTING EMBANKMENT	CUYD	\$4.000	100	\$400.00
	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	CUYD	\$40.000	507	\$20,280.00
	0120	6113040	PLACING TYPE 2 ROCK BLANKET	CUYD	\$25.000	507	\$12,675.00
	0190	6206000C	$4\ \mbox{IN.}$ WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.350	1,832	\$641.20
	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.350	590	\$206.50
	0220	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	SQYD	\$2.500	1,510	\$3,775.00
	0240	8051000A	SEEDING - COOL SEASON MIXTURES	ACRE	\$3,400.000	1	\$3,400.00
	0250	8061005	ROCK DITCH CHECK	LF	\$30.000	65	\$1,950.00
	0280	8061050	TYPE C BERM	LF	\$30.000	515	\$15,450.00
	0290	8069905	MISC.FIBER REINFORCED MATRIX	SQYD	\$5.000	562	\$2,810.00
	0330	6063017	TYPE C CRASHWORTHY END TERMINAL	EA	\$18,000.000	1	\$18,000.00
Project J98	3385 - Tot	al					\$96,337.70

Revision 4/1/2020 Page 1 of 14



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2020

i regreee Eetimate rtamber	Contract ID	200221-H05	•		Original Contract Amount	. , ,
44	Prime Contractor	Phillips Hardy, Inc.	Pay Period End	September 30, 2020	Net Change Order Amount	\$4,515.00
11					<b>Current Contract Amount</b>	\$1,486,254.65

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
Overall - To	Overall - Total						\$96,337.70

### **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract

Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
S3385	0030	CLASS A EXCAVATION	Price	Туре	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	100	(\$0.08)	(\$7.80)
	0040	EMBANKMENT IN PLACE	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	500	(\$0.14)	(\$68.25)
	0040	EMBANKMENT IN PLACE	Material			-2,241	\$30.00	(\$67,230.00)
	0040	EMBANKMENT IN PLACE	gene		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.	2,241	\$30.00	\$67,230.00
	0050	COMPACTING EMBANKMENT	Material			-529	\$4.00	(\$2,116.00)
	0050	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.	529	\$4.00	\$2,116.00
	0100	TACK COAT	Material			-40	\$18.50	(\$740.00)
	0100	TACK COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.	40	\$18.50	\$740.00
	0190	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun			-132	\$0.35	(\$46.20)
	0200	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun			-27	\$0.35	(\$9.45)
	0240	SEEDING - COOL SEASON MIXTURES	Material			-1	\$3,400.00	(\$3,400.00)
	0240	SEEDING - COOL SEASON MIXTURES	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 15 on the current Payment Estimate.	1	\$3,400.00	\$3,400.00
	0280	TYPE C BERM	Material			-515	\$30.00	(\$15,450.00)
	0280	TYPE C BERM	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 20 on the current Payment Estimate.	515	\$30.00	\$15,450.00
	0290	MISC.	Material			-562	\$5.00	(\$2,810.00)
	0290	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 21 on the current Payment Estimate.	562	\$5.00	\$2,810.00

Revision 4/1/2020 Page 2 of 14



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2020

Progress Estimate Number	Contract ID		•		Original Contract Amount	
11	Prime Contractor	Phillips Hardy, Inc.	Pay Period End	September 30, 2020	Net Change Order Amount	\$4,515.00
11					Current Contract Amount	\$1,486,254.65

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
9S3385	0310	MGS VERTICAL CONCRETE BARRIER TRANSITION	Material			-3	\$2,950.00	(\$8,850.00
	0310	MGS VERTICAL CONCRETE BARRIER TRANSITION	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 11 on the current Payment Estimate.	3	\$2,950.00	\$8,850.00
	0320	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material			-3	\$2,850.00	(\$8,550.00)
	0320	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 12 on the current Payment Estimate.	3	\$2,850.00	\$8,550.00
	0330	TYPE C CRASHWORTHY END TERMINAL	Material			-1	\$18,000.00	(\$18,000.00)
	0330	TYPE C CRASHWORTHY END TERMINAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user rothel overridding Payment Estimate Exception 13 on the current Payment Estimate.	1	\$18,000.00	\$18,000.00
	0350	BRIDGE APPROACH SLAB (MINOR ROAD)	Material			-122	\$140.00	(\$17,080.00)
	0350	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 4 on the current Payment Estimate.	122	\$140.00	\$17,080.00
	0470	SLAB ON CONCRETE BEAM	Material			-305.455	\$377.00	(\$115,156.54)
	0470	SLAB ON CONCRETE BEAM	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user rothel overridding Payment Estimate Exception 14 on the current Payment Estimate.	305.455	\$377.00	\$115,156.54
otal								(\$131.70

Revision 4/1/2020 Page 3 of 14



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Informatio	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9S3385	FAS S702(48)	Bridge replacement	J	OZARK	over Lick Creek		
Totals by J	Job Numbe	rs					
J9S3385	Deete	d Item Pay			This Estimate	Previous	To Date
		ltem Adjustm		Item Pay	\$96,337.70 (\$131.70)	\$1,387,100.60 (\$3,066.14)	\$1,483,438.30 (\$3,197.84)
	Incent	ilvo	Gross	s item Pay	<b>\$96,206.00</b> \$0.00	\$1,384,034.46 \$0.00	\$1,480,240.46 \$0.00
	Disino				\$0.00	(\$25,200.00)	(\$25,200.00)
		lated Damages Contract Adju			\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00

Revision 4/1/2020 Page 4 of 14



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

seffendenisment, Acceptance Actions Corrects (2000ACCS) in instificiation.  Estimate Encoption Type: Instificiation Market Project (1983AS), Item (2000DIC). Project Item Line Number (2005), Malerial See (2000DIC). Asserted (2000ACCS). Compared Sol for Subgraphs (2000ACCS). Asserted (2000ACCS). Compared Sol for Subgraphs (2000ACCS). Asserted (2000ACCS). Compared Sol for Subgraphs (2000ACCS). Asserted (2000	Exceptions (Discrepancies) This Estimate Period			
Names 0400, Materials Set 2005000000, Material Colonoxics Companies Sol for Subgrade Terminaturent, Accordance Author Care Description Type: Insufficient Materials Proposed BioSolid, Inter 2005000, Project Internal Engine Control	Exceptions / Discrepencies	Explanation		Status
Number 0003, Material Sez 2008000000, Material Sez 20080000000000000000000000000000000000	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 2035500, Project Item Line Number 0040, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Number Of Di. Material Set 407 (1905) A largerial Set 507 (1905) A largeria	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Number COSO, Material Set 6303 11 Asia, Material 10 CATAMETREP - Preformed Tiber Expansion John Mad (a). Acceptions of Conformation Cost Materials Project alexagolates (a). Acceptions of Cost Grant (a). Acception of Cost Grant (a). Accepting Cost Grant (a). Accepting Cost Grant (a). Accepting Co	Number 0100, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0250, Material Set 95031011AB, Material 1005FACCNS, CB - Natural Sand for Conc Class B, Acceptance Action Genetic 1005FACCNS, CB is statificated.  Estimate Exception Type: Insufficient Materials: Project 958338; Item 5031011A, Project Item Line Number 0250, Material set 9503011AB, Anterial 1005CM, Material 1005CM, Materi	Number 0350, Material Set 5031011A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl		ROTHEL	Overridden
Number 0350, Material Set 5031011A96, Material DOCCALL.D10 - Masony 11 Max LSIDO, Acceptance Action of "Masony 12 Market 1985 1986 1986 1986 1986 1986 1986 1986 1986	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 5031011A, Project Item Line Number 0350, Material Set 5031011A96, Material 1005FACCNSCB - Natural Sand for Conc Class B, Acceptance Action Generic 1005FACCNSCB is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0350, Material Set 5031011A86, Material 1058PSBB - Polyetylene Sheeling for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.  Estimate Exception Type: Insufficient Materials: Project J853338, Item 5031011A, Project Item Line Number 0350, Material 501001058, Material 5010001058, Material 501001058, Material 5010001058, Material 5010001058, Material 50100010000000000000000000000000000000	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 5031011A, Project Item Line Number 0350, Material Set 5031011A96, Material 1005CMLD10 - Masonry 1" Max LS/DO, Acceptance Action 1" Masonry LS/DO is insufficient.		ROTHEL	Overridden
Number 0350, Material's et 5031011A96, Material St 1031011A96, Material St 1031011A96, Material St 1031011A96, Material St 1030101A96, Material 1030RSDFEC42M2 - Rein Steel EC No. 7M22 G 60M20 @. Acceptance Action Generic 1012DMCRPE. 04 is insufficient.  Estimate Exception Type: Insufficient Materials: Project J983386, Item 905101A, Project Item Line Number 0350, Material St 030101A96, Material 1030RSDFEC42M2 - Rein Steel EC No. 7M22 G 60M20 @. Acceptance Action Generic ReisBellaria in simufficient.  Estimate Exception Type: Insufficient Materials: Project J983385, Item 9051070, Project Item Line Number 0310, Material St 060107096, Material 1040GRCW. A creatworthy End Terminal Type A. Acceptance Action Generic 1040GRCW. A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J983385, Item 9051007, Project Item Line Number 0330, Material 1040GRCW. A creatworthy End Terminal Type A. Acceptance Action Generic 1040GRCW. A is insufficient.  Estimate Exception Type: Insufficient Materials: Project J983385, Item 9053017, Project Item Line Number 0330, Material 1040GRCW. A creatworthy End Terminal Type A. Acceptance Action Generic 1040GRCW, is insufficient.  Estimate Exception Type: Insufficient Materials: Project J983385, Item 9053007, Project Item Line Number 0340, Material St 06003199, Material 1040GRCW. C crastworthy End Terminal Type CA. Acceptance Action Generic 040GRCW, is insufficient.  Estimate Exception Type: Insufficient Materials: Project J983385, Item 9051000A, Project Item Line Number 0240, Material St 0600031096, Material 9010CRC Agnorular Line -Effective Nuterializer, Acceptance Action Generic 0600TCE20MA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J983385, Item 9051000A, Project Item Line Number 0240, Material St 06051000A96, Material 9010CRC Agnorular Line -Effective Nuterializer, Acceptance Action Generic 0600TA96, Material 9010CRCA	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 5031011A, Project Item Line Number 0350, Material Set 5031011A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.		ROTHEL	Overridden
Number 0350, Material Set 05031011A96, Material 1013DMCRPE. A4 - Underdrain Corrugated PE 4' (100mm). Acceptance Action Generic 1013DMCRPE. D4 is insufficient.  Estimate Exception Type: Insufficient Materials: Project J853385, Item 8031011A, Project Item Line Number 0350, Material Set 050101 A66, Material 10305RSPECA/2422 - Fane Isbel EC No. 7/M22 G7 60/M420 (@. Acceptance Action Generic ReSteelBars is insufficient.  Estimate Exception Type: Insufficient Materials: Project J853385, Item 80610170, Project Item Line Number 0310, Material Set 05010170 is insufficient.  Estimate Exception Type: Insufficient Materials: Project J853385, Item 8063014, Project Item Line Number 0320, Material Set 06030148, Material 1040GRDA Grashworthy End Terminal Type A. Acceptance Action Generic 1040GRCW As insufficient.  Estimate Exception Type: Insufficient Materials: Project J853385, Item 8063014, Project Item Line Number 0330, Material Set 06030148, Material 1040GRCW A Crashworthy End Terminal Type A. Acceptance Action Generic 1040GRCW Si insufficient.  Estimate Exception Type: Insufficient Materials: Project J853385, Item 8063014, Project Item Line Number 0330, Material Set 06030176, Material 1040GRCW Crashworthy End Terminal Type C. Acceptance Action Generic 1040GRCW Si insufficient.  Estimate Exception Type: Insufficient Materials: Project J853385, Item 805100A, Project Item Line Number 0470, Material Set 070402296, Material 0501CCBMDA - Concrete, Modified B-2 wWirk. Acceptance Action Generic 0501CCBMDA - Si insufficient.  Estimate Exception Type: Insufficient Materials: Project J853385, Item 8051000A, Project Item Line Number 0400, Material Set 8051000A96, Material 80810AG - Agricultural Lime - Effective Nuetralizer, Acceptance Action Generic 0501CCBMDA - Si insufficient.  Estimate Exception Type: Insufficient Materials: Project J853385, Item 8051000A, Project Item Line Number 0400, Material Set 8051000A96, Material 808107CB, Project Item Line Number 0400, Material Set 8051000A96, Material 80807CB, Project I	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 5031011A, Project Item Line Number 0350, Material Set 5031011A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Number 039.0 Material Set 6031011A96, Material 1036RSDFEC4ZM22 - Rein Steel EC No. 7M/22 G 60M/22 @ Acceptance Action Generic Residealises in issufficient  Estimate Exception Type: Insufficient Materials: Project JISS3385, Item 6061070, Project Item Line Number 0310, Material Set 606107096, Material 1040GRAB - Bridge Anchor Section, Acceptance Action Generic 1040GRAB is insufficient.  Estimate Exception Type: Insufficient Materials: Project JISS3385, Item 6063014, Project Item Line Number 0300, Material Set 606301796, Material 1040GRCW.A - Constituently End Terminal Type A, Acceptance Action Generic 1040GRAB - Bridge Anchor Section, Acceptance Acceptance Action Generic 1040GRAB - Bridge Anchor Section, Acceptance Acceptance Action Generic 1040GRAB - Bridge Anchor Section, Acceptance Acceptance Action Generic 1040GRAB - Bridge Anchor Section, Acceptance Acceptance Action Generic 1040GRAB - Bridge Anchor Section, Acceptance Acceptance Action Generic 1040GRAB - Bridge Anchor Section, Acceptance Acceptance Action Generic 105031CISS - Bridge Anchor Section, Material Set 7043229, Bridgerial 6010CGRAB - Concrete, Modified B-2 wAlir, Acceptance Action Generic 0801CCISMBA insufficient.  Estimate Exception Type: Insufficient Materials: Project JISS3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000AS, Material 901AG - Agricultural Lime - Effective Nuctralizer, Acceptance Action Generic 0801AG is insufficient.  Estimate Exception Type: Insufficient Materials: Project JISS3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000AS, Material 9001AG - Agricultural Lime - Effective Nuctralizer, Acceptance Action Generic 0800AS and Material 9001AG - Agricultural Lime - Effective Nuctralizer, Acceptance Action Generic 0800AS and Material 9000AS, Item 8051000A, Project Item Line Number 0240, Material Set 8061000AS, M	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 5031011A, Project Item Line Number 0350, Material Set 5031011A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0310, Material Set 606107096, Material 14040GRAB - Bridge Anchor Section, Acceptance Action Generic 1040GRAB is insufficient.  Estimate Exception Type: Insufficient Materials: Project J983395, Item 6063014, Project Item Line Number 1030, Material Set 6063014, Material Set 6063014, Project Item Line Number 0300, Material Set 6063014, Set January 1040GRCW. As insufficient.  Estimate Exception Type: Insufficient Materials: Project J983385, Item 6063017, Project Item Line Number 0303, Material Set 6063017, Project J983385, Item 6063017, Project Item Line Number 0400, Material Set 6063017, Material Set 6063017, Project Item Line Number 0470, Material Set 7034222, Project J983385, Item 7034222, Project Item Line Number 0470, Material Set 703422266, Material 6081046, Agricultural Line = Effective Nucleralizer, Acceptance Action Generic 05010C82MDA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J983385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 6801AG - Agricultural Line = Effective Nucleralizer, Acceptance Action Generic 0501AG is insufficient.  Estimate Exception Type: Insufficient Materials: Project J983385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0801AG - Agricultural Line = Effective Nucleralizer, Acceptance Action Generic 0801AG is insufficient.  Estimate Exception Type: Insufficient Materials: Project J983385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.  Estimate Exception Type: Insufficient Materials: Project J983385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 8080MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.  Estimate Exception Type: Insufficient Materials: Project J983385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 8080MLST - Mulch Straw (Vegetative Mulch), Acceptance Ac	Number 0350, Material Set 5031011A96, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0200, Material Set 608301496, Material 1040GRCW.A is instificient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8063017, Project Item Line Number 0330, Material Set 806301796, Material 1040GRCW.C - Crashworthy End Terminal Type C, Acceptance Action Generic 1040GRCW.C is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 804222, Project Item Line Number 0470, Material Set 806301796, Material Set 80630004, Material Set 806300	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 6061070, Project Item Line Number 0310, Material Set 606107096, Material 1040GRAB - Bridge Anchor Section, Acceptance Action Generic 1040GRAB is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0240, Material Set 8065001796, Material 1040CRCW. C Crashworthy End Terminal Type C. Acceptance Action Generic 0400CRCW. C. is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 703422286, Material 0501CCB2MDs in sufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 30416A - Agricultural Lime - Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 8001F2 - Fertilizer, Acceptance Action Generic 0801AG is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 8002MLST - Fertilizer, Acceptance Action Generic 0802MLSP is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0802MLST - Auchien Set 805100A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLSP is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0802MLST is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8061050, Project Item Line Number 0240, Material Set 806105096, Material 8065CPC M - Fiber Matrix for Erosion Blankets, Accion Generic 0806TEC is insufficient.  Estimate Exception Type: Insufficient Materials	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 6063014, Project Item Line Number 0320, Material Set 606301496, Material 1040GRCWA - Crashworthy End Terminal Type A, Acceptance Action Generic 1040GRCWA is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0470, Material Set 703422296, Material 0501CCBZMDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCBZMDA is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0801FZ - Insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLSP is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 08058D - Grass Seed -Seed, Acceptance Action Generic 08058D is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8061050, Project Item Line Number 0240, Material Set 806105096, Materia	Number 0330, Material Set 606301796, Material 1040GRCWC - Crashworthy End Terminal Type C,	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0240, Material Set 8051000A96, Material 0801AG - Agricultural Lime - Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.  No Remark was entered by Engineer  No Remark was entered by Engineer  ROTHEL Overridden Number 0240, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.  No Remark was entered by Engineer  No Remark was entered by Engineer  ROTHEL Overridden Number 0240, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0250, Material Set 805105096, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805FEC is insufficient.  No Remark was entered by Engineer  No Remark was entered by Engineer  No Remark was entered by Engineer  ROTHEL Overridden Number 0290, Material 3806ECFM - Fiber Matrix for Erosion Blankets, Acceptance Action Generic 3806ECFM is insufficient.  Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item Line Number 0190, Contract Line Item Number 0190, Unter 8206000C, Minor Item.  Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item No Remark was entered b	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 7034222, Project Item Line Number 0470, Material Set 703422296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0240, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.  No Remark was entered by Engineer  ROTHEL Overridden Number 0240, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0805SD - Grass Seed - Seed, Acceptance Action Generic 0802MLST is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0280, Material Set 8051000A96, Material 0805SD - Grass Seed - Seed, Acceptance Action Generic 0805SD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8061050, Project Item Line Number 0280, Material Set 806105096, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8069905, Project Item Line Number 0290, Material Set 806905, Material 3806ECFM - Fiber Matrix for Erosion Blankets, Acceptance Action Generic 3806ECFM is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8069905, Project Item Line Number 0190, Contract Line Item Number 0190, Item 6206000C, Minor Item.  No Remark was entered by Engineer  ROTHEL Acknowledged Line Number 0190, Contract 200221-H05, Contract Project J9S3385, Project Item No Remark was entered by Engineer	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0240, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8061050, Project Item Line No Remark was entered by Engineer  No Remark was entered by Engineer  No Remark was entered by Engineer  ROTHEL Overridden  No Remark was entered by Engineer  ROTHEL Overridden  No Remark was entered by Engineer  No Remark was entered by Engineer  ROTHEL Overridden  No Remark was entered by Engineer  ROTHEL Acknowledged  Line Number 0190, Contract Line Item Number 0190, Item 6206000C, Minor Item.  Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item  No Remark was entered by Engineer  No Remark was entered by Engineer	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0240, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8061050, Project Item Line Number 0280, Material Set 806105096, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8069905, Project Item Line Number 0290, Material Set 8069905, Material 3806ECFM - Fiber Matrix for Erosion Blankets, Acceptance Action Generic 3806ECFM is insufficient.  Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item Line Number 0190, Contract Line Item Number 0190, Item 6206000C, Minor Item.  Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item No Remark was entered by Engineer  No Remark was entered by Engineer  ROTHEL Acknowledged  No Remark was entered by Engineer  ROTHEL Acknowledged	Number 0240, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0240, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8061050, Project Item Line Number 0280, Material Set 806105096, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8069905, Project Item Line No Remark was entered by Engineer  No Remark was entered by Engineer  ROTHEL Overridden Verridden Set 8069905, Material 3806ECFM - Fiber Matrix for Erosion Blankets, Acceptance Action Generic 3806ECFM is insufficient.  Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item Line No Remark was entered by Engineer  No Remark was entered by Engineer  ROTHEL Acknowledged Line Number 0190, Contract Line Item Number 0190, Item 6206000C, Minor Item.  Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item No Remark was entered by Engineer  ROTHEL Acknowledged	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8051000A, Project Item Line Number 0240, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0280, Material Set 806105096, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.  Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8069905, Project Item Line Number 0290, Material Set 8069905, Material 3806ECFM - Fiber Matrix for Erosion Blankets, Acceptance Action Generic 3806ECFM is insufficient.  Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item Line Number 0190, Contract Line Item Number 0190, Item 6206000C, Minor Item.  Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item Line Number 0190, Contract Line Item Number 0190, Item 6206000C, Minor Item.  No Remark was entered by Engineer ROTHEL Acknowledged	Number 0240, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action	No Remark was entered by Engineer	ROTHEL	Overridden
Number 0290, Material Set 8069905, Material 3806ECFM - Fiber Matrix for Erosion Blankets, Acceptance Action Generic 3806ECFM is insufficient.  Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item Line Number 0190, Contract Line Item Number 0190, Item 6206000C, Minor Item.  Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item No Remark was entered by Engineer ROTHEL Acknowledged	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8061050, Project Item Line Number 0280, Material Set 806105096, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
Line Number 0190, Contract Line Item Number 0190, Item 6206000C, Minor Item.  Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item No Remark was entered by Engineer ROTHEL Acknowledged	Estimate Exception Type: Insufficient Materials: Project J9S3385, Item 8069905, Project Item Line Number 0290, Material Set 8069905, Material 3806ECFM - Fiber Matrix for Erosion Blankets, Acceptance Action Generic 3806ECFM is insufficient.	No Remark was entered by Engineer	ROTHEL	Overridden
	Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item Line Number 0190, Contract Line Item Number 0190, Item 6206000C, Minor Item.	No Remark was entered by Engineer	ROTHEL	Acknowledged
Line Number 0200, Contract Line Item Number 0200, Item 6206001C, Minor Item.	Estimate Exception Type: Item Overrun: Contract 200221-H05, Contract Project J9S3385, Project Item Line Number 0200, Contract Line Item Number 0200, Item 6206001C, Minor Item.	No Remark was entered by Engineer	ROTHEL	Acknowledged

Revision 4/1/2020 Page 5 of 14



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					eport Generated date and can differ from the posted amo							
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200221-H05	J9S3385	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$4,200.00	\$4,200.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$9,000.00	\$9,000.00
		0001	0030	2031000	CLASS A EXCAVATION	635.00	0.00	635.00	CUYD	635.00	\$17.50	\$11,112.50
		0001	0040	2035500	EMBANKMENT IN PLACE	2,241.00	0.00	2,241.00	CUYD	2,241.00	\$30.00	\$67,230.00
		0001	0050	2036000	COMPACTING EMBANKMENT	529.00	0.00	529.00	CUYD	529.00	\$4.00	\$2,116.00
		0001	0060	3040163	TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)	1,194.00	0.00	1,194.00	SQYD	1,194.00	\$12.00	\$14,328.00
		0001	0070	3105002	GRAVEL (A) OR CRUSHED STONE (B)	32.00	0.00	32.00	TONS	32.00	\$50.00	\$1,600.00
		0001	0080	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	45.50	0.00	45.50	TONS	45.50	\$110.00	\$5,005.00
		0001	0090	4019905	MISC.OPTIONAL PAVEMENT	1,070.40	0.00	1,070.40	SQYD	1,070.40	\$54.00	\$57,801.60
		0001	0100	4071005	TACK COAT	40.00	0.00	40.00	GAL	40.00	\$18.50	\$740.00
		0001	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	1,007.00	0.00	1,007.00	CUYD	1,007.00	\$40.00	\$40,280.00
		0001	0120	6113040	PLACING TYPE 2 ROCK BLANKET	1,007.00	0.00	1,007.00	CUYD	1,007.00	\$25.00	\$25,175.00
		0001	0130	6161005	CONSTRUCTION SIGNS	360.00	26.00	386.00	SQFT	386.00	\$10.00	\$3,860.00
		0001	0140	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	1.00	5.00	EA	5.00	\$100.00	\$500.00
		0001	0150	6161009	FLAG ASSEMBLY	4.00	1.00	5.00	EA	5.00	\$30.00	\$150.00
		0001	0160	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	10.00	3.00	13.00	EA	13.00	\$225.00	\$2,925.00
		0001	0170	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	3.00	0.00	3.00	EA	3.00	\$3,300.00	\$9,900.00
		0001	0180	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$172,700.00	\$172,700.00
		0001	0190	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,700.00	0.00	1,700.00	LF	1,832.00	\$0.35	\$641.20
		0001	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	563.00	0.00	563.00	LF	590.00	\$0.35	\$206.50
		0001	0210	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	462.00	0.00	462.00	SQYD	0.00	\$6.00	\$0.00
		0001	0220	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,510.00	0.00	1,510.00	SQYD	1,510.00	\$2.50	\$3,775.00
		0001	0230	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$9,000.00	\$9,000.00
		0001	0240	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	1.00	\$3,400.00	\$3,400.00
		0001	0250	8061005	ROCK DITCH CHECK	65.00	0.00	65.00	LF	65.00	\$30.00	\$1,950.00
		0001	0260	8061016	SEDIMENT REMOVAL	20.00	0.00	20.00	CUYD	0.00	\$5.00	\$0.00
		0001	0270	8061019	SILT FENCE	670.00	150.00	820.00	LF	820.00	\$4.00	\$3,280.00
		0001	0280	8061050	TYPE C BERM	515.00	0.00	515.00	LF	515.00	\$30.00	\$15,450.00
		0001	0290	8069905	MISC.FIBER REINFORCED MATRIX	562.00	0.00	562.00	SQYD	562.00	\$5.00	\$2,810.00
		0010	0300	6061060	MGS GUARDRAIL	350.00	0.00	350.00	LF	350.00	\$24.00	\$8,400.00
		0010	0310	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	3.00	0.00	3.00	EA	3.00	\$2,950.00	\$8,850.00
		0010	0320	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	3.00	\$2,850.00	\$8,550.00
		0010	0330	6063017	TYPE C CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	1.00	\$18,000.00	\$18,000.00
		0070	0335	2061000	CLASS 1 EXCAVATION	55.00	13.00	68.00	CUYD	68.00	\$50.00	\$3,400.00
		0070	0340	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$55,000.00	\$55,000.00
		0070	0350	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	122.00	0.00	122.00	SQYD	122.00	\$140.00	\$17,080.00
		0070	0360	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	84.00	0.00	84.00	LF	84.00	\$920.00	\$77,280.00
		0070	0370	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	60.00	0.00	60.00	LF	60.00	\$475.00	\$28,500.00
		0070	0380	7011300	VIDEO CAMERA INSPECTION	6.00	0.00	6.00	EA	6.00	\$800.00	\$4,800.00
		0070	0390	7011400	FOUNDATION INSPECTION HOLES	120.00	0.00	120.00	LF	120.00	\$95.00	\$11,400.00
		0070	0400	7011600	SONIC LOGGING TESTING	6.00	0.00	6.00	EA	6.00	\$1,300.00	\$7,800.00
		0070	0410	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	192.00	-19.00	173.00	LF	173.00	\$110.00	\$19,030.00
		0070	0420	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$400.00	\$800.00
		0070	0430	7026000	PRE-BORE FOR PILING	136.00	26.00	162.00	LF	162.00	\$165.00	\$26,730.00
		0070	0440	7027000	PILE POINT REINFORCEMENT	8.00	0.00	8.00	EA	8.00	\$100.00	\$800.00
Revision 4/1/203	20											Page 6 of 14

Page 6 of 14 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200221-H05	J9S3385	0070	0450	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	86.90	0.00	86.90	CUYD	86.90	\$1,000.00	\$86,900.00
		0070	0460	7034215	SAFETY BARRIER CURB	499.00	0.00	499.00	LF	499.00	\$75.00	\$37,425.00
		0070	0470	7034222	SLAB ON CONCRETE BEAM	760.00	0.00	760.00	SQYD	760.00	\$377.00	\$286,520.00
		0070	0480	7056049	21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	939.00	0.00	939.00	LF	939.00	\$275.00	\$258,225.00
		0070	0490	7061060	REINFORCING STEEL (BRIDGES)	27,330.00	0.00	27,330.00	LB	27,330.00	\$1.25	\$34,162.50
		0070	0500	7123610	SLAB DRAIN	2.00	0.00	2.00	EA	2.00	\$325.00	\$650.00
		0070	0510	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$2,200.00	\$4,400.00
		0070	0520	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	32.00	0.00	32.00	EA	32.00	\$300.00	\$9,600.00
	Project J	9S3385 - To	otal Value	Posted to I	Date as of Report Generated Date							\$1,483,438.30
200221-H05 Overall - Total Value Posted to Date as of Report Generated Date								\$1,483,438.30				

Page 7 of 14 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3385

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	2031000	CLASS A EXCAVATION	9/21/20	9/29/20	100.00	CUYD	Rte. J					
0040	2035500	EMBANKMENT IN PLACE	9/21/20	9/29/20	500.00	CUYD	Rte. J					
0050	2036000	COMPACTING EMBANKMENT	9/21/20	9/29/20	100.00	CUYD	Rte. J					
0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	9/21/20	9/29/20	507.00	CUYD	Rte. J					
0120	6113040	PLACING TYPE 2 ROCK BLANKET	9/21/20	9/29/20	507.00	CUYD	Rte. J					
0190	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	9/16/20	9/22/20	1,832.00	LF	Rte. J					
0200	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	9/16/20	9/22/20	590.00	LF	Rte. J					
0220	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	9/21/20	9/29/20	1,510.00	SQYD	Rte. J					
0240	8051000A	SEEDING - COOL SEASON MIXTURES	9/19/20	9/22/20	1.00	ACRE	Rte. J					
0250	8061005	ROCK DITCH CHECK	9/19/20	9/22/20	65.00	LF	Rte. J					
0280	8061050	TYPE C BERM	9/21/20	9/29/20	515.00	LF	Rte. J					
0290	8069905	MISC. EROSION CONTROL	9/19/20	9/22/20	562.00	SQYD	Rte. J					
0330	6063017	TYPE C CRASHWORTHY END TERMINAL	9/30/20	10/1/20	1.00	EA	Rte. J					

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 8 of 14



2020 10 Sep 16, SYSTEM (\$17.16) Re 2020	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL
2020	, , , , , , , , , , , , , , , , , , , ,
Price - Total (\$51.42)  0030 - Total (\$51.42)  (\$51.42)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Price - Total         (\$51.42)           0030 - Total         (\$51.42)	
0030 - Total (\$51.42)	
0040 EMBANKMENT IN PLACE Material 9 Sep 2 SYSTEM (\$33,600,00)	
2020 (\$55,000.00)	
2020 Es	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
10 Sep 16, 2020 SYSTEM (\$52,230.00)	
2020 Es	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
11 Oct 1, 2020 (\$67,230.00)	
2020 Es	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
- Total \$0.00	
Material - Total \$0.00	
EMBANKMENT IN PLACE         Price         9         Sep 2, 2020         SYSTEM (\$164.64)         Re	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
10 Sep 16, 2020 (\$84.77) Re	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
11 Oct 1, 2020 SYSTEM (\$68.25) Re	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
- Total (\$317.66)	
Price - Total (\$317.66)	
0040 - Total (\$317.66)	
0050         COMPACTING EMBANKMENT         Material         9         Sep 2, 2020         SYSTEM (\$1,056.00)	
2020 Es	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
10 Sep 16, 2020 SYSTEM (\$1,716.00)	
2020 Es	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
11 Oct 1, 2020 SYSTEM (\$2,116.00)	
2020 Es	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
- Total \$0.00	
Material - Total \$0.00	
Material - Total         \$0.00           0050 - Total         \$0.00	
0050 - Total         \$0.00           0060         TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)         Material 2020         10 Sep 16, 2020         SYSTEM (\$14,328.00)	
10   Sep 16, 2020   SYSTEM   \$14,328.00   Type 1 AGGREGATE FOR BASE (6 IN. THICK)   10   Sep 16, 2020   SySTEM   \$14,328.00   The Estern Control of the Co	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
0050 - Total   \$0.00	Estimate Item Adjustment (0006) due to user rothel overridding Payment
10   Sep 16, 2020   SYSTEM   \$14,328.00   Type 1 AGGREGATE FOR BASE (6 IN. THICK)   10   Sep 16, 2020   SySTEM   \$14,328.00   The Estern Control of the Co	Estimate Item Adjustment (0006) due to user rothel overridding Payment
0050 - Total   \$0.00	Estimate Item Adjustment (0006) due to user rothel overridding Payment

Revision 4/1/2020 Page 9 of 14



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0060	Price - Total						(\$107.10)	
0060 -	Total						(\$107.10)	
0070	GRAVEL (A) OR CRUSHED STONE (B)	Material		10	Sep 16, 2020	SYSTEM	(\$1,600.00)	
				10	Sep 16, 2020	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user rothel overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0070 -	· Total						\$0.00	
0800	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)		ACAD	10	Sep 16, 2020	ROTHEL	(\$159.71)	This Adjustment is being made for 45.50 tons of BP-1 installed during this estimate period.
			ACAD - Tota	al			(\$159.71)	
	Other Item Adjustment - Total						(\$159.71)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Price		10	Sep 16, 2020	SYSTEM	(\$58.91)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$58.91)	
	Price - Total						(\$58.91)	
0080 -	Total						(\$218.62)	
0090	MISC. OPTIONAL PAVEMENT	Other Item Adjustment	ACAD	10	Sep 16, 2020	ROTHEL	(\$2,164.76)	This Adjustment is being made for 1070.40 sq yds of optional pavement installed during this estimate period.
			ACAD - Total				(\$2,164.76)	
	Other Item Adjustment - Total						(\$2,164.76)	
0090 -	· Total						(\$2,164.76)	
0100	TACK COAT	Material		10	Sep 16, 2020	SYSTEM	(\$740.00)	
				10	Sep 16, 2020	SYSTEM	\$740.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 5 on the current Payment Estimate.
				11	Oct 1, 2020	SYSTEM	(\$740.00)	
				11	Oct 1, 2020	SYSTEM	\$740.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0100 -	· Total						\$0.00	
0130	CONSTRUCTION SIGNS	Overrun	Overrun	1	May 4, 2020	SYSTEM	(\$160.00)	
				5	Jun 30, 2020	SYSTEM	\$160.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',10.00000 - 10.00000, 'is applied (if non-zero).
			Overrun - Total				\$0.00	
	Overrun - Total						\$0.00	
0130 -	Total						\$0.00	
0140	ADVANCED WARNING RAIL SYSTEM	Overrun	Overrun	1	May 4, 2020	SYSTEM	(\$100.00)	
				5	Jun 30, 2020	SYSTEM	\$100.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',100.00000 - 100.00000, 'is applied (if non-zero).
			Overrun - Total				\$0.00	
	Overrun - Total						\$0.00	
0140 -	Total						\$0.00	
0150	FLAG ASSEMBLY	Overrun	Overrun	1	May 4, 2020	SYSTEM	(\$30.00)	
				5	Jun 30, 2020	SYSTEM	\$30.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',30.00000 - 30.00000, 'is applied (if non-zero).
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	

Revision 4/1/2020 Page 10 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0150 -	Total						\$0.00	
0190	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun	11	Oct 1, 2020	SYSTEM	(\$46.20)	
			Overrun - T	otal			(\$46.20)	
	Overrun - Total						(\$46.20)	
0190 -	Total						(\$46.20)	
0200	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun	11	Oct 1, 2020	SYSTEM	(\$9.45)	
			Overrun - T	otal			(\$9.45)	
	Overrun - Total						(\$9.45)	
0200 -	Total						(\$9.45)	
0240	SEEDING - COOL SEASON MIXTURES	Material		11	Oct 1, 2020	SYSTEM	(\$3,400.00)	
				11	Oct 1, 2020	SYSTEM	\$3,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0240 -	Total						\$0.00	
0270	SILT FENCE	Overrun	Overrun	1	May 4, 2020	SYSTEM	(\$600.00)	
				5	Jun 30, 2020	SYSTEM	\$600.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4.00000 - 4.00000, 'is applied (if non-zero).
	Overrun - Total						\$0.00	
	Overrun - Total						\$0.00	
0270 -	Total						\$0.00	
0280	TYPE C BERM	Material		11	Oct 1, 2020	SYSTEM	(\$15,450.00)	
				11	Oct 1, 2020	SYSTEM	\$15,450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0280 -	Total						\$0.00	
0290	MISC. FIBER REINFORCED MATRIX	Material		11	Oct 1, 2020	SYSTEM	(\$2,810.00)	
				11	Oct 1, 2020	SYSTEM	\$2,810.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 21 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0290 -	Total						\$0.00	
0300	MGS GUARDRAIL	Construction Stockpile		4	Jun 16, 2020	SYSTEM	\$3,731.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Sep 16, 2020	SYSTEM	(\$3,731.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		- Total				\$0.00		
	Construction Stockpile - Total						\$0.00	
0300 -	Total						\$0.00	
0310	MGS VERTICAL CONCRETE BARRIER TRANSITION	Construction Stockpile		4	Jun 16, 2020	SYSTEM	\$3,912.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Sep 16, 2020	SYSTEM	(\$3,912.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	MGS VERTICAL CONCRETE	Material		10	Sep 16,	SYSTEM	(\$8,850.00)	

Revision 4/1/2020 Page 11 of 14



Lina	Description	A dissatura a mt	Other	Fet	Created	Created	Amazumt	Devenue
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0310	BARRIER TRANSITION	Material			2020			
				10	Sep 16, 2020	SYSTEM	\$8,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 16 on the current Payment Estimate.
				11	Oct 1, 2020	SYSTEM	(\$8,850.00)	
				11	Oct 1, 2020	SYSTEM	\$8,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0310 -	Total						\$0.00	
0320	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		4	Jun 16, 2020	SYSTEM	\$4,530.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Sep 16, 2020	SYSTEM	(\$4,530.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		10	Sep 16, 2020	SYSTEM	(\$8,550.00)	
				10	Sep 16, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 17 on the current Payment Estimate.
				11	Oct 1, 2020	SYSTEM	(\$8,550.00)	
				11	Oct 1, 2020	SYSTEM	\$8,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0320 -	Total						\$0.00	
0330	TYPE C CRASHWORTHY END TERMINAL	Material		11	Oct 1, 2020	SYSTEM	(\$18,000.00)	
				11	Oct 1, 2020	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user rothel overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0330 -	Total						\$0.00	
0335	CLASS 1 EXCAVATION	Overrun	Overrun	4	Jun 16, 2020	SYSTEM	(\$650.00)	
				7	Aug 3, 2020	SYSTEM	\$650.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',50.00000 - 50.00000, 'is applied (if non-zero).
			Overrun - Total				\$0.00	
	Overrun - Total						\$0.00	
0335 -							\$0.00	
0350	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		10	Sep 16, 2020	SYSTEM	(\$17,080.00)	
				10	Sep 16, 2020	SYSTEM	\$17,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate.
				11	Oct 1, 2020	SYSTEM	(\$17,080.00)	
				11	Oct 1, 2020	SYSTEM	\$17,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Material - Total  BRIDGE APPROACH SLAB (MINOR ROAD)	Other Item Adjustment	ACAD	10	Sep 16, 2020	ROTHEL	\$0.00 (\$282.63)	This Adjustment is being made for 122.0 sq yds of BP-1 installed during this estimate period.

Revision 4/1/2020 Page 12 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0350	Other Item Adjustment - Total		31				(\$282.63)	
0350 -	Total						(\$282.63)	
0360	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		5	Jun 30, 2020	SYSTEM	(\$77,280.00)	
				6	Jul 16, 2020	SYSTEM	(\$77,280.00)	
				6	Jul 16, 2020	SYSTEM	\$77,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Aug 3, 2020	SYSTEM	(\$77,280.00)	
				7	Aug 3, 2020	SYSTEM	\$77,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$77,280.00)	
				8	Aug 16, 2020	SYSTEM	\$77,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				(\$77,280.00)	
	Material - Total						(\$77,280.00)	
	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	MaterialCredit		6	Jul 16, 2020	SYSTEM	\$77,280.00	
			- Total				\$77,280.00	
	MaterialCredit - Total						\$77,280.00	
0360 -	Total						\$0.00	
0370	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		5	Jun 30, 2020	SYSTEM	(\$28,500.00)	
				6	Jul 16, 2020	SYSTEM	(\$28,500.00)	
				6	Jul 16, 2020	SYSTEM	\$28,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Aug 3, 2020	SYSTEM	(\$28,500.00)	
				7	Aug 3, 2020	SYSTEM	\$28,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				(\$28,500.00)	
	Material - Total						(\$28,500.00)	
	ROCK SOCKETS (3 FT 0 IN. DIA.)	MaterialCredit		6	Jul 16, 2020	SYSTEM	\$28,500.00	
			- Total				\$28,500.00	
	MaterialCredit - Total						\$28,500.00	
0370 -	Total						\$0.00	
0430	PRE-BORE FOR PILING	Overrun	Overrun	4	Jun 16, 2020	SYSTEM	(\$4,290.00)	
				7	Aug 3, 2020	SYSTEM	\$4,290.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',165.00000 - 165.00000, 'is applied (if non-zero).
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	
0430 -	Total						\$0.00	
0450	CLASS B CONCRETE (SUBSTRUCTURE)	Material		5	Jun 30, 2020	SYSTEM	(\$19,000.00)	
				6	Jul 16, 2020	SYSTEM	(\$86,900.00)	
				6	Jul 16, 2020	SYSTEM	\$86,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Aug 3, 2020	SYSTEM	(\$86,900.00)	
				7	Aug 3,	SYSTEM	\$86,900.00	This adjustment offsets the original system-generated Overrun Payment

Revision 4/1/2020 Page 13 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0450	CLASS B CONCRETE (SUBSTRUCTURE)	Material			2020			Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$86,900.00)	
				8	Aug 16, 2020	SYSTEM	\$86,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				(\$19,000.00)	
	Material - Total						(\$19,000.00)	
	CLASS B CONCRETE (SUBSTRUCTURE)	MaterialCredit		6	Jul 16, 2020	SYSTEM	\$19,000.00	
		- Total				\$19,000.00		
	MaterialCredit - Total						\$19,000.00	
0450 -	· Total						\$0.00	
0460	SAFETY BARRIER CURB	Material		9	Sep 2, 2020	SYSTEM	(\$37,425.00)	
				9	Sep 2, 2020	SYSTEM	\$37,425.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Sep 16, 2020	SYSTEM	(\$37,425.00)	
				10	Sep 16, 2020	SYSTEM	\$37,425.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0460 -	· Total						\$0.00	
0470	SLAB ON CONCRETE BEAM	Material		7	Aug 3, 2020	SYSTEM	(\$57,304.00)	
				7	Aug 3, 2020	SYSTEM	\$57,304.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate.
				8	Aug 16, 2020	SYSTEM	(\$171,912.00)	
				8	Aug 16, 2020	SYSTEM	\$171,912.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Sep 2, 2020	SYSTEM	(\$286,520.00)	
				9	Sep 2, 2020	SYSTEM	\$286,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate.
				10	Sep 16, 2020	SYSTEM	(\$286,520.00)	
				10	Sep 16, 2020	SYSTEM	\$286,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user rothel overridding Payment Estimate Exception 21 on the current Payment Estimate.
				11	Oct 1, 2020	SYSTEM	(\$115,156.54)	
				11	Oct 1, 2020	SYSTEM	\$115,156.54	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user rothel overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0470 -	· Total						\$0.00	
0520	LAMINATED NEOPRENE BEARING PAD (TAPERED)	Material		7	Aug 3, 2020	SYSTEM	(\$9,600.00)	
				7	Aug 3, 2020	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user rothel overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0520 -	Total						\$0.00	
Overa	ıll - Total						(\$3,197.84)	
							(, 2, , 2, 10 2)	

Revision 4/1/2020 Page 14 of 14