

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 1, 2021

| Progr | | timate Numb | oer | Contract ID Prime Cont | | 200320-B03 Phillips Hardy, l | | | January 16, January 31, | 2021 Net Ch | al Contract <i>I</i> lange Order lt Contract <i>I</i> | Amount \$ | \$2,553,542.91 \$9,648.04 \$2,563,190.95 |
|---|------------------------------|----------------------------|--|---------------------------|---|---------------------------------|---|--|----------------------------|--|---|--------------------------|--|
| Approva | al Date | | | | | | | | | | | | By User |
| February | 1, 2021 | 1 | | | G | Senerated and A | Approved (and s | hould be | considered | Draft) at the Pi | roject Office I | evel by | vierss |
| February | 1, 2021 | 1 | | | Revie | wed and Appro | ved (and should | d be cons | idered Draft |) at the Reside | nt Engineer I | evel by | vierss |
| February : | 2, 2021 | 1 | | | | F | Reviewed and A | pproved | at the Centr | al Office Contr | ollers Office I | evel by | greggd1 |
| Origi | nal Co | mpletion Dat | te | Current | Comple | etion Date | Actual Co | mpletion | Date | % of Cu | rrent Contra | ct Amount | Complete |
| D | ecemb | er 1, 2020 | | Dec | ember 1, | , 2020 | | | | | 90. | 97% | |
| lo Milesto | nes Ex | ist for Contrac | ct | | | | | | | | | | |
| Contract | Total F | Pay For Estin | nate N | o. 16 | | | | | | | | | |
| | | | | | Т | his Estimate | | Previo | ous | | To Date | | |
| 200320-B03 Total Posted Items Pay Gross Item Adjustments Incentive Disincentive Liquidated Damage Other Contract Adjustments | | \$ \$ \$ | \$61,506.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 (\$15,646.99) | | (\$1,01 \$0.00 \$0.00 (\$42,4 (\$154 | , | | \$2,331,8 (\$1,012. \$0.00 \$0.00 (\$42,400 (\$169,94 | 89)).00) 48.78) | | | | |
| Contract | Total F | Payable This | Estima | ate: | \$ | 45,859.01 | | Ψ2,07 | 2,007.00 | | ΨΖ, 110,- | 130.57 | |
| ems Paid | l This I | Estimate Per | <u>iod</u> | | | | | | | | | | |
| Project | Numbe | er Line Nur | mher | Item Code | | Item Descr | intion | Unit | Unit Price | Current Ins | talled Oty | Current Ins | talled Amount |
| J2S2168 | | 0390 | | 7034219A | TYPE I | D BARRIER | iption | LF | \$93.500 | Our one mo | 536 | Our one mo | \$50,116.00 |
| 0202100 | , | 0410 | | 7034630 | | RETE CURB (B | RIDGE RAIL) | | | | 268 | | \$11,390.00 |
| Project. | 125216 | 88 - Total | , | 7004000 | 001101 | KETE GOIND (B | TUDOL TUTL) | | Ψ-2.000 | | 200 | | \$61,506.00 |
| Overall | | o rotal | | | | | | | | | | | \$61,506.00 |
| | | nents This E | stimat | e | | | | | | | | | 401,000.00 |
| | Adj Ty | | | Entered By | | Comme | ents | Time | e Units | Rat | Δ | Δn | nount |
| | | ner Contract Adjustment | | | vierss | | ord saved to d emailed to | | <i>-</i> | 1 (3) | | , | (\$15,646.99) |
| Overall - | Total | | | | | | contractor | | | | | | (\$15,646.99) |
| ine Item | Adjust | These amo ments This E | | | he Incen | ntive, Disincent | tive, Liquidated | d Damag | es or Other | Contract Adj | ustments | | |
| Project | Line | Item | Descrip | ption | Adjustm | nent Other Iter | n | Co | mments | | Adjustment | Line Item | Adjustment |
| Number | No. | | , | | Туре | | nt | | | | Quantity | Adjustment Unit Price | |
| J2S2168 | 0290 | BRIDGE A | | OACH SLAB OR ROAD) | Mate | erial | | | | | -163 | \$165.00 | (\$26,895.00) |
| | 0290 | BRIDGE A | | OACH SLAB IOR ROAD) | Mate | generate Adj | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 2 on the current Payment Estimate. | | Estimate Item o user sandip exception 2 on | m ip on | | \$26,895.00 |
| | 0390 TYPE D BARRIER Material | | erial | | | | | -536 | \$93.50 | (\$50,116.00) | | | |
| | 0390 | (| | generate Adj | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment Estimate Exception 17 on the current Payment Estimate. | | | 536 | \$93.50 | \$50,116.00 | | | |
| | 0400 | SLAB ON C | ONCR | ETE BEAM | Mate | erial | | | | | -887 | | (\$278,518.00) |
| | 0400 | SLAB ON C | ONCR | CRETE BEAM Material | | generate Adj | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user sandip overridding Payment Estimate Exception 19 on the current Payment Estimate. | | | | \$314.00 | \$278,518.00 | |

Revision 4/1/2020 Page 1 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 1, 2021

| Progress Estimate Number | Contract ID | | | , , , | 9 | \$2,553,542.91 |
|--------------------------|------------------|----------------------|----------------|------------------|-------------------------|----------------|
| 16 | Prime Contractor | Phillips Hardy, Inc. | Pay Period End | January 31, 2021 | Net Change Order Amount | \$9,648.04 |
| 10 | | | | | Current Contract Amount | \$2,563,190.95 |

| | | | | | Current Contract Amount \$2,505,190.95 | | | | | | | |
|-------------------|-------------|--|--------------------|----------------------------------|---|------------------------|---------------------------------------|-------------------|--|--|--|--|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount | | | | |
| J2S2168 | 0410 | CONCRETE CURB (BRIDGE RAIL) | Material | | | -268 | \$42.50 | (\$11,390.00) | | | | |
| | 0410 | CONCRETE CURB (BRIDGE RAIL) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 22 on the current Payment Estimate. | 268 | \$42.50 | \$11,390.00 | | | | |
| J2S3198 | 0770 | BRIDGE APPROACH SLAB (MINOR ROAD) | Material | | | -114 | \$170.00 | (\$19,380.00) | | | | |
| | 0770 | BRIDGE APPROACH SLAB (MINOR ROAD) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. | 114 | \$170.00 | \$19,380.00 | | | | |
| | 0810 | CLASS B-2 CONCRETE (SUPERSTRUCTURE SOLID SLAB) | Material | | | -44.4 | \$956.00 | (\$42,446.40) | | | | |
| | 0810 | CLASS B-2 CONCRETE (SUPERSTRUCTURE SOLID SLAB) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user sandip overridding Payment Estimate Exception 12 on the current Payment Estimate. | 44.4 | \$956.00 | \$42,446.40 | | | | |
| | 0820 | TYPE D BARRIER | Material | | | -251 | \$117.00 | (\$29,367.00) | | | | |
| | 0820 | TYPE D BARRIER | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user sandip overridding Payment Estimate Exception 18 on the current Payment Estimate. | 251 | \$117.00 | \$29,367.00 | | | | |
| Total | | | | | | | | \$0.00 | | | | |

Revision 4/1/2020 Page 2 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | (| Contract Project Information | | | | | | | |
|--|----------------------------|---------------------------|--------|----------|--|--|---|--|--|--|--|--|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | Location of Work | | | | | | | | |
| J2S2168 | FAS S201(24) | Bridge replacement | D | MACON | Over Burlington Northern Santa Fe Railroad in La Plata | | | | | | | | |
| J2S3198 | FAS- S201(043) | Bridge replacement | DD | MACON | over Billy's Branch 0.8 mil | e west of Route K near Ten | Mile | | | | | | |
| Γotals by . | Job Number | s | | | | | | | | | | | |
| J2S2168 Posted Item Pay Gross Item Adjustments Gross Item Pay | | | | Item Pay | This Estimate \$61,506.00 \$0.00 \$61,506.00 | Previous \$1,534,316.94 (\$1.01) \$1,534,315.93 | To Date \$1,595,822.94 (\$1.01) \$1,595,821.93 | | | | | | |
| | | | | | \$0.00 \$0.00 \$0.00 (\$11,148.48) | \$0.00 \$0.00 (\$30,091.28) (\$109,548.55) | \$0.00 \$0.00 (\$30,091.28) (\$120,697.03) | | | | | | |
| J2S3198 | | Item Pay Item Adjustme | | Item Pay | This Estimate \$0.00 \$0.00 \$0.00 | Previous \$736,035.30 (\$1,011.88) \$735,023.42 | To Date \$736,035.30 (\$1,011.88) \$735,023.42 | | | | | | |
| | | | tments | | \$0.00 \$0.00 \$0.00 (\$4,498.51) | \$0.00 \$0.00 (\$12,308.72) (\$44,753.24) | \$0.00 \$0.00 (\$12,308.72) (\$49,251.75) | | | | | | |

Revision 4/1/2020 Page 3 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Period | | | |
|--|-----------------------------------|---------------|------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project J2S2168, Item 5031011A, Project Item Line Number 0290, Material Set 5031011A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S2168, Item 5031011A, Project Item Line Number 0290, Material Set 5031011A96, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 5031011A, Project Item Line Number 0770, Material Set 5031011A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 5031011A, Project Item Line Number 0770, Material Set 5031011A96, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 5031011A, Project Item Line Number 0770, Material Set 5031011A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 5031011A, Project Item Line Number 0770, Material Set 5031011A96, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 5031011A, Project Item Line Number 0770, Material Set 5031011A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S2168, Item 7029903, Project Item Line Number 0360, Material Set 702990396, Material 0501CCB1 - Concrete, Class B-1 No Air, Acceptance Action Generic 0501CCB1 is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S2168, Item 7029903, Project Item Line Number 0360, Material Set 702990396, Material 0702PTBIPL - Bituminous Paint for Pile Coating, Acceptance Action Generic 0702PTBIPL is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 7034003, Project Item Line Number 0800, Material Set 703400396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 7034003, Project Item Line Number 0800, Material Set 703400396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 7034208, Project Item Line Number 0810, Material Set 703420896, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 7034208, Project Item Line Number 0810, Material Set 703420896, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 7034208, Project Item Line Number 0810, Material Set 703420896, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 7034208, Project Item Line Number 0810, Material Set 703420896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 7034208, Project Item Line Number 0810, Material Set 703420896, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S2168, Item 7034219A, Project Item Line Number 0390, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 7034219A, Project Item Line Number 0820, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S2168, Item 7034222, Project Item Line Number 0400, Material Set 703422296, Material 3703SIPF - Stay in Place Forms, Acceptance Action Generic 3703SIPF is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S2168, Item 7034222, Project Item Line Number 0400, Material Set 703422296, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S2168, Item 7034222, Project Item Line Number 0400, Material Set 703422296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S2168, Item 7034630, Project Item Line Number 0410, Material Set 703463096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3198, Item 8061005, Project Item Line Number 0680, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient. | No Remark was entered by Engineer | sandip | Overridden |
| | | | |

Revision 4/1/2020 Page 4 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| | | | | | eport Generated date and can differ from the posted am | | | | | | | |
|-------------------------|----------------|----------|-------------|--------------------|---|-----------------|------------------------|------------------------------|----------|------------------------------------|------------------------|--|
| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| 200320-B03 | J2S2168 | 0001 | 0010 | 2013000 | CLEARING AND GRUBBING | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$4,450.00 | \$4,450.00 |
| | | 0001 | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$10,600.00 | \$10,600.00 |
| | | 0001 | 0030 | 2031000 | CLASS A EXCAVATION | 742.00 | 0.00 | 742.00 | CUYD | 0.00 | \$23.00 | \$0.00 |
| | | 0001 | 0040 | 2035500 | EMBANKMENT IN PLACE | 1,124.00 | 0.00 | 1,124.00 | CUYD | 0.00 | \$27.00 | \$0.00 |
| | | 0001 | 0050 | 2036000 | COMPACTING EMBANKMENT | 645.00 | 0.00 | 645.00 | CUYD | 0.00 | \$5.85 | \$0.00 |
| | | 0001 | 0060 | 2101006A | SUBGRADE COMPACTION (6-INCH DEPTH) | 1.00 | 0.00 | 1.00 | 100F | 1.00 | \$1,800.00 | \$1,800.00 |
| | | 0001 | 0070 | 3040143 | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | 332.00 | 0.00 | 332.00 | SQYD | 332.00 | \$11.00 | \$3,652.00 |
| | | 0001 | 0080 | 4019905 | MISC.OPTIONAL PAVEMENT | 332.00 | 0.00 | 332.00 | SQYD | 332.00 | \$85.00 | \$28,220.00 |
| | | 0001 | 0090 | 6096010A | FURNISHING TYPE 1 ROCK DITCH LINER | 24.00 | 0.00 | 24.00 | CUYD | 0.00 | \$42.00 | \$0.00 |
| | | 0001 | 0100 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | 188.00 | 0.00 | 188.00 | CUYD | 0.00 | \$52.50 | \$0.00 |
| | | 0001 | 0110 | 6096042 | PLACING TYPE 2 ROCK DITCH LINER | 188.00 | 0.00 | 188.00 | CUYD | 0.00 | \$35.50 | \$0.00 |
| | | 0001 | 0120 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 857.00 | 0.00 | 857.00 | CUYD | 320.00 | \$48.50 | \$15,520.00 |
| | | 0001 | 0130 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 857.00 | 0.00 | 857.00 | CUYD | 320.00 | \$21.50 | \$6,880.00 |
| | | 0001 | 0140 | 6161005 | CONSTRUCTION SIGNS | 286.00 | 0.00 | 286.00 | SQFT | 286.00 | \$10.00 | \$2,860.00 |
| | | 0001 | 0150 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$35.00 | \$70.00 |
| | | 0001 | 0160 | 6161009 | FLAG ASSEMBLY | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$20.00 | \$40.00 |
| | | 0001 | 0170 | 6161030 | TYPE III MOVEABLE BARRICADE | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$135.00 | \$1,350.00 |
| | | 0001 | 0180 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$191,000.00 | \$191,000.00 |
| | | 0001 | 0190 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT | 732.00 | 0.00 | 732.00 | LF | 0.00 | \$3.00 | \$0.00 |
| | | 0001 | 0200 | 6240103A | MARKING PAINT, TYPE P BEADS PERMANENT EROSION CONTROL GEOTEXTILE | 952.00 | 0.00 | 952.00 | SQYD | 356.00 | \$4.55 | \$1,619.80 |
| | | 0001 | 0210 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$11,500.00 | \$11,500.00 |
| | | 0001 | 0220 | 8059901 | MISC.SEEDING- COOL SEASON MIXTURES | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$4,000.00 | \$0.00 |
| | | 0001 | 0230 | 8061005 | ROCK DITCH CHECK | 180.00 | 0.00 | 180.00 | LF | 0.00 | \$20.00 | \$0.00 |
| | | 0001 | 0240 | 8061016 | SEDIMENT REMOVAL | 24.00 | 0.00 | 24.00 | CUYD | 0.00 | \$50.00 | \$0.00 |
| | | 0001 | 0250 | 8061019 | SILT FENCE | 581.00 | 0.00 | 581.00 | LF | 0.00 | \$3.00 | \$0.00 |
| | | 0001 | 0260 | 8069901 | MISC.TEMPORARY SEEDING AND MULCHING | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$750.00 | \$0.00 |
| | | 0070 | 0270 | 2061000 | CLASS 1 EXCAVATION | 150.00 | 0.00 | 150.00 | CUYD | 150.00 | \$48.50 | \$7,275.00 |
| | | 0070 | 0280 | 2160500 | REMOVAL OF BRIDGES | 1.00 | 0.00 | 1.00 | LS | | \$125,000.00 | \$125,000.00 |
| | | 0070 | 0290 | 5031011A | BRIDGE APPROACH SLAB (MINOR ROAD) | 163.00 | 0.00 | 163.00 | SQYD | 163.00 | \$165.00 | \$26,895.00 |
| | | | 0300 | 6071067 | (112 IN.) CURVED TOP PEDESTRIAN FENCE (STRUCTURES) | 264.00 | 0.00 | 264.00 | LF | 0.00 | \$183.01 | \$20,895.00 |
| | | 0070 | 0310 | 6079903 | | 222.00 | 0.00 | 222.00 | LF | 0.00 | \$116.16 | \$0.00 |
| | | 0070 | | | MISC.(78 in.) Pedestrian Fence (Structures) | | | | | | | \$67,105.50 |
| | | 0070 | 0320 | 7021212 7026000 | GALVANIZED STRUCTURAL STEEL PILES (12 IN) PRE-BORE FOR PILING | 960.00 | 0.00 | 960.00 | LF LF | 913.00 | \$73.50 \$150.00 | \$8,100.00 |
| | | 0070 | 0340 | 7027000 | PILE POINT REINFORCEMENT | 12.00 | 0.00 | 12.00 | EA | 12.00 | \$95.00 | \$1,140.00 |
| | | 0070 | | | | | | | | | | |
| | | 0070 | 0350 | 7029902 7029903 | MISC.Pile Point Reinforcement (Open Ended CIP) MISC.Galvanized Cast-In-Place Concrete Piles (42 in.) | 6.00 474.00 | 0.00 | 6.00 474.00 | EA LF | 6.00 473.00 | \$1,450.00 \$410.00 | \$8,700.00 \$193,930.00 |
| | | 0070 | 0370 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 84.70 | 0.00 | 84.70 | CUYD | 84.70 | \$994.00 | \$84,191.80 |
| | | 0070 | | | , , | | | | | | | |
| | | 0070 | 0380 | 7034003 | CLASS B-1 CONCRETE (SUBSTRUCTURE) | 79.90 | 0.00 | 79.90 | CUYD | 79.90 | \$714.00 | \$57,048.60 |
| | | 0070 | 0390 | 7034219A | TYPE D BARRIER | 536.00 | 0.00 | 536.00 | LF | 536.00 | \$93.50 | \$50,116.00 |
| | | 0070 | 0400 | 7034222 | SLAB ON CONCRETE BEAM | 934.00 | 0.00 | 934.00 | SQYD | 887.00 | \$314.00 | \$278,518.00 |
| | | 0070 | 0410 | 7034630 | CONCRETE CURB (BRIDGE RAIL) | 268.00 | 0.00 | 268.00 | LF | 268.00 | \$42.50 | \$11,390.00 |
| | | 0070 | 0420 | 7056050A | 27 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM | 1,128.00 | 0.00 | 1,128.00 | LF | 1,128.00 | \$279.00 | \$314,712.00 |
| | | 0070 | 0430 | 7061060 | REINFORCING STEEL (BRIDGES) | 41,420.00 | 0.00 | 41,420.00 | LB | 41,420.00 | \$1.25 | \$51,775.00 |
| | | 0070 | 0440 | 7071000 | CONDUIT SYSTEM ON STRUCTURE | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$8,000.00 | \$0.00 |
| | | 0070 | 0450 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,350.00 | \$6,700.00 |
| | | 0070 | 0460 | 7161000 | PLAIN NEOPRENE BEARING PAD | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$277.00 | \$2,770.00 |
| Revision 4/1/203 | 21.) | | | | | | | | | | | Page 5 of 16 |

Page 5 of 16 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

| Note: Posted Quantities and Values ar | e based on I | Report Generated date and | can differ from the posted amount: | at the time the Estimate was Generated. |
|---------------------------------------|--------------|---------------------------|------------------------------------|---|

| Contract CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POST To Date (See rep generated date |
|----------------------|----------------|---------------------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 20-B03 | J2S2168 | 0070 | 0470 | 7161002 | LAMINATED NEOPRENE BEARING PAD | 20.00 | 0.00 | 20.00 | EA | 20.00 | \$310.00 | \$6,200 |
| | | 0070 | 5001 | 7025002 | PILE WAVE ANALYSIS | 0.00 | 2.00 | 2.00 | EA | 2.00 | \$1,050.00 | \$2,100 |
| | | 0070 | 5002 | 7039901 | MISC.Heated Cure of Bridge Deck | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$12,594.24 | \$12,594 |
| | Project J | 2 S2168 - To | tal Value | Posted to D | ate as of Report Generated Date | | | | | | | \$1,595,822 |
| | J2S3198 | 0001 | 0480 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$4,300.00 | \$4,300 |
| | | 0001 | 0490 | 2031000 | CLASS A EXCAVATION | 30.00 | 0.00 | 30.00 | CUYD | 30.00 | \$54.50 | \$1,63 |
| | | 0001 | 0500 | 2035500 | EMBANKMENT IN PLACE | 963.00 | 0.00 | 963.00 | CUYD | 963.00 | \$31.00 | \$29,85 |
| | | 0001 | 0510 | 2036000 | COMPACTING EMBANKMENT | 26.00 | 0.00 | 26.00 | CUYD | 26.00 | \$29.00 | \$75 |
| | | 0001 | 0520 | 3040143 | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | 740.00 | 0.00 | 740.00 | SQYD | 740.00 | \$11.00 | \$8,14 |
| | | 0001 | 0530 | 3102002 | CRUSHED STONE (B) | 20.00 | 0.00 | 20.00 | TONS | 20.00 | \$88.00 | \$1,76 |
| | | 0001 | 0540 | 4019905 | MISC.OPTIONAL PAVEMENT | 740.00 | 0.00 | 740.00 | SQYD | 740.00 | \$75.00 | \$55,50 |
| | | 0001 | 0550 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 327.00 | 0.00 | 327.00 | CUYD | 327.00 | \$48.50 | \$15,85 |
| | | 0001 | 0560 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 327.00 | 0.00 | 327.00 | CUYD | 327.00 | \$27.00 | \$8,82 |
| | | 0001 | 0570 | 6161005 | CONSTRUCTION SIGNS | 231.00 | 0.00 | 231.00 | SQFT | 224.50 | \$12.00 | \$2,69 |
| | | 0001 | 0580 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$35.00 | \$14 |
| | | 0001 | 0590 | 6161009 | FLAG ASSEMBLY | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$20.00 | \$4 |
| | | 0001 | 0600 | 6161010 | RELOCATED SIGNS | 64.00 | 0.00 | 64.00 | SQFT | 64.00 | \$6.00 | \$38 |
| | | 0001 | 0610 | 6161030 | TYPE III MOVEABLE BARRICADE | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$135.00 | \$1,35 |
| | | 0001 | 0620 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$91,300.00 | \$91,30 |
| | | 0001 | 0630 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 886.00 | 117.00 | 1,003.00 | LF | 1,003.00 | \$2.30 | \$2,30 |
| | | 0001 | 0640 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 111.00 | 199.00 | 310.00 | LF | 310.00 | \$2.30 | \$71 |
| | | 0001 | 0650 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 490.00 | 0.00 | 490.00 | SQYD | 490.00 | \$7.00 | \$3,43 |
| | | 0001 | 0660 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$7,000.00 | \$7,00 |
| | | 0001 | 0670 | 8059901 | MISC.LUMP SUM SEEDING | | 0.00 | 1.00 | LS | 0.80 | \$4,000.00 | \$3,20 |
| | | 0001 | 0680 | 8061005 | ROCK DITCH CHECK | 84.00 | -24.00 | 60.00 | LF | 60.00 | \$20.00 | \$1,20 |
| | | 0001 | 0690 | 8061016 | SEDIMENT REMOVAL | 10.00 | -10.00 | | CUYD | 0.00 | \$50.00 | |
| | | 0001 | 0700 | 8061019 | SILT FENCE | 223.00 | 0.00 | 223.00 | LF | 223.00 | \$4.00 | \$89 |
| | | 0001 | 0710 | 8061050 | TYPE C BERM | 172.00 | -172.00 | 0.00 | LF | 0.00 | \$43.00 | |
| | | 0001 | 0720 | 8069901 | MISC.TEMPORARY SEEDING AND MULCHING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$750.00 | \$75 |
| | | 0010 | 0730 | 6061069 | MGS BRIDGE APPROACH TRANSITION SECTION | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$3,100.00 | \$12,40 |
| | | 0010 | 0740 | 6063014 | (REGULAR/NO CURB) TYPE A CRASHWORTHY END TERMINAL (MASH) | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$2,950.00 | \$11,80 |
| | | 0070 | 0750 | 2061000 | CLASS 1 EXCAVATION | 60.00 | 0.00 | 60.00 | CUYD | 60.00 | \$50.50 | \$3,03 |
| | | 0070 | 0760 | 2160500 | REMOVAL OF BRIDGES | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$30,000.00 | \$30,00 |
| | | 0070 | 0770 | 5031011A | BRIDGE APPROACH SLAB (MINOR ROAD) | 114.00 | 0.00 | 114.00 | SQYD | 114.00 | \$170.00 | \$19,38 |
| | | 0070 | 0780 | 7021212 | GALVANIZED STRUCTURAL STEEL PILES (12 IN) | 825.00 | 38.00 | 863.00 | LF | 863.00 | \$68.50 | \$59,11 |
| | | | 0790 | 70272000 | PILE POINT REINFORCEMENT | 18.00 | 0.00 | 18.00 | EA | 18.00 | \$95.00 | \$1,71 |
| | | 0070 | | 7034003 | | | | | CUYD | | \$1,120.00 | |
| | | 0070 | 0800 | | CLASS B-1 CONCRETE (SUBSTRUCTURE) | 25.60 | 0.00 | 25.60 | | 25.60 | | \$28,67 |
| | | 0070 | 0810 | 7034208 | CLASS B-2 CONCRETE (SUPERSTRUCTURE SOLID SLAB) | 244.40 | 0.00 | 244.40 | CUYD | 244.40 | \$956.00 | \$233,64 |
| | | 0070 | 0820 | 7034219A | TYPE D BARRIER DEINICOPONIC STEEL (EDOVY COATED) | 251.00 | 0.00 | 251.00 | LF | 251.00 | \$117.00 | \$29,36 |
| | | 0070 | 0830 | 7101000 | REINFORCING STEEL (EPOXY COATED) | 46,220.00 | 0.00 | 46,220.00 | LB | 46,220.00 | \$1.20 | \$55,46 |
| | | 0070 | 0840 | 7123610 | SLAB DRAIN | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$340.00 | \$2,72 |
| | | 0070 | 0850 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,350.00 | \$6,70 |
| | Project J | 2S3198 - To | | | ate as of Report Generated Date | | | | | | | \$736,0 |

Revision 4/1/2020 Page 6 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J2S2168

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|-----------------------------|-------------|-------------------------|--------------------|-------|----------|------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0390 | 7034219A | TYPE D BARRIER | 1/21/21 | 1/27/21 | 536.00 | LF | | 649+20.28 | | 2+08.91 | | |
| 0410 | 7034630 | CONCRETE CURB (BRIDGE RAIL) | 1/20/21 | 1/27/21 | 268.00 | LF | | 649+20.28 | | 2+08.91 | | |

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 7 of 16



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|--------------------|-----------------------------|---------------------------------------|---|--|---|---|
| 0070 | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | Price | | 14 | Dec 31, 2020 | SYSTEM | (\$1.67) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | 15 | Jan 15, 2021 | SYSTEM | \$0.66 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | - Total | | | | (\$1.01) | |
| | Price - Total | | | | | | (\$1.01) | |
| 0070 - | - Total | | | | | | (\$1.01) | |
| 0800 | MISC. OPTIONAL PAVEMENT | Material | | 15 | Jan 15, 2021 | SYSTEM | (\$28,220.00) | |
| | | | | 15 | Jan 15, 2021 | SYSTEM | \$28,220.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sandip overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0080 - | · Total | | | | | | \$0.00 | |
| 0290 | BRIDGE APPROACH SLAB (MINOR ROAD) | Material | | 14 | Dec 31, 2020 | SYSTEM | (\$26,895.00) | |
| | | | | 14 | Dec 31, 2020 | SYSTEM | \$26,895.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 15 | Jan 15, 2021 | SYSTEM | (\$26,895.00) | |
| | | | | 15 | Jan 15, 2021 | SYSTEM | \$26,895.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 16 | Feb 1, 2021 | SYSTEM | (\$26,895.00) | |
| | | | | 16 | Feb 1, 2021 | SYSTEM | \$26,895.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0290 - | - Total | | | | | | \$0.00 | |
| | | | | | | | | |
| 0320 | GALVANIZED STRUCTURAL STEEL PILES | Material | | 9 | Oct 15, 2020 | SYSTEM | (\$67,105.50) | |
| 0320 | | Material | | 9 | | SYSTEM | (\$67,105.50) \$67,105.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| 0320 | STRUCTURAL STEEL PILES | Material | | | 2020 Oct 15, | | | Estimate Item Adjustment (0004) due to user sandip overridding Payment |
| 0320 | STRUCTURAL STEEL PILES | Material | | 9 | 2020 Oct 15, 2020 Nov 1, | SYSTEM | \$67,105.50 | Estimate Item Adjustment (0004) due to user sandip overridding Payment |
| 0320 | STRUCTURAL STEEL PILES | Material | | 9 | 2020 Oct 15, 2020 Nov 1, 2020 Nov 1, | SYSTEM SYSTEM | \$67,105.50 (\$67,105.50) | Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment |
| 0320 | STRUCTURAL STEEL PILES | Material | | 9 10 10 | 2020 Oct 15, 2020 Nov 1, 2020 Nov 1, 2020 Nov 15, | SYSTEM SYSTEM | \$67,105.50 (\$67,105.50) \$67,105.50 | Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment |
| 0320 | STRUCTURAL STEEL PILES | Material | | 9 10 10 11 | 2020 Oct 15, 2020 Nov 1, 2020 Nov 1, 2020 Nov 15, 2020 Nov 15, 2020 | SYSTEM SYSTEM SYSTEM | \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) | Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment |
| 0320 | STRUCTURAL STEEL PILES | Material | | 9 10 10 11 11 | 2020 Oct 15, 2020 Nov 1, 2020 Nov 1, 2020 Nov 15, 2020 Nov 15, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) | Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment |
| 0320 | STRUCTURAL STEEL PILES | Material | - Total | 9 10 10 11 11 11 12 | 2020 Oct 15, 2020 Nov 1, 2020 Nov 1, 2020 Nov 15, 2020 Nov 15, 2020 Nov 30, 2020 Nov 30, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) \$67,105.50 | Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment |
| 0320 | STRUCTURAL STEEL PILES | Material | - Total | 9 10 10 11 11 11 12 | 2020 Oct 15, 2020 Nov 1, 2020 Nov 1, 2020 Nov 15, 2020 Nov 15, 2020 Nov 30, 2020 Nov 30, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) | Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment |
| | STRUCTURAL STEEL PILES (12 IN) | Material | - Total | 9 10 10 11 11 11 12 | 2020 Oct 15, 2020 Nov 1, 2020 Nov 1, 2020 Nov 15, 2020 Nov 15, 2020 Nov 30, 2020 Nov 30, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) \$67,105.50 | Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment |
| | STRUCTURAL STEEL PILES (12 IN) | Material | - Total | 9 10 10 11 11 11 12 | 2020 Oct 15, 2020 Nov 1, 2020 Nov 1, 2020 Nov 15, 2020 Nov 15, 2020 Nov 30, 2020 Nov 30, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) \$67,105.50 | Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment |
| 0320 - | Material - Total PILE POINT | | - Total | 9 10 10 11 11 12 12 | 2020 Oct 15, 2020 Nov 1, 2020 Nov 1, 2020 Nov 15, 2020 Nov 30, 2020 Nov 30, 2020 Oct 15, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) \$0.00 \$0.00 | Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment |
| 0320 - | Material - Total PILE POINT | | - Total | 9 10 10 11 11 12 12 | 2020 Oct 15, 2020 Nov 1, 2020 Nov 15, 2020 Nov 15, 2020 Nov 30, 2020 Oct 15, 2020 Oct 15, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) \$67,105.50 (\$67,105.50) \$67,105.50 \$0.00 \$0.00 (\$1,140.00) | Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user sandip overridding Payment Estimate Item Adjustment (0005) due to user sandip overridding Payment |

Revision 4/1/2020 Page 8 of 16



| Estimate Exception 4 on the current Payment Estimate. | | | | | | | | | |
|--|----------------|---------------------------|----------|------------|----|-------|--------|----------------|--|
| SEINFORCEMENT | Line | Description | | Adjustment | | | | Amount | Remarks |
| 1 | 0340 | | Material | | | 2020 | | | Estimate Item Adjustment (0002) due to user sandip overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| 2000 12 Nov 30 SYSTEM (81,140,00) 12 Nov 30 SYSTEM (81,140,00) 12 Nov 30 SYSTEM (81,140,00) 13 Nov 10 SYSTEM (81,140,00) 14 Nov 30 SYSTEM (81,140,00) 15 Nov 30 SYSTEM (81,700,00) 15 | | | | | 11 | | SYSTEM | (\$1,140.00) | |
| 12 Nov 30 279 TEM 31,140,00 This adjustment offsets the original system-generated Overrun Payment Estimate Incursion (1002) are in user sands operating Flayment Estimate Exception 4 on the curried Payment Estimate. | | | | | 11 | | SYSTEM | \$1,140.00 | Estimate Item Adjustment (0002) due to user sandip overridding Payment |
| Total | | | | | 12 | | SYSTEM | (\$1,140.00) | |
| Material - Total | | | | | 12 | | SYSTEM | \$1,140.00 | Estimate Item Adjustment (0002) due to user sandip overridding Payment |
| Material - Total 10 | | | | - Total | | | | \$0.00 | |
| National September Septe | | Material - Total | | | | | | | |
| Masterial - Total | 0240 | | | | | | | | |
| Reinforcement (Open Ended CIP) | | | | | 40 | N 4 | OVOTEM | | |
| 10 | 0350 | Reinforcement (Open Ended | Material | | | 2020 | | | |
| 1 | | , | | | 10 | | SYSTEM | \$8,700.00 | Estimate Item Adjustment (0003) due to user sandip overridding Payment |
| 2020 SysTem So.00 SysTem Sectionale Exception 5 on the current Payment Estimate. | | | | | 11 | | SYSTEM | (\$8,700.00) | |
| 2020 12 | | | | | 11 | | SYSTEM | \$8,700.00 | Estimate Item Adjustment (0003) due to user sandip overridding Payment |
| Solid Soli | | | | | 12 | | SYSTEM | (\$8,700.00) | |
| Material - Total \$0.00 | | | | | 12 | | SYSTEM | \$8,700.00 | Estimate Item Adjustment (0003) due to user sandip overridding Payment |
| 10 | | | | - Total | | | | \$0.00 | |
| 10 | | Material - Total | | | | | | \$0.00 | |
| MISC. Galvanized Cast-In-Place Concrete Piles (42 in.) Material 10 | 0350 - | Total | | | | | | \$0.00 | |
| Place Concrete Piles (42 in.) | | | Material | | 10 | Nov 1 | SVSTEM | | |
| 2020 Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 6 on the current Payment Estimate. | 0300 | | Waterial | | | 2020 | | | This adjustment offsets the original system generated Overrup Payment |
| 2020 11 Nov 15, SYSTEM \$193,930.00 12 Nov 30, SYSTEM \$193,930.00 13 SYSTEM \$193,930.00 14 SYSTEM \$193,930.00 15 SYSTEM 1 | | | | | | | | φ90,700.00 | Estimate Item Adjustment (0004) due to user sandip overridding Payment |
| 2020 Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 6 on the current Payment Estimate. 12 Nov 30, 2020 12 Nov 30, SYSTEM \$193,930.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 6 on the current Payment Estimate. 30.00 300 - Total 30.00 500 - Total 30.00 300 - Total 30.00 | | | | | 11 | 2020 | | (\$193,930.00) | |
| 2020 12 | | | | | 11 | | SYSTEM | \$193,930.00 | Estimate Item Adjustment (0004) due to user sandip overridding Payment |
| Solution | | | | | 12 | | SYSTEM | (\$193,930.00) | |
| Material - Total S0.00 CLASS B CONCRETE (SUBSTRUCTURE) Material POct 15, 2020 SYSTEM (\$32,802.00) Total S0.00 Type D BARRIER Material S0.00 Material - Total S0.00 Type D BARRIER Material S0.00 Material SYSTEM SYSTEM SYSTEM SO.00 SYSTEM SO.00 SYSTEM SO.00 SO.00 Type D BARRIER Material SYSTEM SYSTEM SYSTEM SO.00 Type D BARRIER Material SYSTEM SYST | | | | | 12 | | SYSTEM | \$193,930.00 | Estimate Item Adjustment (0004) due to user sandip overridding Payment |
| | | | | - Total | | | | \$0.00 | |
| CLASS B CONCRETE (SUBSTRUCTURE) Material 9 Oct 15, 2020 9 Oct 15, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user sandip overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00 TYPE D BARRIER Material 16 Feb 1, 2021 16 Feb 1, 2021 SYSTEM \$50,116.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment | | Material - Total | | | | | | \$0.00 | |
| CLASS B CONCRETE (SUBSTRUCTURE) Material 9 Oct 15, 2020 9 Oct 15, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user sandip overridding Payment Estimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate. Total S0.00 Material - Total S0.00 TYPE D BARRIER Material 16 Feb 1, 2021 16 Feb 1, 2021 SYSTEM \$50,116.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment | 03 <u>60</u> - | Total | | | | | | \$0.00 | |
| 2020 Estimate Item Adjustment (0006) due to user sandip overridding Payment Estimate Exception 7 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00 0370 - Total \$0.00 TYPE D BARRIER Material | | CLASS B CONCRETE | Material | | 9 | | SYSTEM | | |
| Material - Total \$0.00 | | | | | 9 | | SYSTEM | \$32,802.00 | Estimate Item Adjustment (0006) due to user sandip overridding Payment |
| 0370 - Total TYPE D BARRIER Material 16 Feb 1, 2021 17 Feb 1, SYSTEM (\$50,116.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment | | | | - Total | | | | \$0.00 | |
| 0390 TYPE D BARRIER Material 16 Feb 1, 2021 16 Feb 1, SYSTEM (\$50,116.00) 16 Feb 1, SYSTEM \$50,116.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment | | Material - Total | | | | | | \$0.00 | |
| 0390 TYPE D BARRIER Material 16 Feb 1, 2021 16 Feb 1, SYSTEM (\$50,116.00) 16 Feb 1, SYSTEM \$50,116.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment | 0370 - | Total | | | | | | \$0.00 | |
| 16 Feb 1, SYSTEM \$50,116.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment | | | Material | | 16 | | SYSTEM | | |
| Estimate Estephon in on the standard all manuals. | 0390 | | | | | | | | |

Revision 4/1/2020 Page 9 of 16



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|
| 0390 | | Material | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0390 - | Total | | | | | | \$0.00 | |
| 0400 | SLAB ON CONCRETE BEAM | Material | | 12 | Nov 30, 2020 | SYSTEM | (\$102,678.00) | |
| | | | | 12 | Nov 30, 2020 | SYSTEM | \$102,678.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user sandip overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 13 | Dec 15, 2020 | SYSTEM | (\$278,518.00) | |
| | | | | 13 | Dec 15, 2020 | SYSTEM | \$278,518.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 14 | Dec 31, 2020 | SYSTEM | (\$278,518.00) | |
| | | | | 14 | Dec 31, 2020 | SYSTEM | \$278,518.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | 15 | Jan 15, 2021 | SYSTEM | (\$278,518.00) | |
| | | | | 15 | Jan 15, 2021 | SYSTEM | \$278,518.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | 16 | Feb 1, 2021 | SYSTEM | (\$278,518.00) | |
| | | | | 16 | Feb 1, 2021 | SYSTEM | \$278,518.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sandip overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0400 - | Total | | | | | | \$0.00 | |
| 0410 | CONCRETE CURB (BRIDGE RAIL) | Material | | 16 | Feb 1, 2021 | SYSTEM | (\$11,390.00) | |
| | | | | 16 | Feb 1, 2021 | SYSTEM | \$11,390.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 22 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0410 - | Total | | | | | | \$0.00 | |
| 0430 | REINFORCING STEEL (BRIDGES) | Material | | 10 | Nov 1, 2020 | SYSTEM | (\$7,587.50) | |
| | | | | 10 | Nov 1, 2020 | SYSTEM | \$7,587.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user sandip overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 11 | Nov 15, 2020 | SYSTEM | (\$51,775.00) | |
| | | | | 11 | Nov 15, 2020 | SYSTEM | \$51,775.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user sandip overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 12 | Nov 30, 2020 | SYSTEM | (\$51,775.00) | |
| | | | | 12 | Nov 30, 2020 | SYSTEM | \$51,775.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user sandip overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0430 - | Total | | | | | | \$0.00 | |
| 0490 | CLASS A EXCAVATION | Price | | 8 | Oct 1, 2020 | SYSTEM | (\$1.56) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | - Total | | | | (\$1.56) | |
| | Price - Total | | | | | | (\$1.56) | |
| 0490 - | | | | | | 2112 | (\$1.56) | |
| 0500 | EMBANKMENT IN PLACE | Material | | 2 | Jun 30, | SYSTEM | (\$29,853.00) | |

Revision 4/1/2020 Page 10 of 16



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | |
|------|--------------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|---------------|--|--|--|---|-----------------|--------|---------------|----|-----------------|--------|---------------|
| 0500 | EMBANKMENT IN PLACE | Material | | | 2020 | | | | | | | | | | | | | |
| | | | | 2 | Jun 30, 2020 | SYSTEM | \$29,853.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user sandip overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | |
| | | | | 3 | Jul 15, 2020 | SYSTEM | (\$29,853.00) | | | | | | | | | | | |
| | | | | 3 | Jul 15, 2020 | SYSTEM | \$29,853.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | |
| | | | | 4 | Aug 3, 2020 | SYSTEM | (\$29,853.00) | | | | | | | | | | | |
| | | | | 4 | Aug 3, 2020 | SYSTEM | \$29,853.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | |
| | | | | 5 | Aug 16, 2020 | SYSTEM | (\$29,853.00) | | | | | | | | | | | |
| | | | | 5 | Aug 16, 2020 | SYSTEM | \$29,853.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | |
| | | | | 6 | Sep 1, 2020 | SYSTEM | (\$29,853.00) | | | | | | | | | | | |
| | | | | 6 | Sep 1, 2020 | SYSTEM | \$29,853.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user sandip overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | |
| | | | | | | | | | | | 7 | Sep 15, 2020 | SYSTEM | (\$29,853.00) | | | | |
| | | | | | | | | | | | | | | | 7 | Sep 15, 2020 | SYSTEM | \$29,853.00 |
| | | | | 8 | Oct 1, 2020 | SYSTEM | (\$29,853.00) | | | | | | | | | | | |
| | | | | 8 | Oct 1, 2020 | SYSTEM | \$29,853.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | |
| | | | | | 9 | Oct 15, 2020 | SYSTEM | (\$29,853.00) | | | | | | | | | | |
| | | | | 9 | Oct 15, 2020 | SYSTEM | \$29,853.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user sandip overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | |
| | | | | 10 | Nov 1, 2020 | SYSTEM | (\$29,853.00) | | | | | | | | | | | |
| | | | | 10 | Nov 1, 2020 | SYSTEM | \$29,853.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user sandip overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | |
| | | | | 11 | Nov 15, 2020 | SYSTEM | (\$29,853.00) | | | | | | | | | | | |
| | | | | | 11 | Nov 15, 2020 | SYSTEM | \$29,853.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user sandip overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | |
| | | | | | | | | | | | | | | | 12 | Nov 30, 2020 | SYSTEM | (\$29,853.00) |
| | | | | 12 | Nov 30, 2020 | SYSTEM | \$29,853.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user sandip overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | | | | | |
| | | | - Total | | | | \$0.00 | | | | | | | | | | | |
| | Material - Total | | | | | | \$0.00 | | | | | | | | | | | |
| | EMBANKMENT IN PLACE | Price | ce | 2 | Jun 30, 2020 | SYSTEM | (\$182.01) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | |
| | | | - Total | | | | (\$182.01) | | | | | | | | | | | |
| | Price - Total | | | | | | (\$182.01) | | | | | | | | | | | |
| | ·Total | | | | | | (\$182.01) | | | | | | | | | | | |
| 0510 | COMPACTING EMBANKMENT | Material | | 8 | Oct 1, 2020 | SYSTEM | (\$754.00) | | | | | | | | | | | |
| | | | | 8 | Oct 1, 2020 | SYSTEM | \$754.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user sandip overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | | | | | | | |

Revision 4/1/2020 Page 11 of 16



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|----------------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|----------------------------|---|
| 0510 | COMPACTING EMBANKMENT | Material | | 9 | Oct 15, 2020 | SYSTEM | (\$754.00) | |
| | | | | 9 | Oct 15, 2020 | SYSTEM | \$754.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user sandip overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 10 | Nov 1, 2020 | SYSTEM | (\$754.00) | |
| | | | | 10 | Nov 1, 2020 | SYSTEM | \$754.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user sandip overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 11 | Nov 15, 2020 | SYSTEM | (\$754.00) | |
| | | | | 11 | Nov 15, 2020 | SYSTEM | \$754.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user sandip overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 12 | Nov 30, 2020 | SYSTEM | (\$754.00) | |
| | | | | 12 | Nov 30, 2020 | SYSTEM | \$754.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user sandip overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0510 - | Total | | | | | | \$0.00 | |
| 0520 | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | Material | | 8 | Oct 1, 2020 | SYSTEM | (\$8,140.00) | |
| | | | | 8 | Oct 1, 2020 | SYSTEM | \$8,140.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 9 | Oct 15, 2020 | SYSTEM | (\$8,140.00) | |
| | | | | 9 | Oct 15, 2020 | SYSTEM | \$8,140.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | - Total | | | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | Price | | 8 | Oct 1, 2020 | SYSTEM | (\$28.86) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | - Total | | | | (\$28.86) | |
| | Price - Total | | | | | | (\$28.86) | |
| 0520 - | | Meterial | | 9 | Oat 15 | CVCTEM | (\$28.86) | |
| 0530 | CRUSHED STONE (B) | Material | | 9 | Oct 15, 2020 | SYSTEM | (\$1,760.00) \$1,760.00 | This adjustment offsets the original system-generated Overrun Payment |
| | | | | | 2020 | 0.0.2 | ψ1,1 co.oc | Estimate Item Adjustment (0010) due to user sandip overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0530 - | | Otto and II | 1015 | 0 | 0.4.1 | | \$0.00 | |
| 0540 | MISC. OPTIONAL PAVEMENT | Other Item Adjustment | ACAD | | Oct 1, 2020 | vierss | (\$799.45) | |
| | ACAD - Total | | | | | | (\$799.45) | |
| 0540 | Other Item Adjustment - Total) - Total | | | | | | (\$799.45) | |
| 0540 - 0670 | MISC. LUMP SUM SEEDING | Material | | 10 | Nov 1, | SYSTEM | (\$799.45) (\$3,200.00) | |
| 5070 | MIGO. LOWII GOW GLLDING | Material | | 10 | 2020 Nov 1, | SYSTEM | \$3,200.00) | This adjustment offsets the original system-generated Overrun Payment |
| | | | | | 2020 | | | Estimate Item Adjustment (0008) due to user sandip overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | 11 | Nov 15, 2020 | SYSTEM | (\$3,200.00) | |
| | | | | 11 | Nov 15, 2020 | SYSTEM | \$3,200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user sandip overridding Payment Estimate Exception 15 on the current Payment Estimate. |

Revision 4/1/2020 Page 12 of 16



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|---|---|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 0670 | | Material | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0670 - | Total | | | | | | \$0.00 | |
| 0730 | MGS BRIDGE APPROACH TRANSITION SECTION | Construction Stockpile | | 1 | Jun 13, 2020 | SYSTEM | \$5,996.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | (REGULAR/NO CURB) | | | 9 | Oct 15, 2020 | SYSTEM | (\$5,996.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | - Total | | | | \$0.00 | |
| | Construction Stockpile - Tota | ıl | | | | | \$0.00 | |
| 0730 - | Total | | | | | | \$0.00 | |
| 0740 | TYPE A CRASHWORTHY END TERMINAL (MASH) | Construction Stockpile | | 1 | Jun 13, 2020 | SYSTEM | \$6,040.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | 9 | Oct 15, 2020 | SYSTEM | (\$6,040.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | - Total | | | | \$0.00 | |
| | Construction Stockpile - Tota | ll en | | | | | \$0.00 | |
| 0740 - | | | | | | | \$0.00 | |
| 0770 | BRIDGE APPROACH SLAB (MINOR ROAD) | Material | | 13 | Dec 15, 2020 | SYSTEM | (\$19,380.00) | |
| | | | | 13 | Dec 15, 2020 | SYSTEM | \$19,380.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user sandip overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 14 | Dec 31, 2020 | SYSTEM | (\$19,380.00) | |
| | | | | 14 | Dec 31, 2020 | SYSTEM | \$19,380.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandip overridding Payment |
| | | | | 15 | Jan 15, 2021 | SYSTEM | (\$19,380.00) | Estimate Exception 5 on the current Payment Estimate. |
| | | | | 15 | Jan 15, 2021 | SYSTEM | \$19,380.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandip overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | 16 | Feb 1, 2021 | SYSTEM | (\$19,380.00) | |
| | | | | 16 | Feb 1, 2021 | SYSTEM | \$19,380.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | Total | | | | \$0.00 | |
| 0770 - | | | | | | | \$0.00 | |
| 0780 | GALVANIZED STRUCTURAL STEEL PILES (12 IN) | Material | | 3 | Jul 15, 2020 | SYSTEM | (\$47,402.00) | |
| | | | - Total | | | | (\$47,402.00) | |
| | Material - Total | | | | | | (\$47,402.00) | |
| | GALVANIZED STRUCTURAL STEEL PILES (12 IN) | MaterialCredit | | 4 | Aug 3, 2020 | SYSTEM | \$47,402.00 | |
| | . , | | - Total | | | | \$47,402.00 | |
| | MaterialCredit - Total | | | | | \$47,402.00 | | |
| | GALVANIZED STRUCTURAL STEEL PILES | Overrun | Overrun | 4 | Aug 3, 2020 | SYSTEM | (\$2,603.00) | |
| | (12 IN) | | | 14 | Dec 31, 2020 | SYSTEM | \$2,603.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',68.50000 - 68.50000, 'is applied (if non-zero). |
| | | Overrun - T | otal | | | \$0.00 | | |
| | Overrun - Total | | | | | | \$0.00 | |
| 0780 - | Total | | | | | | \$0.00 | |
| | | | | | A O | CVCTEM | (01.710.00) | |
| 0790 | PILE POINT REINFORCEMENT | Material | | 4 | Aug 3, 2020 | SYSTEM | (\$1,710.00) | |

Revision 4/1/2020 Page 13 of 16



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|--------|--|--------------------|-----------------------------|----------------|-----------------|-----------------|----------------|--|--|
| 0790 | PILE POINT REINFORCEMENT | Material | | | | | | Estimate Exception 2 on the current Payment Estimate. | |
| | | | - Total | | | | \$0.00 | | |
| | Material - Total | | | | | | \$0.00 | | |
| 0790 - | | | | | | | \$0.00 | | |
| 0800 | CLASS B-1 CONCRETE (SUBSTRUCTURE) | Material | | 4 | Aug 3, 2020 | SYSTEM | (\$28,672.00) | | |
| | | | | 4 | Aug 3, 2020 | SYSTEM | \$28,672.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user sandip overridding Payment Estimate Exception 3 on the current Payment Estimate. | |
| | | | - Total | | | | \$0.00 | | |
| | Material - Total | | | | | | \$0.00 | | |
| 0800 - | Total | | | | | | \$0.00 | | |
| 0810 | CLASS B-2 CONCRETE (SUPERSTRUCTURE SOLID SLAB) | Material | | 4 | Aug 3, 2020 | SYSTEM | (\$13,001.60) | | |
| | OLABI | | | 4 | Aug 3, 2020 | SYSTEM | \$13,001.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user sandip overridding Payment Estimate Exception 8 on the current Payment Estimate. | |
| | | | | 5 | Aug 16, 2020 | SYSTEM | (\$13,001.60) | | |
| | | | | 5 | Aug 16, 2020 | SYSTEM | \$13,001.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user sandip overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | 6 | Sep 1, 2020 | SYSTEM | (\$90,055.20) | | |
| | | | | 6 | Sep 1, 2020 | SYSTEM | \$90,055.20 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user sandip overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | 7 | Sep 15, 2020 | SYSTEM | (\$221,792.00) | | |
| | | | | 7 | Sep 15, 2020 | SYSTEM | \$221,792.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user sandip overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | 8 | Oct 1, 2020 | SYSTEM | (\$221,792.00) | | |
| | | | | 8 | Oct 1, 2020 | SYSTEM | \$221,792.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user sandip overridding Payment Estimate Exception 4 on the current Payment Estimate. | |
| | | | | 9 | Oct 15, 2020 | SYSTEM | (\$42,446.40) | | |
| | | | | 9 | Oct 15, 2020 | SYSTEM | \$42,446.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user sandip overridding Payment Estimate Exception 8 on the current Payment Estimate. | |
| | | | | 10 | Nov 1, 2020 | SYSTEM | (\$42,446.40) | | |
| | | | | 10 | Nov 1, 2020 | SYSTEM | \$42,446.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user sandip overridding Payment Estimate Exception 7 on the current Payment Estimate. | |
| | | | | 11 | Nov 15, 2020 | SYSTEM | (\$42,446.40) | | |
| | | | | | 11 | Nov 15, 2020 | SYSTEM | \$42,446.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user sandip overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | 12 | Nov 30, 2020 | SYSTEM | (\$42,446.40) | | |
| | | | | 12 | Nov 30, 2020 | SYSTEM | \$42,446.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user sandip overridding Payment Estimate Exception 7 on the current Payment Estimate. | |
| | | | | 13 | Dec 15, 2020 | SYSTEM | (\$42,446.40) | | |
| | | | | 13 | Dec 15, 2020 | SYSTEM | \$42,446.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment Estimate Exception 7 on the current Payment Estimate. | |
| | | | | 14 | Dec 31, 2020 | SYSTEM | (\$42,446.40) | | |
| | | | | 14 | Dec 31, | SYSTEM | \$42,446.40 | This adjustment offsets the original system-generated Material Payment | |

Revision 4/1/2020 Page 14 of 16



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | | | | | | |
|--------|--|--------------------|-----------------------------|----------------|-----------------|-----------------|---------------|--|--|-----------------|--------|-------------|--|--|--|--|--|--|--|--|----|-----------------|--------|-------------|--|
| 0810 | CLASS B-2 CONCRETE (SUPERSTRUCTURE SOLID SLAB) | Material | | | 2020 | | | Estimate Item Adjustment (0007) due to user sandip overridding Payment Estimate Exception 14 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | 15 | Jan 15, 2021 | SYSTEM | (\$42,446.40) | | | | | | | | | | | | | | | | | | |
| | | | | 15 | Jan 15, 2021 | SYSTEM | \$42,446.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandip overridding Payment Estimate Exception 15 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | 16 | Feb 1, 2021 | SYSTEM | (\$42,446.40) | | | | | | | | | | | | | | | | | | |
| | | | | 16 | Feb 1, 2021 | SYSTEM | \$42,446.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandip overridding Payment Estimate Exception 12 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | 1 | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | | | |
| | Material - Total | | | | | | \$0.00 | | | | | | | | | | | | | | | | | | |
| 0810 - | Total | | | | | | \$0.00 | | | | | | | | | | | | | | | | | | |
| 0820 | TYPE D BARRIER | Material | | 7 | Sep 15, 2020 | SYSTEM | (\$29,367.00) | | | | | | | | | | | | | | | | | | |
| | | | | 7 | Sep 15, 2020 | SYSTEM | \$29,367.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | 8 | Oct 1, 2020 | SYSTEM | (\$29,367.00) | | | | | | | | | | | | | | | | | | |
| | | | | 8 | Oct 1, 2020 | SYSTEM | \$29,367.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment Estimate Exception 6 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | 9 | Oct 15, 2020 | SYSTEM | (\$29,367.00) | | | | | | | | | | | | | | | | | | |
| | | | | | 9 | Oct 15, 2020 | SYSTEM | \$29,367.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user sandip overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | | | | | | | | | | |
| | | | | 10 | Nov 1, 2020 | SYSTEM | (\$29,367.00) | | | | | | | | | | | | | | | | | | |
| | | | | 10 | Nov 1, 2020 | SYSTEM | \$29,367.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user sandip overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | 11 | Nov 15, 2020 | SYSTEM | (\$29,367.00) | | | | | | | | | | | | | | | | | | |
| | | | | 11 | Nov 15, 2020 | SYSTEM | \$29,367.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user sandip overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | 12 | Nov 30, 2020 | SYSTEM | (\$29,367.00) | | | | | | | | | | | | | | | | | | |
| | | | | 12 | Nov 30, 2020 | SYSTEM | \$29,367.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user sandip overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | | 13 | Dec 15, 2020 | SYSTEM | (\$29,367.00) | | | | | | | | | | | | | | | | | |
| | | | | | | | | | 13 | Dec 15, 2020 | SYSTEM | \$29,367.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user sandip overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | 14 | Dec 31, 2020 | SYSTEM | (\$29,367.00) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | 14 | Dec 31, 2020 | SYSTEM | \$29,367.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user sandip overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | 15 | Jan 15, 2021 | SYSTEM | (\$29,367.00) | | | | | | | | | | | | | | | | | | |
| | | | | 15 | Jan 15, 2021 | SYSTEM | \$29,367.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandip overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | | 16 | Feb 1, 2021 | SYSTEM | (\$29,367.00) | | | | | | | | | | | | | | | | | | |
| | | | | 16 | Feb 1, 2021 | SYSTEM | \$29,367.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandip overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | | | | | | | | | | | | | | | |
| | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | | | |
| | Material - Total | | | | | | \$0.00 | | | | | | | | | | | | | | | | | | |

Revision 4/1/2020 Page 15 of 16



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | |
|--------------|-------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|--|---|----------------|--------|---------------|--|
| 0820 - | Total | | | | | | \$0.00 | | | | | | | |
| 0830 | REINFORCING STEEL Ma (EPOXY COATED) | Material | Material | Material | Material | Material | Material | Material | | 4 | Aug 3, 2020 | SYSTEM | (\$10,180.80) | |
| | | | | 4 | Aug 3, 2020 | SYSTEM | \$10,180.80 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user sandip overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | |
| | | | - Total | | | | \$0.00 | | | | | | | |
| | Material - Total | | | | | | \$0.00 | | | | | | | |
| 0830 - Total | | | | | | | \$0.00 | | | | | | | |
| Overa | II - Total | | | | | | (\$1,012.89) | | | | | | | |

Revision 4/1/2020 Page 16 of 16