

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2020

Progress Estimate Number 10		Contract ID 200320 Prime Contractor R. V. W				2020	Original Contract Amount Net Change Order Amoun Current Contract Amount	t (\$312,683.09)
Approval Date								By User
October 1, 2020		Generate	d and Approved	(and should b	e considered Dra	aft) at	the Project Office Level by	steppr1
October 2, 2020		Reviewed and	d Approved (and	should be cor	sidered Draft) at	the R	esident Engineer Level by	morgac1
October 5, 2020			d at the Central C	Office	Controllers Office Level by	greggd1		
Original Comp	letion Date	e Current Completion Date Actual Completion Date % of Current Contract Ame					nt Complete	
December	1, 2020	December 1, 2020					92.63%	

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 10											
		This Estimate	Previous	To Date							
200320-F03											
	Total Posted Items Pay	\$36,512.00	\$1,596,590.81	\$1,633,102.81							
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00							
	Incentive	\$0.00	\$0.00	\$0.00							
	Disincentive	\$0.00	\$0.00	\$0.00							
	Liquidated Damage	\$0.00	\$0.00	\$0.00							
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00							
	·		\$1,596,590.81	\$1,633,102.81							
Contract Total Pa	yable This Estimate:	\$36,512.00									

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J6I3243	0100	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	LF	\$13.000	221	\$2,873.00		
	0120	7172054	OPEN CELL FOAM JOINT SEAL	LF	\$33.000	221	\$7,293.00		
	0130	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	LF	\$13.000	221	\$2,873.00		
	0150	7172054	OPEN CELL FOAM JOINT SEAL	LF	\$33.000	221	\$7,293.00		
	0160	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	LF	\$14.000	210	\$2,940.00		
	0180	7172054	OPEN CELL FOAM JOINT SEAL	LF	\$34.000	210	\$7,140.00		
	0260	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	LF	\$15.000	122	\$1,830.00		
	0280	7172054	OPEN CELL FOAM JOINT SEAL	LF	\$35.000	122	\$4,270.00		
Project J6l3243 - Total									
Overall - Tota	al						\$36,512.00		

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3243	0120	OPEN CELL FOAM JOINT SEAL	Material			-221	\$33.00	(\$7,293.00)
	0120	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	221	\$33.00	\$7,293.00
	0150	OPEN CELL FOAM JOINT SEAL	Material			-221	\$33.00	(\$7,293.00)
	0150	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1	221	\$33.00	\$7,293.00

Revision 4/1/2020 Page 1 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2020

Progress Estimate Number 10 Contract ID 200320-F03 Pay Period Start September 16, 2020 Original Contract Amount \$2,075,731.00 September 30, 2020 For Amount Current Contract Amount \$1,763,047.91

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3243					overridding Payment Estimate Exception 3 on the current Payment Estimate.			
	0180	OPEN CELL FOAM JOINT SEAL	Material			-210	\$34.00	(\$7,140.00)
	0180	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	210	\$34.00	\$7,140.00
	0210	OPEN CELL FOAM JOINT SEAL	Material			-210	\$34.00	(\$7,140.00)
	0210	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	210	\$34.00	\$7,140.00
	0250	OPEN CELL FOAM JOINT SEAL	Material			-210	\$34.00	(\$7,140.00
	0250	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	210	\$34.00	\$7,140.00
	0280	OPEN CELL FOAM JOINT SEAL	Material			-242	\$35.00	(\$8,470.00)
	0280	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	242	\$35.00	\$8,470.00
otal								\$0.00

Revision 4/1/2020 Page 2 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information	1				
Project Federal Project Route County Location of Number Route Proj. Number											
J6I3243	I 44-3(118)	7 Bridge rehabilitations	I-44	FRANKLIN	east of MO 100 to Highway OO in Pacific						
J6I3252	I 44-4(201)	6 Bridge rehabilitations	I-44	ST LOUIS	from US Route 66 to E	BNSF R.R. on I-44 in Eureka					
Totals by	otals by Job Numbers										
J6I3243		d Item Pay Item Adjustme		Item Pay	This Estimate \$36,512.00 \$0.00 \$36,512.00	Previous \$621,009.10 \$0.00 \$621,009.10	To Date \$657,521.10 \$0.00 \$657,521.10				
	Liquid	tive centive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J6l3252 Posted Item Pay Gross Item Adjustment		ents Gross Item Pay		This Estimate \$0.00 \$0.00 \$0.00	Previous \$975,581.71 \$0.00 \$975,581.71	To Date \$975,581.71 \$0.00 \$975,581.71					
Incentive Disincentive Liquidated Damages Other Contract Adjustm		tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 4/1/2020 Page 3 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3243, Item 7172054, Project Item Line Number 0250, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3243, Item 7172054, Project Item Line Number 0280, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3243, Item 7172054, Project Item Line Number 0150, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3243, Item 7172054, Project Item Line Number 0120, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3243, Item 7172054, Project Item Line Number 0210, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	No Remark was entered by Engineer	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3243, Item 7172054, Project Item Line Number 0180, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	No Remark was entered by Engineer	steppr1	Overridden

Revision 4/1/2020 Page 4 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-F03	J6I3243	0001	0010	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.95	\$50,000.00	\$47,500.00
		0001	0020	6169902	MISC.CHANGEABLE MESSAGE SIGN NTCIP COMPLIANT, CONTRACTOR FURNISHED/RETAINED	2.00	0.00	2.00	EA	2.00	\$3,800.00	\$7,600.00
		0001	0030	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$79,000.00	\$79,000.00
		0001	0040	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,386.00	0.00	1,386.00	LF	0.00	\$0.30	\$0.00
		0001	0050	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	5,430.00	0.00	5,430.00	LF	0.00	\$0.55	\$0.00
		0001	0060	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,618.00	0.00	3,618.00	LF	0.00	\$0.40	\$0.00
		0001	0070	6209903	MISC.4 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,386.00	0.00	1,386.00	LF	0.00	\$0.30	\$0.00
		0001	0080	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	43,544.00	-23,514.00	20,030.00	LB	20,030.00	\$4.10	\$82,123.00
		0001	0090	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$800.00	\$0.00
		0070	0100	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	221.00	0.00	221.00	LF	221.00	\$13.00	\$2,873.00
		0070	0110	6233000	EPOXY POLYMER WEARING SURFACE	2,012.00	0.00	2,012.00	SQYD	2,012.00	\$32.45	\$65,289.40
		0070	0120	7172054	OPEN CELL FOAM JOINT SEAL	221.00	0.00	221.00	LF	221.00	\$33.00	\$7,293.00
		0071	0130	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	221.00	0.00	221.00	LF	221.00	\$13.00	\$2,873.00
		0071	0140	6233000	EPOXY POLYMER WEARING SURFACE	2,156.00	0.00	2,156.00	SQYD	2,156.00	\$31.45	\$67,806.20
		0071	0150	7172054	OPEN CELL FOAM JOINT SEAL	221.00	0.00	221.00	LF	221.00	\$33.00	\$7,293.00
		0072	0160	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	210.00	0.00	210.00	LF	210.00	\$14.00	\$2,940.00
		0072	0170	6233000	EPOXY POLYMER WEARING SURFACE	905.00	0.00	905.00	SQYD	905.00	\$41.75	\$37,783.75
		0072	0180	7172054	OPEN CELL FOAM JOINT SEAL	210.00	0.00	210.00	LF	210.00	\$34.00	\$7,140.00
		0073	0190	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	210.00	0.00	210.00	LF	210.00	\$14.00	\$2,940.00
		0073	0200	6233000	EPOXY POLYMER WEARING SURFACE	903.00	0.00	903.00	SQYD	903.00	\$41.85	\$37,790.55
		0073	0210	7172054	OPEN CELL FOAM JOINT SEAL	210.00	0.00	210.00	LF	210.00	\$34.00	\$7,140.00
		0074	0220	6233000	EPOXY POLYMER WEARING SURFACE	1,514.00	0.00	1,514.00	SQYD	1,514.00	\$36.70	\$55,563.80
		0075	0230	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	210.00	0.00	210.00	LF	210.00	\$14.00	\$2,940.00
		0075	0240	6233000	EPOXY POLYMER WEARING SURFACE	1,272.00	0.00	1,272.00	SQYD	1,272.00	\$40.15	\$51,070.80
		0075	0250	7172054	OPEN CELL FOAM JOINT SEAL	210.00	0.00	210.00	LF	210.00	\$34.00	\$7,140.00
		0076	0260	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	242.00	0.00	242.00	LF	242.00	\$15.00	\$3,630.00
		0076	0270	6233000	EPOXY POLYMER WEARING SURFACE	1,456.00	0.00	1,456.00	SQYD	1,456.00	\$37.60	\$54,745.60
		0076	0280	7172054	OPEN CELL FOAM JOINT SEAL	242.00	0.00	242.00	LF	242.00	\$35.00	\$8,470.00
		0070	5001	7040104	HALF-SOLE REPAIR	0.00	20.00	20.00	SQFT	20.00	\$134.00	\$2,680.00
		0070	5002	7040104	HALF-SOLE REPAIR	0.00	2.00	2.00	SQFT	2.00	\$134.00	\$268.00
			5002	7040104	HALF-SOLE REPAIR	0.00	29.00	29.00	SQFT	29.00	\$134.00	\$3,886.00
		0072	5004	7040104	HALF-SOLE REPAIR	0.00	8.00	8.00	SQFT	8.00	\$134.00	\$1,072.00
		0075	5005	7040104	HALF-SOLE REPAIR	0.00	5.00	5.00	SQFT	5.00	\$134.00	\$670.00
	Project				Date as of Report Generated Date	0.00	5.00	3.00	JQI I	5.00	\$134.00	\$657,521.10
	J6I3252	0001	0290	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$27,000.00	\$20,250.00
		0001	0300	2037075	COMPACTING IN CUT	0.50	0.00	0.50	STA	0.00	\$1,000.00	\$0.00
		0001	0310	2071000	LINEAR GRADING CLASS 1	0.50	0.00	0.50	STA	0.00	\$6,850.00	\$0.00
		0001	0320	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	102.00	0.00	102.00	SQYD	0.00	\$16.00	\$0.00
		0001	0330	5029905	MISC.TYPE A2 SHOULDER	102.20	0.00	102.20	SQYD	0.00	\$57.00	\$0.00
		0001	0340	6099903	MISC.4 IN. TYPE 'A' INTEGRAL CURB (MODIFIED ON	66.00	0.00	66.00	LF	0.00	\$57.00	\$0.00
		0001	0350	6113020	CONCRETE) FURNISHING TYPE 2 ROCK BLANKET	120.00	0.00	120.00	CUYD	0.00	\$31.00	\$0.00
		0001	0360	6113040	PLACING TYPE 2 ROCK BLANKET	120.00	0.00	120.00	CUYD	0.00	\$50.00	\$0.00
		0001	0370	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.95	\$49,000.00	\$46,550.00
		0001	0380	6169902	MISC.CHANGEABLE MESSAGE SIGN NTCIP COMPLIANT,	2.00	0.00	2.00	EA	2.00	\$3,800.00	\$7,600.00
		0001	0390	6181000	CONTRACTOR FURNISHED/RETAINED MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$108,000.00	\$108,000.00

Page 5 of 10 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract ONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0-F03	J6I3252	0001	0400	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,238.00	0.00	1,238.00	LF	0.00	\$0.30	\$0.00
		0001	0410	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	10,113.00	0.00	10,113.00	LF	0.00	\$0.55	\$0.00
		0001	0420	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,033.00	0.00	7,033.00	LF	0.00	\$0.40	\$0.00
		0001	0430	6209903	MISC.4 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,238.00	0.00	1,238.00	LF	0.00	\$0.30	\$0.00
		0001	0440	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	42,988.00	-32,511.00	10,477.00	LB	10,477.00	\$4.10	\$42,955.70
		0001	0450	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$7,000.00	\$0.00
		0010	0460	6061060	MGS GUARDRAIL	4,175.00	0.00	4,175.00	LF	4,112.50	\$22.50	\$92,531.25
		0010	0470	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	575.00	0.00	575.00	LF	575.00	\$25.00	\$14,375.00
		0010	0480	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	11.00	0.00	11.00	EA	11.00	\$3,100.00	\$34,100.00
		0010	0490	6061080	MGS END ANCHOR	3.00	0.00	3.00	EA	3.00	\$1,070.00	\$3,210.00
		0010	0500	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	6.00	0.00	6.00	EA	6.00	\$2,900.00	\$17,400.00
		0010	0510	6063017	TYPE C CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	0.00	\$17,600.00	\$0.00
		0070	0520	6233000	EPOXY POLYMER WEARING SURFACE	2,093.00	0.00	2,093.00	SQYD	2,093.00	\$34.35	\$71,894.55
		0070	0530	7040104	HALF-SOLE REPAIR	200.00	-188.00	12.00	SQFT	12.00	\$134.00	\$1,608.00
		0070	0540	7173002	SILICONE EXPANSION JOINT SEALANT	29.00	0.00	29.00	LF	0.00	\$43.00	\$0.00
		0070	0550	7174002	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	121.00	0.00	121.00	LF	0.00	\$49.00	\$0.00
		0071	0560	6233000	EPOXY POLYMER WEARING SURFACE	2,950.00	0.00	2,950.00	SQYD	2,950.00	\$30.15	\$88,942.50
		0071	0570	7040104	HALF-SOLE REPAIR	100.00	-87.00	13.00	SQFT	13.00	\$134.00	\$1,742.00
		0071	0575	7172054	OPEN CELL FOAM JOINT SEAL	477.00	0.00	477.00	LF	0.00	\$32.00	\$0.00
		0072	0590	6233000	EPOXY POLYMER WEARING SURFACE	5,074.00	0.00	5,074.00	SQYD	5,074.00	\$31.50	\$159,831.00
		0072	0600	7040104	HALF-SOLE REPAIR	100.00	-80.00	20.00	SQFT	20.00	\$134.00	\$2,680.00
		0072	0610	7173002	SILICONE EXPANSION JOINT SEALANT	68.00	0.00	68.00	LF	0.00	\$40.00	\$0.00
		0072	0620	7174002	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	265.00	0.00	265.00	LF	0.00	\$46.00	\$0.00
		0073	0630	6233000	EPOXY POLYMER WEARING SURFACE	3,976.00	0.00	3,976.00	SQYD	3,976.00	\$33.15	\$131,804.40
		0073	0640	7040104	HALF-SOLE REPAIR	200.00	-195.00	5.00	SQFT	5.00	\$134.00	\$670.00
		0074	0650	6233000	EPOXY POLYMER WEARING SURFACE	1,224.00	0.00	1,224.00	SQYD	1,124.00	\$39.60	\$44,510.40
		0074	0660	7040104	HALF-SOLE REPAIR	50.00	-47.00	3.00	SQFT	3.00	\$134.00	\$402.00
		0074	0670	7174002	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	89.00	0.00	89.00	LF	0.00	\$57.00	\$0.00
		0075	0680	6233000	EPOXY POLYMER WEARING SURFACE	2,090.00	0.00	2,090.00	SQYD	2,090.00	\$33.15	\$69,283.50
		0075	0690	7040104	HALF-SOLE REPAIR	200.00	-191.00	9.00	SQFT	9.00	\$134.00	\$1,206.00
		0075	0700	7174002	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	121.00	0.00	121.00	LF	0.00	\$48.00	\$0.00
		0001	5101	2159903		0.00	400.00	400.00	LF	400.00	\$9.45	\$3,780.00
		0074	5102	2161502	REMOVAL OF CONCRETE WEARING SURFACE	0.00	10,359.00	10,359.00	SQFT	10,359.00	\$0.99	\$10,255.41
	Project .	1613252 - To	otal Value	Posted to E	Date as of Report Generated Date							\$975,581.71
0-F03 Ove	rall - Tota	Value Pos	ted to Da	ite as of Rep	ort Generated Date							\$1,633,102.

Page 6 of 10 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J6I3243

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0100	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL	9/23/20	9/24/20	110.50	LF	A52431 (UP) - WB I-44 - RP / PAS & PAS / BAS East of Bridge - Shoulders, Lanes 1, 2, 3	1636+14	LT	1636+72	LT	
				9/24/20	110.50	LF	A52431 (UP) - WB I-44 - RP / PAS & PAS / BAS West of Bridge - Shoulders, Lanes 1, 2, 3	1639+79	LT	1640+64	LT	
0120	7172054	OPEN CELL FOAM JOINT SEAL	9/23/20	9/24/20	110.50	LF	A52431 (UP) - WB I-44 - RP / PAS & PAS / BAS East of Bridge - Shoulders, Lanes 1, 2, 3	1636+14	LT	1636+72	LT	
				9/24/20	110.50	LF	A52431 (UP) - WB I-44 - RP / PAS & PAS / BAS West of Bridge - Shoulders, Lanes 1, 2, 3	1639+79	LT	1640+64	LT	
0130	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL	9/24/20	9/25/20	38.20	LF	A52581 (UP) - EB I-44 - RP / PAS & PAS / BAS East of Bridge - Inner Should & Lane 1	1640+06	RT	1640+64	RT	
				9/25/20	38.20	LF	A52581 (UP) - EB I-44 - RP / PAS & PAS / BAS West of Bridge - Inner Should & Lane 1	1636+14	RT	1636+99	RT	
			9/25/20	9/28/20	72.30	LF	A52581 (UP) - EB I-44 - RP / PAS & PAS / BAS East of Bridge - Outter Shoulder & Lanes 2 & 3	1640+06	RT	1640+64	RT	
				9/28/20	72.30	LF	A52581 (UP) - EB I-44 - RP / PAS & PAS / BAS West of Bridge - Outter Shoulder & Lanes 2 & 3	1636+14	RT	1636+99	RT	
0150	7172054	OPEN CELL FOAM JOINT SEAL	9/24/20	9/25/20	38.20	LF	A52581 (UP) - EB I-44 - RP / PAS & PAS / BAS East of Bridge - Inner Should & Lane 1	1640+06	RT	1640+64	RT	
				9/25/20	38.20	LF	A52581 (UP) - EB I-44 - RP / PAS & PAS / BAS West of Bridge - Inner Should & Lane 1	1636+14	RT	1636+99	RT	
			9/25/20	9/28/20	72.30	LF	A52581 (UP) - EB I-44 - RP / PAS & PAS / BAS East of Bridge - Outter Shoulder & Lanes 2 & 3	1640+06	RT	1640+64	RT	
				9/28/20	72.30	LF	A52581 (UP) - EB I-44 - RP / PAS & PAS / BAS West of Bridge - Outter Shoulder & Lanes 2 & 3	1636+14	RT	1636+99	RT	
0160	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL	9/16/20	9/18/20	44.00	LF	A57591 (Pacific) - WB I-44 - RP / PAS & PAS / BAS East of Bridge - Outter Shoulder & Lane 3	1787+46	LT	1787+76	LT	
				9/18/20	44.00	LF	A57591 (Pacific) - WB I-44 - RP / PAS & PAS / BAS West of Bridge - Outter Shoulder & Lane 3	1785+76	LT	1786+06	LT	
			9/18/20	9/19/20	61.00	LF	A57591 (Pacific) - WB I-44 - RP / PAS & PAS / BAS East of Bridge - Inner Shoulder & Lanes 1 & 2	1787+46	LT	1787+76	LT	
				9/19/20	61.00	LF	A57591 (Pacific) - WB I-44 - RP / PAS & PAS / BAS West of Bridge - Inner Shoulder & Lanes 1 & 2	1785+76	LT	1786+06	LT	
0180	7172054	OPEN CELL FOAM JOINT SEAL	9/16/20	9/18/20	44.00	LF	A57591 (Pacific) - WB I-44 - RP / PAS & PAS / BAS East of Bridge - Outter Shoulder & Lane 3	1787+46	LT	1787+76	LT	
				9/18/20	44.00	LF	A57591 (Pacific) - WB I-44 - RP / PAS & PAS / BAS West of Bridge - Outter Shoulder & Lane 3	1785+76	LT	1786+06	LT	
			9/18/20	9/19/20	61.00	LF	A57591 (Pacific) - WB I-44 - RP / PAS & PAS / BAS East of Bridge - Inner Shoulder & Lanes 1 & 2	1787+46	LT	1787+76	LT	
				9/19/20	61.00	LF	A57591 (Pacific) - WB I-44 - RP / PAS & PAS / BAS West of Bridge - Inner Shoulder & Lanes 1 & 2	1785+76	LT	1786+06	LT	
0260	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL	9/17/20	9/18/20	61.00	LF	A69071 (OO) - WB I-44 - RP / PAS & PAS / BAS East of Bridge - Inner Shoulder and Lanes 1 & 2	1835+92	LT	1836+22	LT	
				9/18/20	61.00	LF	A69071 (OO) - WB I-44 - RP / PAS & PAS / BAS West of Bridge - Inner Shoulder and Lanes 1 & 2	1833+63	LT	1833+93	LT	
0280	7172054	OPEN CELL FOAM JOINT SEAL	9/17/20	9/18/20	61.00	LF	A69071 (OO) - WB I-44 - RP / PAS & PAS / BAS East of Bridge - Inner Shoulder and Lanes 1 & 2	1835+92	LT	1836+22	LT	
				9/18/20	61.00	LF	A69071 (OO) - WB I-44 - RP / PAS & PAS / BAS West of Bridge - Inner Shoulder and Lanes 1 & 2	1833+63	LT	1833+93	LT	

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 7 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0120	OPEN CELL FOAM JOINT SEAL	Material		10	Oct 1, 2020	SYSTEM	(\$7,293.00)	
				10	Oct 1, 2020	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0120 -	· Total						\$0.00	
0150	OPEN CELL FOAM JOINT SEAL	Material		10	Oct 1, 2020	SYSTEM	(\$7,293.00)	
				10	Oct 1, 2020	SYSTEM	\$7,293.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0150 -	· Total						\$0.00	
0180	OPEN CELL FOAM JOINT SEAL	Material		10	Oct 1, 2020	SYSTEM	(\$7,140.00)	
				10	Oct 1, 2020	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0180 -	· Total						\$0.00	
0210	OPEN CELL FOAM JOINT SEAL	Material		9	Sep 17, 2020	SYSTEM	(\$7,140.00)	
				9	Sep 17, 2020	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Oct 1, 2020	SYSTEM	(\$7,140.00)	
				10	Oct 1, 2020	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0210 -	Total						\$0.00	
0250	OPEN CELL FOAM JOINT SEAL	Material		9	Sep 17, 2020	SYSTEM	(\$7,140.00)	
				9	Sep 17, 2020	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Oct 1, 2020	SYSTEM	(\$7,140.00)	
				10	Oct 1, 2020	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0250 -	· Total						\$0.00	
0280	OPEN CELL FOAM JOINT SEAL	Material		9	Sep 17, 2020	SYSTEM	(\$4,200.00)	
				9	Sep 17, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Oct 1, 2020	SYSTEM	(\$8,470.00)	
				10	Oct 1, 2020	SYSTEM	\$8,470.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0280 -	Total						\$0.00	

Revision 4/1/2020 Page 8 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0440	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	Material		1	May 18, 2020	SYSTEM	(\$17,519.30)	
	FOLTORETHANE			1	May 18, 2020	SYSTEM	\$17,519.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0440 -	· Total						\$0.00	
0460	MGS GUARDRAIL	Material		1	May 18, 2020	SYSTEM	(\$41,625.00)	
				1	May 18, 2020	SYSTEM	\$41,625.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				2	Jun 3, 2020	SYSTEM	(\$89,718.75)	
				2	Jun 3, 2020	SYSTEM	\$89,718.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0460 -	· Total						\$0.00	
0470	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		2	Jun 3, 2020	SYSTEM	(\$14,375.00)	
	SPACING			2	Jun 3, 2020	SYSTEM	\$14,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0470 -	· Total						\$0.00	
0480	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Material		1	May 18, 2020	SYSTEM	(\$15,500.00)	
	(1.202.4110.001.12)			1	May 18, 2020	SYSTEM	\$15,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				2	Jun 3, 2020	SYSTEM	(\$27,900.00)	
				2	Jun 3, 2020	SYSTEM	\$27,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0480 -	·Total						\$0.00	
0490	MGS END ANCHOR	Material		2	Jun 3, 2020	SYSTEM	(\$2,140.00)	
				2	Jun 3, 2020	SYSTEM	\$2,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0490 -	· Total						\$0.00	
0500	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		1	May 18, 2020	SYSTEM	(\$5,800.00)	
				1	2020	SYSTEM	\$5,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				2	Jun 3, 2020		(\$14,500.00)	
				2	Jun 3, 2020	SYSTEM	\$14,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0500 -	Total						\$0.00	

Revision 4/1/2020 Page 9 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5001	HALF-SOLE REPAIR	Material		5	Jul 17, 2020	SYSTEM	(\$2,680.00)	
				5	Jul 17, 2020	SYSTEM	\$2,680.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5001 -	Total						\$0.00	
5002	HALF-SOLE REPAIR	Material		5	Jul 17, 2020	SYSTEM	(\$268.00)	
				5	Jul 17, 2020	SYSTEM	\$268.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5002 -	Total						\$0.00	
5003	HALF-SOLE REPAIR	Material		5	Jul 17, 2020	SYSTEM	(\$3,886.00)	
				5	Jul 17, 2020	SYSTEM	\$3,886.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5003 -	Total						\$0.00	
5004	HALF-SOLE REPAIR	Material		5	Jul 17, 2020	SYSTEM	(\$1,072.00)	
				5	Jul 17, 2020	SYSTEM	\$1,072.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5004 -	Total						\$0.00	
5005	HALF-SOLE REPAIR	Material		5	Jul 17, 2020	SYSTEM	(\$670.00)	
				5	Jul 17, 2020	SYSTEM	\$670.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5005 - Total							\$0.00	
Overall - Total							\$0.00	

Revision 4/1/2020 Page 10 of 10