

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 2, 2020

Progress Estim	ate Number	Contract ID Prime Contractor	200320-F03 R. V. Wagner, Inc.	•	October 16, 2020 November 1, 2020	Original Contract Amount Net Change Order Amount Current Contract Amount	\$2,075,731.00 (\$318,347.09) \$1,757,383.91
Approval Date							By User
November 2, 2020		(Generated and Appro	oved (and should be	e considered Draft)	at the Project Office Level by	steppr1
November 3, 2020		Revie	ewed and Approved	(and should be con	sidered Draft) at the	Resident Engineer Level by	morgac1
November 4, 2020			Revie	ewed and Approved	at the Central Offic	e Controllers Office Level by	greggd1
Original Comp	letion Date	Current Comp	oletion Date	Actual Completion	% of Current Contract Amour	nt Complete	
December 1, 2020 December 1, 2020 98.76%							

No Milestones Exist for Contract

Contract Total Pa	ay For Estimate No. 12			
		This Estimate	Previous	To Date
200320-F03				
	Total Posted Items Pay	\$29,561.00	\$1,706,066.66	\$1,735,627.66
	Gross Item Adjustments	\$0.00	(\$8.68)	(\$8.68)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$1,706,057.98	\$1,735,618.98
Contract Total Pa	ayable This Estimate:	\$29,561.00		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3243	0090	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$800.000	1	\$800.00
Project J6I32	43 - Total						\$800.00
J6l3252	0340	6099903	MISC.4 IN. TYPE 'A' INTEGRAL CURB (MODIFIED ON CONCRETE)	LF	\$57.000	73	\$4,161.00
	0450	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$7,000.000	1	\$7,000.00
	0510	6063017	TYPE C CRASHWORTHY END TERMINAL	EA	\$17,600.000	1	\$17,600.00
Project J6I32	52 - Total						\$28,761.00
Overall - Tota	al						\$29,561.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3243	0120	OPEN CELL FOAM JOINT SEAL	Material			-221	\$33.00	(\$7,293.00)
	0120	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	221	\$33.00	\$7,293.00
	0150	OPEN CELL FOAM JOINT SEAL	Material			-221	\$33.00	(\$7,293.00)
	0150	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	221	\$33.00	\$7,293.00
	0180	OPEN CELL FOAM JOINT SEAL	Material			-210	\$34.00	(\$7,140.00)
	0180	OPEN CELL FOAM JOINT	Material		This adjustment offsets the original system-	210	\$34.00	\$7,140.00

Revision 4/1/2020 Page 1 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 2, 2020

Progress Estimate Number
12 Contract ID 200320-F03 Pay Period Start October 16, 2020 Original Contract Amount \$2,075,731.00
Prime Contractor R. V. Wagner, Inc. Pay Period End November 1, 2020 Original Contract Amount \$3,075,731.00
November 1, 2020 Original Contract Amount Current Contract Amount \$1,757,383.91

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3243		SEAL			generated Overrun Payment Estimate Item Adjustment (0007) due to user steppr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
	0210	OPEN CELL FOAM JOINT SEAL	Material			-210	\$34.00	(\$7,140.00)
	0210	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	210	\$34.00	\$7,140.00
	0250	OPEN CELL FOAM JOINT SEAL	Material			-210	\$34.00	(\$7,140.00)
	0250	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	210	\$34.00	\$7,140.00
	0280	OPEN CELL FOAM JOINT SEAL	Material			-242	\$35.00	(\$8,470.00)
	0280	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user steppr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	242	\$35.00	\$8,470.00
J6I3252	0320	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '-0.07356' is applied (if non-zero).	-16	\$15.93	(\$254.82)
	0320	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-118	\$16.00	(\$1,888.00)
	0320	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 14 on the current Payment Estimate.	16	\$15.93	\$254.82
	0320	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	118	\$16.00	\$1,888.00
	0330	MISC.	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-15.6	\$57.00	(\$889.20)
	0330	MISC.	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	15.6	\$57.00	\$889.20
	0340	MISC.	Overrun			-7	\$57.00	(\$399.00)
	0340	MISC.	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	7	\$57.00	\$399.00
	0575	OPEN CELL FOAM JOINT SEAL	Material			-300	\$32.00	(\$9,600.00)
	0575	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item	300	\$32.00	\$9,600.00

Revision 4/1/2020 Page 2 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 2, 2020

Progress Estimate Number
12
Contract ID 200320-F03 Pay Period Start October 16, 2020 Original Contract Amount \$2,075,731.00
Prime Contractor R. V. Wagner, Inc. Pay Period End November 1, 2020 Original Contract Amount (\$318,347.09)
Current Contract Amount \$1,757,383.91

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3252					Adjustment (0011) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
	5103	OPEN CELL FOAM JOINT SEAL	Material			-121	\$49.00	(\$5,929.00
	5103	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user steppr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	121	\$49.00	\$5,929.00
	5104	OPEN CELL FOAM JOINT SEAL	Material			-265	\$46.00	(\$12,190.00
	5104	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	265	\$46.00	\$12,190.00
	5105	OPEN CELL FOAM JOINT SEAL	Material			-89	\$57.00	(\$5,073.00
	5105	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user steppr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	89	\$57.00	\$5,073.00
	5106	OPEN CELL FOAM JOINT SEAL	Material			-121	\$48.00	(\$5,808.00
	5106	OPEN CELL FOAM JOINT SEAL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	121	\$48.00	\$5,808.00
Fotal								\$0.00

Revision 4/1/2020 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information							
Project Number													
J6I3243	I 44-3(118)	7 Bridge rehabilitations	I-44	FRANKLIN	east of MO 100 to High	of MO 100 to Highway OO in Pacific							
J6I3252	I 44-4(201)	6 Bridge rehabilitations	I-44	ST LOUIS	from US Route 66 to Bl	om US Route 66 to BNSF R.R. on I-44 in Eureka							
Γotals by .	tals by Job Numbers												
J6l3243		d Item Pay Item Adjustme		Item Pay	This Estimate \$800.00 \$0.00 \$800.00	Previous \$657,521.10 \$0.00 \$657,521.10	To Date \$658,321.10 \$0.00 \$658,321.10						
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						
J6I3252		d Item Pay Item Adjustme		Item Pay	This Estimate \$28,761.00 \$0.00 \$28,761.00	Previous \$1,048,545.56 (\$8.68) \$1,048,536.88	To Date \$1,077,306.56 (\$8.68) \$1,077,297.88						
	Liquid	ive entive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						

Revision 4/1/2020 Page 4 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3252, Item 3040506, Project Item Line Number 0320, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with QC to clear exceptions.	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3243, Item 7172054, Project Item Line Number 0210, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Exceptions will be cleared once PALs are entered	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3243, Item 7172054, Project Item Line Number 0150, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Exceptions will be cleared once PALs are entered	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3252, Item 7172054, Project Item Line Number 5104, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Exceptions will be cleared once PALs are entered	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3252, Item 7172054, Project Item Line Number 0575, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Exceptions will be cleared once PALs are entered	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3252, Item 7172054, Project Item Line Number 5106, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Exceptions will be cleared once PALs are entered	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3252, Item 7172054, Project Item Line Number 5105, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Exceptions will be cleared once PALs are entered	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3252, Item 7172054, Project Item Line Number 5103, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Exceptions will be cleared once PALs are entered	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3243, Item 7172054, Project Item Line Number 0250, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Exceptions will be cleared once PALs are entered	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3243, Item 7172054, Project Item Line Number 0280, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Exceptions will be cleared once PALs are entered	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3243, Item 7172054, Project Item Line Number 0180, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Exceptions will be cleared once PALs are entered	steppr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3243, Item 7172054, Project Item Line Number 0120, Material Set 717205496, Material 1073JMOCFJ - Open Cell Foam Exp. Joint @, Acceptance Action Generic 1073JMOCFJ is insufficient.	Exceptions will be cleared once PALs are entered	steppr1	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F03, Contract Project J6l3252, Project Item Line Number 0340, Contract Line Item Number 0340, Item 6099903, Minor Item.	Will be on future change order	steppr1	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F03, Contract Project J6l3252, Project Item Line Number 0320, Contract Line Item Number 0320, Item 3040506, Minor Item.	Will be on future change order	steppr1	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F03, Contract Project J6l3252, Project Item Line Number 0330, Contract Line Item Number 0330, Item 5029905, Minor Item.	Will be on future change order	steppr1	Overridden

Revision 4/1/2020 Page 5 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT Project No. Category No. Line No. Item Code Description Bid Quantity Net Change Order Total Quantity Unit 200320-F03 J6i3243 0001 0010 6169901 MISC.TEMPORARY TRAFFIC CONTROL 1.00 0.00 1.00 LS 0001 0020 6169902 MISC.CHANGEABLE MESSAGE SIGN NTCIP COMPLIANT, CONTRACTOR FURNISHED/RETAINED 2.00 0.00 2.00 EA 0001 0030 6181000 MOBILIZATION 1.00 0.00 1.00 LS	Total Posted Approved Qty 0.95	Unit Price \$50,000.00	Total Value POSTED To Date (See report generated date)				
0001 0020 6169902 MISC.CHANGEABLE MESSAGE SIGN NTCIP COMPLIANT, 2.00 0.00 EA CONTRACTOR FURNISHED/RETAINED	0.95	\$50,000.00					
CONTRACTOR FURNISHED/RETAINED	2.00		\$47,500.00				
0001 0030 6181000 MOBILIZATION 1.00 0.00 1.00 LS		\$3,800.00	\$7,600.00				
	1.00	\$79,000.00	\$79,000.00				
0001 0040 6205901A 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT 1,386.00 0.00 1,386.00 LF	0.00	\$0.30	\$0.00				
0001 0050 6205902A 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING 5,430.00 0.00 5,430.00 LF PAINT, TYPE L BEADS	0.00	\$0.55	\$0.00				
0001 0060 6205903A 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT 3,618.00 0.00 3,618.00 LF	0.00	\$0.40	\$0.00				
0001 0070 6209903 MISC.4 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT 1,386.00 0.00 1,386.00 LF MARKING PAINT, TYPE L BEADS	0.00	\$0.30	\$0.00				
0001 0080 6252003 SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE 43,544.00 -23,514.00 20,030.00 LB	20,030.00	\$4.10	\$82,123.00				
0001 0090 6274000 CONTRACTOR FURNISHED SURVEYING AND STAKING 1.00 0.00 1.00 LS	1.00	\$800.00	\$800.00				
0070 0100 2165000 REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT 221.00 0.00 221.00 LF	221.00	\$13.00	\$2,873.00				
0070 0110 6233000 EPOXY POLYMER WEARING SURFACE 2,012.00 0.00 2,012.00 SQYD	2,012.00	\$32.45	\$65,289.40				
0070 0120 7172054 OPEN CELL FOAM JOINT SEAL 221.00 0.00 221.00 LF	221.00	\$33.00	\$7,293.00				
0071 0130 2165000 REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT 221.00 0.00 221.00 LF	221.00	\$13.00	\$2,873.00				
0071 0140 6233000 EPOXY POLYMER WEARING SURFACE 2,156.00 0.00 2,156.00 SQYD	2,156.00	\$31.45	\$67,806.20				
0071 0150 7172054 OPEN CELL FOAM JOINT SEAL 221.00 0.00 221.00 LF	221.00	\$33.00	\$7,293.00				
0072 0160 2165000 REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT 210.00 0.00 210.00 LF	210.00	\$14.00	\$2,940.00				
0072 0170 6233000 EPOXY POLYMER WEARING SURFACE 905.00 0.00 905.00 SQYD	905.00	\$41.75	\$37,783.75				
0072 0180 7172054 OPEN CELL FOAM JOINT SEAL 210.00 0.00 210.00 LF	210.00	\$34.00	\$7,140.00				
0073 0190 2165000 REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT 210.00 0.00 210.00 LF	210.00	\$14.00	\$2,940.00				
0073 0200 6233000 EPOXY POLYMER WEARING SURFACE 903.00 0.00 903.00 SQYD	903.00	\$41.85	\$37,790.55				
0073 0210 7172054 OPEN CELL FOAM JOINT SEAL 210.00 0.00 210.00 LF	210.00	\$34.00	\$7,140.00				
0074 0220 6233000 EPOXY POLYMER WEARING SURFACE 1,514.00 0.00 1,514.00 SQYD	1,514.00	\$36.70	\$55,563.80				
0075 0230 2165000 REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT 210.00 0.00 210.00 LF	210.00	\$14.00	\$2,940.00				
0075 0240 6233000 EPOXY POLYMER WEARING SURFACE 1,272.00 0.00 1,272.00 SQYD	1,272.00	\$40.15	\$51,070.80				
0075 0250 7172054 OPEN CELL FOAM JOINT SEAL 210.00 0.00 210.00 LF	210.00	\$34.00	\$7,140.00				
0076 0260 2165000 REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT 242.00 0.00 242.00 LF	242.00	\$15.00	\$3,630.00				
0076 0270 6233000 EPOXY POLYMER WEARING SURFACE 1,456.00 0.00 1,456.00 SQYD	1,456.00	\$37.60	\$54,745.60				
0076 0280 7172054 OPEN CELL FOAM JOINT SEAL 242.00 0.00 242.00 LF	242.00	\$35.00	\$8,470.00				
0070 5001 7040104 HALF-SOLE REPAIR 0.00 20.00 20.00 SQFT	20.00	\$134.00	\$2,680.00				
0071 5002 7040104 HALF-SOLE REPAIR 0.00 2.00 2.00 SQFT	2.00	\$134.00	\$268.00				
0072 5003 7040104 HALF-SOLE REPAIR 0.00 29.00 29.00 SQFT	29.00	\$134.00	\$3,886.00				
0073 5004 7040104 HALF-SOLE REPAIR 0.00 8.00 8.00 SQFT	8.00	\$134.00	\$1,072.00				
0075 5005 7040104 HALF-SOLE REPAIR 0.00 5.00 SQFT	5.00	\$134.00	\$670.00				
Project J6l3243 - Total Value Posted to Date as of Report Generated Date J6l3252 0001 0290 2022010 REMOVAL OF IMPROVEMENTS 1.00 0.00 1.00 LS	1.00	\$27,000.00	\$658,321.10 \$27,000.00				
0001 0300 2037075 COMPACTING IN CUT 0.50 0.00 0.50 STA	0.50	\$1,000.00	\$500.00				
0001 0310 2071000 LINEAR GRADING CLASS 1 0.50 0.00 0.50 STA	0.50	\$6,850.00	\$3,425.00				
	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) 102.00 0.00 102.00 SQYD 118.00						
	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) 102.00 0.00 102.00 SQYD 118.00 \$16. MISC.TYPE A2 SHOULDER 102.20 0.00 102.20 SQYD 117.80 \$57.						
0001 0340 6099903 MISC.4 IN. TYPE 'A' INTEGRAL CURB (MODIFIED ON 66.00 0.00 66.00 LF	73.00	\$57.00	\$6,714.60 \$4,161.00				
CONCRETE)	120.00	\$31.00	\$3,720.00				
	120.00		\$3,720.00				
	0.95		\$46,550.00				
	2.00	\$49,000.00	\$46,550.00				
CONTRACTOR FURNISHED/RETAINED							
0001 0390 6181000 MOBILIZATION 1.00 0.00 1.00 LS	1.00	\$108,000.00	\$108,000.00				

Revision 4/1/2020 Page 6 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bid Net Total Unit To

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)		
200320-F03	J6I3252	0001	0400	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,238.00	0.00	1,238.00	LF	0.00	\$0.30	\$0.00		
		0001	0410	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	10,113.00	0.00	10,113.00	LF	0.00	\$0.55	\$0.00		
		0001	0420	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,033.00	0.00	7,033.00	LF	0.00	\$0.40	\$0.00		
		0001	0430	6209903	MISC.4 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,238.00	0.00	1,238.00	LF	0.00	\$0.30	\$0.00		
		0001	0440	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	42,988.00	-32,511.00	10,477.00	LB	10,477.00	\$4.10	\$42,955.70		
		0001	0450	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$7,000.00	\$7,000.00		
		0010	0460	6061060	MGS GUARDRAIL	4,175.00	0.00	4,175.00	LF	4,175.00	\$22.50	\$93,937.50		
		0010	0470	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	575.00	0.00	575.00	LF	575.00	\$25.00	\$14,375.00		
		0010	0480	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	11.00	0.00	11.00	EA	11.00	\$3,100.00	\$34,100.00		
		0010	0490	6061080	MGS END ANCHOR	3.00	0.00	3.00	EA	3.00	\$1,070.00	\$3,210.00		
		0010	0500	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	6.00	0.00	6.00	EA	6.00	\$2,900.00	\$17,400.00		
		0010	0510	6063017	TYPE C CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	1.00	\$17,600.00	\$17,600.00		
		0070	0520	6233000	EPOXY POLYMER WEARING SURFACE	2,093.00	0.00	2,093.00	SQYD	2,093.00	\$34.35	\$71,894.55		
		0070	0530	7040104	HALF-SOLE REPAIR	200.00	-188.00	12.00	SQFT	12.00	\$134.00	\$1,608.00		
		0070	0540	7173002	SILICONE EXPANSION JOINT SEALANT	29.00	0.00	29.00	LF	0.00	\$43.00	\$0.00		
		0070	0550	7174002	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	121.00	-121.00	0.00	LF	0.00	\$49.00	\$0.00		
		0071	0560	6233000	EPOXY POLYMER WEARING SURFACE	2,950.00	0.00	2,950.00	SQYD	2,950.00	\$30.15	\$88,942.50		
		0071	0570	7040104	HALF-SOLE REPAIR	100.00	-87.00	13.00	SQFT	13.00	\$134.00	\$1,742.00		
		0071	0575	7172054	OPEN CELL FOAM JOINT SEAL	477.00	-177.00	300.00	LF	300.00	\$32.00	\$9,600.00		
		0072	0590	6233000	EPOXY POLYMER WEARING SURFACE	5,074.00	0.00	5,074.00	SQYD	5,074.00	\$31.50	\$159,831.00		
		0072	0600	7040104	HALF-SOLE REPAIR	100.00	-80.00	20.00	SQFT	20.00	\$134.00	\$2,680.00		
		0072	0610	7173002	SILICONE EXPANSION JOINT SEALANT	68.00	0.00	68.00	LF	0.00	\$40.00	\$0.00		
		0072	0620	7174002	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	265.00	-265.00	0.00	LF	0.00	\$46.00	\$0.00		
		0073	0630	6233000	EPOXY POLYMER WEARING SURFACE	3,976.00	0.00	3,976.00	SQYD	3,976.00	\$33.15	\$131,804.40		
		0073	0640	7040104	HALF-SOLE REPAIR	200.00	-195.00	5.00	SQFT	5.00	\$134.00	\$670.00		
		0074	0650	6233000	EPOXY POLYMER WEARING SURFACE	1,224.00	0.00	1,224.00	SQYD	1,224.00	\$39.60	\$48,470.40		
		0074	0660	7040104	HALF-SOLE REPAIR	50.00	-47.00	3.00	SQFT	3.00	\$134.00	\$402.00		
		0074	0670	7174002	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	89.00	-89.00	0.00	LF	0.00	\$57.00	\$0.00		
		0075	0680	6233000	EPOXY POLYMER WEARING SURFACE	2,090.00	0.00	2,090.00	SQYD	2,090.00	\$33.15	\$69,283.50		
		0075	0690	7040104	HALF-SOLE REPAIR	200.00	-191.00	9.00	SQFT	9.00	\$134.00	\$1,206.00		
		0075	0700	7174002	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	121.00	-121.00	0.00	LF	0.00	\$48.00	\$0.00		
		0001	5101	2159903		0.00 400.00 LF 400.00 \$9.45								
		0074	5102	2161502	REMOVAL OF CONCRETE WEARING SURFACE	\$10,255.41								
		0070	5103	7172054	OPEN CELL FOAM JOINT SEAL	\$49.00	\$5,929.00							
		0072	5104	7172054	OPEN CELL FOAM JOINT SEAL	0.00	265.00	265.00	LF	265.00	\$46.00	\$12,190.00		
		0074	5105	7172054	OPEN CELL FOAM JOINT SEAL	0.00	89.00	89.00	LF	89.00	\$57.00	\$5,073.00		
		0075	5106	7172054	OPEN CELL FOAM JOINT SEAL	0.00	121.00	121.00	LF	121.00	\$48.00	\$5,808.00		
	Project .	J6I3252 - To	otal Value	Posted to D	Date as of Report Generated Date							\$1,077,306.56		
200320-F03 Ove	rall - Tota	I Value Pos	sted to Da	ite as of Rep	ort Generated Date							\$1,735,627.66		

Revision 4/1/2020 Page 7 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J6I3243

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0090	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	10/20/20	10/21/20	1.00	LS		209+90		1837+72		

Project: J6l3252

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0340	6099903	MISC. PAVED DRAINAGE	10/16/20	10/20/20	8.00	LF	A40122 (UP) - East of Bridge	386+55	RT	386+62	RT	
				10/20/20	8.00	LF	A40122 (UP) - East of Bridge	387+31	LT	387+38	LT	
				10/20/20	8.00	LF	A40122 (UP) - West of Bridge	382+82	RT	382+89	RT	
				10/20/20	16.00	LF	A40102 (UP) - East of Bridge	373+29	RT	373+44	RT	
				10/20/20	16.00	LF	A40102 (UP) - East of Bridge	373+75	LT	373+90	LT	
				10/20/20	17.00	LF	A40102 (UP) - West of Bridge	371+33	RT	371+48	RT	
0450	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	10/20/20	10/21/20	1.00	LS		173+71		394+86		
0510	6063017	TYPE C CRASHWORTHY END TERMINAL	10/20/20	10/21/20	1.00	EA	I-44 Median	394+35	CL	394+86	CL	

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 8 of 14



Description									
10	Line	Description		Adjustment				Amount	Remarks
	0120		Material		10		SYSTEM	(\$7,293.00)	
1					10		SYSTEM	\$7,293.00	Item Adjustment (0001) due to user steppr1 overridding Payment Estimate
12 Nov. 2 SYSTEM G7.293.00 This adjustment (2003) also for user risport overridding Payment Estimate Exception 12 on the current Payment Estimate Estimate Exception 12 on the Current					11		SYSTEM	(\$7,293.00)	
12 Nov.2 2000 12 Nov.2 2000 13 2000 13 2000 13 2000 13 2000 13 2000 14 2000 15 2000 20					11		SYSTEM	\$7,293.00	Item Adjustment (0008) due to user steppr1 overridding Payment Estimate
					12		SYSTEM	(\$7,293.00)	
					12		SYSTEM	\$7,293.00	Item Adjustment (0005) due to user steppr1 overridding Payment Estimate
10				- Total				\$0.00	
10		Material - Total						\$0.00	
10	0120 -	· Total						\$0.00	
10		OPEN CELL FOAM JOINT	Material		10		SYSTEM		
1		32712			10	Oct 1,	SYSTEM	\$7,293.00	Item Adjustment (0002) due to user steppr1 overridding Payment Estimate
2020					11		SYSTEM	(\$7,293.00)	
12 Nov 2 SYSTEM \$7,293.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 3 on the current Payment Estimate Exception 6 on the current Payment Estimate Exception 11 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the curren					11		SYSTEM	\$7,293.00	Item Adjustment (0004) due to user steppr1 overridding Payment Estimate
Page					12		SYSTEM	(\$7,293.00)	
Material - Total					12		SYSTEM	\$7,293.00	Item Adjustment (0006) due to user steppr1 overridding Payment Estimate
10				- Total				\$0.00	
OPEN CELL FOAM JOINT SEAL Material 10		Material - Total						\$0.00	
2020	0150 -	· Total						\$0.00	
Lem Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	0180		Material			2020			
2020					10		SYSTEM	\$7,140.00	Item Adjustment (0003) due to user steppr1 overridding Payment Estimate
Litern Adjustment (0005) due to user stepport overridding Payment Éstimate Exception 11 on the current Payment Estimate.					11		SYSTEM	(\$7,140.00)	
2020 12 Nov 2, 2020 SYSTEM \$7,140.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user steppr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. S0.00					11		SYSTEM	\$7,140.00	Item Adjustment (0005) due to user steppr1 overridding Payment Estimate
Continue					12		SYSTEM	(\$7,140.00)	
Material - Total \$0.00					12		SYSTEM	\$7,140.00	Item Adjustment (0007) due to user steppr1 overridding Payment Estimate
OPEN CELL FOAM JOINT SEAL Sep 17, 2020 SySTEM (\$7,140.00)				- Total				\$0.00	
OPEN CELL FOAM JOINT SEAL 9 Sep 17, 2020 SYSTEM (\$7,140.00) 9 Sep 17, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 10 Oct 1, 2020 SYSTEM (\$7,140.00) 10 Oct 1, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate. 10 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		Material - Total						\$0.00	
OPEN CELL FOAM JOINT SEAL 9 Sep 17, 2020 SYSTEM (\$7,140.00) 9 Sep 17, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 10 Oct 1, 2020 SYSTEM (\$7,140.00) 10 Oct 1, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate. 10 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	0180 -	Total						\$0.00	
9 Sep 17, 2020 SYSTEM \$7,140.00 This adjustment offsets the original system-generated Overrun Payment Estimate ltem Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 10 Oct 1, 2020 SYSTEM (\$7,140.00) 10 Oct 1, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate ltem Adjustment (0004) due to user steppr1 overridding Payment Estimate ltem Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		OPEN CELL FOAM JOINT	Material		9		SYSTEM		
2020 10 Oct 1, 2020 \$YSTEM \$7,140.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 11 Oct 16, SYSTEM (\$7,140.00)					9	Sep 17,	SYSTEM	\$7,140.00	Item Adjustment (0001) due to user steppr1 overridding Payment Estimate
ltem Adjustment (0004) due to user steppr1 overridding Payment Éstimate Exception 5 on the current Payment Estimate. 11 Oct 16, SYSTEM (\$7,140.00)					10		SYSTEM	(\$7,140.00)	
					10		SYSTEM	\$7,140.00	Item Adjustment (0004) due to user steppr1 overridding Payment Estimate
					11		SYSTEM	(\$7,140.00)	

Revision 4/1/2020 Page 9 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0210	OPEN CELL FOAM JOINT SEAL	Material		11	Oct 16, 2020	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				12	Nov 2, 2020	SYSTEM	(\$7,140.00)	
				12	Nov 2, 2020	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0210 -							\$0.00	
0250	OPEN CELL FOAM JOINT SEAL	Material		9	Sep 17, 2020	SYSTEM	(\$7,140.00)	
				9	Sep 17, 2020	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Oct 1, 2020	SYSTEM	(\$7,140.00)	
				10	Oct 1, 2020	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Oct 16, 2020	SYSTEM	(\$7,140.00)	
				11	Oct 16, 2020	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user steppr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				12	Nov 2, 2020	SYSTEM	(\$7,140.00)	
					Nov 2, 2020	SYSTEM	\$7,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0250 -							\$0.00	
0280	OPEN CELL FOAM JOINT SEAL	Material		9	Sep 17, 2020	SYSTEM	(\$4,200.00)	
				9	Sep 17, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Oct 1, 2020	SYSTEM	(\$8,470.00)	
				10	Oct 1, 2020	SYSTEM	\$8,470.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				11	Oct 16, 2020	SYSTEM	(\$8,470.00)	
				11	Oct 16, 2020	SYSTEM	\$8,470.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				12	Nov 2, 2020	SYSTEM	(\$8,470.00)	
				12	Nov 2, 2020	SYSTEM	\$8,470.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user steppr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Type & Acceptonic for	Material		44	04440	CVCTC**	\$0.00	
0320	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		11	Oct 16, 2020	SYSTEM	(\$1,888.00)	
				11	Oct 16, 2020	SYSTEM	\$1,888.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Nov 2, 2020	SYSTEM	(\$1,888.00)	
				12	Nov 2, 2020	SYSTEM	\$1,888.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate

Revision 4/1/2020 Page 10 of 14



1700 1700	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Mariel Total Tot			Туре	Adjustment Type	Number	Date	Ву		
Material - Inchi Type 5 ACQCCCQTT FOR Overlan 1	0320		Material						Exception 1 on the current Payment Estimate.
TYPE & AGGREGATE FOR Commun 11				- Total				\$0.00	
SASE (8 N. THICK)		Material - Total						\$0.00	
12 Nov 2, SYSTEM (\$254.42) Average Pirice Aglustment (Bott) eventuring Payment Estimate Exception 1 on the current Payment Estimate (International Control Payment Estimate)			Overrun	Overrun	11		SYSTEM	(\$254.82)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
2003 12 Nov.2 SYSTEM 32/4.82 The adjustment offsets the original system-generated Overrun Payment Estimate four full flags (2002) overrun Flags (2002) Nov. 2 SYSTEM 1					11		SYSTEM	\$254.82	Item Adjustment (0002) overridding Payment Estimate Exception 13 on the
Description					12		SYSTEM	(\$254.82)	
Overrun - Total					12		SYSTEM	\$254.82	Item Adjustment (0002) overridding Payment Estimate Exception 14 on the
YPE 5 ACCRECATE FOR Pice Adjustment Type applied in FUEL Control C				Overrun - T	otal			\$0.00	
ASSE (BIN THICK)		Overrun - Total						\$0.00	
Price - Total (8.6.60)			Price		11		SYSTEM	(\$8.68)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				(\$8.68)	
Nisc. TYPE A2 SHOULDER		Price - Total						(\$8.68)	
1	0320 -	· Total						(\$8.68)	
2020 Item Adjustment (001) due to user steppri* overridding Payment Estimate Exception 14 on the Jurse Payment Estimate Exception 14 on the Jurse Payment Estimate Exception 15 on the current Payment Estimate (1000) designed (1000) des	0330	MISC. TYPE A2 SHOULDER	Overrun	Overrun	11		SYSTEM	(\$889.20)	
2020 12 Nov 2 SYSTEM \$889.20 This adjustment offset the original system-generated Overrun Estimate Exception 15 on the current Payment Estimate Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 15 on the current Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Item Adjustment (0001) due to user steppr1					11		SYSTEM	\$889.20	Item Adjustment (0011) due to user steppr1 overridding Payment Estimate
Coverrun - Total So.00 So.00 So.00					12		SYSTEM	(\$889.20)	
Noverun - Total S0.00 S0.00					12		SYSTEM	\$889.20	Item Adjustment (0004) due to user steppr1 overridding Payment Estimate
1								\$0.00	
MISC. 4 IN. TYPE 'A' INTEGRAL CURB (MODIFIED)		Overrun - Total						\$0.00	
INTEGRAL CURB (MODIFIED ON CONCRETE) 2020 12 Nov 2, 2 SYSTEM \$399.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 13 on the current Payment Estimate Exception 14 on the current Payment Estimate Item Adjustment (0011) due to user steppr1 overridding Payment Estimate Exception 14 on the current Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 14 on the current Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Item Adjustment (0001) due to user steppr1 ov	0330 -	· Total						\$0.00	
12 Nov 2, 2020 SYSTEM \$399.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. S0.00	0340	INTEGRAL CURB (MODIFIED	Overrun	Overrun		2020		(\$399.00)	
Overrun - Total Sum		,			12		SYSTEM	\$399.00	Item Adjustment (0001) due to user steppr1 overridding Payment Estimate
SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE Material HIGH DENSITY POLYURETHANE Material - Total Su.00				Overrun - T	otal			\$0.00	
SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE 1		Overrun - Total						\$0.00	
HIGH DENSITY POLYURETHANE 1	0340 -	· Total						\$0.00	
1 May 18, 2020 SYSTEM \$17,519.30 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 4 on the current Payment Estimate Exception 4 on the current Payment Estimate	0440	HIGH DENSITY	Material		1		SYSTEM	(\$17,519.30)	
Material - Total \$0.00 0440 - Total Material Materia		. 02.0			1		SYSTEM	\$17,519.30	Item Adjustment (0001) due to user steppr1 overridding Payment Estimate
MGS GUARDRAIL Material May 18, 2020 SYSTEM (\$41,625.00)		- Total						\$0.00	
MGS GUARDRAIL Material Material May 18, 2020 May 18, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. Jun 3, 2020 Jun 3, 2020 Jun 3, 2020 SYSTEM (\$89,718.75) Jun 3, 2020 SYSTEM (\$89,718.75) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. - Total So.00		Material - Total						\$0.00	
1 May 18, 2020 \$\frac{1}{2}\$ \$	0440 -	· Total						\$0.00	
ltem Adjustment (0002) due to user steppr1 overridding Payment Éstimate 2	0460	MGS GUARDRAIL	Material		1		SYSTEM	(\$41,625.00)	
2 Jun 3, 2020 2 Jun 3, 2020 3 SYSTEM \$89,718.75 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. - Total \$0.00									Item Adjustment (0002) due to user steppr1 overridding Payment Estimate
2020 Item Adjustment (0001) due to user steppr1 overridding Payment Éstimate Exception 1 on the current Payment Estimate.					2		SYSTEM	(\$89,718.75)	
					2		SYSTEM		Item Adjustment (0001) due to user steppr1 overridding Payment Estimate
Material - Total \$0.00				- Total				\$0.00	
		Material - Total						\$0.00	

Revision 4/1/2020 Page 11 of 14



Line	Description	Adjustment		Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0460 -	· Total						\$0.00	
0470	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		2	Jun 3, 2020	SYSTEM	(\$14,375.00)	
	SI ASINO			2	Jun 3, 2020	SYSTEM	\$14,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0470 -	- Total						\$0.00	
0480	MGS BRIDGE APPROACH TRANSITION SECTION	Material		1	May 18, 2020	SYSTEM	(\$15,500.00)	
	(REGULAR/NO CURB)			1	May 18, 2020	SYSTEM	\$15,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				2	Jun 3, 2020	SYSTEM	(\$27,900.00)	
				2	Jun 3, 2020	SYSTEM	\$27,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0480 -	Total						\$0.00	
0490	MGS END ANCHOR	Material		2	Jun 3, 2020	SYSTEM	(\$2,140.00)	
				2	Jun 3, 2020	SYSTEM	\$2,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0490 -	· Total						\$0.00	
0500	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		1	May 18, 2020	SYSTEM	(\$5,800.00)	
			1	1	May 18, 2020	SYSTEM	\$5,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					Jun 3, 2020	SYSTEM	(\$14,500.00)	
				2	Jun 3, 2020	SYSTEM	\$14,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0500 -	· Total						\$0.00	
0575	OPEN CELL FOAM JOINT SEAL	Material		11	Oct 16, 2020	SYSTEM	(\$9,600.00)	
				11	Oct 16, 2020	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				12	Nov 2, 2020	SYSTEM	(\$9,600.00)	
				12	Nov 2, 2020	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total	12		SYSTEM	\$9,600.00 \$0.00	Item Adjustment (0011) due to user steppr1 overridding Payment Estimate
	Material - Total		- Total	12		SYSTEM		Item Adjustment (0011) due to user steppr1 overridding Payment Estimate
0575 -	Material - Total Total		- Total	12		SYSTEM	\$0.00	Item Adjustment (0011) due to user steppr1 overridding Payment Estimate
0575 - 5001		Material	- Total	12		SYSTEM	\$0.00 \$0.00	Item Adjustment (0011) due to user steppr1 overridding Payment Estimate
	· Total	Material	- Total		2020 Jul 17,		\$0.00 \$0.00 \$0.00	Item Adjustment (0011) due to user steppr1 overridding Payment Estimate
	· Total	Material	- Total	5	Jul 17, 2020 Jul 17,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$2,680.00)	Item Adjustment (0011) due to user steppr overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user steppr overridding Payment Estimate

Revision 4/1/2020 Page 12 of 14



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
5001 -	Total						\$0.00	
5002	HALF-SOLE REPAIR	Material		5	Jul 17, 2020	SYSTEM	(\$268.00)	
				5	Jul 17, 2020	SYSTEM	\$268.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5002 -	Total						\$0.00	
5003	HALF-SOLE REPAIR	Material		5	Jul 17, 2020	SYSTEM	(\$3,886.00)	
				5	Jul 17, 2020	SYSTEM	\$3,886.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5003 -	Total						\$0.00	
5004	HALF-SOLE REPAIR	Material		5	Jul 17, 2020	SYSTEM	(\$1,072.00)	
				5	Jul 17, 2020	SYSTEM	\$1,072.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5004 -	Total						\$0.00	
5005	HALF-SOLE REPAIR	Material		5	Jul 17, 2020	SYSTEM	(\$670.00)	
				5	Jul 17, 2020	SYSTEM	\$670.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5005 -	Total						\$0.00	
5103	OPEN CELL FOAM JOINT SEAL	Material		11	Oct 16, 2020	SYSTEM	(\$5,929.00)	
				11	Oct 16, 2020	SYSTEM	\$5,929.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user steppr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				12	Nov 2, 2020	SYSTEM	(\$5,929.00)	
				12	Nov 2, 2020	SYSTEM	\$5,929.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user steppr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5103 -	Total						\$0.00	
5104	OPEN CELL FOAM JOINT SEAL	Material		11	Oct 16, 2020	SYSTEM	(\$12,190.00)	
				11	Oct 16, 2020	SYSTEM	\$12,190.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				12	Nov 2, 2020	SYSTEM	(\$12,190.00)	
				12	Nov 2, 2020	SYSTEM	\$12,190.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5104 -	Total						\$0.00	
5105	OPEN CELL FOAM JOINT SEAL	Material		11	Oct 16, 2020	SYSTEM	(\$5,073.00)	
				11	Oct 16,	SYSTEM	\$5,073.00	This adjustment offsets the original system-generated Overrun Payment Estimate

Revision 4/1/2020 Page 13 of 14



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
5105	OPEN CELL FOAM JOINT SEAL	Material	Type		2020			Item Adjustment (0013) due to user steppr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				12	Nov 2, 2020	SYSTEM	(\$5,073.00)	
				12	Nov 2, 2020	SYSTEM	\$5,073.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user steppr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
5105 -	Total						\$0.00	
5106	OPEN CELL FOAM JOINT SEAL	Material		11	Oct 16, 2020	SYSTEM	(\$5,808.00)	
				11	Oct 16, 2020	SYSTEM	\$5,808.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				12	Nov 2, 2020	SYSTEM	(\$5,808.00)	
				12	Nov 2, 2020	SYSTEM	\$5,808.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user steppr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
Material - Total							\$0.00	
5106 - Total							\$0.00	
Overa	II - Total						(\$8.68)	

Revision 4/1/2020 Page 14 of 14