

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 19, 2021

Progress Estim	ate Number	Contract ID Prime Contractor	200320-F04 Collins & Hermann, In	Pay Period Start c. Pay Period End		Original Contract Amoun Net Change Order Amoun Current Contract Amount	nt \$2,700.00				
Approval Date							By User				
January 19, 2021		Generated and Approved (and should be considered Draft) at the Project Office Level by									
January 19, 2021		Rev	viewed and Approved (and should be conside	red Draft) at the R	esident Engineer Level by	morgac1				
January 20, 2021			Revie	wed and Approved at t	he Central Office (Controllers Office Level by	greggd1				
Original Comp	letion Date	Current Comp	ate % d	of Current Contract Amour	t Complete						
December	1, 2020	December	1, 2020	December 1, 2020		91.30%					

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 15				
	This Estimate	Previous	To Date	
200320-F04				
Total Posted Items Pay	\$12,724.17	\$657,548.07	\$670,272.24	
Gross Item Adjustments	(\$2,267.72)	\$0.00	(\$2,267.72)	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		\$657,548.07	\$668,004.52	
Contract Total Payable This Estimate:	\$10,456.45			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3405	0090	9031010	CONCRETE FOOTINGS, EMBEDDED	CUYD	\$3,092.890	1.92	\$5,938.35
	0100	9031210	STRUCTURAL STEEL POSTS	LB	\$3.340	162	\$541.08
	0110	9031220	PIPE POSTS	LB	\$3.800	1,341	\$5,095.80
	0130	9035004A	SH-FLAT SHEET	SQFT	\$16.390	70.1	\$1,148.94
Project J6I3405	- Total						\$12,724.17
Overall - Total	\$12,724.17						

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3405	0800	MISC.	Material			-2	\$59,106.96	(\$118,213.92)
	0800	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user ingrue overridding Payment Estimate Exception 1 on the current Payment Estimate.	2	\$59,106.96	\$118,213.92
	0090	CONCRETE FOOTINGS, EMBEDDED	Overrun			-0.63	\$3,092.89	(\$1,948.52)
	0110	PIPE POSTS	Overrun			-84	\$3.80	(\$319.20)
	0120	7 FT. CHANNEL POST DELINEATOR, WHITE/RED	Material			-12	\$41.38	(\$496.56)
	0120	7 FT. CHANNEL POST DELINEATOR, WHITE/RED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user ingrue overridding Payment Estimate Exception 2 on the current Payment Estimate.	12	\$41.38	\$496.56
Total								(\$2,267.72

Revision 4/1/2020 Page 1 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	on						
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work						
J6I3405	I 44-4(202)	Sign installation	I-44	VARIOUS	from Route WW/D in Sullivan to 7th Street in St. Louis City								
Totals by .	Job Numbe	ers											
J6I3405		d Item Pay Item Adjustm		Item Pay	This Estimate \$12,724.17 (\$2,267.72) \$10,456.45	Previous \$657,548.07 \$0.00 \$657,548.07	To Date \$670,272.24 (\$2,267.72) \$668,004.52						
	Liquid	tive centive dated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						

Revision 4/1/2020 Page 2 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6l3405, Item 9029902, Project Item Line Number 0080, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	No Remark was entered by Engineer	INGRUE	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3405, Item 9031258, Project Item Line Number 0120, Material Set 903125896, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	No Remark was entered by Engineer	INGRUE	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3405, Item 9031258, Project Item Line Number 0120, Material Set 903125896, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	No Remark was entered by Engineer	INGRUE	Overridden
Estimate Exception Type: Item Overrun: Contract 200320-F04, Contract Project J6l3405, Project Item Line Number 0090, Contract Line Item Number 0090, Item 9031010, Minor Item.	No Remark was entered by Engineer	INGRUE	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200320-F04, Contract Project J6I3405, Project Item Line Number 0110, Contract Line Item Number 0110, Item 9031220, Minor Item.	No Remark was entered by Engineer	INGRUE	Acknowledged

Revision 4/1/2020 Page 3 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-F04	J6I3405	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$108,635.51	\$108,635.51
		0001	0020	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	EA	1.00	\$228.66	\$228.66
		0001	0030	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,016.26	\$2,032.52
		0001	0040	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.90	\$13,056.32	\$11,750.69
		0001	0050	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	4.00	0.00	4.00	EA	2.00	\$2,540.64	\$5,081.28
		0001	0060	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$44,309.86	\$44,309.86
		0001	0070	6209902	MISC.TIER TWO INLAID PAVEMENT MARKER SYSTEM	9.00	0.00	9.00	EA	9.00	\$4,725.59	\$42,530.31
		0030	0080	9029902	MISC.TIER THREE SYSTEM	3.00	0.00	3.00	EA	2.00	\$59,106.96	\$118,213.92
		0040	0090	9031010	CONCRETE FOOTINGS, EMBEDDED	45.90	0.00	45.90	CUYD	46.53	\$3,092.89	\$143,912.17
		0040	0100	9031210	STRUCTURAL STEEL POSTS	2,550.00	0.00	2,550.00	LB	2,496.00	\$3.34	\$8,336.64
		0040	0110	9031220	PIPE POSTS	29,560.00	0.00	29,560.00	LB	29,644.00	\$3.80	\$112,647.20
		0040	0120	9031258	7 FT. CHANNEL POST DELINEATOR, WHITE/RED	13.00	0.00	13.00	EA	12.00	\$41.38	\$496.56
		0040	0130	9035004A	SH-FLAT SHEET	4,260.00	0.00	4,260.00	SQFT	4,234.10	\$16.39	\$69,396.90
		0001	5001	6209901	MISC.Misc Tier II Pavement Marker Removal	0.00	1.00	1.00	LS	1.00	\$2,700.00	\$2,700.00
	Project J	J6I3405 - To	tal Value	Posted to D	late as of Report Generated Date							\$670,272.22
00320-F04 Ove	rall - Tota	l Value Pos	ted to Da	ite as of Rep	ort Generated Date							\$670,272.22

Revision 4/1/2020 Page 4 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6I3405

Project:	0010100											
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0090	9031010	CONCRETE FOOTINGS, EMBEDDED	1/14/21	1/19/21			Location 14, Sign # 84,					
				1/19/21	0.13		Location 19, Sign # 117,					
				1/19/21			Location 19, Sign # 118, Location 19, Sign # 120,					
				1/19/21			Location 20, Sign # 125,					
				1/19/21	0.13		Location 22, Sign # 139,					
				1/19/21	0.13	CUYD	Location 26, Sign # 164,					
				1/19/21	0.13	CUYD	Location 27, Sign # 172,					
				1/19/21			Location 44, Sign # 277,					
				1/19/21			Location 49, Sign # 304, Location 56, Sign # 344,					
				1/19/21	0.13		Location 56, Sign # 344,					
				1/19/21	0.36		Location 5, Sign # 37,					
0100	9031210	STRUCTURAL STEEL POSTS	1/14/21	1/19/21	32.00	LB	Location 2, Sign # 13, R1-1 (Stop), R6-1R (One Way Rt.), R6-1L (One Way Lt.)					
				1/19/21	32.00	LB	Location 2, Sign # 8, R3-1 (No Rt.), R6-1R (One Way Rt.), R6-1L (One Way Lt.)					
				1/19/21	32.00	LB	Location 21, Sign # 131, R3-1 (No Rt.), R6-1R (One Way					
				1/19/21	32.00	LB	Rt.), R6-1L (One Way Lt.) Location 23, Sign # 151, R1-1 (Stop), R6-1R (One Way					
				1/19/21	32.00	LB	Rt.), R6-1L (One Way Lt.) Location 3, Sign # 15, R6-1R (One Way Rt.), R6-1L (One					
				1/19/21	32.00	LB	Way Lt.) Location 5, Sign # 32, R3-1 (No Rt.), R6-1R (One Way					
				1/19/21	32.00		Rt.), R6-1L (One Way Lt.)					
							Location 56, Sign # 344, R6-1R (One Way Rt.), R6-1L (One Way Lt.)					
				1/19/21	32.00	LB	Location 6, Sign # 40, R3-1 (No Rt.), R6-1R (One Way Rt.), R6-1L (One Way Lt.)					
				1/19/21	32.00	LB	Location 60, Sign # 380, R6-1R (One Way Rt.), R6-1L (One Way Lt.)					
			1/15/21	1/15/21	-94.00	LB	Incorrectly added pipe post quantity to the SS line on 8/26					
				1/15/21	-32.00	LB	Correction - sign #29 paid twice on 8/26 and 9/3					
				1/15/21	0.00		Sign #75 paid on 8/27 should be sign #74					
0110	9031220	PIPE POSTS	1/14/21	1/19/21	71.00	LB	Location 33, Sign # 344, R6-1R (One Way Rt.), R6-1L (One Way Lt.)					
				1/19/21	71.00	LB	Location 54, Sign # 336, R6-1R (One Way Rt.), R6-1L (One Way Lt.)					
				1/19/21	86.00	LB	Location 21, Sign # 134, R5-1A (Wrong Way)					
				1/19/21	86.00	LB	Location 58, Sign # 363, R5-1A (Wrong Way)					
				1/19/21	89.00	LB	Location 21, Sign # 132, R5-1A (Wrong Way)					
				1/19/21	89.00		Location 21, Sign # 133, R5-1A (Wrong Way)					
				1/19/21	89.00		Location 21, Sign # 135, R5-1A (Wrong Way)					
				1/19/21	89.00 91.00		Location 27, Sign # 172, R5-1A (Wrong Way) Location 20, Sign # 125, R5-1A (Wrong Way)					
				1/19/21	91.00		Location 20, Sign # 128, R5-1A (Wrong Way)					
				1/19/21	94.00		Location 19, Sign # 117, R5-1 (Do Not Enter)					
				1/19/21	94.00	LB	Location 19, Sign # 120, R5-1A (Wrong Way)					
				1/19/21	94.00	LB	Location 20, Sign # 126, R5-1A (Wrong Way)					
				1/19/21	94.00		Location 20, Sign # 127, R5-1A (Wrong Way)					
				1/19/21	97.00		Location 19, Sign # 118, R5-1A (Wrong Way)					
				1/19/21	140.00	LB	Location 1, Sign # 6, R1-1 (Stop), R6-1R (One Way Rt.), R6-1L (One Way Lt.)					
				1/19/21	173.00	LB	Location 2, Sign # 13, R1-1 (Stop), R6-1R (One Way Rt.), R6-1L (One Way Lt.)					
			1/15/21	1/15/21	-214.00	LB	Correction for quantity entered on 9/3. Sign #29 was already paid on 8/26					
				1/15/21	-83.00	LB	Correction for payment on 8/27, Sign #60.					
				1/15/21	0.00		Correction for entry on 8/27. Sign #61 should be sign #60					
0130	9035004A	SH-FLAT SHEET	1/14/21	1/19/21			Location 19, Sign #121, R3-2 (No Lt.),					
				1/19/21	4.00		Location 2, Sign # 14, R3-2 (No Lt.)					
				1/19/21	4.00		Location 20, Sign # 124, R3-1 (No Rt), Location 23, Sign #145, R3-1 (No Rt),					
				1/19/21	4.00		Location 3, Sign #22, R3-2 (No Lt.)					
				1/19/21	4.00		Location 4, Sign # 30, R3-2 (No Lt.),					
				1/19/21	6.30	SQFT	Location 19, Sign # 117, R5-1 (Do Not Enter),					
				1/19/21	6.30	SQFT	Location 19, Sign #120, R5-1 (Do Not Enter),					
				1/19/21	6.30		Location 20, Sign #125, R5-1(Do Not Enter),					
				1/19/21			Location 20, Sign #128, R5-1 (Do Not Enter),					
				1/19/21	6.30		Location 21, Sign #132, R5-1(Do Not Enter),					
				1/19/21	6.30 8.80		Location 21, Sign #135, R5-1 (Do Not Enter), Location 19, Sign #118, R5-1A (Wrong Way),					
				1/19/21	8.80		Location 20, Sign #126, R5-1A (Wrong Way),					
				1/19/21			Location 20, Sign #120, R5-1A (Wrong Way),					
				1/19/21	8.80		Location 21, Sign #133, R5-1A (Wrong Way),					
				1/19/21	8.80		Location 21, Sign #134, R5-1A (Wrong Way),					
				1/19/21	8.80	SQFT	Location 27, Sign #172, R5-1A (Wrong Way),					
				1/19/21	8.80		Location 31, Sign #202, R5-1A (Wrong Way),					
				1/19/21	9.00		Location 1, Sign # 5, R5-1, Do Not Enter					
				1/19/21	13.60	SQFT	Location 60, Sign #380, R6-1R (No Rt), R6-1L (No Lt.)					

Revision 4/1/2020 Page 5 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0130	9035004A	SH-FLAT SHEET	1/14/21	1/19/21	16.10	SQFT	Location 3, Sign # 15, R1-3P (All Way), R6-1R (One Way Rt), R6-1L (One Way Lt.)					
				1/19/21	17.60	SQFT	Location 2, Sign # 8, R3-1 (No Rt.), R6-1R (One Way Rt), R6-1L (One Way Lt.)					
				1/19/21	17.60	SQFT	Location 21, Sign #131, R3-1 (No Rt), R6-1R (One Way Rt.), R6-1L (One Way Lt)					
				1/19/21	26.90	SQFT	Location 2, Sign # 13, R1-1 (Stop), R6-1R (One Way Rt), R6-1L (One Way Lt.)					
				1/19/21	26.90	SQFT	Location 23, Sign #151, R1-1 (Stop), R6-1R (One Way Rt.), R6-1L (One Way Lt.)					
			1/15/21	1/15/21	-100.70	SQFT	Correction for entry on 8/24, sign #50					
				1/15/21	-48.00	SQFT	Correction for entry 8/27, sign #60					
				1/15/21	-24.40	SQFT	Correction for entry on 8/26, Sign #30					
				1/15/21	-13.30	SQFT	Correction for entry on 9/3, sign #29, R1-1, Stop. Previously paid on 8/26					
				1/15/21	-9.00	SQFT	Correction for entry on 8/24, sign #4, previously paid on 7/29					
				1/15/21	-9.00	SQFT	Correction for entry on 8/25, sign #38					
				1/15/21	-6.80	SQFT	Correction for entry on 9/3, sign #29, R6-1L,One Way Left. Previously paid on 8/26					
				1/15/21	-6.80	SQFT	Correction for entry on 9/3, sign #29, R6-1R,One Way Right. Previously paid on 8/26					
				1/15/21	0.00	SQFT	Correction for entry on 8/25. Listed as sign #35. Should be sign #36					
				1/15/21	4.00	SQFT	Sign #30, R3-2, No Left Turn (sym)					
				1/15/21	4.00	SQFT	Sign #38, R3-2, No Left Turn (sym)					
				1/15/21	9.00	SQFT	Sign #50, R5-1, Do Not Enter					
				1/15/21	16.00	SQFT	Sign #60, R5-1, Do Not Enter					

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	TRUCK OR TRAILER MOUNTED	Material		11	Nov 16, 2020	SYSTEM	(\$228.66)	
	ATTENUATOR (TMA)			11	Nov 16, 2020	SYSTEM	\$228.66	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user ingrue overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Dec 2, 2020	SYSTEM	(\$228.66)	
				12	Dec 2, 2020	SYSTEM	\$228.66	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user silvej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0020 -	Total						\$0.00	
0030	FLASHING ARROW PANEL	Material		11	Nov 16, 2020	SYSTEM	(\$2,032.52)	
				11	Nov 16, 2020	SYSTEM	\$2,032.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user ingrue overridding Payment Estimate Exception 2 on the current Payment Estimate.
				12	Dec 2, 2020	SYSTEM	(\$2,032.52)	
				12	Dec 2, 2020	SYSTEM	\$2,032.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user silvej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0030 -	Total						\$0.00	
0080	MISC. TIER THREE SYSTEM	Material		12	Dec 2, 2020	SYSTEM	(\$118,213.92)	
				12	Dec 2, 2020	SYSTEM	\$118,213.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user silvej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				13	Dec 16, 2020	SYSTEM	(\$118,213.92)	
				13	Dec 16, 2020	SYSTEM	\$118,213.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user ingrue overridding Payment Estimate Exception 1 on the current Payment Estimate.
				14	Jan 4, 2021	SYSTEM	(\$118,213.92)	
				14	Jan 4, 2021	SYSTEM	\$118,213.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ingrue overridding Payment Estimate Exception 1 on the current Payment Estimate.
				15	Jan 19, 2021	SYSTEM	(\$118,213.92)	
				15	Jan 19, 2021	SYSTEM	\$118,213.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ingrue overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0080 -	Total						\$0.00	
0090	CONCRETE FOOTINGS,	Material		1	Jun 16, 2020	SYSTEM	(\$4,330.05)	
	EMBEDDED			1	Jun 16, 2020	SYSTEM	\$4,330.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user ingrue overridding Payment Estimate Exception 1 on the current Payment Estimate.
				2	Jun 30, 2020	SYSTEM	(\$49,393.45)	
				2	Jun 30, 2020	SYSTEM	\$49,393.45	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user ingrue overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Jul 16, 2020	SYSTEM	(\$102,807.66)	
				3	Jul 16, 2020	SYSTEM	\$102,807.66	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user ingrue overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	

Revision 4/1/2020 Page 7 of 8



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0090	Material - Total						\$0.00	
	CONCRETE FOOTINGS, EMBEDDED	Overrun	Overrun	15	Jan 19, 2021	SYSTEM	(\$1,948.52)	
			Overrun - To	otal			(\$1,948.52)	
	Overrun - Total						(\$1,948.52)	
0090 -	Total						(\$1,948.52)	
0110	PIPE POSTS	Overrun	Overrun	15	Jan 19, 2021	SYSTEM	(\$319.20)	
			Overrun - To	otal			(\$319.20)	
	Overrun - Total						(\$319.20)	
0110 -	Total						(\$319.20)	
0120	7 FT. CHANNEL POST DELINEATOR,	Material		12	Dec 2, 2020	SYSTEM	(\$496.56)	
	WHITE/RED			12	Dec 2, 2020	SYSTEM	\$496.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user silvej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				13	Dec 16, 2020	SYSTEM	(\$496.56)	
				13	Dec 16, 2020	SYSTEM	\$496.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user ingrue overridding Payment Estimate Exception 2 on the current Payment Estimate.
				14	Jan 4, 2021	SYSTEM	(\$496.56)	
				14	Jan 4, 2021	SYSTEM	\$496.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ingrue overridding Payment Estimate Exception 2 on the current Payment Estimate.
				15	Jan 19, 2021	SYSTEM	(\$496.56)	
				15	Jan 19, 2021	SYSTEM	\$496.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ingrue overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0120 -	Total						\$0.00	
Overa	II - Total						(\$2,267.72)	

Revision 4/1/2020 Page 8 of 8