

#### Pay Estimate Created Date: January 15, 2021

Progress Estima 18	ate Number	Contract ID Prime Contractor	200320-H03 Emery Sapp & Sons, I	Pay Period Start Jan nc. Pay Period End Jan		Original Contract Amount Net Change Order Amount Current Contract Amount	\$3,685,526.19 \$197,732.52 \$3,883,258.71		
Approval Date							By User		
January 15, 2021		Generated and Approved (and should be considered Draft) at the Project Office Level by							
January 19, 2021		F	Reviewed and Approved	(and should be considered	Draft) at the F	Resident Engineer Level by	plottk1		
January 20, 2021			Revi	iewed and Approved at the	Central Office	Controllers Office Level by	greggd1		
Original Comp	letion Date	Current Con	npletion Date	Actual Completion Date	%	of Current Contract Amount	Complete		
October 1,	1, 2020 November 7, 2020 November 4, 2020 95.98%								

#### No Milestones Exist for Contract

Contract Total Pa	ay For Estimate No. 18			
		This Estimate	Previous	To Date
200320-H03				
	Total Posted Items Pay	\$0.00	\$3,727,029.04	\$3,727,029.04
	Gross Item Adjustments	\$0.00	\$37,941.82	\$37,941.82
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$3,764,970.86	\$3,764,970.86
<b>Contract Total Pa</b>	yable This Estimate:	\$0.00		

#### Items Paid This Estimate Period

#### No Data Available

#### Contract Adjustments This Estimate

#### No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
9P3512	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Material			-21,827.3	\$61.40	(\$1,340,196.22)
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user evansk overridding Payment Estimate Exception 1 on the current Payment Estimate.	21,827.3	\$61.40	\$1,340,196.22
	0350	CURB BLOCKOUT	Material			-514	\$127.45	(\$65,509.30)
	0350	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.	514	\$127.45	\$65,509.30
	5002	CURB BLOCKOUT	Material			-205	\$235.00	(\$48,175.00)
	5002	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 19 on the current Payment Estimate.	205	\$235.00	\$48,175.00
	5003	CURB BLOCKOUT	Material			-199	\$235.00	(\$46,765.00)
	5003	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment Estimate Exception 8 on the current Payment Estimate.	199	\$235.00	\$46,765.00
	5004	CURB BLOCKOUT	Material			-199	\$235.00	(\$46,765.00)
	5004	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 14 on the current Payment Estimate.	199	\$235.00	\$46,765.00
otal								\$0.00



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Со	ntract Project Information	on
Project Number	Federal Proj. Number	Description	Route	County			Location of Work
J9P3512	FAF 62-1(28)	Coldmill and resurface	62	NEW MADRID	from Route 25 to Route 61		
Totals by J	Job Numb	ers					
J9P3512		ed Item Pay s Item Adjustn		<mark>s Item Pay</mark>	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous   \$3,727,029.04   \$37,941.82   \$3,764,970.86	To Date \$3,727,029.04 \$37,941.82 <b>\$3,764,970.86</b>
	Liqui	ntive Icentive Idated Damage r Contract Adji		5	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Periou Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 4011211, Project Item Line Number 0050, Material Set 401121196, Material 0401BPPMBP2 - Plant Mix for Bit Pavement BP-2, Acceptance Action Generic AspLow is insufficient.	CRE20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 0350, Material Set 703460096, Material 1036RSDFEC42M19 - Rein Steel EC No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 0350, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	PAL reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 0350, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	CRE20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 0350, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	CRE20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 0350, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	PAL reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 0350, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	CRE20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5003, Material Set 703460096, Material 1036RSDFEC42M19 - Rein Steel EC No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5003, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	PAL reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5003, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	CRE20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5003, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	PAL reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5003, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	CRE20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5003, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	CR20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5004, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	CRE20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5004, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	CRE20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5004, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	PAL reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5004, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	CRE20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5004, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	PAL reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5002, Material Set 703460096, Material 1036RSDFEC42M19 - Rein Steel EC No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5002, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	CRE20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5002, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	CRE20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5002, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	PAL reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5002, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	CRE20 reports pending	evansk	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3512, Item 7034600, Project Item Line Number 5002, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance	PAL reports pending	evansk	Overridden



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status	
Action Generic 1053CSSIL is insufficient.				

# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

## Total Paid / All Items / All Estimates (Including this Estimate)

d date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200320-H03	J9P3512	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$28,130.39	\$28,130.39
		0001	0020	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	5,295.00	0.00	5,295.00	LF	5,295.00	\$31.95	\$169,175.25
		0001	0030	3049910	MISC.PERMANEMT AGGREGATE EDGE TREATMENT	6,405.60	0.00	6,405.60	TONS	4,912.00	\$32.30	\$158,657.60
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	85.00	0.00	85.00	TONS	0.00	\$117.00	\$0.00
		0001	0050	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	36,754.50	72.80	36,827.30	TONS	36,827.30	\$61.40	\$2,261,196.22
		0001	0060	4071005	TACK COAT	31,701.00	0.00	31,701.00	GAL	14,710.00	\$2.15	\$31,626.50
		0001	0070	4134000	BITUMINOUS FOG SEAL	11,304.00	0.00	11,304.00	GAL	6,090.00	\$2.60	\$15,834.00
		0001	0080	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	107.00	0.00	107.00	CUYD	107.00	\$73.40	\$7,853.80
		0001	0090	6096042	PLACING TYPE 2 ROCK DITCH LINER	107.00	0.00	107.00	CUYD	107.00	\$51.90	\$5,553.30
		0001	0100	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	2.00	2.00	4.00	EA	4.00	\$2,665.00	\$10,660.00
		0001	0110	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	1.00	\$750.00	\$750.00
		0001	0120	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	499.60	34.00	533.60	TONS	533.60	\$122.50	\$65,366.00
		0001	0130	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	1,689.50	200.00	1,889.50	SQYD	1,889.50	\$14.45	\$27,303.28
		0001	0140	6161005	CONSTRUCTION SIGNS	2,071.00	0.00	2,071.00	SQFT	1,522.00	\$5.85	\$8,903.70
		0001	0150	6161009	FLAG ASSEMBLY	6.00	2.00	8.00	EA	8.00	\$21.30	\$170.40
		0001	0160	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	70.00	\$19.20	\$1,344.00
		0001	0170	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,665.00	\$5,330.00
		0001	0180	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$93,059.10	\$0.00
		0001	0181	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$77,785.10	\$77,785.10
		0001	0190	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	78.00	0.00	78.00	LF	36.00	\$21.30	\$766.80
		0001	0200	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	201,672.00	0.00	201,672.00	LF	201,672.00	\$0.12	\$24,200.64
		0001	0210	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	36,880.00	0.00	36,880.00	LF	36,880.00	\$0.11	\$4,056.80
		0001	0220	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0001	0230	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	6,279.00	0.00	6,279.00	SQYD	5,479.00	\$3.90	\$21,368.1
		0001	0240	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	13,052.00	0.00	13,052.00	SQYD	12,899.00	\$3.70	\$47,726.3
		0001	0250	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	267.00	0.00	267.00	SQYD	267.00	\$3.20	\$854.4
		0001	0260	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,923.30	0.00	1,923.30	STA	1,923.30	\$16.00	\$30,772.8
		0001	0270	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	961.70	0.00	961.70	STA	961.70	\$16.00	\$15,387.20
		0010	0280	6061060	MGS GUARDRAIL	1,975.00	0.00	1,975.00	LF	1,975.00	\$26.65	\$52,633.7
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	39.00	0.00	39.00	EA	39.00	\$2,985.00	\$116,415.0
		0010	0300	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	39.00	0.00	39.00	EA	39.00	\$2,880.00	\$112,320.0
		0010	0310	6063017	TYPE C CRASHWORTHY END TERMINAL	11.00	0.00	11.00	EA	11.00	\$14,920.00	\$164,120.00
		0040	0320	9031270A	2 IN. PSST POST - 12 GA.	325.00	0.00	325.00	LF	325.00	\$12.80	\$4,160.00
		0040	0330	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	132.00	0.00	132.00	LF	132.00	\$21.30	\$2,811.60
		0040	0340	9035069A	SHF-FLAT SHEET FLUORESCENT	132.00	0.00	132.00	SQFT	132.00	\$26.65	\$3,517.80
		0070	0350	7034600	CURB BLOCKOUT	514.00	0.00	514.00	LF	514.00	\$127.45	\$65,509.30
		0071	0360	7034535	CURB MODIFICATION	3.00	0.00	3.00	LF	0.00	\$9,165.00	\$0.00
		0001	5001	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$15,274.00	\$15,274.00
		0001	5002	7034600	CURB BLOCKOUT	0.00	205.00	205.00	LF	205.00	\$235.00	\$48,175.00
	0001 5003 7034600 CURB BLOCKOUT		0.00	199.00	199.00	LF	199.00	\$235.00	\$46,765.00			
	0001 5004 7034600 CURB BLOCKOUT		0.00	199.00	199.00	LF	199.00	\$235.00	\$46,765.00			
		0001	5005	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$7,000.00	\$7,000.00
		0001	5006	6122030	IMPACT ATTENUATOR (RELOCATION)	0.00	17.00	17.00	EA	11.00	\$1,890.00	\$20,790.00
	Project .I	P3512 - To	otal Value	Posted to D	ate as of Report Generated Date						1	\$3,727,029.02



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q	Jote: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.											
Contract		Category		Item	Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved		To Date (See report generated date)

								Qty	
200320-H03 Ove	erall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date				\$3,727,029.02

## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

## The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
9P3512	0140	May 27, 2020	96	CONST-7-72 72x36 18.00 RATE OUR WORK ZONE		15.095	rt	1.00	18			1
				GO20-2 48x24 8.00 END ROAD WORK		15.095	lt	1.00	8			
				See Special Sign Details				0.00				
				GO20-2 48x24 8.00 END ROAD WORK		34.315	rt	1.00	8			
				CONST-7-72 72x36 18.00 RATE OUR WORK ZONE		34.315	lt	1.00	18			1
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		34.255	lt	1.00	10			1
				special ??x?? ??.00 NO PASSING ZONE		34.150	It	1.00		No Phone Zone	12.00	1
				special ??x?? ??.00 NO PASSING ZONE		15.225	rt	1.00		No Phone Zone	12.00	1
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		15.160	rt	1.00	10			1
		May 28, 2020	144	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		29.120	Rte W - It	1.00	16			1
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		23.225	Rte 153 - It and rt	2.00	16			3
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		17.430	Rte NN - It	1.00	16			1
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		17.430	Rte J - rt	1.00	16			1
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		15.065	Rte 25 - It and rt	2.00	16			3
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		34.345	Rte 61 - It and rt	2.00	16			3
				See Special Sign Details				0.00				
		June 10, 2020	96	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		15.070 - 34.338		2.00	16			3
				See Special Sign Details				0.00				
				WO3-3 48x48 16.00 SIGNAL AHEAD (SYMBOL)		15.070 - 34.338		2.00	16			3
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		15.070 - 34.338		2.00	16			3
		July 27, 2020	192	WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		15.070 - 34.338		4.00	16			6
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		15.070 - 34.338		4.00	16			6
				WO20-7a 48x48 16.00 FLAGGER (SYMBOL)		15.070 - 34.338		4.00	16			6
				See Special Sign Details				0.00				
		July 29, 2020	92	GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR		15.070 - 34.338		10.00	8.75			87
				GO20-4 36x18 4.50 PILOT CAR FOLLOW ME		15.070 - 34.338		1.00	4.5			4.
				See Special Sign Details				0.00				
		August 5, 2020	518	WO8-1 48x48 16.00 BUMP		15.070 - 34.338		14.00	16			22
				WO8-15 48x48 16.00 GROOVED PAVEMENT		15.070 - 34.338		14.00	16			22
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		15.070 - 34.338		14.00	5			7
				See Special Sign Details				0.00				
		August 21, 2020	384	WO8-11 48x48 16.00 UNEVEN LANES		15.070 - 34.338		6.00	16			g
				WO8-12 48x48 16.00 NO CENTER		15.070 -		18.00	16			



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J9P3512	0140	August	384	LINE		34.338						
		21, 2020		See Special Sign Details				0.00				
	0140 - To	otal										1522



	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
\ \		Type	Adjustment Type	Number	Date	Ву	(\$1.100.149.14)		
)	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Material		8	Aug 17, 2020	SYSTEM			
				8	Aug 17, 2020	SYSTEM	\$1,199,148.14	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user evansk overridding Payme Estimate Exception 1 on the current Payment Estimate.	
				9	Sep 1, 2020	SYSTEM	(\$1,522,830.52)		
				9	Sep 1, 2020	SYSTEM	\$1,522,830.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				10	Sep 16, 2020	SYSTEM	(\$1,522,830.52)		
				10	Sep 16, 2020	SYSTEM	\$1,522,830.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user evansk overridding Payme Estimate Exception 1 on the current Payment Estimate.	
				11	Oct 1, 2020	SYSTEM	(\$1,338,630.52)		
				11	Oct 1, 2020	SYSTEM	\$1,338,630.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user evansk overridding Payme Estimate Exception 1 on the current Payment Estimate.	
				12	Oct 16, 2020	SYSTEM	(\$1,338,630.52)		
				12	Oct 16, 2020	SYSTEM	\$1,338,630.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user evansk overridding Payme Estimate Exception 1 on the current Payment Estimate.	
				13	Nov 2, 2020	SYSTEM	(\$1,338,630.52)		
				13	Nov 2, 2020	SYSTEM	\$1,338,630.52	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0002) due to user evansk overridding Payme Estimate Exception 1 on the current Payment Estimate.	
					14	Nov 16, 2020	SYSTEM	(\$1,340,196.22)	
						14	Nov 16, 2020	SYSTEM	\$1,340,196.22
				15	Dec 1, 2020	SYSTEM	(\$1,340,196.22)		
				15	Dec 1, 2020	SYSTEM	\$1,340,196.22	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0001) due to user evansk overridding Payme Estimate Exception 1 on the current Payment Estimate.	
				16	Dec 15, 2020	SYSTEM	(\$1,340,196.22)		
				16	Dec 15, 2020	SYSTEM	\$1,340,196.22	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0001) due to user evansk overridding Paym Estimate Exception 1 on the current Payment Estimate.	
				17	Jan 4, 2021	SYSTEM	(\$1,340,196.22)		
				17	Jan 4, 2021	SYSTEM	\$1,340,196.22	This adjustment offsets the original system-generated Material Paymen Estimate Item Adjustment (0002) due to user evansk overridding Payme Estimate Exception 1 on the current Payment Estimate.	
				18	Jan 15, 2021	SYSTEM	(\$1,340,196.22)		
				18	Jan 15, 2021	SYSTEM	\$1,340,196.22	This adjustment offsets the original system-generated Material Paymer Estimate Item Adjustment (0002) due to user evansk overridding Paym Estimate Exception 1 on the current Payment Estimate.	
			- Total				\$0.00		
M	laterial - Total	Others	LIDD/	0	Sec. 6		\$0.00		
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Other Item Adjustment	MDPA		Sep 2, 2020	connen1	(\$2,904.22)	Adjustment was made to remove the pay for the overrun since the char order has not been completed.	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)		MDPA - Tot		Dec 1, 2020	plottk1	(\$2,904.22) \$2,904.22	Entered to pay back MDPA adjustment on estimate 9.	
			OTHR - Tota	al			\$2,904.22		
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)		SMAB	16	Dec 16, 2020	plottk1	\$38,669.38	Payment for percent improvement smoothness bonus Plan width=12 ft Overlay thickness= 1.5" Overlay Density= 2.04 tons/CY Asphalt unit price= \$61.40/ton	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050	Other Adjust							West Bound Lane Summary: Total bonus= \$20,127.55 96714 ft @ 103%= \$20,190.12 1,343 ft @ 100%= \$0.00 300 ft @ 97%= (-62.57)
								East Bound Lane Summary: Total bonus= \$18,541.83 89875 ft @ 103%= \$18,762.27 6812 ft @ 100%= \$0.00 1056 ft @ 97%= (-220.44)
			SMAB - Tot	al			\$38,669.38	
	Other Item Adjustment - Total						\$38,669.38	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Overrun	Overrun		Sep 1, 2020	SYSTEM	(\$2,904.22)	
				9	Sep 1, 2020	SYSTEM	\$2,904.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 7 on the current Payment Estimate.
				10	Sep 16, 2020	SYSTEM	(\$2,904.22)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Sep 16, 2020	SYSTEM	\$2,904.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 6 on the current Payment Estimate.
				11	Oct 1, 2020	SYSTEM	(\$2,904.22)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				11	Oct 1, 2020	SYSTEM	\$2,904.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 6 on the current Payment Estimate.
				12	Oct 16, 2020	SYSTEM	(\$2,904.22)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Oct 16, 2020	SYSTEM	\$2,904.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 33 on the current Payment Estimate.
			13	Nov 2, 2020	SYSTEM	(\$2,904.22)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
				13	Nov 2, 2020	SYSTEM	\$2,904.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 41 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0050 -	Total						\$38,669.38	
0080	FURNISHING TYPE 2 ROCK DITCH LINER	Material	al	6	Jul 16, 2020	SYSTEM	(\$7,853.80)	
				6	Jul 16, 2020	SYSTEM	\$7,853.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user evansk overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Aug 3, 2020	SYSTEM	(\$7,853.80)	
				7	Aug 3, 2020	SYSTEM	\$7,853.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user evansk overridding Payment Estimate Exception 5 on the current Payment Estimate.
				8	Aug 17, 2020	SYSTEM	(\$7,853.80)	
				8	Aug 17, 2020	SYSTEM	\$7,853.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user evansk overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Sep 1, 2020	SYSTEM	(\$7,853.80)	
				9	Sep 1, 2020	SYSTEM	\$7,853.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		- Total				\$0.00		
						\$0.00		
	Material - Total						\$0.00	
0080 -								
0080 - 0150		Overrun	Overrun	7	Aug 3, 2020	SYSTEM	(\$42.60)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0150		Overrun	Overrun - T	otal			\$0.00			
	Overrun - Total						\$0.00			
0150 -	Total						\$0.00			
0200	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL		Dec 1, 2020	plottk1	(\$739.93)	No pay adjustment= -\$1,064.83 80% pay adjustment= -\$324.29 105% pay adjustment= \$649.18 Total of adjustments= -\$739.93		
			REFL - Tota	ıl			(\$739.93)			
	Other Item Adjustment - Total						(\$739.93)			
0200 -	Total						(\$739.93)			
0210	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL		Dec 1, 2020	plottk1	\$12.37	No pay adjustment= -\$20.28 80% pay adjustment= -\$56.80 105% adjustment= \$89.45 Total adjustment= \$12.37		
			REFL - Tota	l .			\$12.37			
	Other Item Adjustment - Total						\$12.37			
0210 -	Total						\$12.37			
0280	MGS GUARDRAIL	Material		4	Jun 16, 2020	SYSTEM	(\$5,330.00)			
				4	Jun 16, 2020	SYSTEM	\$5,330.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user evansk overridding Payment Estimate Exception 1 on the current Payment Estimate.		
				5	Jul 1, 2020	SYSTEM	(\$9,327.50)			
				5	Jul 1, 2020	SYSTEM	\$9,327.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user evansk overridding Payment Estimate Exception 1 on the current Payment Estimate.		
				6	Jul 16, 2020	SYSTEM	(\$9,327.50)			
				6	Jul 16, 2020	SYSTEM	\$9,327.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user evansk overridding Payment Estimate Exception 1 on the current Payment Estimate.		
				7	Aug 3, 2020	SYSTEM	(\$9,327.50)			
				7	Aug 3, 2020	SYSTEM	\$9,327.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment Estimate Exception 1 on the current Payment Estimate.		
				8	Aug 17, 2020	SYSTEM	(\$9,327.50)			
				8	Aug 17, 2020	SYSTEM	\$9,327.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.		
				9	Sep 1, 2020	SYSTEM	(\$9,327.50)			
				9	Sep 1, 2020	SYSTEM	\$9,327.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
				10	Sep 16, 2020	SYSTEM	(\$9,327.50)			
				10	Sep 16, 2020	SYSTEM	\$9,327.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.		
				11	Oct 1, 2020	SYSTEM	(\$9,327.50)			
						11	Oct 1, 2020	SYSTEM	\$9,327.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.
				12	Oct 16, 2020	SYSTEM	(\$18,655.00)			
						12	Oct 16, 2020	SYSTEM	\$18,655.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.
				13	Nov 2, 2020	SYSTEM	(\$23,985.00)			
				13	Nov 2, 2020	SYSTEM	\$23,985.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment		



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0280	MGS GUARDRAIL	Material						Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	
0290	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Material		4	Jun 16, 2020	SYSTEM	(\$23,880.00)	
				4	Jun 16, 2020	SYSTEM	\$23,880.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Jul 1, 2020	SYSTEM	(\$47,760.00)	
				5	Jul 1, 2020	SYSTEM	\$47,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Jul 16, 2020	SYSTEM	(\$47,760.00)	
				6	Jul 16, 2020	SYSTEM	\$47,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Aug 3, 2020	SYSTEM	(\$47,760.00)	
				7	Aug 3, 2020	SYSTEM	\$47,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Aug 17, 2020	SYSTEM	(\$47,760.00)	
				8	Aug 17, 2020	SYSTEM	\$47,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Sep 1, 2020	SYSTEM	(\$47,760.00)	
				9	Sep 1, 2020	SYSTEM	\$47,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Sep 16, 2020	SYSTEM	(\$47,760.00)	
				10	Sep 16, 2020	SYSTEM	\$47,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 3 on the current Payment Estimate.
				11	Oct 1, 2020	SYSTEM	(\$47,760.00)	
				11	Oct 1, 2020	SYSTEM	\$47,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 3 on the current Payment Estimate.
				12	Oct 16, 2020	SYSTEM	(\$83,580.00)	
				12	Oct 16, 2020	SYSTEM	\$83,580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 3 on the current Payment Estimate.
				13	Nov 2, 2020	SYSTEM	(\$104,475.00)	
					2020			
				13	Nov 2, 2020	SYSTEM	\$104,475.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total	13	Nov 2,	SYSTEM	\$104,475.00 <b>\$0.00</b>	Estimate Item Adjustment (0004) due to user evansk overridding Payment
	Material - Total		- Total	13	Nov 2,	SYSTEM		Estimate Item Adjustment (0004) due to user evansk overridding Payment
0290 -	Material - Total - Total		- Total	13	Nov 2,	SYSTEM	\$0.00	Estimate Item Adjustment (0004) due to user evansk overridding Payment
0290 - 0300		Material	- Total	13	Nov 2,	SYSTEM SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0004) due to user evansk overridding Payment
	- Total TYPE A CRASHWORTHY END	Material	- Total		Nov 2, 2020 Jun 16,		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user evansk overridding Payment
	- Total TYPE A CRASHWORTHY END	Material	- Total	4	Nov 2, 2020 Jun 16, 2020 Jun 16,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$23,040.00)	Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 3 on the current Payment Estimate.



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0300	TYPE A CRASHWORTHY END	Material						Estimate Exception 3 on the current Payment Estimate.
	TERMINAL (MASH			6	Jul 16, 2020	SYSTEM	(\$46,080.00)	
				6	Jul 16, 2020	SYSTEM	\$46,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Aug 3, 2020	SYSTEM	(\$46,080.00)	
				7	Aug 3, 2020	SYSTEM	\$46,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Aug 17, 2020	SYSTEM	(\$46,080.00)	
				8	Aug 17, 2020	SYSTEM	\$46,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 4 on the current Payment Estimate.
				9	Sep 1, 2020	SYSTEM	(\$46,080.00)	
				9	Sep 1, 2020	SYSTEM	\$46,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				10	Sep 16, 2020	SYSTEM	(\$46,080.00)	
				10	Sep 16, 2020	SYSTEM	\$46,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 4 on the current Payment Estimate.
				11	Oct 1, 2020	SYSTEM	(\$46,080.00)	
				11	Oct 1, 2020	SYSTEM	\$46,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 4 on the current Payment Estimate.
				12	Oct 16, 2020	SYSTEM	(\$80,640.00)	
				12	Oct 16, 2020	SYSTEM	\$80,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 4 on the current Payment Estimate.
				13	Nov 2, 2020	SYSTEM	(\$100,800.00)	
				13	Nov 2, 2020	SYSTEM	\$100,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0300 -	Total						\$0.00	
0310	TYPE C CRASHWORTHY END TERMINAL	Material		5	Jul 1, 2020	SYSTEM	(\$29,840.00)	
				5	Jul 1, 2020	SYSTEM	\$29,840.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	Jul 16, 2020	SYSTEM	(\$104,440.00)	
				6	Jul 16, 2020	SYSTEM	\$104,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Aug 3, 2020	SYSTEM	(\$164,120.00)	
				7	Aug 3, 2020	SYSTEM	\$164,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user evansk overridding Payment Estimate Exception 4 on the current Payment Estimate.
				8	Aug 17, 2020	SYSTEM	(\$164,120.00)	
				8	Aug 17, 2020	SYSTEM	\$164,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user evansk overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Sep 1, 2020	SYSTEM	(\$164,120.00)	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0310	TYPE C CRASHWORTHY END TERMINAL	Material	5.		2020			Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				10	Sep 16, 2020	SYSTEM	(\$164,120.00)	
				10	Sep 16, 2020	SYSTEM	\$164,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user evansk overridding Payment Estimate Exception 5 on the current Payment Estimate.
				11	Oct 1, 2020	SYSTEM	(\$164,120.00)	
				11	Oct 1, 2020	SYSTEM	\$164,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user evansk overridding Payment Estimate Exception 5 on the current Payment Estimate.
				12	Oct 16, 2020	SYSTEM	(\$164,120.00)	
				12	Oct 16, 2020	SYSTEM	\$164,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user evansk overridding Payment Estimate Exception 5 on the current Payment Estimate.
				13	Nov 2, 2020	SYSTEM	(\$164,120.00)	Esumate Exception o on the current rayment Esumate.
				13	Nov 2, 2020	SYSTEM	\$164,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user evansk overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0310 -	Total						\$0.00	
0350	CURB BLOCKOUT	Material		13	Nov 2, 2020	SYSTEM	(\$65,509.30)	
				13	Nov 2, 2020	SYSTEM	\$65,509.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user evansk overridding Payment Estimate Exception 24 on the current Payment Estimate.
				14	Nov 16, 2020	SYSTEM	(\$65,509.30)	
				14	Nov 16, 2020	SYSTEM	\$65,509.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment Estimate Exception 3 on the current Payment Estimate.
				15	Dec 1, 2020	SYSTEM	(\$65,509.30)	
				15	Dec 1, 2020	SYSTEM	\$65,509.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user evansk overridding Payment Estimate Exception 22 on the current Payment Estimate.
				16	Dec 15, 2020	SYSTEM	(\$65,509.30)	
				16	Dec 15, 2020	SYSTEM	\$65,509.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user evansk overridding Payment Estimate Exception 22 on the current Payment Estimate.
				17	Jan 4, 2021	SYSTEM	(\$65,509.30)	
				17	Jan 4, 2021	SYSTEM	\$65,509.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.
				18	Jan 15, 2021	SYSTEM	(\$65,509.30)	
				18	Jan 15, 2021	SYSTEM	\$65,509.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total						\$0.00	
5002	CURB BLOCKOUT	Material		12	Oct 16, 2020	SYSTEM	(\$48,175.00)	
				12	Oct 16, 2020	SYSTEM	\$48,175.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user evansk overridding Payment Estimate Exception 24 on the current Payment Estimate.
				13	Nov 2, 2020	SYSTEM	(\$48,175.00)	
				13	Nov 2,	SYSTEM	\$48,175.00	This adjustment offsets the original system-generated Overrun Payment



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5002	CURB BLOCKOUT	Material			2020			Estimate Item Adjustment (0008) due to user evansk overridding Payment Estimate Exception 6 on the current Payment Estimate.
				14	Nov 16, 2020	SYSTEM	(\$48,175.00)	
				14	Nov 16, 2020	SYSTEM	\$48,175.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 10 on the current Payment Estimate.
				15	Dec 1, 2020	SYSTEM	(\$48,175.00)	
				15	Dec 1, 2020	SYSTEM	\$48,175.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.
				16	Dec 15, 2020	SYSTEM	(\$48,175.00)	
				16	Dec 15, 2020	SYSTEM	\$48,175.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate.
				17	Jan 4, 2021	SYSTEM	(\$48,175.00)	
				17	Jan 4, 2021	SYSTEM	\$48,175.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 19 on the current Payment Estimate.
				18	Jan 15, 2021	SYSTEM	(\$48,175.00)	
				18	Jan 15, 2021	SYSTEM	\$48,175.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	
5003	CURB BLOCKOUT	Material		12	Oct 16, 2020	SYSTEM	(\$46,765.00)	
				12	Oct 16, 2020	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user evansk overridding Payment Estimate Exception 15 on the current Payment Estimate.
				13	Nov 2, 2020	SYSTEM	(\$46,765.00)	
				13	Nov 2, 2020	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user evansk overridding Payment Estimate Exception 15 on the current Payment Estimate.
				14	Nov 16, 2020	SYSTEM	(\$46,765.00)	
				14	Nov 16, 2020	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 23 on the current Payment Estimate.
				15	Dec 1, 2020	SYSTEM	(\$46,765.00)	
				15	Dec 1, 2020	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 15 on the current Payment Estimate.
				16	Dec 15, 2020	SYSTEM	(\$46,765.00)	
				16	Dec 15, 2020	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 15 on the current Payment Estimate.
				17	Jan 4, 2021	SYSTEM	(\$46,765.00)	
				17	Jan 4, 2021	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment Estimate Exception 8 on the current Payment Estimate.
				18	Jan 15, 2021	SYSTEM	(\$46,765.00)	
				18	Jan 15, 2021	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user evansk overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5003 ·	Total						\$0.00	
5004	CURB BLOCKOUT	Material		12	Oct 16, 2020	SYSTEM	(\$46,765.00)	
				12	Oct 16, 2020	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user evansk overridding Payment Estimate Exception 6 on the current Payment Estimate.
				13	Nov 2, 2020	SYSTEM	(\$46,765.00)	
				13	Nov 2, 2020	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user evansk overridding Payment Estimate Exception 33 on the current Payment Estimate.
				14	Nov 16, 2020	SYSTEM	(\$46,765.00)	
				14	Nov 16, 2020	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user evansk overridding Payment Estimate Exception 17 on the current Payment Estimate.
				15	Dec 1, 2020	SYSTEM	(\$46,765.00)	
				15	Dec 1, 2020	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 9 on the current Payment Estimate.
				16	Dec 15, 2020	SYSTEM	(\$46,765.00)	
				16	Dec 15, 2020	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 9 on the current Payment Estimate.
				17	Jan 4, 2021	SYSTEM	(\$46,765.00)	
				17	Jan 4, 2021	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 14 on the current Payment Estimate.
				18	Jan 15, 2021	SYSTEM	(\$46,765.00)	
				18	Jan 15, 2021	SYSTEM	\$46,765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5004 ·	Total						\$0.00	
Overa	III - Total						\$37,941.82	