

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 4, 2021

Progress Estimate Number	Contract ID	200320-H04	Pay Period Start	December 16, 2020	Original Contract Amour	nt \$4,898,461.04
9	Prime Contractor	Capital Paving & Construction, LLC	Pay Period En	<b>d</b> January 1, 2021	Net Change Order Amount Current Contract Amoun	\$30,171.88 <b>t</b> \$4,928,632.92

Approval Date					By User				
January 4, 2021		Generated and Approved (and should be considered Draft) at the Project Office Level by							
January 4, 2021		Reviewed and Appr	oved (and should be considered Dra	aft) at the Resident Engineer Level by	wilkem1				
January 5, 2021			Reviewed and Approved at the Cer	tral Office Controllers Office Level by	greggd1				
Original Comp	letion Date	etion Date							
November	er 1, 2020 November 25, 2020 95.31%								

No Milestones Exist for Contract

Contract Total Pay	For Estimate No. 9			
		This Estimate	Previous	To Date
200320-H04				
	Total Posted Items Pay	\$0.00	\$4,697,718.52	\$4,697,718.52
	Gross Item Adjustments	\$0.00	(\$204,306.67)	(\$204,306.67)
	Incentive	\$0.00	\$89,983.32	\$89,983.32
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$4,583,395.17	\$4,583,395.17
<b>Contract Total Pay</b>	able This Estimate:	\$0.00		

#### **Items Paid This Estimate Period**

### No Data Available Contract Adjustments This Estimate

		ments This Estimate						
roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
P3520	0030	MISC.	Material			-3,091.6	\$38.68	(\$119,583.09
	0030	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	3,091.6	\$38.68	\$119,583.09
	0040	GRAVEL (A) OR CRUSHED STONE (B)	Material			-134	\$27.53	(\$3,689.02
	0040	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.	134	\$27.53	\$3,689.02
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material			-26,478.8	\$56.48	(\$1,495,522.62
	0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.	26,478.8	\$56.48	\$1,495,522.62
	0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material			-36,605.1	\$64.69	(\$2,367,983.92
	0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.	36,605.1	\$64.69	\$2,367,983.92
	0090	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',500.00000 - 500.00000, 'is	2	\$500.00	\$1,000.00

Revision 4/1/2020 Page 1 of 17



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 4, 2021

Progress Estimate Number 9 Contract ID 200320-H04 Prime Contractor LLC Pay Period December 16, Start 2020 Original Contract Amount \$4,898,461.04 Pay Period End January 1, 2021 Net Change Order Amount \$4,998,461.04 Pay Period End January 1, 2021 Current Contract Amount \$4,998,632.92

						ourrent com	iluot Allioulit	ψ4,320,032.32
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3520					applied (if non-zero).			
	0090	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Other Item Adjustment	Overrun Re- adjustment	Removing the \$1000 automatic overrun adjustment. Change Order 0003 has been submitted and approved which included overrun adjustment for 2 additional TMAs.			(\$1,000.00)
	0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-414	\$20.00	(\$8,280.00)
	0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.	414	\$20.00	\$8,280.00
	0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material			-390	\$20.00	(\$7,800.00)
	0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.	390	\$20.00	\$7,800.00
	0190	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-13	\$280.00	(\$3,640.00)
	0190	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.	13	\$280.00	\$3,640.00
	0230	MISC.	Material			-2	\$2,000.00	(\$4,000.00)
	0230	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 10 on the current Payment Estimate.	2	\$2,000.00	\$4,000.00
	5001	ADVANCED WARNING RAIL SYSTEM	Material			-2	\$35.00	(\$70.00)
	5001	ADVANCED WARNING RAIL SYSTEM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.	2	\$35.00	\$70.00
Total								\$0.00

Revision 4/1/2020 Page 2 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9P3520	FAF 412-1(17)	Resurface	412	DUNKLIN	from end of divided highw	vay to Route VV	
Totals by	Job Numbe	rs					
J9P3520					This Estimate	Previous	To Date
	Poste	d Item Pay			\$0.00	\$4,697,718.52	\$4,697,718.52
		d Item Pay Item Adjustme	ents		\$0.00 \$0.00	\$4,697,718.52 (\$204,306.67)	\$4,697,718.52 (\$204,306.67)
				Item Pay			
		Item Adjustme		Item Pay	\$0.00	(\$204,306.67) <b>\$4,493,411.85</b>	(\$204,306.67) <b>\$4,493,411.85</b>
	Gross	Item Adjustme		Item Pay	\$0.00 <b>\$0.00</b>	(\$204,306.67)	(\$204,306.67)
	Gross Incent Disinc	Item Adjustme	Gross	Item Pay	\$0.00 <b>\$0.00</b> \$0.00	(\$204,306.67) <b>\$4,493,411.85</b> \$89,983.32	(\$204,306.67) <b>\$4,493,411.85</b> \$89,983.32

Revision 4/1/2020 Page 3 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 3049910, Project Item Line Number 0030, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Awaiting QA results to be entered.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 3105002, Project Item Line Number 0040, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Awaiting QA results to be entered.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 4011209, Project Item Line Number 0050, Material Set 401120996, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	Awaiting QA results to be entered.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 4030103, Project Item Line Number 0060, Material Set 403010396, Material 0403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	Awaiting QA results to be entered.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 4071005, Project Item Line Number 0070, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Awaiting Certifications to be entered.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 6161008, Project Item Line Number 5001, Material Set 616100896, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Awaiting Certifications to be entered.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 6200015, Project Item Line Number 0170, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Awaiting Certifications to be entered.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 6200018, Project Item Line Number 0180, Material Set 620001896, Material 1048PMPFYL - Performed Thermoplastic Marking Tape YL, Acceptance Action Generic 1048PMPFYL is insufficient.	Awaiting Certifications to be entered.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 6200021, Project Item Line Number 0190, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Awaiting Certifications to be entered.	turnep3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3520, Item 6209902, Project Item Line Number 0230, Material Set 6209902, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Awaiting Certifications to be entered.	turnep3	Overridden

Revision 4/1/2020 Page 4 of 17



## Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00320-H04	J9P3520	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$16,064.79	\$16,064.79
		0001	0020	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	4,918.00	0.00	4,918.00	LF	3,942.50	\$14.00	\$55,195.00
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	4,090.90	0.00	4,090.90	TONS	3,091.60	\$38.68	\$119,583.09
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	134.00	0.00	134.00	TONS	134.00	\$27.53	\$3,689.02
		0001	0050	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	26,084.80	394.00	26,478.80	TONS	26,478.80	\$56.48	\$1,495,522.62
		0001	0060	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	37,345.50	0.00	37,345.50	TONS	36,605.10	\$64.69	\$2,367,983.92
		0001	0070	4071005	TACK COAT	50,915.00	191.00	51,106.00	GAL	51,106.00	\$2.00	\$102,212.00
		0001	0080	4134000	BITUMINOUS FOG SEAL	18,233.00	0.00	18,233.00	GAL	6,642.00	\$2.34	\$15,542.28
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	2.00	4.00	EA	4.00	\$500.00	\$2,000.00
		0001	0100	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	307.20	26.10	333.30	TONS	333.30	\$172.35	\$57,444.26
		0001	0110	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	1,806.10	105.50	1,911.60	SQYD	1,911.60	\$13.35	\$25,519.86
		0001	0120	6161005	CONSTRUCTION SIGNS	3,547.00	0.00	3,547.00	SQFT	2,183.00	\$5.00	\$10,915.00
		0001	0130	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	4.00	\$20.00	\$80.00
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	110.00	0.00	110.00	EA	110.00	\$20.00	\$2,200.00
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	0160	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$118,630.47	\$118,630.47
		0001	0170	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	429.00	0.00	429.00	LF	414.00	\$20.00	\$8,280.00
		0001	0180	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	425.00	0.00	425.00	LF	390.00	\$20.00	\$7,800.00
		0001	0190	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	11.00	2.00	13.00	EA	13.00	\$280.00	\$3,640.00
		0001	0200	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	63,365.00	0.00	63,365.00	LF	0.00	\$0.15	\$0.00
		0001	0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	229,952.00	0.00	229,952.00	LF	0.00	\$0.20	\$0.00
		0001	0220	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0001	0230	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0240	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	27,934.00	0.00	27,934.00	SQYD	26,692.00	\$1.23	\$32,831.16
		0001	0250	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	9,730.00	0.00	9,730.00	SQYD	8,146.00	\$5.36	\$43,662.56
		0001	0260	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,914.00	0.00	1,914.00	STA	1,914.00	\$15.50	\$29,667.00
		0001	0270	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	941.00	0.00	941.00	STA	941.00	\$15.50	\$14,585.50
		0010	0280	6061060	MGS GUARDRAIL	2,088.00	0.00	2,088.00	LF	1,550.00	\$24.00	\$37,200.00
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	20.00	0.00	20.00	EA	19.00	\$3,050.00	\$57,950.00
		0010	0300	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	26.00	0.00	26.00	EA	21.00	\$2,850.00	\$59,850.00
		0001	5001	6161008	ADVANCED WARNING RAIL SYSTEM	0.00	2.00	2.00	EA	2.00	\$35.00	\$70.00
	Project J	9P3520 - To	otal Value	Posted to D	Date as of Report Generated Date							\$4,697,718.53
320-H04 Ove	rall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$4,697,718.53

Page 5 of 17 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

The info	<u>rmation</u>	below this I	line are details for C	<u>onstruction Signs (if applicable</u>	<u>).</u>							
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J9P3520	0120	October 23, 2020	816	GO20-2 48x24 8.00 END ROAD WORK		.833	28' L of C/L		8			
				CONST-7-72 72x36 18.00 RATE OUR WORK ZONE		.856	28' R of C/L		18			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		.97	28' R of C/L		10			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		1.033	28' R of C/L		12			
				WO8-12 48x48 16.00 NO CENTER LINE		1.118	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		1.284	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		1.82	28' L of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		10.581	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		10.731	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		10.774	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		11.513	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		11.614	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		11.731	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		11.791	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		12.649	28' L of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		12.798	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		13.654	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		13.694	28' L of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		19.431	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		2.252	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		2.753	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		2.816	28' L of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		20.217	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		20.262	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		20.453	28' R of C/L		16			
				WO8-11 48x48 16.00 UNEVEN LANES		20.677	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		20.751	28' L of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		21.846	28' L of C/L		16			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		21.929	28' L of C'L		12			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		21.971	28' L of C/L		10			
				CONST-7-72 72x36 18.00 RATE OUR WORK ZONE		22.052	28' L of C/L		18			
				GO20-2 48x24 8.00 END ROAD WORK		22.052	28' R of C/L		8			

Revision 4/1/2020 Page 6 of 17



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date		Sign II	nformation	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post																	
J9P3520	0120	October 23, 2020	816	WO8-12 LINE	48x48	16.00 NO CENTER		3.00	28' R of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		3.047	28' R of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		3.317	28' L of C/L		16																				
				WO8-12 LINE	48x48	16.00 NO CENTER		4.355	28' L of C/L		16																				
				WO8-12 LINE	48x48	16.00 NO CENTER		4.477	28' R of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		4.522	28' R of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		5.138	28' L of C/L		16																				
				WO8-12 LINE	48x48	16.00 NO CENTER		5.178	28' L of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		5.474	28' R of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		5.938	28' L of C/L		16																				
				WO8-12 LINE	48x48	16.00 NO CENTER		6.421	28' R of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		6.465	28' R of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		6.868	28' L of C/L		16																				
				WO8-12 LINE	48x48	16.00 NO CENTER		6.986	28' L of C/L		16																				
						WO8-12 LINE	48x48	16.00 NO CENTER		7.591	28' L of C/L		16																		
				WO8-11 LANES	48x48	16.00 UNEVEN		8.124	28' R of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		8.535	28' L of C/L		16																				
																					WO8-12 LINE	48x48	16.00 NO CENTER		8.792	28' R of C/L		16			
						WO8-11 LANES	48x48	16.00 UNEVEN		8.838	28' R of C/L		16																		
				WO8-12 LINE	48x48	16.00 NO CENTER		9.598	28' L of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		9.783	28' R of C/L		16																				
		November 11, 2020	128	WO8-11 LANES	48x48	16.00 UNEVEN		16.041	25' L of C/L		16																				
				WO8-12 LINE	48x48	16.00 NO CENTER		16.152	25' L of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		16.335	25' R of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		18.173	25' L of C/L		16																				
				WO8-12 LINE	48x48	16.00 NO CENTER		18.263	25' L of C/L		16																				
				WO8-12 LINE	48x48	16.00 NO CENTER		18.399	25' R of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		18.442	25' R of C/L		16																				
				WO8-11 LANES	48x48	16.00 UNEVEN		19.286	25' L of C/L		16																				
		November 12, 2020	80	WO8-12 LINE	48x48	16.00 NO CENTER		14.037	28' R of C/L		16																				
				WO8-12 LINE	48x48	16.00 NO CENTER		15.064	28' L of C/L		16																				
				WO8-12	18×18	16.00 NO CENTER		16.292	28' R of		16																				

Revision 4/1/2020 Page 7 of 17



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J9P3520	0120	November 12, 2020	80	WO8-12 48x48 16.00 NO CENTER LINE		20.829	28' R of C/L		16			
				WO8-12 48x48 16.00 NO CENTER LINE		7.117	28' R of C/L		16			
	0120 - To	tal										

Revision 4/1/2020 Page 8 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	MISC. MODIFIED SHAPING SLOPES, CLASS III	Material		6	Nov 16, 2020	SYSTEM	(\$10,080.00)	
				6	Nov 16, 2020	SYSTEM	\$10,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$54,635.00)	
				7	Dec 3, 2020	SYSTEM	\$54,635.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0020 -							\$0.00	
0030	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		7	Dec 3, 2020	SYSTEM	(\$119,582.31)	
				7	Dec 3, 2020	SYSTEM	\$119,582.31	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$119,583.09)	
				8	Dec 16, 2020	SYSTEM	\$119,583.09	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$119,583.09)	
				9	Jan 4, 2021	SYSTEM	\$119,583.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
							Ψ0.00	
	Material - Total						\$0.00	
0030 -								
<b>0030</b> -		Material		7	Dec 3, 2020	SYSTEM	\$0.00	
	Total	Material		7		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	Total	Material			2020 Dec 3,		\$0.00 \$0.00 (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current
	Total	Material		7	2020 Dec 3, 2020 Dec 16,	SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current
	Total	Material		7	Dec 3, 2020  Dec 16, 2020  Dec 16,	SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current
	Total	Material		7 8 8	Dec 3, 2020  Dec 16, 2020  Dec 16, 2020  Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current
	Total  GRAVEL (A) OR CRUSHED STONE (B)	Material	- Total	7 8 8 9	2020 Dec 3, 2020  Dec 16, 2020  Jan 4, 2021  Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) (\$3,689.02)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	GRAVEL (A) OR CRUSHED STONE (B)	Material		7 8 8 9	2020 Dec 3, 2020  Dec 16, 2020  Jan 4, 2021  Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	Total  GRAVEL (A) OR CRUSHED STONE (B)  Material - Total  Total			7 8 8 9 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 \$3,689.02 \$0.00 \$0.00	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	GRAVEL (A) OR CRUSHED STONE (B)	Material Material		7 8 8 9 9	2020 Dec 3, 2020  Dec 16, 2020  Jan 4, 2021  Jan 4,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	GRAVEL (A) OR CRUSHED STONE (B)  Material - Total  Total  BITUMINOUS PAVEMENT MIXTURE			7 8 8 9 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 \$3,689.02 \$0.00 \$0.00	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current
0040	GRAVEL (A) OR CRUSHED STONE (B)  Material - Total  Total  BITUMINOUS PAVEMENT MIXTURE			7 8 8 9 9	2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Jan 4, 2021 Jan 4, 2021 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,689.02) \$3,689.02 (\$3,689.02) \$3,689.02 (\$3,689.02) \$0.00 \$0.00 \$0.00 (\$734,432.03)	Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 1 on the current

Revision 4/1/2020 Page 9 of 17



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
50	BITUMINOUS PAVEMENT MIXTURE	Material						Payment Estimate.
	PG64-22, (BP-1)			5	Nov 2, 2020	SYSTEM	(\$734,432.03)	
				5	Nov 2, 2020	SYSTEM	\$734,432.03	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$1,495,517.54)	
				6	Nov 16, 2020	SYSTEM	\$1,495,517.54	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$1,495,517.54)	
				7	Dec 3, 2020	SYSTEM	\$1,495,517.54	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$1,495,522.62)	
				8	Dec 16, 2020	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$1,495,522.62)	
				9	Jan 4, 2021	SYSTEM	\$1,495,522.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
Ma	aterial - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item AC Adjustment	ACAD	2	Sep 16, 2020	turnep3	(\$9,731.85)	AC Index Price Adjustment: -\$9,731.85
				3	Oct 1, 2020	turnep3	(\$20,988.69)	AC Index Price Adjustment: -\$20,988.69
				6		turnep3	(\$20,988.69)	AC Index Price Adjustment: -\$20,988.69  Asphalt Index Price Adjustment: -\$34,193.60
			ACAD - Tota	6	2020 Nov 16,			
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)		ACAD - Tota	6 al	2020 Nov 16,		(\$34,193.60)	Asphalt Index Price Adjustment: -\$34,193.60
	PG64-22, (BP-1)			6 al 8	2020 Nov 16, 2020 Dec 16,	turnep3	(\$34,193.60) (\$64,914.14)	Asphalt Index Price Adjustment: -\$34,193.60
Ot	PG64-22, (BP-1)		FUEL - Tota	6 al 8	2020 Nov 16, 2020 Dec 16, 2020	turnep3	(\$34,193.60) (\$64,914.14) \$0.02 \$0.02 (\$64,914.12)	Asphalt Index Price Adjustment: -\$34,193.60  Correction of Fuel Price adjustment due to rounding BP-1 totals.
Ot	PG64-22, (BP-1)	Overrun	FUEL	6 al 8	2020 Nov 16, 2020 Dec 16,	turnep3 turnep3	(\$34,193.60) (\$64,914.14) \$0.02	Asphalt Index Price Adjustment: -\$34,193.60  Correction of Fuel Price adjustment due to rounding BP-1 totals  Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Ot	PG64-22, (BP-1) ther Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Overrun	FUEL - Tota	6 al 8	2020 Nov 16, 2020 Dec 16, 2020	turnep3	(\$34,193.60) (\$64,914.14) \$0.02 \$0.02 (\$64,914.12)	Asphalt Index Price Adjustment: -\$34,193.60  Correction of Fuel Price adjustment due to rounding BP-1 totals  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun
Ot	PG64-22, (BP-1) ther Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Overrun	FUEL - Tota	6 al 8	2020 Nov 16, 2020 Dec 16, 2020 Nov 16, 2020 Nov 16,	turnep3 turnep3	(\$34,193.60) (\$64,914.14) \$0.02 \$0.02 (\$64,914.12) (\$21,855.70)	Asphalt Index Price Adjustment: -\$34,193.60  Correction of Fuel Price adjustment due to rounding BP-1 totals.  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment
Ot	PG64-22, (BP-1) ther Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Overrun	FUEL - Tota	6 8 II	2020 Nov 16, 2020 Dec 16, 2020 Nov 16, 2020 Nov 16, 2020 Dec 3,	turnep3 turnep3 SYSTEM	(\$34,193.60) (\$64,914.14) \$0.02 \$0.02 (\$64,914.12) (\$21,855.70) \$21,855.70	Asphalt Index Price Adjustment: -\$34,193.60  Correction of Fuel Price adjustment due to rounding BP-1 totals.  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 6 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun
Ot	PG64-22, (BP-1) ther Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Overrun	FUEL - Tota	6 8 I 6 6 7	2020 Nov 16, 2020 Dec 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3,	turnep3 turnep3 SYSTEM SYSTEM	(\$34,193.60) (\$64,914.14) \$0.02 \$0.02 (\$64,914.12) (\$21,855.70) \$21,855.70	Asphalt Index Price Adjustment: -\$34,193.60  Correction of Fuel Price adjustment due to rounding BP-1 totals.  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 6 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment
Ot	PG64-22, (BP-1) ther Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Overrun	FUEL - Tota	6 8 I 6 6 7 7 7	2020 Nov 16, 2020 Dec 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3, 2020	turnep3 turnep3 SYSTEM SYSTEM SYSTEM	(\$34,193.60) (\$64,914.14) \$0.02 \$0.02 (\$64,914.12) (\$21,855.70) \$21,855.70 (\$21,881.39)	Asphalt Index Price Adjustment: -\$34,193.60  Correction of Fuel Price adjustment due to rounding BP-1 totals.  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 6 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 11 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous
Ot	PG64-22, (BP-1) ther Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Overrun	FUEL - Tota	6 8 6 7 7 8 8	2020 Nov 16, 2020  Dec 16, 2020  Nov 16, 2020  Dec 3, 2020  Dec 3, 2020  Dec 16, 2020  Dec 16, 2020	turnep3 turnep3 SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$34,193.60) (\$64,914.14) \$0.02 \$0.02 (\$64,914.12) (\$21,855.70) \$21,855.70 (\$21,881.39) \$21,881.39	Asphalt Index Price Adjustment: -\$34,193.60  Correction of Fuel Price adjustment due to rounding BP-1 totals.  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 6 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 11 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun
Ot	PG64-22, (BP-1) ther Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Overrun	FUEL - Tota	6 8 8 8 8	2020 Nov 16, 2020 Dec 16, 2020  Nov 16, 2020  Nov 16, 2020  Dec 3, 2020  Dec 3, 2020  Dec 16, 2020  Dec 16, 2020  Dec 16, 2020	turnep3  turnep3  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM	(\$34,193.60) (\$64,914.14) \$0.02 \$0.02 (\$64,914.12) (\$21,855.70) \$21,855.70 (\$21,881.39) \$21,881.39 (\$21,881.39)	Asphalt Index Price Adjustment: -\$34,193.60  Correction of Fuel Price adjustment due to rounding BP-1 totals.  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 6 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 11 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.
Ot	PG64-22, (BP-1) ther Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE	Overrun	FUEL - Tota	6 8 8 8 8 8	2020 Nov 16, 2020  Dec 16, 2020  Nov 16, 2020  Nov 16, 2020  Dec 3, 2020  Dec 3, 2020  Dec 16, 2020  Dec 16, 2020  Dec 16, 2020	turnep3 turnep3 system system system system system system system system	(\$34,193.60) (\$64,914.14) \$0.02 \$0.02 (\$64,914.12) (\$21,855.70) \$21,855.70 (\$21,881.39) \$21,881.39 (\$21,881.39) (\$5.07)	Asphalt Index Price Adjustment: -\$34,193.60  Correction of Fuel Price adjustment due to rounding BP-1 totals.  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 6 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 11 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '-0.93078' is applied (if non-zero).  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Payment Estimate Item Adjustment (0003) overridding Payment

Revision 4/1/2020 Page 10 of 17



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Type	Adjustment Type	Number	Date	Ву		
0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Price		2	Sep 16, 2020	SYSTEM	(\$3,555.78)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				3	Oct 1, 2020	SYSTEM	(\$7,668.76)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				6	Nov 16, 2020	SYSTEM	(\$13,421.40)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Dec 16, 2020	SYSTEM	(\$0.02)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$24,645.96)	
	Price - Total						(\$24,645.96)	
0050 -	Total						(\$89,560.08)	
0060	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		4	Oct 16, 2020	SYSTEM	(\$831,265.85)	
				4	Oct 16, 2020	SYSTEM	\$831,265.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Nov 2, 2020	SYSTEM	(\$2,367,981.98)	
				5	Nov 2, 2020	SYSTEM	\$2,367,981.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$2,367,981.98)	
				6	Nov 16, 2020	SYSTEM	\$2,367,981.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$2,367,981.98)	
				7	Dec 3, 2020	SYSTEM	\$2,367,981.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$2,367,983.92)	
				8	Dec 16, 2020	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$2,367,983.92)	
				9	Jan 4, 2021	SYSTEM	\$2,367,983.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	4	Oct 16, 2020	turnep3	(\$28,623.35)	AC Index Price Adjustment: -\$28623.35
	10-22 (OI 1200 MIX)	, ajasanont			2020			Calculated by hand using appropriate indexes. AC Index spreadsheet did not include index for October 2020, but value was given in index list on MoDOT website.
				5	Nov 2, 2020	turnep3	(\$52,914.44)	AC Index Price Adjustment: -\$52914.44
			ACAD - Tot	al			(\$81,537.79)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)		FUEL	5	Nov 2, 2020	turnep3	(\$25,237.40)	Fuel Price Adjustment: -\$25237.40
				6	Nov 16, 2020	turnep3	\$25,237.40	Correction for double adjustment of Fuel Price Adjustment on Estimate 0005: \$25,237.40
				8	Dec 16, 2020	turnep3	\$0.01	Correction of Fuel Price adjustment due to rounding SP125 totals.
			FUEL - Tota	al			\$0.01	
	Other Item Adjustment - Total						(\$81,537.78)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Price		4	Oct 16, 2020	SYSTEM	(\$13,651.84)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL

Revision 4/1/2020 Page 11 of 17



Table									
Prior - Total	Line	Description	Adjustment Type		Est. Number	Created Date	Created By	Amount	Remarks
Price - Total   Price - Total - Price - Tota	0060		Price		5		SYSTEM	(\$25,237.40)	
Price - Total					8		SYSTEM	(\$0.01)	
TACK COAT   Material				- Total				(\$38,889.25)	
Material   TACK COAT   Material   Facility   Facil		Price - Total						(\$38,889.25)	
Material   TACK COAT   Material	0060 -	- Total						(\$120,427.03)	
Payment Estimate tens Adjustment (1001) due to user turneps overriding Payment Estimate Exception 1 on the current Payment Estimate (1001) due to user turneps overriding Payment Estimate (1001) due to user turneps (	0070	TACK COAT	Material		1		SYSTEM		
					1		SYSTEM	\$78.00	Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 1 on the current
2020   Payment Estimate Exception 1 on the current pay overricinal payment estimate Exception 1 on the current payment Estimate Exception 2 on the current payment Estimate Exception 3 on the current payment Estimate Exception 7 to the current payment Estimate Exception 7 to the current payment Estimate Exception 1 on the current payment Estimate Exception 1 on the current payment Estimate Exception 1 on the current payment Estimate Exception 8 on the current payment Estimate Exception 8 on the current payment Estimate Exception 8 on the curre					2		SYSTEM	(\$9,036.00)	
					2		SYSTEM	\$9,036.00	Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 1 on the current
Naterial - Total					3		SYSTEM	(\$22,768.00)	
Material - Total					3		SYSTEM	\$22,768.00	Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 2 on the current
TACK COAT				- Total				\$0.00	
		Material - Total						\$0.00	
Payment Estimate Item Adjustment (0016) due to user turnep3 overriding Payment Estimate Item Adjustment (0016) due to user turnep3 overriding Payment Estimate.  7 Dec 3, SYSTEM (\$382.00) Averaged Price Adjustment from this item on all previous payment estimates of 0.00000' is applied (if non-zero).  7 Dec 3, SYSTEM \$382.00 This adjustment offsets the original system-generated Overrun Payment Estimate Estimate Exception 12 on the current Payment Estimate Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 12 on the current Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 11 on the current Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 11 on the current Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Item Adjustment for overrun of 2 TMAS.  Total  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment for overrun of 2 TMAS.		TACK COAT	Overrun	Overrun	6		SYSTEM	(\$382.00)	
Payment estimate of 0.00000 is applied (if non-zero).					6		SYSTEM	\$382.00	Payment Estimate Item Adjustment (0016) due to user turnep3 overridding Payment Estimate Exception 7 on the current
Payment Estimate Exception 12 on the current Payment Estimate Srd 0.00000' is applied (fin on-zero).    Payment Estimate Item Adjustment (0009) due to user turneg apyment Estimate Exception 11 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 13 on the current Payment Estimate Exception 14 on the current Payment Estimate Exception 15 on the Current Payment Estimate Exception 15 on the current Payment Estimate Exception 16 on the current Payment Estimate Exception 17 on the current Payment Estimate Exception 18 on the current Payment Estimate Exception 18 on the current Payment Estimate Exception 19 on the					7		SYSTEM	(\$382.00)	
2020   payment estimates of '0,00000' is applied (if non-zero).					7		SYSTEM	\$382.00	Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 12 on the current
2020   Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 11 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 13 on the current Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate Item Adjustment Footable Transport In Payment Item In Payment I					8		SYSTEM	(\$382.00)	
Overrun - Total   Sum					8		SYSTEM	\$382.00	Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 11 on the current
DOTO - Total   SO.00				Overrun - T	otal			\$0.00	
BITUMINOUS FOG SEAL Material  7 Dec 3, 2020  7 Dec 3, 2020  8 YSTEM (\$15,542.28)  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.  - Total  So.00  Material - Total  \$0.00  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  ATTENUATOR (TMA)  Adjustment  OADJ  8 Dec 16, 2020  9 Jan 4, 2021  turnep3 (\$1,000.00)  Removal of previous line item adjustment for overrun of 2 TMAs. Change Order has been submitted and is awaiting approval.  Removing the \$1000 automatic overrun adjustment. Change Order 0003 has been submitted and approved which included overrun adjustment for 2 additional TMAs.		Overrun - Total						\$0.00	
BITUMINOUS FOG SEAL Material  7 Dec 3, 2020  7 Dec 3, 2020  8 YSTEM (\$15,542.28)  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.  - Total  So.00  Material - Total  \$0.00  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  ATTENUATOR (TMA)  Adjustment  OADJ  8 Dec 16, 2020  9 Jan 4, 2021  turnep3 (\$1,000.00)  Removal of previous line item adjustment for overrun of 2 TMAs. Change Order has been submitted and is awaiting approval.  Removing the \$1000 automatic overrun adjustment. Change Order 0003 has been submitted and approved which included overrun adjustment for 2 additional TMAs.	0070 -	- Total						\$0.00	
Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.  **Total**  **So.00**  **Material - Total**  **So.00**  **Material - Total**  **So.00**  **TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)*  ATTENUATOR (TMA)*  Adjustment*  OADJ 8 Dec 16, 2020 (\$1,000.00) Removal of previous line item adjustment for overrun of 2 TMAs. Change Order has been submitted and is awaiting approval.  9 Jan 4, 2021 (\$1,000.00) Removing the \$1000 automatic overrun adjustment. Change Order 0003 has been submitted and approved which included overrun adjustment for 2 additional TMAs.			Material		7		SYSTEM		
Material - Total  0080 - Total  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  Material - Total  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  Material - Total  So.00  (\$1,000.00) Removal of previous line item adjustment for overrun of 2 TMAs. Change Order has been submitted and is awaiting approval.  9 Jan 4, 2021  (\$1,000.00) Removing the \$1000 automatic overrun adjustment. Change Order 0003 has been submitted and approved which included overrun adjustment for 2 additional TMAs.					7		SYSTEM	\$15,542.28	Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 8 on the current
TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  OADJ 8 Dec 16, 2020				- Total				\$0.00	
TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  Other Item Adjustment  OADJ 8 Dec 16, 2020 (\$1,000.00) Removal of previous line item adjustment for overrun of 2 TMAs. Change Order has been submitted and is awaiting approval.  9 Jan 4, 2021 (\$1,000.00) Removing the \$1000 automatic overrun adjustment. Change Order 0003 has been submitted and approved which included overrun adjustment for 2 additional TMAs.		Material - Total						\$0.00	
TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  Other Item Adjustment  OADJ 8 Dec 16, 2020 (\$1,000.00) Removal of previous line item adjustment for overrun of 2 TMAs. Change Order has been submitted and is awaiting approval.  9 Jan 4, 2021 (\$1,000.00) Removing the \$1000 automatic overrun adjustment. Change Order 0003 has been submitted and approved which included overrun adjustment for 2 additional TMAs.	0080 -	- Total						\$0.00	
2021 Order 0003 has been submitted and approved which included overrun adjustment for 2 additional TMAs.	0090			OADJ	8		turnep3		
QAD I - Total (\$2,000,00)					9		turnep3	(\$1,000.00)	Order 0003 has been submitted and approved which included
(\$2,000.00)				OADJ - Tota	al			(\$2,000.00)	
Other Item Adjustment - Total (\$2,000.00)		Other Item Adjustment - Total						(\$2,000.00)	
TRUCK OF TRAILER MOUNTER COLUMN 7 DUG OVERTIME (64.000.00)		TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Overrun	Overrun	7	Dec 3, 2020	SYSTEM	(\$1,000.00)	
TRUCK OR TRAILER MOUNTED   Overrun   Overrun   / Dec 3,   SYSTEM   (\$1.000.00)								(, , , , , , , , , , , , )	

Revision 4/1/2020 Page 12 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0090	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Overrun	Overrun	7	Dec 3, 2020	turnep3	\$1,000.00	Due to additional TMAs required for Striping and Rumble Strips operations, \$1000 was adjusted for the 2 additional TMAs (\$500 per EA) until a Change Order correcting the quantity is submitted.
				9	Jan 4, 2021	SYSTEM	\$1,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',500.00000 - 500.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$1,000.00	
	Overrun - Total						\$1,000.00	
0090 -	Total						(\$1,000.00)	
0100	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Material		1	Sep 2, 2020	SYSTEM	(\$6,206.32)	
				1	Sep 2, 2020	SYSTEM	\$6,206.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				2	Sep 16, 2020	SYSTEM	(\$6,206.32)	
				2	Sep 16, 2020	SYSTEM	\$6,206.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	Oct 1, 2020	SYSTEM	(\$6,206.32)	
				3	Oct 1, 2020	SYSTEM	\$6,206.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	Oct 16, 2020	SYSTEM	(\$57,433.91)	
				4	Oct 16, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Nov 2, 2020	SYSTEM	(\$57,433.91)	
				5	Nov 2, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$57,433.91)	
				6	Nov 16, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$57,433.91)	
				7	Dec 3, 2020	SYSTEM	\$57,433.91	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Other Item Adjustment	ACAD		Sep 2, 2020	turnep3	(\$80.21)	AC Price Index Adjustment: -\$80.21
				4	Oct 16, 2020	turnep3	(\$662.28)	AC Index Price Adjustment: -\$662.28  Calculated according to index appropriate for when the work was performed (9/9/2020).
			ACAD - Tota	al			(\$742.49)	
	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C		FUEL	1	Sep 2, 2020	turnep3	(\$34.67)	Asphalt Paving Production and Hauling Fuel Adjustment: - \$34.67
	PARTIAL DEPTH PAVEMENT REPAIR			4	Oct 16, 2020	turnep3	(\$256.65)	Fuel Price Adjustment: -\$256.65  Calculated according to index appropriate for when the work was performed (9/9/2020).
			FUEL - Tota				(\$291.32)	
	Other Item Adjustment Total		TOLL - TOLA				<u> </u>	
	Other Item Adjustment - Total						(\$1,033.81)	

Revision 4/1/2020 Page 13 of 17



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	•	Туре	Adjustment Type	Number	Date	Ву		
0100	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C	Overrun	Overrun	4	Oct 16, 2020	SYSTEM	(\$4,487.99)	
	PARTIAL DEPTH PAVEMENT REPAIR			4	Oct 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 4 on the current Payment Estimate.
				5	Nov 2, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Nov 2, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Nov 16, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				6	Nov 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 8 on the current Payment Estimate.
				7	Dec 3, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Dec 3, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 14 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$4,487.99)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Dec 16, 2020	SYSTEM	(\$10.34)	
				8	Dec 16, 2020	SYSTEM	\$10.34	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	\$4,487.99	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user turnep3 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
			Overruii - I	otai			φυ.υυ	
	Overrun - Total		Overruit - 1	otai			\$0.00	
0100 -	Overrun - Total Total		Overruit - 1	otai				
<b>0100</b> -		Overrun	Overrun		Sep 16, 2020	SYSTEM	\$0.00	
	Total  REMOVAL FOR CLASS C PARTIAL	Overrun				SYSTEM SYSTEM	\$0.00 (\$1,033.81)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	Total  REMOVAL FOR CLASS C PARTIAL	Overrun		2	2020 Sep 16,		\$0.00 (\$1,033.81) (\$1,408.43)	Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current
	Total  REMOVAL FOR CLASS C PARTIAL	Overrun		2	2020 Sep 16, 2020	SYSTEM	\$0.00 (\$1,033.81) (\$1,408.43) \$1,408.43	Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous
	Total  REMOVAL FOR CLASS C PARTIAL	Overrun		2 2 3	2020 Sep 16, 2020 Oct 1, 2020 Oct 1,	SYSTEM	\$0.00 (\$1,033.81) (\$1,408.43) \$1,408.43	Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 4 on the current
	Total  REMOVAL FOR CLASS C PARTIAL	Overrun		2 2 3 3 3	2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$1,033.81) (\$1,408.43) \$1,408.43 (\$1,408.43)	Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous
	Total  REMOVAL FOR CLASS C PARTIAL	Overrun		2 2 3 3 4	2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$1,033.81) (\$1,408.43) \$1,408.43 (\$1,408.43) \$1,408.43	Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 5 on the current
	Total  REMOVAL FOR CLASS C PARTIAL	Overrun		2 2 3 3 4 4 4	2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$1,033.81) (\$1,408.43) \$1,408.43 (\$1,408.43) \$1,408.43 (\$1,408.43)	Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous
	Total  REMOVAL FOR CLASS C PARTIAL	Overrun		2 2 3 3 4 4	2020 Sep 16, 2020 Oct 1, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$1,033.81) (\$1,408.43) \$1,408.43 (\$1,408.43) \$1,408.43 (\$1,408.43)	Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 6 on the current
	Total  REMOVAL FOR CLASS C PARTIAL	Overrun		2 2 3 3 4 4 5	2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, Nov 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$1,033.81) (\$1,408.43) \$1,408.43 (\$1,408.43) \$1,408.43 (\$1,408.43) \$1,408.43	Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.000000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous
	Total  REMOVAL FOR CLASS C PARTIAL	Overrun		2 2 3 3 4 4 5 5	2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020  Nov 2, 2020  Nov 16, 2020  Nov 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$1,033.81) (\$1,408.43) \$1,408.43 (\$1,408.43) \$1,408.43 (\$1,408.43) \$1,408.43 (\$1,408.43)	Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment Estimate.  Averaged Price Adjustment from this item on all previous payment Estimate.  Averaged Price Adjustment from this item on all previous payment Estimate.  Averaged Price Adjustment from this item on all previous payment Estimate.  Averaged Price Adjustment from this item on all previous payment Estimate.

Revision 4/1/2020 Page 14 of 17



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
		Турс	Туре	Number	Date	Бу		
0110	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Overrun	Overrun					overridding Payment Estimate Exception 15 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0110 -	Total						\$0.00	
0120	CONSTRUCTION SIGNS	Material		1	Sep 2, 2020	SYSTEM	(\$480.00)	
				1	Sep 2, 2020	SYSTEM	\$480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0120 -	Total						\$0.00	
0150	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR	Material		1	Sep 2, 2020	SYSTEM	(\$5,600.00)	
	FURNISHED, CONTRACTOR RETAINED			1	Sep 2, 2020	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0150 -	Total						\$0.00	
0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		7	Dec 3, 2020	SYSTEM	(\$7,120.00)	
				7	Dec 3, 2020	SYSTEM	\$7,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Dec 16, 2020	SYSTEM	(\$8,280.00)	
				8	Dec 16, 2020	SYSTEM	\$8,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$8,280.00)	
				9	Jan 4, 2021	SYSTEM	\$8,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0170 -	Total						\$0.00	
0180	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		8	Dec 16, 2020	SYSTEM	(\$7,800.00)	
				8	Dec 16, 2020	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$7,800.00)	
				9	Jan 4, 2021	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0180 -	Total						\$0.00	
0190	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT	Material		8	Dec 16, 2020	SYSTEM	(\$3,640.00)	
	ARROW			8	Dec 16, 2020	SYSTEM	\$3,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.

Revision 4/1/2020 Page 15 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0190	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT	Material		9	Jan 4, 2021	SYSTEM	(\$3,640.00)	
	ARROW			9	Jan 4, 2021	SYSTEM	\$3,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Overrun	Overrun		Dec 16, 2020	SYSTEM	(\$560.00)	
				8	Dec 16, 2020	SYSTEM	\$560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 14 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0190 -	· Total						\$0.00	
0230	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	Material		8	Dec 16, 2020	SYSTEM	(\$4,000.00)	
				8	Dec 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$4,000.00)	
				9	Jan 4, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user turnep3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0230 -	· Total						\$0.00	
0280	MGS GUARDRAIL	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$21,339.36	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Nov 16, 2020	SYSTEM	(\$3,690.56)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Dec 3, 2020	SYSTEM	(\$13,910.55)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$3,738.25	
	Construction Stockpile - Total						\$3,738.25	
0280 -							\$3,738.25	
0290	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$29,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Nov 16, 2020	SYSTEM	(\$3,244.44)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total	7	Dec 3, 2020	SISIEM	(\$25,955.56)	Payment Estimate Item Adjustment generated Stockpile Transaction
	Construction Stockpile - Total		Total				\$0.00	
0290	· Total						\$0.00	
0300	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$38,766.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	, ,	·		6	Nov 16, 2020	SYSTEM	(\$6,626.67)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Dec 3, 2020	SYSTEM	(\$28,163.33)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$3,976.00	
	Construction Stockpile - Total						\$3,976.00	
0300 -	· Total						\$3,976.00	
5001	ADVANCED WARNING RAIL SYSTEM	Material		8	Dec 16, 2020	SYSTEM	(\$70.00)	
				8	Dec 16, 2020	SYSTEM	\$70.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user turnep3 overridding Payment Estimate Exception 5 on the current

Revision 4/1/2020 Page 16 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5001	ADVANCED WARNING RAIL SYSTEM	Material						Payment Estimate.
				9	Jan 4, 2021	SYSTEM	(\$70.00)	
				9	Jan 4, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5001 -	Total				\$0.00			
Overa	ıll - Total						(\$204,306.67)	

Revision 4/1/2020 Page 17 of 17