

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 2, 2021

Progress Estima	ate Number	Contract ID Prime Contractor	200417-C03 Comanche Construction, Ir			Original Contract Amount Net Change Order Amount Current Contract Amount	\$4,099,005.37 \$341,966.30 \$4,440,971.67
Approval Date							By User
June 2, 2021			Generated and Approved	(and should be cons	idered Draft) at	the Project Office Level by	watsom1
June 2, 2021		R	eviewed and Approved (and	should be considere	d Draft) at the F	Resident Engineer Level by	penner1
June 3, 2021	Reviewed and Approved at the Central Office Controlle						greggd1
Original Comp	letion Date	Current Con	npletion Date Act	ial Completion Date	%	of Current Contract Amoun	t Complete
November	5, 2021	Decembe	er 3, 2021			40.02%	

	Contract Informational Dates										
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract								
Acceptance Date											
Awarded Date	May 6, 2020	May 6, 2020									
Letting Date	April 17, 2020	April 17, 2020									
Notice to Proceed Date	July 6, 2020	July 6, 2020									
Open to Traffic Date											
Work Began Date											

Contract Total Pay For Estimate No. 12				
	This Estimate	Previous	To Date	
200417-C03				
Total Posted Items Pay	\$307,919.20	\$1,469,138.23	\$1,777,057.43	
Gross Item Adjustments	(\$26,711.24)	\$159,378.49	\$132,667.25	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustmen	ts \$0.00	\$0.00	\$0.00	
		\$1,628,516.72	\$1,909,724.68	
Contract Total Payable This Estimate:	\$281,207.96			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3266	0040	6161005	CONSTRUCTION SIGNS	SQFT	\$19.600	64	\$1,254.40
	0110	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	LF	\$19.750	819.5	\$16,185.13
	0120	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	LF	\$29.750	345.5	\$10,278.63
	0160	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$257.600	12	\$3,091.20
	0190	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.150	1,340	\$201.00
	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.150	555	\$83.25
	0210	6207001	PAVEMENT MARKING REMOVAL	LF	\$2.250	950	\$2,137.50
	0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$26.500	153.9	\$4,078.35
	0280	2161502	REMOVAL OF CONCRETE WEARING SURFACE	SQFT	\$2.800	4,832.5	\$13,531.00
	0290	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	LS	\$1,818.400	0.5	\$909.20
	0360	2161502	REMOVAL OF CONCRETE WEARING SURFACE	SQFT	\$2.800	4,115	\$11,522.00
	0370	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	LS	\$1,818.400	0.5	\$909.20
	1030	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	LF	\$448.950	193	\$86,647.35
	1040	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	LF	\$709.900	12	\$8,518.80
	1050	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	SQFT	\$166.850	24	\$4,004.40
	1060	7034214	CLASS B-2 CONCRETE	CUYD	\$2,888.200	16.9	\$48,810.58

Revision 4/1/2020 Page 1 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 2, 2021

Progress Estimate Number	Contract ID	200417-C03	Pay Period Start	May 16, 2021	Original Contract Amount	\$4,099,005.37
12	Prime Contractor	Comanche Construction, Inc.	Pay Period End	June 1, 2021	Net Change Order Amount	\$341,966.30
12					Current Contract Amount	\$4,440,971.67

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3266	1070	7049903	MISC.RAISED MEDIAN REPAIR	LF	\$122.750	20	\$2,455.00
	1080	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$2.700	2,570	\$6,939.00
	1100	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	LF	\$380.050	163	\$61,948.15
	5001	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	EA	\$3,417.280	2	\$6,834.56
	5005	9029901	MISC.SIGNAL MODIFICATION	LS	\$5,224.890	0.5	\$2,612.45
	5007	4039910	MISC.ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125B MIX)	TONS	\$559.650	19.2	\$10,745.28
	5008	6189901	MISC.MOBILIZATION FOR ASPHALT TIE-IN PAVEMENT	LS	\$3,150.000	1	\$3,150.00
	5009	4071005	TACK COAT	GAL	\$2.630	39	\$102.57
	5010	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$22.050	44	\$970.20
Project J4F	23266 - Tot	al					\$307,919.20
Overall - To	otal						\$307,919.20

Contract Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
4P3266	0040	CONSTRUCTION SIGNS	Overrun			-30	\$19.60	(\$588.00
	0160	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-12	\$257.60	(\$3,091.20
	0160	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user watsom1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	12	\$257.60	\$3,091.20
	0190	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-1,340	\$0.15	(\$201.00)
	0190	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user watsom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1,340	\$0.15	\$201.00
	0200	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-555	\$0.15	(\$83.25)
	0200	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user watsom1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	555	\$0.15	\$83.25
	0530	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			-1,376	\$137.30	(\$188,924.80)
	0530	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user watsom1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1,376	\$137.30	\$188,924.80
	0570	HALF-SOLE REPAIR	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all	743	\$43.90	\$32,617.70

Page 2 of 17 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 2, 2021

Number No. Type									· · · · · · · · · · · · · · · · · · ·
Adjustments of '43 9,0000 - 43 9,0000 - 15			Item Description		Adjustment	Comments		Adjustment	Adjustment amount
Adjustment Readjustment alous the total of all adjustments 0. Secondary Color	J4P3266					Adjustments of ',43.90000 - 43.90000, 'is			
adjustments of installed quantity on all previous payment estimates. Price Adjustments of 1,63,80000, 1-63,8000, 1-63,800		0570	HALF-SOLE REPAIR		Re-	11. This adjustment makes the total of all			(\$18,438.00)
Adjustment Readjustment algorithms and purpose and pur		0580	FULL DEPTH REPAIR	Overrun		adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',63.80000 - 63.80000, 'is	87	\$63.80	\$5,550.60
1060 CLASS B-2 CONCRETE Material This adjustment offsets the original system-generated Material Payment Estimate Issumate Issumate Estimate Exception 12 on the current Payment Estimate. 1080 REINFORCING STEEL (EPOXY COATED) 1100 STRIP SEAL EXPANSION ON Stockpile Transaction 1100 STRIP SEAL EXPANSION ON JOINT SYSTEM 1100 STRIP SEAL EXPANSION ON JOINT SYSTEM 1100 STRIP SEAL EXPANSION ON JOINT SYSTEM 1100 MPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY) 1100 MISC. Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user watsom1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 1100 Material This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Item Adjustment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate.		0580	FULL DEPTH REPAIR		Re-	11. This adjustment makes the total of all			(\$5,550.60)
generated Material Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment Estimate Exception 12 on the current Payment Estimate Item Adjustment generated Stockpile Transaction Transaction Stockpile Transaction Transaction Stockpile Transaction Stockpile Transaction Stockpile Transaction Transaction Stockpile Transaction Transaction Transaction Transaction Transaction Stockpile Transaction Trans		1060	CLASS B-2 CONCRETE	Material			-16.9	\$2,888.20	(\$48,810.58)
Stockpile Transaction Stockpile Stockpile Transaction Stockpile Transaction STRIP SEAL EXPANSION Construction Stockpile Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Transac		1060	CLASS B-2 CONCRETE	Material		generated Material Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment Estimate Exception 12	16.9	\$2,888.20	\$48,810.58
JOINT SYSTEM Stockpile Stockpile Stockpile Stockpile Stockpile Transaction Material MPH (SAND BARREL ARRAY) Material		1080							(\$1,712.91)
MPH (SAND BARREL ARRAY) 5001 IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY) 5007 MISC. Material Material Material Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0011) due to user watsom1 overridding Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Exception 3 on the current Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 5010 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE		1100							(\$38,590.03)
MPH (SAND BARREL ARRAY) MPH (SAND BARREL ARRAY) MISC. Material MISC. Material Material Material Material Material Material Department (0011) due to user watsom1 overridding Payment Estimate Exception 3 on the current Payment Estimate. MISC. Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate. Material PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		5001	MPH (SAND BARREL	Material			-2	\$3,417.28	(\$6,834.56)
5007 MISC. Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate. 5010 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE 5010 PREFORMED THIS Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		5001	MPH (SAND BARREL	Material		generated Material Payment Estimate Item Adjustment (0011) due to user watsom1 overridding Payment Estimate Exception 3 on	2	\$3,417.28	\$6,834.56
generated Material Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 5010 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		5007	MISC.	Material			-19.2	\$559.65	(\$10,745.28)
THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE 5010 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		5007	MISC.	Material		generated Material Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Exception 1 on	19.2	\$559.65	\$10,745.28
THERMOPLASTIC generated Material Payment Estimate Item PAVEMENT MARKING, 24 Adjustment (0012) due to user watsom1 IN. WHITE overridding Payment Estimate Exception 4 on the current Payment Estimate.		5010	THERMOPLASTIC PAVEMENT MARKING, 24	Material			-44	\$22.05	(\$970.20)
Total (\$26,711.24		5010	THERMOPLASTIC PAVEMENT MARKING, 24	Material		generated Material Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Exception 4 on	44	\$22.05	\$970.20
	Total								(\$26,711.24)

Revision 4/1/2020 Page 3 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4P3266	FAS S302(002)	Bridge Rehabilitation	Various	VARIOUS	at various locations th	roughout the urban Kansas C	ity district
Totals by	Job Number	s					
J4P3266					This Estimate	Previous	To Date
	Posted	Item Pay			\$307,919.20	\$1,469,138.23	\$1,777,057.43
	Gross	ltem Adjustmen			(\$26,711.24)	\$159,378.49	\$132,667.25
	Gross		its Gross Ite	m Pay	(\$26,711.24) \$281,207.96	\$159,378.49 \$1,628,516.72	
	Gross	•		m Pay			\$132,667.25
		ve		m Pay	\$281,207.96	\$1,628,516.72	\$132,667.25 \$1,909,724.68
	Incenti Disince	ve		m Pay	\$281,207.96 \$0.00	\$1,628,516.72 \$0.00	\$132,667.25 \$1,909,724.68 \$0.00

Revision 4/1/2020 Page 4 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 4039910, Project Item Line Number 5007, Material Set 403991096, Material 0403SP250E - Superpave 25.0 mm, Des E, Acceptance Action Generic AspHigh is insufficient.	Will have to complete materials reporting after this estimate.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 5052000, Project Item Line Number 0530, Material Set 505200096, Material 1005GECMGTBD - Bridge Wearing Surface Grade E Granite, Acceptance Action Generic 1005GECMGTBD is insufficient.	Waiting on District Materials to report QA aggregate samples.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 6122017, Project Item Line Number 5001, Material Set 612201796, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Will have to complete materials reporting after this estimate.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 6200015, Project Item Line Number 5010, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Will have to complete materials reporting after this estimate.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 6200021, Project Item Line Number 0160, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Will have to complete materials reporting after this estimate.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 6206000C, Project Item Line Number 0190, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Will have to complete materials reporting after this estimate.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 6206000C, Project Item Line Number 0190, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Will have to complete materials reporting after this estimate.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 6206000C, Project Item Line Number 0190, Material Set 6206000C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Will have to complete materials reporting after this estimate.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 6206001C, Project Item Line Number 0200, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Will have to complete materials reporting after this estimate.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 6206001C, Project Item Line Number 0200, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne /ellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Will have to complete materials reporting after this estimate.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 6206001C, Project Item Line Number 0200, Material Set 6206001C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Will have to complete materials reporting after this estimate.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 7034214, Project Item Line Number 1060, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Will have to complete materials reporting after this estimate.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 7040103, Project Item Line Number 0560, Material Set 704010396, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	This item will be change ordered out.	watsom1	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C03, Contract Project J4P3266, Project Item ine Number 0040, Contract Line Item Number 0040, Item 6161005, Minor Item.	Will have to issue a change order for this item.	watsom1	Acknowledged

Revision 4/1/2020 Page 5 of 17



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					eport Generated date and can differ from the posted am						11.11.0.1	T. L. IV. I DOOTED
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$113,120.00	\$0.00
		0001	0020	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	153.00	0.00	153.00	SQFT	0.00	\$67.35	\$0.00
		0001	0030	4030007	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095BSM MIX)	231.20	0.00	231.20	TONS	0.00	\$432.80	\$0.00
		0001	0040	6161005	CONSTRUCTION SIGNS	1,078.00	0.00	1,078.00	SQFT	1,108.00	\$19.60	\$21,716.80
		0001	0050	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	-4.00	4.00	EA	0.00	\$309.15	\$0.00
		0001	0060	6161009	FLAG ASSEMBLY	8.00	-8.00	0.00	EA	0.00	\$103.05	\$0.00
		0001	0070	6161025	CHANNELIZER (TRIM LINE)	210.00	120.00	330.00	EA	330.00	\$51.50	\$16,995.00
		0001	0800	6161030	TYPE III MOVEABLE BARRICADE	16.00	0.00	16.00	EA	16.00	\$412.20	\$6,595.20
		0001	0090	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$5,152.30	\$20,609.20
		0001	0100	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$17,002.60	\$68,010.40
		0001	0105	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	0.00	\$7,728.45	\$0.00
		0001	0110	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,230.00	0.00	1,230.00	LF	819.50	\$19.75	\$16,185.12
		0001	0120	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	1,289.00	0.00	1,289.00	LF	881.50	\$29.75	\$26,224.62
		0001	0130	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	6.00	0.00	6.00	EA	4.00	\$497.85	\$1,991.40
		0001	0140	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	6,444.00	0.00	6,444.00	LF	0.00	\$9.95	\$0.00
		0001	0150	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$406,875.00	\$0.00
		0001	0151	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.75	\$388,169.00	\$291,126.75
		0001	0160	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	16.00	0.00	16.00	EA	12.00	\$257.60	\$3,091.20
		0001	0170	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,271.00	0.00	4,271.00	LF	0.00	\$0.30	\$0.00
		0001	0180	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,458.00	0.00	1,458.00	LF	0.00	\$0.30	\$0.00
		0001	0190	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,640.00	0.00	1,640.00	LF	1,340.00	\$0.15	\$201.00
		0001	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,071.00	0.00	5,071.00	LF	555.00	\$0.15	\$83.25
		0001	0210	6207001	PAVEMENT MARKING REMOVAL	20,939.00	23,714.00	44,653.00	LF	950.00	\$2.25	\$2,137.50
		0001	0220	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	18,663.00	13,750.00	32,413.00	LF	950.00	\$2.25	\$2,137.50
		0001	0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,534.00	153.20	2,687.20	SQYD	153.90	\$26.50	\$4,078.35
		0010	0240	6061060	MGS GUARDRAIL	5,588.00	0.00	5,588.00	LF	0.00	\$19.05	\$0.00
		0010	0250	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	12.00	0.00	12.00	EA	0.00	\$2,833.75	\$0.00
		0010	0260	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	0.00	\$875.90	\$0.00
		0010	0270	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	6.00	0.00	6.00	EA	0.00	\$2,627.65	\$0.00
		0070	0280	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,665.00	0.00	8,665.00	SQFT	4,832.50	\$2.80	\$13,531.00
		0070	0290	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.50	\$1,818.40	\$909.20
		0070	0300	5050001	OPTIONAL CONCRETE WEARING SURFACE	963.00	0.00	963.00	SQYD	0.00	\$91.80	\$0.00
		0070	0310	7040104	HALF-SOLE REPAIR	450.00	0.00	450.00	SQFT	0.00	\$43.90	\$0.00
		0071	0320	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,665.00	0.00	8,665.00	SQFT	0.00	\$2.80	\$0.00
		0071	0330	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,818.40	\$0.00
		0071	0340	5050001	OPTIONAL CONCRETE WEARING SURFACE	963.00	0.00	963.00	SQYD	0.00	\$91.80	\$0.00
		0071	0350	7040104	HALF-SOLE REPAIR	450.00	0.00	450.00	SQFT	0.00	\$43.90	\$0.00
		0072	0360	2161502	REMOVAL OF CATHODIC PROTECTION SYSTEM	8,230.00	0.00	8,230.00	SQFT	4,115.00	\$2.80	\$11,522.00
		0072	0370	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.50	\$1,818.40	\$909.20
		0072	0380	5050001	OPTIONAL CONCRETE WEARING SURFACE	914.00	0.00	914.00	SQYD	0.00	\$91.80	\$0.00
		0072	0390	7040104	HALF-SOLE REPAIR	400.00	0.00	400.00	SQFT	0.00	\$43.90	\$0.00
		0072	0400	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	0.00	\$63.80	\$0.00
		0073	0410	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,330.00	0.00	9,330.00	SQFT	0.00	\$2.60	\$0.00
		0073	0420	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$11,742.65	\$0.00

Page 6 of 17 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0073	0430	2164000	CURB REMOVAL	10.00	0.00	10.00	LF	0.00	\$275.85	\$0.00
		0073	0440	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,818.40	\$0.00
		0073	0450	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,037.00	0.00	1,037.00	SQYD	0.00	\$91.80	\$0.00
		0073	0460	7034001	CLASS B-1 CONCRETE	4.20	0.00	4.20	CUYD	0.00	\$3,283.90	\$0.00
		0073	0470	7034600	CURB BLOCKOUT	21.00	0.00	21.00	LF	0.00	\$314.05	\$0.00
		0073	0480	7040104	HALF-SOLE REPAIR	450.00	0.00	450.00	SQFT	0.00	\$43.90	\$0.00
		0073	0490	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	0.00	\$63.80	\$0.00
		0073	0500	7101000	REINFORCING STEEL (EPOXY COATED)	790.00	0.00	790.00	LB	0.00	\$2.45	\$0.00
		0074	0510	2161502	REMOVAL OF CONCRETE WEARING SURFACE	12,442.00	0.00	12,442.00	SQFT	12,442.00	\$2.05	\$25,506.10
		0074	0520	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	243.00	0.00	243.00	LF	243.00	\$321.05	\$78,015.15
		0074	0530	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,376.00	0.00	1,376.00	SQYD	1,376.00	\$137.30	\$188,924.80
		0074	0540	7034001	CLASS B-1 CONCRETE	16.30	0.00	16.30	CUYD	16.30	\$3,465.40	\$56,486.02
		0074	0550	7040101	SUBSTRUCTURE REPAIR (FORMED)	200.00	-125.00	75.00	SQFT	75.00	\$162.15	\$12,161.25
		0074	0560	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	500.00	-500.00	0.00	SQFT	0.00	\$162.15	\$0.00
		0074	0570	7040104	HALF-SOLE REPAIR	1,850.00	5,393.00	7,243.00	SQFT	7,243.00	\$43.90	\$317,967.70
		0074	0580	7040106	FULL DEPTH REPAIR	600.00	887.00	1,487.00	SQFT	1,487.00	\$63.80	\$94,870.60
		0074	0590	7101000	REINFORCING STEEL (EPOXY COATED)	4,280.00	0.00	4,280.00	LB	4,280.00	\$2.15	\$9,202.00
		0075	0600	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,139.00	0.00	9,139.00	SQFT	0.00	\$2.70	\$0.00
		0075	0610	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,015.00	0.00	1,015.00	SQYD	0.00	\$91.80	\$0.00
		0075	0620	7034600	CURB BLOCKOUT	509.00	0.00	509.00	LF	0.00	\$97.20	\$0.00
		0075	0630	7040104	HALF-SOLE REPAIR	900.00	0.00	900.00	SQFT	0.00	\$43.90	\$0.00
		0075	0640	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	450.00	0.00	450.00	SQFT	0.00	\$75.50	\$0.00
		0076	0650	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,139.00	0.00	9,139.00	SQFT	0.00	\$2.70	\$0.00
		0076	0660	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,015.00	0.00	1,015.00	SQYD	0.00	\$91.80	\$0.00
		0076	0670	7034600	CURB BLOCKOUT	509.00	0.00	509.00	LF	0.00	\$98.00	\$0.00
		0076	0680	7040104	HALF-SOLE REPAIR	900.00	0.00	900.00	SQFT	0.00	\$43.90	\$0.00
		0076	0690	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	450.00	0.00	450.00	SQFT	0.00	\$75.50	\$0.00
		0077	0700	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,187.00	0.00	5,187.00	SQFT	0.00	\$4.35	\$0.00
		0077	0710	5050001	OPTIONAL CONCRETE WEARING SURFACE	576.00	0.00	576.00	SQYD	0.00	\$91.80	\$0.00
		0077	0720	7034600	CURB BLOCKOUT	301.00	0.00	301.00	LF	0.00	\$124.00	\$0.00
		0077	0730	7040104	HALF-SOLE REPAIR	500.00	0.00	500.00	SQFT	0.00	\$43.90	\$0.00
		0077	0740	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	250.00	0.00	250.00	SQFT	0.00	\$75.50	\$0.00
		0077	0750	7040113	CLEANING AND EPOXY COATING	990.00	0.00	990.00	SQFT	0.00	\$5.50	\$0.00
		0078	0760	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,187.00	0.00	5,187.00	SQFT	0.00	\$4.35	\$0.00
		0078	0770	5050001	OPTIONAL CONCRETE WEARING SURFACE	576.00	0.00	576.00	SQYD	0.00	\$91.80	\$0.00
		0078	0780	7034600	CURB BLOCKOUT	301.00	0.00	301.00	LF	0.00	\$124.00	\$0.00
		0078	0790	7040104	HALF-SOLE REPAIR	500.00	0.00	500.00	SQFT	0.00	\$43.90	\$0.00
		0078	0800	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	250.00	0.00	250.00	SQFT	0.00	\$75.50	\$0.00
		0078	0810	7040113	CLEANING AND EPOXY COATING	990.00	0.00	990.00	SQFT	0.00	\$5.50	\$0.00
		0079	0820	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	144.00	0.00	144.00	LF	0.00	\$45.75	\$0.00
		0079	0830	2169903	MISC.REMOVAL AND REINSTALLATION OF SIDEWALK SKID PLATE	30.00	0.00	30.00	LF	0.00	\$261.45	\$0.00
		0079	0840	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS ((EPOXY)	1.00	0.00	1.00	LS	1.00	\$7,120.50	\$7,120.50
		0079	0850	7171002	PREFORMED COMPRESSION SEAL	110.00	0.00	110.00	LF	0.00	\$95.15	\$0.00
		0080	0860	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	196.00	0.00	196.00	LF	0.00	\$45.75	\$0.00
		0080	0870	2169903	MISC.REMOVAL AND REINSTALLATION OF SIDEWALK SKID	26.00	0.00	26.00	LF	0.00	\$301.65	\$0.00

Revision 4/1/2020 Page 7 of 17



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0080	0880	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$7,812.95	\$7,812.95
		0800	0890	7171002	PREFORMED COMPRESSION SEAL	165.00	0.00	165.00	LF	0.00	\$95.15	\$0.00
		0081	0900	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	63.00	0.00	63.00	LF	0.00	\$704.60	\$0.00
		0081	0910	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	0.00	\$709.90	\$0.00
		0081	0920	7034214	CLASS B-2 CONCRETE	5.90	0.00	5.90	CUYD	0.00	\$2,888.20	\$0.00
		0081	0930	7101000	REINFORCING STEEL (EPOXY COATED)	730.00	0.00	730.00	LB	0.00	\$3.55	\$0.00
		0081	0940	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$3,634.45	\$0.00
		0081	0950	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	63.00	0.00	63.00	LF	0.00	\$380.05	\$0.00
		0082	0960	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	92.00	0.00	92.00	LF	0.00	\$45.75	\$0.00
		0082	0970	7171002	PREFORMED COMPRESSION SEAL	92.00	0.00	92.00	LF	0.00	\$95.15	\$0.00
		0083	0980	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	92.00	0.00	92.00	LF	0.00	\$45.75	\$0.00
		0083	0990	7171002	PREFORMED COMPRESSION SEAL	92.00	0.00	92.00	LF	0.00	\$95.15	\$0.00
		0084	1000	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	192.00	0.00	192.00	LF	0.00	\$45.75	\$0.00
		0084	1010	7049903	MISC.RAISED MEDIAN REPAIR	40.00	0.00	40.00	LF	0.00	\$122.70	\$0.00
		0084	1020	7171002	PREFORMED COMPRESSION SEAL	192.00	0.00	192.00	LF	0.00	\$95.15	\$0.00
		0085	1030	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	193.00	0.00	193.00	LF	193.00	\$448.95	\$86,647.35
		0085	1040	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	12.00	\$709.90	\$8,518.80
		0085	1050	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	24.00	\$166.85	\$4,004.40
		0085	1060	7034214	CLASS B-2 CONCRETE	16.90	0.00	16.90	CUYD	16.90	\$2,888.20	\$48,810.58
		0085	1070	7049903	MISC.RAISED MEDIAN REPAIR	20.00	0.00	20.00	LF	20.00	\$122.75	\$2,455.00
		0085	1080	7101000	REINFORCING STEEL (EPOXY COATED)	2,570.00	0.00	2,570.00	LB	2,570.00	\$2.70	\$6,939.00
		0085	1090	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$4,907.05	\$0.00
		0085	1100	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	163.00	0.00	163.00	LF	163.00	\$380.05	\$61,948.15
		0086	1110	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	162.00	0.00	162.00	LF	162.00	\$448.95	\$72,729.90
		0086	1120	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	24.00	\$122.75	\$2,946.00
		0086	1130	7034214	CLASS B-2 CONCRETE	15.30	0.00	15.30	CUYD	15.30	\$2,888.20	\$44,189.46
		0086	1140	7101000	REINFORCING STEEL (EPOXY COATED)	2,080.00	0.00	2,080.00	LB	2,080.00	\$3.05	\$6,344.00
		0086	1150	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$6,167.30	\$0.00
		0086	1160	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	162.00	0.00	162.00	LF	162.00	\$380.05	\$61,568.10
		0087	1170	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	192.00	0.00	192.00	LF	0.00	\$448.95	\$0.00
		0087	1180	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	0.00	\$709.90	\$0.00
		0087	1190	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	0.00	\$122.75	\$0.00
		0087	1200	7034214	CLASS B-2 CONCRETE	17.20	0.00	17.20	CUYD	0.00	\$2,888.20	\$0.00
		0087	1210	7101000	REINFORCING STEEL (EPOXY COATED)	2,900.00	0.00	2,900.00	LB	0.00	\$3.10	\$0.00
		0087	1220	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$4,118.75	\$0.00
		0087	1230	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	162.00	0.00	162.00	LF	0.00	\$380.05	\$0.00
		0088	1240	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	185.00	0.00	185.00	LF	0.00	\$45.75	\$0.00
		0088	1250	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$6,380.60	\$6,380.60
		0088	1260	7171002	PREFORMED COMPRESSION SEAL	185.00	0.00	185.00	LF	0.00	\$95.15	\$0.00
		0001	5001	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	0.00	2.00	2.00	EA	2.00	\$3,417.28	\$6,834.56
		0001	5002	6122030	IMPACT ATTENUATOR (RELOCATION)	0.00	14.00	14.00	EA	0.00	\$1,257.22	\$0.00
		0001	5003	6122020	REPLACEMENT SAND BARREL	0.00	1.00	1.00	EA	0.00	\$526.52	\$0.00
		0001	5004	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$18,706.00	\$18,706.00
			5005	9029901		0.00	1.00	1.00	LS	1.00	\$5,224.89	\$5,224.89
		0001	5005	9029901	MISC.SIGNAL MODIFICATION	0.00	1.00	1.00	LS	1.00	\$5,224.89	\$5,22

Revision 4/1/2020 Page 8 of 17



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0074	5006	7049904	MISC.Clean and Epoxy Seal	0.00	910.00	910.00	SQFT	910.00	\$12.88	\$11,720.80
		0001	5007	4039910	MISC.ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125B MIX)	0.00	19.20	19.20	TONS	19.20	\$559.65	\$10,745.28
		0001	5008	6189901	MISC.MOBILIZATION FOR ASPHALT TIE-IN PAVEMENT	0.00	1.00	1.00	LS	1.00	\$3,150.00	\$3,150.00
		0001	5009	4071005	TACK COAT	0.00	274.00	274.00	GAL	39.00	\$2.63	\$102.57
		0001	5010	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	0.00	44.00	44.00	LF	44.00	\$22.05	\$970.20
	Project J	4P3266 - To	otal Value	Posted to E	ate as of Report Generated Date							\$1,777,057.41
200417-C03 Ove	rall - Total	Value Post	ted to Da	te as of Rep	ort Generated Date							\$1,777,057.41

Revision 4/1/2020 Page 9 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3266

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0040	6161005	CONSTRUCTION SIGNS	6/1/21	6/1/21	64.00	SQFT	NB I-435 over Oldham Rd. and Gregory Blvd.	1				
0110	6173600D	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	5/25/21	5/27/21	409.00	LF	NB Gregory Stage 1	621+12				
				5/27/21	410.50	LF	NB Oldham Stage 1	671+81				
0120	6173700B	TEMP. TRAFFIC BARRIER ANCHORED., CONT	5/25/21	5/27/21	166.50	LF	NB Oldham Stage 1	671+83				
				5/27/21	179.00	LF	NB Gregory Stage 1	621+12				
0160	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	5/24/21	5/27/21	12.00	EA	Bannister EB & WB	238+15				
0190	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	5/24/21	5/27/21	1,340.00	LF	Bannister EB & WB	238+15				
0200	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	5/24/21	5/27/21	555.00	LF		238+15				
0210	6207001	PAVEMENT MARKING REMOVAL	5/24/21	5/27/21	950.00	LF	Bannister EB & WB	238+15				
0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	5/20/21	5/27/21	153.90	SQYD	EB/WB Tie in for A16433	238+15				
0280	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5/26/21	5/27/21	4,832.50	SQFT	NB Stage 1	621+12				
0290	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	5/26/21	5/27/21	0.50	LS	NB stage 1	621+12				
0360	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5/26/21	5/27/21	4,115.00	SQFT	NB Stage 1	671+83				
0370	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	5/26/21	5/27/21	0.50	LS	NB Stage 1	671+83				
1030	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	5/18/21	5/27/21	193.00	LF	WB & EB A51801	8+73				
1040	2169903	MISC. REMOVALS	6/1/21	6/1/21	12.00	LF	31st St. bridge over 71 Hwy, all four corners of bridge where barrier wall met the expansion joints.	1				
1050	2169904	MISC. REMOVALS	6/1/21	6/1/21	24.00	SQFT	31st St. bridge over 71 Hwy, bullnose on each end of median.					
1060	7034214	CLASS B-2 CONCRETE	5/20/21	5/27/21	8.45	CUYD	Bridge A51801, 31st St. over 71 Hwy. Expansion joint on west end of bridge.	1				
			5/26/21	5/27/21	8.45	CUYD	31st St. over 71 Hwy, expansion joint on east side of bridge	1				
1070	7049903	MISC.	6/1/21	6/1/21	20.00	LF	31st St. bridge over 71 Hwy, replacement section at expansion joint on both ends of bridge.	1				
1080	7101000	REINFORCING STEEL (EPOXY COATED)	5/20/21	5/27/21	1,285.00	LB	Bridge A51801, 31st St. over 71 Hwy. Expansion joint on west end of bridge.	1				
			5/26/21	5/27/21	1,285.00	LB	31st St. over 71 Hwy, expansion joint on east side of bridge	1				
1100	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	5/26/21	5/27/21	163.00	LF	31st St. over 71 Hwy, expansion joints on both ends of bridge	1				
5001	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL	5/25/21	5/27/21	1.00	EA	NB Stage 1 Gregory	621+12				
		ARRAY)		5/27/21	1.00	EA	NB Stage 1 Oldham	671+83				
5005	9029901	MISC.	5/24/21	5/27/21	0.50	LS	Bannister EB	238+15				
5007	4039910	MISC.	5/20/21	5/27/21	19.20	TONS	EB/WB Tie in for A16433	238+15				
5008	6189901	MISC.	5/20/21	5/27/21	1.00	LS	EB/WB Tie in for A16433	238+15				
5009	4071005	TACK COAT	5/20/21	5/27/21	39.00	GAL	EB/WB Tie in for A16433	238+15				
5010	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	5/24/21	5/27/21	44.00	LF	Bannister EB & WB	238+15				

The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	n Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
P3266	0040	March 8, 2021	453	special ??x?? ??.00 NO ZONE	PASSING	0.005	Drury Ave	1.00		36x36 Road Work Ahead	9.00	
				special ??x?? ??.00 NO ZONE	PASSING	0.005	Marian Park	1.00		36x36 Road Work Ahead	9.00	
				special ??x?? ??.00 NO ZONE	PASSING	0.068	Freemont	1.00		36x36 Road Work Ahead	9.00	
				special ??x?? ??.00 NO ZONE	PASSING	0.104	Drury Ave.	1.00		36x36 Road Work Ahead	9.00	
				special ??x?? ??.00 NO ZONE	PASSING	0.287	95th Terr.	1.00		36x36 Road Work Ahead	9.00	
				special ??x?? ??.00 NO ZONE	PASSING	0.697	Belmont	1.00		36x36 Road Work Ahead	9.00	
				special ??x?? ??.00 NO ZONE	PASSING	0.94	EB 87th	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO ZONE	PASSING	0.94	EB 87th	1.00		21x15 Arrow	2.19	2
				special ??x?? ??.00 NO ZONE	PASSING	0.94	EB 87th	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO ZONE	PASSING	1.028	Marian Dr.	1.00		36x36 Road Work Ahead	9.00	
				special ??x?? ??.00 NO ZONE	PASSING	1.0335	Hillcrest Rd.	1.00		36x36 Road Work Ahead	9.00	
				special ??x?? ??.00 NO ZONE	PASSING	1.536	EB 87th	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO ZONE	PASSING	1.536	EB 87th	1.00		21x15 Arrow	2.19	2
				special ??x?? ??.00 NO ZONE	PASSING	1.536	EB 87th	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO ZONE	PASSING	1.585	EB 87th	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO ZONE	PASSING	1.585	EB 87th	1.00		21x15 Arrow	2.19	2
				special ??x?? ??.00 NO ZONE	PASSING	1.585	EB 87th	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO ZONE	PASSING	1.633	EB 87th	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO ZONE	PASSING	1.633	EB 87th	1.00		21x15 Arrow	2.19	2
				special ??x?? ??.00 NO ZONE	PASSING	1.633	EB 87th	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO ZONE	PASSING	124.355	SB US 71	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO ZONE	PASSING	124.355	SB US 71	1.00		24x12 South	2.00	
				special ??x?? ??.00 NO ZONE	PASSING	124.355	SB US 71	1.00		21x15 Arrow	2.19	2
				special ??x?? ??.00 NO	PASSING	124.355	SB US 71	1.00		30x24 Interstate Marker	5.00	

Revision 4/1/2020 Page 10 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

Project			are details for Construction		Oteti	Logitalia	1	No. and the second	OE	Constitution	OF Foot Correct	Total OF
roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
3266	0040	March 8, 2021	453	ZONE special ??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		24x12 Detour	2.00	
				Special ??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		24x12 South	2.00	
				Special ??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		21x15 Arrow	2.19	2.
				ZONE special ??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		30x24 Interstate Marker	5.00	
				ZONE special ??x?? ??.00 NO PASSING		2.045	Hillcrest	1.00		36x36 Road Work Ahead	9.00	
				ZONE special ??x?? ??.00 NO PASSING		3.955	EB Banister Rd.	2.00		36x36 Road Work Ahead	9.00	
				ZONE special ??x?? ??.00 NO PASSING		4.048	EB Banister Rd.	2.00		24x36 WZ Speed Limit	6.00	
				ZONE R3-7L 30x30 6.25 LEFT LANE		4.099	EB Banister Rd.	1.00	6.25	24x30 WZ Opeed Ellilli	0.00	6
				MUST TURN LEFT		4.196	EB Banister Rd.	1.00	6.25			
				MUST TURN LEFT								
				R3-7L 30x30 6.25 LEFT LANE MUST TURN LEFT		4.229	EB Banister Rd.	1.00	6.25			'
				R3-7L 30x30 6.25 LEFT LANE MUST TURN LEFT		4.23	EB Banister Rd.	1.00	6.25			'
				special ??x?? ??.00 NO PASSING ZONE		4.286	EB Banister Rd.	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING ZONE		4.286	EB Banister	1.00		21x15 Arrow	2.19	:
				special ??x?? ??.00 NO PASSING ZONE		4.286	EB Banister Rd.	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO PASSING ZONE		4.286	EB Banister Rd.	1.00		48x24 Semi Trucks	8.00	
				R3-2 48x48 16.00 NO LEFT TURN (SYMBOL)		4.286	EB Banister Rd.	1.00	16			
				WO20-2 48x48 16.00 DETOUR AHEAD		4.325	NB 435	1.00	16			
				special ??x?? ??.00 NO PASSING ZONE		4.509	NB 435	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING ZONE		4.509	NB 435	1.00		21x15 Arrow	2.19	
				special ??x?? ??.00 NO PASSING ZONE		4.509	NB 435	1.00		24x24 State Marker	4.00	
				WO20-1 48x48 16.00		4.695	NB 435	1.00	16			
				ROAD/BRIDGE/RAMP WORK AHEAD special ??x?? ??.00 NO PASSING		4.972	NB 435	1.00		24x12 Detour	2.00	
				Special ??x?? ??.00 NO PASSING		4.972	NB 435	1.00		21x15 Arrow	2.19	
				ZONE special ??x?? ??.00 NO PASSING		4.972	NB 435	1.00		24x24 State Marker	4.00	
				ZONE special ??x?? ??.00 NO PASSING		49.992	SB 435	1.00		24x12 Detour	2.00	
				ZONE special ??x?? ??.00 NO PASSING		49.992	SB 435	1.00		21x15 Arrow	2.19	
				ZONE special ??x?? ??.00 NO PASSING		49.992	SB 435	1.00		24x24 State Marker	4.00	
				ZONE			WB Banister Rd.			36x36 Road Work Ahead		
				special ??x?? ??.00 NO PASSING ZONE		5.701		1.00			9.00	
				special ??x?? ??.00 NO PASSING ZONE		5.734	NB 435	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING ZONE		5.734	NB 435	1.00		21x15 Arrow	2.19	
				special ??x?? ??.00 NO PASSING ZONE		5.734	NB 435	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO PASSING ZONE		5.773	WB Banister Rd.	1.00		36x36 Left Lane Closed Ahead	9.00	
				special ??x?? ??.00 NO PASSING ZONE		5.778	WB Banister Rd.	1.00		36x36 Left Lane Closed	9.00	
				special ??x?? ??.00 NO PASSING ZONE		5.925	NB 435	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING ZONE		5.925	NB 435	1.00		21x15 Arrow	2.19	
				special ??x?? ??.00 NO PASSING ZONE		5.925	NB 435	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO PASSING ZONE		5.944	WB Banister Rd.	1.00		24x36 WZ Speed Limit	6.00	
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		50.21	SB 435	1.00	16			
				MO4-8a 24x18 3.00 END DETOUR		50.215	SB 435	1.00	3			
				MO4-8a 24x18 3.00 END DETOUR		51.833	SB 435	1.00	3			
				special ??x?? ??.00 NO PASSING ZONE		6.056	WB Banister Rd.	1.00		30x30 Double Down	6.25	
				special ??x?? ??.00 NO PASSING ZONE		6.256	WB Banister Rd.	2.00		36x36 Left Lane Closed Ahead	9.00	
				special ??x?? ??.00 NO PASSING ZONE		6.288	WB Banister Rd.	1.00		36x36 Detour Ahead	9.00	
				special ??x?? ??.00 NO PASSING ZONE		6.355	WB Banister Rd.	1.00		30x30 Double Down	6.25	
				special ??x?? ??.00 NO PASSING ZONE		6.405	WB Banister Rd.	1.00		30x30 Double Down	6.25	
				special ??x?? ??.00 NO PASSING ZONE		6.405	WB Banister Rd.	1.00		36x36 Left Lane Closed	9.00	
				special ??x?? ??.00 NO PASSING ZONE		6.405	WB Banister Rd.	1.00		36x36 Merge	9.00	
				special ??x?? ??.00 NO PASSING		6.453	WB Banister Rd.	1.00		30x30 Double Down	6.25	
				ZONE special ??x?? ??.00 NO PASSING		6.601	WB Banister Rd.	1.00		24x12 Detour	2.00	

Revision 4/1/2020 Page 11 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Stone (if applicable).

5 0040	March 8, 2021	453	special ??x?? ??.00 NO PASSING ZONE special ??x?? ??.00 NO PASSING ZONE	6.601	WB Banister Rd.	1.00		24x12 South	2.00	
			special ??x?? ??.00 NO PASSING							
				6.601	WB Banister Rd.	1.00		21x15 Arrow	2.19	2.
			special ??x?? ??.00 NO PASSING ZONE	6.601	WB Banister Rd.	1.00		30x24 Interstate Marker	5.00	
			special ??x?? ??.00 NO PASSING	6.624	WB Banister Rd.	1.00		36x36 No Left Turn	9.00	
			ZONE special ??x?? ??.00 NO PASSING	7.192	WB Banister Rd.	1.00		24x12 Detour	2.00	
			ZONE special ??x?? ??.00 NO PASSING	7.192	WB Banister Rd.	1.00		24x12 South	2.00	
			ZONE special ??x?? ??.00 NO PASSING	7.192	WB Banister Rd.	1.00		21x15 Arrow	2.19	2.1
			ZONE special ??x?? ??.00 NO PASSING	7.192	WB Banister Rd.	1.00		30x24 Interstate Marker	5.00	2
	14 1 40	407	ZONE				40	30A24 IIITEISTATE WAIKEI	5.00	
	March 16, 2021	187	WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT)	49.319	SB 435	1.00	16			1
			R2-1 36x48 12.00 SPEED LIMIT XX	49.079	SB 435	2.00	12			-
			WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	48.911	SB 435	1.00	16			1
			W4-1(48) 48x48 16.00 MERGE	48.911	SB 435	1.00	16			1
			EO5-2 48x36 12.00 EXIT OPEN	50.109	SB 435	1.00	12			1
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	48.255	SB 435	2.00	16			3
			W3-2A(48) 48x48 16.00 YIELD AHEAD	0.202	EB 87TH RAMP TO 435 S	1.00	16			1
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	0.145	EB 87TH RAMP TO 435 S	1.00	16			1
			R1-2 48 TRI 6.93 YIELD	49.476	SB 435	1.00	6.93			6.9
			WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	48.591	SB 435	2.00	16			;
	April 12,	368	See Special Sign Details	1.1 to 1.82	EB and WB Linwood	2.00		Road Closed Ahead 36"x36"	9.00	
	2021		See Special Sign Details	1.034	EB Linwood Blvd	1.00		Right Lane Closed Ahead 36"x36"	9.00	
			See Special Sign Details	1	Flora, Woodland, and Highland	4.00		Road Work Ahead 36"x36"	9.00	3
			See Special Sign Details	0.957	EB Linwood Blvd	1.00		Road Work Ahead 36"x36"	9.00	
			See Special Sign Details	0.833	NB Euclid Ave	2.00		No Left Turn 24"x24"	4.00	
			See Special Sign Details	0.362	SB Michigan Ave	2.00		No Left Turn 24"x24"	4.00	
			See Special Sign Details	0.352	SB Garfield Ave.	1.00		Road Work Ahead 36"x36"	9.00	
			See Special Sign Details	0.349	SB Wayne Ave	1.00		Road Work Ahead 36"x36"	9.00	
			See Special Sign Details	1.109	EB Linwood Blvd	1.00		Right Lane Closed 36"x36"	9.00	
			See Special Sign Details	4.014	NE The Paseo	1.00		Detour Right Arrow 30"x24"	5.00	
			See Special Sign Details	1.275	EB 31st St.	1.00		Detour Up Arrow 30"x24"	5.00	
			See Special Sign Details	1.287 and 2.058	Linwood Blvd on barricades	2.00		Detour 48"x18"	6.00	
			R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC	1.287 to 2.099	Linwood Blvd on barricades	4.00	12.5			
			See Special Sign Details	1.479	EB 31st St	1.00		Detour Right Arrow 30"x24"	5.00	
			See Special Sign Details	1.516 to 2.892	NB and SB Brooklyn Ave.	2.00		Road Work Ahead 36"x36"	9.00	1
			R11-2 48x30 10.00 ROAD	1.591 to 2.17	Linwood Blvd on barricades	2.00	10			2
			CLOSED See Special Sign Details	1.646	NB Brooklyn Ave.	1.00		Detour Left Arrow 30"x24"	5.00	
			See Special Sign Details	1.82	WB Linwood Blvd	1.00		Road Work Ahead 36"x36"	9.00	
			See Special Sign Details	1.847	WB Linwood Blvd	1.00		Right Lane Closed Ahead 36"x36"	9.00	
			See Special Sign Details	1.937	WB Linwood Blvd	1.00		Right Lane Closed 36"x36"	9.00	
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	120.4	SB 71 Hwy	2.00	16			;
			See Special Sign Details	120.45	SB 71 Hwy	2.00		Right Shoulder Closed Ahead 48"x48"	16.00	3
			See Special Sign Details	120.5	SB 71 Hwy	2.00		Right Shoulder Closed 48"x48"	16.00	3
			See Special Sign Details	2.45	WB 31st St.	0.00		Detour Up Arrow 30"x24"	0.00	
			See Special Sign Details	2.455	WB 31st St	1.00		Detour Up Arrow 30"x24"	5.00	
			See Special Sign Details	2.834	WB 31st St	1.00		Detour Left Arrow 30"x24"	5.00	
	April 19, 2021	36	See Special Sign Details	1.657 to 2.546	Euclid, Michigan, and 2x The Paseo	4.00		Road Work Ahead 36"x36"	9.00	
	June 1, 2021	64	WO1-4bR 48x48 16.00 DOUBLE ARROW REVERSE CURVE (SYMBOL RIGHT ARROWS)	7.161	NB I-435 at Oldham Rd and Gregory Blvd	4.00	16			6

Revision 4/1/2020 Page 12 of 17



266 0040 CONSTRUCTION SIGNS Overrun Overrun 12 Jun 2, 2021 SYSTEM (\$588.00) Overrun - Total (\$588.00)	
Overrun - Total (\$588.00)	
Overrun - Total (\$588.00)	
0040 - Total (\$588.00)	
0070 CHANNELIZER (TRIM LINE) Overrun Overrun 7 Mar 16, 2021 SYSTEM (\$515.00)	
8 Apr 2, 2021 SYSTEM (\$5,665.00)	
9 Apr 16, SYSTEM \$6,180.00 Unit price based on averaged overrung previous payment estimates. Price Argapiled (if non-zero).	
Overrun - Total \$0.00	
Overrun - Total \$0.00	
0070 - Total \$0.00	
0160 PREF THERMO Material 12 Jun 2, SYSTEM \$3,091.20 This adjustment offsets the original sy Estimate Item Adjustment (0003) due Estimate Exception 5 on the current forms.	to user watsom1 overridding Payme
12 Jun 2, SYSTEM (\$3,091.20)	
- Total \$0.00	
Material - Total \$0.00	
0160 - Total \$0.00	
0190 4 IN. WHITE Material 12 Jun 2, SYSTEM \$201.00 This adjustment offsets the original sy Estimate Item Adjustment (0004) due Estimate Exception 6 on the current for the current forms of the curren	to user watsom1 overridding Payme
MARKING 12 Jun 2, SYSTEM (\$201.00)	
- Total \$0.00	
Material - Total \$0.00	
0190 - Total \$0.00	
0200 4 IN. YELLOW Material 12 Jun 2, SYSTEM \$83.25 This adjustment offsets the original sy Estimate Item Adjustment (0005) due Estimate Exception 9 on the current F	to user watsom1 overridding Payme
0200 4 IN. YELLOW Material 12 Jun 2, SYSTEM \$83.25 This adjustment offsets the original sy WATERBORNE 2021 Estimate Item Adjustment (0005) due	to user watsom1 overridding Payme
0200 4 IN. YELLOW Material VATERBORNE PAVEMENT MARKING 12 Jun 2, 2021 SYSTEM \$83.25 This adjustment offsets the original systemate ltem Adjustment (0005) due Estimate Exception 9 on the current Marking 12 Jun 2, SYSTEM (\$83.25)	to user watsom1 overridding Payme
0200 4 IN. YELLOW WATERBORNE PAVEMENT MARKING 12 Jun 2, 2021 13 SYSTEM \$83.25 This adjustment offsets the original systemate Item Adjustment (0005) due Estimate Exception 9 on the current Face System (\$83.25) 14 SYSTEM \$83.25 This adjustment offsets the original systemate Item Adjustment (0005) due Estimate Exception 9 on the current Face System (\$83.25)	to user watsom1 overridding Payme
0200 4 IN. YELLOW WATERBORNE PAVEMENT MARKING 12 Jun 2, 2021 SYSTEM \$83.25 This adjustment offsets the original statement of the current formula of the current	to user watsom1 overridding Payme
12 Jun 2, 2021 SYSTEM \$83.25 This adjustment offsets the original system to provide the part of sets than 1 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment offsets the original system to provide the part of sets than 2 adjustment	to user watsom1 overridding Payme Payment Estimate.
12 Jun 2, 2021 SYSTEM \$83.25 This adjustment offsets the original statement of sets than 1 (0005) due Estimate Item Adjustment (0005) due Estimate Exception 9 on the current F	to user watsom1 overridding Payme Payment Estimate.
12 Jun 2, 2021 SYSTEM \$83.25 This adjustment offsets the original state of the strimate Item Adjustment (0005) due	to user watsom1 overridding Payme Payment Estimate.
12	to user watsom1 overridding Payme Payment Estimate.
12	to user watsom1 overridding Payme Payment Estimate.
12	to user watsom1 overridding Payme Payment Estimate.
12	to user watsom1 overridding Payme Payment Estimate.
12	to user watsom1 overridding PaymePayment Estimate.
12	to user watsom1 overridding PaymePayment Estimate.
12	to user watsom1 overridding Payme Payment Estimate.
12 Jun 2, 2021 SYSTEM \$83.25 This adjustment offsets the original sy Estimate Item Adjustment (0005) due Estimate Exception 9 on the current form	to user watsom1 overridding PaymePayment Estimate.
12	to user watsom1 overridding Payme Payment Estimate. Identification Identific
12	to user watsom1 overridding Payme Payment Estimate. Identification Identific
12	to user watsom1 overridding Payme Payment Estimate. Identification Identific



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3266	0470	CURB BLOCKOUT	Construction Stockpile		5	Nov 2, 2020	SYSTEM	\$324.55	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$324.55	
			Construction	Stockpile STI	/II - Total			\$324.55	
	0470 -	Total						\$324.55	
	0500	REINFORCING STEEL (EPOXY	Construction Stockpile		5	Nov 2, 2020	SYSTEM	\$526.23	Payment Estimate Item Adjustment generated Stockpile Transaction
		COATED)	STMI	- Total				\$526.23	
			Construction S	Stockpile STI	/II - Total			\$526.23	
	0500 -	Total						\$526.23	
	0530	LATEX MODIFIED CONCRETE	Material		11	May 17, 2021	SYSTEM	\$188,924.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		WEARING SURFACE			11	May 17, 2021	SYSTEM	(\$188,924.80)	
					12	Jun 2, 2021	SYSTEM	\$188,924.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user watsom1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Jun 2, 2021	SYSTEM	(\$188,924.80)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0530 -	Total						\$0.00	
	0540	CLASS B-1 CONCRETE	Material		8	Apr 2, 2021	SYSTEM	(\$56,486.02)	
				- Total				(\$56,486.02)	
			Material - Tota	ı				(\$56,486.02)	
			MaterialCredit		9	Apr 16, 2021	SYSTEM	\$56,486.02	
				- Total				\$56,486.02	
			MaterialCredit	- Total				\$56,486.02	
	0540 -	Total						\$0.00	
	0550	SUBSTRUCTURE REPAIR (FORMED)	Material		8	Apr 2, 2021	SYSTEM	(\$4,702.35)	
				Total	10	May 3, 2021	SYSTEM	(\$12,161.25)	
			Matarial Tat	- Total				(\$16,863.60)	
			Material - Tota		0	A., 45	OVOT-	(\$16,863.60)	
			MaterialCredit		9	Apr 16, 2021 May 17,	SYSTEM	\$4,702.35 \$12,161.25	
						2021	STOTEW	Ψ12,101.23	
				- Total				\$16,863.60	
			MaterialCredit	- Total				\$16,863.60	
	0550 -	Total						\$0.00	
	0570	HALF-SOLE REPAIR	Other Item Adjustment	OADJ	11	May 17, 2021	watsom1	\$18,438.00	Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.
					12	Jun 2, 2021	watsom1	(\$18,438.00)	Contractor was paid for this work on estimate 11. This adjustment makes the total of all adjustments 0.
				OADJ - Tota	ıl			\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
			Overrun	Overrun	8	Apr 2, 2021	SYSTEM	(\$7,748.35)	
					9	Apr 16, 2021	SYSTEM	\$7,748.35	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
					10	May 3,	SYSTEM	(\$14,179.70)	applied (if non-zero).
						2021			



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
66	0570	HALF-SOLE REPAIR	Overrun	Overrun	11	May 17, 2021	SYSTEM	(\$18,438.00)	
					12	Jun 2, 2021	SYSTEM	\$32,617.70	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0570 -	Total						\$0.00	
	0580	FULL DEPTH REPAIR	Other Item Adjustment	OADJ	11	May 17, 2021	watsom1	\$5,550.60	Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.
					12	Jun 2, 2021	watsom1	(\$5,550.60)	Contractor was paid for this work on estimate 11. This adjustment makes the total of all adjustments 0.
				OADJ - Tota	al			\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
			Overrun	Overrun	9	Apr 16, 2021	SYSTEM	(\$8,389.70)	
					10	May 3, 2021	SYSTEM	\$8,389.70	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',63.80000 - 63.80000, 'is applied (if non-zero).
					11	May 17, 2021	SYSTEM	(\$5,550.60)	
					12	Jun 2, 2021	SYSTEM	\$5,550.60	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',63.80000 - 63.80000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0580 -	Total						\$0.00	
	0590	00 REINFORCING	Construction Stockpile		8	Apr 2, 2021	SYSTEM	(\$2,855.51)	Payment Estimate Item Adjustment generated Stockpile Transaction
		30/1123/		- Total				(\$2,855.51)	
			Construction	Stockpile - To	otal			(\$2,855.51)	
			Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$2,855.51	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$2,855.51	
			Construction	Stockpile STI				\$2,855.51	
			Material	Takal	8	Apr 2, 2021	SYSTEM	(\$9,202.00)	
			Material Total	- Total				(\$9,202.00)	
			Material - Tota MaterialCredit	al .	9	Apr 16, 2021	SYSTEM	(\$9,202.00) \$9,202.00	
				- Total		2021		\$9,202.00	
			MaterialCredit					\$9,202.00	
	0590 -	Total	materialorean	· rotar				\$0.00	
	0620	CURB BLOCKOUT	Construction Stockpile		5	Nov 2, 2020	SYSTEM	\$2,816.11	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$2,816.11	
			Construction	Stockpile STI	VII - Total			\$2,816.11	
	0620 -	Total						\$2,816.11	
ſ	0670	CURB BLOCKOUT	Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$2,816.11	Payment Estimate Item Adjustment generated Stockpile Transaction
			2	- Total				\$2,816.11	
			Construction	Stockpile STI	VII - Total			\$2,816.11	
	0670 -	Total						\$2,816.11	
	0720	CURB BLOCKOUT	Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$1,875.85	Payment Estimate Item Adjustment generated Stockpile Transaction
			C I IVII	- Total				\$1,875.85	
			Construction	Stockpile STI	MI - Total			\$1,875.85	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
266	0720 -	Total						\$1,875.85	
	0780	CURB BLOCKOUT	Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$1,875.85	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$1,875.85	
			Construction	Stockpile STI	/II - Total			\$1,875.85	
	0780 -	Total						\$1,875.85	
	0930	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$484.82	Payment Estimate Item Adjustment generated Stockpile Transaction
		·		- Total				\$484.82	
			Construction	Stockpile STI	/II - Total			\$484.82	
	0930 -		-		-			\$484.82	
	0950	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile STMI		3	Oct 1, 2020	SYSTEM	\$13,856.25	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$13,856.25	
			Construction	Stockpile STI	MI - Total			\$13,856.25	
	0950 -						2).42==	\$13,856.25	
	1060	CLASS B-2 CONCRETE	Material		12	Jun 2, 2021	SYSTEM	\$48,810.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					12	Jun 2, 2021	SYSTEM	(\$48,810.58)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	1060 -	Total						\$0.00	
	1080	STEEL (EPOXY COATED)	Construction Stockpile		12	Jun 2, 2021	SYSTEM	(\$1,712.91)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,712.91)	
			Construction	Stockpile - To	otal			(\$1,712.91)	
			Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$1,712.91	Payment Estimate Item Adjustment generated Stockpile Transaction
							\$1,712.91		
			Construction	Stockpile STI	/II - Total			\$1,712.91	
	1080 -	Total						\$0.00	
	1100	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		12	Jun 2, 2021	SYSTEM	(\$38,590.03)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$38,590.03)	
			Construction	Stockpile - To				(\$38,590.03)	
			Construction Stockpile STMI		3	Oct 1, 2020	SYSTEM	\$38,590.03	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total	II Tetal			\$38,590.03	
	1100-	Total	Construction	Stockpile STI	m - Total			\$38,590.03	
	1100 - 1140	REINFORCING STEEL (EPOXY	Construction Stockpile		10	May 3, 2021	SYSTEM	\$0.00 (\$1,390.36)	Payment Estimate Item Adjustment generated Stockpile Transaction
		COATED)		- Total				(\$1,390.36)	
			Construction		otal			(\$1,390.36)	
			Construction		5	Nov 2,	SYSTEM	\$1,390.36	Payment Estimate Item Adjustment generated Stockpile Transaction
			Stockpile STMI			2020		,550.00	, Turning generated electrical interest of the second in the s
			JIVII	- Total				\$1,390.36	
			Construction	Stockpile STI	/II - Total			\$1,390.36	
	1140 -	Total						\$0.00	
	1160	STRIP SEAL EXPANSION	Construction Stockpile		10	May 3, 2021	SYSTEM	(\$17,280.62)	Payment Estimate Item Adjustment generated Stockpile Transaction
		EXPANSION S JOINT SYSTEM			11	May 17, 2021	SYSTEM	(\$17,280.63)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total					1001	
		C						(\$34,561.25)	

Jun 3, 2021



Line Item Adjustments by Estimate

MP2266 1190 STRIP SEAL EXPANSION Sinclude 2007 STRIM	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Total	J4P3266	1160	EXPANSION	Stockpile		3		SYSTEM	\$34,561.25	Payment Estimate Item Adjustment generated Stockpile Transaction
1169 - Total			JOINT SYSTEM	STMI	- Total				\$34,561.25	
1210 REINFORCING Construction STEEL (EPDV) STMII Construction STEEL (EPDV) STMII Construction Stockpile STMI Total S1,931.95				Construction	Stockpile STI	MI - Total			\$34,561.25	
STELL (EPOXY Stockpile 2020 51M -Total 51,931.95		1160 -	Total						\$0.00	
Total \$1,931.95		1210	STEEL (EPOXY	Stockpile		5		SYSTEM	\$1,931.95	Payment Estimate Item Adjustment generated Stockpile Transaction
1210 - Total STRIP SEAL Construction Stockpile 2020 SYSTEM \$38,590.03 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total \$38,590.03 STRIP SEAL Construction Stockpile STMI - Total \$38,590.03 STRIP STATE STATE			COATED)	STMI	- Total				\$1,931.95	
1230 STRIP SEAL				Construction	Stockpile STI	VII - Total			\$1,931.95	
Source Scripped Scripped Scripped State St		1210 -	Total						\$1,931.95	
Total \$38,890.03		1230	EXPANSION	Stockpile		3		SYSTEM	\$38,590.03	Payment Estimate Item Adjustment generated Stockpile Transaction
1230 - Total 1230 - Total 1340 - Total 1440 - Total 1540			JOINT SYSTEM	STMI	- Total				\$38,590.03	
Sout				Construction	Stockpile STI	MI - Total			\$38,590.03	
ATTENUATOR 65		1230 -	Total						\$38,590.03	
12		5001	ATTENUATOR 65 MPH (SAND	Material		12		SYSTEM	\$6,834.56	Estimate Item Adjustment (0011) due to user watsom1 overridding Payment
Material - Total S0.00			BARREL ARRAY)			12		SYSTEM	(\$6,834.56)	
S001 - Total S0.00									\$0.00	
Source				Material - Tota	ıl				\$0.00	
2021 Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		5001 -	Total						\$0.00	
2021 \$0.00		5007	MISC.	Material		12		SYSTEM	\$10,745.28	Estimate Item Adjustment (0013) due to user watsom1 overridding Payment
Material - Total \$0.00						12		SYSTEM	(\$10,745.28)	
Source S					- Total				\$0.00	
FOUR PREF THERMO PVMT MARK, 24 IN WHIT POTAL PROPERTY OF THE P				Material - Tota	ıl				\$0.00	
PVMT MARK, 24 2021 Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 12		5007 -	Total						\$0.00	
2021		5010	PVMT MARK, 24	Material		12		SYSTEM	\$970.20	Estimate Item Adjustment (0012) due to user watsom1 overridding Payment
Material - Total \$0.00 5010 - Total \$0.00 J4P3266 - Total \$132,667.25						12		SYSTEM	(\$970.20)	
5010 - Total \$0.00 J4P3266 - Total \$132,667.25					- Total				\$0.00	
J4P3266 - Total \$132,667.25				Material - Tota	il				\$0.00	
		5010 -	Total						\$0.00	
Overall - Total \$132,667.25	J4P3266 -	Total							\$132,667.25	
	Overall -	Total							\$132,667.25	