

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2021

Progress Estimate Number 13	Contract ID Prime Contractor	200417-C03 Comanche Construction, Inc.	June 15, 2021	Original Contract Amount Net Change Order Amoun Current Contract Amount	t \$341,966.30	
Approval Date					By Hear	

By User		Approval Date
watsom1	Generated and Approved (and should be considered Draft) at the Project Office Level by	June 16, 2021
penner1	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	June 16, 2021
greggd1	Reviewed and Approved at the Central Office Controllers Office Level by	June 17, 2021

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 5, 2021	December 3, 2021		43.01%

### Contract Informational Dates Miles

Date Description	Original Completion Date	Current Completion Date			
Acceptance Date					
Awarded Date	May 6, 2020	May 6, 2020			
Letting Date	April 17, 2020	April 17, 2020			
Notice to Proceed Date	July 6, 2020	July 6, 2020			
Open to Traffic Date					
Work Began Date	March 8, 2021	March 8, 2021			

Milestones										
Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days						
Bridge A14855 - NB I-435 at Gregory - Milestone - Calendar Time	June 12, 2021	June 14, 2021	-2							
Bridge A16405 - NB I-435 at Oldham - Milestone - Calendar Time	June 12, 2021	June 14, 2021	-2							
Bridge A16433 - Bannister Rd - Milestone - Calendar Time	June 5, 2021	June 5, 2021	Milestone Complete							
Bridge A51801 - 31st St - Milestone - Calendar Time	June 26, 2021	June 26, 2021	Milestone Complete							
Bridge A51811 - Linwood Blvd - Milestone - Calendar Time	May 29, 2021	May 29, 2021	Milestone Complete							
Bridge A51831 - 39th St - Milestone - Calendar Time	July 24, 2021	July 24, 2021	38							

Contract Total Pay For Estimate No. 13  This Estimate Previous To Date 200417-C03  Total Posted Items Pay \$133,114.70 \$1,777,057.43 \$1,910,172.13 Gross Item Adjustments \$0.00 \$132,667.25 \$132,667.25									
		This Estimate	Previous	To Date					
200417-C03									
	Total Posted Items Pay	\$133,114.70	\$1,777,057.43	\$1,910,172.13					
	Gross Item Adjustments	\$0.00	\$132,667.25	\$132,667.25					
	Incentive	\$0.00	\$0.00	\$0.00					
	Disincentive	\$0.00	\$0.00	\$0.00					
	Liquidated Damage	\$0.00	\$0.00	\$0.00					
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00					
	•		\$1,909,724.68	\$2,042,839.38					
Contract Total Pag	yable This Estimate:	\$133,114.70							

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J4P3266	0050	6161008	ADVANCED WARNING RAIL SYSTEM	EA	\$309.150	3	\$927.45		
	0210	6207001	PAVEMENT MARKING REMOVAL	LF	\$2.250	3,905	\$8,786.25		
	0220	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	LF	\$2.250	9,012	\$20,277.00		
	0310	7040104	HALF-SOLE REPAIR	SQFT	\$43.900	1,337	\$58,694.30		
	0390	7040104	HALF-SOLE REPAIR	SQFT	\$43.900	983	\$43,153.70		
	0400	7040106	FULL DEPTH REPAIR	SQFT	\$63.800	20	\$1,276.00		
Project J4P326	Project J4P3266 - Total								
Overall - Total	overall - Total								

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	<u>Adjustr</u>	nents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3266	0190	4 IN. WHITE STANDARD	Material			-1,340	\$0.15	(\$201.00)

Revision 4/1/2020 Page 1 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2021

Progress Estimate Number
13 Contract ID 200417-C03 Pay Period Start June 2, 2021 Original Contract Amount \$4,099,005.37 Pay Period End June 15, 2021 Original Contract Amount \$4,099,005.37 Pay Period End June 15, 2021 Original Contract Amount \$4,099,005.37 Current Contract Amount \$4,409,71.67 Pay Period End June 15, 2021 Original Contract Amount \$4,409,71.67 Pay Period End June 15, 2021 Original Contract Amount \$4,409,71.67 Pay Period End June 15, 2021 Original Contract Amount \$4,409,71.67 Pay Period End June 15, 2021 Pay Period End

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3266		WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS						
	0190	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user watsom1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1,340	\$0.15	\$201.00
	0200	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-555	\$0.15	(\$83.25)
	0200	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user watsom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	555	\$0.15	\$83.25
	0310	HALF-SOLE REPAIR	Overrun			-545	\$43.90	(\$23,925.50)
	0310	HALF-SOLE REPAIR	Overrun			-342	\$43.90	(\$15,013.80)
	0310	HALF-SOLE REPAIR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user watsom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	342	\$43.90	\$15,013.80
	0310	HALF-SOLE REPAIR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user watsom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	545	\$43.90	\$23,925.50
	0390	HALF-SOLE REPAIR	Overrun			-583	\$43.90	(\$25,593.70)
	0390	HALF-SOLE REPAIR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user watsom1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	583	\$43.90	\$25,593.70
	0530	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			-1,376	\$137.30	(\$188,924.80)
	0530	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,376	\$137.30	\$188,924.80
	0550	SUBSTRUCTURE REPAIR (FORMED)	Material			-75	\$162.15	(\$12,161.25)
	0550	SUBSTRUCTURE REPAIR (FORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user watsom1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	75	\$162.15	\$12,161.25
Total								\$0.00

Revision 4/1/2020 Page 2 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Informatio	n		
Project Number									
J4P3266	FAS S302(002)	Bridge Rehabilitation	Various	VARIOUS	at various locations th	nroughout the urban Kansa	s City district		
Totals by .	Job Number	s							
J4P3266		l Item Pay Item Adjustmer		m Day	This Estimate \$133,114.70 \$0.00	Previous \$1,777,057.43 \$132,667.25	To Date \$1,910,172.13 \$132,667.25		
	Incenti Disince Liquida	ve	Gross Ite	т Рау	\$133,114.70 \$0.00 \$0.00 \$0.00	\$1,909,724.68 \$0.00 \$0.00 \$0.00	\$2,042,839.38 \$0.00 \$0.00 \$0.00		
	Other (	Contract Adjust	ments		\$0.00	\$0.00	\$0.00		

Revision 4/1/2020 Page 3 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 5052000, Project Item Line Number 0530, Material Set 505200096, Material 1005GECMGTBD - Bridge Wearing Surface Grade E Granite, Acceptance Action Generic 1005GECMGTBD is insufficient.	Waiting on District Materials to report aggregate samples.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 5052000, Project Item Line Number 0530, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on District Materials to report aggregate samples.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 6206000C, Project Item Line Number 0190, Material Set 6206000C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Need a pavement marking performance visual inspection to be completed on striping as the project progress in different locations.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 6206001C, Project Item Line Number 0200, Material Set 6206001C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Need a pavement marking performance visual inspection to be completed on striping as the project progress in different locations.	watsom1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 7040101, Project Item Line Number 0550, Material Set 704010196, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	Material for special mortar needs to be reported.	watsom1	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C03, Contract Project J4P3266, Project Item Line Number 0310, Contract Line Item Number 0310, Item 7040104, Minor Item.	Payment is being made for work performed by the contractor. A change order will be issued for overrun quantities.	watsom1	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C03, Contract Project J4P3266, Project Item Line Number 0390, Contract Line Item Number 0390, Item 7040104, Minor Item.	Payment is being made for work performed by the contractor. A change order will be issued for overrun quantities.	watsom1	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C03, Contract Project J4P3266, Project Item Line Number 0040, Contract Line Item Number 0040, Item 6161005, Minor Item.	A change order will be issued for the overrun quantities.	watsom1	Acknowledged

Revision 4/1/2020 Page 4 of 17



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					eport Generated date and can differ from the posted am						II. 'I D.'	T. I. I. V. I BOOTED
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$113,120.00	\$0.00
		0001	0020	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	153.00	0.00	153.00	SQFT	0.00	\$67.35	\$0.00
		0001	0030	4030007	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095BSM MIX)	231.20	0.00	231.20	TONS	0.00	\$432.80	\$0.00
		0001	0040	6161005	CONSTRUCTION SIGNS	1,078.00	0.00	1,078.00	SQFT	1,108.00	\$19.60	\$21,716.80
		0001	0050	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	-4.00	4.00	EA	3.00	\$309.15	\$927.45
		0001	0060	6161009	FLAG ASSEMBLY	8.00	-8.00	0.00	EA	0.00	\$103.05	\$0.00
		0001	0070	6161025	CHANNELIZER (TRIM LINE)	210.00	120.00	330.00	EA	330.00	\$51.50	\$16,995.00
		0001	0800	6161030	TYPE III MOVEABLE BARRICADE	16.00	0.00	16.00	EA	16.00	\$412.20	\$6,595.20
		0001	0090	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$5,152.30	\$20,609.20
		0001	0100	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$17,002.60	\$68,010.40
		0001	0105	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	0.00	\$7,728.45	\$0.00
		0001	0110	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	1,230.00	0.00	1,230.00	LF	819.50	\$19.75	\$16,185.12
		0001	0120	6173700B	RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	1,289.00	0.00	1,289.00	LF	881.50	\$29.75	\$26,224.62
		0001	0130	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	6.00	0.00	6.00	EA	4.00	\$497.85	\$1,991.40
		0001	0140	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	6,444.00	0.00	6,444.00	LF	0.00	\$9.95	\$0.00
		0001	0150	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$406,875.00	\$0.00
		0001	0151	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.75	\$388,169.00	\$291,126.75
		0001 0160	0160	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	16.00	0.00	16.00	EA	12.00	\$257.60	\$3,091.20
		0001	0170	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,271.00	0.00	4,271.00	LF	0.00	\$0.30	\$0.00
		0001	0180	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,458.00	0.00	1,458.00	LF	0.00	\$0.30	\$0.00
		0001	0190	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,640.00	0.00	1,640.00	LF	1,340.00	\$0.15	\$201.00
		0001	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,071.00	0.00	5,071.00	LF	555.00	\$0.15	\$83.25
		0001	0210	6207001	PAVEMENT MARKING REMOVAL	20,939.00	23,714.00	44,653.00	LF	4,855.00	\$2.25	\$10,923.75
		0001	0220	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	18,663.00	13,750.00	32,413.00	LF	9,962.00	\$2.25	\$22,414.50
		0001	0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,534.00	153.20	2,687.20	SQYD	153.90	\$26.50	\$4,078.35
		0010	0240	6061060	MGS GUARDRAIL	5,588.00	0.00	5,588.00	LF	0.00	\$19.05	\$0.00
		0010	0250	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	12.00	0.00	12.00	EA	0.00	\$2,833.75	\$0.00
		0010	0260	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	0.00	\$875.90	\$0.00
		0010	0270	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	6.00	0.00	6.00	EA	0.00	\$2,627.65	\$0.00
		0070	0280	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,665.00	0.00	8,665.00	SQFT	4,832.50	\$2.80	\$13,531.00
		0070	0290	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.50	\$1,818.40	\$909.20
		0070	0300	5050001	OPTIONAL CONCRETE WEARING SURFACE	963.00	0.00	963.00	SQYD	0.00	\$91.80	\$0.00
		0070	0310	7040104	HALF-SOLE REPAIR	450.00	0.00	450.00	SQFT	1,337.00	\$43.90	\$58,694.30
		0071	0320	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,665.00	0.00	8,665.00	SQFT	0.00	\$2.80	\$0.00
		0071	0330	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,818.40	\$0.00
		0071	0340	5050001	OPTIONAL CONCRETE WEARING SURFACE	963.00	0.00	963.00	SQYD	0.00	\$91.80	\$0.00
		0071	0350	7040104	HALF-SOLE REPAIR	450.00	0.00	450.00	SQFT	0.00	\$43.90	\$0.00
		0072	0360	2161502	REMOVAL OF CONCRETE WEARING SURFACE  REMOVAL OF CATHODIC PROTECTION SYSTEM	8,230.00	0.00	8,230.00	SQFT	4,115.00	\$2.80	\$11,522.00
		0072	0370	2165500		914.00	0.00	914.00	LS	0.50	\$1,818.40	\$909.20
		0072	0380	5050001	OPTIONAL CONCRETE WEARING SURFACE		0.00			0.00	\$91.80	\$0.00
		0072	0390	7040104	HALF-SOLE REPAIR	400.00	0.00	400.00	SQFT	983.00	\$43.90	\$43,153.70
		0072	0400	7040106	FULL DEPTH REPAIR  DEMOVAL OF CONCRETE WEARING SURFACE	100.00	0.00	100.00	SQFT	20.00	\$63.80	\$1,276.00
		0073	0410	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,330.00	0.00	9,330.00	SQFT	0.00	\$2.60	\$0.00
		0073	0420	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$11,742.65	\$0.00

Page 5 of 17 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0073	0430	2164000	CURB REMOVAL	10.00	0.00	10.00	LF	0.00	\$275.85	\$0.00
		0073	0440	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,818.40	\$0.00
		0073	0450	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,037.00	0.00	1,037.00	SQYD	0.00	\$91.80	\$0.00
		0073	0460	7034001	CLASS B-1 CONCRETE	4.20	0.00	4.20	CUYD	0.00	\$3,283.90	\$0.00
		0073	0470	7034600	CURB BLOCKOUT	21.00	0.00	21.00	LF	0.00	\$314.05	\$0.00
		0073	0480	7040104	HALF-SOLE REPAIR	450.00	0.00	450.00	SQFT	0.00	\$43.90	\$0.00
		0073	0490	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	0.00	\$63.80	\$0.00
		0073	0500	7101000	REINFORCING STEEL (EPOXY COATED)	790.00	0.00	790.00	LB	0.00	\$2.45	\$0.00
		0074	0510	2161502	REMOVAL OF CONCRETE WEARING SURFACE	12,442.00	0.00	12,442.00	SQFT	12,442.00	\$2.05	\$25,506.10
		0074	0520	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	243.00	0.00	243.00	LF	243.00	\$321.05	\$78,015.15
		0074	0530	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,376.00	0.00	1,376.00	SQYD	1,376.00	\$137.30	\$188,924.80
		0074	0540	7034001	CLASS B-1 CONCRETE	16.30	0.00	16.30	CUYD	16.30	\$3,465.40	\$56,486.02
		0074	0550	7040101	SUBSTRUCTURE REPAIR (FORMED)	200.00	-125.00	75.00	SQFT	75.00	\$162.15	\$12,161.25
		0074	0560	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	500.00	-500.00	0.00	SQFT	0.00	\$162.15	\$0.00
		0074	0570	7040104	HALF-SOLE REPAIR	1,850.00	5,393.00	7,243.00	SQFT	7,243.00	\$43.90	\$317,967.70
		0074	0580	7040106	FULL DEPTH REPAIR	600.00	887.00	1,487.00	SQFT	1,487.00	\$63.80	\$94,870.60
		0074	0590	7101000	REINFORCING STEEL (EPOXY COATED)	4,280.00	0.00	4,280.00	LB	4,280.00	\$2.15	\$9,202.00
		0075	0600	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,139.00	0.00	9,139.00	SQFT	0.00	\$2.70	\$0.00
		0075	0610	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,015.00	0.00	1,015.00	SQYD	0.00	\$91.80	\$0.00
		0075	0620	7034600	CURB BLOCKOUT	509.00	0.00	509.00	LF	0.00	\$97.20	\$0.00
		0075	0630	7040104	HALF-SOLE REPAIR	900.00	0.00	900.00	SQFT	0.00	\$43.90	\$0.00
		0075	0640	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	450.00	0.00	450.00	SQFT	0.00	\$75.50	\$0.00
		0076	0650	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,139.00	0.00	9,139.00	SQFT	0.00	\$2.70	\$0.00
		0076	0660	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,015.00	0.00	1,015.00	SQYD	0.00	\$91.80	\$0.00
		0076	0670	7034600	CURB BLOCKOUT	509.00	0.00	509.00	LF	0.00	\$98.00	\$0.00
		0076	0680	7040104	HALF-SOLE REPAIR	900.00	0.00	900.00	SQFT	0.00	\$43.90	\$0.00
		0076	0690	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	450.00	0.00	450.00	SQFT	0.00	\$75.50	\$0.00
		0077	0700	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,187.00	0.00	5,187.00	SQFT	0.00	\$4.35	\$0.00
		0077	0710	5050001	OPTIONAL CONCRETE WEARING SURFACE	576.00	0.00	576.00	SQYD	0.00	\$91.80	\$0.00
		0077	0720	7034600	CURB BLOCKOUT	301.00	0.00	301.00	LF	0.00	\$124.00	\$0.00
		0077	0730	7040104	HALF-SOLE REPAIR	500.00	0.00	500.00	SQFT	0.00	\$43.90	\$0.00
		0077	0740	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	250.00	0.00	250.00	SQFT	0.00	\$75.50	\$0.00
		0077	0750	7040113	CLEANING AND EPOXY COATING	990.00	0.00	990.00	SQFT	0.00	\$5.50	\$0.00
		0078	0760	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,187.00	0.00	5,187.00	SQFT	0.00	\$4.35	\$0.00
		0078	0770	5050001	OPTIONAL CONCRETE WEARING SURFACE	576.00	0.00	576.00	SQYD	0.00	\$91.80	\$0.00
		0078	0780	7034600	CURB BLOCKOUT	301.00	0.00	301.00	LF	0.00	\$124.00	\$0.00
		0078	0790	7040104	HALF-SOLE REPAIR	500.00	0.00	500.00	SQFT	0.00	\$43.90	\$0.00
		0078	0800	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	250.00	0.00	250.00	SQFT	0.00	\$75.50	\$0.00
		0078	0810	7040113	CLEANING AND EPOXY COATING	990.00	0.00	990.00	SQFT	0.00	\$5.50	\$0.00
		0079	0820	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	144.00	0.00	144.00	LF	0.00	\$45.75	\$0.00
		0079	0830	2169903	MISC.REMOVAL AND REINSTALLATION OF SIDEWALK SKID PLATE	30.00	0.00	30.00	LF	0.00	\$261.45	\$0.00
		0079	0840	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS ((EPOXY)	1.00	0.00	1.00	LS	1.00	\$7,120.50	\$7,120.50
		0079	0850	7171002	PREFORMED COMPRESSION SEAL	110.00	0.00	110.00	LF	0.00	\$95.15	\$0.00
		0080	0860	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	196.00	0.00	196.00	LF	0.00	\$45.75	\$0.00
		0080	0870	2169903	MISC.REMOVAL AND REINSTALLATION OF SIDEWALK SKID	26.00	0.00	26.00	LF	0.00	\$301.65	\$0.00

Revision 4/1/2020 Page 6 of 17



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0080	0880	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$7,812.95	\$7,812.95
		0800	0890	7171002	PREFORMED COMPRESSION SEAL	165.00	0.00	165.00	LF	0.00	\$95.15	\$0.00
		0081	0900	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	63.00	0.00	63.00	LF	0.00	\$704.60	\$0.00
		0081	0910	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	0.00	\$709.90	\$0.00
		0081	0920	7034214	CLASS B-2 CONCRETE	5.90	0.00	5.90	CUYD	0.00	\$2,888.20	\$0.00
		0081	0930	7101000	REINFORCING STEEL (EPOXY COATED)	730.00	0.00	730.00	LB	0.00	\$3.55	\$0.00
		0081	0940	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$3,634.45	\$0.00
		0081	0950	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	63.00	0.00	63.00	LF	0.00	\$380.05	\$0.00
		0082	0960	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	92.00	0.00	92.00	LF	0.00	\$45.75	\$0.00
		0082	0970	7171002	PREFORMED COMPRESSION SEAL	92.00	0.00	92.00	LF	0.00	\$95.15	\$0.00
		0083	0980	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	92.00	0.00	92.00	LF	0.00	\$45.75	\$0.00
		0083	0990	7171002	PREFORMED COMPRESSION SEAL	92.00	0.00	92.00	LF	0.00	\$95.15	\$0.00
		0084	1000	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	192.00	0.00	192.00	LF	0.00	\$45.75	\$0.00
		0084	1010	7049903	MISC.RAISED MEDIAN REPAIR	40.00	0.00	40.00	LF	0.00	\$122.70	\$0.00
		0084	1020	7171002	PREFORMED COMPRESSION SEAL	192.00	0.00	192.00	LF	0.00	\$95.15	\$0.00
		0085	1030	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	193.00	0.00	193.00	LF	193.00	\$448.95	\$86,647.35
		0085	1040	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	12.00	\$709.90	\$8,518.80
		0085	1050	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	24.00	\$166.85	\$4,004.40
		0085	1060	7034214	CLASS B-2 CONCRETE	16.90	0.00	16.90	CUYD	16.90	\$2,888.20	\$48,810.58
		0085	1070	7049903	MISC.RAISED MEDIAN REPAIR	20.00	0.00	20.00	LF	20.00	\$122.75	\$2,455.00
		0085	1080	7101000	REINFORCING STEEL (EPOXY COATED)	2,570.00	0.00	2,570.00	LB	2,570.00	\$2.70	\$6,939.00
		0085	1090	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$4,907.05	\$0.00
		0085	1100	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	163.00	0.00	163.00	LF	163.00	\$380.05	\$61,948.15
		0086	1110	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	162.00	0.00	162.00	LF	162.00	\$448.95	\$72,729.90
		0086	1120	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	24.00	\$122.75	\$2,946.00
		0086	1130	7034214	CLASS B-2 CONCRETE	15.30	0.00	15.30	CUYD	15.30	\$2,888.20	\$44,189.46
		0086	1140	7101000	REINFORCING STEEL (EPOXY COATED)	2,080.00	0.00	2,080.00	LB	2,080.00	\$3.05	\$6,344.00
		0086	1150	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$6,167.30	\$0.00
		0086	1160	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	162.00	0.00	162.00	LF	162.00	\$380.05	\$61,568.10
		0087	1170	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	192.00	0.00	192.00	LF	0.00	\$448.95	\$0.00
		0087	1180	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	0.00	\$709.90	\$0.00
		0087	1190	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	0.00	\$122.75	\$0.00
		0087	1200	7034214	CLASS B-2 CONCRETE	17.20	0.00	17.20	CUYD	0.00	\$2,888.20	\$0.00
		0087	1210	7101000	REINFORCING STEEL (EPOXY COATED)	2,900.00	0.00	2,900.00	LB	0.00	\$3.10	\$0.00
		0087	1220	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$4,118.75	\$0.00
		0087	1230	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	162.00	0.00	162.00	LF	0.00	\$380.05	\$0.00
		0088	1240	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	185.00	0.00	185.00	LF	0.00	\$45.75	\$0.00
		0088	1250	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$6,380.60	\$6,380.60
		0088	1260	7171002	PREFORMED COMPRESSION SEAL	185.00	0.00	185.00	LF	0.00	\$95.15	\$0.00
		0001	5001	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	0.00	2.00	2.00	EA	2.00	\$3,417.28	\$6,834.56
		0001	5002	6122030	IMPACT ATTENUATOR (RELOCATION)	0.00	14.00	14.00	EA	0.00	\$1,257.22	\$0.00
		0001	5003	6122020	REPLACEMENT SAND BARREL	0.00	1.00	1.00	EA	0.00	\$526.52	\$0.00
		0001	5004	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$18,706.00	\$18,706.00
			5005	9029901		0.00	1.00	1.00	LS	1.00	\$5,224.89	\$5,224.89
		0001	5005	9029901	MISC.SIGNAL MODIFICATION	0.00	1.00	1.00	LS	1.00	\$5,224.89	\$5,2

Revision 4/1/2020 Page 7 of 17



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0074	5006	7049904	MISC.Clean and Epoxy Seal	0.00	910.00	910.00	SQFT	910.00	\$12.88	\$11,720.80
		0001	5007	4039910	MISC.ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125B MIX)	0.00	19.20	19.20	TONS	19.20	\$559.65	\$10,745.28
		0001	5008	6189901	MISC.MOBILIZATION FOR ASPHALT TIE-IN PAVEMENT	0.00	1.00	1.00	LS	1.00	\$3,150.00	\$3,150.00
		0001	5009	4071005	TACK COAT	0.00	274.00	274.00	GAL	39.00	\$2.63	\$102.57
		0001	5010	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	0.00	44.00	44.00	LF	44.00	\$22.05	\$970.20
	Project J	4P3266 - To	otal Value	Posted to D	ate as of Report Generated Date							\$1,910,172.11
200417-C03 Ove	erall - Total	Value Pos	ted to Dat	te as of Repo	ort Generated Date							\$1,910,172.11

Revision 4/1/2020 Page 8 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### $\underline{\textbf{The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.}$

Project: J4P3266

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0050	6161008	ADVANCED WARNING RAIL SYSTEM	6/8/21	6/16/21	3.00	EA	2 on NB I-435 between Bannister Rd. and 87th St, and 1 on the 87th St on-ramp to NB I-435.	5.423				
0210	6207001	PAVEMENT MARKING REMOVAL	6/8/21	6/16/21	3,905.00	LF	NB I-435 over Oldham Rd. and Gregory Blvd. for phase 1 construction.	7.16		8.35		
0220	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	6/8/21	6/16/21	9,012.00	LF	NB I-435 over Oldham Rd. and Gregory Blvd. for phase 1 construction.	7.16		8.35		
0310	7040104	HALF-SOLE REPAIR	6/4/21	6/16/21	545.00	SQFT	NB 435 over Gregory	621+12				
			6/9/21	6/16/21	404.00	SQFT	NB I-435 over Gregory Blvd. near end bent 4.	1				
			6/11/21	6/16/21	202.00	SQFT	NB Gregory	621+12				
			6/15/21	6/16/21	186.00	SQFT	NB I-435 over Gregory Blvd, phase 1 construction	1				
0390	7040104	HALF-SOLE REPAIR	6/2/21	6/16/21	693.00	SQFT	NB I-435 over Oldham Rd., Phase 1 left side of bridge, non-special repair zones.	1				
			6/10/21	6/16/21	290.00	SQFT	NB Oldham Stage 1	671+83				
0400	7040106	FULL DEPTH REPAIR	6/2/21	6/16/21	14.00	SQFT	NB I-435 over Oldham Rd., Phase 1 left side of bridge, non-special repair zones.	1				
			6/10/21	6/16/21	6.00	SQFT	NB Oldham Stage 1	671+83				

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date		Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
P3266		March 8, 2021	453	special ZONE	??x?? ??.00 NO PASSING		0.005	Drury Ave	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		0.005	Marian Park	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		0.068	Freemont	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		0.104	Drury Ave.	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		0.287	95th Terr.	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		0.697	Belmont	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		0.94	EB 87th	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		0.94	EB 87th	1.00		21x15 Arrow	2.19	2
				special ZONE	??x?? ??.00 NO PASSING		0.94	EB 87th	1.00		24x24 State Marker	4.00	
				special ZONE	??x?? ??.00 NO PASSING		1.028	Marian Dr.	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		1.0335	Hillcrest Rd.	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		1.536	EB 87th	1.00		24x12 Detour	2.00	
				special ZONF	??x?? ??.00 NO PASSING		1.536	EB 87th	1.00		21x15 Arrow	2.19	2
				special ZONE	??x?? ??.00 NO PASSING		1.536	EB 87th	1.00		24x24 State Marker	4.00	
				special ZONE	??x?? ??.00 NO PASSING		1.585	EB 87th	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		1.585	EB 87th	1.00		21x15 Arrow	2.19	:
				special ZONE	??x?? ??.00 NO PASSING		1.585	EB 87th	1.00		24x24 State Marker	4.00	
				special ZONE	??x?? ??.00 NO PASSING		1.633	EB 87th	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		1.633	EB 87th	1.00		21x15 Arrow	2.19	:
				special ZONE	??x?? ??.00 NO PASSING		1.633	EB 87th	1.00		24x24 State Marker	4.00	
				special ZONE	??x?? ??.00 NO PASSING		124.355	SB US 71	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		124.355	SB US 71	1.00		24x12 South	2.00	
				special ZONE	??x?? ??.00 NO PASSING		124.355	SB US 71	1.00		21x15 Arrow	2.19	:
				special ZONE	??x?? ??.00 NO PASSING		124.355	SB US 71	1.00		30x24 Interstate Marker	5.00	
				special ZONE	??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		24x12 Detour	2.00	
				special ZONE	??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		24x12 South	2.00	
				special ZONE	??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		21x15 Arrow	2.19	:
				special ZONE	??x?? ??.00 NO PASSING		129.559	SB US 71	1.00		30x24 Interstate Marker	5.00	
				special ZONE	??x?? ??.00 NO PASSING		2.045	Hillcrest	1.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		3.955	EB Banister Rd.	2.00		36x36 Road Work Ahead	9.00	
				special ZONE	??x?? ??.00 NO PASSING		4.048	EB Banister Rd.	2.00		24x36 WZ Speed Limit	6.00	
				R3-7L	30x30 6.25 LEFT LANE URN LEFT		4.099	EB Banister Rd.	1.00	6.25			6
				R3-7L	30x30 6.25 LEFT LANE TURN LEFT		4.196	EB Banister Rd.	1.00	6.25			6
				R3-7L	30x30 6.25 LEFT LANE URN LEFT		4.229	EB Banister Rd.	1.00	6.25			6
							4.00	1	4.00	0.05			_

Revision 4/1/2020 Page 9 of 17

4.23

4.286

4.286

EB Banister Rd.

EB Banister Rd.

EB Banister

1.00

1.00

1.00

6.25

24x12 Detour

21x15 Arrow

2.00

2.19

6.25

2.19

R3-7L 30x30 6.25 LEFT LANE MUST TURN LEFT

special ??x?? ??.00 NO PASSING ZONE

special ??x?? ??.00 NO PASSING ZONE



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
3266	0040	March 8, 2021	453	special ??x?? ??.00 NO PASSING ZONE		4.286	EB Banister Rd.	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO PASSING ZONE		4.286	EB Banister Rd.	1.00		48x24 Semi Trucks	8.00	
				R3-2 48x48 16.00 NO LEFT TURN (SYMBOL)		4.286	EB Banister Rd.	1.00	16			
				WO20-2 48x48 16.00 DETOUR AHEAD		4.325	NB 435	1.00	16			
				special ??x?? ??.00 NO PASSING		4.509	NB 435	1.00		24x12 Detour	2.00	
				Special ??x?? ??.00 NO PASSING		4.509	NB 435	1.00		21x15 Arrow	2.19	2
				Special ??x?? ??.00 NO PASSING		4.509	NB 435	1.00		24x24 State Marker	4.00	
				ZONE WO20-1 48x48 16.00		4.695	NB 435	1.00	16			
				ROAD/BRIDGE/RAMP WORK AHEAD special ??x?? ??.00 NO PASSING		4.972	NB 435	1.00		24x12 Detour	2.00	
				ZONE special ??x?? ??.00 NO PASSING		4.972	NB 435	1.00		21x15 Arrow	2.19	2
				ZONE special ??x?? ??.00 NO PASSING		4.972	NB 435	1.00		24x24 State Marker	4.00	
				ZONE special ??x?? ??.00 NO PASSING		49.992	SB 435	1.00		24x12 Detour	2.00	
				ZONE special ??x?? ??.00 NO PASSING		49.992	SB 435	1.00		21x15 Arrow	2.19	:
				ZONE special ??x?? ??.00 NO PASSING		49.992	SB 435	1.00		24x24 State Marker	4.00	
				ZONE		5.701	WB Banister Rd.	1.00		36x36 Road Work Ahead	9.00	
				ZONE								
				special ??x?? ??.00 NO PASSING ZONE		5.734	NB 435	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING ZONE		5.734	NB 435	1.00		21x15 Arrow	2.19	
				special ??x?? ??.00 NO PASSING ZONE		5.734	NB 435	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO PASSING ZONE		5.773	WB Banister Rd.	1.00		36x36 Left Lane Closed Ahead	9.00	
				special ??x?? ??.00 NO PASSING ZONE		5.778	WB Banister Rd.	1.00		36x36 Left Lane Closed	9.00	
				special ??x?? ??.00 NO PASSING ZONE		5.925	NB 435	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING ZONE		5.925	NB 435	1.00		21x15 Arrow	2.19	
				special ??x?? ??.00 NO PASSING ZONE		5.925	NB 435	1.00		24x24 State Marker	4.00	
				special ??x?? ??.00 NO PASSING ZONE		5.944	WB Banister Rd.	1.00		24x36 WZ Speed Limit	6.00	
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		50.21	SB 435	1.00	16			
				MO4-8a 24x18 3.00 END DETOUR		50.215	SB 435	1.00	3			
				MO4-8a 24x18 3.00 END DETOUR special ??x?? ??.00 NO PASSING		51.833 6.056	SB 435 WB Banister Rd.	1.00	3	30x30 Double Down	6.25	
				ZONE special ??x?? ??.00 NO PASSING		6.256	WB Banister Rd.	2.00		36x36 Left Lane Closed Ahead	9.00	
				ZONE								
				special ??x?? ??.00 NO PASSING ZONE		6.288	WB Banister Rd.	1.00		36x36 Detour Ahead	9.00	
				special ??x?? ??.00 NO PASSING ZONE		6.355	WB Banister Rd.	1.00		30x30 Double Down	6.25	
				special ??x?? ??.00 NO PASSING ZONE		6.405	WB Banister Rd.	1.00		30x30 Double Down	6.25	
				special ??x?? ??.00 NO PASSING ZONE		6.405	WB Banister Rd.	1.00		36x36 Left Lane Closed	9.00	
				special ??x?? ??.00 NO PASSING ZONE		6.405	WB Banister Rd.	1.00		36x36 Merge	9.00	
				special ??x?? ??.00 NO PASSING ZONE		6.453	WB Banister Rd.	1.00		30x30 Double Down	6.25	
				special ??x?? ??.00 NO PASSING ZONE		6.601	WB Banister Rd.	1.00		24x12 Detour	2.00	
				special ??x?? ??.00 NO PASSING ZONE		6.601	WB Banister Rd.	1.00		24x12 South	2.00	
				special ??x?? ??.00 NO PASSING ZONE		6.601	WB Banister Rd.	1.00		21x15 Arrow	2.19	
				special ??x?? ??.00 NO PASSING ZONE		6.601	WB Banister Rd.	1.00		30x24 Interstate Marker	5.00	
				special ??x?? ??.00 NO PASSING ZONE		6.624	WB Banister Rd.	1.00		36x36 No Left Turn	9.00	
				special ??x?? ??.00 NO PASSING		7.192	WB Banister Rd.	1.00		24x12 Detour	2.00	
				ZONE special ??x?? ??.00 NO PASSING		7.192	WB Banister Rd.	1.00		24x12 South	2.00	
				ZONE special ??x?? ??.00 NO PASSING		7.192	WB Banister Rd.	1.00		21x15 Arrow	2.19	
				ZONE special ??x?? ??.00 NO PASSING		7.192	WB Banister Rd.	1.00		30x24 Interstate Marker	5.00	
		March 16,	187	ZONE  WO4-1aR 48x48 16.00 MERGE		49.319	SB 435	1.00	16			
		2021		(SYMBOL FROM RIGHT)			SB 435					
				xx		49.079		2.00	12			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		48.911	SB 435	1.00	16			
				W4-1(48) 48x48 16.00 MERGE EO5-2 48x36 12.00 EXIT OPEN		48.911 50.109	SB 435 SB 435	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		48.255	SB 435	2.00	16			

Revision 4/1/2020 Page 10 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Stone (if applicable)

ect	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
266 0	0040	March 16, 2021	187	W3-2A(48) 48x48 16.00 YIELD AHEAD		0.202	EB 87TH RAMP TO 435 S	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		0.145	EB 87TH RAMP TO 435 S	1.00	16			
				R1-2 48 TRI 6.93 YIELD		49.476	SB 435	1.00	6.93			6.9
				WO20-5 48x48 16:00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		48.591	SB 435	2.00	16			:
		April 12,	368	See Special Sign Details		1.1 to 1.82	EB and WB Linwood	2.00		Road Closed Ahead 36"x36"	9.00	1
		2021		See Special Sign Details		1.034	EB Linwood Blvd	1.00		Right Lane Closed Ahead 36"x36"	9.00	
				See Special Sign Details		1	Flora, Woodland, and Highland	4.00		Road Work Ahead 36"x36"	9.00	:
				See Special Sign Details		0.957	EB Linwood Blvd	1.00		Road Work Ahead 36"x36"	9.00	
				See Special Sign Details		0.833	NB Euclid Ave	2.00		No Left Turn 24"x24"	4.00	
				See Special Sign Details		0.362	SB Michigan Ave	2.00		No Left Turn 24"x24"	4.00	
				See Special Sign Details		0.352	SB Garfield Ave.	1.00		Road Work Ahead 36"x36"	9.00	
				See Special Sign Details		0.349	SB Wayne Ave	1.00		Road Work Ahead 36"x36"	9.00	
				See Special Sign Details		1.109	EB Linwood Blvd	1.00		Right Lane Closed 36"x36"	9.00	
				See Special Sign Details		4.014	NE The Paseo	1.00		Detour Right Arrow 30"x24"	5.00	
				See Special Sign Details		1.275	EB 31st St.	1.00		Detour Up Arrow 30"x24"	5.00	
				See Special Sign Details		1.287 and 2.058	Linwood Blvd on barricades	2.00		Detour 48"x18"	6.00	
				R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC		1.287 to 2.099	Linwood Blvd on barricades	4.00	12.5			Ę
				See Special Sign Details		1.479	EB 31st St	1.00		Detour Right Arrow 30"x24"	5.00	
				See Special Sign Details		1.516 to 2.892	NB and SB Brooklyn Ave.	2.00		Road Work Ahead 36"x36"	9.00	1
				R11-2 48x30 10.00 ROAD CLOSED		1.591 to 2.17	Linwood Blvd on barricades	2.00	10			2
				See Special Sign Details		1.646	NB Brooklyn Ave.	1.00		Detour Left Arrow 30"x24"	5.00	
				See Special Sign Details		1.82	WB Linwood Blvd	1.00		Road Work Ahead 36"x36"	9.00	
				See Special Sign Details		1.847	WB Linwood Blvd	1.00		Right Lane Closed Ahead 36"x36"	9.00	
				See Special Sign Details		1.937	WB Linwood Blvd	1.00		Right Lane Closed 36"x36"	9.00	
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		120.4	SB 71 Hwy	2.00	16			3
				See Special Sign Details		120.45	SB 71 Hwy	2.00		Right Shoulder Closed Ahead 48"x48"	16.00	3
				See Special Sign Details		120.5	SB 71 Hwy	2.00		Right Shoulder Closed 48"x48"	16.00	3
				See Special Sign Details		2.45	WB 31st St.	0.00		Detour Up Arrow 30"x24"	0.00	
				See Special Sign Details		2.455	WB 31st St	1.00		Detour Up Arrow 30"x24"	5.00	
				See Special Sign Details		2.834	WB 31st St	1.00		Detour Left Arrow 30"x24"	5.00	
		April 19, 2021	36	See Special Sign Details		1.657 to 2.546	Euclid, Michigan, and 2x The Paseo	4.00		Road Work Ahead 36"x36"	9.00	
		June 1, 2021	64	W01-4bR 48x48 16.00 DOUBLE ARROW REVERSE CURVE (SYMBOL RIGHT ARROWS)		7.161	NB I-435 at Oldham Rd and Gregory Blvd	4.00	16			6
	0040 - Total			<u></u>			<u> </u>					1107.5

Revision 4/1/2020 Page 11 of 17



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3266	0040	CONSTRUCTION SIGNS	Overrun	Overrun	12	Jun 2, 2021	SYSTEM	(\$588.00)	
				Overrun - T	otal			(\$588.00)	
			Overrun - Tota	al				(\$588.00)	
	0040 -	Total						(\$588.00)	
	0070	CHANNELIZER (TRIM LINE)	Overrun	Overrun	7	Mar 16, 2021	SYSTEM	(\$515.00)	
					8	Apr 2, 2021	SYSTEM	(\$5,665.00)	
					9	Apr 16, 2021	SYSTEM	\$6,180.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',51.50000 - 51.50000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0070 -	Total						\$0.00	
	0160	PREF THERMO PVMT MARK, LT/RT ARROW	Material		12	Jun 2, 2021	SYSTEM	\$3,091.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user watsom1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					12	Jun 2, 2021	SYSTEM	(\$3,091.20)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0160 -	Total						\$0.00	
	0190	4 IN. WHITE WATERBORNE PAVEMENT	Material		12	Jun 2, 2021	SYSTEM	\$201.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user watsom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		MARKING			12	Jun 2, 2021	SYSTEM	(\$201.00)	
					13	Jun 16, 2021	SYSTEM	\$201.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user watsom1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$201.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0190 -	Total						\$0.00	
	0200	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		12	Jun 2, 2021	SYSTEM	\$83.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user watsom1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		WARRING			12	Jun 2, 2021	SYSTEM	(\$83.25)	
					13	Jun 16, 2021	SYSTEM	\$83.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user watsom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$83.25)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0200 -	Total						\$0.00	
	0240	MGS GUARDRAIL	Construction Stockpile STMA		2	Sep 16, 2020	SYSTEM	\$4,775.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$4,775.50	
			Construction	Stockpile STI				\$4,775.50	
			Construction Stockpile STMI	- Total	2	Sep 16, 2020	SYSTEM	\$46,935.00 \$46,935.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Canatinati		M. Total				
			Construction	Stockpile STI	vii - Total			\$46,935.00	
		Total						\$51,710.50	
	0250	MGS BRIDGE APP. TRANS SEC (REG/NO	Construction Stockpile STMI		2	Sep 16, 2020	SYSTEM	\$14,940.00	Payment Estimate Item Adjustment generated Stockpile Transaction





ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
66	0250	CURB)	Construction Stockpile STMI	- Total				\$14,940.00	
			Construction	Stockpile STI	MI - Total			\$14,940.00	
	0250 -	Total						\$14,940.00	
	0270	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile STMI		2	Sep 16, 2020	SYSTEM	\$1,507.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)		- Total				\$1,507.00	
			Construction	Stockpile STI	VII - Total			\$1,507.00	
	0270 -	Total						\$1,507.00	
	0310	HALF-SOLE REPAIR	Overrun	Overrun	13	Jun 16, 2021	SYSTEM	\$23,925.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user watsom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	\$15,013.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user watsom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$38,939.30)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0310 -	Total						\$0.00	
	0390	HALF-SOLE REPAIR	Overrun	Overrun	13	Jun 16, 2021	SYSTEM	\$25,593.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user watsom1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$25,593.70)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0390 -	Total						\$0.00	
	0470	CURB BLOCKOUT	Construction Stockpile STMI	Total	5	Nov 2, 2020	SYSTEM	\$324.55	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$324.55	
			Construction	Stockpile STI	VII - I otal			\$324.55	
	0470 - 0500	REINFORCING STEEL (EPOXY	Construction Stockpile		5	Nov 2, 2020	SYSTEM	<b>\$324.55</b> \$526.23	Payment Estimate Item Adjustment generated Stockpile Transaction
		COATED)	STMI	- Total				\$526.23	
			Construction	Stockpile STI	MI - Total			\$526.23	
	0500 -	Total						\$526.23	
	0530	LATEX MODIFIED CONCRETE	Material		11	May 17, 2021	SYSTEM	\$188,924.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		WEARING SURFACE			11	May 17, 2021	SYSTEM	(\$188,924.80)	
					12	Jun 2, 2021	SYSTEM	\$188,924.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user watsom1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Jun 2, 2021	SYSTEM	(\$188,924.80)	
					13	Jun 16, 2021	SYSTEM	\$188,924.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$188,924.80)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0530 -	Total						\$0.00	
		CLASS B-1	Material		8	Apr 2,	SYSTEM	(\$56,486.02)	
	0540	CONCRETE	Waterial	- Total	Ů	2021		(\$56,486.02)	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3266	0540	CLASS B-1	Material - Tota	ıl				(\$56,486.02)	
		CONCRETE	MaterialCredit		9	Apr 16, 2021	SYSTEM	\$56,486.02	
				- Total		2021		\$56,486.02	
			MaterialCredit					\$56,486.02	
	0540 -	- Total	materiarorean	Total				\$0.00	
	0550	SUBSTRUCTURE	Material		8	Apr 2,	SYSTEM	(\$4,702.35)	
		REPAIR (FORMED)			10	2021 May 3,	SYSTEM	(\$12,161.25)	
						2021			
					13	Jun 16, 2021	SYSTEM	\$12,161.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user watsom1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$12,161.25)	
				- Total		2021		(\$16,863.60)	
			Material - Tota					(\$16,863.60)	
			MaterialCredit		9	Apr 16,	SYSTEM	\$4,702.35	
			Waterlaioredit		3	2021	OTOTEW	ψ+,702.00	
					11	May 17, 2021	SYSTEM	\$12,161.25	
				- Total				\$16,863.60	
			MaterialCredit	- Total				\$16,863.60	
	0550 -	- Total						\$0.00	
	0570	HALF-SOLE REPAIR	Other Item Adjustment	OADJ	11	May 17, 2021	watsom1	\$18,438.00	Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.
					12	Jun 2, 2021	watsom1	(\$18,438.00)	Contractor was paid for this work on estimate 11. This adjustment makes the total of all adjustments 0.
				OADJ - Tota	al l			\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
			Other Item Ad		stal 8	Apr 2, 2021	SYSTEM	<b>\$0.00</b> (\$7,748.35)	
				justment - To	tal		SYSTEM SYSTEM	\$0.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).
				justment - To	stal 8	2021 Apr 16, 2021 May 3,		<b>\$0.00</b> (\$7,748.35)	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
				justment - To	8 9	2021 Apr 16, 2021	SYSTEM	\$0.00 (\$7,748.35) \$7,748.35	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
				justment - To	9 10	2021 Apr 16, 2021 May 3, 2021 May 17,	SYSTEM	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70)	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
				justment - To	9 10 11 12	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00)	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
				justment - To Overrun Overrun - To	9 10 11 12	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
	0570 -	- Total	Overrun	justment - To Overrun Overrun - To	9 10 11 12	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
	<b>0570</b> - 0580	- Total FULL DEPTH REPAIR	Overrun	justment - To Overrun Overrun - To	9 10 11 12 otal	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is
		FULL DEPTH	Overrun - Tota Other Item	justment - To Overrun Overrun - To	9 10 11 12 otal	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021 May 17, 7, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00 \$0.00	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next
		FULL DEPTH	Overrun - Tota Other Item	justment - To Overrun Overrun - To	10 11 12 11 12 12	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021  May 17, 2021  Jun 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM watsom1	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00 \$0.00 \$5,550.60	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.  Contractor was paid for this work on estimate 11. This adjustment makes the
		FULL DEPTH	Overrun - Tota Other Item	Overrun - Total  OADJ - Total	10 11 12 12 12 14 14 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021  May 17, 2021  Jun 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM watsom1	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00 \$0.00 \$5,550.60	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.  Contractor was paid for this work on estimate 11. This adjustment makes the
		FULL DEPTH	Overrun - Tota Other Item Adjustment	Overrun - Total  OADJ - Total	10	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021  May 17, 2021  Jun 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM watsom1 watsom1	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00 \$0.00 \$5,550.60 (\$5,550.60)	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.  Contractor was paid for this work on estimate 11. This adjustment makes the
		FULL DEPTH	Overrun - Tota Other Item Adjustment Other Item Ad	Overrun - Total  OADJ - Tota	110	2021 Apr 16, 2021 May 3, 2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021  Apr 16, 4	SYSTEM SYSTEM SYSTEM SYSTEM watsom1	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00 \$0.00 \$5,550.60 (\$5,550.60)	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.  Contractor was paid for this work on estimate 11. This adjustment makes the
		FULL DEPTH	Overrun - Tota Other Item Adjustment Other Item Ad	Overrun - Total  OADJ - Tota	10	2021 Apr 16, 2021 May 3, 2021 Jun 2, 2021  May 17, 2021  Jun 2, 2021  Apr 16, 2021  May 3,	SYSTEM SYSTEM SYSTEM SYSTEM watsom1 watsom1	\$0.00 (\$7,748.35) \$7,748.35 (\$14,179.70) (\$18,438.00) \$32,617.70 \$0.00 \$0.00 \$5,550.60 (\$5,550.60) \$0.00 (\$6,389.70)	previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).  Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.  Contractor was paid for this work on estimate 11. This adjustment makes the total of all adjustments 0.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',63.80000 - 63.80000, 'is



SEB-Total	ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Octobar   Contraction   Cont	266	0580		Overrun	Overrun					applied (if non-zero).
SENETORING   Sen			REPAIR		Overrun - T	otal			\$0.00	
Contraction Stockyle   S				Overrun - Tota	ıl				\$0.00	
STEEL (EPOXY   Stockage   2021		0580 -	Total						\$0.00	
Construction Stockpile - Total   (28,88.51)   (28,88.51)   Construction Stockpile - Total   (28,88.51)   (28,88.51)   Construction Stockpile - Total   (28,88.51)   Construction Stockpile STM   T		0590	STEEL (EPOXY			8		SYSTEM	(\$2,855.51)	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile   State   Sta			COATED)		- Total				(\$2,855.51)	
Stockpile   STM   -Total				Construction	Stockpile - To	otal			(\$2,855.51)	
Construction Stockpile STMI - Total   \$2,885.51     Material   8				Stockpile		5		SYSTEM	\$2,855.51	Payment Estimate Item Adjustment generated Stockpile Transaction
Material					- Total				\$2,855.51	
Total   (\$9.202.00)				Construction	Stockpile STI	MI - Total			\$2,855.51	
Material - Total  Material Credit  9				Material		8		SYSTEM	(\$9,202.00)	
Material Credit   9									(\$9,202.00)	
2021				Material - Tota	ıl				(\$9,202.00)	
Material Credit - Total   \$9,202.00				MaterialCredit		9		SYSTEM		
Current   Substitution   Stockpile   STMI   Substitution   Stackpile   S										
CURB BLOCKOUT Slockpile Transaction Slockpil				MaterialCredit	- Total					
BLOCKOUT   Stockpile   STMI   -Total   \$2,816.11		0590 -								
Construction   Stockpile STMI - Total		0620		Stockpile		5		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
Construction   Stockpile   Transaction   System   Syste				Construction	Stockpile STI	MI - Total				
SLOCKOUT   Stockpile   STMI   - Total										
Construction Stockpile STMI - Total  0720 CURB BLOCKOUT Stockpile STMI - Total  0720 CURB BLOCKOUT Stockpile STMI - Total  - Total  0720 - Total  0720 - Total  0730 CURB BLOCKOUT Stockpile STMI - Total  0740 CURB BLOCKOUT Stockpile STMI - Total  0750 - T		0670		Stockpile		5		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
10720   CURB   BLOCKOUT   STMI   STMI   Total   S1,875.85   Payment Estimate Item Adjustment generated Stockpile Transaction   Stockpile STMI - Total   S1,875.85				0 1 11						
O720 CURB BLOCKOUT Stockpile STMI - Total S1,875.85  O780 - Total -		0070	Total	Construction	Stocкрие S и	vii - Totai				
STAIL   Stockpile   STMI   -Total   \$1,875.85				Construction		-	New 2	CVCTEM		Decimant Fetimate Item Adjustment generated Steelerile Transcration
Construction Stockpile STMI - Total  7780   CURB BLOCKOUT   Stockpile STMI - Total   S1,875.85    Construction Stockpile STMI   Total   S1,875.85    Construction Stockpile STMI - Total   S1,875.85    Construction Stockpile STMI - Total   S1,875.85    Construction Stockpile STMI - Total   S1,875.85    O780 - Total   STELL (EPOXY COATED)   STMI - Total   S484.82    Construction Stockpile STMI - Total   S484.82    Construction Stockpile STMI - Total   S484.82    Construction Stockpile STMI - Total   S484.82    O950 - Total   S7RIP SEAL EXPANSION JOINT SYSTEM   S13,856.25    Construction Stockpile STMI - Total   S13,856.25    Construction		0720		Stockpile	Total	5		SYSTEM		Payment Estimate item Adjustment generated Stockpile Transaction
CURB   BLOCKOUT   Stockpile   STMI   - Total   S1,875.85   Payment Estimate Item Adjustment generated Stockpile Transaction   Stockpile   STMI   - Total   S1,875.85   Payment Estimate Item Adjustment generated Stockpile Transaction   S1,875.85				Construction		MI Total				
CURB BLOCKOUT Stockpile STMI 5 Nov 2, 2020 SYSTEM \$1,875.85 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total \$1,875.85 STMI STAND STOCKPILE STMI - Total \$1,875.85 STMI STAND STAND STOCKPILE STMI - Total \$1,875.85 STMI STAND S		0720	Total	Sonstruction :	элоскрие от	m - Total				
STMI - Total \$1,875.85  Construction Stockpile STMI - Total \$1,875.85  0780 - Total \$1,875.85  0930 REINFORCING STEEL (EPOXY COATED) 5 Nov 2, 2020 SYSTEM \$484.82 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total \$484.82  Construction Stockpile STMI - Total \$484.82  0930 - Total \$484.82  0930 - Total \$484.82  0950 STRIP SEAL EXPANSION JOINT SYSTEM STMI - Total \$13,856.25  Construction Stockpile STMI - Total \$13,856.25			CURB			5		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
Steel (EPOXY COATED)   STMI   State					- Total				\$1,875.85	
REINFORCING STEEL (EPOXY COATED)  REINFORCING STEEL (EPOXY COATED)  Total  Construction Stockpile STMI - Total  S484.82  Construction Stockpile STMI - Total  S484.82  O950 STRIP SEAL EXPANSION JOINT SYSTEM  STMI  - Total  SYSTEM \$484.82  Payment Estimate Item Adjustment generated Stockpile Transaction  \$484.82  O950 STRIP SEAL EXPANSION Stockpile STMI - Total  SYSTEM \$13,856.25  Construction Stockpile STMI - Total  \$13,856.25  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment				Construction	Stockpile STI	MI - Total			\$1,875.85	
STEEL (EPOXY COATED)  - Total  - Total  - Total  - Total  - Total  - Total  S484.82  Construction Stockpile STMI - Total  S484.82  0930 - Total  STRIP SEAL  EXPANSION  JOINT SYSTEM  - Total  - Total  - Total  - Total  SYSTEM  - Total  S13,856.25  Construction Stockpile STMI - Total  S13,856.25  Total  S13,856.25  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment		0780 -	Total						\$1,875.85	
Total   \$484.82		0930	STEEL (EPOXY	Stockpile		5		SYSTEM	\$484.82	Payment Estimate Item Adjustment generated Stockpile Transaction
9930 - Total  STRIP SEAL EXPANSION JOINT SYSTEM  STMI  - Total  Construction Stockpile STMI - Total  S13,856.25  Construction Stockpile STMI - Total  \$13,856.25  Construction Stockpile STMI - Total  \$13,856.25  O950 - Total  \$13,856.25  D050 - Total  \$13,856.25  SYSTEM \$13,856.25  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment			COATED)	STIVII	- Total				\$484.82	
O950 STRIP SEAL Construction Stockpile STMI 3 Oct 1, 2020 SYSTEM \$13,856.25 Payment Estimate Item Adjustment generated Stockpile Transaction \$13,856.25 STMI \$				Construction	Stockpile STI	MI - Total			\$484.82	
EXPANSION JOINT SYSTEM		0930 -	Total						\$484.82	
- Total \$13,856.25  Construction Stockpile STMI - Total \$13,856.25  0950 - Total \$13,856.25  1060 CLASS B-2 CONCRETE 2021 SYSTEM \$48,810.58 Estimate Item Adjustment (0009) due to user watsom1 overridding Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment		0950	EXPANSION	Stockpile		3		SYSTEM	\$13,856.25	Payment Estimate Item Adjustment generated Stockpile Transaction
0950 - Total     \$13,856.25       1060     CLASS B-2 CONCRETE     Material     12 Jun 2, 2021     SYSTEM \$48,810.58     This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment			JOHN STOTEW	CTIVII	- Total				\$13,856.25	
1060 CLASS B-2 CONCRETE 12 Jun 2, SYSTEM \$48,810.58 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Paymen				Construction	Stockpile STI	MI - Total			\$13,856.25	
CONCRETE 2021 Estimate Item Adjustment (0009) due to user watsom1 overridding Paymen		0950 -	Total						\$13,856.25	
		1060		Material		12		SYSTEM	\$48,810.58	Estimate Item Adjustment (0009) due to user watsom1 overridding Payment
12 Jun 2, 2021 (\$48,810.58)						12		SYSTEM	(\$48,810.58)	,



Construction   Construction   Construction   Stockpile   Total   Stockpile   Construction   Stockpile   Stimul   Stimu		Remarks	Amount	Created By	Created Date	Est. Number	Other Adjustment Type	Adjustment Type	Description	Line
Material - Total   \$0.00			\$0.00					Material	CLASS B-2	1060
REINFORCING STEEL (EPOXY COATED)  - Total  Construction Stockpile - Total  Construction Stockpile   12			\$0.00					Material - Tota	CONCRETE	
STEEL (EPOXY COATED)  - Total  Construction Stockpile - Total  Construction Stockpile STMI  - Total  Construction Stockpile STMI  - Total  Construction Stockpile STMI - Total  S1,712.91  Construction Stockpile STMI - Total  S1,712.91  Construction Stockpile STMI - Total  S1,712.91  S1,712.91  S1,712.91  S1,712.91  STRIP SEAL EXPANSION Stockpile STMI - Total  S1,712.91			\$0.00						- Total	1060 -
Construction Stockpile - Total  Construction Stockpile - Total  Construction Stockpile - Total  Construction Stockpile STMI  - Total  Construction Stockpile STMI - Total  Solution Stockpile STMI - Total	I	Payment Estimate Item Adjustment generated Stockpile Transaction	(\$1,712.91)	SYSTEM		12			STEEL (EPOXY	1080
Construction Stockpile STMI  - Total  Construction Stockpile STMI  - Total  Construction Stockpile STMI - Total  S1,712.91  Construction Stockpile STMI - Total  S1,712.91			(\$1,712.91)				- Total		COATED)	
Stockpile STMI - Total \$1,712.91  Construction Stockpile STMI - Total \$1,712.91  1080 - Total \$1,712.91  STRIP SEAL Construction Stockpile STMI - Total \$0.00  1100 STRIP SEAL Construction Stockpile 12 Jun 2, 2021 SYSTEM (\$38,590.03) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI SYSTEM (\$38,590.03)			(\$1,712.91)			otal	Stockpile - To	Construction		
- Total \$1,712.91  Construction Stockpile STMI - Total \$1,712.91  1080 - Total \$0.00  STRIP SEAL EXPANSION Stockpile Transaction Sto	ı	Payment Estimate Item Adjustment generated Stockpile Transaction	\$1,712.91	SYSTEM		5		Stockpile		
1080 - Total \$0.00  1100 STRIP SEAL EXPANSION Stockpile 12 Jun 2, 2021 Payment Estimate Item Adjustment generated Stockpile Transaction 2021										
1100 STRIP SEAL Construction Stockpile Transaction Stockpile Unit System Stockpile Transaction Stockpile Transaction System System System System Stockpile Transaction System System System System Stockpile Transaction System Sy						VII - Total	Stockpile STI	Construction		
EXPANSION Stockpile 2021  JOINT SYSTEM										
	1	Payment Estimate Item Adjustment generated Stockpile Transaction	, ,	SYSTEM		12				1100
- Total (\$38,590.03)								0 1 11		
Construction Stockpile - Total (\$38,590.03)				OVOTEN	0.14		Stockpile - 10			
Stockpile 2020	i	Payment Estimate Item Adjustment generated Stockpile Transaction	\$38,590.03	SYSTEM		3		Stockpile		
- Total \$38,590.03			\$38,590.03				- Total	SIMI		
Construction Stockpile STMI - Total \$38,590.03			\$38,590.03			VII - Total	Stockpile STI	Construction		
1100 - Total \$0.00			\$0.00						- Total	1100 -
REINFORCING STEEL (EPOXY COATED)  10 May 3, 2YSTEM (\$1,390.36) Payment Estimate Item Adjustment generated Stockpile Transaction 2021	ı	Payment Estimate Item Adjustment generated Stockpile Transaction	(\$1,390.36)	SYSTEM		10			STEEL (EPOXY	1140
- Total (\$1,390.36)			(\$1,390.36)				- Total		COATED)	
Construction Stockpile - Total (\$1,390.36)			(\$1,390.36)			otal	Stockpile - To	Construction		
Construction 5 Nov 2, SYSTEM \$1,390.36 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI	ı	Payment Estimate Item Adjustment generated Stockpile Transaction	\$1,390.36	SYSTEM		5		Stockpile		
- Total \$1,390.36			\$1,390.36				- Total	O T WII		
Construction Stockpile STMI - Total \$1,390.36			\$1,390.36			MI - Total	Stockpile STI	Construction		
1140 - Total \$0.00			\$0.00						- Total	1140 -
1160 STRIP SEAL Construction Stockpile 10 May 3, SYSTEM (\$17,280.62) Payment Estimate Item Adjustment generated Stockpile Transaction 2021 Payment Estimate Item Adjustment generated Stockpile Transaction 2021	1	Payment Estimate Item Adjustment generated Stockpile Transaction	(\$17,280.62)	SYSTEM		10			EXPANSION	1160
11 May 17, 2021 SYSTEM (\$17,280.63) Payment Estimate Item Adjustment generated Stockpile Transaction	ı	Payment Estimate Item Adjustment generated Stockpile Transaction	(\$17,280.63)	SYSTEM		11			00	
- Total (\$34,561.25)										
Construction Stockpile - Total (\$34,561.25)			(\$34,561.25)			otal	Stockpile - To	Construction		
Stockpile 2020 STMI		Payment Estimate Item Adjustment generated Stockpile Transaction		SYSTEM		3		Stockpile		
- Total \$34,561.25										
Construction Stockpile STMI - Total \$34,561.25						VII - Total	Stockpile STI	Construction		
1160 - Total \$0.00										
STEEL (EPOXY   Stockpile   2020   COATED)   STMI	i	Payment Estimate Item Adjustment generated Stockpile Transaction		SYSTEM		5		Stockpile	STEEL (EPOXY	1210
- Total \$1,931.95										
Construction Stockpile STMI - Total \$1,931.95						VII - Total	Stockpile STI	Construction		
1210 - Total \$1,931.95										
EXPANSION Stockpile 2020  JOINT SYSTEM STMI		Payment Estimate Item Adjustment generated Stockpile Transaction		SYSTEM		3		Stockpile	EXPANSION	1230
- Total \$38,590.03										
Construction Stockpile STMI - Total \$38,590.03						VII - Total	Stockpile STI	Construction		
1230 - Total \$38,590.03				a) / = =						
5001 IMPACT Material 12 Jun 2, SYSTEM \$6,834.56 This adjustment offsets the original system-generated Material Payr		This adjustment offsets the original system-generated Material Paym Estimate Item Adjustment (0011) due to user watsom1 overridding P Estimate Exception 3 on the current Payment Estimate.	\$6,834.56	SYSTEM	Jun 2, 2021	12		Material	ATTENUATOR 65 MPH (SAND	5001
ATTENUATOR 65 2021 Estimate Item Adjustment (0011) due to user watsom1 overridding F MPH (SAND Estimate Exception 3 on the current Payment Estimate.			(\$6,834.56)	SYSTEM	Jun 2, 2021	12			DAKKEL AKKAY)	
ATTENUATOR 65 MPH (SAND BARREL ARRAY)  2021 Estimate Item Adjustment (0011) due to user watsom1 overridding F Estimate Exception 3 on the current Payment Estimate.										

Jun 17, 2021



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3266	5001	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY) Material - Total						\$0.00	
	5001 -	01 - Total						\$0.00	
	5007	MISC.	Material		12	Jun 2, 2021	SYSTEM	\$10,745.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Jun 2, 2021	SYSTEM	(\$10,745.28)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5007 - Total							\$0.00	
	5010	PREF THERMO PVMT MARK, 24 IN WHIT	Material		12	Jun 2, 2021	SYSTEM	\$970.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Jun 2, 2021	SYSTEM	(\$970.20)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5010 - Total							\$0.00	
J4P3266 -	J4P3266 - Total							\$132,667.25	
Overall - Total							\$132,667.25		