Pay Estimate Created Date: July 18, 2022

Progress Estimate N 34	umber	Contract ID Prime Contractor	200417-C03 Comanche Const	truction, Inc.			Original Contract Amount Net Change Order Amount Current Contract Amount	
Approval Date								By User
July 18, 2022			Generated and A	Approved (ar	nd should be consid	lered Draft) at	the Project Office Level by	baldwc2
July 18, 2022		Re	eviewed and Appro	oved (and sh	ould be considered	Draft) at the F	lesident Engineer Level by	penner1
July 19, 2022			I	Controllers Office Level by	ramses1			
Original Completion	n Date	Current Con	pletion Date	Actual	Completion Date	%	of Current Contract Amount	Complete
November 5, 202	21	August	26, 2022			96.13%		
	Contrac	t Informational Dat	tes		Milestor	nes		
Date Description	Origina	I Completion Date	Current Comple	tion Date	No Milestones Exis	t for Contract		
Acceptance Date								
Awarded Date	May 6, 2	2020	May 6, 2020					
Letting Date	May 4, 2	2020	May 4, 2020					
Notice to Proceed Date	July 6, 2	2020	July 6, 2020					
Open to Traffic Date								
Work Began Date	March 8	, 2021	March 8, 2021					

Contract Total Pay For Es	stimate No. 34				
		This Estimate	Previous	To Date	
200417-C03					
Tot	tal Posted Items Pay	\$21,185.50	\$5,473,329.61	\$5,494,515.11	
Gro	oss Item Adjustments	(\$4,741.20)	\$0.00	(\$4,741.20)	
Inc	entive	\$0.00	\$0.00	\$0.00	
Dis	sincentive	\$0.00	\$0.00	\$0.00	
Liq	uidated Damage	\$0.00	\$0.00	\$0.00	
Oth	her Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$5,473,329.61	\$5,489,773.91	
Contract Total Payable Th	nis Estimate:	\$16,444.30			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3266	0730	7040104	HALF-SOLE REPAIR	SQFT	\$43.900	345	\$15,145.50
	0740	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	SQFT	\$75.500	80	\$6,040.00
Project J4P326	6 - Total						\$21,185.50
Overall - Total							\$21,185.50

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3266	0640	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material			-429	\$75.50	(\$32,389.50)
	0640	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	429	\$75.50	\$32,389.50
	0730	HALF-SOLE REPAIR	Overrun			-108	\$43.90	(\$4,741.20)
Total								(\$4,741.20)



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4P3266	FAS S302(002	Bridge Rehabilitation	Various	VARIOUS	at various locations th	nroughout the urban Kansas	City district
Totals by J	Job Numbe	rs					
J4P3266		d Item Pay Item Adjustmer	nts Gross Ite	em Pay	This Estimate \$21,185.50 (\$4,741.20) \$16,444.30	Previous \$5,473,329.61 \$0.00 \$5,473,329.61	To Date \$5,494,515.11 (\$4,741.20) \$5,489,773.91
	Liquid	tive centive lated Damages Contract Adjust	ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3266, Item 7040112, Project Item Line Number 0640, Material Set 704011296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Working with MoDOT materials to resolve the discrepancy.	baldwc2	Overridden
Estimate Exception Type: Item Overrun: Contract 200417-C03, Contract Project J4P3266, Project Item Line Number 0730, Contract Line Item Number 0730, Item 7040104, Minor Item.	A Change Order is being developed to resolve the overrun of quantities.	baldwc2	Acknowledged

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

lote: Posted Q	uantities	and Valu	es are b	pased on R	eport Generated date and can differ from the posted amo	ount at the	time the E	stimate was	s Genera	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$113,120.00	\$113,120.00
		0001	0020	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	153.00	-153.00	0.00	SQFT	0.00	\$67.35	\$0.00
		0001	0030	4030007	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095BSM MIX)	231.20	0.00	231.20	TONS	152.08	\$432.80	\$65,820.22
		0001	0040	6161005	CONSTRUCTION SIGNS	1,078.00	490.00	1,568.00	SQFT	1,568.00	\$19.60	\$30,732.80
		0001	0050	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	-4.00	4.00	EA	4.00	\$309.15	\$1,236.60
		0001	0060	6161009	FLAG ASSEMBLY	8.00	-8.00	0.00	EA	0.00	\$103.05	\$0.00
		0001	0070	6161025	CHANNELIZER (TRIM LINE)	210.00	120.00	330.00	EA	330.00	\$51.50	\$16,995.00
		0001	0080	6161030	TYPE III MOVEABLE BARRICADE	16.00	8.00	24.00	EA	24.00	\$412.20	\$9,892.80
		0001	0090	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$5,152.30	\$20,609.20
		0001	0100	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$17,002.60	\$68,010.40
		0001	0105	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$7,728.45	\$7,728.45
		0001	0110	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,230.00	2,582.50	3,812.50	LF	3,812.50	\$19.75	\$75,296.88
		0001	0120	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR	1,289.00	341.00	1,630.00	LF	1,630.00	\$29.75	\$48,492.50
		0001	0130	6174000A	FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	6.00	0.00	6.00	EA	6.00	\$497.85	\$2,987.10
		0001	0140	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	6,444.00	-4,536.50	1,907.50	LF	1,907.50	\$9.95	\$18,979.62
		0001	0150	6181000	MOBILIZATION	1.00	-1.00	0.00	LS		\$406,875.00	\$0.00
		0001	0151	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00		\$388,169.00
		0001	0160	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	16.00	-4.00	12.00	EA	12.00	\$257.60	\$3,091.20
		0001	0170	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,271.00	13,759.00	18,030.00	LF	13,093.00	\$0.30	\$3,927.90
		0001	0180	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,458.00	8,197.00	9,655.00	LF	5,729.00	\$0.30	\$1,718.70
		0001	0190	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,640.00	-300.00	1,340.00	LF	1,340.00	\$0.15	\$201.00
		0001	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	5,071.00	-1,881.00	3,190.00	LF	3,190.00	\$0.15	\$478.50
		0001	0210	6207001	PAVEMENT MARKING REMOVAL	20,939.00	57,548.00	78,487.00	LF	73,515.00	\$2.25	\$165,408.75
		0001	0220	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	18,663.00	44,995.00	63,658.00	LF	63,658.00	\$2.25	\$143,230.50
		0001	0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,534.00	153.20	2,687.20	SQYD	2,687.20	\$26.50	\$71,210.80
		0010	0240	6061060	MGS GUARDRAIL	5,588.00	25.00	5,613.00	LF	5,613.00	\$19.05	\$106,927.65
		0010	0250	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	12.00	0.00	12.00	EA	12.00	\$2,833.75	\$34,005.00
		0010	0260	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	2.00	\$875.90	\$1,751.80
		0010	0270	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	6.00	0.00	6.00	EA	6.00	\$2,627.65	\$15,765.90
		0070	0280	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,665.00	0.00	8,665.00	SQFT	8,665.00	\$2.80	\$24,262.00
		0070	0290	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,818.40	\$1,818.40
		0070	0300	5050001	OPTIONAL CONCRETE WEARING SURFACE	963.00	0.00	963.00	SQYD	963.00	\$91.80	\$88,403.40
		0070	0310	7040104	HALF-SOLE REPAIR	450.00	2,125.00	2,575.00	SQFT	2,575.00	\$43.90	\$113,042.50
		0071	0320	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,665.00	0.00	8,665.00	SQFT	8,665.00	\$2.80	\$24,262.00
		0071	0330	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,818.40	\$1,818.40
		0071	0340	5050001	OPTIONAL CONCRETE WEARING SURFACE	963.00	0.00	963.00	SQYD	963.00	\$91.80	\$88,403.40
		0071	0350	7040104	HALF-SOLE REPAIR	450.00	7,322.00	7,772.00	SQFT	7,772.00	\$43.90	\$341,190.80
		0072	0360	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8,230.00	0.00	8,230.00	SQFT	8,230.00	\$2.80	\$23,044.00
		0072	0370	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,818.40	\$1,818.40
		0072	0380	5050001	OPTIONAL CONCRETE WEARING SURFACE	914.00	0.00	914.00	SQYD	914.00	\$91.80	\$83,905.20
		0072	0390	7040104	HALF-SOLE REPAIR	400.00	1,212.00	1,612.00	SQFT	1,612.00	\$43.90	\$70,766.80
		0072	0400	7040106	FULL DEPTH REPAIR	100.00	-28.00	72.00	SQFT	72.00	\$63.80	\$4,593.60
		0073	0410	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,330.00	0.00	9,330.00	SQFT	9,330.00	\$2.60	\$24,258.00
		0073	0420	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	1.00	\$11,742.65	\$11,742.65

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

om the posted amount at the time the Estimate was Generated and can diffe Ν

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
00417-C03	J4P3266	0073	0430	2164000	CURB REMOVAL	10.00	0.00	10.00	LF	10.00	\$275.85	\$2,758.5
		0073	0440	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,818.40	\$1,818.4
		0073	0450	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,037.00	0.00	1,037.00	SQYD	1,037.00	\$91.80	\$95,196.0
		0073	0460	7034001	CLASS B-1 CONCRETE	4.20	0.00	4.20	CUYD	4.20	\$3,283.90	\$13,792.3
		0073	0470	7034600	CURB BLOCKOUT	21.00	0.00	21.00	LF	21.00	\$314.05	\$6,595.0
		0073	0480	7040104	HALF-SOLE REPAIR	450.00	2,340.50	2,790.50	SQFT	2,790.50	\$43.90	\$122,502.9
		0073	0490	7040106	FULL DEPTH REPAIR	100.00	56.00	156.00	SQFT	156.00	\$63.80	\$9,952.
		0073	0500	7101000	REINFORCING STEEL (EPOXY COATED)	790.00	0.00	790.00	LB	790.00	\$2.45	\$1,935.
		0074	0510	2161502	REMOVAL OF CONCRETE WEARING SURFACE	12,442.00	0.00	12,442.00	SQFT	12,442.00	\$2.05	\$25,506.
		0074	0520	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	243.00	0.00	243.00	LF	243.00	\$321.05	\$78,015.
		0074	0530	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,376.00	0.00	1,376.00	SQYD	1,376.00	\$137.30	\$188,924.
		0074	0540	7034001	CLASS B-1 CONCRETE	16.30	0.00	16.30	CUYD	16.30	\$3,465.40	\$56,486.
		0074	0550	7040101	SUBSTRUCTURE REPAIR (FORMED)	200.00	-125.00	75.00	SQFT	75.00	\$162.15	\$12,161.
		0074	0560	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	500.00	-500.00	0.00	SQFT	0.00	\$162.15	\$0.
		0074	0570	7040104	HALF-SOLE REPAIR	1,850.00	5,393.00	7,243.00	SQFT	7,243.00	\$43.90	\$317,967.
		0074	0580	7040106	FULL DEPTH REPAIR	600.00	887.00	1,487.00	SQFT	1,487.00	\$63.80	\$94,870.
		0074	0590	7101000	REINFORCING STEEL (EPOXY COATED)	4,280.00	0.00	4,280.00	LB	4,280.00	\$2.15	\$9,202.
		0075	0600	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,139.00	0.00	9,139.00	SQFT	9,139.00	\$2.70	\$24,675.
		0075	0610	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,015.00	0.00	1,015.00	SQYD	0.00	\$91.80	\$0
		0075	0620	7034600	CURB BLOCKOUT	509.00	0.00	509.00	LF	509.00	\$97.20	\$49,474
		0075	0630	7040104	HALF-SOLE REPAIR	900.00	900.00	1,800.00	SQFT	1,577.00	\$43.90	\$69,230
		0075	0640	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	450.00	550.00	1,000.00	SQFT	729.00	\$75.50	\$55,039
		0076	0650	2161502	REMOVAL OF CONCRETE WEARING SURFACE	9,139.00	0.00	9,139.00	SQFT	9,139.00	\$2.70	\$24,675
		0076	0660	5050001	OPTIONAL CONCRETE WEARING SURFACE	1,015.00	0.00	1,015.00	SQYD	1,015.00	\$91.80	\$93,177
		0076	0670	7034600	CURB BLOCKOUT	509.00	0.00	509.00	LF	509.00	\$98.00	\$49,882
		0076	0680	7040104	HALF-SOLE REPAIR	900.00	2,005.00	2,905.00	SQFT	2,905.00	\$43.90	\$127,529
		0076	0690	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	450.00	610.00	1,060.00	SQFT	1,060.00	\$75.50	\$80,030
		0077	0700	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,187.00	0.00	5,187.00	SQFT	5,187.00	\$4.35	\$22,563
		0077	0710	5050001	OPTIONAL CONCRETE WEARING SURFACE	576.00	0.00	576.00	SQYD	0.00	\$91.80	\$0
		0077	0720	7034600	CURB BLOCKOUT	301.00	0.00	301.00	LF	301.00	\$124.00	\$37,324
		0077	0730	7040104	HALF-SOLE REPAIR	500.00	0.00	500.00	SQFT	608.00	\$43.90	\$26,691
		0077	0740	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	250.00	0.00	250.00	SQFT	240.00	\$75.50	\$18,120
		0077	0750	7040113	CLEANING AND EPOXY COATING	990.00	0.00	990.00	SQFT	990.00	\$5.50	\$5,445
		0078	0760	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,187.00	0.00	5,187.00	SQFT	5,187.00	\$4.35	\$22,563
		0078	0770	5050001	OPTIONAL CONCRETE WEARING SURFACE	576.00	0.00	576.00	SQYD	576.00	\$91.80	\$52,876
		0078	0780	7034600	CURB BLOCKOUT	301.00	0.00	301.00	LF	301.00	\$124.00	\$37,324
		0078	0790	7040104	HALF-SOLE REPAIR	500.00	-179.00	321.00	SQFT	321.00	\$43.90	\$14,091
		0078	0800	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	250.00	-162.00	88.00	SQFT	88.00	\$75.50	\$6,644
		0078	0810	7040113	CLEANING AND EPOXY COATING	990.00	0.00	990.00	SQFT	990.00	\$5.50	\$5,445
		0079	0820	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	144.00	0.00	144.00	LF	144.00	\$45.75	\$6,588
		0079	0830	2169903	MISC.REMOVAL AND REINSTALLATION OF SIDEWALK SKID	30.00	0.00	30.00	LF	30.00	\$261.45	\$7,843
			0840	7110200	PLATE PROTECTIVE COATING - CONCRETE BENTS AND PIERS		0.00					
		0079			(EPOXY)	1.00		1.00	LS	1.00	\$7,120.50	\$7,120
		0079	0850	7171002	PREFORMED COMPRESSION SEAL	110.00	0.00	110.00	LF	110.00	\$95.15	\$10,466
		0080	0860	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	196.00	0.00	196.00	LF	196.00	\$45.75	\$8,967.
		0080	0870	2169903	MISC.REMOVAL AND REINSTALLATION OF SIDEWALK SKID PLATE	26.00	0.00	26.00	LF	26.00	\$301.65	\$7,842.



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at the	time the E	Estimate was	Gener	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0080	0880	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$7,812.95	\$7,812.95
		0080	0890	7171002	PREFORMED COMPRESSION SEAL	165.00	0.00	165.00	LF	165.00	\$95.15	\$15,699.75
		0081	0900	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	63.00	0.00	63.00	LF	63.00	\$704.60	\$44,389.80
		0081	0910	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	12.00	\$709.90	\$8,518.80
		0081	0920	7034214	CLASS B-2 CONCRETE	5.90	0.00	5.90	CUYD	5.90	\$2,888.20	\$17,040.38
		0081	0930	7101000	REINFORCING STEEL (EPOXY COATED)	730.00	0.00	730.00	LB	730.00	\$3.55	\$2,591.50
		0081	0940	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$3,634.45	\$3,634.45
		0081	0950	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	63.00	0.00	63.00	LF	63.00	\$380.05	\$23,943.15
		0082	0960	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	92.00	0.00	92.00	LF	92.00	\$45.75	\$4,209.00
		0082	0970	7171002	PREFORMED COMPRESSION SEAL	92.00	0.00	92.00	LF	92.00	\$95.15	\$8,753.80
		0083	0980	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	92.00	0.00	92.00	LF	92.00	\$45.75	\$4,209.00
		0083	0990	7171002	PREFORMED COMPRESSION SEAL	92.00	0.00	92.00	LF	92.00	\$95.15	\$8,753.80
		0084	1000	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	192.00	0.00	192.00	LF	192.00	\$45.75	\$8,784.00
		0084	1010	7049903	MISC.RAISED MEDIAN REPAIR	40.00	-40.00	0.00	LF	0.00	\$122.70	\$0.00
		0084	1020	7171002	PREFORMED COMPRESSION SEAL	192.00	0.00	192.00	LF	192.00	\$95.15	\$18,268.80
		0085	1030	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	193.00	0.00	193.00	LF	193.00	\$448.95	\$86,647.35
		0085	1040	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	12.00	\$709.90	\$8,518.80
		0085	1050	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	24.00	\$166.85	\$4,004.40
		0085	1060	7034214	CLASS B-2 CONCRETE	16.90	0.00	16.90	CUYD	16.90	\$2,888.20	\$48,810.58
		0085	1070	7049903	MISC.RAISED MEDIAN REPAIR	20.00	0.00	20.00	LF	20.00	\$122.75	\$2,455.00
		0085	1080	7101000	REINFORCING STEEL (EPOXY COATED)	2,570.00	0.00	2,570.00	LB	2,570.00	\$2.70	\$6,939.00
		0085	1090	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$4,907.05	\$4,907.05
		0085	1100	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	163.00	0.00	163.00	LF	163.00	\$380.05	\$61,948.15
		0086	1110	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	162.00	0.00	162.00	LF	162.00	\$448.95	\$72,729.90
		0086	1120	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	24.00	\$122.75	\$2,946.00
		0086	1130	7034214	CLASS B-2 CONCRETE	15.30	0.00	15.30	CUYD	15.30	\$2,888.20	\$44,189.46
		0086	1140	7101000	REINFORCING STEEL (EPOXY COATED)	2,080.00	0.00	2,080.00	LB	2,080.00	\$3.05	\$6,344.00
		0086	1150	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$6,167.30	\$6,167.30
		0086	1160	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	162.00	0.00	162.00	LF	162.00	\$380.05	\$61,568.10
		0087	1170	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	192.00	0.00	192.00	LF	192.00	\$448.95	\$86,198.40
		0087	1180	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	12.00	0.00	12.00	LF	12.00	\$709.90	\$8,518.80
		0087	1190	2169904	MISC.REMOVE AND REPLACE RAISED MEDIAN CURB	24.00	0.00	24.00	SQFT	24.00	\$122.75	\$2,946.00
		0087	1200	7034214	CLASS B-2 CONCRETE	17.20	0.00	17.20	CUYD	17.20	\$2,888.20	\$49,677.04
		0087	1210	7101000	REINFORCING STEEL (EPOXY COATED)	2,900.00	0.00	2,900.00	LB	2,900.00	\$3.10	\$8,990.00
		0087	1220	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$4,118.75	\$4,118.75
		0087	1230	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	162.00	0.00	162.00	LF	162.00	\$380.05	\$61,568.10
		0088	1240	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	185.00	15.00	200.00	LF	200.00	\$45.75	\$9,150.00
		0088	1250	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$6,380.60	\$6,380.60
		0088	1260	7171002	PREFORMED COMPRESSION SEAL	185.00	15.00	200.00	LF	200.00	\$95.15	\$19,030.00
		0001	5001	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	0.00	2.00	2.00	EA	2.00	\$3,417.28	\$6,834.56
		0001	5002	6122030	IMPACT ATTENUATOR (RELOCATION)	0.00	10.00	10.00	EA	10.00	\$1,257.22	\$12,572.20
		0001	5003	6122020	REPLACEMENT SAND BARREL	0.00	0.00	0.00	EA	0.00	\$526.52	\$0.00
		0001	5004	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$18,706.00	\$18,706.00
		0001	5005	9029901	MISC.SIGNAL MODIFICATION	0.00	1.00	1.00	LS	1.00	\$5,224.89	\$5,224.89



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					eport Generated date and can differ from the posted amo						Linit Daina	
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-C03	J4P3266	0074	5006	7049904	MISC.Clean and Epoxy Seal	0.00	910.00	910.00	SQFT	910.00	\$12.88	\$11,720.80
		0001	5007	4039910	MISC.ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125B MIX)	0.00	19.20	19.20	TONS	19.20	\$559.65	\$10,745.28
		0001	5008	6189901	MISC.MOBILIZATION FOR ASPHALT TIE-IN PAVEMENT	0.00	1.00	1.00	LS	1.00	\$3,150.00	\$3,150.00
		0001	5009	4071005	TACK COAT	0.00	274.00	274.00	GAL	195.00	\$2.63	\$512.85
		0001	5010	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	0.00	44.00	44.00	LF	44.00	\$22.05	\$970.20
		0001	5011	4039910	MISC.SP125C (70-22) (100.1-500 TONS) (OVER 9 FEET WIDE)	0.00	417.70	417.70	TONS	417.70	\$94.37	\$39,418.35
		0072	5012	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	0.00	3,372.40	3,372.40	SQYD	3,372.40	\$9.95	\$33,555.38
		0001	5013	4071005	TACK COAT	0.00	412.00	412.00	GAL	412.00	\$4.16	\$1,713.92
		0001	5014	6189902	MISC.MOBILIZATION COLDMILLING & RESURFACING (15-1000 tons)	0.00	4.00	4.00	EA	4.00	\$5,617.50	\$22,470.00
		0001	5015	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	0.00	0.00	0.00	LB	0.00	\$6.83	\$0.00
		0001	5016	6189901	MISC.MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$2,205.00	\$2,205.00
		0087	5017	6169902	MISC.ADA BARRICADE	0.00	4.00	4.00	EA	4.00	\$110.25	\$441.00
		0070	5018	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	0.00	691.00	691.00	LF	691.00	\$20.35	\$14,061.85
		0081	5019	7040101	SUBSTRUCTURE REPAIR (FORMED)	0.00	20.00	20.00	SQFT	20.00	\$162.15	\$3,243.00
		0073	5020	1046002	VALUE ENGINEERING	0.00	35,298.30	35,298.30	EA	35,298.30	\$1.00	\$35,298.30
		0073	5021	2169901	MISC.REMOVAL BY JACK HAMMERING	0.00	1.00	1.00	LS	1.00	\$9,714.11	\$9,714.11
		0001	5022	6169901	MISC.MOBILIZATION FOR CMS BOARDS	0.00	1.00	1.00	LS	1.00	\$1,575.00	\$1,575.00
		0073	5023	6069901	MISC.GUARDRAIL REMOVAL AND INSTALL	0.00	1.00	1.00	LS	1.00	\$12,384.66	\$12,384.66
		0001	5024	2071000	LINEAR GRADING CLASS 1	0.00	5.00	5.00	STA	5.00	\$313.53	\$1,567.65
		0010	5025	6069902	MISC.DUARDRAIL POSTS DRILLED IN CONCRETE FLUMES	0.00	55.00	55.00	EA	53.00	\$194.25	\$10,295.25
		0001	5026	4030003	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	0.00	96.00	96.00	TONS	96.00	\$155.40	\$14,918.40
		0001	5027	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	0.00	22.00	22.00	SQYD	22.00	\$65.63	\$1,443.86
		0071	5028	7040113	CLEANING AND EPOXY COATING	0.00	16.00	16.00	SQFT	16.00	\$5.50	\$88.00
		0079	5029	6189901	MISC.MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$988.37	\$988.37
		0001	5030	4019910	MISC.SHOULDER MIX (100.1-500 TONS)(4.1-9 FEET WIDE)	0.00	138.00	138.00	TONS	138.00	\$82.95	\$11,447.10
		0001	5031	4019910	MISC.SHOULDER MIX (15-100 TONS) (2-4 FEET WIDE)	0.00	110.70	110.70	TONS	110.70	\$128.10	\$14,180.67
		0001	5032	6229905	MISC.MILLING per SY (>6")	0.00	418.00	418.00	SQYD	418.00	\$7.56	\$3,160.08
		0001	5033	6229905	MISC.MILLING per SY (2"-4")	0.00	220.00	220.00	SQYD	220.00	\$2.52	\$554.40
		0001	5034	6189902	MISC.MOBILIZATION COLDMILL & RESURFACING (15-1000 TONS)	0.00	1.00	1.00	EA	1.00	\$5,250.00	\$5,250.00
		0001	5035	4071005	TACK COAT	0.00	19.00	19.00	GAL	19.00	\$3.89	\$73.91
		0001	5036	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	0.00	182.80	182.80	TONS	182.80	\$157.50	\$28,791.00
		0001	5037	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	0.00	1,205.00	1,205.00	SQYD	1,205.00	\$52.50	\$63,262.50
		0001	5038	6169902	MISC.SINGLE LANE CLOSURE	0.00	1.00	1.00	EA	1.00	\$3,150.00	\$3,150.00
		0001	5039	6169902	MISC.RAMP CLOSURE	0.00	2.00	2.00	EA	2.00	\$1,890.00	\$3,780.00
		0001	5040	6189902	MISC.MOBILIZATION	0.00	1.00	1.00	EA	1.00	\$5,250.00	\$5,250.00
					bate as of Report Generated Date							\$5,494,515.02
200417-C03 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$5,494,515.02



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	ltem Code		Description		DWR Date	DWR Approva Date	Quantity Posted	Units		Location	From Station/ Log Mile	Offset/ Distance	Log	n/ Distance		Comments	
0730	7040104	HALF-SOLE REI	PAIR		7/6/22	7/7/22	179.00	SQFT	EB Searcy		Mile 129+75		Mile				
					7/12/22	7/12/22	166.00	SQFT	EB Searcy		129+75						
0740	7040112	DECK REPAIR V	WITH VOID TUBE REPLACEMENT		7/6/22 7/12/22				EB Searcy EB Searcy		129+75 129+75						
			are details for Constructio	on Sigr				04	-tion I Mi		Mumh	6	05 5		Canadial Olar	OF Fack Consid	Tatal OF
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date			Informati			ation Log Mi		Numbe		SF Each Sign		Special Sign	SF Each Special Sign	Total SF Post
P3266	0040	March 8, 2021	453	special ZONE					0.005	Drury Ave Marian Park	1.00				ad Work Ahead	9.00	
				special ZONE			O PASSING		0.005		1.00					9.00	
				special ZONE			O PASSING		0.068	Freemont	1.00				ad Work Ahead	9.00	
				special ZONE			O PASSING		0.104	Drury Ave.	1.00				ad Work Ahead	9.00	
				special ZONE	??x??	??.00 N	O PASSING	6	0.287	95th Terr.	1.00			36x36 Ro	ad Work Ahead	9.00	
				special ZONE	??x??	??.00 N	O PASSING	;	0.697	Belmont	1.00			36x36 Ro	ad Work Ahead	9.00	
				special ZONE	??x??	??.00 N	O PASSING	6	0.94	EB 87th	1.00			24x12 De	tour	2.00	
				special ZONE	??x??	??.00 N	O PASSING	6	0.94	EB 87th	1.00			21x15 An	'OW	2.19	
				special ZONE	??x??	??.00 N	O PASSING	6	0.94	EB 87th	1.00			24x24 St	ate Marker	4.00	
				special ZONE	??x??	??.00 N	O PASSING	3	1.028	Marian Dr.	1.00			36x36 Ro	ad Work Ahead	9.00	
				special ZONE	??x??	??.00 N	O PASSING	3	1.0335	Hillcrest Rd.	1.00			36x36 Ro	ad Work Ahead	9.00	
				special ZONE	??x??	??.00 N	O PASSING	3	1.536	EB 87th	1.00			24x12 De	tour	2.00	
				special ZONE	??x??	??.00 N	O PASSING	;	1.536	EB 87th	1.00			21x15 Ar	ow	2.19	
				special ZONE	??x??	??.00 N	O PASSING	;	1.536	EB 87th	1.00			24x24 St	ate Marker	4.00	
				special ZONE	??x??	??.00 N	O PASSING	6	1.585	EB 87th	1.00			24x12 De	tour	2.00	
				special ZONE	??x??	??.00 N	O PASSING	6	1.585	EB 87th	1.00			21x15 An	'ow	2.19	
				special ZONE	??x??	??.00 N	O PASSING	;	1.585	EB 87th	1.00			24x24 St	ate Marker	4.00	
				special ZONE	??x??	??.00 N	O PASSING	3	1.633	EB 87th	1.00			24x12 De	tour	2.00	
				special	??x??	??.00 N	O PASSING	;	1.633	EB 87th	1.00			21x15 An	°OW	2.19	
				special	??x??	??.00 N	O PASSING	3	1.633	EB 87th	1.00			24x24 St	ate Marker	4.00	
				special	??x??	??.00 N	O PASSING	;	124.355	SB US 71	1.00			24x12 De	tour	2.00	
				special	??x??	??.00 N	O PASSING	3	124.355	SB US 71	1.00			24x12 Sc	uth	2.00	
				ZONE special	??x??	??.00 N	O PASSING	;	124.355	SB US 71	1.00			21x15 An	ow	2.19	
				ZONE	??x??	??.00 N	O PASSING	3	124.355	SB US 71	1.00			30x24 Int	erstate Marker	5.00	
				ZONE special	??x??	??.00 N	O PASSING	;	129.559	SB US 71	1.00			24x12 De	tour	2.00	
				ZONE special	??x??	??.00 N	O PASSING	;	129.559	SB US 71	1.00			24x12 Sc	uth	2.00	
				ZONE special	??x??	??.00 N	O PASSING	;	129.559	SB US 71	1.00			21x15 An	'OW	2.19	
				ZONE special			O PASSING		129.559	SB US 71	1.00				erstate Marker	5.00	
				ZONE			O PASSING		2.045	Hillcrest	1.00				ad Work Ahead	9.00	
				ZONE			O PASSING		3.955	EB Banister Rd.	2.00				ad Work Ahead	9.00	
				ZONE			O PASSING		4.048	EB Banister Rd.	2.00				Z Speed Limit	6.00	
				ZONE R3-7L			EFT LANE		4.048	EB Banister Rd.	1.00	6	25	24730 W	- opeou cittiit	0.00	
				MUST	TURN LE	FT											
				MUST	TURN LE	FT	EFT LANE		4.196	EB Banister Rd.	1.00		25				
				MUST	TURN LE	FT	EFT LANE		4.229	EB Banister Rd.	1.00		25				
				MUST	TURN LE	FT	EFT LANE		4.23	EB Banister Rd.	1.00	6.	25			0.05	
				ZONE			O PASSING		4.286	EB Banister Rd.	1.00			24x12 De		2.00	
				special ZONE			O PASSING		4.286	EB Banister	1.00			21x15 An		2.19	
				special ZONE	??x??	??.00 N	O PASSING	3	4.286	EB Banister Rd.	1.00			24x24 St	ate Marker	4.00	
				special ZONE	??x??	??.00 N	O PASSING	6	4.286	EB Banister Rd.	1.00			48x24 Se	mi Trucks	8.00	
				R3-2 (SYMB0	48x48 OL)	16.00 N	D LEFT TUI	RN	4.286	EB Banister Rd.	1.00	16	i				
				WO20-2 AHEAD	2 48x48	3 16.00	DETOUR		4.325	NB 435	1.00	16	;				
				special ZONE		??.00 N	O PASSING	;	4.509	NB 435	1.00			24x12 De	tour	2.00	
				special ZONE	??x??	??.00 N	O PASSING	;	4.509	NB 435	1.00			21x15 An	°OW	2.19	



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information be low this line are details for Construction Signs (if applicable). Project Line Number DWR Date Total Quantity Posted For DWR Date Sign Information Station Log Mile Location Number of SF Each Special Sign SF Each Special Total SF to Items Sign Sig Post J4P3266 0040 March 8, 2021 453 special ??x?? ??.00 NO PASSING ZONE 4.509 NB 435 1.00 24x24 State Marker 4.00 4 WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD 4.695 NB 435 1.00 16 16 ??x?? ??.00 NO PASSING 4.972 NB 435 1.00 24x12 Detour 2.00 2 special ZONE special ZONE ??x?? ??.00 NO PASSING 4.972 NB 435 1.00 21x15 Arrow 2.19 2.19 ??x?? ??.00 NO PASSING 4.972 NB 435 1.00 24x24 State Marke 4.00 4 special ZONE ??x?? ??.00 NO PASSING 49.992 SB 435 1.00 24x12 Detour 2.00 2 special ZONE 22x22 22:00 NO PASSING 49 992 SB 435 1.00 21x15 Arrow 2.19 2 19 special ZONE ??x?? ??.00 NO PASSING 49.992 SB 435 1.00 24x24 State Marke 4.00 4 special ZONE special ZONE ??x?? ??.00 NO PASSING 5.701 WB Banister Rd 1.00 36x36 Road Work Ahead 9.00 9 22x22 22:00 NO PASSING 5 7 3 4 NB 435 1.00 24x12 Detour 2 00 2 special ZONE special ZONE ??x?? ??.00 NO PASSING 5.734 NB 435 1.00 21x15 Arrow 2.19 2.19 22x22 22:00 NO PASSING 5 7 3 4 NB 435 1.00 24x24 State Marker 4 00 A special ZONE ??x?? ??.00 NO PASSING 5773 WB Banister Rd 1.00 36x36 Left Lane Closed Ahead 9.00 9 special ZONE ??x?? ??.00 NO PASSING 5.778 WB Banister Rd 1.00 36x36 Left Lane Closed 9.00 9 special ZONE 22x22 22:00 NO PASSING 5 925 NB 435 1.00 24x12 Detour 2 00 2 special ZONE special ZONE ??x?? ??.00 NO PASSING 5.925 NB 435 1.00 21x15 Arrow 2.19 2.19 22x22 22:00 NO PASSING 5 925 NR 435 1.00 24x24 State Marke 4 00 4 specia ZONE special ZONE ??x?? ??.00 NO PASSING 5 944 WB Banister Rd 1.00 24x36 WZ Speed Limit 6.00 6 WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD 50.21 SB 435 1.00 16 16 MO4-8a 24x18 3.00 END DETOUR 50 215 SB 435 1.00 3 MO4-8a 24x18 3.00 END DETOUR 51.833 SB 435 1.00 3 3 6.25 ??x?? ??.00 NO PASSING 6.056 WB Banister Rd. 1.00 30x30 Double Down 6.25 special ZONE ??x?? ??.00 NO PASSING 6.256 WB Banister Rd 2.00 36x36 Left Lane Closed Ahead 9.00 18 special ZONE ??x?? ??.00 NO PASSING 6.288 9 WB Banister Rd. 1.00 36x36 Detour Ahead 9.00 special ZONE ??x?? ??.00 NO PASSING 6.355 1.00 30x30 Double Down 6.25 6.25 WB Banister Rd. special ZONE ??x?? ??.00 NO PASSING 6.405 WB Banister Rd 1.00 30x30 Double Down 6.25 6.25 special ZONE ??x?? ??.00 NO PASSING 6.405 WB Banister Rd 1.00 9.00 9 36x36 Left Lane Closed special ZONE ??x?? ??.00 NO PASSING 6.405 WB Banister Rd 1.00 36x36 Merge 9.00 9 special ZONE ??x?? ??.00 NO PASSING 6.453 1.00 30x30 Double Down 6.25 6.25 WB Banister Rd. special ZONE ??x?? ??.00 NO PASSING special ZONE 6.601 WB Banister Rd. 1.00 24x12 Detour 2.00 2 ??x?? ??.00 NO PASSING 6.601 1.00 2.00 2 WB Banister Rd 24x12 South special ZONE special ZONE ??x?? ??.00 NO PASSING 6.601 WB Banister Rd. 1.00 21x15 Arrow 2.19 2.19 5.00 5 ??x?? ??.00 NO PASSING 6.601 WB Banister Rd. 1.00 30x24 Interstate Marker special ZONE ??x?? ??.00 NO PASSING 6.624 WB Banister Rd. 1.00 36x36 No Left Turn 9.00 9 special ZONE ??x?? ??.00 NO PASSING 7.192 2.00 2 special ZONE WB Banister Rd. 1.00 24x12 Detour special ZONE ??x?? ??.00 NO PASSING 7.192 WB Banister Rd. 1.00 24x12 South 2.00 2 7.192 1.00 2.19 2.19 special ZONE ??x?? ??.00 NO PASSING WB Banister Rd. 21x15 Arrow ??x?? ??.00 NO PASSING special ZONE 7.192 WB Banister Rd. 1.00 30x24 Interstate Marker 5.00 5 WO4-1(48) 48x48 16.00 MERGE 16 March 16, 2021 187 48.911 SB 435 1.00 16 WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD 48.591 SB 435 2.00 16 32 WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD 48.255 SB 435 16 32 2.00 WO3-2A(48) 48x48 16.00 YIELD AHEAD 0.202 EB 87TH RAMP TO 435 S 1.00 16 16 WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED 48.911 SB 435 1.00 16 16 EO5-2 48x36 12.00 EXIT OPEN 12 50.109 SB 435 1.00 12 R1-2 48 TRI 6.93 YIELD 49.476 SB 435 1.00 6.93 6.93 WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT) 49.319 SB 435 1.00 16 16 R2-1 XX 36x48 12.00 SPEED LIMIT 49 079 SB 435 2.00 12 24 0.145 EB 87TH RAMP TO 435 S 1.00 16 WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD 16 April 12, 2021 368 See Special Sign Details 1.287 and 2.058 2.00 Detour 48"x18" 6.00 12 Lin vood Blvd on barricade 1.287 to 2.099 Linwood Blvd on barricades 4.00 12.5 50 R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC

Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

moi	iniation be	now this line	are details for Constructi	on signs (ir applicable).								
ect	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
266	0040	April 12, 2021	368	See Special Sign Details		1.479	EB 31st St	1.00		Detour Right Arrow 30"x24"	5.00	
				See Special Sign Details		1.516 to 2.892	NB and SB Brooklyn Ave.	2.00		Road Work Ahead 36"x36"	9.00	1
				R11-2 48x30 10.00 ROAD CLOSED		1.591 to 2.17	Linwood Blvd on barricades	2.00	10			2
				See Special Sign Details		1.275	EB 31st St.	1.00		Detour Up Arrow 30"x24"	5.00	
				See Special Sign Details		1.109	EB Linwood Blvd	1.00		Right Lane Closed 36"x36"	9.00	
				See Special Sign Details		1.1 to 1.82	EB and WB Linwood	2.00		Road Closed Ahead 36"x36"	9.00	1
				See Special Sign Details		1.034	EB Linwood Blvd	1.00		Right Lane Closed Ahead 36"x36"	9.00	
				See Special Sign Details		1	Flora, Woodland, and Highland	4.00		Road Work Ahead 36"x36"	9.00	3
				See Special Sign Details		0.957	EB Linwood Blvd	1.00		Road Work Ahead 36"x36"	9.00	
				See Special Sign Details		0.833	NB Euclid Ave	2.00		No Left Turn 24"x24"	4.00	
				See Special Sign Details		0.362	SB Michigan Ave	2.00		No Left Turn 24"x24"	4.00	
				See Special Sign Details		0.352	SB Garfield Ave.	1.00		Road Work Ahead 36"x36"	9.00	
				See Special Sign Details		0.349	SB Wayne Ave	1.00		Road Work Ahead 36"x36"	9.00	
				See Special Sign Details		1.646	NB Brooklyn Ave.	1.00		Detour Left Arrow 30"x24"	5.00	
				See Special Sign Details		4 014	NE The Paseo	1.00		Detour Right Arrow 30"x24"	5.00	
										· ·		
				See Special Sign Details		2.834	WB 31st St	1.00		Detour Left Arrow 30"x24"	5.00	
				See Special Sign Details		2.455	WB 31st St	1.00		Detour Up Arrow 30"x24"	5.00	
				See Special Sign Details		2.45	WB 31st St.	0.00		Detour Up Arrow 30"x24"	0.00	
				See Special Sign Details		120.5	SB 71 Hwy	2.00		Right Shoulder Closed 48"x48"	16.00	
				See Special Sign Details		120.45	SB 71 Hwy	2.00		Right Shoulder Closed Ahead 48"x48"	16.00	:
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		120.4	SB 71 Hwy	2.00	16			
				See Special Sign Details		1.937	WB Linwood Blvd	1.00		Right Lane Closed 36"x36"	9.00	
				See Special Sign Details		1.847	WB Linwood Blvd	1.00		Right Lane Closed Ahead 36"x36"	9.00	
				See Special Sign Details		1.82	WB Linwood Blvd	1.00		Road Work Ahead 36"x36"	9.00	
		April 19, 2021	36	See Special Sign Details		1.657 to 2.546	Euclid, Michigan, and 2x The Paseo	4.00		Road Work Ahead 36"x36"	9.00	
		June 1, 2021	64	W01-4bR 48x48 16:00 DOUBLE ARROW REVERSE CURVE (SYMBOL RIGHT ARROWS)		7.161	NB I-435 at Oldham Rd and Gregory Blvd	4.00	16			
		July 16, 2021	124	WO1-3L 48x48 16.00 REVERSE TURN (SYMBOL LEFT ARROW)		1	435	2.00	16			:
				R10-6 24x36 6.00 STOP HERE ON RED (45 DEGREE ARROW		1	77th	2.00	6			
				WO1-2L 48x48 16.00 CURVE (SYMBOL LEFT ARROW)		1	77th	1.00	16			
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		1	77th	2.00	16			:
				WO3-3 48x48 16.00 SIGNAL AHEAD (SYMBOL)		1	77th	2.00	16			
		October 8, 2021	96	WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS		42.293	SB 435	2.00	16			
				WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS		41.817	SB 435	2.00	16			
				WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS		43.766	SB 435	2.00	16			
		May 4, 2022	32	WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		114+90	WB 210	2.00	16			
		May 9, 2022	208	R6-2L 24x30 5.00 ONE WAY (LEFT)			WB Outer Road		5			
				See Special Sign Details			WB Outer Road	6.00		Detour Route Assembly	19.50	1
				WO20-2 48x48 16.00 DETOUR AHEAD			WB Outer Road	2.00	16			
				R1-1 48x48 13.25 STOP			WB Outer Road	2.00	13.25			20
				WO3-1 48x48 16.00 STOP AHEAD (SYMBOL)			WB Outer Road	2.00	16			
	0040 - Tota			1						1		1567.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J4P3266	0040	CONSTRUCTION SIGNS	Overrun	Overrun	12	Jun 2, 2021	SYSTEM	(\$588.00)			
					16	Aug 2, 2021	SYSTEM	(\$2,430.40)			
					17	Aug 16, 2021	SYSTEM	\$1,215.20	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.60000 - 19.60000, 'is applied (if non-zero).		
					18	Sep 1, 2021	SYSTEM	\$1,803.20	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.60000 - 19.60000, 'is applied (if non-zero).		
					21	Oct 18, 2021	SYSTEM	(\$1,881.60)			
					22	Nov 3, 2021	SYSTEM	\$1,881.60	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.60000 - 19.60000, 'is		
					30	May 16, 2022	SYSTEM	(\$4,704.00)	applied (if non-zero).		
					31	Jun 1, 2022	SYSTEM	\$4,704.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.60000 - 19.60000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - Tota					\$0.00			
	0040 -	- Total						\$0.00			
	0070	CHANNELIZER (TRIM LINE)	Overrun	Overrun	7	Mar 16, 2021	SYSTEM	(\$515.00)			
					8	Apr 2, 2021	SYSTEM	(\$5,665.00)			
					9	Apr 16, 2021	SYSTEM	\$6,180.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',51.50000 - 51.50000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - Tota	al				\$0.00			
	0070 -	- Total						\$0.00			
	0080		MOVEABLE		Overrun Overrun		30	May 16, 2022	SYSTEM	(\$3,297.60)	
				31		Jun 1, 2022	SYSTEM	\$3,297.60	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',412.20000 - 412.20000, 'is applied (if non-zero).		
				Overrun - Total				\$0.00			
			Overrun - Tota	al				\$0.00			
	0080 -	- Total						\$0.00			
	0110	TEMPORARY TRAFFIC BARRIER, CONT.	Overrun	Overrun	17	Aug 16, 2021	SYSTEM	(\$12,886.88)			
		FÜRN/RE			18	Sep 1, 2021	SYSTEM	\$12,886.88	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.75000 - 19.75000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - Tota	al				\$0.00			
	0110 -	- Total						\$0.00			
	0160	PVMT MARK,	Material		12	Jun 2, 2021	SYSTEM	\$3,091.20	This adjustment offsets the original system-generated Material Payment		
		LT/RT ARROW							Estimate Item Adjustment (0003) due to user watsom1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					12	Jun 2, 2021	SYSTEM	(\$3,091.20)			
				- Total	12		SYSTEM	(\$3,091.20) \$0.00			
		LT/RT ARROW	Material - Tota		12		SYSTEM	\$0.00 \$0.00			
		LT/RT ARROW		al		2021		\$0.00 \$0.00 \$0.00			
	0160 - 0170	- Total 6 IN. WHITE HIGH BUILD WATERBORNE	Material - Tota Overrun		30	2021 May 16, 2022	SYSTEM	\$0.00 \$0.00 \$0.00 (\$318.90)	Estimate Exception 5 on the current Payment Estimate.		
		LT/RT ARROW		al		2021 May 16,		\$0.00 \$0.00 \$0.00			



Jul 20, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
4P3266	0170	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	Overrun - Tota	al				\$0.00			
	0170 -	Total						\$0.00			
	0180	6 IN. YELLOW HIGH BUILD	Overrun	Overrun	30	May 16, 2022	SYSTEM	(\$22.20)			
		WATERBORNE PAINT			32	Jun 16, 2022	SYSTEM	\$22.20	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.30000 - 0.30000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - Tota					\$0.00			
	0180 -	Total						\$0.00			
					40		OVOTEN				
	0190	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		12	Jun 2, 2021	SYSTEM	\$201.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user watsom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					12	Jun 2, 2021	SYSTEM	(\$201.00)			
					13	Jun 16, 2021	SYSTEM	\$201.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user watsom1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					13	Jun 16, 2021	SYSTEM	(\$201.00)			
				- Total				\$0.00			
			Material - Tota	ıl				\$0.00			
	0190 -	Total						\$0.00			
	0200	00 4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		12	Jun 2, 2021	SYSTEM	\$83.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user watsom1 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
							12	Jun 2, 2021	SYSTEM	(\$83.25)	
							13	Jun 16, 2021	SYSTEM	\$83.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user watsom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$83.25)			
				- Total				\$0.00			
			Material - Tota	ıl				\$0.00			
	0200 -	Total						\$0.00			
	0210	PAVEMENT MARKING REMOVAL	Overrun	Overrun	30	May 16, 2022	SYSTEM	(\$2,853.00)			
					31	Jun 1, 2022	SYSTEM	\$540.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.25000 - 2.25000, 'is applied (if non-zero).		
					32	Jun 16, 2022	SYSTEM	\$2,313.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.25000 - 2.25000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - Tota	al				\$0.00			
	0210 -	Total						\$0.00			
	0220	4 IN TEMPORARY	Overrun	Overrun	20	Oct 4, 2021	SYSTEM	(\$9,191.25)			
		PAVEMENT MARKING PAINT			21	Oct 18, 2021	SYSTEM	(\$21,384.00)			
					22	Nov 3, 2021	SYSTEM	\$30,575.25	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.25000 - 2.25000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - Tota	al				\$0.00			
	0220 -	Total						\$0.00			
	0240	MGS GUARDRAIL	Construction Stockpile		22	Nov 3, 2021	SYSTEM	(\$7,518.75)	Payment Estimate Item Adjustment generated Stockpile Transaction		
					23	Nov 16,	SYSTEM	(\$12,608.37)	Payment Estimate Item Adjustment generated Stockpile Transaction		



Jul 20, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J4P3266	0240	MGS GUARDRAIL	Construction Stockpile			2021										
		GUARDRAIL	Stockpile		29	May 2, 2022	SYSTEM	(\$4,746.98)	Payment Estimate Item Adjustment generated Stockpile Transaction							
					32	Jun 16, 2022	SYSTEM	(\$26,836.40)	Payment Estimate Item Adjustment generated Stockpile Transaction							
				- Total				(\$51,710.50)								
			Construction	Stockpile - To	otal			(\$51,710.50)								
			Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$4,775.50	Payment Estimate Item Adjustment generated Stockpile Transaction							
			STMA	- Total				\$4,775.50								
			Construction	Stockpile ST	MA - Total			\$4,775.50								
			Construction Stockpile		2	Sep 16, 2020	SYSTEM	\$46,935.00	Payment Estimate Item Adjustment generated Stockpile Transaction							
			STMI	- Total				\$46,935.00								
			Construction	Stockpile ST	/II - Total			\$46,935.00								
	0240 -	Total						\$0.00								
	0250	MGS BRIDGE APP. TRANS SEC (REG/NO	Construction Stockpile		22	Nov 3, 2021	SYSTEM	(\$2,988.12)	Payment Estimate Item Adjustment generated Stockpile Transaction							
		CURB)				23	Nov 16, 2021	SYSTEM	(\$2,988.12)	Payment Estimate Item Adjustment generated Stockpile Transaction						
					29	May 2, 2022	SYSTEM	(\$2,988.12)	Payment Estimate Item Adjustment generated Stockpile Transaction							
					32	Jun 16, 2022	SYSTEM	(\$5,975.64)	Payment Estimate Item Adjustment generated Stockpile Transaction							
				- Total				(\$14,940.00)								
			Construction	Stockpile - To	otal			(\$14,940.00)								
			Construction Stockpile STMI		2	Sep 16, 2020	SYSTEM	\$14,940.00	Payment Estimate Item Adjustment generated Stockpile Transaction							
			•	- Total				\$14,940.00								
			Construction	Stockpile ST	/II - Total			\$14,940.00								
	0250 -	Total						\$0.00								
	0270	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		22	Nov 3, 2021	SYSTEM	(\$1,506.70)	Payment Estimate Item Adjustment generated Stockpile Transaction							
		(MASH)			29	May 2, 2022	SYSTEM	(\$0.30)	Payment Estimate Item Adjustment generated Stockpile Transaction							
				- Total				(\$1,507.00)								
			Construction	Stockpile - To				(\$1,507.00)								
			Construction Stockpile STMI		2	Sep 16, 2020	SYSTEM	\$1,507.00	Payment Estimate Item Adjustment generated Stockpile Transaction							
				- Total				\$1,507.00								
			Construction	Stockpile ST	/II - Total			\$1,507.00								
	0270 -	Total						\$0.00								
	0310	HALF-SOLE REPAIR	Material		16	Aug 2, 2021	SYSTEM	\$113,042.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user baldwc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
					16	Aug 2, 2021	SYSTEM	(\$113,042.50)								
					17	Aug 16, 2021	SYSTEM	\$113,042.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
					17	Aug 16, 2021	SYSTEM	(\$113,042.50)								
					18	Sep 1, 2021	SYSTEM	\$113,042.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					18	Sep 1, 2021	SYSTEM	(\$113,042.50)								
												19	Sep 16, 2021	SYSTEM	\$113,042.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Jul 20, 2022

roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3266	0310	HALF-SOLE REPAIR	Material		19	Sep 16, 2021	SYSTEM	(\$113,042.50)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
			Overrun	Overrun	13	Jun 16, 2021	SYSTEM	\$23,925.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user watsom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	\$15,013.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user watsom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$38,939.30)	
					14	Jul 1, 2021	SYSTEM	(\$38,939.30)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					14	Jul 1, 2021	SYSTEM	\$6,321.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user baldwc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Jul 1, 2021	SYSTEM	\$10,975.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Jul 1, 2021	SYSTEM	\$8,560.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user baldwc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Jul 1, 2021	SYSTEM	\$38,939.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user baldwc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Jul 1, 2021	SYSTEM	(\$25,857.10)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0310 -	Total						\$0.00	
	0350	HALF-SOLE REPAIR	Overrun	Overrun	24	Dec 2, 2021	SYSTEM	\$19,316.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user baldwc2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					24	Dec 2, 2021	SYSTEM	(\$19,316.00)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0350 -	Total						\$0.00	
	0390	HALF-SOLE REPAIR	Overrun	Overrun	13	Jun 16, 2021	SYSTEM	\$25,593.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user watsom1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$25,593.70)	
					14	Jul 1, 2021	SYSTEM		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					14	Jul 1, 2021	SYSTEM	\$25,593.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user baldwc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0390 -	Total						\$0.00	
	0470	CURB BLOCKOUT	Construction Stockpile		22	Nov 3, 2021	SYSTEM	(\$324.55)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$324.55)	
			Construction	Stockpile - To	otal			(\$324.55)	
			Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$324.55	Payment Estimate Item Adjustment generated Stockpile Transaction
			51101	- Total				\$324.55	
			Construction	Stockpile ST	/II - Total			\$324.55	
			Material		22	Nov 3, 2021	SYSTEM	\$6,595.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Draiget	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Project	Line	Description	Туре	Adjustment Type	Number	Date	By	Amount	remaiks
J4P3266	0470	CURB BLOCKOUT	Material		22	Nov 3, 2021	SYSTEM	(\$6,595.05)	
					23	Nov 16, 2021	SYSTEM	\$6,595.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user baldwc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					23	Nov 16, 2021	SYSTEM	(\$6,595.05)	
					24	Dec 2, 2021	SYSTEM	\$6,595.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user baldwc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					24	Dec 2, 2021	SYSTEM	(\$6,595.05)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0470 -	Total						\$0.00	
	0500	REINFORCING STEEL (EPOXY	Construction Stockpile		22	Nov 3, 2021	SYSTEM	(\$526.23)	Payment Estimate Item Adjustment generated Stockpile Transaction
		COATED)		- Total				(\$526.23)	
			Construction	Stockpile - To	otal			(\$526.23)	
			Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$526.23	Payment Estimate Item Adjustment generated Stockpile Transaction
			SIMI	- Total				\$526.23	
			Construction	Stockpile STI	MI - Total			\$526.23	
	0500 -	Total						\$0.00	
	0530	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		11	May 17, 2021	SYSTEM	\$188,924.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	May 17, 2021	SYSTEM	(\$188,924.80)	
					12	Jun 2, 2021	SYSTEM	\$188,924.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user watsom1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Jun 2, 2021	SYSTEM	(\$188,924.80)	
						13	Jun 16, 2021	SYSTEM	\$188,924.80
					13	Jun 16, 2021	SYSTEM	(\$188,924.80)	
				- Total				\$0.00	
			Material - Tota	d				\$0.00	
	0530 -	Total						\$0.00	
	0540	CLASS B-1 CONCRETE	Material		8	Apr 2, 2021	SYSTEM	(\$56,486.02)	
				- Total				(\$56,486.02)	
			Material - Tota					(\$56,486.02)	
			MaterialCredit		9	Apr 16, 2021	SYSTEM	\$56,486.02	
				- Total				\$56,486.02	
			MaterialCredit	- Total				\$56,486.02	
	0540 -	Total						\$0.00	
	0550	SUBSTRUCTURE REPAIR (FORMED)	Material		8	Apr 2, 2021	SYSTEM	(\$4,702.35)	
					10	May 3, 2021	SYSTEM	(\$12,161.25)	
					13	Jun 16, 2021	SYSTEM	\$12,161.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user watsom1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	Jun 16, 2021	SYSTEM	(\$12,161.25)	
				- Total				(\$16,863.60)	



Jul 20, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3266	0550	SUBSTRUCTURE	Material - Tota					(\$16,863.60)		
		REPAIR (FORMED)	MaterialCredit		9	Apr 16, 2021	SYSTEM	\$4,702.35		
					11	May 17, 2021	SYSTEM	\$12,161.25		
				- Total				\$16,863.60		
			MaterialCredit	- Total				\$16,863.60		
	0550 -	Total						\$0.00		
	0570	HALF-SOLE REPAIR	Other Item Adjustment	OADJ	11	May 17, 2021	watsom1	\$18,438.00	Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.	
					12	Jun 2, 2021	watsom1	(\$18,438.00)	Contractor was paid for this work on estimate 11. This adjustment makes the total of all adjustments $0. \label{eq:contractor}$	
				OADJ - Tota	ıl			\$0.00		
			Other Item Ad	justment - To	tal			\$0.00		
			Overrun	Overrun	8	Apr 2, 2021	SYSTEM	(\$7,748.35)		
					9	Apr 16, 2021	SYSTEM	\$7,748.35	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).	
					10	May 3, 2021	SYSTEM	(\$14,179.70)		
					11	May 17, 2021	SYSTEM	(\$18,438.00)		
				Overrun - 1	12	Jun 2, 2021	SYSTEM	\$32,617.70	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',43.90000 - 43.90000, 'is applied (if non-zero).	
				Overrun - To	otal			\$0.00		
	0570 - Total		Overrun - Tota	al				\$0.00		
		Total						\$0.00		
	0580	Total FULL DEPTH REPAIR	Other Item Adjustment	OADJ	11	May 17, 2021	watsom1	\$5,550.60	Adjustment is being made so the contractor can receive payment for the work that has been completed. A change order should be approved before the next estimate.	
					12	Jun 2, 2021	watsom1	(\$5,550.60)	Contractor was paid for this work on estimate 11. This adjustment makes the total of all adjustments 0. $% \left({{{\rm{D}}_{\rm{B}}}} \right)$	
				OADJ - Tota	ıl			\$0.00		
			Other Item Ad	justment - To	tal	_		\$0.00		
			Overrun	Overrun	9	Apr 16, 2021	SYSTEM	(\$8,389.70)		
					10	May 3, 2021	SYSTEM	\$8,389.70	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',63.80000 - 63.80000, 'is applied (if non-zero).	
					11	May 17, 2021	SYSTEM	(\$5,550.60)		
					12	Jun 2, 2021	SYSTEM	\$5,550.60	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',63.80000 - 63.80000, 'is applied (if non-zero).	
				Overrun - To	otal			\$0.00		
			Overrun - Tota	al				\$0.00		
	0580 -	Total						\$0.00		
	0590	REINFORCING STEEL (EPOXY	Construction Stockpile		8	Apr 2, 2021	SYSTEM	(\$2,855.51)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		COATED)		- Total				(\$2,855.51)		
			Construction	Stockpile - To	otal			(\$2,855.51)		
			Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$2,855.51	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$2,855.51		
			Construction	Stockpile STM	/II - Total			\$2,855.51		
			Material		8	Apr 2, 2021	SYSTEM	(\$9,202.00)		
					- Total				(\$9,202.00)	



Jul 20, 2022

Bits Processors Control Reservation Service Service Se	ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
CONTEDIM Meteral Codel P Age 10 SYSTEM System Status SUB - Fodal - Fodal - Solal - Solal <td>266</td> <td>0590</td> <td></td> <td>Material - Tota</td> <td>al</td> <td></td> <td></td> <td></td> <td>(\$9,202.00)</td> <td></td>	266	0590		Material - Tota	al				(\$9,202.00)								
Image: status Visit of the status				MaterialCredit		9		SYSTEM	\$9,202.00								
0950 - Total Sinciple Sincintraterelinte and sinciple Sinciple					- Total				\$9,202.00								
OURSE CURE BLOCKING BLOCKI				MaterialCredit	t - Total				\$9,202.00								
BLOCKOUT Sinschafte 2022 100		0590 -	Total						\$0.00								
Construction Construction S No.2, a SYSTEM S22.81.51 Perment Estimate Rem Adjustment generated Stocopie Transaction Odd - Total - Total - Total - Sole - Sole <td></td> <td>0620</td> <td>CURB BLOCKOUT</td> <td></td> <td></td> <td>31</td> <td></td> <td>SYSTEM</td> <td>(\$2,816.11)</td> <td>Payment Estimate Item Adjustment generated Stockpile Transaction</td>		0620	CURB BLOCKOUT			31		SYSTEM	(\$2,816.11)	Payment Estimate Item Adjustment generated Stockpile Transaction							
Schedule					- Total				(\$2,816.11)								
Stochlip Image: Construction Stochpile STML - Total South Stochpile STML - Total South Stochpile STML - Total 0620 Construction Stochpile STML - Total South Stochpile STML - Total South Stochpile STML - Total 0630 HR FPAR Material Image: Stochpile STML - Total Strates 0630 HR FPAR Material Image: Strates Strates 1 Jun 1, Strates Strates Strates Strates 22 Jun 10, Strates Strates Strates Strates 22 Jun 10, Strates Strates Strates Strates 232 Jun 10, Strates Strates Strates Strates 312 Jun 10, Strates Strates Strates Strates 32 Jun 10, Strates Strates Strates Strates 32 Jun 10, Strates Strates Strates Strates 32 Jun 10, Strates Strates Strates Strates Strates Strates Strates Strates Strates Strates				Construction	Stockpile - To	otal			(\$2,816.11)								
Image: state 128,816.10 Construction Block BTM - rotat 92,816.31 OPC0 - Total 92,912.10 OPC0 - Total 99,920 HAP, SOURCE Material 20,221 SYSTEM 91,71,428.30 The adjustment offeets the original system-generated Material Payment Estimate. OPC0 - Total 2022 20,121 SYSTEM (817,428.30) The adjustment offeets the original system-generated Material Payment Estimate. OPC0 - Total 2022 20,12 SYSTEM (817,428.30) The adjustment offeets the original system-generated Material Payment Estimate. OPC0 - Total -Total SYSTEM (817,057.00) Decision Total Company System-generated Material Payment Estimate. OPC0 - Total -Total SYSTEM (81,05,07) The adjustment offeets the original system-generated Material Payment Estimate. OPC0 - Total -Total SYSTEM (82,083.00) SYSTEM				Stockpile		5		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction							
Occounce Subsection Subsecti				•	- Total				\$2,816.11								
Op30 HALE-SCIE REPAR Material 31 Jun 1, 2022 SYSTEM \$17,428.30 This adjustment official time adjustment operand presented Material Payment Estimate Exception 1 on the current Payment Estimate. 0630 File 31 Jun 10, 2022 SYSTEM \$617,428.30 12 Jun 10, 202 SYSTEM \$617,428.30 Estimate Exception 1 on the current Payment Estimate. 12 Jun 10, 202 SYSTEM \$610,657.70 Estimate Exception 1 on the current Payment Estimate. 13 Jun 10, 2022 SYSTEM \$51,055.70 Estimate Exception 1 on the current Payment Estimate. 0640 DECK REPAR WTH VOID TUBE Material T ordat \$0.00 Initia adjustment offices the original system-generated Material Payment Estimate Exception 2 no the current Payment Estimate. 0640 DECK REPAR WTH VOID TUBE Material \$1 Jun 1, 2022 SYSTEM \$20,088.00 32 Jun 1, 2022 SYSTEM \$20,088.00 Estimate Exception 2 no the current Payment Estimate. 33 Jul 2, 2022 SYSTEM \$40,462.50 Estimate Exception 1 on the current Payment Estimate. 34 Jul 1, 2022 SYSTEM </td <td></td> <td></td> <td></td> <td>Construction</td> <td>Stockpile STI</td> <td>MI - Total</td> <td></td> <td></td> <td>\$2,816.11</td> <td></td>				Construction	Stockpile STI	MI - Total			\$2,816.11								
REPAIR REPAIR REPAIR Repair Repai		0620 -	Total						\$0.00								
Nome Nome <th< td=""><td></td><td>0630</td><td></td><td>Material</td><td></td><td>31</td><td></td><td>SYSTEM</td><td>\$17,428.30</td><td>Estimate Item Adjustment (0005) due to user baldwc2 overridding Payment</td></th<>		0630		Material		31		SYSTEM	\$17,428.30	Estimate Item Adjustment (0005) due to user baldwc2 overridding Payment							
Image: Problem in the strengt in the streng						31		SYSTEM	(\$17,428.30)								
Image: Control in the contro						32		SYSTEM	\$51,055.70	Estimate Item Adjustment (0006) due to user baldwc2 overridding Payment							
Image: Note of the image: No						32		SYSTEM	(\$51,055.70)								
OS30 - Total S0.00 0630 - Total DECK REFAIR REPLACEMENT Material VICUO TUBE REPLACEMENT Material 2022 31 Jun 1, 2022 SVSTEM \$20,830.00 This adjustment offsets the original system-generated Material Payment Estimate tex-option 2 on the current Payment Estimate. 31 Jun 1, 2022 SVSTEM \$20,830.00 This adjustment offsets the original system-generated Material Payment Estimate tex-option 2 on the current Payment Estimate. 32 Jun 16, 2022 SVSTEM \$49,452.50 This adjustment offsets the original system-generated Material Payment Estimate tex-option 2 on the current Payment Estimate. 33 Jul 5, 2022 SVSTEM \$49,452.50 This adjustment offsets the original system-generated Material Payment Estimate tex-option 2 on the current Payment Estimate. 33 Jul 5, 2022 SVSTEM \$32,389.50 This adjustment offsets the original system-generated Material Payment Estimate tex-option 1 on the current Payment Estimate. 44 Jul 18, 2022 SVSTEM \$32,389.50 This adjustment offsets the original system-generated Material Payment Estimate tex-option 1 on the current Payment Estimate. 6600 CONCRETE VEAT SUSTEM \$32,389.50 This adjustment offsets the original system-generated Material Payment Estimate tex-option 1 on the current Paymen					- Total				\$0.00								
0940 DECK REPAIR WITH VOID TUBE REPLACEMENT Material Material 21 2022 SYSTEM S20,838.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate Estimate Exception 2 on the current Payment Estimate 31 Jun 1, 2022 SYSTEM (20,838.00) 32 Jun 1, 2022 SYSTEM (20,838.00) 32 Jun 16, 2022 SYSTEM (49,452.50) This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate 32 Jun 16, 2022 SYSTEM (49,452.50) This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate 33 Jul 5, 2022 SYSTEM (32,389.50) This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. 44 Jul 18, 2022 SYSTEM (32,389.50) This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. 50.00 Cotal				Material - Tota	al				\$0.00								
WITH VOID TUBE REPLACEMENT WITH VOID TUBE REPLACEMENT Image: Standage St		0630 -	Total						\$0.00								
		0640	WITH VOID TUBE	VOID TUBE	JBE		31		SYSTEM	\$20,838.00	Estimate Item Adjustment (0006) due to user baldwc2 overridding Payment						
 			REPLACEMENT										31		SYSTEM	(\$20,838.00)	
							32		SYSTEM	\$49,452.50	Estimate Item Adjustment (0007) due to user baldwc2 overridding Payment						
Image: base base base base base base base base						32		SYSTEM	(\$49,452.50)								
$ \begin{array}{ c c c c c } \hline \\ \hline $						33		SYSTEM	\$32,389.50	Estimate Item Adjustment (0001) due to user persic1 overridding Payment							
$ \begin{array}{c c c c c c c c c c c c c c c c c c c $						33		SYSTEM	(\$32,389.50)								
0640 - Total 071000-000-000-000-000-000-000-000-000-0										34		SYSTEM	\$32,389.50	Estimate Item Adjustment (0002) due to user baldwc2 overridding Payment			
Odd) - Total S0.00 0640 - Total \$0.00 0660 OPTIONAL CONCREL WEARING SURFACE Material 23 Nov 16, 2021 SYSTEM \$53,427.60 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment							34		SYSTEM	(\$32,389.50)							
Odd) - Total S0.00 0640 - Total \$0.00 0660 OPTIONAL CONCREL WEARING SURFACE Material 23 Nov 16, 2021 SYSTEM \$53,427.60 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment					- Total				\$0.00								
0640 - Total \$0.00 0660 OPTIONAL CONCRETE WEARING SURFACE Material A 23 Nov 16, 2021 SYSTEM \$53,427.60 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. 23 Nov 16, 2021 SYSTEM \$\$53,427.60 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. 24 Dec 2, 2021 SYSTEM \$\$53,427.60 This adjustment (0004) due to user baldwc2 overridding Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. 24 Dec 2, 2021 SYSTEM \$\$53,427.60				Material - Tota	al				\$0.00								
CONCRETE WEARING SURFACE 2021 23 Nov 16, 2021 24 Dec 2, 2021 24 Dec 2, 2021 24 Dec 2, 2021 25 SYSTEM 24 Dec 2, 2021 25 SYSTEM 26 SYSTEM 27 SYSTEM 28 SYSTEM 29 SYSTEM 2021 SYSTEM		0640 -	Total						\$0.00								
SURFACE Nov 16, 2021 SYSTEM (\$53,427.60) 24 Dec 2, 2021 SYSTEM \$53,427.60		0660	CONCRETE	Material		23		SYSTEM	\$53,427.60	Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment							
2021 Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. 24 Dec 2, 2021 SYSTEM (\$53,427.60)						23		SYSTEM	(\$53,427.60)								
2021						24		SYSTEM	\$53,427.60	Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment							
- Total \$0.00						24		SYSTEM	(\$53,427.60)								
					- Total				\$0.00								



Jul 20, 2022

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks													
402266	0660	ODTIONAL	Material - Tota	Туре				\$0.00														
J4P3266	0660	OPTIONAL CONCRETE WEARING SURFACE	material - Tota	1				\$0.00														
	0660 -	Total						\$0.00														
	0670	CURB BLOCKOUT	Construction Stockpile		20	Oct 4, 2021	SYSTEM	(\$2,816.11)	Payment Estimate Item Adjustment generated Stockpile Transaction													
				- Total				(\$2,816.11)														
			Construction	Stockpile - To	otal			(\$2,816.11)														
			Construction Stockpile		5	Nov 2, 2020	SYSTEM	\$2,816.11	Payment Estimate Item Adjustment generated Stockpile Transaction													
			STMI	- Total				\$2,816.11														
			Construction	Stockpile STI	MI - Total			\$2,816.11														
			Material		20	Oct 4, 2021	SYSTEM	\$24,941.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					20	Oct 4, 2021	SYSTEM	(\$24,941.00)														
				- Total			\$0.00															
			Material - Tota	ıl				\$0.00														
	0670 -	Total						\$0.00														
	0690	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		21	Oct 18, 2021	SYSTEM	\$30,275.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
																		21	Oct 18, 2021	SYSTEM	(\$30,275.50)	
					22	Nov 3, 2021	SYSTEM	\$41,676.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user baldwc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
					22	Nov 3, 2021	SYSTEM	(\$41,676.00)														
					23	Nov 16, 2021	SYSTEM	\$50,358.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user baldwc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
					23	Nov 16, 2021	SYSTEM	(\$50,358.50)														
					24	Dec 2, 2021	SYSTEM	\$20,158.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user baldwc2 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
					24	Dec 2, 2021	SYSTEM	(\$20,158.50)														
				- Total				\$0.00														
			Material - Tota	I				\$0.00														
			Overrun	Overrun	21	Oct 18, 2021	SYSTEM	\$3,850.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 401.000; Overrun Quantity Balance 51.00.													
					21	Oct 18, 2021	SYSTEM	(\$3,850.50)														
				Overrun - T	otal			\$0.00														
			Overrun - Tota	al				\$0.00														
	0690 -	Total						\$0.00														
	0720	CURB BLOCKOUT	Construction Stockpile		31	Jun 1, 2022	SYSTEM	(\$1,875.85)	Payment Estimate Item Adjustment generated Stockpile Transaction													
				- Total				(\$1,875.85)														
			Construction	Stockpile - To				(\$1,875.85)														
			Construction Stockpile STMI	Total	5	Nov 2, 2020	SYSTEM	\$1,875.85	Payment Estimate Item Adjustment generated Stockpile Transaction													
			Construction	- Total	AL Total			\$1,875.85														
	0700	Total	Construction	Stockpile STI	m - Total			\$1,875.85														
		Total						\$0.00														
	0730	HALF-SOLE	Overrun	Overrun	34	Jul 18,	SYSTEM	(\$4,741.20)														



Jul 20, 2022

ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
66	0730	REPAIR	Overrun			2022					
				Overrun - T	otal			(\$4,741.20)			
			Overrun - Tota	al				(\$4,741.20)			
- 1	0730 -	Total						(\$4,741.20)			
	0740	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		33	Jul 5, 2022	SYSTEM	\$4,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user persic1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					33	Jul 5, 2022	SYSTEM	(\$4,530.00)			
				- Total				\$0.00			
			Material - Tota	al				\$0.00			
	0740 -	Total						\$0.00			
	0780	CURB BLOCKOUT	Construction Stockpile		20	Oct 4, 2021	SYSTEM	(\$1,875.85)	Payment Estimate Item Adjustment generated Stockpile Transaction		
				- Total				(\$1,875.85)			
			Construction	Stockpile - To	otal			(\$1,875.85)			
			Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$1,875.85	Payment Estimate Item Adjustment generated Stockpile Transaction		
				- Total				\$1,875.85			
			Construction	Stockpile STI	MI - Total			\$1,875.85			
			Material		20	Oct 4, 2021	SYSTEM	\$18,662.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user baldwc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					20	Oct 4, 2021	SYSTEM	(\$18,662.00)			
				- Total				\$0.00			
			Material - Tota	al				\$0.00			
	0780 -	Total						\$0.00			
	0790	- Total HALF-SOLE REPAIR	HALF-SOLE	HALF-SOLE	Material		20	Oct 4, 2021	SYSTEM	\$9,438.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user baldwc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
						20	Oct 4, 2021	SYSTEM	(\$9,438.50)		
				- Total							
			Material - Tota	al				\$0.00			
	0790 -	Total						\$0.00			
	0800	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		20	Oct 4, 2021	SYSTEM	\$3,850.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user baldwc2 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					20	Oct 4, 2021	SYSTEM	(\$3,850.50)			
				- Total				\$0.00			
			Material - Tota	al				\$0.00			
	0800 -	Total						\$0.00			
	0850	PREFORMED COMPRESSION SEAL	Material		24	Dec 2, 2021	SYSTEM	\$10,466.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user baldwc2 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					24	Dec 2, 2021	SYSTEM	(\$10,466.50)			
				- Total				\$0.00			
	0850 - T 0920		Material - Tota	al				\$0.00			
		Total						\$0.00			
		CLASS B-2 CONCRETE	Material		16	Aug 2, 2021	SYSTEM	\$8,520.19	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					16	Aug 2, 2021	SYSTEM	(\$8,520.19)			
					17	Aug 16, 2021	SYSTEM	\$12,780.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user baldwc2 overridding Payment Estimate Exception 1 on the current Payment Estimate.		



Jul 20, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3266	0920	CLASS B-2 CONCRETE	Material		17	Aug 16, 2021	SYSTEM	(\$12,780.28)		
				- Total				\$0.00		
			Material - Tota	al				\$0.00		
	0920 -	Total						\$0.00		
	0930	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		16	Aug 2, 2021	SYSTEM	(\$243.75)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		00/(125)			17	Aug 16, 2021	SYSTEM	(\$121.88)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				T ()	18	Sep 1, 2021	SYSTEM	(\$119.19)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$484.82)		
			Construction	Stockpile - To	1	NI 0	OVOTEN	(\$484.82)		
			Construction Stockpile STMI	- Total	5	Nov 2, 2020	SYSTEM	\$484.82 \$484.82	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Ormation		T -4-1					
	0020	Total	Construction	Stockpile ST	m - rotal			\$484.82		
	0930 - Total 0950 STRIP SEAL EXPANSION		Construction Stockpile		18	Sep 1, 2021	SYSTEM	\$0.00 (\$13,856.25)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		JOINT SYSTEM		- Total				(\$13,856.25)		
			Construction		otal			(\$13,856.25)		
			Construction		3	Oct 1,	SYSTEM	\$13,856.25	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Stockpile				OTOTEM	φ10,000.20	Taymont Estimate ton Adjustment generated elestique transaction	
			31101	- Total				\$13,856.25		
		Construction Stockpile STMI		MI - Total			\$13,856.25			
	0950 -	Total						\$0.00		
	0970	D PREFORMED COMPRESSION SEAL	COMPRESSION	Material		24	Dec 2, 2021	SYSTEM	\$8,753.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user baldwc2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					24	Dec 2, 2021	SYSTEM	(\$8,753.80)		
				- Total				\$0.00		
			Material - Tota	al				\$0.00		
	0970 -	Total						\$0.00		
	0990	PREFORMED COMPRESSION SEAL	Material		23	Nov 16, 2021	SYSTEM	\$8,753.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user baldwc2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					23	Nov 16, 2021	SYSTEM	(\$8,753.80)		
					24	Dec 2, 2021	SYSTEM	\$8,753.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user baldwc2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					24	Dec 2, 2021	SYSTEM	(\$8,753.80)		
				- Total				\$0.00		
			Material - Tota	al				\$0.00		
	0990 -	Total						\$0.00		
	1020	PREFORMED COMPRESSION SEAL	Material		24	Dec 2, 2021	SYSTEM	\$9,134.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user baldwc2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					24	Dec 2, 2021	SYSTEM	(\$9,134.40)		
				- Total				\$0.00		
			Material - Tota	al				\$0.00		
	1020 -	Total						\$0.00		
	1060	CLASS B-2 CONCRETE	Material		12	Jun 2, 2021	SYSTEM	\$48,810.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user watsom1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					12	Jun 2,	SYSTEM	(\$48,810.58)		



Jul 20, 2022

roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
P3266	1060	CLASS B-2 CONCRETE	Material			2021				
		CONCRETE		- Total				\$0.00		
			Material - Tota	ı				\$0.00		
	1060 -	Total						\$0.00		
	1080	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		12	Jun 2, 2021	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction	
		,		- Total				(\$1,712.91)		
			Construction	Stockpile - To				(\$1,712.91)		
			Construction Stockpile STMI		5	Nov 2, 2020	SYSTEM	\$1,712.91	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$1,712.91		
			Construction	Stockpile STI	MI - Total			\$1,712.91		
	1080 -							\$0.00		
	1100	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		12	Jun 2, 2021	SYSTEM	(\$38,590.03)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$38,590.03)		
			Construction	Stockpile - To				(\$38,590.03)		
			Construction Stockpile STMI	Tetal	3	Oct 1, 2020	SYSTEM	\$38,590.03	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$38,590.03		
	1100		Construction	Stockpile ST	MI - Iotal			\$38,590.03		
	1100 - 1140	REINFORCING STEEL (EPOXY			10	May 3, 2021	SYSTEM	\$0.00 (\$1,390.36)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		COATED)	ereenpiio	- Total		2021		(\$1,390.36)		
			Construction		otal			(\$1,390.36)		
				Construction Stockpile		5	Nov 2, 2020	SYSTEM	\$1,390.36	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$1,390.36		
			Construction	Stockpile STI	MI - Total			\$1,390.36		
	1140 -	Total						\$0.00		
	1160	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		10	May 3, 2021	SYSTEM	(\$17,280.62)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		JOINT STSTEM			11	May 17, 2021	SYSTEM	(\$17,280.63)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$34,561.25)		
			Construction	Stockpile - To				(\$34,561.25)		
			Construction Stockpile STMI		3	Oct 1, 2020	SYSTEM	\$34,561.25	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$34,561.25		
			Construction	Stockpile STI	MI - Total			\$34,561.25		
	1160 - 1200	Total CLASS B-2 CONCRETE	Material		14	Jul 1, 2021	SYSTEM	\$0.00 \$24,838.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user baldwc2 overridding Payment	
		0011011212			14	Jul 1,	SYSTEM	(\$24,838.52)	Estimate Exception 1 on the current Payment Estimate.	
				- Total		2021		\$0.00		
			Material - Tota	I				\$0.00		
	1200 -	Total						\$0.00		
	1210	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		14	Jul 1, 2021	SYSTEM	(\$968.30)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		GUATED)			15	Jul 16, 2021	SYSTEM	(\$963.65)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$1,931.95)		
			Construction	Stockpile - To	otal			(\$1,931.95)		
			Construction		5	Nov 2,	SYSTEM	\$1,931.95	Payment Estimate Item Adjustment generated Stockpile Transaction	



Jul 20, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3266	1210	REINFORCING STEEL (EPOXY	Stockpile STMI			2020			
		COATED)	0 mil	- Total				\$1,931.95	
			Construction	Stockpile STI	VI - Total			\$1,931.95	
			Material		14	Jul 1, 2021	SYSTEM	\$4,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user baldwc2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Jul 1, 2021	SYSTEM	(\$4,495.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	1210 -		-					\$0.00	
	1230	STRIP SEAL EXPANSION JOINT SYSTEM	Construction Stockpile		14	Jul 1, 2021	SYSTEM	(\$19,295.01)	Payment Estimate Item Adjustment generated Stockpile Transaction
		JOINT OTOTEM			15	Jul 16, 2021	SYSTEM	(\$19,295.02)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$38,590.03)	
			Construction	- Stockpile - To	otal			(\$38,590.03)	
			Construction Stockpile		3	Oct 1, 2020	SYSTEM	\$38,590.03	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$38,590.03	
			Construction	Stockpile STI	MI - Total			\$38,590.03	
	1230 -	Total						\$0.00	
	5001		Material		12	Jun 2, 2021	SYSTEM	\$6,834.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user watsom1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Jun 2, 2021	SYSTEM	(\$6,834.56)	
				- Total				\$0.00	
			Material - Tota	al .				\$0.00	
	5001 -	Total						\$0.00	
	5007	MISC.	MISC. Material		12	Jun 2, 2021	SYSTEM	\$10,745.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user watsom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Jun 2, 2021	SYSTEM	(\$10,745.28)	
				- Total				\$0.00	
			Material - Tota	1 1				\$0.00	
	5007 -	Total						\$0.00	
	5010	PREF THERMO PVMT MARK, 24 IN WHIT	Material		12	Jun 2, 2021	SYSTEM	\$970.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user watsom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Jun 2, 2021	SYSTEM	(\$970.20)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	5010 -	Total						\$0.00	
	5012	MODIFIED COLDMILLING	Overrun	Overrun	21	Oct 18, 2021	SYSTEM	(\$392.03)	
		(DEPTH TRANSITIONS)			22	Nov 3, 2021	SYSTEM	\$392.03	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',9.95000 - 9.95000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
	5012 -		Overrun - Tota	al				\$0.00	
		Total						\$0.00	
	5013	TACK COAT	Overrun	Overrun	20	Oct 4, 2021	SYSTEM	(\$2.91)	
					22	Nov 3, 2021	SYSTEM	\$2.91	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4.16000 - 4.16000, 'is applied (if non-zero).
				Overrun - T	otal	1		\$0.00	



Jul 20, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3266	5013	TACK COAT	TACK COAT Overrun - Total					\$0.00	
	5013 - Total							\$0.00	
J4P3266 - Total							(\$4,741.20)		
Overall - Total								(\$4,741.20)	