

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 15, 2020

Progress Estin	Progress Estimate Number 3		200417-H03 Koch Electric, Inc.	•	October 1, 2020 October 15, 2020	Original Contract Amount Net Change Order Amount Current Contract Amount	\$603,739.80 \$0.00 \$603,739.80		
Approval Date							By User		
October 15, 2020		Ge	enerated and Appro	ved (and should be	considered Draft) a	t the Project Office Level by	petrid1		
October 16, 2020		Review	ved and Approved (and should be consi	dered Draft) at the	Resident Engineer Level by	holtb1		
October 20, 2020	Reviewed and Approved at the Central Office Controllers Office Level by								
Original Comp	letion Date	Current Comple	etion Date	Actual Completion	of Current Contract Amount	Complete			
January 1	anuary 1, 2021 January 1, 2021 35.40%								

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 3											
		This Estimate	Previous	To Date							
200417-H03											
	Total Posted Items Pay	\$110,021.50	\$103,721.90	\$213,743.40							
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00							
	Incentive	\$0.00	\$0.00	\$0.00							
	Disincentive	\$0.00	\$0.00	\$0.00							
	Liquidated Damage	\$0.00	\$0.00	\$0.00							
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00							
			\$103,721.90	\$213,743.40							
Contract Total Pa	ayable This Estimate:	\$110,021.50									

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3572	0290	6181000	MOBILIZATION	LS	\$7,350.000	0.25	\$1,837.50
	0295	8051000A	SEEDING - COOL SEASON MIXTURES	ACRE	\$1,500.000	1.5	\$2,250.00
	0320	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	EA	\$1,880.000	10	\$18,800.00
	0330	9011106	BRACKET ARM, 6 FT. OR 1.8 M	EA	\$350.000	8	\$2,800.00
	0340	9011115	BRACKET ARM, 15 FT. OR 4.6 M	EA	\$680.000	2	\$1,360.00
	0350	9011312	LUMINAIRE, LED-B	EA	\$320.000	10	\$3,200.00
	0360	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	EA	\$2,750.000	1	\$2,750.00
	0370	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	LF	\$15.000	63	\$945.00
	0380	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	LF	\$16.000	20	\$320.00
	0390	9014004	CONDUIT, 4 IN. RIGID, PUSHED	LF	\$16.000	546	\$8,736.00
	0400	9015010	TRENCHING TYPE I	LF	\$3.200	5,460	\$17,472.00
	0410	9016110	PULL BOX, PREFORMED CLASS 1	EA	\$575.000	21	\$12,075.00
	0430	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	LF	\$0.900	1,140	\$1,026.00
	0440	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	LF	\$3.250	8,600	\$27,950.00
	0450	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	EA	\$850.000	10	\$8,500.00
Project J9I3	572 - Total						\$110,021.50
Overall - To	tal						\$110,021.50

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	<u>tments This Estimate</u>						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3572	0295	SEEDING - COOL SEASON MIXTURES	Material			-1.5	\$1,500.00	(\$2,250.00)
	0295	SEEDING - COOL SEASON	Material		This adjustment offsets the original system-	1.5	\$1,500.00	\$2,250.00

Revision 4/1/2020 Page 1 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 15, 2020

Prog	ress Es	stimate Number 3	Contract I Prime Cor)417-H03 ch Electric, Inc.	. Pay Period End October 15, 2020 Net 0	nal Contract Change Order ent Contract	Amount	6603,739.80 60.00 6603,739.80
Project Number	Line No.	Item Descrip	otion	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9l3572		N	MIXTURES			generated Overrun Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
	0450	POLE FOUNDATION OR 13.5 M M		Material			-20	\$850.00	(\$17,000.00)
	0450	POLE FOUNDATION OR 13.5 M M	,	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user petrid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		\$850.00	\$17,000.00
Total									\$0.00

Revision 4/1/2020 Page 2 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	on					
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J9I3559	I 57-1(41)	Light installation	I-55, I-57	MISSISSIPPI	in various locations in the Southeast District							
J9I3572	I 155-1(122)	Light installation	I-155	PEMISCOT	on Route U exit 4 and Route 84 exit 6							
Γotals by .	Job Number	s										
J9l3559		Item Pay Item Adjustme		Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$144.00 \$0.00 \$144.00	To Date \$144.00 \$0.00 \$144.00					
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					
J9l3572		Item Pay Item Adjustme		Item Pay	This Estimate \$110,021.50 \$0.00 \$110,021.50	Previous \$103,577.90 \$0.00 \$103,577.90	To Date \$213,599.40 \$0.00 \$213,599.40					
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 4/1/2020 Page 3 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9I3572, Item 8051000A, Project Item Line Number 0295, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Material Certification Received	petrid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3572, Item 8051000A, Project Item Line Number 0295, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.	Material testing needs zeroed	petrid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3572, Item 8051000A, Project Item Line Number 0295, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Material testing complete but not approved	petrid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3572, Item 8051000A, Project Item Line Number 0295, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Material Certification Received	petrid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3572, Item 9018245, Project Item Line Number 0450, Material Set 901824596, Material 0901LHPFSA - Foundation for Highway Lighting, Acceptance Action Generic 0901LHPFSA is insufficient.	D-15 received, but shop drawings still needed.	petrid1	Overridden

Revision 4/1/2020 Page 4 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTI To Date (See repo generated date)
17-H03	J9I3559	0001	0010	6161005	CONSTRUCTION SIGNS	784.00	0.00	784.00	SQFT	0.00	\$5.50	\$0.
		0001	0020	6161009	FLAG ASSEMBLY	11.00	0.00	11.00	EA	0.00	\$20.00	\$0.
		0001	0030	6161025	CHANNELIZER (TRIM LINE)	265.00	0.00	265.00	EA	12.00	\$12.00	\$144.
		0001	0040	6161033	DIRECTIONAL INDICATOR BARRICADE	35.00	0.00	35.00	EA	0.00	\$55.00	\$0
		0001	0050	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$10,250.00	\$0
		0001	0055	8051000A	SEEDING - COOL SEASON MIXTURES	2.80	0.00	2.80	ACRE	0.00	\$1,500.00	\$0
		0001	0060	8061005	ROCK DITCH CHECK	50.00	0.00	50.00	LF	0.00	\$22.50	\$0
		0001	0070	8061019	SILT FENCE	100.00	0.00	100.00	LF	0.00	\$4.50	\$0
		0020	0800	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	30.00	0.00	30.00	EA	0.00	\$1,885.00	\$1
		0020	0090	9011106	BRACKET ARM, 6 FT. OR 1.8 M	19.00	0.00	19.00	EA	0.00	\$350.00	\$1
		0020	0100	9011115	BRACKET ARM, 15 FT. OR 4.6 M	11.00	0.00	11.00	EA	0.00	\$680.00	\$
		0020	0110	9011312	LUMINAIRE, LED-B	30.00	0.00	30.00	EA	0.00	\$320.00	\$1
		0020	0120	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	4.00	0.00	4.00	EA	0.00	\$2,750.00	\$1
		0020	0130	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	513.00	0.00	513.00	LF	0.00	\$15.00	\$
		0020	0140	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	322.00	0.00	322.00	LF	0.00	\$16.00	\$
		0020	0150	9014004	CONDUIT, 4 IN. RIGID, PUSHED	1,872.00	0.00	1,872.00	LF	0.00	\$16.00	\$
		0020	0160	9015010	TRENCHING TYPE I	17,742.00	0.00	17,742.00	LF	0.00	\$3.20	\$
		0020	0170	9016110	PULL BOX, PREFORMED CLASS 1	57.00	0.00	57.00	EA	0.00	\$575.00	\$
		0020	0180	9017002	CABLE, 2 AWG 1 CONDUCTOR	2,040.00	0.00	2,040.00	LF	0.00	\$2.50	\$
		0020	0190	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	3,520.00	0.00	3,520.00	LF	0.00	\$0.90	\$
		0020	0200	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 6 AWG	7,130.00	0.00	7,130.00	LF	0.00	\$3.50	\$
		0020	0210	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	14,900.00	0.00	14,900.00	LF	0.00	\$3.25	\$
		0020	0220	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	30.00	0.00	30.00	EA	0.00	\$850.00	\$
		0020	0230	9018610	POWER SUPPLY ASSEMBLY, TYPE 1, 240/120 VOLT SERVICE, LIGHTING ONLY	3.00	0.00	3.00	EA	0.00	\$2,750.00	\$
		0020	0240	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	1.00	0.00	1.00	EA	0.00	\$2,750.00	\$
	Project J	913559 - To	tal Value	Posted to D	late as of Report Generated Date							\$14
	J9I3572	0001	0250	6161005	CONSTRUCTION SIGNS	784.00	0.00	784.00	SQFT	640.00	\$5.50	\$3,52
		0001	0260	6161009	FLAG ASSEMBLY	11.00	0.00	11.00	EA	11.00	\$20.00	\$22
		0001	0270	6161025	CHANNELIZER (TRIM LINE)	265.00	0.00	265.00	EA	265.00	\$12.00	\$3,18
		0001	0280	6161033	DIRECTIONAL INDICATOR BARRICADE	35.00	0.00	35.00	EA	0.00	\$55.00	\$
		0001	0290	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$7,350.00	\$7,35
		0001	0295	8051000A	SEEDING - COOL SEASON MIXTURES	1.80	0.00	1.80	ACRE	1.50	\$1,500.00	\$2,25
		0001	0300	8061005	ROCK DITCH CHECK	50.00	0.00	50.00	LF	0.00	\$22.50	\$
		0001	0310	8061019	SILT FENCE	100.00	0.00	100.00	LF	0.00	\$4.50	\$
		0020	0320	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	20.00	0.00	20.00	EA	20.00	\$1,880.00	\$37,60
		0020	0330	9011106	BRACKET ARM, 6 FT. OR 1.8 M	16.00	0.00	16.00	EA	16.00	\$350.00	\$5,60
		0020	0340	9011115	BRACKET ARM, 15 FT. OR 4.6 M	4.00	0.00	4.00	EA	4.00	\$680.00	\$2,72
		0020	0350	9011312	LUMINAIRE, LED-B	20.00	0.00	20.00	EA	20.00	\$320.00	\$6,40
		0020	0360	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	2.00	0.00	2.00	EA	1.00	\$2,750.00	\$2,75
		0020	0370	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	389.00	0.00	389.00	LF	63.00	\$15.00	\$94
		0020	0380	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	96.00	0.00	96.00	LF	20.00	\$16.00	\$32
		0020	0390	9014004	CONDUIT, 4 IN. RIGID, PUSHED	1,074.00	0.00	1,074.00	LF	1,074.00	\$16.00	\$17,18
		0020	0400	9015010	TRENCHING TYPE I	11,232.00	0.00	11,232.00	LF	11,137.00	\$3.20	\$35,63
				0010110	DULL DOV DEFENDATE OLAGO	42.00	0.00	42.00	Ε.Δ	40.00	A = = = 0.0	604.45
		0020	0410	9016110	PULL BOX, PREFORMED CLASS 1	42.00	0.00	42.00	EA	42.00	\$575.00	\$24,15

Revision 4/1/2020 Page 5 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200417-H03	J9I3572	0020	0430	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	2,280.00	0.00	2,280.00	LF	2,280.00	\$0.90	\$2,052.00
		0020	0440	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	13,760.00	0.00	13,760.00	LF	13,760.00	\$3.25	\$44,720.00
		0020	0450	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	20.00	0.00	20.00	EA	20.00	\$850.00	\$17,000.00
		0020	0460	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	2.00	0.00	2.00	EA	0.00	\$2,750.00	\$0.00
	Project J	1913572 - To	otal Value	Posted to D	Date as of Report Generated Date							\$213,599.40
200417-H03 Overall - Total Value Posted to Date as of Report Generated Date										\$213,743.40		

Revision 4/1/2020 Page 6 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9I3572

Project:	J9I3572											
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0290	6181000	MOBILIZATION	10/15/20	10/15/20	0.25	LS	J9I3572 - I-155	7.122 SB	RT	4.315 NB	RT	
0295	8051000A	SEEDING - COOL SEASON MIXTURES	10/13/20	10/15/20	0.80	ACRE	J9I3572 - I-155 SB to I-155 NB - Exit 6	7.122	RT	4.315	RT	
			10/14/20	10/15/20	0.70	ACRE	J9I3572 - I-155 SB to I-155 NB - Exit 4	4.668	RT	6.647	RT	
0320	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT	10/6/20	10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 NB Off Ramp - LP 203	0.169	RT			
				10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 NB Off Ramp - LP 204	0.015	RT			
				10/15/20	1.00	EA	J9I3572 - Exit 4 - Route U WB - LP 201	1.361	RT			
				10/15/20	1.00	EA	J9I3572 - Route U WB - LP 202	1.333	RT			
			10/7/20	10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 NB - LP 103	6.647				
				10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 SB - LP 102	4.123				
				10/15/20	1.00		J9I3572 - Exit 4 - I-155 SB Off Ramp - LP 101	0.170				
				10/15/20	1.00	EA EA	J913572 - Exit 4 - Route U EB - LP 301	3.627	RT			
				10/15/20	1.00	EA	J9I3572 - I-155 SB - LP 303 J9I3572 - Route U EB - LP 302	4.668 3.649				
0330	9011106	BRACKET ARM, 6 FT. OR 1.8 M	10/6/20	10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 NB Off Ramp - LP 203	0.169	RT			
0000	5011100	Brother Film, 611. Steller	10/0/20	10/15/20	1.00	EA	J9I3572 - Exit 4 - Route U WB - LP 201	1.361				
				10/15/20	1.00	EA	J9I3572 - Route U WB - LP 202	1.333				
			10/7/20	10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 NB - LP 103	6.647				
				10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 SB Off Ramp - LP 101	0.170	RT			
				10/15/20	1.00	EA	J9I3572 - Exit 4 - Route U EB - LP 301	3.627	RT			
				10/15/20	1.00	EA	J9I3572 - I-155 SB - LP 303	4.668	RT			
				10/15/20	1.00	EA	J9I3572 - Route U EB - LP 302	3.649	RT			
0340	9011115	BRACKET ARM, 15 FT. OR 4.6 M	10/6/20	10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 NB Off Ramp - LP 204	0.015				
			10/7/20	10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 SB - LP 102	4.123				
0350	9011312	LUMINAIRE, LED-B	10/6/20	10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 NB Off Ramp - LP 203	0.169	RT			
				10/15/20	1.00	EA EA	J913572 - Exit 4 - I-155 NB Off Ramp - LP 204	0.015	RT			
				10/15/20	1.00	EA	J9I3572 - Exit 4 - Route U WB - LP 201 J9I3572 - Route U WB - LP 202	1.361	RT			
			10/7/20	10/15/20	1.00		J9I3572 - Exit 4 - I-155 NB - LP 103	6.647				
				10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 SB - LP 102	4.123				
				10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 SB Off Ramp - LP 101	0.170	RT			
				10/15/20	1.00	EA	J9I3572 - Exit 4 - Route U EB - LP 301	3.627	RT			
				10/15/20	1.00	EA	J9I3572 - I-155 SB - LP 303	4.648	RT			
				10/15/20	1.00	EA	J9I3572 - Route U EB - LP 302	3.629	RT			
0360	9012230	BASE MOUNTED CONTROL STATION	10/8/20	10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 SB Off Ramp	0.176	RT			
0370	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	10/12/20	10/15/20	63.00	LF	J9I3572 - Exit 4 - I-155 SB Off Ramp - PB 20 to Controller	0.176	RT			Measured 26' - Paid plan quantity per Spec 901.18
0380	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	10/8/20	10/15/20	7.00	LF	J9l3572 - Exit 4 - I-155 SB Off Ramp - Controller to PB 1 J9l3572 - Exit 6 - I-155 NB Off Ramp - Controller to PB 21	0.176				Paid measured quantity per Spec 901.18 - Plan quantity of 42 - field changes Paid measured quantities per Spec 901.18 - Plan quantity
0390	9014004	CONDUIT, 4 IN. RIGID, PUSHED		10/15/20	46.00	LF	J9I3572 - Exit 4 - I-155 NB On Ramp - PB 8 to PB 9	0.022		0.022	PT	54' - Changes during construction Measured 43' - Paid plan quantity per Spec 901.18.2 - No
0000	0011001	CONSCIT, 4 M. NOIS, 1 CONES	10/0/20	10/15/20	54.00	LF	J9I3572 - Exit 4 - I-155 SB On Ramp - PB 15 to PB 16	0.019	RT	0.019		appreciable errors found for total quantity. Measured 43' - Paid plan quantity per Spec 901.18.2 - No
				10/15/20	56.00	LF	J9I3572 - Exit 4 - Route U WB to Route U EB - PB 13 to	1.477	RT	3.607	RT	appreciable errors found for total quantity. Measured 59' - Paid plan quantity per Spec 901.18.2 - No
				10/15/20	60.00	LF	PB 14 J913572 - Exit 4 - Route U WB to Route U EB - PB 10 to PB 11	1.316	RT	3.769	RT	appreciable errors found for total quantity. Measured 56' - Paid plan quantity per Spec 901.18.2 - No appreciable errors found for total quantity.
			10/6/20	10/15/20	46.00	LF	J9I3572 - Exit 4 - I-155 SB Off Ramp - PB 1 to PB 5	0.176	RT	0.176	LT	Measured 44' - Paid plan quantity per Spec 901.18.2
				10/15/20	147.00	LF	J9I3572 - Exit 4 - I-155 SB to I-155 NB - PB 6 to PB 7	4.300	RT	6.424		Measured 146' - Paid plan quantity per Spec 901.18.2
			10/7/20	10/15/20	-21.00	LF	J9l3572 - Exit 4 - I-155 SB - PB 3 to PB 4	4.089	RT	6.643	RT	Overrun for error and adjustments to avoid AT&T line at Exit 6.
				10/15/20	158.00	LF	J9I3572 - Exit 4 - I-155 SB - PB 3 to PB 4	4.089	RT	6.643	RT	Measured 162' - Paid plan quantity per Spec 901.18.2
0400	9015010	TRENCHING TYPE I	10/1/20	10/15/20	230.00		J9I3572 - Exit 6 - I-155 NB - PB 24 to PB 25	3.668	RT	3.763	RT	
				10/15/20	487.00		J9I3572 - Exit 4 - I-155 SB On Ramp - PB 15 to PB 17	0.019		0.115		
				10/15/20	503.00 503.00		J9l3572 - Exit 4 - I-155 SB On Ramp - PB 17 to PB 18 J9l3572 - Exit 4 - I-155 SB On Ramp to I-155 SB - PB 18 to PB 19	0.115 0.203		0.203 4.616		
			10/6/20	10/15/20	77.00	LE	J9I3572 - Exit 4 - Route U WB - LP 202 to PB 10	1.333	RT	1.316	RT	
				10/15/20	113.00		J9I3572 - Exit 4 - Route U EB to I-155 NB Off Ramp - PB 11 to LP 203	3.769		0.169		
				10/15/20	138.00	LF	J9I3572 - Exit 4 - I-155 NB On Ramp to Route U WB - PB 9 to LP 202	0.022	RT	1.333	RT	
				10/15/20	144.00		J9I3572 - Exit 4 - I-155 SB Off Ramp to I-155 SB - PB 5 to PB 6	0.176		4.300		
				10/15/20	341.00		J9I3572 - Exit 4 - I-155 NB to I-155 NB On Ramp	4.300		6.424		
				10/15/20	351.00 505.00		J9I3572 - Exit 4 - I-155 NB Off Ramp - PB 12 to LP 204 J9I3572 - Exit 4 - I-155 NB Off Ramp - LP 203 to PB 12	0.069		0.015		
			10/7/20	10/15/20	17.00		J9I3572 - Exit 4 - I-155 NB - PB 4 to LP 103	6.643		6.647		
			10///20		17.00		J9I3572 - Exit 4 - I-155 NB - PB 4 to LP 103 J9I3572 - Exit 4 - I-155 SB Off Ramp - PB 1 to LP 101	0.176		0.170		
				10/15/20		E1.						
				10/15/20	73.00	LF	J9I3572 - Exit 4 - I-155 SB On Ramp to Route U EB - PB 16 to LP 302	0.019	LI	3.649	RI	
				10/15/20	73.00 84.00	LF	16 to LP 302 J9l3572 - Exit 4 - Route U EB - PB 14 to LP 301	3.607	RT	3.627	RT	
				10/15/20 10/15/20 10/15/20	73.00 84.00 85.00	LF LF	16 to LP 302 J913572 - Exit 4 - Route U EB - PB 14 to LP 301 J913572 - Exit 4 - I-155 SB Off Ramp to Route U WB - PB 1 to PB 13	3.607 0.176	RT RT	3.627 1.477	RT RT	
				10/15/20 10/15/20 10/15/20 10/15/20	73.00 84.00 85.00 89.00	LF LF	16 to LP 302 J915372 - Exit 4 - Route U EB - PB 14 to LP 301 J915372 - Exit 4 - I-155 SB Off Ramp to Route U WB - PB 1 to PB 13 J915372 - Exit 4 - I-155 NB On Ramp to Route U WB - PB 8 to LP 201	3.607 0.176 0.022	RT RT LT	3.627 1.477 1.361	RT RT	
				10/15/20 10/15/20 10/15/20 10/15/20 10/15/20	73.00 84.00 85.00 89.00	LF LF	16 to LP 302 J913572 - Exit 4 - Noute U EB - PB 14 to LP 301 J913572 - Exit 4 - I-155 SB Off Ramp to Route U WB - PB 1 to PB 13 J913572 - Exit 4 - I-155 NB On Ramp to Route U WB - PB 8 to LP 201 J913572 - Exit 4 - I-155 NB On Ramp - LP 301 to PB 15	3.607 0.176 0.022 3.627	RT RT LT	3.627 1.477 1.361 0.019	RT RT RT	
				10/15/20 10/15/20 10/15/20 10/15/20	73.00 84.00 85.00 89.00	LF LF LF	16 to LP 302 J915372 - Exit 4 - Route U EB - PB 14 to LP 301 J915372 - Exit 4 - I-155 SB Off Ramp to Route U WB - PB 1 to PB 13 J915372 - Exit 4 - I-155 NB On Ramp to Route U WB - PB 8 to LP 201	3.607 0.176 0.022	RT RT LT RT RT	3.627 1.477 1.361	RT RT RT RT	

Revision 4/1/2020 Page 7 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0400	9015010	TRENCHING TYPE I	10/7/20	10/15/20	510.00	LF	J9I3572 - Exit 4 - I-155 SB Off Ramp to I-155 SB - LP 101 to PB 2	0.170	RT	4.199	RT	
			10/12/20	10/15/20	26.00	LF	J9I3572 - Exit 6 - I-155 NB Off Ramp - LP 401 to PB 21	0.218	RT	0.219	RT	
				10/15/20	175.00	LF	J9I3572 - Exit 6 - I-155 NB Off Ramp to Route 84 WB - PB 21 to PB 36	0.219	RT	0.109	RT	
0410	9016110	PULL BOX, PREFORMED CLASS 1	10/1/20	10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 NB Off Ramp - PB 12	0.069	RT			
				10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 SB - PB 19	4.616	RT			
				10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 SB On Ramp - PB 15	0.019	RT			
				10/15/20	1.00		J9I3572 - Exit 4 - I-155 SB On Ramp - PB 17	0.115				
			40/5/00	10/15/20	1.00		J9I3572 - Exit 4 - I-155 SB On Ramp - PB 18	0.203				
			10/5/20	10/15/20	1.00	EA EA	J9I3572 - Exit 4 - I-155 NB On Ramp - PB 8 J9I3572 - Exit 4 - I-155 NB On Ramp - PB 9	0.022				
				10/15/20	1.00	EA	J9I3572 - Exit 4 - Route U EB - PB 11	3.769				
				10/15/20	1.00	EA	J9I3572 - Exit 4 - Route U EB - PB 14	3.607				
				10/15/20	1.00	EA	J9I3572 - Exit 4 - Route U WB - PB 10	1.316	RT			
				10/15/20	1.00	EA	J9I3572 - Exit 4 - Route U WB - PB 13	1.477	RT			
				10/15/20	1.00		J9I3572 - I-155 SB On Ramp - PB 16	0.019				
			10/6/20	10/15/20	1.00	EA	J913572 - Exit 4 - I-155 SB - PB 6	4.300				
				10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 SB Off Ramp - PB 5 J9I3572 - I-155 NB - PB 7	0.176 6.424				
			10/7/20	10/15/20	1.00		J9I3572 - Exit 4 - I-155 NB - PB 4	6.643				
				10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 SB - PB 2	4.199				
				10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 SB - PB 3	4.089	RT			
				10/15/20	1.00	EA	J9I3572 - Exit 4 - I-155 SB Off Ramp - PB 1	0.176	RT			
			10/8/20	10/15/20	1.00	EA		0.176				
			10/12/20	10/15/20	1.00		J9I3572 - Exit 6 - I-155 SB Off Ramp - PB 21	0.219				
0430	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE & BRACKE	10/6/20	10/15/20	110.00	LF	J9I3572 - Exit 4 - I-155 NB Off Ramp - LP 203 J9I3572 - Exit 4 - Route U WB - LP 201	0.169				
				10/15/20	110.00	LF	J9I3572 - Route U WB - LP 202	1.333				
				10/15/20	130.00	LF	J9I3572 - Exit 4 - I-155 NB Off Ramp - LP 204	0.015				
			10/7/20	10/15/20	110.00	LF	J9I3572 - Exit 4 - I-155 NB - LP 103	6.647	RT			
				10/15/20	110.00	LF	J9I3572 - Exit 4 - I-155 SB Off Ramp - LP 101	0.170	RT			
				10/15/20	110.00	LF	J9I3572 - Exit 4 - Route U EB - LP 301	3.627	RT			
				10/15/20	110.00	LF	J9I3572 - I-155 SB - LP 303	4.648				
				10/15/20	110.00	LF	J9I3572 - Route U EB - LP 302 J9I3572 - Exit 4 - I-155 SB - LP 102	3.649 4.123				
0440	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	10/1/20	10/15/20	1 020 00		J913572 - 1155 NB to I-155 SB - LP 402 to LP 403	3.763		7.122	RT	
0110	0011-101	orbic company, risk, a company or or	10/7/20	10/15/20	80.00	LF	J9I3572 - Exit 4 - I-155 NB On Ramp to Route U WB - PB	0.022		1.361	RT	Measured 97' - Paid plan quantity at 10' increments pe
				10/15/20	100.00	LF	8 to LP 201 J9I3572 - Exit 4 - Route U EB to I-155 SB On Ramp - LP 301 to PB 15	3.627	RT	0.019	RT	spec book section 901.18.3 Measured 123' - Paid plan quantity at 10' increments p
				10/15/20	120.00	LF	J9I3572 - Exit 4 - I-155 SB On Ramp to Route U EB - PB 15 to LP 302	0.019	RT	3.649	LT	spec book section 901.18.3 Measured 130' - Paid plan quantity at 10' increments p spec book section 901.18.3
				10/15/20	210.00	LF	J9I3572 - Exit 4 - I-155 NB On Ramp - PB 8 to LP 202	0.022	LT	0.022	RT	Measured 195' - Paid plan quantity at 10' increments p spec book section 901.18.3
				10/15/20	230.00	LF	J9I3572 - Exit 4 - Snaking - I-155 NB to I-155 SB	6.647	RT	4.668	RT	Paid plan quantity at 10' increments per spec book section 901.18.3
				10/15/20	260.00	LF	J9I3572 - Exit 4 - Route U WB to Route U EB - LP 202 to LP 203	1.333	RT	3.769	RT	Measured 268' - Paid plan quantity at 10' increments p spec book section 901.18.3
				10/15/20	870.00		J9I3572 - Exit 4 - I-155 NB Off Ramp - LP 203 to LP 204	0.169		0.015		Measured 872' - Paid plan quantity at 10' increments p spec book section 901.18.3
				10/15/20	900.00	LF	J9I3572 - Exit 4 - I-155 SB Off Ramp - I-155 SB - LP 101 to LP 102	0.170		4.199		Measured 902' - Paid plan quantity at 10' increments p spec book section 901.18.3
				10/15/20	1,820.00	LF	to LP 303	0.019	RT	4.668	RT	Measured 1810' - Paid plan quantity at 10' increments spec book section 901.18.3
			10/8/20	10/15/20	40.00 80.00	LF	J9I3572 - I-155 - Exit 4 - Snaking J9I3572 - Exit 4 - I-155 SB Off Ramp - Controller to LP	0.176	RT			Snaking - Paid plan quantity per Spec 901.18 Measured 47' - Paid plan quantity per Spec 901.18
				10/15/20	300.00		J9I3572 - Exit 4 - I-155 SB Off Ramp to Route U WB -	0.176		3.627	RT	Measured 270' - Paid plan quantity per Spec 901.18
							Controller to LP 301					
				10/15/20	410.00 800.00		J913572 - Exit 4 - I-155 SB - LP 102 to LP 103	4.132 0.176		6.647 0.022		Measured 388' - Paid plan quantity per Spec 901.18
			10/12/20	10/15/20	100.00		J9l3572 - Exit 4 - I-155 SB Off Ramp to I-155 NB On Ramp - Controller to PB 8 J9l3572 - Exit 6 - I-155 NB Off Ramp - LP 401 to	0.176		0.022		Measured 721' - Paid plan quantity per Spec 901.18 Measured 50' -
				10/15/20	110.00		Controller J913572 - Exit 6 - Snaking	7.122		4.315		
				10/15/20	340.00	LF	J9I3572 - Exit 6 - I-155 NB Off Ramp to Route 84 EB -	SB 0.219	RT	NB 30.060	RT	
				10/15/20	810.00	LF	Controller to LP 601 J9I3527- Exit 6 - I-155 NB Off Ramp to I-155 SB -	0.219	RT	6.798	RT	Measured 704' - Paid plan quantity per Spec 901.18
0450	9018245	POLE FOUNDATION (45 FT. OR 13.5 M	10/6/20	10/15/20	1.00		Controller to PB 30 J9l3572 - Exit 4 - I-155 NB Off Ramp - LP 203	0.169				
				10/15/20	1.00		J9I3572 - Exit 4 - I-155 NB Off Ramp - LP 204	0.015				
				10/15/20	1.00		J9I3572 - Exit 4 - Route U WB - LP 201	1.361				
			405	10/15/20	1.00		J9I3572 - Route U WB - LP 202	1.333				
			10/7/20	10/15/20	1.00		J9I3572 - Exit 4 - I-155 NB - LP 103 J9I3572 - Exit 4 - I-155 SB - LP 102	6.647 4.123				
				10/15/20	1.00		J9I3572 - Exit 4 - I-I55 SB - LP 102 J9I3572 - Exit 4 - I-I55 SB Off Ramp - LP 101	0.170				
				10/15/20	1.00		J9I3572 - Exit 4 - Route U EB - LP 301	3.627				
				10/15/20	1.00		J9I3572 - I-155 SB - LP 303	4.648	RT			
							J9I3572 - Route U EB - LP 302	3.649				

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 8 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

			2.1					
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0030	CHANNELIZER (TRIM LINE)	Material		1	Sep 16, 2020	SYSTEM	(\$144.00)	
				1	Sep 16, 2020	SYSTEM	\$144.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0030 -	Total						\$0.00	
0250	CONSTRUCTION SIGNS	Material		1	Sep 16, 2020	SYSTEM	(\$880.00)	
				1	Sep 16, 2020	SYSTEM	\$880.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0250 -	Total						\$0.00	
0260	FLAG ASSEMBLY	Material		1	Sep 16, 2020	SYSTEM	(\$120.00)	
				1	Sep 16, 2020	SYSTEM	\$120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user petrid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0260 -	Total						\$0.00	
0295	SEEDING - COOL SEASON MIXTURES	Material		3	Oct 15, 2020	SYSTEM	(\$2,250.00)	
				3	Oct 15, 2020	SYSTEM	\$2,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0295 -	Total						\$0.00	
0320	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	Material		2	Sep 30, 2020	SYSTEM	(\$18,800.00)	
				2	Sep 30, 2020	SYSTEM	\$18,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user petrid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0320 - 0330	BRACKET ARM, 6 FT. OR 1.8	Material		2	Sep 30,	SYSTEM	\$0.00 (\$2,800.00)	
	М			2	2020 Sep 30, 2020	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user petrid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total		Total				\$0.00	
0330 -							\$0.00	
0340	BRACKET ARM, 15 FT. OR 4.6 M	Material		2	Sep 30, 2020	SYSTEM	(\$1,360.00)	
				2	Sep 30, 2020	SYSTEM	\$1,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user petrid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0340 -	Total						\$0.00	
0350	LUMINAIRE, LED-B	Material		2	Sep 30, 2020	SYSTEM	(\$3,200.00)	
				2	Sep 30, 2020	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user petrid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.

Revision 4/1/2020 Page 9 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0350		Material	- Total				\$0.00	
	Material - Total						\$0.00	
0350 -	- Total						\$0.00	
0390	CONDUIT, 4 IN. RIGID, PUSHED	Material		2	Sep 30, 2020	SYSTEM	(\$8,448.00)	
				2	Sep 30, 2020	SYSTEM	\$8,448.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user petrid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0390 -	- Total						\$0.00	
0410	PULL BOX, PREFORMED CLASS 1	Material		2	Sep 30, 2020	SYSTEM	(\$12,075.00)	
				2	Sep 30, 2020	SYSTEM	\$12,075.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user petrid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0410 -	- Total						\$0.00	
0430	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material		2	Sep 30, 2020	SYSTEM	(\$1,026.00)	
				2	Sep 30, 2020	SYSTEM	\$1,026.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user petrid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0430 -	- Total						\$0.00	
0440	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material		2	Sep 30, 2020	SYSTEM	(\$16,770.00)	
				2	Sep 30, 2020	SYSTEM	\$16,770.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user petrid1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
			- i Otai				\$0.00	
	Material - Total		- Total				\$0.00	
0440 -	Material - Total - Total		- Total					
0440 - 0450	- Total POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING	Material	- Total	2	Sep 30, 2020	SYSTEM	\$0.00	
	- Total POLE FOUNDATION (45 FT.	Material	- 10tal	2		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user petrid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
	- Total POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING	Material	-100		2020 Sep 30,	SYSTEM	\$0.00 \$0.00 (\$8,500.00)	Item Adjustment (0009) due to user petrid1 overridding Payment Estimate
	- Total POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING	Material	-100	2	2020 Sep 30, 2020 Oct 15,	SYSTEM	\$0.00 \$0.00 (\$8,500.00) \$8,500.00	Item Adjustment (0009) due to user petrid1 overridding Payment Estimate
	- Total POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING	Material	- Total	2	2020 Sep 30, 2020 Oct 15, 2020 Oct 15,	SYSTEM	\$0.00 \$0.00 (\$8,500.00) \$8,500.00 (\$17,000.00)	Item Adjustment (0009) due to user petrid1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user petrid1 overridding Payment Estimate
	- Total POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING	Material		2	2020 Sep 30, 2020 Oct 15, 2020 Oct 15,	SYSTEM	\$0.00 \$0.00 (\$8,500.00) \$8,500.00 (\$17,000.00) \$17,000.00	Item Adjustment (0009) due to user petrid1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user petrid1 overridding Payment Estimate
0450	- Total POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	Material		2	2020 Sep 30, 2020 Oct 15, 2020 Oct 15,	SYSTEM	\$0.00 \$0.00 (\$8,500.00) \$8,500.00 (\$17,000.00) \$17,000.00	Item Adjustment (0009) due to user petrid1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user petrid1 overridding Payment Estimate

Revision 4/1/2020 Page 10 of 10