

# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 3, 2022

Progress Estim	nate Number	Contract ID Prime Contracto	200515-C05 or Comanche Cons	truction, Inc.		e 1, 2022 I	Original Contract Amour Net Change Order Amou Current Contract Amoun	nt \$974,806.07			
Approval Date								By User			
June 3, 2022			Generated and Approved (and should be considered Draft) at the Project Office Level by								
June 3, 2022		R	eviewed and Approv	/ed (and sho	uld be considered Draf	t) at the Re	sident Engineer Level by	sandis1			
June 6, 2022			R	Reviewed and	d Approved at the Cent	ral Office C	ontrollers Office Level by	ramses1			
Original Comp	oletion Date	Current Co	ompletion Date	Actual	Completion Date	% o	f Current Contract Amou	int Complete			
June 30,	2021	June	30, 2022				54.27%				
	Contro										

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	June 3, 2020	June 3, 2020	
Letting Date	May 15, 2020	May 15, 2020	
Notice to Proceed Date	July 1, 2020	July 1, 2020	
Open to Traffic Date			
Work Began Date			

Contract Total P	ay For Estimate No. 32			
		This Estimate	Previous	To Date
200515-C05				
	Total Posted Items Pay	\$57,647.34	\$1,554,173.84	\$1,611,821.18
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	(\$55,450.60)	\$55,450.60	\$0.00
	•		\$1,609,624.44	\$1,611,821.18
Contract Total Pa	avable This Estimate:	\$2,196,74		

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4I3175	0030	6189916	MISC.WEEKEND WORK ADJUSTMENT FACTOR	DLR	\$1.750	2,644	\$4,627.00
	5008	7039901	MISC. Bridge Approach Pavement Repair	LS	\$53,020.340	1	\$53,020.34
Project J4I317	5 - Total						\$57,647.34
Overall - Total							\$57,647.34

### **Contract Adjustments This Estimate**

Adj Type	Entered By	Comments	Time Units	Rate	Amount
OTHROther Contract Adjustment	, ,	This negative contract adjustment is being made to retract a contract adjustment that was made on Pay Estimate 0025 for prompt payment to the contractor for replacement and installation of bridge approach slabs on Route W. The work and materials are being paid for as part of Contingent Line No. 5008 on this Pay Estimate (Pay Estimate 32).			(\$55,450.60)

Overall - Total
These amounts are listed in the Incentive, Disincentive, Liquidated Damages or Other Contract Adjustments

(\$55,450.60)

Line Item Adjustments This Estimate

Revision 4/1/2020 Page 1 of 10



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 3, 2022

Progress Estimate Number 32 Contract ID 200515-C05 Pay Period Start April 16, 2022 Original Contract Amount \$1,995,000.00 Prime Contractor Comanche Construction, Inc. Pay Period End June 1, 2022 Original Contract Amount \$974,806.07 Current Contract Amount \$2,969,806.07

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3175	5001	REINFORCING STEEL	Material			-681	\$4.71	(\$3,207.51)
	5001	REINFORCING STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user yostj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	681	\$4.71	\$3,207.51
	5010	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material			-408	\$23.98	(\$9,783.84)
	5010	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	408	\$23.98	\$9,783.84
	5011	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	Material			-1	\$3,490.73	(\$3,490.73)
	5011	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1	\$3,490.73	\$3,490.73
	5013	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-2,665	\$0.98	(\$2,611.70)
	5013	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	2,665	\$0.98	\$2,611.70
	5014	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-919	\$0.98	(\$900.62)
	5014	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	919	\$0.98	\$900.62
Total								\$0.00

Revision 4/1/2020 Page 2 of 10



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	l					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
J4I3175	FAS S302(5)	Job Order Contracting for bridge repair	Various	VARIOUS	at various locations in the	at various locations in the urban Kansas City District						
Totals by	Job Numb	ers										
J4I3175		ed Item Pay s Item Adjustr		Item Pay	This Estimate \$57,647.34 \$0.00 \$57,647.34	Previous \$1,554,173.84 \$0.00 \$1,554,173.84	To Date \$1,611,821.18 \$0.00 \$1,611,821.18					
	Liqui	ntive centive dated Damage r Contract Adj			\$0.00 \$0.00 \$0.00 (\$55,450.60)	\$0.00 \$0.00 \$0.00 \$55,450.60	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 4/1/2020 Page 3 of 10



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 6122017, Project Item Line Number 5011, Material Set 612201796, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 6173600D, Project Item Line Number 5010, Material Set 6173600D96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 6205902A, Project Item Line Number 5013, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 6205902A, Project Item Line Number 5013, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 6205903A, Project Item Line Number 5014, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 6205903A, Project Item Line Number 5014, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M22 - Reinforcing Steel No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M32 - Reinforcing Steel No. 10/M32 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSSRPLAB - Plain Spiral Stl Rein for Anchor Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3175, Item 7061000, Project Item Line Number 5001, Material Set 706100096, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials and the contractor to resolve materials exception.	yostj1	Overridden

Revision 4/1/2020 Page 4 of 10



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-C05	J4I3175	0001	0010	6189916	MISC.NIGHTTIME WORK ADJUSTMENT FACTOR	1,125,000.00	0.00	1,125,000.00	DLR	0.00	\$1.25	\$0.00
		0001	0020	6189916	MISC.NORMAL WORK ADJUSTMENT FACTOR	225,000.00	0.00	225,000.00	DLR	192,378.00	\$1.45	\$278,948.10
		0001	0030	6189916	MISC.WEEKEND WORK ADJUSTMENT FACTOR	150,000.00	0.00	150,000.00	DLR	206,814.00	\$1.75	\$361,924.50
		0001	5001	7061000	REINFORCING STEEL	0.00	1,500.00	1,500.00	LB	681.00	\$4.71	\$3,207.51
		0001	5002	6079901	MISC. FENCE REPAIR	0.00	1.00	1.00	LS	1.00	\$30,203.25	\$30,203.25
		0001	5003	7129901	MISC.Bridge Beam Cap Repair	0.00	1.00	1.00	LS	1.00	\$29,135.80	\$29,135.80
		0001	5004	7049901	MISC Bridge Joint Repair	0.00	1.00	1.00	LS	1.00	\$2,795.81	\$2,795.81
		0001	5005	7129901	MISC.Bridge Joint Repair	0.00	1.00	1.00	LS	1.00	\$306,833.05	\$306,833.05
		0001	5006	7039901	MISC. Concrete Column Repair	0.00	1.00	1.00	LS	1.00	\$41,202.58	\$41,202.58
		0001	5007	7129901	MISC. Bridge Abutment Wing Wall Repair	0.00	1.00	1.00	LS	1.00	\$122,826.67	\$122,826.67
		0001	5008	7039901	MISC. Bridge Approach Pavement Repair	0.00	1.00	1.00	LS	1.00	\$53,020.34	\$53,020.34
		0001	5009	7129901	MISC Bridge Joint Removal and Replacement	0.00	1.00	1.00	LS	1.00	\$347,055.08	\$347,055.08
		0001	5010	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	0.00	408.00	408.00	LF	408.00	\$23.98	\$9,783.84
		0001	5011	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	0.00	1.00	1.00	EA	1.00	\$3,490.73	\$3,490.73
		0001	5012	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	0.00	10,160.00	10,160.00	LF	10,160.00	\$1.76	\$17,881.60
		0001	5013	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	0.00	2,665.00	2,665.00	LF	2,665.00	\$0.98	\$2,611.70
		0001	5014	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	0.00	919.00	919.00	LF	919.00	\$0.98	\$900.62
		0001	9000	6189916	MISC.Liquidated Damages	0.00			DLR	0.00	(\$1.00)	\$0.00
		0001	9100	6189916	MISC.Additional Items	0.00			DLR	0.00	\$1.00	\$0.00
		0001	9200	6189902	MISC.High Priority Repair	0.00			EA	0.00	\$2,400.00	\$0.00
	Project .	J4I3175 - To	otal Value	Posted to D	late as of Report Generated Date							\$1,611,821.18
200515-C05 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$1,611,821.18

Page 5 of 10 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	6189916	MISC.	5/31/22	6/3/22	2,644.00	DLR	EB I-70 over Manchester					This provides payment for the work completed on EB I-70 over Manchester on 5/14: Double Lane Closure - 1 EA Repairing Concrete Deck (half-soling) (Under 200 SF) - 24 SF
5008	7039901	MISC. CONCRETE CONSTRUCTION	4/29/22	5/3/22	1.00	LS	Bridge A2351E (Rt. W over the Blue River)					This payment is for the Extra Work associated with Work Order 11 (Rt. W over Blue River Approach Pavement Repair).

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 6 of 10



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3175	5001	REINFORCING STEEL	Material		4	Dec 16, 2020	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Dec 16, 2020	SYSTEM	(\$3,207.51)	
					5	Jan 5, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jan 5, 2021	SYSTEM	(\$3,207.51)	
					6	Jan 20, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jan 20, 2021	SYSTEM	(\$3,207.51)	
					7	Feb 3, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sandis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Feb 3, 2021	SYSTEM	(\$3,207.51)	
					8	Feb 17, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Feb 17, 2021	SYSTEM	(\$3,207.51)	
					9	Mar 2, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Mar 2, 2021	SYSTEM	(\$3,207.51)	
					10	Mar 16, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Mar 16, 2021	SYSTEM	(\$3,207.51)	
					11	Apr 6, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Apr 6, 2021	SYSTEM	(\$3,207.51)	
					12	Apr 16, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Apr 16, 2021	SYSTEM	(\$3,207.51)	
					13	May 4, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sandis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	May 4, 2021	SYSTEM	(\$3,207.51)	
					14	May 17, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	May 17, 2021	SYSTEM	(\$3,207.51)	
					15	Jun 1, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Jun 1, 2021	SYSTEM	(\$3,207.51)	
					16	Jun 17, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Jun 17, 2021	SYSTEM	(\$3,207.51)	



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3175	5001	REINFORCING STEEL	Material		17	Jul 2, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Jul 2, 2021	SYSTEM	(\$3,207.51)	
					18	Jul 16, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					18	Jul 16, 2021	SYSTEM	(\$3,207.51)	
					19	Aug 3, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					19	Aug 3, 2021	SYSTEM	(\$3,207.51)	
					20	Aug 16, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					20	Aug 16, 2021	SYSTEM	(\$3,207.51)	
					21	Sep 2, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					21	Sep 2, 2021	SYSTEM	(\$3,207.51)	
					22	Sep 16, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					22	Sep 16, 2021	SYSTEM	(\$3,207.51)	
					23	Oct 1, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					23	Oct 1, 2021	SYSTEM	(\$3,207.51)	
					24	Oct 18, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					24	Oct 18, 2021	SYSTEM	(\$3,207.51)	
					25	Nov 1, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					25	Nov 1, 2021	SYSTEM	(\$3,207.51)	
					26	Nov 15, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					26	Nov 15, 2021	SYSTEM	(\$3,207.51)	
					27	Dec 2, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					27	Dec 2, 2021	SYSTEM	(\$3,207.51)	
					28	Dec 16, 2021	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					28	Dec 16, 2021	SYSTEM	(\$3,207.51)	
					29	Jan 19, 2022	SYSTEM	\$3,207.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					29	Jan 19, 2022	SYSTEM	(\$3,207.51)	



# Line Item Adjustments by Estimate

STEEL	
2022	nal system-generated Material Payment due to user sandis1 overridding Payment ent Payment Estimate.
2022   Stimate Item Adjustment (DOZ Estimate Exception 7 on the Curr	
2022   32	nal system-generated Material Payment due to user mcclon1 overridding Payment ent Payment Estimate.
2022   Estimate Etm Adjustment (0001	
Solid   Total   Solid   Soli	nal system-generated Material Payment due to user yostj1 overridding Payment ent Payment Estimate.
Material - Total   S0.00	
S001 - Total   S000   TEMPORARY   TRAFFIC BARRIER, CONT.   FURNINE   S000   S11 - Total   S	
Solid   TEMPORARY TRAFFICE BARRIER, CONT.   Solid	
Solid   TEMPORARY TRAFFIC BARRIER, CONT.   FURN/RE	
SOUD - Total   SOUD	nal system-generated Material Payment due to user mcclon1 overridding Payment ent Payment Estimate.
2022   Sestimate Item Adjustment (0002 Estimate Exception 2 on the curr	
2022   Sum   Sum	nal system-generated Material Payment due to user yostj1 overridding Payment ent Payment Estimate.
Solid - Total   Solid   Soli	
S010 - Total   S0.00	
Solid   IMPACT ATTENUATOR   65 MPH (SAND BARREL ARRAY)   Solid   System   Solid   System   System   Solid   System   System   Solid   System   System   Solid   System   System   Solid   System   System   Solid   System   Solid   System   System   Solid   System   System   Solid   System   System   Solid   System   System   System   Solid   System   System   System   Solid   System   System	
ATTENUATOR 65 MPH (SAND BARREL ARRAY)	
ARRAY	nal system-generated Material Payment due to user mcclon1 overridding Payment ent Payment Estimate.
2022   Estimate Item Adjustment (0003)	
2022	nal system-generated Material Payment due to user yostj1 overridding Payment ent Payment Estimate.
Material - Total   \$0.00	
Solid   Soli	
31   Apr 15, 2022   SYSTEM   \$2,611.70   This adjustment offsets the origin	
31	
31	nal system-generated Material Payment due to user mcclon1 overridding Paymen ent Payment Estimate.
2022 Estimate Item Adjustment (0004) Estimate Exception 3 on the curr  32 Jun 3, SYSTEM (\$2,611.70)	
	nal system-generated Material Payment due to user yostj1 overridding Payment ent Payment Estimate.
- Total \$0.00	
Material - Total \$0.00	
5013 - Total \$0.00	
5014 6 IN. YELLOW Material 31 Apr 15, SYSTEM \$900.62 This adjustment offsets the origin Estimate Item Adjustment (0005)	nal system-generated Material Payment due to user mcclon1 overridding Paymen
WATERBORNE PAINT  31 Apr 15, SYSTEM (\$900.62)	ent Payment Estimaté.

Jun 7, 2022



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4I3175	5014	014 6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material			2022				
					32	Jun 3, 2022	SYSTEM	\$900.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					3	32	Jun 3, 2022	SYSTEM	(\$900.62)	
				- Total				\$0.00		
			Material - Total					\$0.00		
	5014 - Total							\$0.00		
J4I3175	5 - Total							\$0.00		
Overall - Total							\$0.00			