

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 1, 2022

Progress Estimate Number	Contract ID	200515-C06	Pay Period Start	May 2, 2022	Original Contract	\$1,664,400.00
31	Prime Contractor	Custom Lighting Services, LLC dba Black	Pay Period En	d June 1, 2022	Net Change Order Amount Current Contract Amoun	\$60,104.61 <b>t</b> \$1,724,504.61

Approval Date		By User
June 3, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	sandis1
June 3, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	sandis1
June 6, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	<b>Current Completion Date</b>	Actual Completion Date	% of Current Contract Amount Complete		
May 31, 2021	May 31, 2022		69.74%		

	Milestones		
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	June 3, 2020	June 3, 2020	
Letting Date	May 15, 2020	May 15, 2020	
Notice to Proceed Date	June 4, 2020	June 4, 2020	
Open to Traffic Date			
Work Began Date	August 17, 2020	August 17, 2020	

Contract Total Pay For Estimate No. 31										
		This Estimate	Previous	To Date						
200515-C06										
	Total Posted Items Pay	\$139,411.13	\$1,063,299.09	\$1,202,710.22						
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
			\$1,063,299.09	\$1,202,710.22						
<b>Contract Total Pay</b>	able This Estimate:	\$139,411.13								

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4I3239	0010	9019902	MISC.LABOR/EQUIPMENT FOR TROUBLE SHOOTING/INVESTIGATION/REPAIR WORK ADJUSTMENT FACTOR	EA	\$1.045	81,032.5	\$84,678.96
	0020	9019902	MISC.MATERIAL FOR REPAIR WORK ADJUSTMENT FACTOR	EA	\$1.750	26,261.24	\$45,957.17
	0030	9019902	MISC.TRAFFIC CONTROL ADJUSTMENT FACTOR	EA	\$3.250	2,700	\$8,775.00
Project J4	1 <mark>3239 - T</mark> o	tal					\$139,411.13
Overall - T	otal						\$139,411.13

#### **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3239	5001	MISC.	Material			-1	\$686.21	(\$686.21)
	5001	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1	\$686.21	\$686.21
	5002	MISC.	Material			-1	\$832.54	(\$832.54)
	5002	MISC.	Material		This adjustment offsets the original system-	1	\$832.54	\$832.54

Revision 4/1/2020 Page 1 of 27



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 1, 2022

Progress Estimate Number 31

Contract ID 200515-C06 Prime Custom Lighting Services, LLC dba Black Pay Period Start Pay Period End June 1, 2022 Prime Current Contract Amount \$1,664,400.00 Prime Contractor Pay Period End June 1, 2022 Prime Report Start Pay Period End June 1, 2022 Prime Report Pay Period End June 1, 2022 Prime Pay Period End June 1, 2022 Prime Pay Period End June 1, 20

- 4	Lina	Itama Daganintian	A ali a tuan a un t	Oth an Itama	Comments	A -1:	l in a léana	Λ -l:t
ect oer	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustmen amount
39					generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
	5003	MISC.	Material			-1	\$52.32	(\$52.32
	5003	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	1	\$52.32	\$52.32
	5004	MISC.	Material			-1	\$1,374.44	(\$1,374.44
	5004	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1	\$1,374.44	\$1,374.44
	5005	MISC.	Material			-1	\$17.88	(\$17.88
	5005	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1	\$17.88	\$17.88
	5006	MISC.	Material			-1	\$190.62	(\$190.62
	5006	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	1	\$190.62	\$190.62
	5007	MISC.	Material			-1	\$462.00	(\$462.00
	5007	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	1	\$462.00	\$462.00
	5008	MISC.	Material			-1	\$431.40	(\$431.40
	5008	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	1	\$431.40	\$431.40
	5009	MISC.	Material			-1	\$1,072.87	(\$1,072.87
	5009	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	1	\$1,072.87	\$1,072.87
	5010	MISC.	Material			-1	\$13.20	(\$13.20
	5010	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	1	\$13.20	\$13.20
	5051	MISC.	Material			-1	\$2,590.18	(\$2,590.18
	5051	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	1	\$2,590.18	\$2,590.18

Revision 4/1/2020 Page 2 of 27



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 1, 2022

Progress Estimate Number 31 Contract ID 200515-C06 Prime Contractor Custom Lighting Services, LLC dba Black Pay Period End June 1, 2022 Original Contract \$1,664,400.00 Prime Contractor Pay Period End June 1, 2022 Prime Net Change Order Amount Current Contract Amount \$1,724,504.61

Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
413239					Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
	5052	MISC.	Material			-1	\$1,264.92	(\$1,264.92)
	5052	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	1	\$1,264.92	\$1,264.92
	5053	MISC.	Material			-1	\$462.00	(\$462.00)
	5053	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	1	\$462.00	\$462.00
	5054	MISC.	Material			-1	\$462.00	(\$462.00)
	5054	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	1	\$462.00	\$462.00
	5055	MISC.	Material			-1	\$924.00	(\$924.00)
	5055	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	1	\$924.00	\$924.00
	5056	MISC.	Material			-1	\$456.00	(\$456.00)
	5056	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	1	\$456.00	\$456.00
	5057	MISC.	Material			-1	\$474.00	(\$474.00)
	5057	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	1	\$474.00	\$474.00
	5058	MISC.	Material			-1	\$571.68	(\$571.68)
	5058	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	1	\$571.68	\$571.68
	5059	MISC.	Material			-1	\$1,126.32	(\$1,126.32)
	5059	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	1	\$1,126.32	\$1,126.32
	5060	MISC.	Material			-1	\$1,452.46	(\$1,452.46)
	5060	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user weathc1	1	\$1,452.46	\$1,452.46

Revision 4/1/2020 Page 3 of 27



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 1, 2022

Progress Estimate Number 31

Contract ID

200515-C06

Pay Period Start

Custom Lighting Services, LLC dba Black

Pay Period End June 1, 2022

Pay Period End June 1, 2022

Original Contract Amount \$1,664,400.00

Net Change Order Amount \$60,104.61

Current Contract Amount \$1,724,504.61

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3239					overridding Payment Estimate Exception 26 on the current Payment Estimate.			
	5061	MISC.	Material			-1	\$750.91	(\$750.91)
	5061	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	1	\$750.91	\$750.91
	5062	MISC.	Material			-1	\$685.66	(\$685.66)
	5062	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	1	\$685.66	\$685.66
	5063	MISC.	Material			-1	\$462.00	(\$462.00)
	5063	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	1	\$462.00	\$462.00
	5064	MISC.	Material			-1	\$462.00	(\$462.00)
	5064	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	1	\$462.00	\$462.00
	5065	MISC.	Material			-1	\$462.00	(\$462.00)
	5065	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	1	\$462.00	\$462.00
	5066	MISC.	Material			-1	\$924.00	(\$924.00)
	5066	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1	\$924.00	\$924.00
	5067	MISC.	Material			-1	\$462.00	(\$462.00)
	5067	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	1	\$462.00	\$462.00
	5068	MISC.	Material			-1	\$319.10	(\$319.10)
	5068	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	1	\$319.10	\$319.10
	5069	MISC.	Material			-1	\$462.00	(\$462.00)
	5069	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 29	1	\$462.00	\$462.00

Revision 4/1/2020 Page 4 of 27



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 1, 2022

Progress Estimate Number	Contract ID	200515-C06	Pay Period May 2, 20	<sub>22</sub> Original Contract Amount	\$1,664,400.00
31	Prime Contractor	Custom Lighting Services, LLC dba Black	Pay Period End June 1, 2022	Net Change Order Amount Current Contract Amo	\$60,104.61 <b>bunt</b> \$1,724,504.61

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3239					on the current Payment Estimate.			
	5070	MISC.	Material			-1	\$462.00	(\$462.00)
	5070	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	1	\$462.00	\$462.00
	5071	MISC.	Material			-1	\$462.00	(\$462.00)
	5071	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	1	\$462.00	\$462.00
Total								\$0.00

Revision 4/1/2020 Page 5 of 27



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information	1						
						John det i reject illicillade							
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work							
J4I3239		Job Order Contract for lighting repair	Various	VARIOUS	at various locations in the	e urban Kansas City District	t .						
Totals by .	Job Numb	ers											
J4I3239					This Estimate	Previous	To Date						
	Poste	ed Item Pay			\$139,411.13	\$1,063,299.09	\$1,202,710.22						
	Gros	s Item Adjustr	nents		\$0.00	\$0.00	\$0.00						
			Gross	Item Pay	\$139,411.13	\$1,063,299.09	\$1,202,710.22						
	Incer	ntive			\$0.00	\$0.00	\$0.00						
		centive			\$0.00	\$0.00	\$0.00						
		dated Damage	s		\$0.00	\$0.00	\$0.00						
		r Contract Adj			\$0.00	\$0.00	\$0.00						

Revision 4/1/2020 Page 6 of 27



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5001, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5002, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5005, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5008, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5010, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5004, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5007, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5009, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5003, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5006, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5053, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5059, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5061, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5062, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5064, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5066, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5070, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5051, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5054, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5057, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5063, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5065, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5052, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5056, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic	Working with Materials.	weathc1	Overridden

Revision 4/1/2020 Page 7 of 27



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
0901LHXX is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5058, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5060, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5067, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5068, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5069, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5071, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3239, Item 9019901, Project Item Line Number 5055, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with Materials.	weathc1	Overridden

Revision 4/1/2020 Page 8 of 27



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uanuues	and vail	ies are i	based on	Report Generated date and can differ from the posted ar	nount at the	e time tn	e Estimate i	was Ger	ierated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-C06	J4I3239	0020	0010	9019902	MISC.LABOR/EQUIPMENT FOR TROUBLE SHOOTING/INVESTIGATION/REPAIR WORK ADJUSTMENT FACTOR	720,000.00	0.00	720,000.00	EA	609,119.25	\$1.04	\$636,529.62
		0020	0020	9019902	MISC.MATERIAL FOR REPAIR WORK ADJUSTMENT FACTOR	432,000.00	0.00	432,000.00	EA	203,432.69	\$1.75	\$356,007.21
		0020	0030	9019902	MISC.TRAFFIC CONTROL ADJUSTMENT FACTOR	48,000.00	0.00	48,000.00	EA	46,175.00	\$3.25	\$150,068.75
		0020	5001	9019901	MISC.MISC. WORK ORDER NUMBER 2987438	0.00	1.00	1.00	LS	1.00	\$686.21	\$686.21
		0020	5002	9019901	MISC.MISC. WORK ORDER NUMBER 2992895	0.00	1.00	1.00	LS	1.00	\$832.54	\$832.54
		0020	5003	9019901	MISC.MISC. WORK ORDER NUMBER 2987439	0.00	1.00	1.00	LS	1.00	\$52.32	\$52.32
		0020	5004	9019901	MISC.MISC. WORK ORDER NUMBER 2992889	0.00	1.00	1.00	LS	1.00	\$1,374.44	\$1,374.44
		0020	5005	9019901	MISC.MISC. WORK ORDER NUMBER 2992988	0.00	1.00	1.00	LS	1.00	\$17.88	\$17.88
		0020	5006	9019901	MISC.MISC. WORK ORDER NUMBER 2993000	0.00	1.00	1.00	LS	1.00	\$190.62	\$190.62
		0020	5007	9019901	MISC.MISC. WORK ORDER NUMBER 3044858	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5008	9019901	MISC.MISC. WORK ORDER NUMBER 3050651	0.00	1.00	1.00	LS	1.00	\$431.40	\$431.40
		0020	5009	9019901	MISC.MISC. WORK ORDER NUMBER 2992985	0.00	1.00	1.00	LS	1.00	\$1,072.87	\$1,072.87
		0020	5010	9019901	MISC.MISC. WORK ORDER NUMBER 3020566	0.00	1.00	1.00	LS	1.00	\$13.20	\$13.20
		0020	5011	9019901	MISC.MISC. WORK ORDER NUMBER 2993015	0.00	1.00	1.00	LS	1.00	\$1,043.92	\$1,043.92
		0020	5012	9019901	MISC.MISC. WORK ORDER NUMBER 3052659	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
		0020	5013	9019901	MISC.MISC. WORK ORDER NUMBER 3107298	0.00	1.00	1.00	LS	1.00	\$1,587.19	\$1,587.19
		0020	5014	9019901	MISC.MISC. WORK ORDER NUMBER 3085642	0.00	1.00	1.00	LS	1.00	\$432.61	\$432.61
		0020	5015	9019901	MISC.MISC. WORK ORDER NUMBER 3107288	0.00	1.00	1.00	LS	1.00	\$260.50	\$260.50
		0020	5016	9019901	MISC.MISC. WORK ORDER NUMBER 3107323	0.00	1.00	1.00	LS	1.00	\$685.66	\$685.66
		0020	5017	9019901	MISC.MISC. WORK ORDER NUMBER 3107326	0.00	1.00	1.00	LS	1.00	\$190.87	\$190.87
		0020	5018	9019901	MISC.MISC. WORK ORDER NUMBER 3130075	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5019	9019901	MISC.MISC. WORK ORDER NUMBER 3130077	0.00	1.00	1.00	LS	1.00		\$1,064.71
		0020	5020	9019901	MISC.MISC. WORK ORDER NUMBER 2993014	0.00	1.00	1.00	LS	1.00	\$303.96	\$303.96
		0020	5021	9019901	MISC.MISC. WORK ORDER NUMBER 2993017	0.00	1.00	1.00	LS	1.00		\$1,336.20
		0020	5022	9019901	MISC.MISC. WORK ORDER NUMBER 3050652	0.00	1.00	1.00	LS	1.00	\$3,252.31	\$3,252.31
		0020	5023	9019901	MISC.MISC. WORK ORDER NUMBER 3081298	0.00	1.00	1.00	LS	1.00	\$205.62	\$205.62
		0020	5024	9019901	MISC.MISC. WORK ORDER NUMBER 3085436	0.00	1.00	1.00	LS	1.00	\$442.87	\$442.87
			5025	9019901	MISC.MISC. WORK ORDER NUMBER 3085458	0.00	1.00	1.00	LS		\$1,406.86	\$1,406.86
		0020	5026	9019901		0.00	1.00	1.00	LS	1.00	\$900.88	\$900.88
		0020	5026		MISC.MISC. WORK ORDER NUMBER 3107284	0.00	1.00	1.00	LS	1.00	\$618.00	\$618.00
		0020			MISC.MISC. WORK ORDER NUMBER 3107295  MISC.MISC. WORK ORDER NUMBER 3023831							\$2,089.56
		0020	5028			0.00	1.00	1.00	LS		\$2,089.56	
		0020	5029		MISC.MISC. WORK ORDER NUMBER 3130070	0.00	1.00	1.00	LS		\$2,523.84	\$2,523.84
		0020	5030	9019901	MISC.MISC. WORK ORDER NUMBER 3135995	0.00	1.00	1.00	LS	1.00	\$730.20	\$730.20
		0020	5031	9019901		0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
		0020	5032	9019901		0.00	1.00	1.00	LS		\$1,120.75	\$1,120.75
		0020	5033		MISC.MISC. WORK ORDER NUMBER 3158110	0.00	1.00	1.00	LS	1.00	\$560.38	\$560.38
		0020	5034	9019901		0.00	1.00	1.00	LS		\$1,285.02	\$1,285.02
		0020	5035		MISC.MISC. WORK ORDER NUMBER 3193508	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
		0020	5036	9019901		0.00	1.00	1.00	LS	1.00	\$361.02	\$361.02
		0020	5037		MISC.MISC. WORK ORDER NUMBER 3158121	0.00	1.00	1.00	LS		\$1,120.75	\$1,120.75
		0020	5038	9019901	MISC.MISC. WORK ORDER NUMBER 3193505	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5039	9019901	MISC.MISC. WORK ORDER NUMBER 3193506	0.00	1.00	1.00	LS	1.00	\$1,215.84	\$1,215.84
		0020	5040	9019901	MISC.MISC. WORK ORDER NUMBER 3227823	0.00	1.00	1.00	LS	1.00	\$2,508.74	\$2,508.74
		0020	5041	9019901	MISC.MISC. WORK ORDER NUMBER 3252353	0.00	1.00	1.00	LS	1.00	\$143.88	\$143.88

Revision 4/1/2020 Page 9 of 27



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00515-C06	J4I3239	0020	5042	9019901	MISC.MISC. WORK ORDER NUMBER 3252358	0.00	1.00	1.00	LS	1.00	\$379.32	\$379.32
		0020	5043	9019901	MISC.MISC. WORK ORDER NUMBER 3182841	0.00	1.00	1.00	LS	1.00	\$578.88	\$578.88
		0020	5044	9019901	MISC.MISC. WORK ORDER NUMBER 3218501	0.00	1.00	1.00	LS	1.00	\$2,517.60	\$2,517.60
		0020	5045	9019901	MISC.MISC. WORK ORDER NUMBER 3252366	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
		0020	5046	9019901	MISC.MISC. WORK ORDER NUMBER 3273946	0.00	1.00	1.00	LS	1.00	\$823.02	\$823.02
		0020	5047	9019901	MISC.MISC. WORK ORDER NUMBER 3273948	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
		0020	5048	9019901	MISC.MISC. WORK ORDER NUMBER 3280047	0.00	1.00	1.00	LS	1.00	\$652.94	\$652.94
		0020	5049	9019901	MISC.MISC. WORK ORDER NUMBER 3300194	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5050	9019901	MISC.MISC. WORK ORDER NUMBER 3300194	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.00
		0020	5051	9019901	MISC.MISC. WORK ORDER NUMBER 3218502	0.00	1.00	1.00	LS	1.00	\$2,590.18	\$2,590.18
		0020	5052	9019901	MISC.MISC. WORK ORDER NUMBER 3307381	0.00	1.00	1.00	LS	1.00	\$1,264.92	\$1,264.92
		0020	5053	9019901	MISC.MISC. WORK ORDER NUMBER 3334227	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.00
		0020	5054	9019901	MISC.MISC. WORK ORDER NUMBER 3357349	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.0
		0020	5055	9019901	MISC.MISC. WORK ORDER NUMBER 3357350	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.0
		0020	5056	9019901	MISC.MISC. WORK ORDER NUMBER 3365085	0.00	1.00	1.00	LS	1.00	\$456.00	\$456.0
		0020	5057	9019901	MISC.MISC. WORK ORDER NUMBER 3273944	0.00	1.00	1.00	LS	1.00	\$474.00	\$474.0
		0020	5058	9019901	MISC.MISC. WORK ORDER NUMBER 3365087	0.00	1.00	1.00	LS	1.00	\$571.68	\$571.6
		0020	5059	9019901	MISC.MISC. WORK ORDER NUMBER 3365092	0.00	1.00	1.00	LS	1.00	\$1,126.32	\$1,126.3
		0020	5060	9019901	MISC.MISC. WORK ORDER NUMBER 3372013	0.00	1.00	1.00	LS	1.00	\$1,452.46	\$1,452.4
		0020	5061	9019901	MISC.MISC. WORK ORDER NUMBER 3372016	0.00	1.00	1.00	LS	1.00	\$750.91	\$750.9
		0020	5062	9019901	MISC.MISC. WORK ORDER NUMBER 3373553	0.00	1.00	1.00	LS	1.00	\$685.66	\$685.6
		0020	5063	9019901	MISC.MISC. WORK ORDER NUMBER 3392019	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.0
		0020	5064	9019901	MISC.MISC. WORK ORDER NUMBER 3402437	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.0
		0020	5065	9019901	MISC.MISC. WORK ORDER NUMBER 3402441	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.0
		0020	5066	9019901	MISC.MISC. WORK ORDER NUMBER 3402443	0.00	1.00	1.00	LS	1.00	\$924.00	\$924.0
		0020	5067	9019901	MISC.MISC. WORK ORDER NUMBER 3402447	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.0
		0020	5068	9019901	MISC.MISC. WORK ORDER NUMBER 3402451	0.00	1.00	1.00	LS	1.00	\$319.10	\$319.1
		0020	5069	9019901	MISC.MISC. WORK ORDER NUMBER 3420396	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.0
		0020	5070	9019901	MISC.MISC. WORK ORDER NUMBER 3428785	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.0
		0020	5071	9019901	MISC.MISC. WORK ORDER NUMBER 3431481	0.00	1.00	1.00	LS	1.00	\$462.00	\$462.0
		0020	9000	6189916	MISC.Liquidated Damages	0.00			DLR	0.00	(\$1.00)	\$0.0
		0020	9100	6189916	MISC.Additional Items	0.00			DLR	0.00	\$1.00	\$0.00
		0020	9200	6189902	MISC.High Priority Repair	0.00			EA	0.00	\$2,400.00	\$0.00
	Project J	413239 - To	tal Value	Posted to	Date as of Report Generated Date							\$1,202,710.18

Revision 4/1/2020 Page 10 of 27



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J4l3239

ne nber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
010	9019902	MISC. HIGHWAY LIGHTING	5/26/22	6/1/22	225.00	EA	SB I-29 before Bond Bridge					76-1301867, WO3532544
				6/1/22	450.00	EA	I-470 EB at Exit 2					76-1301850, WO3550761
				6/1/22	675.00	EA	71 Highway SB at Red Bridge Exit					76-1301872, WO3562024
				6/1/22	675.00	EA	Broadway Bridge					76-1301868, WO3536035
				6/1/22	675.00	EA	I-35 SB at 7.8MM					76-1301851, WO3562021
				6/1/22	675.00	EA	I-435 NB from Front St.					76-1301862, WO3516532
				6/1/22	900.00	EA	I-70 WB 3.22 MM to Harrison					76-1301860, WO3516529
				6/1/22	1,125.00	EA	I-35 SB at Exit 3					76-1301871, WO3562020
				6/1/22	1,350.00	EA	71 Highway SB & Bannister					76-1301864, WO3516534
				6/1/22	1,687.50	EA	SB 71 Highway before 22 St.					76-1301845, WO3516897
				6/1/22	1,800.00	EA	I-35 NB & Front St.					76-1301863, WO3516533
				6/1/22	1,912.50	EA	I-70 EB at the Admiral Ramp					76-1201861, WO3516530
				6/1/22	2,025.00	EA	I-435 SB to I-70 WB					76-1301873, WO3566087
				6/1/22	2,137.50	EA	SB I-435 & 40 Highway					76-1301843, WO3516535
				6/1/22	2,250.00	EA	50 Highway btw Jefferson & 3 St.					76-1301844, WO3516537
				6/1/22	2,250.00	EA	I-435 & Front St.					76-1301849, WO3550750
				6/1/22	2,365.00	EA	I-70 & 23 St.					76-1301841, WO3373925
				6/1/22	2,925.00	EA	SB 71 Highway & 59 St.					76-1301846, WO3516898
				6/1/22	3,151.00	EA	I-70 & 27th St.					76-1301840, WO3373556
				6/1/22	3,600.00	EA	I-35 SB transition to 71 Highway					76-1301852, WO3562023
				6/1/22	3,716.50	EA	NB 435 at Front St. Off Ramp					76-1301859, WO3482665
				6/1/22	4,050.00	EA	I-435 EB & I-470 EB					76-1301870, WO3550752
				6/1/22	4,166.50	EA	NB 71 Highway & 63 St.					76-120866, WO3532543
				6/1/22	4,837.50	EA	I-435 & 87th Street Ramp					76-1301838, WO3211562
				6/1/22	7,321.50	EA	I-29 NW of I-35 / I-29 Split					76-1301842, WO3402500
				6/1/22	24,087.00	EA	I-29 SB by 169 Highway					76-1301875, WO3268621
20	9019902	MISC. HIGHWAY LIGHTING	5/26/22	6/1/22	29.40	EA	I-435 & Front St.					76-1301849, WO3550750
				6/1/22	375.76	EA	I-35 SB at 7.8MM					76-1301851, WO3562021
				6/1/22	751.52	EA	NB 435 at Front St. Off Ramp					76-1301859, WO3482665
				6/1/22	754.76	EA	I-35 NB & Front St.					76-1301863, WO3516533
				6/1/22	1,127.28	EA	I-435 NB from Front St.					76-1301862, WO3516532
				6/1/22	1,503.04	EA	I-35 SB at Exit 3					76-1301867, WO3532544
				6/1/22	1,503.04	EA	I-70 EB at the Admiral Ramp					76-1201861, WO3516530
				6/1/22	1,658.76	EA	I-29 SB by 169 Highway					76-1301875, WO3268621
				6/1/22	1,878.80	EA	I-70 & 27th St.					76-1301840, WO3373556
				6/1/22	2,254.56	EA	I-29 NW of I-35 / I-29 Split					76-1301842, WO3402500
				6/1/22	2,254.56	EA	I-35 SB transition to 71 Highway					76-1301852, WO3562023
				6/1/22	2,254.56	EA	I-70 & 23 St.					76-1301841, WO3373925
				6/1/22	2,254.56	EA	SB 71 Highway & 59 St.					76-1301846, WO3516898
				6/1/22	2,400.00	EA	SB I-435 & 40 Highway					76-1301843, WO3516535
				6/1/22	2,630.32	EA	71 Highway SB & Bannister					76-1301864, WO3516534
				6/1/22	2,630.32		NB 71 Highway & 63 St.					76-120866, WO3532543
30	9019902	MISC. HIGHWAY LIGHTING	5/26/22	6/1/22	250.00		71 Highway SB & Bannister					76-1301864, WO3516534
				6/1/22	250.00		I-35 SB at 7.8MM					76-1301851, WO3562021
				6/1/22	250.00		I-35 SB at Exit 3					76-1301867, WO3532544
				6/1/22	250.00		I-35 SB transition to 71 Highway					76-1301852, WO3562023
				6/1/22	250.00		I-435 & Front St.					76-1301849, WO3550750
				6/1/22	250.00		NB 71 Highway & 63 St.					76-120866, WO3532543
				6/1/22	500.00		SB I-29 before Bond Bridge					76-1301867, WO3532544
				6/1/22	700.00		I-35 NB & Front St.					76-1301863, WO35352544 76-1301863, WO3516533

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 11 of 27



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
413239	5001	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$686.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					29	Apr 15, 2022	SYSTEM	(\$686.21)	
					30	May 2, 2022	SYSTEM	\$686.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$686.21)	
					31	Jun 1, 2022	SYSTEM	\$686.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$686.21)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	5001 -	- Total						\$0.00	
	5002	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$832.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					29	Apr 15, 2022	SYSTEM	(\$832.54)	
					30	May 2, 2022	SYSTEM	\$832.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$832.54)	
					31	Jun 1, 2022	SYSTEM	\$832.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$832.54)	
				- Total	31		SYSTEM	(\$832.54) \$0.00	
			Material - To		31		SYSTEM	` '	
	5002 -	- Total	Material - T		31		SYSTEM	\$0.00	
	<b>5002</b> - 5003	- Total MISC. HIGHWAY LIGHTING	Material - To		29		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		MISC. HIGHWAY				2022 Apr 15,		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0009) due to user weathc1 overridding Payment
		MISC. HIGHWAY			29	Apr 15, 2022  Apr 15,	SYSTEM	\$0.00 \$0.00 \$0.00 \$52.32	Estimate Item Adjustment (0009) due to user weathc1 overridding Payment
		MISC. HIGHWAY			29	Apr 15, 2022  Apr 15, 2022  May 2,	SYSTEM	\$0.00 \$0.00 \$0.00 \$52.32 (\$52.32)	Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment
		MISC. HIGHWAY			29 29 30	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 4022	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$52.32 (\$52.32) \$52.32	Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment
		MISC. HIGHWAY			29 29 30 30	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 2022  Jun 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$52.32 (\$52.32) \$52.32	Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment
		MISC. HIGHWAY			29 29 30 30 31	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 2022  Jun 1, 2022  Jun 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$52.32 (\$52.32) \$52.32 (\$52.32)	Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment
		MISC. HIGHWAY		otal - Total	29 29 30 30 31	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 2022  Jun 1, 2022  Jun 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$52.32 (\$52.32) \$52.32 (\$52.32)	Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment
	5003	MISC. HIGHWAY	Material	otal - Total	29 29 30 30 31	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 2022  Jun 1, 2022  Jun 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$52.32 (\$52.32) \$52.32 (\$52.32) \$52.32 (\$52.32)	Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment
	5003	MISC. HIGHWAY LIGHTING	Material	otal - Total	29 29 30 30 31	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 2022  Jun 1, 2022  Jun 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$52.32 (\$52.32) \$52.32 (\$52.32) \$52.32 (\$52.32) \$0.00	Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment
	5003	MISC. HIGHWAY LIGHTING  Total MISC. HIGHWAY	Material - T	otal - Total	29 29 30 30 31 31	Apr 15, 2022  Apr 15, 2022  May 2, 2022  Jun 1, 2022  Jun 1, 2022  Apr 15,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$52.32 (\$52.32) \$52.32 (\$52.32) \$52.32 (\$52.32) \$0.00 \$0.00	Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J4I3239	5004	MISC. HIGHWAY	Material			2022			Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.											
		LIGHTING			30	May 2, 2022	SYSTEM	(\$1,374.44)												
					31	Jun 1, 2022	SYSTEM	\$1,374.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.											
					31	Jun 1, 2022	SYSTEM	(\$1,374.44)												
				- Total				\$0.00												
			Material - T	otal				\$0.00												
	5004 -	- Total						\$0.00												
	5005	005 MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$17.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					29	Apr 15, 2022	SYSTEM	(\$17.88)												
				30	May 2, 2022	SYSTEM	\$17.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
						30	May 2, 2022	SYSTEM	(\$17.88)											
																31	Jun 1, 2022	SYSTEM	\$17.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$17.88)												
				- Total				\$0.00												
			Material - T	otal				\$0.00												
	5005 -	- Total						\$0.00												
	5005 - 5006	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	<b>\$0.00</b> \$190.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
		MISC. HIGHWAY	Material		29		SYSTEM SYSTEM		Estimate Item Adjustment (0010) due to user weathc1 overridding Payment											
		MISC. HIGHWAY	Material			2022 Apr 15,		\$190.62	Estimate Item Adjustment (0010) due to user weathc1 overridding Payment											
		MISC. HIGHWAY	Material		29	2022 Apr 15, 2022 May 2,	SYSTEM	\$190.62 (\$190.62)	Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment											
		MISC. HIGHWAY	Material		29	2022  Apr 15, 2022  May 2, 2022  May 2,	SYSTEM	\$190.62 (\$190.62) \$190.62	Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment											
		MISC. HIGHWAY	Material		29 30 30	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1,	SYSTEM SYSTEM	\$190.62 (\$190.62) \$190.62	Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment											
		MISC. HIGHWAY	Material	- Total	29 30 30 31	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022 Jun 1, 1,	SYSTEM SYSTEM SYSTEM	\$190.62 (\$190.62) \$190.62 (\$190.62)	Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment											
		MISC. HIGHWAY	Material - To		29 30 30 31	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022 Jun 1, 1,	SYSTEM SYSTEM SYSTEM	\$190.62 (\$190.62) \$190.62 (\$190.62) \$190.62	Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment											
	5006	MISC. HIGHWAY			29 30 30 31	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022 Jun 1, 1,	SYSTEM SYSTEM SYSTEM	\$190.62 (\$190.62) \$190.62 (\$190.62) \$190.62 (\$190.62)	Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment											
	5006	MISC. HIGHWAY LIGHTING			29 30 30 31	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022 Jun 1, 1,	SYSTEM SYSTEM SYSTEM	\$190.62 (\$190.62) \$190.62 (\$190.62) \$190.62 (\$190.62) \$0.00	Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment											
	5006	MISC. HIGHWAY LIGHTING  Total MISC. HIGHWAY	Material - T		29 30 30 31 31	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022  Apr 15,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$190.62 (\$190.62) \$190.62 (\$190.62) \$190.62 (\$190.62) \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment											
	5006	MISC. HIGHWAY LIGHTING  Total MISC. HIGHWAY	Material - T		29 30 30 31 31	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022 Jun 1, 2022 Apr 15, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$190.62 (\$190.62) \$190.62 (\$190.62) \$190.62 (\$190.62) \$0.00 \$0.00 \$462.00	Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment											
	5006	MISC. HIGHWAY LIGHTING  Total MISC. HIGHWAY	Material - T		29 30 30 31 31 29	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022 Jun 1, 2022 Apr 15, 2022 Apr 45, 2022 May 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$190.62 (\$190.62) \$190.62 (\$190.62) \$190.62 (\$190.62) \$0.00 \$0.00 \$462.00	Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																						
J4I3239	5007	MISC.	Material	Турс					Estimate Exception 7 on the current Payment Estimate.																						
		HIGHWAY LIGHTING			31	Jun 1, 2022	SYSTEM	(\$462.00)																							
				- Total				\$0.00																							
			Material - To	otal				\$0.00																							
	5007 -	Total						\$0.00																							
	5008	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$431.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																						
					29	Apr 15, 2022	SYSTEM	(\$431.40)																							
					30	May 2, 2022	SYSTEM	\$431.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																						
					30	May 2, 2022	SYSTEM	(\$431.40)																							
					31	Jun 1, 2022	SYSTEM	\$431.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																						
					31	Jun 1, 2022	SYSTEM	(\$431.40)																							
				- Total				\$0.00																							
			Material - To	otal				\$0.00																							
	5008 -	Total						\$0.00																							
	5009	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$1,072.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.																						
					29	Apr 15, 2022	SYSTEM	(\$1,072.87)																							
						30	May 2, 2022	SYSTEM	\$1,072.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.																					
							30	May 2, 2022	SYSTEM	(\$1,072.87)																					
														31	Jun 1, 2022	SYSTEM	\$1,072.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.													
					31	Jun 1, 2022	SYSTEM	(\$1,072.87)																							
				- Total				\$0.00																							
			Material - To	otal				\$0.00																							
	5009 -	Total						\$0.00																							
	5010	MISC. HIGHWAY LIGHTING	Material	Material	Material	Material	Material	Material	Material	Material		29	Apr 15, 2022	SYSTEM	\$13.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.															
						29	Apr 15, 2022	SYSTEM	(\$13.20)																						
																													30	May 2, 2022	SYSTEM
				30 May 2, SYSTE 2022		SYSTEM	(\$13.20)																								
					31	Jun 1, 2022	SYSTEM	\$13.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																						
					31	Jun 1, 2022	SYSTEM	(\$13.20)																							
				- Total				\$0.00																							
			Material - To	otal				\$0.00																							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
413239	5010 -	Total						\$0.00	
	5011	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,043.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user weathc1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$1,043.92)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5011 -	Total						\$0.00	
	5012	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$924.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5012 -	Total						\$0.00	
	5013	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,587.19	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
	5013 - Total	LIGITING			28	Apr 1, 2022	SYSTEM	(\$1,587.19)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5013 -	Total						\$0.00	
	5014	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$432.61	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user weathc1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$432.61)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5014 -	Total						\$0.00	
	5015	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$260.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weatho1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$260.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5015 -							\$0.00	
	5016	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$685.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$685.66)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5016 -	Total						\$0.00	
	5017	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$190.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user weathc1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$190.87)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3239	5017 -	Total						\$0.00	
	5018	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$462.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5018 -	Total						\$0.00	
	5019	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,064.71	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$1,064.71)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5019 -	Total						\$0.00	
	5020	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$303.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user weathc1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$303.96)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5020 -	Total						\$0.00	
	5021	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
		LIGITING			28	Apr 1, 2022	SYSTEM	(\$1,336.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5021 -	Total						\$0.00	
	5022	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$3,252.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$3,252.31)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5022 -	Total						\$0.00	
	5023	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$205.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$205.62)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5023 -	Total						\$0.00	
	5024	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$442.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$442.87)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3239	5024 -	Total						\$0.00	
	5025	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,406.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$1,406.86)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5025 -	Total						\$0.00	
	5026	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$900.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$900.88)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5026 -	Total						\$0.00	
	5027	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$618.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user weathc1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$618.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5027 -	Total						\$0.00	
	5028	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$2,089.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user weathc1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
		LIGITING			28	Apr 1, 2022	SYSTEM	(\$2,089.56)	
				- Total				\$0.00	
			Material - To	Material - Total				\$0.00	
	5028 -	Total						\$0.00	
	5029	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$2,523.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$2,523.84)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5029 -	Total						\$0.00	
	5030	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$730.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$730.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5030 -	Total						\$0.00	
	5031	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user weathof overridding Payment Estimate Exception 16 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$924.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	



		Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
13239 5	5031 -	Total						\$0.00	
5	5032	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,120.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$1,120.75)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
5	5032 -	Total						\$0.00	
5	5033	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$560.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$560.38)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
5	5033 -	Total						\$0.00	
5	5034	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,285.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$1,285.02)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
5	5034 -	Total						\$0.00	
5	5035	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$924.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
5	5035 -	Total						\$0.00	
5	5036	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$361.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user weathc1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$361.02)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
5	5036 -	Total						\$0.00	
5	5037	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,120.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user weathc1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$1,120.75)	
				- Total				\$0.00	
_			Material - To	otal				\$0.00	
5	5037 -	Total						\$0.00	
5	5038	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$462.00)	
				- Total				\$0.00	
								\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3239	5038 -	Total						\$0.00	
	5039	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$1,215.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$1,215.84)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5039 -	Total						\$0.00	
	5040	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$2,508.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user weatho1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$2,508.74)	
				- Total				\$0.00	
			Material - To	Material - Total					
	5040 -	Total						\$0.00	
	5041	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$143.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$143.88)	
								\$0.00	
			Material - To	otal				\$0.00	
	5041 -	Total						\$0.00	
	5042	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$379.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user weathc1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$379.32)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5042 -	Total						\$0.00	
	5043	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$578.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathof overridding Payment Estimate Exception 6 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$578.88)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5043 -	Total						\$0.00	
	5044	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$2,517.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$2,517.60)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5044 -	Total						\$0.00	
	5045	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					28	Apr 1, 2022	SYSTEM	(\$924.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4I3239	5045 -	Total						\$0.00													
	5046	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$823.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 29 on the current Payment Estimate.												
					28	Apr 1, 2022	SYSTEM	(\$823.02)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	5046 -	Total						\$0.00													
	5047	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 12 on the current Payment Estimate.												
					28	Apr 1, 2022	SYSTEM	(\$924.00)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	5047 -	Total						\$0.00													
	5048	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$652.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Exception 30 on the current Payment Estimate.												
					28	Apr 1, 2022	SYSTEM	(\$652.94)													
								\$0.00													
			Material - To	otal				\$0.00													
	5048 -	Total						\$0.00													
	5049	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 21 on the current Payment Estimate.												
					28	Apr 1, 2022	SYSTEM	(\$462.00)													
				- Total		\$0.00															
			Material - To	aterial - Total				\$0.00													
	5049 -	Total						\$0.00													
	5050	MISC. HIGHWAY LIGHTING	Material		28	Apr 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 22 on the current Payment Estimate.												
					28	Apr 1, 2022	SYSTEM	(\$924.00)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	5050 -	Total						\$0.00													
	5051	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$2,590.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.												
					29	Apr 15, 2022	SYSTEM	(\$2,590.18)													
																	30	May 2, 2022	SYSTEM	\$2,590.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$2,590.18)													
					31	Jun 1, 2022	SYSTEM	\$2,590.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user weathc1 overridding Payment Estimate Exception 18 on the current Payment Estimate.												
					31	Jun 1, 2022	SYSTEM	(\$2,590.18)													
				- Total				\$0.00													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3239	5051	MISC. HIGHWAY LIGHTING	Material - To	otal				\$0.00	
	5051 -	Total						\$0.00	
	5052	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$1,264.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					29	Apr 15, 2022	SYSTEM	(\$1,264.92)	
					30	May 2, 2022	SYSTEM	\$1,264.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$1,264.92)	
					31	Jun 1, 2022	SYSTEM	\$1,264.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user weathc1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$1,264.92)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5052 -	Total						\$0.00	
	5053	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					29	Apr 15, 2022	SYSTEM	(\$462.00)	
					30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weatho1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$462.00)	
					31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$462.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5053 -	Total						\$0.00	
	5054	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weatho1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					29	Apr 15, 2022	SYSTEM	(\$462.00)	
					30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weatho1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$462.00)	
					31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weatho1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$462.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5054 -	Total						\$0.00	
	5055	MISC. HIGHWAY	Material		29	Apr 15, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
13239	5055	LIGHTING	Material						Estimate Exception 31 on the current Payment Estimate.		
					29	Apr 15, 2022	SYSTEM	(\$924.00)			
					30	May 2, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 31 on the current Payment Estimate.		
					30	May 2, 2022	SYSTEM	(\$924.00)			
					31	Jun 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user weathc1 overridding Payment Estimate Exception 31 on the current Payment Estimate.		
					31	Jun 1, 2022	SYSTEM	(\$924.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	5055 -	Total						\$0.00			
	5056	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$456.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 24 on the current Payment Estimate.		
					29	Apr 15, 2022	SYSTEM	(\$456.00)			
					30	May 2, 2022	SYSTEM	\$456.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 24 on the current Payment Estimate.		
							30	May 2, 2022	SYSTEM	(\$456.00)	
						31	Jun 1, 2022	SYSTEM	\$456.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user weathc1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	
					31	Jun 1, 2022	SYSTEM	(\$456.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	5056 -	Total						\$0.00			
	5057	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$474.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.		
					29	Apr 15, 2022	SYSTEM	(\$474.00)			
					30	May 2, 2022	SYSTEM	\$474.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.		
							30	May 2, 2022	SYSTEM	(\$474.00)	
					31	Jun 1, 2022	SYSTEM	\$474.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 20 on the current Payment Estimate.		
					31	Jun 1, 2022	SYSTEM	(\$474.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	5057 -	Total						\$0.00			
	5058	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$571.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user weathc1 overridding Payment Estimate Exception 25 on the current Payment Estimate.		
					29	Apr 15, 2022	SYSTEM	(\$571.68)			
					30	May 2,	SYSTEM	\$571.68	This adjustment offsets the original system-generated Material Payment		



14-14-15-  1	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
31   Jun 1, SYSTEM   SST-168   This adjustment offises the original system-generated Material Psyment Calmate.	J4I3239	5058	HIGHWAY	Material		30		SYSTEM	(\$571.68)									
Total			LIGHTING			31		SYSTEM	\$571.68	Estimate Item Adjustment (0025) due to user weathc1 overridding Payment								
						31		SYSTEM	(\$571.68)									
Soss - Total					- Total				\$0.00									
Michael   Company   Comp				Material - To	otal				\$0.00									
		5058 -	·Total						\$0.00									
2022   30   May 2,   2022   31   Jun 1,   3   3   30   30   30   30   30   30		5059	HIGHWAY	Material		29		SYSTEM	\$1,126.32	Estimate Item Adjustment (0012) due to user weathc1 overridding Payment								
2022   SYSTEM   St.1,26.32   This adjustment (OT2) due to user wealthof overnidding Payment Estimate Exception 12 on the current Payment Estimate Payment Estimate Exception 12 on the current Payment Estimate Payment Estimate Payment Estimate Payment Estimate Payment P						29		SYSTEM	(\$1,126.32)									
2022   31						30		SYSTEM	\$1,126.32	Estimate Item Adjustment (0012) due to user weathc1 overridding Payment								
2022   Estimate Exception 12 on the current Payment Estimate.						30		SYSTEM	(\$1,126.32)									
Sobject   Sobj										31		SYSTEM	\$1,126.32	Estimate Item Adjustment (0012) due to user weathc1 overridding Payment				
S059 - Total					31		SYSTEM	(\$1,126.32)										
				- Total				\$0.00										
Misc. Highway Lightness   Material   Mater				Material - To	otal				\$0.00									
HighWay LightInns		5059 -	Total						\$0.00									
2022   30 May 2, 2022   37 SYSTEM   \$1,452.46   2022   2		5060	HIGHWAY	Material		29		SYSTEM	\$1,452.46	Estimate Item Adjustment (0026) due to user weathc1 overridding Payment								
Substitute   Lestimate   Les						29		SYSTEM	(\$1,452.46)									
2022						30		SYSTEM	\$1,452.46	Estimate Item Adjustment (0026) due to user weathc1 overridding Payment								
Estimate Item Adjustment (0026) due to user weathc1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  31 Jun 1, 2022  **Total***  **S0.00  **Material - Total**  **S0.00  **S060 - Total**  **S0.00  **Material - Total**  **S0.00  **S060 - Total**  **S0.00  **S060 - Total**  **S0.00  **S060 - Total**  **S0.00  **Material - Total**  **S0.00  **Soft IGHTING**  **Misc. HIGHWAY LIGHTING**  **Apr 15, 2022  **SYSTEM**  **S750.91  **SYSTEM**  **S750.91  **SYSTEM**  **S750.91  **SYSTEM**  **S750.91  **This adjustment offsets the original system-generated Material Payment Estimate.*  **Sufficiency of the current Payment Estimate.*  **Sufficiency of the current Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  **SySTEM**  **SUSTEM**  **S												30		SYSTEM	(\$1,452.46)			
Source   S										31		SYSTEM	\$1,452.46	Estimate Item Adjustment (0026) due to user weathc1 overridding Payment				
Social   S						31		SYSTEM	, , ,									
\$0.00    MISC HIGHWAY LIGHTING   Material   29   Apr 15, 2022   2																		
Misc. Highway Lighting   Material   29   Apr 15, 2022   SYSTEM   \$750.91   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathout overridding Payment Estimate Exception 13 on the current Payment Estimate.				Material - To	otal													
HIGHWAY LIGHTING  29 Apr 15, 2022  30 May 2, 2022  30 May 2, 2022  30 May 2, 2022  30 May 2, 2022  30 May 3, 2022  30 May 4, 2022  30 May 5, 2022  30 May 5, 2022  30 May 6, 2022  30 May 1, 2022  30 May 2, 2022  30 May 3, 2022  30 May 4, 2022  30 May 5, 2022  30 May 6, 2022  30 May 6, 2022  30 May 1, 2022  30 May 2, 2022  30 May 2, 2022  31 Jun 1, 2022  31 Jun 1, 2022  32 Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.				Maria		00	A 45	0)/0751										
2022  30 May 2, 2022  \$750.91 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  30 May 2, 2022  31 Jun 1, 2022  \$750.91 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		5061	HIGHWAY	Material			2022			Estimate Item Adjustment (0013) due to user weathc1 overridding Payment								
Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  30 May 2, 2022  31 Jun 1, 2022  SYSTEM \$750.91  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								2022		, ,								
2022  31 Jun 1, 2022  \$750.91 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.															2022			Estimate Item Adjustment (0013) due to user weathc1 overridding Payment
Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.					30		SYSTEM	(\$750.91)										
31 Jun 1, SYSTEM (\$750.91)						31		SYSTEM	\$750.91	Estimate Item Adjustment (0013) due to user weathc1 overridding Payment								
						31	Jun 1,	SYSTEM	(\$750.91)									



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
13239	5061	MISC.	Material			2022												
		HIGHWAY LIGHTING		- Total				\$0.00										
			Material - To	otal				\$0.00										
	5061 -	Total						\$0.00										
	5062	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$685.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.									
					29	Apr 15, 2022	SYSTEM	(\$685.66)										
					30	May 2, 2022	SYSTEM	\$685.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.									
						30	May 2, 2022	SYSTEM	(\$685.66)									
					31	Jun 1, 2022	SYSTEM	\$685.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 14 on the current Payment Estimate.									
					31	Jun 1, 2022	SYSTEM	(\$685.66)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	5062 -	Total						\$0.00										
	5063	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 21 on the current Payment Estimate.									
							29	Apr 15, 2022	SYSTEM	(\$462.00)								
						30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 21 on the current Payment Estimate.								
														30	May 2, 2022	SYSTEM	(\$462.00)	
					31	Jun 1, 2022	SYSTEM	(\$462.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	5063 -	Total						\$0.00										
	5064	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 15 on the current Payment Estimate.									
					29	Apr 15, 2022	SYSTEM	(\$462.00)										
					30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 15 on the current Payment Estimate.									
								30	May 2, 2022	SYSTEM	(\$462.00)							
				31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 15 on the current Payment Estimate.										
				31	Jun 1, 2022	SYSTEM	(\$462.00)											
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	5064 -	Total						\$0.00										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
413239	5065	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					29	Apr 15, 2022	SYSTEM	(\$462.00)	
					30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$462.00)	
					31	Jun 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user weathc1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$462.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	5065 -	- Total						\$0.00	
	5066	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					29	Apr 15, 2022	SYSTEM	(\$924.00)	
					30	May 2, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					30	May 2, 2022	SYSTEM	(\$924.00)	
					31	Jun 1, 2022	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user weathc1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					31	Jun 1, 2022	SYSTEM	(\$924.00)	
				- Total	31		SYSTEM	(\$924.00) \$0.00	
			Material - To		31		SYSTEM	` '	
	5066 -	- Total	Material - T		31		SYSTEM	\$0.00	
	<b>5066</b> - 5067	- Total MISC. HIGHWAY LIGHTING	Material - To		29		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weatho1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
		MISC. HIGHWAY				2022 Apr 15,		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0027) due to user weathc1 overridding Payment
		MISC. HIGHWAY			29	Apr 15, 2022  Apr 15,	SYSTEM	\$0.00 \$0.00 \$0.00 \$462.00	Estimate Item Adjustment (0027) due to user weathc1 overridding Payment
		MISC. HIGHWAY			29	Apr 15, 2022  Apr 15, 2022  May 2,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$462.00	Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment
		MISC. HIGHWAY			29 29 30	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 2022	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$462.00 (\$462.00)	Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment
		MISC. HIGHWAY			29 29 30 30	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 2022  Jun 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$462.00 (\$462.00) \$462.00	Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment
		MISC. HIGHWAY			29 29 30 30 31	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 2022  Jun 1, 2022  Jun 1, 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$462.00 (\$462.00) \$462.00 (\$462.00)	Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment
		MISC. HIGHWAY		otal - Total	29 29 30 30 31	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 2022  Jun 1, 2022  Jun 1, 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$462.00 (\$462.00) \$462.00 (\$462.00)	Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment
	5067	MISC. HIGHWAY	Material	otal - Total	29 29 30 30 31	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 2022  Jun 1, 2022  Jun 1, 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$462.00 (\$462.00) \$462.00 (\$462.00) \$462.00	Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment
	5067	MISC. HIGHWAY LIGHTING	Material	otal - Total	29 29 30 30 31	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 2022  Jun 1, 2022  Jun 1, 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$462.00 (\$462.00) \$462.00 (\$462.00) \$462.00 \$0.00	Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment
	5067 -	MISC. HIGHWAY LIGHTING  Total MISC. HIGHWAY	Material - T	otal - Total	29 29 30 30 31 31	Apr 15, 2022  Apr 15, 2022  May 2, 2022  May 2, 2022  Jun 1, 2022  Jun 1, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$462.00 (\$462.00) \$462.00 (\$462.00) \$0.00 \$0.00	Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user weathc1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 27 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J4I3239	5068	MISC. HIGHWAY	Material			2022			Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 28 on the current Payment Estimate.		
		LIGHTING			30	May 2, 2022	SYSTEM	(\$319.10)			
					31	Jun 1, 2022	SYSTEM	\$319.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user weathc1 overridding Payment Estimate Exception 28 on the current Payment Estimate.		
					31	Jun 1, 2022	SYSTEM	(\$319.10)			
				- Total				\$0.00			
			Material - T	otal				\$0.00			
	5068 -	- Total						\$0.00			
	5069	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 29 on the current Payment Estimate.		
					29	Apr 15, 2022	SYSTEM	(\$462.00)			
					30	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user weathc1 overridding Payment Estimate Exception 29 on the current Payment Estimate.		
						30	May 2, 2022	SYSTEM	(\$462.00)		
									31	Jun 1, 2022	SYSTEM
					31	Jun 1, 2022	SYSTEM	(\$462.00)			
				- Total				\$0.00			
			Material - T	otal				\$0.00			
	5069 -	- Total						\$0.00			
	5069 - 5070	MISC. HIGHWAY LIGHTING	Material		29	Apr 15, 2022	SYSTEM	<b>\$0.00</b> \$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.		
		MISC. HIGHWAY	Material		29		SYSTEM SYSTEM		Estimate Item Adjustment (0017) due to user weathc1 overridding Payment		
		MISC. HIGHWAY	Material			2022 Apr 15,		\$462.00	Estimate Item Adjustment (0017) due to user weathc1 overridding Payment		
		MISC. HIGHWAY	Material		29	2022 Apr 15, 2022 May 2,	SYSTEM	\$462.00 (\$462.00)	Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment		
		MISC. HIGHWAY	Material		29	2022  Apr 15, 2022  May 2, 2022  May 2,	SYSTEM SYSTEM	\$462.00 (\$462.00) \$462.00	Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment		
		MISC. HIGHWAY	Material		29 30 30	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1,	SYSTEM SYSTEM	\$462.00 (\$462.00) \$462.00 (\$462.00)	Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment		
		MISC. HIGHWAY	Material	- Total	29 30 30 31	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022 Jun 1, 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$462.00 (\$462.00) \$462.00 (\$462.00) \$462.00	Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment		
		MISC. HIGHWAY	Material - To		29 30 30 31	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022 Jun 1, 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$462.00 (\$462.00) \$462.00 (\$462.00) \$462.00	Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment		
	5070	MISC. HIGHWAY			29 30 30 31	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022 Jun 1, 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$462.00 (\$462.00) \$462.00 (\$462.00) \$462.00 (\$462.00)	Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment		
	5070	MISC. HIGHWAY LIGHTING			29 30 30 31	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022 Jun 1, 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$462.00 (\$462.00) \$462.00 (\$462.00) \$462.00 (\$462.00) \$0.00	Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment		
	5070	MISC. HIGHWAY LIGHTING  Total MISC. HIGHWAY	Material - T		29 30 30 31 31	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022  Apr 15,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$462.00 (\$462.00) \$462.00 (\$462.00) \$462.00 (\$462.00) \$0.00 \$0.00	Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment		
	5070	MISC. HIGHWAY LIGHTING  Total MISC. HIGHWAY	Material - T		29 30 30 31 31	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022 Jun 1, 2022 Apr 15, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$462.00 (\$462.00) \$462.00 (\$462.00) \$462.00 (\$462.00) \$0.00 \$0.00 \$462.00	Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment		
	5070	MISC. HIGHWAY LIGHTING  Total MISC. HIGHWAY	Material - T		29 30 30 31 31 29	2022 Apr 15, 2022 May 2, 2022 May 2, 2022 Jun 1, 2022 Jun 1, 2022 Apr 15, 2022 May 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$462.00  (\$462.00)  \$462.00  (\$462.00)  \$462.00  (\$462.00)  \$0.00  \$0.00  \$462.00  (\$462.00)	Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment Estimate Item Adjustment (0030) due to user weathc1 overridding Payment		

Jun 7, 2022



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3239	5071	MISC.	Material						Estimate Exception 30 on the current Payment Estimate.
		HIGHWAY LIGHTING			31	Jun 1, 2022	SYSTEM	(\$462.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5071 -	Total						\$0.00	
J4I3239 -	Total							\$0.00	
Overall -	Total							\$0.00	