

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2021

Progress Estima	ate Number	Contract ID Prime Contractor	200515-D01 Meyer Electric Com				Original Contract Amou Net Change Order Amou Current Contract Amou	int \$500.00	
Approval Date								By User	r
June 16, 2021			Generated and Ap	pproved (an	d should be consi	dered Draft) at th	ne Project Office Level by	sto	tokez1
June 21, 2021		R	eviewed and Approv	ed (and sho	uld be considered	d Draft) at the Re	sident Engineer Level by	bro	owns1
June 21, 2021			R	Reviewed and	d Approved at the	Central Office C	ontrollers Office Level by	gre	eggd1
Oniminal Caman	leties Dete	Command Com	aulatian Data	A -41 C	Name Indian Date	0/ -	f C C = mtm= at A		

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 10, 2020	August 20, 2021		53.65%

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	June 3, 2020	June 3, 2020	
Letting Date	May 15, 2020	May 15, 2020	
Notice to Proceed Date	July 6, 2020	July 6, 2020	
Open to Traffic Date			
Work Began Date	April 5, 2021	April 5, 2021	

Contract Total Pa	ay For Estimate No. 7				
		This Estimate	Previous	To Date	
200515-D01					
	Total Posted Items Pay	\$55,237.50	\$217,492.11	\$272,729.61	
	Gross Item Adjustments	\$300.00	\$14,270.85	\$14,570.85	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$231,762.96	\$287,300.46	
Contract Total Pa	yable This Estimate:	\$55,537.50			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3426	0100	6181000	MOBILIZATION	LS	\$15,800.000	0.25	\$3,950.00
	0540	9024281	CONTROLLER ASSEMBLY HOUSING, KEYBOARD ENTRY, 8 PHASE NEMA CONTROLLER	EA	\$15,554.000	2	\$31,108.00
	0560	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	LF	\$9.500	104	\$988.00
	0570	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	LF	\$10.000	35	\$350.00
	0730	9029100	BASE, CONCRETE	CUYD	\$1,350.000	6.15	\$8,302.50
	5001	9011064	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 3	EA	\$2,634.750	4	\$10,539.00
Project J5P	3426 - Tot	al					\$55,237.50
Overall - To	otal						\$55,237.50

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjusti	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3426	0020	6 IN. CONCRETE MEDIAN STRIP	Material			-2.4	\$600.00	(\$1,440.00)
	0020	6 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	2.4	\$600.00	\$1,440.00
	0120	PREFORMED	MaterialCredit			12	\$25.00	\$300.00

Revision 4/1/2020 Page 1 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2021

Progress Estimate Number 7 Contract ID 200515-D01 Pay Period Start June 2, 2021 Original Contract Amount Science Sponsor Spons

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3426		THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE						
	0370	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING AND SIGNALS	Material			-1	\$3,395.00	(\$3,395.00)
	0370	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING AND SIGNALS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	1	\$3,395.00	\$3,395.00
	0430	SH-FLAT SHEET - SIGNAL SIGN	Material			-90	\$40.00	(\$3,600.00)
	0430	SH-FLAT SHEET - SIGNAL SIGN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	90	\$40.00	\$3,600.00
	0730	BASE, CONCRETE	Material			-27.94	\$1,350.00	(\$37,719.00)
	0730	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	27.94	\$1,350.00	\$37,719.00
	5001	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 3	Material			-4	\$2,634.75	(\$10,539.00)
	5001	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 3	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	4	\$2,634.75	\$10,539.00
Total								\$300.00

Revision 4/1/2020 Page 2 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information			
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work		
J5P3426	FAF 52-3(25)	Signal improvements	Various	MILLER	at MO 52 and RT CC in E	Eldon; at RT OO and Summ	it Dr. in Holts Summit; at RT C and R		
Γotals by .	Job Numbe	ers							
J5P3426					This Estimate	Previous	To Date		
		ed Item Pay s Item Adjustme	ents		\$55,237.50 \$300.00	\$217,492.11 \$14.270.85	\$272,729.61 \$14,570.85		
	0.00	nom Aujuound		tem Pay	\$55,537.50	\$231,762.96	\$287,300.46		
	Incen	tive			\$0.00	\$0.00	\$0.00		
	Disin	centive			\$0.00	\$0.00	\$0.00		
					\$0.00 \$0.00 \$0.00				
		dated Damages			\$0.00	φ0.00	ψ0.00		

Revision 4/1/2020 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6083006, Project Item Line Number 0020, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Stokez1 Test have not been received.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6083006, Project Item Line Number 0020, Material Set 608300696, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Stokez1 Test have not been received.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6083006, Project Item Line Jumber 0020, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Stokez1 Test have not been received.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6083006, Project Item Line Jumber 0020, Material Set 608300696, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Stokez1 Test have not been received.	stokez1	Overridden
estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6083006, Project Item Line lumber 0020, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge bissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Stokez1 Test have not been received.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6083006, Project Item Line lumber 0020, Material Set 608300696, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance action Generic 1005GDCMLD is insufficient.	Stokez1 Test have not been received.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9011064, Project Item Line lumber 5001, Material Set 901106496, Material 1091LHLP - Highway Lighting Pole, Acceptance Action Generic 1091LHLP is insufficient.	Stokez1 Material has been inspected. Test needs to be entered.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9011064, Project Item Line lumber 5001, Material Set 901106496, Material 0901LHXX - Highway Lighting Material, Acceptance action Generic 0901LHXX is insufficient.	Stokez1 Material has been inspected. Test needs to be entered.	stokez1	Overridden
estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9018613, Project Item Line stumber 0370, Material Set 901861396, Material 0901LHXX - Highway Lighting Material, Acceptance action Generic 0901LHXX is insufficient.	Stokez1 Test needs to be entered.	stokez1	Overridden
estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9020833, Project Item Line Aumber 0430, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 042SM is insufficient.	Stokez1 Test needs to be entered.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9029100, Project Item Line Aumber 0730, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Stokez1 Test have not been received.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9029100, Project Item Line lumber 0730, Material Set 902910096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, acceptance Action Generic 100510CPCMLD is insufficient.	Stokez1 Test have not been received.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9029100, Project Item Line lumber 0730, Material Set 902910096, Material 1005FACCNSCA - Natural Sand for Conc Class A, acceptance Action Generic 1005FACCNSCA is insufficient.	Stokez1 Test have not been received.	stokez1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-D01, Contract Project J5P3426, Project Item ine Number 0280, Contract Line Item Number 0280, Item 9013002, Minor Item.	Stokez1 Change order is in progress	stokez1	Acknowledge

Revision 4/1/2020 Page 4 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
00515-D01	J5P3426	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	•	\$13,600.00	\$4,528.8
		0001	0020	6083006	6 IN. CONCRETE MEDIAN STRIP	2.40	0.00	2.40	SQYD	2.40	\$600.00	\$1,440.0
		0001	0030	6161005	CONSTRUCTION SIGNS	903.00	0.00	903.00	SQFT	428.00	\$7.50	\$3,210.0
		0001	0040	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	0.00	\$25.00	\$0.0
		0001	0050	6161010	RELOCATED SIGNS	965.00	0.00	965.00	SQFT	348.00	\$7.00	\$2,436.0
		0001	0060	6161025	CHANNELIZER (TRIM LINE)	260.00	0.00	260.00	EA	95.00	\$25.00	\$2,375.0
		0001	0070	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$925.00	\$0.0
		0001	0080	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,000.00	\$16,000.0
		0001	0090	6169902	MISC.DETECTABLE PEDESTRIAN CHANNELIZING BARRICADE - TYPE II	4.00	0.00	4.00	EA	4.00	\$160.00	\$640.
		0001	0100	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$15,800.00	\$15,800.
		0001	0110	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	6.00	0.00	6.00	EA	2.00	\$600.00	\$1,200.
		0001	0120	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	48.00	0.00	48.00	LF	12.00	\$25.00	\$300.
		0001	0130	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	62.00	0.00	62.00	LF	0.00	\$2.00	\$0
		0001	0140	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	16.00	0.00	16.00	LF	0.00	\$2.00	\$0
		0001	0150	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	117.00	0.00	117.00	LF	0.00	\$3.00	\$0
		0001	0160	6207001	PAVEMENT MARKING REMOVAL	137.00	0.00	137.00	LF	4.00	\$3.00	\$12
		0001	0170	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	3.00	0.00	3.00	EA	1.00	\$125.00	\$125
		0001	0180	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$2,800.00	\$1,400
		0001	0190	8061006	ALTERNATE DITCH CHECK	370.00	0.00	370.00	LF	279.00	\$13.00	\$3,627
		0001	0200	8061007A	CURB INLET CHECK	2.00	2.00	4.00	EA	4.00	\$250.00	\$1,000
		0001	0210	8061016	SEDIMENT REMOVAL	37.00	0.00	37.00	CUYD	2.00	\$30.00	\$60
		0020	0220	9011060	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 1	3.00	-3.00	0.00	EA	0.00	\$2,742.00	\$0
		0020	0230	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	1.00	-1.00	0.00	EA	0.00	\$2,313.00	\$0
		0020	0240	9011115	BRACKET ARM, 15 FT. OR 4.6 M	4.00	0.00	4.00	EA	4.00	\$760.00	\$3,040
		0020	0250	9011311	LUMINAIRE, LED-A	7.00	0.00	7.00	EA	0.00	\$569.00	\$0
		0020	0260	9011312	LUMINAIRE, LED-B	4.00	0.00	4.00	EA	0.00	\$610.00	\$0
		0020	0270	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	1.00	\$5,300.00	\$5,300
		0020	0280	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	63.00	0.00	63.00	LF	105.00	\$10.00	\$1,050
		0020	0290	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	116.00	0.00	116.00	LF	74.00	\$11.00	\$814
		0020	0300	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	56.00	0.00	56.00	LF	56.00	\$12.00	\$672
		0020	0310	9014004	CONDUIT, 4 IN. RIGID, PUSHED	266.00	0.00	266.00	LF	266.00	\$18.00	\$4.788
		0020	0320	9016110	PULL BOX. PREFORMED CLASS 1	4.00	0.00	4.00	EA	4.00	\$1,000.00	\$4,000
		0020	0330	9017002	CABLE, 2 AWG 1 CONDUCTOR	240.00	0.00	240.00	LF	237.00	\$2.10	\$497
			0340	9017002	CABLE, 8 AWG 1 CONDUCTOR	1,260.00	0.00	1.260.00	LF		\$1.20	\$1,506
		0020						,		1,255.00		
		0020	0350	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	480.00	0.00	480.00	LF	480.00	\$0.85	\$408
		0020	0360	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	4.00	\$1,200.00	\$4,800
		0020	0370	9018613	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING AND SIGNALS	3.00	0.00	3.00	EA	1.00	\$3,395.00	\$3,395
		0030	0380	9020113	SIGNAL HEAD, TYPE 3T	1.00	0.00	1.00	EA	0.00	\$739.00	\$0
		0030	0390	9020213	SIGNAL HEAD, TYPE 3S	8.00	0.00	8.00	EA	4.00	\$707.00	\$2,828
		0030	0400	9020513	SIGNAL HEAD, TYPE 3B	22.00	0.00	22.00	EA	8.00	\$857.00	\$6,856
		0030	0410	9020514	SIGNAL HEAD, TYPE 4B	3.00	0.00	3.00	EA	0.00	\$987.00	\$0
		0030	0420	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	6.00	0.00	6.00	EA	0.00	\$407.00	\$0
		0030	0430	9020833	SH-FLAT SHEET - SIGNAL SIGN	257.00	0.00	257.00	SQFT	90.00	\$40.00	\$3,600

Revision 4/1/2020 Page 5 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
200515-D01	J5P3426	0030	0440	9020834	SIGNAL SIGN, MOUNTING HARDWARE	40.00	0.00	40.00	EA	12.00	\$195.00	\$2,340.00
		0030	0450	9022708	POST, SIGNAL 8 FT. OR 2.4 M	5.00	0.00	5.00	EA	0.00	\$607.00	\$0.00
		0030	0460	9022715	POST, SIGNAL 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$790.00	\$0.00
		0030	0470	9023115	POST, TYPE CL, 15 FT. ARM OR 4.6 M ARM	1.00	0.00	1.00	EA	0.00	\$6,639.00	\$0.00
		0030	0480	9023120	POST, TYPE CL, 20 FT. ARM OR 6.1 M ARM	1.00	0.00	1.00	EA	0.00	\$6,717.00	\$0.0
		0030	0490	9023125	POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	2.00	0.00	2.00	EA	2.00	\$6,742.00	\$13,484.0
		0030	0500	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	0.00	\$8,289.00	\$0.0
		0030	0510	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	3.00	0.00	3.00	EA	2.00	\$7,600.00	\$15,200.0
		0030	0520	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	2.00	0.00	2.00	EA	0.00	\$9,711.00	\$0.0
		0030	0530	9023445	POST, TYPE BL, LONGEST ARM 45 FT. OR 13.7 M	1.00	0.00	1.00	EA	0.00	\$14,515.00	\$0.0
		0030	0540	9024281	CONTROLLER ASSEMBLY HOUSING, KEYBOARD ENTRY, 8 PHASE NEMA CONTROLLER	3.00	0.00	3.00	EA	2.00	\$15,554.00	\$31,108.0
		0030	0550	9024920	DETECTOR, PUSHBUTTON	6.00	0.00	6.00	EA	0.00	\$206.00	\$0.0
		0030	0560	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	230.00	0.00	230.00	LF	166.00	\$9.50	\$1,577.0
		0030	0570	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	547.00	0.00	547.00	LF	388.00	\$10.00	\$3,880.0
		0030	0580	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	798.00	0.00	798.00	LF	565.00	\$24.00	\$13,560.0
		0030	0590	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	640.00	0.00	640.00	LF	0.00	\$0.85	\$0.0
		0030	0600	9028202	CABLE, 2 AWG 1 CONDUCTOR, POWER	530.00	0.00	530.00	LF	174.00	\$1.80	\$313.2
		0030	0610	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	230.00	0.00	230.00	LF	29.00	\$1.10	\$31.9
		0030	0620	9028302	CABLE, 12 AWG 2 CONDUCTOR	1,170.00	0.00	1,170.00	LF	0.00	\$1.10	\$0.0
		0030	0630	9028308	CABLE, 16 AWG 2 CONDUCTOR	1,500.00	0.00	1,500.00	LF	809.00	\$1.05	\$849.4
		0030	0640	9028310	CABLE, 16 AWG 5 CONDUCTOR	1,500.00	0.00	1,500.00	LF	813.00	\$1.12	\$910.5
		0030	0650	9028311	CABLE, 16 AWG 7 CONDUCTOR	5,200.00	0.00	5,200.00	LF	2,020.00	\$1.20	\$2,424.0
		0030	0660	9028350	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MODE	620.00	0.00	620.00	LF	0.00	\$3.25	\$0.0
		0030	0670	9028510	CABLE, LOOP DETECTOR, LEAD-IN	1,080.00	0.00	1,080.00	LF	0.00	\$1.20	\$0.0
		0030	0680	9028810	PULL BOX, PREFORMED CLASS 1	2.00	0.00	2.00	EA	1.00	\$985.00	\$985.0
		0030	0690	9028811	PULL BOX, PREFORMED CLASS 2	9.00	0.00	9.00	EA	6.00	\$1,350.00	\$8,100.0
		0030	0700	9028812	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	1.00	\$1,600.00	\$1,600.0
		0030	0710	9028816	PULL BOX, PREFORMED CLASS 5	1.00	0.00	1.00	EA	1.00	\$1,600.00	\$1,600.0
		0030	0720	9028824	PULL BOX, CONCRETE, DOUBLE TYPE B	2.00	0.00	2.00	EA	2.00	\$2,900.00	\$5,800.0
		0030	0730	9029100	BASE, CONCRETE	42.20	0.00	42.20	CUYD	27.94	\$1,350.00	\$37,719.0
		0030	0740	9029902	MISC.GRIDSMART V.D.S. Salvage	1.00	0.00	1.00	EA	0.00	\$1,600.00	\$0.0
		0030	0750	9029902	MISC.GRIDSMART Video Detection System	2.00	0.00	2.00	EA	1.00	\$23,000.00	\$23,000.0
		0040	0760	9031010	CONCRETE FOOTINGS, EMBEDDED	0.40	0.00	0.40	CUYD	0.00	\$1,500.00	\$0.0
		0040	0770	9031210	STRUCTURAL STEEL POSTS	50.00	0.00	50.00	LB	0.00	\$25.00	\$0.0
		0040	0780	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	4.00	0.00	4.00	EA	0.00	\$205.00	\$0.0
		0040	0790	9031280	2.5 IN. PSST POST - 12 GA.	64.00	0.00	64.00	LF	0.00	\$11.00	\$0.0
		0040	0800	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	12.00	0.00	12.00	LF	0.00	\$40.00	\$0.0
		0040	0810	9035004A	SH-FLAT SHEET	37.00	0.00	37.00	SQFT	0.00	\$20.00	\$0.
		0020	5001	9011064	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 3	0.00	4.00	4.00	EA	4.00	\$2,634.75	\$10,539.0
	Project J	5P3426 - To	tal Value	Posted to D	Date as of Report Generated Date							\$272,729.6

Revision 4/1/2020 Page 6 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3426

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0100	6181000	MOBILIZATION	6/14/21	6/16/21	0.25	LS	NA					
0540	9024281	CONTROLLER ASSEMBLY HOUSING,	6/11/21	6/16/21	1.00	EA	Rte. 00: 14+00 Rt					
				6/16/21	1.00	EA	Rte. C at Sta. 7+47 Lt					
0560	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	6/11/21	6/16/21	104.00	LF	Rte. C Power supply to controller					
0570	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	6/11/21	6/16/21	35.00	LF	Rte. C 13 feet from pull box 4 to post 3 10 feet from pull box 6 to post 1 12 feet from pull box 1 to post 4					
0730	9029100	BASE, CONCRETE	6/11/21	6/16/21	6.15	CUYD	Rte. C 2.88 CY at post 1 3.27 CY at post 4					
5001	9011064	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT	6/14/21	6/16/21	4.00	EA	Rte. OO: Pole#1 at 14+00 Rt Pole#2 at 14+83 Lt Pole#3 at 15+90 Lt Pole#4 at 15+05 Rt					

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 7 of 14



Project Unit										
CONCRETE STORY Control Contr	Project	Line	Description		Adjustment				Amount	Remarks
3	J5P3426	0020	CONCRETE MEDIAN	Material		3		SYSTEM	\$1,440.00	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment
2021 2021			STRIP			3		SYSTEM	(\$1,440.00)	
2021 S						4		SYSTEM	\$1,440.00	Estimate Item Adjustment (0002) due to user stokez1 overridding Payment
2021 SySTEM S1.440.00 The adjustment (0007) due to user ablocat overading Payment Estimate Exception 1 on the current Payment Estimate 1 Society 1 on the current Payment Estimate						4		SYSTEM	(\$1,440.00)	
						5		SYSTEM	\$1,440.00	Estimate Item Adjustment (0007) due to user stokez1 overridding Payment
2021 SYSTEM St. (400.00) SySTEM Sys						5		SYSTEM	(\$1,440.00)	
2021 7 2.1						6		SYSTEM	\$1,440.00	Estimate Item Adjustment (0007) due to user stokez1 overridding Payment
2021 Estimate Item Adjustment (0003) due to user stokez 1 overridding Payment Estimate Exception 1 on the current Payment Estimate. Substitute Exception 1 on the current Payment Estimate.						6		SYSTEM	(\$1,440.00)	
Total So.00						7		SYSTEM	\$1,440.00	Estimate Item Adjustment (0003) due to user stokez1 overridding Payment
Material - Total S0.00						7		SYSTEM	(\$1,440.00)	
Material Superation Super					- Total				\$0.00	
				Material - Tota					\$0.00	
THERMO		0020 -	Total						\$0.00	
24 IN WHIT		0120	THERMO PVMT MARK,	Material		5		SYSTEM	(\$300.00)	
Material - Total						6		SYSTEM	(\$300.00)	
MaterialCredit					- Total				(\$600.00)	
2021 7 Jun 16, SYSTEM \$300.00				Material - Tota	ı				(\$600.00)	
2021 \$600.00				MaterialCredit		6		SYSTEM	\$300.00	
Material Credit - Total						7		SYSTEM	\$300.00	
D120 - Total					- Total				\$600.00	
ALTERNATE DITCH CHECK				MaterialCredit	- Total				\$600.00	
DITCH CHECK		0120 -	Total						\$0.00	
Material - Total (\$1,287.00)		0190	DITCH	Material		3		SYSTEM	(\$1,287.00)	
MaterialCredit			OHEON		- Total				(\$1,287.00)	
- Total \$1,287.00 MaterialCredit - Total \$1,287.00 0190 - Total \$1,287.00 0200 CURB INLET CHECK				Material - Tota					(\$1,287.00)	
MaterialCredit - Total \$1,287.00				MaterialCredit		4		SYSTEM	\$1,287.00	
D190 - Total					- Total				\$1,287.00	
O200 CURB INLET CHECK				MaterialCredit	- Total				\$1,287.00	
CHECK 2021 (\$1,000.00) Material - Total (\$1,000.00) MaterialCredit 4 May 3, 2021 \$1,000.00 - Total \$1,000.00 MaterialCredit - Total \$1,000.00		0190 -	Total						\$0.00	
Material - Total (\$1,000.00) MaterialCredit 4 May 3, 2021 \$1,000.00 - Total \$1,000.00 MaterialCredit - Total \$1,000.00		0200		Material		3		SYSTEM	(\$1,000.00)	
MaterialCredit 4 May 3, 2021 \$1,000.00 - Total \$1,000.00 MaterialCredit - Total \$1,000.00					- Total				(\$1,000.00)	
2021				Material - Tota					(\$1,000.00)	
MaterialCredit - Total \$1,000.00				MaterialCredit		4		SYSTEM	\$1,000.00	
					- Total				\$1,000.00	
Overrun Overrun 3 Apr 19, SYSTEM \$500.00 This adjustment offsets the original system-generated Overrun Payment				MaterialCredit	- Total				\$1,000.00	
				Overrun	Overrun	3	Apr 19,	SYSTEM	\$500.00	This adjustment offsets the original system-generated Overrun Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J5P3426	0200	CURB INLET CHECK	Overrun	Overrun		2021			Estimate Item Adjustment (0001) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 4.000; Overrun Quantity Balance 2.00.			
					3	Apr 19, 2021	SYSTEM	(\$500.00)				
					4	May 3, 2021	SYSTEM	(\$500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).			
					5	May 17, 2021	SYSTEM	\$500.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',250.00000 - 250.00000, 'is applied (if non-zero).			
				Overrun - To	otal			\$0.00				
			Overrun - Tota	ıl				\$0.00				
	0200 -	Total						\$0.00				
	0270	BASE MOUNTED CONTROL	Material		4	May 3, 2021	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
		STATION			4	May 3, 2021	SYSTEM	(\$5,300.00)				
					5	May 17, 2021	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					5	May 17, 2021	SYSTEM	(\$5,300.00)				
					6	Jun 1, 2021	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					6	Jun 1, 2021	SYSTEM	(\$5,300.00)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	0270 -	Total						\$0.00				
	0280	CONDUIT, 2 IN. RIGID, IN TRENCH	Overrun	Overrun	4	May 3, 2021	SYSTEM	(\$420.00)				
		TILLINGIT		Overrun - To	otal			(\$420.00)				
			Overrun - Tota	ıl				(\$420.00)				
	0280 -	Total						(\$420.00)				
	0330	CABLE, 2 AWG 1 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$497.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					4	May 3, 2021	SYSTEM	(\$497.70)				
								5	May 17, 2021	SYSTEM	\$497.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	May 17, 2021	SYSTEM	(\$497.70)				
					6	Jun 1, 2021	SYSTEM	\$497.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					6	Jun 1, 2021	SYSTEM	(\$497.70)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	0330 -							\$0.00				
	0340	CABLE, 8 AWG 1 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$1,506.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					4	May 3, 2021	SYSTEM	(\$1,506.00)				
					5	May 17, 2021	SYSTEM	\$1,506.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J5P3426	0340	CABLE, 8 AWG 1	Material		5	May 17, 2021	SYSTEM	(\$1,506.00)										
		CONDUCTOR			6	Jun 1, 2021	SYSTEM	\$1,506.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
					6	Jun 1, 2021	SYSTEM	(\$1,506.00)										
				- Total				\$0.00										
			Material - Tota					\$0.00										
	0340 -	Total		·				\$0.00										
							01/07514											
	0350	CABLE, 10 AWG 1 CONDUCTOR, POLE &	Material		4	May 3, 2021	SYSTEM	\$408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
		BRACKE			4	May 3, 2021	SYSTEM	(\$408.00)										
					5	May 17, 2021	SYSTEM	\$408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					5	May 17, 2021	SYSTEM	(\$408.00)										
					6	Jun 1, 2021	SYSTEM	\$408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					6	Jun 1, 2021	SYSTEM	(\$408.00)										
				- Total				\$0.00										
			Material - Tota					\$0.00										
	0350 -	Total						\$0.00										
							OVOTEM		The state of the s									
	0370	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120	Material		4	May 3, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
										4	May 3, 2021	SYSTEM	(\$3,395.00)					
					5	May 17, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					5	May 17, 2021	SYSTEM	(\$3,395.00)										
					6	Jun 1, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
														6	Jun 1, 2021	SYSTEM	(\$3,395.00)	
											7	Jun 16, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					7	Jun 16, 2021	SYSTEM	(\$3,395.00)										
				- Total				\$0.00										
			Material - Total					\$0.00										
	0370 -	Total						\$0.00										
			Motorial		4	Marra	CVCTEM		This adjustment offsets the original system sense-1-1 M-1-1-1 D-11-1-1									
	0390	SIGNAL HEAD, TYPE 3S	E		4	May 3, 2021	SYSTEM	\$2,828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					4	May 3, 2021	SYSTEM	(\$2,828.00)										
					5	May 17, 2021	SYSTEM	\$2,828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.									
					5	May 17, 2021	SYSTEM	(\$2,828.00)										
					6	Jun 1, 2021	SYSTEM	\$2,828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment									



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks			
Floject	LIIIE	Description	Туре	Adjustment	Number	Date	By	Amount	Remarks			
J5P3426	0390	SIGNAL	Material	Type					Estimate Exception 13 on the current Payment Estimate.			
001 0420	0000	HEAD, TYPE 3S	Waterial		6	Jun 1,	SYSTEM	(\$2,828.00)	Estimate Exception to on the current aymont Estimate.			
		33				2021		(+=,-==,)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	0390 -							\$0.00				
	0400	SIGNAL HEAD, TYPE 3B	Material		4	May 3, 2021	SYSTEM	\$6,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.			
					4	May 3, 2021	SYSTEM	(\$6,856.00)				
					5	May 17, 2021	SYSTEM	\$6,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
					5	May 17, 2021	SYSTEM	(\$6,856.00)				
					6	Jun 1,	SYSTEM	\$6,856.00	This adjustment offsets the original system-generated Material Payment			
						2021			Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
					6	Jun 1, 2021	SYSTEM	(\$6,856.00)				
				- Total				\$0.00				
			Material - Tota	ı				\$0.00				
	0400 -	Total						\$0.00				
	0430	SH-FLAT SHEET - SIGNAL SIGN	-		4	May 3, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
					4	May 3, 2021	SYSTEM	(\$3,600.00)				
					5	May 17, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
						5	May 17, 2021	SYSTEM	(\$3,600.00)			
					6	Jun 1, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
								6	Jun 1, 2021	SYSTEM	(\$3,600.00)	
								7	Jun 16, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	Jun 16, 2021	SYSTEM	(\$3,600.00)				
				- Total				\$0.00				
			Material - Tota					\$0.00				
	0430 -	Total						\$0.00				
	0600	CABLE, 2 AWG 1 CONDUCTOR, POWER	AWG 1 JCTOR,		4	May 3, 2021	SYSTEM	\$313.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
					4	May 3, 2021	SYSTEM	(\$313.20)				
					5	May 17, 2021	SYSTEM	\$313.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
					5	May 17, 2021	SYSTEM	(\$313.20)				
					6	Jun 1, 2021	SYSTEM	\$313.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
					6	Jun 1, 2021	SYSTEM	(\$313.20)				



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
P3426	0600	CABLE, 2 AWG 1	Material	- Total				\$0.00					
		CONDUCTOR, POWER	Material - Tota	ı				\$0.00					
	0600 -	Total						\$0.00					
	0610	CABLE, 8 AWG 1 CONDUCTOR, POWER	Material		4	May 3, 2021	SYSTEM	\$31.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
		POWER			4	May 3, 2021	SYSTEM	(\$31.90)					
					5	May 17, 2021	SYSTEM	\$31.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
					5	May 17, 2021	SYSTEM	(\$31.90)					
					6	Jun 1, 2021	SYSTEM	\$31.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
					6	Jun 1, 2021	SYSTEM	(\$31.90)					
				- Total				\$0.00					
			Material - Tota					\$0.00					
	0610 -	Total						\$0.00					
	0630	CABLE, 16 AWG 2 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$849.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
					4	May 3, 2021	SYSTEM	(\$849.45)					
					5	May 17, 2021	SYSTEM	\$849.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					5	May 17, 2021	SYSTEM	(\$849.45)					
					6	Jun 1, 2021	SYSTEM	\$849.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					6	Jun 1, 2021	SYSTEM	(\$849.45)					
				- Total				\$0.00					
			Material - Tota					\$0.00					
	0630 -	Total						\$0.00					
	0640	CABLE, 16 AWG 5 CONDUCTOR	AWG 5	AWG 5	AWG 5			4	May 3, 2021	SYSTEM	\$910.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
									4	May 3, 2021	SYSTEM	(\$910.56)	
										5	May 17, 2021	SYSTEM	\$910.56
							5	May 17, 2021	SYSTEM	(\$910.56)			
								6	Jun 1, 2021	SYSTEM	\$910.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
					6	Jun 1, 2021	SYSTEM	(\$910.56)					
				- Total				\$0.00					
			Material - Tota					\$0.00					
	0640 -	Total						\$0.00					
	0650	CABLE, 16 AWG 7 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user stokez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.				
					4	May 3,	SYSTEM	(\$2,424.00)					



Type Adjustment Type Date By CABLE, 16 AWG 7 CONDUCTOR Material 5 May 17, 2021 5 May 17, 2021 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate. Material 5 May 17, 2021 6 Jun 1, SYSTEM \$2,424.00 This adjustment offsets the original system-generated Material Payment Estimate.								1		
CONDUCTOR	Project	Line	Description		Adjustment				Amount	Remarks
CONDUCTOR	P3426	0650	CABLE, 16	Material			2021			
2021 SYSTEM S2 424 0.0 This adjustment officials the original system-generated Material Payment Estimate Entender Color) due to user stokes of coverading Payment Estimate Exception 20 on the current Payment Estimate Exception 20 on the cu						5		SYSTEM	\$2,424.00	Estimate Item Adjustment (0018) due to user stokez1 overridding Payment
2021 SysTEM (\$2,424.00)						5		SYSTEM	(\$2,424.00)	
						6		SYSTEM	\$2,424.00	Estimate Item Adjustment (0017) due to user stokez1 overridding Payment
National - Total September September						6		SYSTEM	(\$2,424.00)	
					- Total				\$0.00	
10 P.U.L. D.C. Material 2021				Material - Tota	1				\$0.00	
CONCRETE		0650 -	· Total						\$0.00	
Apr 19, 2021		0720	CONCRETE, DOUBLE	Material		3		SYSTEM	\$5,800.00	Estimate Item Adjustment (0005) due to user stokez1 overridding Payment
2021 System Estimate Item Adjustment (0020) use to user slokezt overridding Payment Estimate Exception 20 on the current Payment Estimate Exception 20 on the current Payment Estimate Item Adjustment (012) use to user slokezt overridding Payment Estimate Item Adjustment (012) use to user slokezt overridding Payment Estimate Exception 21 on the current Payment Estimate Estimate Item Adjustment (0012) use to user slokezt overridding Payment Estimate Exception 21 on the current Payment Estimate Estimate Exception 21 on the current Payment Estimate Estimate Item Adjustment (0012) use to user slokezt overridding Payment Estimate Exception 21 on the current Payment Estimate Item Adjustment (0012) user slokezt overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate Item Adjustment (0020) user slokezt overridding Payment Estimate Item Adjustment (0020) user slokezt overridding Payment Estimate Exception 20 on the current Payment Estimate Exception 20 on the current Payment Estimate Estimate Item Adjustment (0020) user slokezt overridding Payment Estimate Item Adjustment (0021) use to user slokezt overridding Payment Estimate Estimate Exception 20 on the current Payment Estimate Item Adjustment (0012) use to user slokezt overridding Payment Estimate Item Adjustment (012) use to user slokezt overridding Payment Estimate Exception 21 on the current Payment Estimate Item Adjustment (0020) due to user slokezt overridding Payment Estimate Exception 21 on the current Payment Estimate Item Adjustment (0020) due to user slokezt overridding Payment Estimate Item Adjustment (0020) due to user slokezt overridding Payment Estimate Item Adjustment (0020) due to user slokezt overridding Payment Item Adjustment (0020) due to user slokezt overridding Payment Item Adjustment (0020) due to user slokezt overridding Payment Item Adjustment (0020) due to user slokezt overridding Payment Item Adjustment (0020) due to user slokezt overriddin			I A P E B			3		SYSTEM	(\$5,800.00)	
2021 5 May 17. SYSTEM \$5,800.00 This adjustment offsets the original system-penerated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 1						4		SYSTEM	\$5,800.00	Estimate Item Adjustment (0020) due to user stokez1 overridding Payment
2021 Settmate Item Adjustment (0012) due to user stokez 1 overridding Payment Estimate Estimate Exception 21 on the current Payment Estimate.						4		SYSTEM	(\$5,800.00)	
Total S0.00						5		SYSTEM	\$5,800.00	Estimate Item Adjustment (0012) due to user stokez1 overridding Payment
Solid Soli						5		SYSTEM	(\$5,800.00)	
Solid					- Total				\$0.00	
D730 BASE, CONCRETE Material				Material - Tota	ı				\$0.00	
CONCRETE		0720 -	· Total						\$0.00	
2021		0730		Material		3		SYSTEM	\$18,508.50	Estimate Item Adjustment (0006) due to user stokez1 overridding Paymen
2021 SYSTEM (\$18,508.50)						3		SYSTEM	(\$18,508.50)	
2021						4		SYSTEM	\$18,508.50	Estimate Item Adjustment (0021) due to user stokez1 overridding Payment
2021 Estimate Item Adjustment (0013) due to user stokez1 overridding Paymen Estimate Exception 23 on the current Payment Estimate.						4		SYSTEM	(\$18,508.50)	
2021						5		SYSTEM	\$22,923.00	Estimate Item Adjustment (0013) due to user stokez1 overridding Payment
2021 Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 21 on the current Payment Estimate.						5		SYSTEM	(\$22,923.00)	
2021						6		SYSTEM	\$29,416.50	Estimate Item Adjustment (0012) due to user stokez1 overridding Paymen
2021 Estimate Item Adjustment (0005) due to user stokez1 overridding Paymen Estimate Exception 11 on the current Payment Estimate. 7						6		SYSTEM	(\$29,416.50)	
2021 \$0.00						7		SYSTEM	\$37,719.00	Estimate Item Adjustment (0005) due to user stokez1 overridding Paymen
Material - Total \$0.00 0730 - Total \$0.00 0750 MISC. Construction 4 May 3, SYSTEM (\$22,999.15) Payment Estimate Item Adjustment generated Stockpile Transaction						7		SYSTEM	(\$37,719.00)	
0730 - Total \$0.00 0750 MISC. Construction 4 May 3, SYSTEM (\$22,999.15) Payment Estimate Item Adjustment generated Stockpile Transaction					- Total				\$0.00	
0750 MISC. Construction 4 May 3, SYSTEM (\$22,999.15) Payment Estimate Item Adjustment generated Stockpile Transaction				Material - Tota	ıl				\$0.00	
		0730 -	· Total						\$0.00	
		0750	MISC.			4		SYSTEM	(\$22,999.15)	Payment Estimate Item Adjustment generated Stockpile Transaction

Jun 21, 2021



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3426	0750	MISC.	Construction Stockpile	- Total				(\$22,999.15)	
			Construction	Stockpile - To	otal			(\$22,999.15)	
			Construction Stockpile		1	Aug 3, 2020	SYSTEM	\$37,990.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$37,990.00	
			Construction S	Stockpile STI	VII - Total			\$37,990.00	
	0750 - Total							\$14,990.85	
	5001	LIGHTING POLE, 45 FT. OR 13.5 M,	Material		7	Jun 16, 2021	SYSTEM	\$10,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		TYPE AT			7	Jun 16, 2021	SYSTEM	(\$10,539.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	5001 -	Total						\$0.00	
J5P3426	- Total						\$14,570.85		
Overall -	Total						\$14,570.85		