

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 30, 2021

Progress Estimate Number	Contract ID	200515-D01	Pay Period Start	June 16, 202	Original Contract Amount	\$507,803.50
8	<b>Prime Contractor</b>	Meyer Electric Company, Inc.	Pay Period End	June 30, 202	Net Change Order Amount	\$500.00
0					<b>Current Contract Amount</b>	\$508,303.50

Approval Date		By User
June 30, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	stokez1
June 30, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	browns1
July 2, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 10, 2020	August 20, 2021		65.06%

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	June 3, 2020	June 3, 2020	
Letting Date	May 15, 2020	May 15, 2020	
Notice to Proceed Date	July 6, 2020	July 6, 2020	
Open to Traffic Date			
Work Began Date	April 5, 2021	April 5, 2021	

Contract Total Pa	ay For Estimate No. 8				
		This Estimate	Previous	To Date	
200515-D01					
	Total Posted Items Pay	\$57,959.10	\$272,729.61	\$330,688.71	
	Gross Item Adjustments	(\$6,973.00)	\$14,570.85	\$7,597.85	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$287,300.46	\$338,286.56	
<b>Contract Total Pa</b>	yable This Estimate:	\$50,986.10			

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3426	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$13,600.000	0.333	\$4,528.80
	0120	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$25.000	12	\$300.00
	0130	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$2.000	62	\$124.00
	0140	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$2.000	16	\$32.00
	0150	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$3.000	117	\$351.00
	0160	6207001	PAVEMENT MARKING REMOVAL	LF	\$3.000	111	\$333.00
	0390	9020213	SIGNAL HEAD, TYPE 3S	EA	\$707.000	4	\$2,828.00
	0400	9020513	SIGNAL HEAD, TYPE 3B	EA	\$857.000	4	\$3,428.00
	0410	9020514	SIGNAL HEAD, TYPE 4B	EA	\$987.000	2	\$1,974.00
	0430	9020833	SH-FLAT SHEET - SIGNAL SIGN	SQFT	\$40.000	71.5	\$2,860.00
	0440	9020834	SIGNAL SIGN, MOUNTING HARDWARE	EA	\$195.000	10	\$1,950.00
	0470	9023115	POST, TYPE CL, 15 FT. ARM OR 4.6 M ARM	EA	\$6,639.000	1	\$6,639.00
	0480	9023120	POST, TYPE CL, 20 FT. ARM OR 6.1 M ARM	EA	\$6,717.000	1	\$6,717.00
	0520	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	EA	\$9,711.000	2	\$19,422.00
	0590	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	LF	\$0.850	348	\$295.80
	0600	9028202	CABLE, 2 AWG 1 CONDUCTOR, POWER	LF	\$1.800	153	\$275.40

Revision 4/1/2020 Page 1 of 16



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 30, 2021

Progress Estimate Number	Contract ID	200515-D01	Pay Period Start	June 16, 2021	Original Contract Amount	\$507,803.50
8	Prime Contractor	Meyer Electric Company, Inc.	Pay Period End	June 30, 2021	Net Change Order Amount	\$500.00
· ·					Current Contract Amount	\$508,303.50

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3426	0610	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	LF	\$1.100	112	\$123.20
	0620	9028302	CABLE, 12 AWG 2 CONDUCTOR	LF	\$1.100	690	\$759.00
	0650	9028311	CABLE, 16 AWG 7 CONDUCTOR	LF	\$1.200	1,402	\$1,682.40
	0660	9028350	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MODE	LF	\$3.250	626	\$2,034.50
	0670	9028510	CABLE, LOOP DETECTOR, LEAD-IN	LF	\$1.200	1,085	\$1,302.00
Project J5	P3426 - To	tal					\$57,959.10
Overall - T	otal						\$57,959.10

#### Contract Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3426	0020	6 IN. CONCRETE MEDIAN STRIP	Material			-2.4	\$600.00	(\$1,440.00)
	0020	6 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	2.4	\$600.00	\$1,440.00
	0130	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-62	\$2.00	(\$124.00)
	0140	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-16	\$2.00	(\$32.00)
	0150	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-117	\$3.00	(\$351.00)
	0370	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING AND SIGNALS	Material			-1	\$3,395.00	(\$3,395.00)
	0370	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING AND SIGNALS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	1	\$3,395.00	\$3,395.00
	0430	SH-FLAT SHEET - SIGNAL SIGN	Material			-161.5	\$40.00	(\$6,460.00)
	0660	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MODE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 626.000; Overrun Quantity Balance 6.00.	6	\$3.25	\$19.50
	0660	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MODE	Overrun			-6	\$3.25	(\$19.50)
	0660	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MODE	Material			-626	\$3.25	(\$2,034.50)
	0660	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MODE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	626	\$3.25	\$2,034.50

Revision 4/1/2020 Page 2 of 16



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 30, 2021

Progress Estimate Number					Original Contract Amount	
8	Prime Contractor	Meyer Electric Company, Inc.	Pay Period End	June 30, 2021	Net Change Order Amount	\$500.00
0					Current Contract Amount	\$508,303.50

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3426					Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.			
	0670	CABLE, LOOP DETECTOR, LEAD-IN	Overrun			-5	\$1.20	(\$6.00)
Total								(\$6,973.00)

Revision 4/1/2020 Page 3 of 16



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5P3426	FAF 52-3(25)	Signal improvements	Various	MILLER	at MO 52 and RT CC in E	Eldon; at RT OO and Summi	t Dr. in Holts Summit; at RT C and R
Γotals by .	Job Numbe	ers					
J5P3426					This Estimate	Previous	To Date
J5P3426	Poste	d Item Pay			This Estimate \$57,959.10	Previous \$272,729.61	To Date \$330,688.71
J5P3426		ed Item Pay s Item Adjustme	ents				
J5P3426			ents Gross It	tem Pay	\$57,959.10	\$272,729.61	\$330,688.71
J5P3426	Gross	s Item Adjustmo		tem Pay	\$57,959.10 (\$6,973.00) <b>\$50,986.10</b>	\$272,729.61 \$14,570.85 <b>\$287,300.46</b>	\$330,688.71 \$7,597.85 <b>\$338,286.56</b>
J5P3426	Gross	s Item Adjustmo		tem Pay	\$57,959.10 (\$6,973.00)	\$272,729.61 \$14,570.85 <b>\$287,300.46</b> \$0.00	\$330,688.71 \$7,597.85 <b>\$338,286.56</b> \$0.00
J5P3426	Gross Incen Disin	s Item Adjustme	Gross I	tem Pay	\$57,959.10 (\$6,973.00) <b>\$50,986.10</b> \$0.00	\$272,729.61 \$14,570.85 <b>\$287,300.46</b>	\$330,688.71 \$7,597.85 <b>\$338,286.56</b>

Revision 4/1/2020 Page 4 of 16



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6083006, Project Item Line Number 0020, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Stokez1 AASHTOWare is not showing any remaining test per contract quantity	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6083006, Project Item Line Number 0020, Material Set 608300696, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Stokez1 AASHTOWare is not showing any remaining test per contract quantity	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6083006, Project Item Line Number 0020, Material Set 608300696, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Stokez1 AASHTOWare is not showing any remaining test per contract quantity	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6206000C, Project Item Line Number 0130, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Stokez1 Certification is needed	stokez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6206000C, Project Item Line Number 0130, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Stokez1 Certification is needed	stokez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6206001C, Project Item Line Number 0140, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Stokez1 Certification is needed	stokez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6206001C, Project Item Line Number 0140, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Stokez1 Certification is needed	stokez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6206108A, Project Item Line Number 0150, Material Set 6206108A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Stokez1 Certification is needed	stokez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6206108A, Project Item Line Number 0150, Material Set 6206108A96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Stokez1 Certification is needed	stokez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 6206108A, Project Item Line Number 0150, Material Set 6206108A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Stokez1 Certification is needed	stokez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9018613, Project Item Line Number 0370, Material Set 901861396, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Stokez1 Certification needs to be entered	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9020833, Project Item Line Number 0430, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Stokez1 Certification is needed	stokez1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3426, Item 9028350, Project Item Line Number 0660, Material Set 902835096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Stokez1 Certification needs to be entered	stokez1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-D01, Contract Project J5P3426, Project Item Line Number 0660, Contract Line Item Number 0660, Item 9028350, Minor Item.	System override	stokez1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-D01, Contract Project J5P3426, Project Item Line Number 0670, Contract Line Item Number 0670, Item 9028510, Minor Item.	Stokez1 Change order is needed	stokez1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200515-D01, Contract Project J5P3426, Project Item Line Number 0280, Contract Line Item Number 0280, Item 9013002, Minor Item.	Stokez1 Change order is needed	stokez1	Acknowledged

Revision 4/1/2020 Page 5 of 16



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
00515-D01	J5P3426	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	•	\$13,600.00	\$9,057.6
		0001	0020	6083006	6 IN. CONCRETE MEDIAN STRIP	2.40	0.00	2.40	SQYD	2.40	\$600.00	\$1,440.0
		0001	0030	6161005	CONSTRUCTION SIGNS	903.00	0.00	903.00	SQFT	428.00	\$7.50	\$3,210.0
		0001	0040	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	0.00	\$25.00	\$0.0
		0001	0050	6161010	RELOCATED SIGNS	965.00	0.00	965.00	SQFT	348.00	\$7.00	\$2,436.0
		0001	0060	6161025	CHANNELIZER (TRIM LINE)	260.00	0.00	260.00	EA	95.00	\$25.00	\$2,375.0
		0001	0070	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$925.00	\$0.0
		0001	0080	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,000.00	\$16,000.0
		0001	0090	6169902	MISC.DETECTABLE PEDESTRIAN CHANNELIZING BARRICADE - TYPE II	4.00	0.00	4.00	EA	4.00	\$160.00	\$640.
		0001	0100	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$15,800.00	\$15,800.
		0001	0110	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	6.00	0.00	6.00	EA	2.00	\$600.00	\$1,200
		0001	0120	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	48.00	0.00	48.00	LF	24.00	\$25.00	\$600.
		0001	0130	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	62.00	0.00	62.00	LF	62.00	\$2.00	\$124
		0001	0140	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	16.00	0.00	16.00	LF	16.00	\$2.00	\$32
		0001	0150	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	117.00	0.00	117.00	LF	117.00	\$3.00	\$351
		0001	0160	6207001	PAVEMENT MARKING REMOVAL	137.00	0.00	137.00	LF	115.00	\$3.00	\$345
		0001	0170	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	3.00	0.00	3.00	EA	1.00	\$125.00	\$125
		0001	0180	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$2,800.00	\$1,400
		0001	0190	8061006	ALTERNATE DITCH CHECK	370.00	0.00	370.00	LF	279.00	\$13.00	\$3,627
		0001	0200	8061007A	CURB INLET CHECK	2.00	2.00	4.00	EA	4.00	\$250.00	\$1,000
		0001	0210	8061016	SEDIMENT REMOVAL	37.00	0.00	37.00	CUYD	2.00	\$30.00	\$60
		0020	0220	9011060	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 1	3.00	-3.00	0.00	EA	0.00	\$2,742.00	\$0
		0020	0230	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	1.00	-1.00	0.00	EA	0.00	\$2,313.00	\$0
		0020	0240	9011115	BRACKET ARM, 15 FT. OR 4.6 M	4.00	0.00	4.00	EA	4.00	\$760.00	\$3,040
		0020	0250	9011311	LUMINAIRE, LED-A	7.00	0.00	7.00	EA	0.00	\$569.00	\$0
		0020	0260	9011312	LUMINAIRE, LED-B	4.00	0.00	4.00	EA	0.00	\$610.00	\$0
		0020	0270	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	1.00	\$5,300.00	\$5,300
		0020	0280	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	63.00	0.00	63.00	LF	105.00	\$10.00	\$1,050
		0020	0290	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	116.00	0.00	116.00	LF	74.00	\$11.00	\$814
		0020	0300	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	56.00	0.00	56.00	LF	56.00	\$12.00	\$672
		0020	0310	9014004	CONDUIT, 4 IN. RIGID, PUSHED	266.00	0.00	266.00	LF	266.00	\$18.00	\$4.788
		0020	0320	9016110	PULL BOX. PREFORMED CLASS 1	4.00	0.00	4.00	EA	4.00	\$1,000.00	\$4,000
		0020	0330	9017002	CABLE, 2 AWG 1 CONDUCTOR	240.00	0.00	240.00	LF	237.00	\$2.10	\$497
		0020	0340	9017008	CABLE, 8 AWG 1 CONDUCTOR	1,260.00	0.00	1.260.00	LF	1,255.00	\$1.20	\$1,506
			0350	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	480.00	0.00	480.00	LF	480.00	\$0.85	\$408
		0020										
		0020	0360	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	4.00	\$1,200.00	\$4,800
		0020	0370	9018613	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING AND SIGNALS	3.00	0.00	3.00	EA	1.00	\$3,395.00	\$3,395
		0030	0380	9020113	SIGNAL HEAD, TYPE 3T	1.00	0.00	1.00	EA	0.00	\$739.00	\$0
		0030	0390	9020213	SIGNAL HEAD, TYPE 3S	8.00	0.00	8.00	EA	8.00	\$707.00	\$5,656
		0030	0400	9020513	SIGNAL HEAD, TYPE 3B	22.00	0.00	22.00	EA	12.00	\$857.00	\$10,284
		0030	0410	9020514	SIGNAL HEAD, TYPE 4B	3.00	0.00	3.00	EA	2.00	\$987.00	\$1,974
		0030	0420	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	6.00	0.00	6.00	EA	0.00	\$407.00	\$0
		0030	0430	9020833	SH-FLAT SHEET - SIGNAL SIGN	257.00	0.00	257.00	SQFT	161.50	\$40.00	\$6,460

Revision 4/1/2020 Page 6 of 16



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00515-D01	J5P3426	0030	0440	9020834	SIGNAL SIGN, MOUNTING HARDWARE	40.00	0.00	40.00	EA	22.00	\$195.00	\$4,290.00
		0030	0450	9022708	POST, SIGNAL 8 FT. OR 2.4 M	5.00	0.00	5.00	EA	0.00	\$607.00	\$0.00
		0030	0460	9022715	POST, SIGNAL 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$790.00	\$0.00
		0030	0470	9023115	POST, TYPE CL, 15 FT. ARM OR 4.6 M ARM	1.00	0.00	1.00	EA	1.00	\$6,639.00	\$6,639.00
		0030	0480	9023120	POST, TYPE CL, 20 FT. ARM OR 6.1 M ARM	1.00	0.00	1.00	EA	1.00	\$6,717.00	\$6,717.0
		0030	0490	9023125	POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	2.00	0.00	2.00	EA	2.00	\$6,742.00	\$13,484.00
		0030	0500	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	0.00	\$8,289.00	\$0.00
		0030	0510	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	3.00	0.00	3.00	EA	2.00	\$7,600.00	\$15,200.0
		0030	0520	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	2.00	0.00	2.00	EA	2.00	\$9,711.00	\$19,422.0
		0030	0530	9023445	POST, TYPE BL, LONGEST ARM 45 FT. OR 13.7 M	1.00	0.00	1.00	EA	0.00	\$14,515.00	\$0.0
		0030	0540	9024281	CONTROLLER ASSEMBLY HOUSING, KEYBOARD ENTRY, 8 PHASE NEMA CONTROLLER	3.00	0.00	3.00	EA	2.00	\$15,554.00	\$31,108.0
		0030	0550	9024920	DETECTOR, PUSHBUTTON	6.00	0.00	6.00	EA	0.00	\$206.00	\$0.0
		0030	0560	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	230.00	0.00	230.00	LF	166.00	\$9.50	\$1,577.0
		0030	0570	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	547.00	0.00	547.00	LF	388.00	\$10.00	\$3,880.0
		0030	0580	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	798.00	0.00	798.00	LF	565.00	\$24.00	\$13,560.0
		0030	0590	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	640.00	0.00	640.00	LF	348.00	\$0.85	\$295.8
		0030	0600	9028202	CABLE, 2 AWG 1 CONDUCTOR, POWER	530.00	0.00	530.00	LF	327.00	\$1.80	\$588.6
		0030	0610	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	230.00	0.00	230.00	LF	141.00	\$1.10	\$155.1
		0030	0620	9028302	CABLE, 12 AWG 2 CONDUCTOR	1,170.00	0.00	1,170.00	LF	690.00	\$1.10	\$759.0
		0030	0630	9028308	CABLE, 16 AWG 2 CONDUCTOR	1,500.00	0.00	1,500.00	LF	809.00	\$1.05	\$849.4
		0030	0640	9028310	CABLE, 16 AWG 5 CONDUCTOR	1,500.00	0.00	1,500.00	LF	813.00	\$1.12	\$910.5
		0030	0650	9028311	CABLE, 16 AWG 7 CONDUCTOR	5,200.00	0.00	5,200.00	LF	3,422.00	\$1.20	\$4,106.4
		0030	0660	9028350	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MODE	620.00	0.00	620.00	LF	626.00	\$3.25	\$2,034.5
		0030	0670	9028510	CABLE, LOOP DETECTOR, LEAD-IN	1,080.00	0.00	1,080.00	LF	1,085.00	\$1.20	\$1,302.0
		0030	0680	9028810	PULL BOX, PREFORMED CLASS 1	2.00	0.00	2.00	EA	1.00	\$985.00	\$985.0
		0030	0690	9028811	PULL BOX, PREFORMED CLASS 2	9.00	0.00	9.00	EA	6.00	\$1,350.00	\$8,100.0
		0030	0700	9028812	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	1.00	\$1,600.00	\$1,600.0
		0030	0710	9028816	PULL BOX, PREFORMED CLASS 5	1.00	0.00	1.00	EA	1.00	\$1,600.00	\$1,600.0
		0030	0720	9028824	PULL BOX, CONCRETE, DOUBLE TYPE B	2.00	0.00	2.00	EA	2.00	\$2,900.00	\$5,800.0
		0030	0730	9029100	BASE, CONCRETE	42.20	0.00	42.20	CUYD	27.94	\$1,350.00	\$37,719.0
		0030	0740	9029902	MISC.GRIDSMART V.D.S. Salvage	1.00	0.00	1.00	EA	0.00	\$1,600.00	\$0.0
		0030	0750	9029902	MISC.GRIDSMART Video Detection System	2.00	0.00	2.00	EA	1.00	\$23,000.00	\$23,000.0
		0040	0760	9031010	CONCRETE FOOTINGS, EMBEDDED	0.40	0.00	0.40	CUYD	0.00	\$1,500.00	\$0.0
		0040	0770	9031210	STRUCTURAL STEEL POSTS	50.00	0.00	50.00	LB	0.00	\$25.00	\$0.0
		0040	0780	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	4.00	0.00	4.00	EA	0.00	\$205.00	\$0.0
		0040	0790	9031280	2.5 IN. PSST POST - 12 GA.	64.00	0.00	64.00	LF	0.00	\$11.00	\$0.0
		0040	0800	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	12.00	0.00	12.00	LF	0.00	\$40.00	\$0.0
		0040	0810	9035004A	SH-FLAT SHEET	37.00	0.00	37.00	SQFT	0.00	\$20.00	\$0.0
		0020	5001	9011064	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 3	0.00	4.00	4.00	EA	4.00	\$2,634.75	\$10,539.0
	Project J		otal <u>Value</u>		Date as of Report Generated Date							\$330,688.7
0515-D01 Ove	_				ort Generated Date							\$330,688.7

Revision 4/1/2020 Page 7 of 16



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3426

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	6/29/21	6/30/21	0.33	LS	Rte. C and CC intersection					
0120	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	6/23/21	6/30/21	12.00	LF	Rte. CC LM 3+48					
0130	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	6/23/21	6/30/21	62.00	LF	Rte. C 28' at LM 6+50 to 6+78 34' at LM 7+19 to 7+53					
0140	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	6/23/21	6/30/21	16.00	LF	Rte. C LM 3+48 to 3+56					
0150	6206108A	8 IN. WHITE WATERBORNE PAVEMENT MARKING	6/23/21	6/30/21	117.00	LF	Rte. C 50' at LM 6+50 to 6+78 Lt 67" at LM 7+19 to 7+53 Rt					
0160	6207001	PAVEMENT MARKING REMOVAL	6/23/21	6/30/21	111.00	LF	Rte. C 52' LM 6+50 to 6+78 Lt 59' LM 7+19 to 7+53 Rt					
0390	9020213	SIGNAL HEAD, TYPE 3S	6/17/21	6/30/21	1.00	EA	Rte. C and CC Post #4 signal head #22					
			6/18/21	6/30/21	3.00	EA	Rte. C and CC 1 at Post 1 signal head #82 1 at Post 2 signal head #62 1 at Post 3 signal head #42					
0400	9020513	SIGNAL HEAD, TYPE 3B	6/17/21	6/30/21	1.00	EA	Rte. C and CC Post #4 signal head #21					
			6/18/21	6/30/21	3.00	EA	Rte. C and CC 1 at post 1 signal head 81 1 at post 2 signal head 61 1 at post 3 signal head 41					
0410	9020514	SIGNAL HEAD, TYPE 4B	6/17/21	6/30/21	1.00	EA	Rte. C and CC Post #4 signal head 50					
			6/18/21	6/30/21	1.00	EA	Rte. C and CC 1 at post 2 signal head 10					
0430	9020833	SH-FLAT SHEET - SIGNAL SIGN	6/21/21	6/30/21	71.50	SQFT	Rte. C and CC R3-5L (7.5 SQFT EA)-1 on post 2 and 1 on post 4 D3-1 (7.5 SQFT EA) - 1 on post 1 and 1 on post 3 D3-1b (8.25 SQFT EA) - 1 on post 2 and 1 on post 4 R10-12 (5 SQFT EA) - 1 on post 1 and 1 on post 3 R10-27A (7.5 SQFT EA) - 1 on post 2 and 1 on post 4					
0440	9020834	SIGNAL SIGN, MOUNTING HARDWARE	6/21/21	6/30/21	10.00	EA	Rte. C and CC R3-5L - 1 on post 2 and 1 on post 4 D3-1 - 1 on post 1 and 1 on post 3 D3-1b - 1 on post 2 and 1 on post 4 R10-12 - 1 on post 1 and 1 on post 4 R10-12 - 1 on post 1 and 1 on post 3 R10-27A - 1 on post 2 and 1 on post 4					
0470	9023115	POST, TYPE CL, 15 FT. ARM OR 4.6 M ARM	6/18/21	6/30/21	1.00	EA	Rte. C and CC Post 1 at LM 6+93 Rt					
0480	9023120	POST, TYPE CL, 20 FT. ARM OR 6.1 M ARM	6/18/21	6/30/21	1.00	EA	Rte. C and CC Post 2 at LM 7+07 Lt					
0520	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	6/17/21	6/30/21	1.00	EA	Rte. C and CC LM 7+49 Lt Post 4					
			6/18/21	6/30/21	1.00	EA	Rte. C and CC Post 3 at LM 7+80 Rt					
0590	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRAC	6/18/21	6/30/21	348.00	LF	Rte. C and CC 78 at Luminaire #1 78 at Luminaire #3 96 at Luminaire #2 96 at Luminaire #2					
0600	9028202	CABLE, 2 AWG 1 CONDUCTOR, POWER	6/17/21	6/30/21	153.00	LF	Rte. C and CC Power pole to power supply box					
0610	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	6/17/21	6/30/21	112.00	LF	Rte. C and CC Power supply to traffic controller					
0620	9028302	CABLE, 12 AWG 2 CONDUCTOR	6/17/21	6/30/21	690.00	LF	Rte. C and CC 284' at Controller to Lum # 3 174' at Controller to Lum # 2 158' at Controller to Lum # 4 74' at Controller to Lum # 1					
0650	9028311	CABLE, 16 AWG 7 CONDUCTOR	6/17/21	6/30/21	1,402.00	LF	Rte. C and CC 315 from Controller to signal #41 21 from signal #41 to signal #42 218 from Controller to signal #61 35 from signal #61 to signal #62 230 from Controller to signal #10 201 from Controller to signal #22 36 from signal #21 to signal #22 14 from Controller to signal #85 108 from Controller to signal #81 24 from Signal #21 to signal #81					
0660	9028350	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MOD	6/29/21	6/30/21	626.00	LF	Rte. CC controller to Rte. 179S-RP controller					
0670	9028510	CABLE, LOOP DETECTOR, LEAD-IN	6/18/21	6/30/21	1,085.00	LF	Rte. C and CC 702' from controller to PB#8 383' from controller to PB #9					

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 8 of 16



		_				_	_		_
oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3426	0020	6 IN. CONCRETE MEDIAN STRIP	Material		3	Apr 19, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Apr 19, 2021	SYSTEM	(\$1,440.00)	
					4	May 3, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 3, 2021	SYSTEM	(\$1,440.00)	
					5	May 17, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	May 17, 2021	SYSTEM	(\$1,440.00)	
					6	Jun 1, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 1, 2021	SYSTEM	(\$1,440.00)	
					7	Jun 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jun 16, 2021	SYSTEM	(\$1,440.00)	
					8	Jun 30, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jun 30, 2021	SYSTEM	(\$1,440.00)	
				- Total				\$0.00	
			Material - Tota	l				\$0.00	
	0020 -	Total						\$0.00	
	0120	PREF THERMO PVMT MARK,	Material		5	May 17, 2021	SYSTEM	(\$300.00)	
		24 IN WHIT			6	Jun 1, 2021	SYSTEM	(\$300.00)	
				- Total				(\$600.00)	
			Material - Tota	l				(\$600.00)	
			MaterialCredit		6	Jun 1, 2021	SYSTEM	\$300.00	
					7	Jun 16, 2021	SYSTEM	\$300.00	
			M ( 1 10 11	- Total				\$600.00	
			MaterialCredit	- I otal				\$600.00	
	0120 - 0130		Material		8	Jun 30, 2021	SYSTEM	\$0.00 (\$124.00)	
		PAVEMENT MARKING		- Total				(\$124.00)	
		11 11 11 11	Material - Tota					(\$124.00)	
	0130 -	Total						(\$124.00)	
	0140	4 IN. YELLOW WATERBORNE	Material		8	Jun 30, 2021	SYSTEM	(\$32.00)	
		PAVEMENT MARKING		- Total				(\$32.00)	
		11 11 11 11	Material - Tota					(\$32.00)	
	0140 -	Total						(\$32.00)	
	0150	8 IN. WHITE WATERBORNE PAVEMENT	Material		8	Jun 30, 2021	SYSTEM	(\$351.00)	
		MARKING		- Total				(\$351.00)	
			Material - Tota					(\$351.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3426	0150 -	· Total						(\$351.00)	
	0190	ALTERNATE DITCH CHECK	Material		3	Apr 19, 2021	SYSTEM	(\$1,287.00)	
				- Total				(\$1,287.00)	
			Material - Tota					(\$1,287.00)	
			MaterialCredit		4	May 3, 2021	SYSTEM	\$1,287.00	
				- Total				\$1,287.00	
			MaterialCredit	- Total				\$1,287.00	
	0190 -	Total						\$0.00	
	0200	CURB INLET CHECK	Material		3	Apr 19, 2021	SYSTEM	(\$1,000.00)	
				- Total				(\$1,000.00)	
			Material - Tota	l				(\$1,000.00)	
			MaterialCredit		4	May 3, 2021	SYSTEM	\$1,000.00	
				- Total				\$1,000.00	
			MaterialCredit	- Total				\$1,000.00	
			Overrun	Overrun	3	Apr 19, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 4.000; Overrun Quantity Balance 2.00.
					3	Apr 19, 2021	SYSTEM	(\$500.00)	
					4	May 3, 2021	SYSTEM	(\$500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	May 17, 2021	SYSTEM	\$500.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',250.00000 - 250.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0200 -	· Total						\$0.00	
	0270	BASE MOUNTED CONTROL	Material		4	May 3, 2021	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		STATION			4	May 3, 2021	SYSTEM	(\$5,300.00)	
					5	May 17, 2021	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	May 17, 2021	SYSTEM	(\$5,300.00)	
					6	Jun 1, 2021	SYSTEM	\$5,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Jun 1, 2021	SYSTEM	(\$5,300.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0270 -	· Total						\$0.00	
	0280	CONDUIT, 2 IN. RIGID, IN	Overrun	Overrun	4	May 3, 2021	SYSTEM	(\$420.00)	
		TRENCH		Overrun - T	otal			(\$420.00)	
			Overrun - Tota					(\$420.00)	
	0280	· Total	1010					(\$420.00)	
	0330	CABLE, 2 AWG	Material		4	May 3, 2021	SYSTEM	\$497.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment
		CONDUCTOR			4	May 3,	SYSTEM	(\$497.70)	Estimate Exception 8 on the current Payment Estimate.
						2021			



March   Marc				I	1				
SPEAZE   CONDUCTOR	Project	Line	Description		Adjustment			Amount	Remarks
CONDUCTOR					Туре				
2021	J5P3426	0330	1	Material		5	SYSTEM	\$497.70	Estimate Item Adjustment (0003) due to user stokez1 overridding Payment
2021						5	SYSTEM	(\$497.70)	
1-Total   1-To						6	SYSTEM	\$497.70	Estimate Item Adjustment (0003) due to user stokez1 overridding Payment
						6	SYSTEM	(\$497.70)	
					- Total			\$0.00	
OS40   CABLE, 8 AWG   CONDUCTOR				Material - Tota	ıl			\$0.00	
CONDUCTOR		0330 -	- Total					\$0.00	
2021   5		0340	1	Material		4	SYSTEM	\$1,506.00	Estimate Item Adjustment (0009) due to user stokez1 overridding Payment
2021   SYSTEM   S1,506,000   SYSTEM   S1,5						4	SYSTEM	(\$1,506.00)	
2021   6						5	SYSTEM	\$1,506.00	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment
2021   Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.   2021						5	SYSTEM	(\$1,506.00)	
2021   S0.00     Material - Total   S0.00     S0.00						6	SYSTEM	\$1,506.00	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment
Naterial - Total   S0.00   S0.00   S0.00   S0.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Estimate Estimate Exception 11 on the current Payment Estimate Exception 11 on the current Payment Estimate Estimate Estimate Exception 11 on the current Payment Estimate Estimate Estimate Exception 12 on the current Payment Estimate Estimate Estimate Estimate End Adjustment (001) due to user stokez1 overridding Payment Estimate Estimate Exception 12 on the current Payment Estimate Estimate Estimate Exception 12 on the current Payment Estimate Estimate Estimate Exception 12 on the current Payment Estimat						6	SYSTEM	(\$1,506.00)	
CABLE, 10					- Total			\$0.00	
A				Material - Tota	ıl			\$0.00	
2021   Estimate Item Adjustment (0010) due to user stokezt overridding Payment Estimate   Estimate Exception 10 on the current Payment Estimate   Estimate Exception 10 on the current Payment Estimate   Estimate Exception 10 on the current Payment Estimate   Estimate Estimate   Estimate Exception 10 on the current Payment Estimate   Estimate Estimate   Estimat		0340 -	- Total					\$0.00	
BRACKE		0350	AWG 1 CONDUCTOR,	Material		4	SYSTEM	\$408.00	Estimate Item Adjustment (0010) due to user stokez1 overridding Payment
2021   Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						4	SYSTEM	(\$408.00)	
2021						5	SYSTEM	\$408.00	Estimate Item Adjustment (0009) due to user stokez1 overridding Payment
Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  -Total  S0.00  Material - Total  S0.00  Material - Total  S0.00  O370 POWER SUPPLY ASSEMBLY, TYPE 2, 240/120  ASSEMBLY, TYPE 2, 240/120  May 17, 2021  SYSTEM \$3,395.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.  SYSTEM \$3,395.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.  May 17, 2021  SYSTEM \$3,395.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.  SYSTEM \$3,395.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate Estimate Exception 12 on the current Payment Estimate.						5	SYSTEM	(\$408.00)	
Total  Total  S0.00  Material - Total  S0.00  POWER SUPPLY ASSEMBLY, TYPE 2, 240/120  Type 2, 240/120  Type 2, 240/120  Type 2, 240/120  Type 3, 395.00  Material - Total  S0.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  May 17, SYSTEM (\$3,395.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.						6	SYSTEM	\$408.00	Estimate Item Adjustment (0009) due to user stokez1 overridding Payment
0350 - Total  0370 POWER SUPPLY ASSEMBLY, TYPE 2, 240/120  50.00  Material - Total  4 May 3, 2021 \$\$3,395.00\$  This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.  4 May 3, 2021 \$\$4 May 3, 2021 \$\$1 May 17, 2021 \$\$1 May 17, 2021 \$\$1 May 17, 2021 \$\$2 May 17, 2021 \$\$3,395.00\$  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  5 May 17, 2021  6 Jun 1, 2021  SYSTEM \$3,395.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.						6	SYSTEM	(\$408.00)	
\$0.00  POWER SUPPLY ASSEMBLY, TYPE 2, 240/120  ASSEMBLY, TYPE 2, 240/120  By the first adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.  A May 3, 2021  By the first adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.  A May 3, 2021  System (\$3,395.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.  May 17, 2021  System (\$3,395.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.  A May 3, 2021  System (\$3,395.00)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.					- Total			\$0.00	
POWER SUPPLY ASSEMBLY, TYPE 2, 240/120  4 May 3, 2021  5 May 17, 2021  5 May 17, 2021  5 May 17, 2021  5 May 17, 2021  6 Jun 1, 2021  SYSTEM \$3,395.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.  4 May 3, 2021  5 May 17, 2021  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  5 May 17, 2021  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.				Material - Tota	ıl			\$0.00	
SUPPLY ASSEMBLY, TYPE 2, 240/120  4 May 3, 2021  5 May 17, 2021  5 May 17, 2021  6 Jun 1, 2021  SYSTEM 2021  Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.  5 May 17, 2021  SYSTEM (\$3,395.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.		0350	- Total					\$0.00	
4 May 3, 2021 \$YSTEM (\$3,395.00)  5 May 17, 2021 \$YSTEM \$3,395.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  5 May 17, 2021 \$YSTEM (\$3,395.00)  6 Jun 1, 2021 \$YSTEM \$3,395.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.		0370	SUPPLY ASSEMBLY,	Material		4	SYSTEM	\$3,395.00	Estimate Item Adjustment (0011) due to user stokez1 overridding Payment
Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  5 May 17, 2021  6 Jun 1, 2021  SYSTEM \$3,395.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			ASSEMBLY, TYPE 2,			4	SYSTEM	(\$3,395.00)	
2021  6 Jun 1, 2021  \$3,395.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.						5	SYSTEM	\$3,395.00	Estimate Item Adjustment (0005) due to user stokez1 overridding Payment
Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.						5	SYSTEM	(\$3,395.00)	
6 Jun 1, SYSTEM (\$3,395.00)						6	SYSTEM	\$3,395.00	Estimate Item Adjustment (0005) due to user stokez1 overridding Payment
									Estimate Exception 12 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J5P3426	0370	POWER	Material			2021										
		SUPPLY ASSEMBLY, TYPE 2, 240/120			7	Jun 16, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.							
					7	Jun 16, 2021	SYSTEM	(\$3,395.00)								
					8	Jun 30, 2021	SYSTEM	\$3,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.							
					8	Jun 30, 2021	SYSTEM	(\$3,395.00)								
				- Total				\$0.00								
			Material - Tota	ı				\$0.00								
	0370 -	- Total						\$0.00								
	0390	SIGNAL HEAD, TYPE 3S	Material		4	May 3, 2021	SYSTEM	\$2,828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.							
					4	May 3, 2021	SYSTEM	(\$2,828.00)								
					5	May 17, 2021	SYSTEM	\$2,828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.							
					5	May 17, 2021	SYSTEM	(\$2,828.00)								
					6	Jun 1, 2021	SYSTEM	\$2,828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.							
					6	Jun 1, 2021	SYSTEM	(\$2,828.00)								
											- Total				\$0.00	
			Material - Tota	ı				\$0.00								
	0390 -	· Total						\$0.00								
	0400	SIGNAL HEAD, TYPE 3B	Material		4	May 3, 2021	SYSTEM	\$6,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.							
					4	May 3, 2021	SYSTEM	(\$6,856.00)								
					5	May 17, 2021	SYSTEM	\$6,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
					5	May 17, 2021	SYSTEM	(\$6,856.00)								
							6	Jun 1, 2021	SYSTEM	\$6,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.					
					6	Jun 1, 2021	SYSTEM	(\$6,856.00)								
				- Total				\$0.00								
			Material - Tota	d				\$0.00								
	0400 -	- Total						\$0.00								
	0430	SH-FLAT SHEET - SIGNAL SIGN	Material		4	May 3, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
					4	May 3, 2021	SYSTEM	(\$3,600.00)								
					5	May 17, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate.							
					5	May 17, 2021	SYSTEM	(\$3,600.00)								
					6	Jun 1, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment							



USP-9426   Modernal   Foundation   September   Septe	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
SPAND   0430   SH-RT A   Material	,				Adjustment					
7	J5P3426	0430	SHEET -	Material	71	6		SYSTEM	(\$3,600.00)	
Section   Sect			SIGNAL SIGN			7		SYSTEM	\$3,600.00	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment
1-Total   168,469.00						7		SYSTEM	(\$3,600.00)	
Material - Total						8		SYSTEM	(\$6,460.00)	
A					- Total				(\$6,460.00)	
CABLE_2_AWG   Moterial   CONDUCTOR.				Material - Tota	ıl				(\$6,460.00)	
CABLE_2 AWG   National		0430 -	· Total						(\$6,460.00)	
4		0600	1	Material		4		SYSTEM		Estimate Item Adjustment (0015) due to user stokez1 overridding Payment
Estimate Exception 1 for on the current Payment Estimate			POWER			4		SYSTEM	(\$313.20)	
2021   SVSTEM   S313.20   This adjustment offsets the original system-generated Material Payment Estimate Estimate Exception 16 on the current Payment Estimate Estimate Exception 16 on the current Payment Estimate Estimate Exception 16 on the current Payment Payment Payment Estimate Exception 16 on the current Payment Payment Payment Payment Payment Payment Estimate Exception 16 on the current Payment Estimate Exception 16 on the current Payment Estimate Exception 17 on the current Payment Estimate Payment Paym						5		SYSTEM	\$313.20	Estimate Item Adjustment (0014) due to user stokez1 overridding Payment
2021   Estimate Item Adjustment (00'13) due to user stokez to verridding Payment						5		SYSTEM	(\$313.20)	
Condition   Cable   Baw   South   So						6		SYSTEM	\$313.20	Estimate Item Adjustment (0013) due to user stokez1 overridding Payment
Material - Total						6		SYSTEM	(\$313.20)	
1					- Total				\$0.00	
A				Material - Tota	ıl				\$0.00	
CONDUCTOR, POWER    2021   Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.		0600 -	· Total						\$0.00	
A		0610	1	Material		4		SYSTEM	\$31.90	Estimate Item Adjustment (0016) due to user stokez1 overridding Payment
2021   Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.						4		SYSTEM	(\$31.90)	
2021						5		SYSTEM	\$31.90	Estimate Item Adjustment (0015) due to user stokez1 overridding Payment
Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.						5		SYSTEM	(\$31.90)	
CABLE, 16 AWG 2 CONDUCTOR   Material - Total   Substitute   Substitu						6		SYSTEM	\$31.90	
Material - Total   S0.00						6				
CABLE, 16 AWG 2 CONDUCTOR  AWG 2 CONDUCTOR  AWG 3 CONDUCTOR  AWG 4 AWG 5 CONDUCTOR  AWG 5 CONDUCTOR  AWG 5 CONDUCTOR  AWG 6 CONDUCTOR  AWG 7 CONDUCTOR  AWG 7 CONDUCTOR  AWG 8 AWG 8 AWG 9 CONDUCTOR  AWG 9 CONDUC						6		SYSTEM	(\$31.90)	
CABLE, 16 AWG 2 CONDUCTOR  Material  4 May 3, 2021  SYSTEM  \$849.45  This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate.  4 May 3, 2021  5 May 17, 2021  SYSTEM  \$849.45  This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate.  5 May 17, 2021  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  5 May 17, 2021  SYSTEM  \$849.45  This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate Estimate Exception 18 on the current Payment Estimate.					- Total	6		SYSTEM	( , ,	
AWG 2 CONDUCTOR  2021  Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  4 May 3, 2021  5 May 17, 2021  5 May 17, 2021  5 May 17, 2021  5 May 17, 2021  6 Jun 1, 2021  SYSTEM  (\$849.45)  This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate.  5 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate.  6 Jun 1, SYSTEM  (\$849.45)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.				Material - Tota		6		SYSTEM	\$0.00	
5 May 17, 2021 SYSTEM \$849.45 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  5 May 17, 2021 (\$849.45)  6 Jun 1, 2021 SYSTEM \$849.45 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		0610	· Total	Material - Tota		6		SYSTEM	\$0.00 \$0.00	
Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  5 May 17, 2021 (\$849.45)  6 Jun 1, 2021 \$849.45 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  6 Jun 1, SYSTEM (\$849.45)			CABLE, 16 AWG 2				2021 May 3,		\$0.00 \$0.00 \$0.00	Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment
2021  6 Jun 1, 2021  8849.45 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  6 Jun 1, SYSTEM (\$849.45)			CABLE, 16 AWG 2			4	May 3, 2021	SYSTEM	\$0.00 \$0.00 \$0.00 \$849.45	Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment
Estimate Item Adjustment (0015) dué to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  6 Jun 1, SYSTEM (\$849.45)			CABLE, 16 AWG 2			4	May 3, 2021  May 3, 2021  May 17,	SYSTEM	\$0.00 \$0.00 \$0.00 \$849.45 (\$849.45)	Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment
			CABLE, 16 AWG 2			4 4 5	May 3, 2021  May 3, 2021  May 17, 2021  May 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$849.45 (\$849.45) \$849.45	Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment
			CABLE, 16 AWG 2			4 4 5 5 5	May 3, 2021  May 3, 2021  May 17, 2021  May 17, 2021  Jun 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$849.45 (\$849.45) \$849.45	Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
126	0630	CABLE, 16 AWG 2	Material	- Total				\$0.00	
		CONDUCTOR	Material - Tota					\$0.00	
	0630 -	Total						\$0.00	
	0640	CABLE, 16 AWG 5 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$910.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user stokez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					4	May 3, 2021	SYSTEM	(\$910.56)	
					5	May 17, 2021	SYSTEM	\$910.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	May 17, 2021	SYSTEM	(\$910.56)	
					6	Jun 1, 2021	SYSTEM	\$910.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Jun 1, 2021	SYSTEM	(\$910.56)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0640 -	Total						\$0.00	
	0650	CABLE, 16 AWG 7 CONDUCTOR	Material		4	May 3, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user stokez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					4	May 3, 2021	SYSTEM	(\$2,424.00)	
					5	May 17, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					5	May 17, 2021	SYSTEM	(\$2,424.00)	
					6	Jun 1, 2021	SYSTEM	\$2,424.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					6	Jun 1, 2021	SYSTEM	(\$2,424.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0650 -	Total						\$0.00	
	0660	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MOD	Material		8	Jun 30, 2021	SYSTEM	\$2,034.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		WOD			8	Jun 30, 2021	SYSTEM	(\$2,034.50)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Overrun	Overrun	8	Jun 30, 2021	SYSTEM	\$19.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 626.000; Overrun Quantity Balance 6.00.
					8	Jun 30, 2021	SYSTEM	(\$19.50)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0660 -	Total						\$0.00	
	0070	CABLE, LOOP	Overrun	Overrun	8	Jun 30, 2021	SYSTEM	(\$6.00)	
	0670	DETECTOR,							
	0670	LEAD-IN		Overrun - T	otal			(\$6.00)	
	0670		Overrun - Tota		otal			(\$6.00) (\$6.00)	



SP3420   C72	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3	J5P3426	0720	CONCRETE, DOUBLE TYPE	Material		3		SYSTEM	\$5,800.00	Estimate Item Adjustment (0005) due to user stokez1 overridding Payment
			В			3		SYSTEM	(\$5,800.00)	
2021   5   May 17   SYSTEM   \$3,800.00   This adjustment offsets the original system-generated Material Payment   Estimate Ecosption 21 on the outrent Payment Estimate						4		SYSTEM	\$5,800.00	Estimate Item Adjustment (0020) due to user stokez1 overridding Payment
2021   Setting   Payment   Estinate   Payment   Estinate   Payment   Payme						4		SYSTEM	(\$5,800.00)	
						5		SYSTEM	\$5,800.00	Estimate Item Adjustment (0012) due to user stokez1 overridding Payment
Material - Total						5		SYSTEM	(\$5,800.00)	
1730   CONCRETE					- Total				\$0.00	
Page   Concrete   Co				Material - Tota	ıl				\$0.00	
CONCRETE     2021		0720 -	Total						\$0.00	
A		0730		Material		3		SYSTEM	\$18,508.50	Estimate Item Adjustment (0006) due to user stokez1 overridding Payment
2021   Estimate Item Adjustment (0027) due to user stokez 1 overridding Payment Estimate Exception 22 on the current Payment Estimate.						3		SYSTEM	(\$18,508.50)	
2021   5   May 17,   SYSTEM   \$22,923.00   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokect overridding Payment Estimate Item Adjustment (0013) due to user stokect overridding Payment Estimate Exception 23 on the current Payment Estimate Estimate Exception 23 on the current Payment Estimate Item Adjustment (0012) due to user stokect overridding Payment Estimate Item Adjustment (0012) due to user stokect overridding Payment Estimate Item Adjustment (0012) due to user stokect overridding Payment Estimate Item Adjustment (0012) due to user stokect overridding Payment Estimate Item Adjustment (0012) due to user stokect overridding Payment Estimate Item Adjustment (0013) due to user stokect overridding Payment Estimate Item Adjustment (0013) due to user stokect overridding Payment Estimate Item Adjustment (0013) due to user stokect overridding Payment Estimate Item Adjustment (0013) due to user stokect overridding Payment Estimate Item Adjustment (0013) due to user stokect overridding Payment Item Adjustment (0013) due to user stokect overridding Payment Item Adjustment Item Adj						4		SYSTEM	\$18,508.50	Estimate Item Adjustment (0021) due to user stokez1 overridding Payment
2021   Estimate tem Adjustment (0013) due to user stokezt overridding Payment Estimate Exception 23 on the current Payment Estimate.						4		SYSTEM	(\$18,508.50)	
2021   6						5		SYSTEM	\$22,923.00	Estimate Item Adjustment (0013) due to user stokez1 overridding Payment
2021   Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 21 on the current Payment Estimate.						5		SYSTEM	(\$22,923.00)	
2021   7						6		SYSTEM	\$29,416.50	Estimate Item Adjustment (0012) due to user stokez1 overridding Payment
2021   Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.   Total   S0.00						6		SYSTEM	(\$29,416.50)	
Total   \$0.00						7		SYSTEM	\$37,719.00	Estimate Item Adjustment (0005) due to user stokez1 overridding Payment
Material - Total   \$0.00						7		SYSTEM	(\$37,719.00)	
O750 - Total   S0.00					- Total				\$0.00	
MISC. Construction Stockpile  - Total  Construction Stockpile - Total  Construction Stockpile - Total  Construction Stockpile - Total  Construction Stockpile - Total  Construction Stockpile - Total  Construction Stockpile STMI  - Total  Construction Stockpile STMI  - Total  S37,990.00  Construction Stockpile STMI - Total  S37,990.00  Construction Stockpile STMI - Total  S14,990.85  S14,990.85  LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT  Aderial  Aderial  7 Jun 16, 2021  SYSTEM \$10,539.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  - Total  SYSTEM \$10,539.00  - Total  SYSTEM \$10,539.00				Material - Tota	ıl				\$0.00	
Stockpile 2021 (\$22,999.15)  Construction Stockpile - Total (\$22,999.15)  Construction Stockpile - Total (\$22,999.15)  Construction Stockpile STMI - Total \$37,990.00 Payment Estimate Item Adjustment generated Stockpile Transaction  Construction Stockpile STMI - Total \$37,990.00  Construction Stockpile STMI - Total \$37,990.00  Construction Stockpile STMI - Total \$37,990.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  Total \$0.00		0730 -	Total						\$0.00	
Construction Stockpile - Total  Construction Stockpile STMI  - Total  Construction Stockpile STMI  - Total  Construction Stockpile STMI - Total  S37,990.00  Construction Stockpile STMI - Total  S37,990.00  Construction Stockpile STMI - Total  S14,990.85  S10,539.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  - Total  - Total  S22,999.15)  Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  - Total  S0.00		0750	MISC.			4		SYSTEM	(\$22,999.15)	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile STMI  - Total  Construction Stockpile STMI - Total  Construction Stockpile STMI - Total  Construction Stockpile STMI - Total  S37,990.00  Construction Stockpile STMI - Total  \$37,990.00  S47,990.00  S14,990.85  S14,990.85  S14,990.85  S14,990.85  S17,990.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  Total  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SUD,539.00  SYSTEM  SUD,539.00  SYSTEM  SUD,539.00  SYSTEM  SUD,539.00					- Total				(\$22,999.15)	
Stockpile   STM    -Total   \$37,990.00				Construction	Stockpile - To	otal			(\$22,999.15)	
Construction Stockpile STMI - Total   \$37,990.00				Stockpile		1		SYSTEM	\$37,990.00	Payment Estimate Item Adjustment generated Stockpile Transaction
System   S				STIVII	- Total				\$37,990.00	
5001 LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT    Total   SYSTEM   S10,539.00   This adjustment offsets the original system-generated Material Payment				Construction	Stockpile STI	/II - Total			\$37,990.00	
POLE, 45 FT. OR 13.5 M, TYPE AT  2021  2021  Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  7 Jun 16, 2021  SYSTEM (\$10,539.00)		0750 -	Total						\$14,990.85	
- Total SYSTEM (\$10,539.00) - Total \$0.00		5001	POLE, 45 FT. OR 13.5 M,	Material		7		SYSTEM	\$10,539.00	Estimate Item Adjustment (0006) due to user stokez1 overridding Payment
			TYPE AT			7		SYSTEM	(\$10,539.00)	
Material - Total \$0.00					- Total				\$0.00	
				Material - Tota	ıl				\$0.00	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3426	5001 -	Total						\$0.00	
J5P3426	- Total							\$7,597.85	
Overall -	Total							\$7,597.85	