72.70%



# Missouri Department of Transportation Contractor's Pay Estimate Summary

October 1, 2021

Pay Estimate Created Date: February 1, 2021

Progress Estimate Number	Contract ID	200515-F10	Pay Period Start		Original Contract Amou	nt \$3,406,354.96
12	Prime Contractor	Lamke Trenching & Excavating, Inc.	Pay Period End	February 1, 2021	Net Change Order Amount	\$0.00
i					Current Contract Amour	nt \$3,406,354.96

Original Completion Date		Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete			
February 3, 2021	ary 3, 2021 Reviewed and Approved at the Central Office Controllers Office Level by						
February 1, 2021							
February 1, 2021							
Approval Date					By User		

No Milestones Exist for Contract

October 1, 2021

Contract Total Pa	y For Estimate No. 12			
		This Estimate	Previous	To Date
200515-F10				
	Total Posted Items Pay	\$29,971.05	\$2,446,493.86	\$2,476,464.91
	Gross Item Adjustments	\$0.00	\$317.73	\$317.73
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$2,446,811.59	\$2,476,782.64
<b>Contract Total Pa</b>	yable This Estimate:	\$29,971.05		

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J6S3258	0070	6039902	WATER	EA	\$225.000	10	\$2,250.00		
	0800	6042010	ADJUSTING MANHOLE	EA	\$500.000	3	\$1,500.00		
	0140	6089902	MISC.ADA CURB RAMP	EA	\$2,250.000	4	\$9,000.00		
	0530	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	LF	\$11.400	20	\$228.00		
	0540	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	LF	\$32.800	135	\$4,428.00		
	0590	9028811	PULL BOX, PREFORMED CLASS 2	EA	\$1,221.000	2	\$2,442.00		
	0610	9029100	BASE, CONCRETE	CUYD	\$1,555.000	6.51	\$10,123.05		
Project J6S325	Project J6S3258 - Total								
Overall - Total	Overall - Total								

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjusti	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3258	0020	EMBANKMENT IN PLACE	Material			-1,987	\$28.56	(\$56,748.72)
	0020	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,987	\$28.56	\$56,748.72
	0120	6 IN. CONCRETE MEDIAN STRIP	Material			-13,452	\$49.50	(\$665,874.00)
	0120	6 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	13,452	\$49.50	\$665,874.00
	0130	8 IN. CONCRETE MEDIAN	Overrun		Averaged Price Adjustment from this item on	-311.33	\$55.00	(\$17,123.15)

Revision 4/1/2020 Page 1 of 23



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 1, 2021

Progress Estimate Number
12 Contract ID 200515-F10 Start 2021 Original Contract Amount \$3,406,354.96
Prime Contractor Lamke Trenching & Excavating, Inc.
Pay Period Start 2021 Original Contract Amount \$3,406,354.96
Pay Period End February 1, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$3,406,354.96

ct er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
58		STRIP			all previous payment estimates of '0.00000' is applied (if non-zero).			
	0130	8 IN. CONCRETE MEDIAN STRIP	Material			-2,209.93	\$55.00	(\$121,546.15
	0130	8 IN. CONCRETE MEDIAN STRIP	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.	311.33	\$55.00	\$17,123.15
	0130	8 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	2,209.93	\$55.00	\$121,546.15
	0135	CONCRETE SIDEWALK, 4 IN.	Material			-321.7	\$54.00	(\$17,371.80
	0135	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	321.7	\$54.00	\$17,371.80
	0140	MISC.	Material			-28	\$2,250.00	(\$63,000.00
	0140	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	28	\$2,250.00	\$63,000.00
	0160	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material			-329	\$15.00	(\$4,935.00)
	0160	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	329	\$15.00	\$4,935.00
	0240	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-476	\$20.00	(\$9,520.00)
	0240	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	476	\$20.00	\$9,520.00
	0250	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material			-113	\$20.00	(\$2,260.00)
	0250	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	113	\$20.00	\$2,260.00
	0290	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-8,077	\$0.11	(\$888.47)
	0290	4 IN. WHITE STANDARD	Material		This adjustment offsets the original system-	8,077	\$0.11	\$888.47

Revision 4/1/2020 Page 2 of 23



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 1, 2021

Progress Estimate Number
12 Contract ID 200515-F10 Pay Period Start 2021 Original Contract Amount \$3,406,354.96

Prime Contractor Inc. Pay Period Start 2021 Net Change Order Amount \$0.00

Pay Period End February 1, 2021 Net Change Order Amount \$0.00

Current Contract Amount \$3,406,354.96

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3258		WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS			generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.			
	0300	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-8,039	\$0.11	(\$884.29)
	0300	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	8,039	\$0.11	\$884.29
	0370	TOPSOIL	Material			-1,609	\$35.00	(\$56,315.00)
	0370	TOPSOIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	1,609	\$35.00	\$56,315.00
	0380	SEEDING - COOL SEASON MIXTURES	Material			-2.3	\$5,800.00	(\$13,340.00)
	0380	SEEDING - COOL SEASON MIXTURES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	2.3	\$5,800.00	\$13,340.00
	0390	TEMPORARY SEEDING AND MULCHING	Material			-0.8	\$2,200.00	(\$1,760.00)
	0390	TEMPORARY SEEDING AND MULCHING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	0.8	\$2,200.00	\$1,760.00
	0610	BASE, CONCRETE	Overrun			-1.97	\$1,555.00	(\$3,063.35)
	0610	BASE, CONCRETE	Material			-14.07	\$1,555.00	(\$21,878.85)
	0610	BASE, CONCRETE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97.	1.97	\$1,555.00	\$3,063.35
	0610	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	14.07	\$1,555.00	\$21,878.85
	0670	CONCRETE FOOTINGS, EMBEDDED	Material			-9.1	\$2,300.00	(\$20,930.00)
	0670	CONCRETE FOOTINGS, EMBEDDED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	9.1	\$2,300.00	\$20,930.00
Total								\$0.00

Revision 4/1/2020 Page 3 of 23



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work					
J6S3258	FAF 115-1(46)	Microsurface and ADA improvements	115	ST LOUIS CITY	from St. Louis city limits to Natural Bridge					
otals by J	lob Number	rs .								
J6S3258					This Fetimate Provious To Date					

Totals by Job	Numbers			
J6S3258		This Estimate	Previous	To Date
	Posted Item Pay	\$29,971.05	\$2,446,493.86	\$2,476,464.91
	Gross Item Adjustments	\$0.00	\$317.73	\$317.73
	Gross Item Pay	\$29,971.05	\$2,446,811.59	\$2,476,782.64
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•			

Revision 4/1/2020 Page 4 of 23



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 2035500, Project Item Line Number 0020, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6083006, Project Item Line Number 0120, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6083006, Project Item Line Number 0120, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6083006, Project Item Line Number 0120, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6083008, Project Item Line Number 0130, Material Set 608300896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6086004, Project Item Line Number 0135, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6086004, Project Item Line Number 0135, Material Set 608600496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6086004, Project Item Line Number 0135, Material Set 608600496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6089902, Project Item Line Number 0140, Material Set 6089902, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6089902, Project Item Line Number 0140, Material Set 6089902, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6089902, Project Item Line Number 0140, Material Set 6089902, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6089902, Project Item Line Number 0140, Material Set 6089902, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6092021, Project Item Line Number 0160, Material Set 609202196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6092021, Project Item Line Number 0160, Material Set 609202196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on sand and rock test report.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6200015, Project Item Line Number 0240, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6200018, Project Item Line Number 0250, Material Set 620001896, Material 1048PMPFYL - Performed Thermoplastic Marking Tape YL, Acceptance Action Generic 1048PMPFYL is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6206000C, Project Item Line Number 0290, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6206000C, Project Item Line Number 0290, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6206001C, Project Item Line Number 0300, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6206001C, Project Item Line Number 0300, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8041000, Project Item Line Number 0370, Material Set 804100096, Material 0804TP - Topsoil, Acceptance Action Generic 0804TP is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8051000A, Project Item Line Number 0380, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8051000A, Project Item Line Number 0380, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8051000A, Project Item Line Number 0380, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch),	Need to create sample record.	washid1	Overridden

Revision 4/1/2020 Page 5 of 23



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 0802MLST is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8051000A, Project Item Line Number 0380, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8061017, Project Item Line Number 0390, Material Set 806101796, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8061017, Project Item Line Number 0390, Material Set 806101796, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8061017, Project Item Line Number 0390, Material Set 806101796, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on concrete breaks	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on concrete breaks	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on concrete breaks.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9031010, Project Item Line Number 0670, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-F10, Contract Project J6S3258, Project Item Line Number 0130, Contract Line Item Number 0130, Item 6083008, Minor Item.	Design change.	washid1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-F10, Contract Project J6S3258, Project Item Line Number 0610, Contract Line Item Number 0610, Item 9029100, Minor Item.	Concrete quantity for signal controller base missed on plans.	washid1	Overridden

Revision 4/1/2020 Page 6 of 23



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

lote: Posted Q		and Valu	es are b	ased on R	eport Generated date and can differ from the posted am		time the					
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F10	J6S3258	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$142,000.00	\$142,000.00
		0001	0020	2035500	EMBANKMENT IN PLACE	1,987.00	0.00	1,987.00	CUYD	1,987.00	\$28.56	\$56,748.72
		0001	0030	3049905	MISC.TYPE 5 AGGREGATE FOR BASE (11.5 IN. THICK)	835.00	0.00	835.00	SQYD	0.00	\$10.00	\$0.00
		0001	0040	4010102	9 INCHES, BITUMINOUS PAVEMENT	418.80	0.00	418.80	SQYD	181.00	\$85.00	\$15,385.00
		0001	0050	4139905	MISC.MODIFIED MICROSURFACING, TYPE II	207,095.00	0.00	207,095.00	SQYD	191,318.30	\$2.90	\$554,823.07
		0001	0060	5029905	MISC.CONTRAST CONCRETE PAVEMENT, 7.5 IN.	878.40	0.00	878.40	SQYD	584.90	\$90.60	\$52,991.94
		0001	0070	6039902	WATER	35.00	0.00	35.00	EA	17.00	\$225.00	\$3,825.00
		0001	0080	6042010	ADJUSTING MANHOLE	5.00	0.00	5.00	EA	3.00	\$500.00	\$1,500.00
		0001	0090	6049902	MISC.ADJUST PULL BOXES	12.00	0.00	12.00	EA	1.00	\$710.00	\$710.00
		0001	0100	6081000	CONCRETE MEDIAN	834.70	0.00	834.70	SQYD	0.00	\$47.50	\$0.00
		0001	0110	6081012	TRUNCATED DOMES	1,350.00	0.00	1,350.00	SQFT	280.00	\$24.00	\$6,720.00
		0001	0120	6083006	6 IN. CONCRETE MEDIAN STRIP	16,524.20	0.00	16,524.20	SQYD	13,452.00	\$49.50	\$665,874.00
		0001	0130	6083008	8 IN. CONCRETE MEDIAN STRIP	1,898.60	0.00	1,898.60	SQYD	2,209.93	\$55.00	\$121,546.15
		0001	0135	6086004	CONCRETE SIDEWALK, 4 IN.	524.40	0.00	524.40	SQYD	321.70	\$54.00	\$17,371.80
		0001	0140	6089902	MISC.ADA CURB RAMP	36.00	0.00	36.00	EA	28.00	\$2,250.00	\$63,000.00
		0001	0150	6089902	MISC.ISLAND TUBULAR MARKER	870.00	0.00	870.00	EA	698.00	\$45.00	\$31,410.00
		0001	0160	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	577.00	0.00	577.00	LF	329.00	\$15.00	\$4,935.00
		0001	0170	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	125.30	0.00	125.30	TONS	108.50	\$250.00	\$27,125.00
		0001	0180	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	747.40	0.00	747.40	SQYD	672.10	\$5.55	\$3,730.16
		0001	0190	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$32,582.50	\$16,291.25
		0001	0200	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	2.00	0.00	2.00	EA	0.00	\$5,000.00	\$0.00
		0001	0210	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$365,000.00	\$365,000.00
		0001	0220	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	2,340.00	0.00	2,340.00	LF	253.00	\$5.00	\$1,265.00
		0001	0230	6200006	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN YELLOW	699.00	0.00	699.00	LF	0.00	\$5.00	\$0.00
		0001	0240	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	1,906.00	0.00	1,906.00	LF	476.00	\$20.00	\$9,520.00
		0001	0250	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	437.00	0.00	437.00	LF	113.00	\$20.00	\$2,260.00
		0001	0260	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	108.00	0.00	108.00	EA	29.00	\$300.00	\$8,700.00
		0001	0270	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	897.00	0.00	897.00	EA	509.00	\$180.00	\$91,620.00
		0001	0280	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	309.00	0.00	309.00	EA	251.00	\$50.00	\$12,550.00
		0001	0290	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	60,094.00	0.00	60,094.00	LF	8,077.00	\$0.11	\$888.47
		0001	0300	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	51,999.00	0.00	51,999.00	LF	8,039.00	\$0.11	\$884.29
		0001	0310	6207001	PAVEMENT MARKING REMOVAL	8,509.00	0.00	8,509.00	LF	3,453.20	\$1.00	\$3,453.20
		0001	0320	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	322.00	0.00	322.00	EA	196.00	\$50.00	\$9,800.00
		0001	0330	6209902	MISC.CURB REFLECTORS	1,302.00	0.00	1,302.00	EA	843.00	\$4.00	\$3,372.00
		0001	0340	6209902	MISC.LANE REDUCTION ARROW	12.00	0.00	12.00	EA	0.00	\$1,700.00	\$0.00
		0001	0350	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	1,669.00	0.00	1,669.00	SQYD	0.00	\$7.85	\$0.00
		0001	0360	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.25	\$22,000.00	\$5,500.00
		0001	0370	8041000	TOPSOIL	1,609.00	0.00	1,609.00	CUYD	1,609.00	\$35.00	\$56,315.00
		0001	0380	8051000A	SEEDING - COOL SEASON MIXTURES	2.30	0.00	2.30	ACRE	2.30	\$5,800.00	\$13,340.00
		0001	0390	8061017	TEMPORARY SEEDING AND MULCHING	0.80	0.00	0.80	ACRE	0.80	\$2,200.00	\$1,760.00
		0020	0400	9019902	MISC.REMOVE AND RESET ST LOUIS CITY LIGHT	5.00	0.00	5.00	EA	4.00	\$2,134.00	\$8,536.00
		0030	0410	9020513	SIGNAL HEAD, TYPE 3B	8.00	0.00	8.00	EA	0.00	\$830.00	\$0.00
		0030	0420	9020514	SIGNAL HEAD, TYPE 4B	2.00	0.00	2.00	EA	0.00	\$905.00	\$0.00
		0030	0430	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	8.00	0.00	8.00	EA	0.00	\$410.00	\$0.00

Page 7 of 23 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bid Net Total Unit Total Unit Price Total Value POSTED

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F10	J6S3258	0030	0440	9020833	SH-FLAT SHEET - SIGNAL SIGN	10.00	0.00	10.00	SQFT	0.00	\$40.00	\$0.00
		0030	0450	9020834	SIGNAL SIGN, MOUNTING HARDWARE	2.00	0.00	2.00	EA	0.00	\$28.00	\$0.00
		0030	0460	9022708	POST, SIGNAL 8 FT. OR 2.4 M	2.00	0.00	2.00	EA	0.00	\$571.00	\$0.00
		0030	0480	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	0.00	\$7,817.00	\$0.00
		0030	0485	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	0.00	\$7,095.00	\$0.00
		0030	0495	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	2.00	0.00	2.00	EA	0.00	\$10,610.00	\$0.00
		0030	0500	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	0.00	\$14,960.00	\$0.00
		0030	0510	9024975	VIDEO DETECTION SYSTEM	1.00	0.00	1.00	EA	0.00	\$16,027.00	\$0.00
		0030	0520	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	14.00	0.00	14.00	LF	0.00	\$9.20	\$0.00
		0030	0530	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	123.00	0.00	123.00	LF	20.00	\$11.40	\$228.00
		0030	0540	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	250.00	0.00	250.00	LF	250.00	\$32.80	\$8,200.00
		0030	0550	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	70.00	0.00	70.00	LF	0.00	\$0.95	\$0.00
		0030	0560	9028308	CABLE, 16 AWG 2 CONDUCTOR	1,270.00	0.00	1,270.00	LF	0.00	\$0.50	\$0.00
		0030	0570	9028310	CABLE, 16 AWG 5 CONDUCTOR	1,280.00	0.00	1,280.00	LF	0.00	\$1.10	\$0.00
		0030	0580	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,150.00	0.00	2,150.00	LF	0.00	\$1.60	\$0.00
		0030	0590	9028811	PULL BOX, PREFORMED CLASS 2	3.00	0.00	3.00	EA	3.00	\$1,221.00	\$3,663.00
		0030	0600	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	1.00	\$1,643.00	\$1,643.00
		0030	0610	9029100	BASE, CONCRETE	12.10	0.00	12.10	CUYD	14.07	\$1,555.00	\$21,878.85
		0030	0620	9029902	MISC.ATC TRAFFIC SIGNAL CONTROLLER	1.00	0.00	1.00	EA	0.00	\$3,270.00	\$0.00
		0030	0630	9029902	MISC.AUDIBLE PEDESTRIAN PUSHBUTTON AND SIGNING	8.00	0.00	8.00	EA	0.00	\$652.00	\$0.00
		0030	0640	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS	1.00	0.00	1.00	EA	0.00	\$12,615.00	\$0.00
		0030	0650	9029902	MISC.FLASHING LED STOP SIGN	4.00	0.00	4.00	EA	0.00	\$2,711.00	\$0.00
		0030	0660	9029902	MISC.RECTANGUALR RAPID FLASHING BEACON	11.00	0.00	11.00	EA	0.00	\$11,742.00	\$0.00
		0040	0670	9031010	CONCRETE FOOTINGS, EMBEDDED	19.00	0.00	19.00	CUYD	9.10	\$2,300.00	\$20,930.00
		0040	0680	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	12.00	0.00	12.00	EA	0.00	\$250.00	\$0.00
		0040	0690	9031270A	2 IN. PSST POST - 12 GA.	1,608.00	0.00	1,608.00	LF	911.00	\$12.00	\$10,932.00
		0040	0700	9031272	2.25 IN. PSST POST - 12 GA.	164.00	0.00	164.00	LF	84.00	\$13.00	\$1,092.00
		0040	0710	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	450.00	0.00	450.00	LF	258.00	\$30.00	\$7,740.00
		0040	0720	9031280	2.5 IN. PSST POST - 12 GA.	503.00	0.00	503.00	LF	84.00	\$14.00	\$1,176.00
		0040	0730	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	120.00	0.00	120.00	LF	18.00	\$40.00	\$720.00
		0040	0740	9035004A	SH-FLAT SHEET	663.00	0.00	663.00	SQFT	433.00	\$23.00	\$9,959.00
		0040	0750	9035069A	SHF-FLAT SHEET FLUORESCENT	768.00	0.00	768.00	SQFT	213.00	\$26.00	\$5,538.00
		0050	0760	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$600.00	\$0.00
		0050	0770	9109902	MISC.CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$2,599.00	\$0.00
		0050	0780	9109902	MISC.FIBER OPTIC FUSION SPLICE	8.00	0.00	8.00	EA	4.00	\$111.00	\$444.00
		0050	0790	9109902	MISC.FIBER OPTIC JUMPER	8.00	0.00	8.00	EA	2.00	\$18.00	\$36.00
		0050	0800	9109902	MISC.FIBER OPTIC PIGTAIL	8.00	0.00	8.00	EA	4.00	\$9.00	\$36.00
		0050	0810	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$800.00	\$0.00
		0050	0820	9109902	MISC.INSTALL COMMUNICATION EQUIPMENT	1.00	0.00	1.00	EA	0.00	\$455.00	\$0.00
		0050	0830	9109902	MISC.ITS PULL BOX, CLASS 5	1.00	0.00	1.00	EA	1.00	\$1,498.00	\$1,498.00
		0050	0840	9109902	MISC.NETWORK CONNECTED SIGNAL MONITOR	1.00	0.00	1.00	EA	0.00	\$1,021.00	\$0.00
		0050	0850	9109902	MISC.WALL-MOUNTED INTERCONNECT CENTER	2.00	0.00	2.00	EA	0.00	\$466.00	\$0.00
		0050	0860	9109903	MISC.CCTV CAMERA CABLE	70.00	0.00	70.00	LF	0.00	\$2.25	\$0.00
		0050	0870	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	90.00	0.00	90.00	LF	0.00	\$1.10	\$0.00
	Project J	6S3258 - To	otal Value	Posted to D	Date as of Report Generated Date							\$2,476,464.90
200515-F10 Over	rall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$2,476,464.90

Revision 4/1/2020 Page 8 of 23



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3258

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0070	6039902	WATER - UTILITY ITEM	1/26/21	1/27/21	10.00	EA	Various locations along Rte.115					Rte.115
0080	6042010	ADJUSTING MANHOLE	1/26/21	1/27/21	3.00	EA	Various locations along Rte.115					Rte.115
0140	6089902	MISC. CONCRETE	1/21/21	1/22/21	4.00	EA	All 4 corners at Rte. 115 and Darby Ave.	3+00		3+54		
0530	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	1/18/21	1/29/21	10.00	LF	Fair Ave. PB2 - P3					Rte.115 & Fair Ave.
				1/29/21	10.00	LF	Fair Ave. PB3 - P5					Rte.115 & Fair Ave.
0540	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	1/18/21	1/29/21	64.00	LF	Fair Ave. PB3 - PB4					Rte.115 & Fair Ave.
				1/29/21	71.00	LF	Fair Ave. PB1 - PB2					Rte.115 & Fair Ave.
0590	9028811	PULL BOX, PREFORMED CLASS 2	1/18/21	1/29/21	2.00	EA	Fair Ave. PB3 & PB4					Rte.115 & Fair Ave.
0610	9029100	BASE, CONCRETE	1/18/21	1/29/21	0.44	CUYD	Fair Ave P2 Relocated to NWQ					Rte.115 & Fair Ave.
				1/29/21	0.44	CUYD	Fair Ave P5					Rte.115 & Fair Ave.
				1/29/21	2.49	CUYD	Fair Ave P6					Rte.115 & Fair Ave.
				1/29/21	3.14	CUYD	Fair Ave P3					Rte.115 & Fair Ave.

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 9 of 23



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	EMBANKMENT IN PLACE	Material		6	Nov 3, 2020	SYSTEM	(\$56,748.72)	
				6	Nov 3, 2020	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Nov 16, 2020	SYSTEM	(\$56,748.72)	
				7	Nov 16, 2020	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Dec 2, 2020	SYSTEM	(\$56,748.72)	
				8	Dec 2, 2020	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$56,748.72)	
				9	Dec 16, 2020	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$56,748.72)	
				10	Jan 4, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Jan 19, 2021	SYSTEM	(\$56,748.72)	
				11	Jan 19, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Feb 1, 2021	SYSTEM	(\$56,748.72)	
				12	Feb 1, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	EMBANKMENT IN PLACE	Price		6	Nov 3, 2020	SYSTEM	\$222.54	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				\$222.54	
	Price - Total						\$222.54	
0020 -	Total						\$222.54	
0040	9 INCHES, BITUMINOUS PAVEMENT	Price		6	Nov 3, 2020	SYSTEM	\$95.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				\$95.19	
	Price - Total						\$95.19	
0040 -	Total						\$95.19	
0070	WATER	Material		3	Sep 17, 2020	SYSTEM	(\$1,575.00)	
				3	Sep 17, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	Oct 1, 2020	SYSTEM	(\$1,575.00)	
				4	Oct 1, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Oct 15, 2020	SYSTEM	(\$1,575.00)	
				5	Oct 15, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Nov 3, 2020	SYSTEM	(\$1,575.00)	
				6	Nov 3, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment

Revision 4/1/2020 Page 10 of 23



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
0070	WATER	Material						Estimate Exception 2 on the current Payment Estimate.						
				7	Nov 16, 2020	SYSTEM	(\$1,575.00)							
				7	Nov 16, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
				8	Dec 2, 2020	SYSTEM	(\$1,575.00)							
				8	Dec 2, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
				9	Dec 16, 2020	SYSTEM	(\$1,575.00)							
				9	Dec 16, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
				10	Jan 4, 2021	SYSTEM	(\$1,575.00)							
										10	Jan 4, 2021	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
									11	Jan 19, 2021	SYSTEM	(\$1,575.00)		
				11	Jan 19, 2021	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
			- Total				\$0.00							
	Material - Total						\$0.00							
	- Total						\$0.00							
0110	TRUNCATED DOMES	Material		9	Dec 16, 2020	SYSTEM	(\$6,720.00)							
				9	Dec 16, 2020	SYSTEM	\$6,720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
						10	Jan 4, 2021	SYSTEM	(\$6,720.00)					
				10	Jan 4,	SYSTEM	\$6,720.00	This adjustment offsets the original system-generated Material Payment						
					2021		ψ0,720.00	Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
			- Total				\$0.00	Estimate Item Adjustment (0006) due to user washid1 overridding Payment						
	Material - Total		- Total					Estimate Item Adjustment (0006) due to user washid1 overridding Payment						
0110 -	Material - Total - Total		- Total		2021		\$0.00	Estimate Item Adjustment (0006) due to user washid1 overridding Payment						
<b>0110</b> - 0120		Material	- Total	1		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0006) due to user washid1 overridding Payment						
	- Total 6 IN. CONCRETE MEDIAN	Material	- Total	1	2021 Aug 17,		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user washid1 overridding Payment						
	- Total 6 IN. CONCRETE MEDIAN	Material	- Total		Aug 17, 2020 Aug 17,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$69,304.95)	Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment						
	- Total 6 IN. CONCRETE MEDIAN	Material	- Total	1	Aug 17, 2020 Aug 17, 2020 Sep 1,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$69,304.95) \$69,304.95	Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment						
	- Total 6 IN. CONCRETE MEDIAN	Material	- Total	1	Aug 17, 2020 Aug 17, 2020 Sep 1, 2020 Sep 1,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$69,304.95) \$69,304.95 (\$259,483.95)	Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment						
	- Total 6 IN. CONCRETE MEDIAN	Material	- Total	2	Aug 17, 2020 Aug 17, 2020 Sep 1, 2020 Sep 1, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$69,304.95) \$69,304.95 (\$259,483.95) \$259,483.95	Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment						
	- Total 6 IN. CONCRETE MEDIAN	Material	- Total	1 2 2 3	Aug 17, 2020 Aug 17, 2020 Sep 1, 2020 Sep 1, 2020 Sep 17,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$69,304.95) \$69,304.95 (\$259,483.95) \$259,483.95 (\$341,807.40)	Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate.						
	- Total 6 IN. CONCRETE MEDIAN	Material	- Total	1 2 2 3 3	Aug 17, 2020 Aug 17, 2020 Sep 1, 2020 Sep 17, 2020 Cot 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$69,304.95) \$69,304.95 (\$259,483.95) \$259,483.95 (\$341,807.40) \$341,807.40	Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate.						
	- Total 6 IN. CONCRETE MEDIAN	Material	- Total	1 2 2 2 3 3 3 4	Aug 17, 2020 Aug 17, 2020 Sep 1, 2020 Sep 17, 2020 Sep 17, 2020 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$69,304.95) \$69,304.95 (\$259,483.95) \$259,483.95 (\$341,807.40) \$341,807.40	Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 2 on the current Payment Estimate.						

Revision 4/1/2020 Page 11 of 23



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks																											
0120	6 IN. CONCRETE MEDIAN	Material	Type					Estimate Exception 2 on the current Payment Estimate.																											
0120	STRIP	Material		6	Nov 3, 2020	SYSTEM	(\$610,300.35)	Estimate Exception 2 on the current Payment Estimate.																											
				6	Nov 3, 2020	SYSTEM	\$610,300.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																											
				7	Nov 16, 2020	SYSTEM	(\$650,202.30)																												
				7	Nov 16, 2020	SYSTEM	\$650,202.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																											
				8	Dec 2, 2020	SYSTEM	(\$665,874.00)																												
				8	Dec 2, 2020	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																											
				9	Dec 16, 2020	SYSTEM	(\$665,874.00)																												
				9	Dec 16, 2020	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																											
				10	Jan 4, 2021	SYSTEM	(\$665,874.00)																												
				10	Jan 4, 2021	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																											
				11	Jan 19, 2021	SYSTEM	(\$665,874.00)																												
				11	Jan 19, 2021	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																											
				12	Feb 1, 2021	SYSTEM	(\$665,874.00)																												
				12	Feb 1, 2021	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																											
			- Total				\$0.00																												
	Material - Total						\$0.00																												
	- Total				0 1	OVOTEN	\$0.00																												
0130	8 IN. CONCRETE MEDIAN STRIP	Material		2	Sep 1, 2020	SYSTEM	(\$53,339.00)																												
				2	Sep 1, 2020	SYSTEM	\$53,339.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																											
				3	Sep 17, 2020	SYSTEM	(\$109,906.50)																												
																			3	Sep 17, 2020	SYSTEM	\$109,906.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
						4	Oct 1, 2020	SYSTEM	(\$121,546.15)																										
																				4 Oct 1, 2020 SYS	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
																					5		SYSTEM	(\$121,546.15)											
																											5	Oct 15, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				
																	6	Nov 3, 2020	SYSTEM	(\$121,546.15)															
			6																												6	Nov 3, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
																																	7	Nov 16,	SYSTEM
					2020																														

Revision 4/1/2020 Page 12 of 23



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0130	8 IN. CONCRETE MEDIAN STRIP	Material			2020			Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				8	Dec 2, 2020	SYSTEM	(\$121,546.15)	
				8	Dec 2, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$121,546.15)	
				9	Dec 16, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$121,546.15)	
				10	Jan 4, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				11	Jan 19, 2021	SYSTEM	(\$121,546.15)	
				11	Jan 19, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				12	Feb 1, 2021	SYSTEM	(\$121,546.15)	
				12	Feb 1, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	8 IN. CONCRETE MEDIAN STRIP	Overrun	Overrun	3	Sep 17, 2020	SYSTEM	(\$5,483.50)	
				3	Sep 17, 2020	SYSTEM	\$5,483.50	This adjustment offsets the original system-generated Overrun Payment
					2020			Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.
				4	Oct 1, 2020	SYSTEM	(\$5,483.50)	
				4	Oct 1,	SYSTEM SYSTEM	(\$5,483.50) (\$11,639.65)	the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of
					Oct 1, 2020		,	the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of
				4	Oct 1, 2020 Oct 1, 2020 Oct 1,	SYSTEM	(\$11,639.65)	the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on
				4	Oct 1, 2020 Oct 1, 2020 Oct 1, 2020	SYSTEM	(\$11,639.65) \$11,639.65 \$5,483.50	the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on
				4	Oct 1, 2020 Oct 1, 2020 Oct 1, 2020 Oct 1, 2020 Oct 15,	SYSTEM SYSTEM	(\$11,639.65) \$11,639.65 \$5,483.50	the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of
				4 4 5	Oct 1, 2020 Oct 15, 2020 Oct 15, 2020	SYSTEM SYSTEM SYSTEM	(\$11,639.65) \$11,639.65 \$5,483.50 (\$17,123.15)	the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on
				4 4 5 5 5	Oct 1, 2020 Oct 15, 2020 Oct 15, 2020 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$11,639.65) \$11,639.65 \$5,483.50 (\$17,123.15) \$17,123.15	the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.
				4 4 4 5 5 6	Oct 1, 2020 Oct 1, 2020 Oct 1, 2020 Oct 1, 2020 Oct 15, 2020 Oct 15, 2020 Oct 15, 2020 Nov 3, 2020 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$11,639.65) \$11,639.65 \$5,483.50 (\$17,123.15) \$17,123.15	the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 20 on
				4 4 5 5 6 6	Oct 1, 2020 Oct 1, 2020 Oct 1, 2020 Oct 1, 2020 Oct 15, 2020 Oct 15, 2020 Nov 3, 2020 Nov 16, Nov 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$11,639.65) \$11,639.65 \$5,483.50 (\$17,123.15) \$17,123.15 (\$17,123.15) \$17,123.15	the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 20 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of
				4 4 5 5 6 6 7	Oct 1, 2020 Oct 1, 2020 Oct 1, 2020 Oct 15, 2020 Oct 15, 2020  Nov 3, 2020 Nov 3, 2020 Nov 16, 2020 Nov 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$11,639.65) \$11,639.65 \$5,483.50 (\$17,123.15) \$17,123.15 (\$17,123.15) \$17,123.15	the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 20 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimates of '0.00000' is applied (if non-zero).
				4 4 5 5 6 6 7 7	Oct 1, 2020 Oct 1, 2020 Oct 1, 2020 Oct 1, 2020 Oct 15, 2020 Oct 15, 2020 Nov 3, 2020 Nov 16, 2020 Nov 16, 2020 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$11,639.65) \$11,639.65 \$5,483.50 (\$17,123.15) \$17,123.15 (\$17,123.15) \$17,123.15 (\$17,123.15)	the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 20 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 21 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4 4 5 5 6 6 7 7	Oct 1, 2020 Oct 1, 2020 Oct 1, 2020 Oct 1, 2020 Oct 15, 2020 Oct 15, 2020 Nov 3, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2, 2020	SYSTEM	(\$11,639.65) \$11,639.65 \$5,483.50 (\$17,123.15) \$17,123.15 (\$17,123.15) \$17,123.15 (\$17,123.15) \$17,123.15	the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 20 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 31 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 31 on the current Payment Estimate.

Revision 4/1/2020 Page 13 of 23



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
0130	8 IN. CONCRETE MEDIAN	Overrun	Overrun					the current Payment Estimate.						
	STRIP			10	Jan 4, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
				10	Jan 4, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.						
				11	Jan 19, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
				11	Jan 19, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 37 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.						
				12	Feb 1, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
			Overrup		12	Feb 1, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.					
			Overrun - T	otal			\$0.00							
	Overrun - Total						\$0.00							
0130 -	- Total						\$0.00							
0135	CONCRETE SIDEWALK, 4 IN.	Material		9	Dec 16, 2020	SYSTEM	(\$6,102.00)							
				9	Dec 16, 2020	SYSTEM	\$6,102.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.						
				10	Jan 4, 2021	SYSTEM	(\$6,102.00)							
				10	Jan 4, 2021	SYSTEM	\$6,102.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
							11	1	11	11	Jan 19, 2021	SYSTEM	(\$17,371.80)	
								11	Jan 19, 2021	SYSTEM	\$17,371.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
				12	Feb 1, 2021	SYSTEM	(\$17,371.80)							
				12	Feb 1, 2021	SYSTEM	\$17,371.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
			- Total				\$0.00							
	Material - Total						\$0.00							
0135	- Total MISC. ADA CURB RAMP	Material		9	Dec 16,	SYSTEM	\$0.00 (\$15,750.00)							
			9	9	2020 Dec 16, 2020	SYSTEM	\$15,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.						
				10	Jan 4, 2021	SYSTEM	(\$15,750.00)							
				10	Jan 4, 2021	SYSTEM	\$15,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user washid1 overridding Payment Estimate Exception 11 on the current Payment Estimate.						
				11	Jan 19, 2021	SYSTEM	(\$54,000.00)							
			11 J	Jan 19, 2021	SYSTEM	\$54,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
				12	Feb 1, 2021	SYSTEM	(\$63,000.00)							
				12	Feb 1, 2021	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.						
			- Total				\$0.00							

Revision 4/1/2020 Page 14 of 23



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
0140	Material - Total						\$0.00															
0140 -	Total						\$0.00															
0160	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material		7	Nov 16, 2020	SYSTEM	(\$4,935.00)															
				7	Nov 16, 2020	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
				8	Dec 2, 2020	SYSTEM	(\$4,935.00)															
				8	Dec 2, 2020	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
				9	Dec 16, 2020	SYSTEM	(\$4,935.00)															
				9	Dec 16, 2020	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.														
				10	Jan 4, 2021	SYSTEM	(\$4,935.00)															
					10	Jan 4, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.													
				11	Jan 19, 2021	SYSTEM	(\$4,935.00)															
				11	Jan 19, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.														
				12	Feb 1, 2021	SYSTEM	(\$4,935.00)															
				12	Feb 1, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.														
		_	- Total				\$0.00															
	Material - Total						\$0.00															
0160 -	· Total						\$0.00															
0190	MISC. TEMPORARY TRAFFIC CONTROL	Material		1	Aug 17, 2020	SYSTEM	(\$4,887.38)															
				1	Aug 17, 2020	SYSTEM	\$4,887.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.														
				2	Sep 1, 2020	SYSTEM	(\$4,887.38)															
				2	Sep 1, 2020	SYSTEM	\$4,887.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.														
				3	Sep 17, 2020	SYSTEM	(\$16,291.25)															
				3	Sep 17, 2020	SYSTEM	\$16,291.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.														
								4	Oct 1, 2020	SYSTEM	(\$16,291.25)											
									,		5	5	Oct 15, 2020	SYSTEM	(\$16,291.25)							
				5	Oct 15, 2020	SYSTEM	\$16,291.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.														
			- Total				\$0.00															
	Material - Total						\$0.00															
0190 -	- Total						\$0.00															
0220	PREFORMED THERMOPLASTIC	Material		9	Dec 16, 2020	SYSTEM	(\$1,265.00)															
	PAVEMENT MARKING, 4 IN.,			9	Dec 16,	SYSTEM	\$1,265.00	This adjustment offsets the original system-generated Overrun Payment														

Revision 4/1/2020 Page 15 of 23



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
0220	WHITE	Material			2020			Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
				10	Jan 4, 2021	SYSTEM	(\$1,265.00)										
				10	Jan 4, 2021	SYSTEM	\$1,265.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.									
				11	Jan 19, 2021	SYSTEM	(\$1,265.00)										
				11	Jan 19, 2021	SYSTEM	\$1,265.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.									
			- Total				\$0.00										
	Material - Total						\$0.00										
0220 -	Total						\$0.00										
0240	PREFORMED THERMOPLASTIC	C I.		7	Nov 16, 2020	SYSTEM	(\$7,900.00)										
	PAVEMENT MARKING, 24 IN. WHITE									7	Nov 16, 2020	SYSTEM	\$7,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
				8	Dec 2, 2020	SYSTEM	(\$9,520.00)										
				8	Dec 2, 2020	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
				9	Dec 16, 2020	SYSTEM	(\$9,520.00)										
				9	Dec 16, 2020	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.									
				10	Jan 4, 2021	SYSTEM	(\$9,520.00)										
					10	Jan 4, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.								
						11	Jan 19, 2021	SYSTEM	(\$9,520.00)								
				11	Jan 19, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.									
						12	Feb 1, 2021	SYSTEM	(\$9,520.00)								
				12	Feb 1, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.									
			- Total				\$0.00										
	Material - Total						\$0.00										
0240 -	Total						\$0.00										
0250	PREFORMED THERMOPLASTIC	Material		8	Dec 2, 2020	SYSTEM	(\$2,260.00)										
	PAVEMENT MARKING, 24 IN. YELLOW				8	Dec 2, 2020	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
													9	Dec 16, 2020	SYSTEM	(\$2,260.00)	
				9	Dec 16, 2020	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.									
				10	Jan 4, 2021	SYSTEM	(\$2,260.00)										
			1	10	Jan 4, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
							1	11	1	1	1		1	11	11	Jan 19, 2021	SYSTEM
				11	Jan 19,	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment									

Revision 4/1/2020 Page 16 of 23



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0250	PREFORMED THERMOPLASTIC	Material			2021			Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
	PAVEMENT MARKING, 24 IN. YELLOW			12	Feb 1, 2021	SYSTEM	(\$2,260.00)				
				12	Feb 1, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
0250 -	Total						\$0.00				
0260	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	Material		7	Nov 16, 2020	SYSTEM	(\$3,900.00)				
	LEFT/RIGHT ARROW			7	Nov 16, 2020	SYSTEM	\$3,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.			
				8	Dec 2, 2020	SYSTEM	(\$8,700.00)				
				8	Dec 2, 2020	SYSTEM	\$8,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
				9	Dec 16, 2020	SYSTEM	(\$8,700.00)				
				9	Dec 16, 2020	SYSTEM	\$8,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.			
					10	Jan 4, 2021	SYSTEM	(\$8,700.00)			
				10	Jan 4, 2021	SYSTEM	\$8,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
0260 -	Total						\$0.00				
0270	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN	Material		7	Nov 16, 2020	SYSTEM	(\$63,180.00)				
	WHITE MIDBLOCK			7	Nov 16, 2020	SYSTEM	\$63,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
				8	Dec 2, 2020	SYSTEM	(\$77,220.00)				
				8	Dec 2, 2020	SYSTEM	\$77,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
				9	Dec 16, 2020	SYSTEM	(\$91,620.00)				
				9	Dec 16, 2020	SYSTEM	\$91,620.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.			
			1				10	Jan 4, 2021	SYSTEM	(\$91,620.00)	
				10	Jan 4, 2021	SYSTEM	\$91,620.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
0270 -	Total						\$0.00				
		NA-A		7	Nov 16,	SYSTEM	(\$4,600.00)				
0280	PREFORMED THERMOPLASTIC	Material			2020						
0280		матела		7	Nov 16, 2020	SYSTEM	\$4,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
0280	THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE	мателаі		7	Nov 16,	SYSTEM	\$4,600.00 (\$4,600.00)	Estimate Item Adjustment (0010) due to user washid1 overridding Payment			

Revision 4/1/2020 Page 17 of 23



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
0280	PREFORMED THERMOPLASTIC	Material		9	Dec 16, 2020	SYSTEM	(\$12,550.00)													
	PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES			9	Dec 16, 2020	SYSTEM	\$12,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 24 on the current Payment Estimate.												
				10	Jan 4, 2021	SYSTEM	(\$12,550.00)													
				10	Jan 4, 2021	SYSTEM	\$12,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.												
			- Total				\$0.00													
	Material - Total						\$0.00													
0280 -	Total						\$0.00													
0290	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		7	Nov 16, 2020	SYSTEM	(\$812.46)													
	BEADS			7	Nov 16, 2020	SYSTEM	\$812.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.												
				8	Dec 2, 2020	SYSTEM	(\$812.46)													
				8	Dec 2, 2020	SYSTEM	\$812.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.												
				9	Dec 16, 2020	SYSTEM	(\$888.47)													
				9	Dec 16, 2020	SYSTEM	\$888.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.												
					10	Jan 4, 2021	SYSTEM	(\$888.47)												
				10	Jan 4, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.												
											11	Jan 19, 2021	SYSTEM	(\$888.47)						
				11	Jan 19, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.												
				12	Feb 1, 2021	SYSTEM	(\$888.47)													
				12	Feb 1, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.												
			- Total				\$0.00													
	Material - Total						\$0.00													
0290 -	Total						\$0.00													
0300	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		7	Nov 16, 2020	SYSTEM	(\$747.67)													
	BEADS			7	Nov 16, 2020	SYSTEM	\$747.67	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.												
																8	Dec 2, 2020	SYSTEM	(\$747.67)	
				8	Dec 2, 2020	SYSTEM	\$747.67	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.												
				9				9	Dec 16, 2020	SYSTEM	(\$884.29)									
										\$	9	9	Dec 16, 2020	SYSTEM	\$884.29	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 27 on the current Payment Estimate.				
				10	Jan 4, 2021	SYSTEM	(\$884.29)													
					10	Jan 4, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.											

Revision 4/1/2020 Page 18 of 23



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
0300	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	Material		11	Jan 19, 2021	SYSTEM	(\$884.29)																		
	MARKING PAINT, TYPE P BEADS			11	Jan 19, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																	
				12	Feb 1, 2021	SYSTEM	(\$884.29)																		
				12	Feb 1, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																	
			- Total				\$0.00																		
	Material - Total						\$0.00																		
0300 -	Total						\$0.00																		
0370	TOPSOIL	Material		6	Nov 3, 2020	SYSTEM	(\$56,315.00)																		
				6	Nov 3, 2020	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																	
				7	Nov 16, 2020	SYSTEM	(\$56,315.00)																		
				7	Nov 16, 2020	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																	
				8	Dec 2, 2020	SYSTEM	(\$56,315.00)																		
				8	Dec 2, 2020	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																	
				9	Dec 16, 2020	SYSTEM	(\$56,315.00)																		
				9	Dec 16, 2020	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																	
				10	Jan 4, 2021	SYSTEM	(\$56,315.00)																		
				10	Jan 4, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 27 on the current Payment Estimate.																	
				11	Jan 19, 2021	SYSTEM	(\$56,315.00)																		
				11	Jan 19, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																	
				12	Feb 1, 2021	SYSTEM	(\$56,315.00)																		
				12	Feb 1, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																	
			- Total				\$0.00																		
	Material - Total						\$0.00																		
0370 -	Total						\$0.00																		
0380	SEEDING - COOL SEASON MIXTURES	Material		6	Nov 3, 2020	SYSTEM	(\$13,340.00)																		
				6	Nov 3, 2020	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																	
				7 7 8	7	7	Nov 16, 2020	SYSTEM	(\$13,340.00)																
																			7	7	7	Nov 16, 2020	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
																			8	Dec 2, 2020	SYSTEM	(\$13,340.00)			
				8	Dec 2, 2020	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																	

Revision 4/1/2020 Page 19 of 23



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0380	SEEDING - COOL SEASON MIXTURES	Material	Туре	9	Dec 16, 2020	SYSTEM	(\$13,340.00)	
				9	Dec 16, 2020	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$13,340.00)	
				10	Jan 4, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				11	Jan 19, 2021	SYSTEM	(\$13,340.00)	
				11	Jan 19, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				12	Feb 1, 2021	SYSTEM	(\$13,340.00)	
				12	Feb 1, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0380 -	Total						\$0.00	
0390	TEMPORARY SEEDING AND MULCHING	Material		6	Nov 3, 2020	SYSTEM	(\$1,760.00)	
				6	Nov 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				7	Nov 16, 2020	SYSTEM	(\$1,760.00)	
				7	Nov 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				8	Dec 2, 2020	SYSTEM	(\$1,760.00)	
				8	Dec 2, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$1,760.00)	
				9	Dec 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user washid1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$1,760.00)	
				10	Jan 4, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				11	Jan 19, 2021	SYSTEM	(\$1,760.00)	
				11	Jan 19, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				12	Feb 1, 2021	SYSTEM	(\$1,760.00)	
				12	Feb 1, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					\$0.00			
	Material - Total						\$0.00	
0390 -							\$0.00	
0610	BASE, CONCRETE	Material		11	Jan 19, 2021	SYSTEM	(\$11,755.80)	
				11	Jan 19, 2021	SYSTEM	\$11,755.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.

Revision 4/1/2020 Page 20 of 23



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0610	BASE, CONCRETE	Material	Туро	12	Feb 1, 2021	SYSTEM	(\$21,878.85)	
				12	Feb 1, 2021	SYSTEM	\$21,878.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BASE, CONCRETE	Overrun	Overrun	12	Feb 1, 2021	SYSTEM	(\$3,063.35)	
				12	Feb 1, 2021	SYSTEM	\$3,063.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97.
		Overrun - Total				\$0.00		
	Overrun - Total						\$0.00	
0610 -	· Total						\$0.00	
0670	CONCRETE FOOTINGS, EMBEDDED	Material		8	Dec 2, 2020	SYSTEM	(\$20,930.00)	
				8	Dec 2, 2020	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$20,930.00)	
				9	Dec 16, 2020	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user washid1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$20,930.00)	
				10	Jan 4, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				11	Jan 19, 2021	SYSTEM	(\$20,930.00)	
				11	Jan 19, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				12	Feb 1, 2021	SYSTEM	(\$20,930.00)	
				12	Feb 1, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0670 -	- Total						\$0.00	
0690	2 IN. PSST POST - 12 GA.	Material		8	Dec 2, 2020	SYSTEM	(\$10,932.00)	
				8	Dec 2, 2020	SYSTEM	\$10,932.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$10,932.00)	
				9	Dec 16, 2020	SYSTEM	\$10,932.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user washid1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
			10	Jan 4, 2021	SYSTEM	(\$10,932.00)		
				10	Jan 4, 2021	SYSTEM	\$10,932.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0690 -	·Total						\$0.00	
0700	2.25 IN. PSST POST - 12 GA.	Material		8	Dec 2, 2020	SYSTEM	(\$1,092.00)	
				8	Dec 2,	SYSTEM	\$1,092.00	This adjustment offsets the original system-generated Overrun Payment

Revision 4/1/2020 Page 21 of 23



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0700	2.25 IN. PSST POST - 12 GA.	Material	. , , , ,		2020			Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$1,092.00)	
				9	Dec 16, 2020	SYSTEM	\$1,092.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user washid1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$1,092.00)	
				10	Jan 4, 2021	SYSTEM	\$1,092.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user washid1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0700 -							\$0.00	
		Material		0	D 0	OVOTEM		
0710	POST ANCHOR FOR 2 IN. PSST - 7 GA.	Material		8	Dec 2, 2020	SYSTEM	(\$7,740.00)	
				8	Dec 2, 2020	SYSTEM	\$7,740.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$7,740.00)	
				9	Dec 16, 2020	SYSTEM	\$7,740.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user washid1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$7,740.00)	
				10	Jan 4, 2021	SYSTEM	\$7,740.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user washid1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0710 -	Total						\$0.00	
0720	2.5 IN. PSST POST - 12 GA.	Material		8	Dec 2, 2020	SYSTEM	(\$1,176.00)	
				8	Dec 2, 2020	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user washid1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$1,176.00)	
				9	Dec 16, 2020	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user washid1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$1,176.00)	
				10	Jan 4, 2021	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user washid1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0720 -							\$0.00	
0720 -	POST ANCHOR FOR 2.5 IN.	Material		8	Dec 2,	SYSTEM	(\$720.00)	
	PSST - 7 GA.			8	2020 Dec 2, 2020	SYSTEM	\$720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user washid1 overridding Payment
				9	Dec 16,	SYSTEM	(\$720.00)	Estimate Exception 34 on the current Payment Estimate.
				9	2020 Dec 16,	SYSTEM	\$720.00	This adjustment offsets the original system-generated Overrun Payment
						0.01 LIVI	ψ, 20.00	
					2020			Estimate Item Adjustment (0026) due to user washid1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
				10	2020 Jan 4, 2021	SYSTEM	(\$720.00)	

Revision 4/1/2020 Page 22 of 23



Material - Total									
Material - Total   100	Line	Description	Adjustment Type		Est. Number	Created Date	Created By	Amount	Remarks
MSC_FIBER OPTIC JUMPER   Material - Total   South   Material - Total   South	0730		Material	- Total				\$0.00	
MSC_FIBER_OPTIC_PUSION   Material		Material - Total						\$0.00	
SPLICE	0730 -	Total						\$0.00	
2020   Estimate Item Adjustment (0011) due to user washied overridding Payment Estimate Exception 17 on the current Payment Estimate.   7	0780		Material		6		SYSTEM	(\$444.00)	
2020   7					6		SYSTEM	\$444.00	Estimate Item Adjustment (0011) due to user washid1 overridding Payment
Supplication					7		SYSTEM	(\$444.00)	
Material - Total   S0.00					7		SYSTEM	\$444.00	Estimate Item Adjustment (0016) due to user washid1 overridding Payment
Misc. Fiber OPTIC JUMPER   Material     6   Nov 3, 2020   SYSTEM   S86.00   This adjustment offsets the original system-generated Overrun Payment Estimate Exception 18 on the current Payment Estimate Exception 19 on the current Payment Estimate Exception 29 on the current Payment Estimate Exception 30 on the current Payment Estimate Exception 36 on the current Payment Estimate				- Total				\$0.00	
MISC. FIBER OPTIC JUMPER   Material		Material - Total						\$0.00	
2020   8	0780 -	Total						\$0.00	
2020   Estimate Item Adjustment (0012) due to user washird overridding Payment Estimate Exception 18 on the current Payment Estimate.	0790	MISC. FIBER OPTIC JUMPER Materia	Material	/laterial	6		SYSTEM	(\$36.00)	
2020   7   Nov 16, SYSTEM   \$36.00   This adjustment offsets the original system-generated Overrun Payment Estimate Exception 29 on the current Payment Estimate Exception 30 on the current Payment Es					6		SYSTEM	\$36.00	Estimate Item Adjustment (0012) due to user washid1 overridding Payment
Sestimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.    Footal   Source   Sourc					7		SYSTEM	(\$36.00)	
Material - Total   S0.00					7		SYSTEM	\$36.00	Estimate Item Adjustment (0017) due to user washid1 overridding Payment
Misc. Fiber OPTIC PIGTAIL   Material				- Total				\$0.00	
MISC. FIBER OPTIC PIGTAIL   Material   6		Material - Total						\$0.00	
2020   6 Nov 3, 2020   836.00   This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.   7 Nov 16, 2020   7 Nov 16, SYSTEM   \$36.00   7 No	0790 -	Total						\$0.00	
2020   Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.   7	0800	MISC. FIBER OPTIC PIGTAIL	ER OPTIC PIGTAIL Material	laterial	6		SYSTEM	(\$36.00)	
2020 7 Nov 16, 2020 \$36.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user washid 1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  - Total  \$0.00  Material - Total  \$0.00  MISC. ITS PULL BOX, CLASS 5  Material  11 Jan 19, 2021  SYSTEM \$1,498.00  SYSTEM \$1,498.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid 1 overridding Payment Estimate Exception 36 on the current Payment Estimate Estimate Exception 36 on the current Payment Estimate.  - Total  \$0.00  Material - Total  \$0.00  SYSTEM \$1,498.00  SYSTEM \$1,498.00  SYSTEM \$1,498.00  SYSTEM \$0.00  SYSTEM \$0.00  SYSTEM \$0.00					6		SYSTEM	\$36.00	Estimate Item Adjustment (0013) due to user washid1 overridding Payment
Batimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 30 on the current Payment Estimate.    Total   \$0.00					7		SYSTEM	(\$36.00)	
Material - Total  \$0.00    MISC. ITS PULL BOX, CLASS   Material					7		SYSTEM	\$36.00	Estimate Item Adjustment (0018) due to user washid1 overridding Payment
0800 - Total  0800   MISC. ITS PULL BOX, CLASS   Material   2021				- Total				\$0.00	
MISC. ITS PULL BOX, CLASS 5 Material 2021 SYSTEM (\$1,498.00)  11 Jan 19, 2021 SYSTEM \$1,498.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.  - Total \$0.00  Material - Total \$0.00  0830 - Total \$0.00		Material - Total						\$0.00	
2021  11 Jan 19, 2021  13 Jan 19, 2021  14 SYSTEM \$1,498.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.  - Total \$0.00  Material - Total \$0.00  80.00	0800 -	Total						\$0.00	
Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.  - Total \$0.00  Material - Total \$0.00  0830 - Total \$0.00	0830	MISC. ITS PULL BOX, CLASS 5	Material		11		SYSTEM	(\$1,498.00)	
Material - Total         \$0.00           0830 - Total         \$0.00					11		SYSTEM		Estimate Item Adjustment (0016) due to user washid1 overridding Payment
0830 - Total \$0.00				- Total				\$0.00	
		Material - Total						\$0.00	
Overall - Total \$317.73	0830 - Total							\$0.00	
	Overa	II - Total						\$317.73	

Revision 4/1/2020 Page 23 of 23