

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 15, 2021

Progress Estimate Number	Contract ID 200515-F10	Pay Period StartMarch 2, 2021 Original Contract Amount \$3,406,354.96
15	Prime ContractorLamke Trenching &	Excavating, Inc.Pay Period End March 15, 2021Net Change Order Amount\$0.00
10		Current Contract Amount \$3,406,354.96

Approval Date		By User
March 15, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	washid1
March 16, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	washas
March 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
October 1, 2021	October 1, 2021		75.72%

	Milestones		
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	June 3, 2020	June 3, 2020	
Letting Date	May 15, 2020	May 15, 2020	
Notice to Proceed Date	August 3, 2020	August 3, 2020	
Open to Traffic Date			
Work Began Date			

Contract Total Pay For Estimate No. 15								
		This Estimate	Previous	To Date				
200515-F10								
	Total Posted Items Pay	\$0.00	\$2,579,275.36	\$2,579,275.36				
	Gross Item Adjustments	\$0.00	\$317.73	\$317.73				
	Incentive	\$0.00	\$0.00	\$0.00				
	Disincentive	\$0.00	\$0.00	\$0.00				
	Liquidated Damage	\$0.00	\$0.00	\$0.00				
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00				
	•		\$2,579,593.09	\$2,579,593.09				
Contract Total Pay	able This Estimate:	\$0.00						

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		nents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3258	0020	EMBANKMENT IN PLACE	Material			-1,987	\$28.56	(\$56,748.72)
	0020	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,987	\$28.56	\$56,748.72
	0120	6 IN. CONCRETE MEDIAN STRIP	Material			-13,452	\$49.50	(\$665,874.00)
	0120	6 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	13,452	\$49.50	\$665,874.00
	0130	8 IN. CONCRETE MEDIAN STRIP	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-311.33	\$55.00	(\$17,123.15)
	0130	8 IN. CONCRETE MEDIAN STRIP	Material			-2,209.93	\$55.00	(\$121,546.15)
	0130	8 IN. CONCRETE MEDIAN STRIP	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment	311.33	\$55.00	\$17,123.15

Revision 4/1/2020 Page 1 of 28



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 15, 2021

Progress Estimate Number
15

Contract ID 200515-F10 Pay Period StartMarch 2, 2021 Original Contract Amount \$3,406,354.96 Prime ContractorLamke Trenching & Excavating, Inc.Pay Period End March 15, 2021Net Change Order Amount \$0.00 Current Contract Amount \$3,406,354.96

roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3258					Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.			
	0130	8 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	2,209.93	\$55.00	\$121,546.15
	0135	CONCRETE SIDEWALK, 4 IN.	Material			-321.7	\$54.00	(\$17,371.80
	0135	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	321.7	\$54.00	\$17,371.80
	0140	MISC.	Material			-28	\$2,250.00	(\$63,000.00
	0140	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	28	\$2,250.00	\$63,000.00
	0160	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material			-329	\$15.00	(\$4,935.00
	0160	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	329	\$15.00	\$4,935.00
	0240	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-476	\$20.00	(\$9,520.00
	0240	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	476	\$20.00	\$9,520.00
	0250	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material			-113	\$20.00	(\$2,260.00
	0250	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	113	\$20.00	\$2,260.00
	0290	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-8,077	\$0.11	(\$888.47
	0290	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	8,077	\$0.11	\$888.47
	0300	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-8,039	\$0.11	(\$884.29
	0300	4 IN. YELLOW STANDARD	Material		This adjustment offsets the original system-	8,039	\$0.11	\$884.29

Revision 4/1/2020 Page 2 of 28



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 15, 2021

Progress Estimate Number
15

Contract ID 200515-F10 Pay Period StartMarch 2, 2021 Original Contract Amount \$3,406,354.96 Prime ContractorLamke Trenching & Excavating, Inc.Pay Period End March 15, 2021Net Change Order Amount \$0.00 Current Contract Amount \$3,406,354.96

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3258		WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS			generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
	0370	TOPSOIL	Material			-1,609	\$35.00	(\$56,315.00)
	0370	TOPSOIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	1,609	\$35.00	\$56,315.00
	0380	SEEDING - COOL SEASON MIXTURES	Material			-2.3	\$5,800.00	(\$13,340.00)
	0380	SEEDING - COOL SEASON MIXTURES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	2.3	\$5,800.00	\$13,340.00
	0390	TEMPORARY SEEDING AND MULCHING	Material			-0.8	\$2,200.00	(\$1,760.00)
	0390	TEMPORARY SEEDING AND MULCHING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	0.8	\$2,200.00	\$1,760.00
	0610	BASE, CONCRETE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-1.97	\$1,555.00	(\$3,063.35)
	0610	BASE, CONCRETE	Material			-14.07	\$1,555.00	(\$21,878.85)
	0610	BASE, CONCRETE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97.	1.97	\$1,555.00	\$3,063.35
	0610	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	14.07	\$1,555.00	\$21,878.85
	0670	CONCRETE FOOTINGS, EMBEDDED	Material			-9.1	\$2,300.00	(\$20,930.00)
	0670	CONCRETE FOOTINGS, EMBEDDED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	9.1	\$2,300.00	\$20,930.00
Total								\$0.00

Revision 4/1/2020 Page 3 of 28



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

Contract Project Information							
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work		
J6S3258	FAF 115-1(46)	Microsurface and ADA improvements	115	ST LOUIS CITY	from St. Louis city limits to Natural Bridge		

	improvements	CITY			
Totals by Jo	bb Numbers				
J6S3258			This Estimate	Previous	To Date
	Posted Item Pay Gross Item Adjustments		\$0.00 \$0.00	\$2,579,275.36 \$317.73	\$2,579,275.36 \$317.73
	Gross Item Pay		\$0.00	\$2,579,593.09	\$2,579,593.09
	Incentive		\$0.00	\$0.00	\$0.00
	Disincentive		\$0.00	\$0.00	\$0.00
	Liquidated Damages		\$0.00	\$0.00	\$0.00
	Other Contract Adjustment	s	\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 4 of 28



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 2035500, Project Item Line Number 0020, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6083006, Project Item Line Number 0120, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6083006, Project Item Line Number 0120, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6083006, Project Item Line Number 0120, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6083008, Project Item Line Number 0130, Material Set 608300896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6086004, Project Item Line Number 0135, Material Set 608600496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6086004, Project Item Line Number 0135, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6086004, Project Item Line Number 0135, Material Set 608600496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6089902, Project Item Line Number 0140, Material Set 6089902, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6089902, Project Item Line Number 0140, Material Set 6089902, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6089902, Project Item Line Number 0140, Material Set 6089902, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6089902, Project Item Line Number 0140, Material Set 6089902, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6092021, Project Item Line Number 0160, Material Set 609202196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6092021, Project Item Line Number 0160, Material Set 609202196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on sand and rock test.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6200015, Project Item Line Number 0240, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6200018, Project Item Line Number 0250, Material Set 620001896, Material 1048PMPFYL - Performed Thermoplastic Marking Tape YL, Acceptance Action Generic 1048PMPFYL is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6206000C, Project Item Line Number 0290, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6206000C, Project Item Line Number 0290, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6206001C, Project Item Line Number 0300, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 6206001C, Project Item Line Number 0300, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8041000, Project Item Line Number 0370, Material Set 804100096, Material 0804TP - Topsoil, Acceptance Action Generic 0804TP is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8051000A, Project Item Line Number 0380, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8051000A, Project Item Line Number 0380, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8051000A, Project Item Line Number 0380, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch),	Need to create sample record.	washid1	Overridden

Revision 4/1/2020 Page 5 of 28



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 0802MLST is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8051000A, Project Item Line Number 0380, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8061017, Project Item Line Number 0390, Material Set 806101796, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8061017, Project Item Line Number 0390, Material Set 806101796, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 8061017, Project Item Line Number 0390, Material Set 806101796, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9029100, Project Item Line Number 0610, Material Set 902910096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3258, Item 9031010, Project Item Line Number 0670, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Need to create sample record.	washid1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-F10, Contract Project J6S3258, Project Item Line Number 0130, Contract Line Item Number 0130, Item 6083008, Minor Item.	Design change	washid1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-F10, Contract Project J6S3258, Project Item Line Number 0610, Contract Line Item Number 0610, Item 9029100, Minor Item.	Design error	washid1	Overridden

Revision 4/1/2020 Page 6 of 28



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted am	ount at the	time the	Estimate wa	s Gener	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F10	J6S3258	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$142,000.00	\$142,000.00
		0001	0020	2035500	EMBANKMENT IN PLACE	1,987.00	0.00	1,987.00	CUYD	1,987.00	\$28.56	\$56,748.72
		0001	0030	3049905	MISC.TYPE 5 AGGREGATE FOR BASE (11.5 IN. THICK)	835.00	0.00	835.00	SQYD	0.00	\$10.00	\$0.00
		0001	0040	4010102	9 INCHES, BITUMINOUS PAVEMENT	418.80	0.00	418.80	SQYD	181.00	\$85.00	\$15,385.00
		0001	0050	4139905	MISC.MODIFIED MICROSURFACING, TYPE II	207,095.00	0.00	207,095.00	SQYD	191,318.30	\$2.90	\$554,823.07
		0001	0060	5029905	MISC.CONTRAST CONCRETE PAVEMENT, 7.5 IN.	878.40	0.00	878.40	SQYD	584.90	\$90.60	\$52,991.94
		0001	0070	6039902	WATER	35.00	0.00	35.00	EA	17.00	\$225.00	\$3,825.00
		0001	0080	6042010	ADJUSTING MANHOLE	5.00	0.00	5.00	EA	3.00	\$500.00	\$1,500.00
		0001	0090	6049902	MISC.ADJUST PULL BOXES	12.00	0.00	12.00	EA	1.00	\$710.00	\$710.00
		0001	0100	6081000	CONCRETE MEDIAN	834.70	0.00	834.70	SQYD	0.00	\$47.50	\$0.00
		0001	0110	6081012	TRUNCATED DOMES	1,350.00	0.00	1,350.00	SQFT	280.00	\$24.00	\$6,720.00
		0001	0120	6083006	6 IN. CONCRETE MEDIAN STRIP	16,524.20	0.00	16,524.20	SQYD	13,452.00	\$49.50	\$665,874.00
		0001	0130	6083008	8 IN. CONCRETE MEDIAN STRIP	1,898.60	0.00	1,898.60	SQYD	2,209.93	\$55.00	\$121,546.15
		0001	0135	6086004	CONCRETE SIDEWALK, 4 IN.	524.40	0.00	524.40	SQYD	321.70	\$54.00	\$17,371.80
		0001	0140	6089902	MISC.ADA CURB RAMP	36.00	0.00	36.00	EA	28.00	\$2,250.00	\$63,000.00
		0001	0150	6089902	MISC.ISLAND TUBULAR MARKER	870.00	0.00	870.00	EA	698.00	\$45.00	\$31,410.00
		0001	0160	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	577.00	0.00	577.00	LF	329.00	\$15.00	\$4,935.00
		0001	0170	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	125.30	0.00	125.30	TONS	108.50	\$250.00	\$27,125.00
		0001	0180	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	747.40	0.00	747.40	SQYD	672.10	\$5.55	\$3,730.16
		0001	0190	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$32,582.50	\$16,291.25
		0001	0200	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	2.00	0.00	2.00	EA	0.00	\$5,000.00	\$0.00
		0001	0210	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$365,000.00	\$365,000.00
		0001	0220	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	2,340.00	0.00	2,340.00	LF	253.00	\$5.00	\$1,265.00
		0001	0230	6200006	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN YELLOW	699.00	0.00	699.00	LF	0.00	\$5.00	\$0.00
		0001	0240	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	1,906.00	0.00	1,906.00	LF	476.00	\$20.00	\$9,520.00
		0001	0250	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	437.00	0.00	437.00	LF	113.00	\$20.00	\$2,260.00
		0001	0260	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	108.00	0.00	108.00	EA	29.00	\$300.00	\$8,700.00
		0001	0270	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	897.00	0.00	897.00	EA	509.00	\$180.00	\$91,620.00
		0001	0280	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	309.00	0.00	309.00	EA	251.00	\$50.00	\$12,550.00
		0001	0290	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	60,094.00	0.00	60,094.00	LF	8,077.00	\$0.11	\$888.47
		0001	0300	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	51,999.00	0.00	51,999.00	LF	8,039.00	\$0.11	\$884.29
		0001	0310	6207001	PAVEMENT MARKING REMOVAL	8,509.00	0.00	8,509.00	LF	3,453.20	\$1.00	\$3,453.20
		0001	0320	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	322.00	0.00	322.00	EA	196.00	\$50.00	\$9,800.00
		0001	0330	6209902	MISC.CURB REFLECTORS	1,302.00	0.00	1,302.00	EA	843.00	\$4.00	\$3,372.00
		0001	0340	6209902	MISC.LANE REDUCTION ARROW	12.00	0.00	12.00	EA	0.00	\$1,700.00	\$0.00
		0001	0350	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	1,669.00	0.00	1,669.00	SQYD	0.00	\$7.85	\$0.00
		0001	0360	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.25	\$22,000.00	\$5,500.00
		0001	0370	8041000	TOPSOIL	1,609.00	0.00	1,609.00	CUYD	1,609.00	\$35.00	\$56,315.00
		0001	0380	8051000A	SEEDING - COOL SEASON MIXTURES	2.30	0.00	2.30	ACRE	2.30	\$5,800.00	\$13,340.00
		0001	0390	8061017	TEMPORARY SEEDING AND MULCHING	0.80	0.00	0.80	ACRE	0.80	\$2,200.00	\$1,760.00
		0020	0400	9019902	MISC.REMOVE AND RESET ST LOUIS CITY LIGHT	5.00	0.00	5.00	EA	4.00	\$2,134.00	\$8,536.00
		0030	0410	9020513	SIGNAL HEAD, TYPE 3B	8.00	0.00	8.00	EA	8.00	\$830.00	\$6,640.00
		0030	0420	9020514	SIGNAL HEAD, TYPE 4B	2.00	0.00	2.00	EA	2.00	\$905.00	\$1,810.00
		0030	0430	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	8.00	0.00	8.00	EA	8.00	\$410.00	\$3,280.00
Revision 4/1/202	20											Page 7 of 28

Page 7 of 28 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-F10	J6S3258	0030	0440	9020833	SH-FLAT SHEET - SIGNAL SIGN	10.00	0.00	10.00	SQFT	0.00	\$40.00	\$0.00
		0030	0450	9020834	SIGNAL SIGN, MOUNTING HARDWARE	2.00	0.00	2.00	EA	0.00	\$28.00	\$0.00
		0030	0460	9022708	POST, SIGNAL 8 FT. OR 2.4 M	2.00	0.00	2.00	EA	2.00	\$571.00	\$1,142.00
		0030	0480	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	1.00	\$7,817.00	\$7,817.00
		0030	0485	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	1.00	\$7,095.00	\$7,095.00
		0030	0495	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	2.00	0.00	2.00	EA	2.00	\$10,610.00	\$21,220.00
		0030	0500	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	1.00	\$14,960.00	\$14,960.00
		0030	0510	9024975	VIDEO DETECTION SYSTEM	1.00	0.00	1.00	EA	1.00	\$16,027.00	\$16,027.00
		0030	0520	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	14.00	0.00	14.00	LF	14.00	\$9.20	\$128.80
		0030	0530	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	123.00	0.00	123.00	LF	123.00	\$11.40	\$1,402.20
		0030	0540	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	250.00	0.00	250.00	LF	250.00	\$32.80	\$8,200.00
		0030	0550	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	70.00	0.00	70.00	LF	63.00	\$0.95	\$59.85
		0030	0560	9028308	CABLE, 16 AWG 2 CONDUCTOR	1,270.00	0.00	1,270.00	LF	1,207.00	\$0.50	\$603.50
		0030	0570	9028310	CABLE, 16 AWG 5 CONDUCTOR	1,280.00	0.00	1,280.00	LF	1,215.00	\$1.10	\$1,336.50
		0030	0580	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,150.00	0.00	2,150.00	LF	2,051.00	\$1.60	\$3,281.60
		0030	0590	9028811	PULL BOX, PREFORMED CLASS 2	3.00	0.00	3.00	EA	3.00	\$1,221.00	\$3,663.00
		0030	0600	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	1.00	\$1,643.00	\$1,643.00
		0030	0610	9029100	BASE, CONCRETE	12.10	0.00	12.10	CUYD	14.07	\$1,555.00	\$21,878.85
		0030	0620	9029902	MISC.ATC TRAFFIC SIGNAL CONTROLLER	1.00	0.00	1.00	EA	0.00	\$3,270.00	\$0.00
		0030	0630	9029902	MISC.AUDIBLE PEDESTRIAN PUSHBUTTON AND SIGNING	8.00	0.00	8.00	EA	0.00	\$652.00	\$0.00
		0030	0640	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS	1.00	0.00	1.00	EA	1.00	\$12,615.00	\$12,615.00
		0030	0650	9029902	MISC.FLASHING LED STOP SIGN	4.00	0.00	4.00	EA	0.00	\$2,711.00	\$0.00
		0030	0660	9029902	MISC.RECTANGUALR RAPID FLASHING BEACON	11.00	0.00	11.00	EA	0.00	\$11,742.00	\$0.00
		0040	0670	9031010	CONCRETE FOOTINGS, EMBEDDED	19.00	0.00	19.00	CUYD	9.10	\$2,300.00	\$20,930.00
		0040	0680	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	12.00	0.00	12.00	EA	0.00	\$250.00	\$0.00
		0040	0690	9031270A	2 IN. PSST POST - 12 GA.	1,608.00	0.00	1,608.00	LF	911.00	\$12.00	\$10,932.00
		0040	0700	9031272	2.25 IN. PSST POST - 12 GA.	164.00	0.00	164.00	LF	84.00	\$13.00	\$1,092.00
		0040	0710	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	450.00	0.00	450.00	LF	258.00	\$30.00	\$7,740.00
		0040	0720	9031280	2.5 IN. PSST POST - 12 GA.	503.00	0.00	503.00	LF	84.00	\$14.00	\$1,176.00
		0040	0730	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	120.00	0.00	120.00	LF	18.00	\$40.00	\$720.00
		0040	0740	9035004A	SH-FLAT SHEET	663.00	0.00	663.00	SQFT	433.00	\$23.00	\$9,959.00
		0040	0750	9035069A	SHF-FLAT SHEET FLUORESCENT	768.00	0.00	768.00	SQFT	213.00	\$26.00	\$5,538.00
		0050	0760	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$600.00	\$0.00
		0050	0770	9109902	MISC.CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	1.00	\$2,599.00	\$2,599.00
		0050	0780	9109902	MISC.FIBER OPTIC FUSION SPLICE	8.00	0.00	8.00	EA	4.00	\$111.00	\$444.00
		0050	0790	9109902	MISC.FIBER OPTIC JUMPER	8.00	0.00	8.00	EA	2.00	\$18.00	\$36.00
		0050	0800	9109902	MISC.FIBER OPTIC PIGTAIL	8.00	0.00	8.00	EA	4.00	\$9.00	\$36.00
		0050	0810	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$800.00	\$0.00
		0050	0820	9109902	MISC.INSTALL COMMUNICATION EQUIPMENT	1.00	0.00	1.00	EA	0.00	\$455.00	\$0.00
		0050	0830	9109902	MISC.ITS PULL BOX, CLASS 5	1.00	0.00	1.00	EA	1.00	\$1,498.00	\$1,498.00
		0050	0840	9109902	MISC.NETWORK CONNECTED SIGNAL MONITOR	1.00	0.00	1.00	EA	1.00	\$1,021.00	\$1,021.00
		0050	0850	9109902	MISC.WALL-MOUNTED INTERCONNECT CENTER	2.00	0.00	2.00	EA	0.00	\$466.00	\$0.00
		0050	0860	9109903	MISC.CCTV CAMERA CABLE	70.00	0.00	70.00	LF	0.00	\$2.25	\$0.00
		0050	0870	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	90.00	0.00	90.00	LF	0.00	\$1.10	\$0.00
	Project J	6S3258 - To	tal Value	Posted to D	Jate as of Report Generated Date							\$2,579,275.34
200515-F10 Over	all - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$2,579,275.34

Page 8 of 28 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 9 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0020	EMBANKMENT IN PLACE	Material	.,,,,,	6	Nov 3, 2020	SYSTEM	(\$56,748.72)		
				6	Nov 3, 2020	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				7	Nov 16, 2020	SYSTEM	(\$56,748.72)		
				7	Nov 16, 2020	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				8	Dec 2, 2020	SYSTEM	(\$56,748.72)		
				8	Dec 2, 2020	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				9	Dec 16, 2020	SYSTEM	(\$56,748.72)		
				9	Dec 16, 2020	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				10	Jan 4, 2021	SYSTEM	(\$56,748.72)		
				10	Jan 4, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				11	Jan 19, 2021	SYSTEM	(\$56,748.72)		
				11	Jan 19, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					12	Feb 1, 2021	SYSTEM	(\$56,748.72)	
						12	Feb 1, 2021	SYSTEM	\$56,748.72
				13	Feb 16, 2021	SYSTEM	(\$56,748.72)		
				13	Feb 16, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				14	Mar 1, 2021	SYSTEM	(\$56,748.72)		
				14	Mar 1, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				15	Mar 15, 2021	SYSTEM	(\$56,748.72)		
				15	Mar 15, 2021	SYSTEM	\$56,748.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total EMBANKMENT IN PLACE	Price		6	Nov 3,	SYSTEM	\$0.00 \$222.54	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
	EMISCHANIST IN FLACE	. 1100	- Total		2020	S. G. LIVI	\$222.54	The applied is 1'UEL	
	Price - Total		- Otal				\$222.54		
0020	- Total						\$222.54		
0040	9 INCHES, BITUMINOUS PAVEMENT	Price		6	Nov 3, 2020	SYSTEM	\$95.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
	District Table		- Total				\$95.19		
0040	Price - Total						\$95.19		
0040	- Total WATER	Material		3	Sep 17,	SYSTEM	\$95.19 (\$1,575.00)		
				3	2020 Sep 17,	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment	
					2020			Estimate Item Adjustment (0003) due to user washid1 overridding Payment	

Revision 4/1/2020 Page 10 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
0070	WATER	Material						Estimate Exception 1 on the current Payment Estimate.																			
				4	Oct 1, 2020	SYSTEM	(\$1,575.00)																				
				4	Oct 1, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																			
				5	Oct 15, 2020	SYSTEM	(\$1,575.00)																				
					5	Oct 15, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
								6	Nov 3, 2020	SYSTEM	(\$1,575.00)																
								6	Nov 3, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
					7	Nov 16, 2020	SYSTEM	(\$1,575.00)																			
																7	Nov 16, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
										8	Dec 2, 2020	SYSTEM	(\$1,575.00)														
							8	Dec 2, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
							9	Dec 16, 2020	SYSTEM	(\$1,575.00)																	
				9	Dec 16, 2020	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																			
						10	Jan 4, 2021	SYSTEM	(\$1,575.00)																		
						10	Jan 4, 2021	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
								11	Jan 19, 2021	SYSTEM	(\$1,575.00)																
				11	Jan 19, 2021	SYSTEM	\$1,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																			
			- Total				\$0.00																				
	Material - Total						\$0.00																				
0070 - 0110	TRUNCATED DOMES	Material		9		SYSTEM	\$0.00 (\$6,720.00)																				
																	9	2020 Dec 16, 2020	SYSTEM	\$6,720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
				10	Jan 4, 2021	SYSTEM	(\$6,720.00)																				
				10	Jan 4, 2021	SYSTEM	\$6,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment																			
			- Total				\$0.00	Estimate Exception 3 on the current Payment Estimate.																			
	Material - Total		- Total				\$0.00																				
0110 -							\$0.00																				
0120	6 IN. CONCRETE MEDIAN	Material		1	Aug 17, 2020	SYSTEM	(\$69,304.95)																				
	STRIP		1																				1	Aug 17, 2020	SYSTEM	\$69,304.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user washid1 overridding Payment
				2	Sep 1,	SYSTEM	(\$259,483.95)	Estimate Exception 1 on the current Payment Estimate.																			
			2	2020 Sep 1,	SYSTEM	\$259,483.95	This adjustment offsets the original system-generated Overrun Payment																				
					2020		,•	Estimate Item Adjustment (0001) due to user washid1 overridding Payment																			

Revision 4/1/2020 Page 11 of 28



ne	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
20	6 IN. CONCRETE MEDIAN	Material						Estimate Exception 1 on the current Payment Estimate.								
	STRIP			3	Sep 17, 2020	SYSTEM	(\$341,807.40)									
			3	Sep 17, 2020	SYSTEM	\$341,807.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.									
			4	Oct 1, 2020	SYSTEM	(\$403,959.60)	,									
				4	Oct 1, 2020	SYSTEM	\$403,959.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
						5	Oct 15, 2020	SYSTEM	(\$608,394.60)							
							5	Oct 15, 2020	SYSTEM	\$608,394.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
								6	Nov 3, 2020	SYSTEM	(\$610,300.35)					
						6	Nov 3, 2020	SYSTEM	\$610,300.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
				7	Nov 16, 2020	SYSTEM	(\$650,202.30)									
				7	Nov 16, 2020	SYSTEM	\$650,202.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
				8	Dec 2, 2020	SYSTEM	(\$665,874.00)									
				8	Dec 2, 2020	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					9	Dec 16, 2020	SYSTEM	(\$665,874.00)								
					9	Dec 16, 2020	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.							
								10	Jan 4, 2021	SYSTEM	(\$665,874.00)					
						10	Jan 4, 2021	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.						
											11	Jan 19, 2021	SYSTEM	(\$665,874.00)		
				11	Jan 19, 2021	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
				12	Feb 1, 2021	SYSTEM	(\$665,874.00)									
				12	Feb 1, 2021	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
				13	Feb 16, 2021	SYSTEM	(\$665,874.00)									
				13	Feb 16, 2021	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
							1					14	Mar 1, 2021	SYSTEM	(\$665,874.00)	
				14	Mar 1, 2021	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
				15	Mar 15, 2021	SYSTEM	(\$665,874.00)									
				15	Mar 15, 2021	SYSTEM	\$665,874.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
			- Total				\$0.00									
N	Material - Total						\$0.00									

Revision 4/1/2020 Page 12 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
0120	- Total						\$0.00														
0130	8 IN. CONCRETE MEDIAN STRIP	Material		2	Sep 1, 2020	SYSTEM	(\$53,339.00)														
				2	Sep 1, 2020	SYSTEM	\$53,339.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
				3	Sep 17, 2020	SYSTEM	(\$109,906.50)														
				3	Sep 17, 2020	SYSTEM	\$109,906.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
				4	Oct 1, 2020	SYSTEM	(\$121,546.15)														
								4	Oct 1, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.									
											5	Oct 15, 2020	SYSTEM	(\$121,546.15)							
				5	Oct 15, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
								6	Nov 3, 2020	SYSTEM	(\$121,546.15)										
				6	Nov 3, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.													
				7	Nov 16, 2020	SYSTEM	(\$121,546.15)														
				7	Nov 16, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.													
				8	Dec 2, 2020	SYSTEM	(\$121,546.15)														
				8	Dec 2, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.													
						9	Dec 16, 2020	SYSTEM	(\$121,546.15)												
				9	Dec 16, 2020	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.													
										10	Jan 4, 2021	SYSTEM	(\$121,546.15)								
																		10	Jan 4, 2021	SYSTEM	\$121,546.15
					11	Jan 19, 2021	SYSTEM	(\$121,546.15)													
						11	Jan 19, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.											
				12	Feb 1, 2021	SYSTEM	(\$121,546.15)														
										1							12	Feb 1, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
												13	Feb 16, 2021	SYSTEM	(\$121,546.15)						
												13	Feb 16, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
				14	Mar 1, 2021	SYSTEM	(\$121,546.15)														
				14	Mar 1, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
				15	Mar 15, 2021	SYSTEM	(\$121,546.15)														

Revision 4/1/2020 Page 13 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
0130	8 IN. CONCRETE MEDIAN STRIP	Material		15	Mar 15, 2021	SYSTEM	\$121,546.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																	
			- Total				\$0.00																		
	Material - Total						\$0.00																		
	8 IN. CONCRETE MEDIAN STRIP	Overrun	Overrun	3	Sep 17, 2020	SYSTEM	(\$5,483.50)																		
				3	Sep 17, 2020	SYSTEM	\$5,483.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.																	
				4	Oct 1, 2020	SYSTEM	(\$5,483.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
				4	Oct 1, 2020	SYSTEM	(\$11,639.65)																		
				4	Oct 1, 2020	SYSTEM	\$11,639.65	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.																	
				4	Oct 1, 2020	SYSTEM	\$5,483.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on the current Payment Estimate.																	
				5	Oct 15, 2020	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
				5	Oct 15, 2020	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.																	
				6	Nov 3, 2020	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
				6	Nov 3, 2020	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 20 on the current Payment Estimate.																	
				7	Nov 16, 2020	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
				7	Nov 16, 2020	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 31 on the current Payment Estimate.																	
					8	Dec 2, 2020	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																
				8	Dec 2, 2020	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 35 on the current Payment Estimate.																	
				9	Dec 16, 2020	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
				9	Dec 16, 2020	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 43 on the current Payment Estimate.																	
														10	Jan 4, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
													10	Jan 4, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.								
				11	Jan 19, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
																					11	Jan 19, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 37 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.
															12	Feb 1, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
											12	Feb 1, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.										
				13	Feb 16, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
				13	Feb 16, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.																	

Revision 4/1/2020 Page 14 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
0130	8 IN. CONCRETE MEDIAN STRIP	Overrun	Overrun	14	Mar 1, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
				14	Mar 1, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 39 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.								
				15	Mar 15, 2021	SYSTEM	(\$17,123.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
				15	Mar 15, 2021	SYSTEM	\$17,123.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 2209.930; Overrun Quantity Balance 311.33.								
			Overrun - T	otal			\$0.00									
	Overrun - Total						\$0.00									
	- Total						\$0.00									
0135	CONCRETE SIDEWALK, 4 IN.	Material		9	Dec 16, 2020	SYSTEM	(\$6,102.00)									
				9	Dec 16, 2020	SYSTEM	\$6,102.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.								
				10	Jan 4, 2021	SYSTEM	(\$6,102.00)									
				10	Jan 4, 2021	SYSTEM	\$6,102.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.								
								11	Jan 19, 2021	SYSTEM	(\$17,371.80)					
				11	Jan 19, 2021	SYSTEM	\$17,371.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.								
					12	Feb 1, 2021	SYSTEM	(\$17,371.80)								
				12	Feb 1, 2021	SYSTEM	\$17,371.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.								
						13	Feb 16, 2021	SYSTEM	(\$17,371.80)							
					13	Feb 16, 2021	SYSTEM	\$17,371.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.							
								14	Mar 1, 2021	SYSTEM	(\$17,371.80)					
				15	Mar 15, 2021	SYSTEM	(\$17,371.80)									
				15	Mar 15, 2021	SYSTEM	\$17,371.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.								
			- Total				\$0.00									
	Material - Total						\$0.00									
0135 -	- Total						\$0.00									
0140	MISC. ADA CURB RAMP	Material		9	Dec 16, 2020	SYSTEM	(\$15,750.00)									
				9	Dec 16, 2020	SYSTEM	\$15,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
				10	Jan 4, 2021	SYSTEM	(\$15,750.00)									
				10	Jan 4, 2021	SYSTEM	\$15,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user washid1 overridding Payment Estimate Exception 11 on the current Payment Estimate.								
			11	Jan 19, 2021	SYSTEM	(\$54,000.00)										
				11	Jan 19, 2021	SYSTEM	\$54,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment								

Revision 4/1/2020 Page 15 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																					
0140	MISC. ADA CURB RAMP	Material						Estimate Exception 10 on the current Payment Estimate.																					
				12	Feb 1, 2021	SYSTEM	(\$63,000.00)																						
				12	Feb 1, 2021	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																					
				13	Feb 16, 2021	SYSTEM	(\$63,000.00)																						
				13	Feb 16, 2021	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																					
				14	Mar 1, 2021	SYSTEM	(\$63,000.00)																						
				14	Mar 1, 2021	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																					
							15	Mar 15, 2021	SYSTEM	(\$63,000.00)																			
				15	Mar 15, 2021	SYSTEM	\$63,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																					
			- Total				\$0.00																						
	Material - Total						\$0.00																						
0140 -	- Total						\$0.00																						
0160	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material		7	Nov 16, 2020	SYSTEM	(\$4,935.00)																						
					7	Nov 16, 2020	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																				
							8	Dec 2, 2020	SYSTEM	(\$4,935.00)																			
					8	Dec 2, 2020	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																				
						9	Dec 16, 2020	SYSTEM	(\$4,935.00)																				
						9	Dec 16, 2020	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																			
								10	Jan 4, 2021	SYSTEM	(\$4,935.00)																		
											10	Jan 4, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
								11	Jan 19, 2021	SYSTEM	(\$4,935.00)																		
										11	Jan 19, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.															
				12	Feb 1, 2021	SYSTEM	(\$4,935.00)																						
				12	Feb 1, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.																					
													13	Feb 16, 2021	SYSTEM	(\$4,935.00)													
													1								13	Feb 16, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.				
								14	Mar 1, 2021	SYSTEM	(\$4,935.00)																		
			1	1	1.	12	12	1	14				1	1	1.								-	1	14	Mar 1, 2021	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
						15	Mar 15, 2021	SYSTEM	(\$4,935.00)																				
				15	Mar 15,	SYSTEM	\$4,935.00	This adjustment offsets the original system-generated Material Payment																					

Revision 4/1/2020 Page 16 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
0160	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	Material			2021			Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.											
			- Total				\$0.00												
	Material - Total						\$0.00												
0160 -	Total						\$0.00												
0190	MISC. TEMPORARY TRAFFIC CONTROL	Material		1	Aug 17, 2020	SYSTEM	(\$4,887.38)												
				1	Aug 17, 2020	SYSTEM	\$4,887.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user washid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.											
				2	Sep 1, 2020	SYSTEM	(\$4,887.38)												
				2	Sep 1, 2020	SYSTEM	\$4,887.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.											
				3	Sep 17, 2020	SYSTEM	(\$16,291.25)												
				3	Sep 17, 2020	SYSTEM	\$16,291.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.											
				4	Oct 1, 2020	SYSTEM	(\$16,291.25)												
									4	Oct 1, 2020	SYSTEM	\$16,291.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					5	Oct 15, 2020	SYSTEM	(\$16,291.25)											
				5	Oct 15, 2020	SYSTEM	\$16,291.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.											
			- Total				\$0.00												
	Material - Total						\$0.00												
0190 -	·Total						\$0.00												
0220	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	Material	Material	Material	Material		9	Dec 16, 2020	SYSTEM	(\$1,265.00)									
	Will				9	Dec 16, 2020	SYSTEM	\$1,265.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.										
				10	Jan 4, 2021	SYSTEM	(\$1,265.00)												
														10	10	Jan 4, 2021	SYSTEM	\$1,265.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				11	Jan 19, 2021	SYSTEM	(\$1,265.00)												
				11	Jan 19, 2021	SYSTEM	\$1,265.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.											
			- Total				\$0.00												
	Material - Total						\$0.00												
0220 -	Total						\$0.00												
0240	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	Material		7	Nov 16, 2020	SYSTEM	(\$7,900.00)												
	WHITE			7	Nov 16, 2020	SYSTEM	\$7,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.											
				8	Dec 2, 2020	SYSTEM	(\$9,520.00)												
				8	8	Dec 2, 2020	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.										
				9	Dec 16, 2020	SYSTEM	(\$9,520.00)												
										9	Dec 16, 2020	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.					

Revision 4/1/2020 Page 17 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
0240	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	Material		10	Jan 4, 2021	SYSTEM	(\$9,520.00)																
	WHITE			10	Jan 4, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.															
				11	Jan 19, 2021	SYSTEM	(\$9,520.00)																
				11	Jan 19, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.															
				12	Feb 1, 2021	SYSTEM	(\$9,520.00)																
				12	Feb 1, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.															
				13	Feb 16, 2021	SYSTEM	(\$9,520.00)																
					13	Feb 16, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
				14	Mar 1, 2021	SYSTEM	(\$9,520.00)																
									14	Mar 1, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.										
					15	Mar 15, 2021	SYSTEM	(\$9,520.00)															
				15	Mar 15, 2021	SYSTEM	\$9,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.															
			- Total				\$0.00																
	Material - Total						\$0.00																
0240	- Total PREFORMED THERMOPLASTIC	Material		8	Dec 2,	SYSTEM	\$0.00 (\$2,260.00)																
0200	PAVEMENT MARKING, 24 IN. YELLOW	Widtorial		8	2020 Dec 2,	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Overrun Payment															
							2020			Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.													
										9	Dec 16, 2020	SYSTEM	(\$2,260.00)										
								9	Dec 16, 2020	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.											
										10	Jan 4, 2021	SYSTEM	(\$2,260.00)										
																			10	Jan 4, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
																	11	Jan 19, 2021	SYSTEM	(\$2,260.00)			
				11	Jan 19, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.															
				12	Feb 1, 2021	SYSTEM	(\$2,260.00)																
			1																12	Feb 1, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
										13	Feb 16, 2021	SYSTEM	(\$2,260.00)										
															13	Feb 16, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
				14	Mar 1, 2021	SYSTEM	(\$2,260.00)																
					14	Mar 1, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														

Revision 4/1/2020 Page 18 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
0250	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	Material		15	Mar 15, 2021	SYSTEM	(\$2,260.00)													
	YELLOW			15	Mar 15, 2021	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.												
			- Total				\$0.00													
	Material - Total						\$0.00													
0250 -	· Total						\$0.00													
0260	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		7	Nov 16, 2020	SYSTEM	(\$3,900.00)													
				7	Nov 16, 2020	SYSTEM	\$3,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.												
				8	Dec 2, 2020	SYSTEM	(\$8,700.00)													
							8	Dec 2, 2020	SYSTEM	\$8,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.									
				9	Dec 16, 2020	SYSTEM	(\$8,700.00)													
				9	Dec 16, 2020	SYSTEM	\$8,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.												
				10	Jan 4, 2021	SYSTEM	(\$8,700.00)													
				10	Jan 4, 2021	SYSTEM	\$8,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.												
			- Total				\$0.00													
	Material - Total						\$0.00													
0260 -	Total						\$0.00													
0270	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material	Material		7	Nov 16, 2020	SYSTEM	(\$63,180.00)												
	WITTE WIDDLOOK					7	Nov 16, 2020	SYSTEM	\$63,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.										
										8	Dec 2, 2020	SYSTEM	(\$77,220.00)							
				8	Dec 2, 2020	SYSTEM	\$77,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.												
				9	Dec 16, 2020	SYSTEM	(\$91,620.00)													
																9	Dec 16, 2020	SYSTEM	\$91,620.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$91,620.00)													
				10	Jan 4, 2021	SYSTEM	\$91,620.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.												
			- Total				\$0.00													
	Material - Total						\$0.00													
0270 -	Total						\$0.00													
0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material		7	Nov 16, 2020	SYSTEM	(\$4,600.00)													
	, TELD LINE INTRINGES			7	Nov 16, 2020	SYSTEM	\$4,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.												
				8	Dec 2, 2020	SYSTEM	(\$4,600.00)													
				8	Dec 2, 2020	SYSTEM	\$4,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.												
				9	Dec 16, 2020	SYSTEM	(\$12,550.00)													

Revision 4/1/2020 Page 19 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material		9	Dec 16, 2020	SYSTEM	\$12,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	
				10	Jan 4, 2021	SYSTEM	(\$12,550.00)		
				10	Jan 4, 2021	SYSTEM	\$12,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
	- Total						\$0.00		
0290	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material	al .	7	Nov 16, 2020	SYSTEM	(\$812.46)		
	BEADS			7	Nov 16, 2020	SYSTEM	\$812.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
				8	Dec 2, 2020	SYSTEM	(\$812.46)		
				8	Dec 2, 2020	SYSTEM	\$812.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
				9	Dec 16, 2020	SYSTEM	(\$888.47)		
				9	Dec 16, 2020	SYSTEM	\$888.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
					10	Jan 4, 2021	SYSTEM	(\$888.47)	
				10	Jan 4, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
				11	Jan 19, 2021	SYSTEM	(\$888.47)		
				11	Jan 19, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
				12	Feb 1, 2021	SYSTEM	(\$888.47)		
				12	Feb 1, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
				13	Feb 16, 2021	SYSTEM	(\$888.47)		
				13	Feb 16, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
				14	Mar 1, 2021	SYSTEM	(\$888.47)		
				14	Mar 1, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
				15	Mar 15, 2021	SYSTEM	(\$888.47)		
				15	Mar 15, 2021	SYSTEM	\$888.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
	- Total					0)/	\$0.00		
0300	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		7	Nov 16, 2020	SYSTEM	(\$747.67)		
	BEADS				Nov 16, 2020	SYSTEM	\$747.67	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
				8	Dec 2, 2020	SYSTEM	(\$747.67)		

Revision 4/1/2020 Page 20 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0300	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		8	Dec 2, 2020	SYSTEM	\$747.67	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
	BEADS			9	Dec 16, 2020	SYSTEM	(\$884.29)			
				9	Dec 16, 2020	SYSTEM	\$884.29	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 27 on the current Payment Estimate.		
						10	Jan 4, 2021	SYSTEM	(\$884.29)	
					10	Jan 4, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	
				11	Jan 19, 2021	SYSTEM	(\$884.29)			
				11	Jan 19, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		
				12	Feb 1, 2021	SYSTEM	(\$884.29)			
				12	Feb 1, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
				13	Feb 16, 2021	SYSTEM	(\$884.29)			
						13	Feb 16, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					14	Mar 1, 2021	SYSTEM	(\$884.29)		
				14	Mar 1, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
				15	Mar 15, 2021	SYSTEM	(\$884.29)			
				15	Mar 15, 2021	SYSTEM	\$884.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
			- Total				\$0.00			
0000	Material - Total						\$0.00			
0300 -	- Total TOPSOIL	Material		6	Nov 3,	SYSTEM	\$0.00 (\$56,315.00)			
0370	101 0012	Iviatorial			2020					
				6	Nov 3, 2020	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user washid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
				7	Nov 16, 2020	SYSTEM	(\$56,315.00)			
				7	Nov 16, 2020	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.		
				8	Dec 2, 2020	SYSTEM	(\$56,315.00)			
				8	Dec 2, 2020	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		
				9	Dec 16, 2020	SYSTEM	(\$56,315.00)			
				9	Dec 16, 2020	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.		
				10	Jan 4, 2021	SYSTEM	(\$56,315.00)			
				10	Jan 4, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 27 on the current Payment Estimate.		
				11	Jan 19, 2021	SYSTEM	(\$56,315.00)			

Revision 4/1/2020 Page 21 of 28



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks																																								
		Туре	Туре	Number	Date	Бу																																										
0370	TOPSOIL	Material		11	Jan 19, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																																								
				12	Feb 1, 2021	SYSTEM	(\$56,315.00)																																									
				12	Feb 1, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																																								
				13	Feb 16, 2021	SYSTEM	(\$56,315.00)																																									
				13	Feb 16, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																																								
				14	Mar 1, 2021	SYSTEM	(\$56,315.00)																																									
				14	Mar 1, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																																								
				15	Mar 15, 2021	SYSTEM	(\$56,315.00)	,																																								
				15	Mar 15, 2021	SYSTEM	\$56,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																																								
			- Total				\$0.00																																									
	Material - Total						\$0.00																																									
0370 -	- Total						\$0.00																																									
0380	SEEDING - COOL SEASON MIXTURES	Material		6	Nov 3, 2020	SYSTEM	(\$13,340.00)																																									
				6	Nov 3, 2020	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user washid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																																								
				7	Nov 16, 2020	SYSTEM	(\$13,340.00)																																									
				7	Nov 16, 2020	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																																								
					8	Dec 2, 2020	SYSTEM	(\$13,340.00)																																								
				8	Dec 2, 2020	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																																								
																																9	Dec 16, 2020	SYSTEM	(\$13,340.00)													
				9	Dec 16, 2020	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 30 on the current Payment Estimate.																																								
				10	Jan 4, 2021	SYSTEM	(\$13,340.00)																																									
				10	Jan 4, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 28 on the current Payment Estimate.																																								
				11	Jan 19, 2021	SYSTEM	(\$13,340.00)																																									
				11	Jan 19, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																																								
																																												12	Feb 1, 2021	SYSTEM	(\$13,340.00)	
				12	Feb 1, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																																								
				13	Feb 16, 2021	SYSTEM	(\$13,340.00)																																									
				13	Feb 16, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																																								
				14	Mar 1, 2021	SYSTEM	(\$13,340.00)																																									

Revision 4/1/2020 Page 22 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0380	SEEDING - COOL SEASON MIXTURES	Material		14	Mar 1, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				15	Mar 15, 2021	SYSTEM	(\$13,340.00)	
				15	Mar 15, 2021	SYSTEM	\$13,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	
0390	TEMPORARY SEEDING AND MULCHING	Material		6	Nov 3, 2020	SYSTEM	(\$1,760.00)	
				6	Nov 3, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user washid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				7	Nov 16, 2020	SYSTEM	(\$1,760.00)	
				7	Nov 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				8	Dec 2, 2020	SYSTEM	(\$1,760.00)	
				8	Dec 2, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$1,760.00)	
				9	Dec 16, 2020	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user washid1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$1,760.00)	
				10	Jan 4, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				11	Jan 19, 2021	SYSTEM	(\$1,760.00)	
				11	Jan 19, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				12	Feb 1, 2021	SYSTEM	(\$1,760.00)	
				12	Feb 1, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				13	Feb 16, 2021	SYSTEM	(\$1,760.00)	
				13	Feb 16, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				14	Mar 1, 2021	SYSTEM	(\$1,760.00)	
				14	Mar 1, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				15	Mar 15, 2021	SYSTEM	(\$1,760.00)	
				15	Mar 15, 2021	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	
0460	POST, SIGNAL 8 FT. OR 2.4 M	Material		14	Mar 1, 2021	SYSTEM	(\$1,142.00)	

Revision 4/1/2020 Page 23 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0460	POST, SIGNAL 8 FT. OR 2.4 M	Material		14	Mar 1, 2021	SYSTEM	\$1,142.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0460 -	Total						\$0.00	
0610	10 BASE, CONCRETE	Material		11	Jan 19, 2021	SYSTEM	(\$11,755.80)	
				11	Jan 19, 2021	SYSTEM	\$11,755.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user washid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				12	Feb 1, 2021	SYSTEM	(\$21,878.85)	
				12	Feb 1, 2021	SYSTEM	\$21,878.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				13	Feb 16, 2021	SYSTEM	(\$21,878.85)	
				13	Feb 16, 2021	SYSTEM	\$21,878.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				14	Mar 1, 2021	SYSTEM	(\$21,878.85)	
			14	Mar 1, 2021	SYSTEM	\$21,878.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	
				15	Mar 15, 2021	SYSTEM	(\$21,878.85)	
				15	Mar 15, 2021	SYSTEM	\$21,878.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
			- Total					
			- Iotai				\$0.00	
	Material - Total		- Total				\$0.00	
	Material - Total BASE, CONCRETE	Overrun	Overrun	12	Feb 1, 2021	SYSTEM		
		Overrun		12		SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97.
		Overrun			2021 Feb 1,		\$0.00 (\$3,063.35)	Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070;
		Overrun		12	2021 Feb 1, 2021 Feb 16,	SYSTEM	\$0.00 (\$3,063.35) \$3,063.35	Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates
		Overrun		12	2021 Feb 1, 2021 Feb 16, 2021 Feb 16,	SYSTEM	\$0.00 (\$3,063.35) \$3,063.35 (\$3,063.35)	Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97.
		Overrun		12 13 13	2021 Feb 1, 2021 Feb 16, 2021 Feb 16, 2021	SYSTEM SYSTEM	\$0.00 (\$3,063.35) \$3,063.35 (\$3,063.35) \$3,063.35	Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates
		Overrun		12 13 13	2021 Feb 1, 2021 Feb 16, 2021 Feb 16, 2021 Mar 1, 2021 Mar 1,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,063.35) \$3,063.35 (\$3,063.35) \$3,063.35	Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 14.070;
		Overrun		13 13 14 14	2021 Feb 1, 2021 Feb 16, 2021 Feb 16, 2021 Mar 1, 2021 Mar 1, 2021 Mar 15,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,063.35) \$3,063.35 (\$3,063.35) \$3,063.35 (\$3,063.35)	Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates
		Overrun		12 13 13 14 14 15	2021 Feb 1, 2021 Feb 16, 2021 Feb 16, 2021 Mar 1, 2021 Mar 1, 2021 Mar 15, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,063.35) \$3,063.35 (\$3,063.35) \$3,063.35 (\$3,063.35)	Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070;
		Overrun	Overrun	12 13 13 14 14 15	2021 Feb 1, 2021 Feb 16, 2021 Feb 16, 2021 Mar 1, 2021 Mar 1, 2021 Mar 15, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,063.35) \$3,063.35 (\$3,063.35) \$3,063.35 (\$3,063.35) \$3,063.35	Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070;
0610 -	BASE, CONCRETE	Overrun	Overrun	12 13 13 14 14 15	2021 Feb 1, 2021 Feb 16, 2021 Feb 16, 2021 Mar 1, 2021 Mar 1, 2021 Mar 15, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,063.35) \$3,063.35 (\$3,063.35) \$3,063.35 (\$3,063.35) \$3,063.35 \$3,063.35	Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070;
0610 - 0640	Overrun - Total Total MISC. COMBINATION PAD MOUNTED 120V/240V POWER		Overrun	12 13 13 14 14 15	2021 Feb 1, 2021 Feb 16, 2021 Feb 16, 2021 Mar 1, 2021 Mar 1, 2021 Mar 15, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,063.35) \$3,063.35 (\$3,063.35) \$3,063.35 (\$3,063.35) \$3,063.35 \$3,063.35	Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070;
	Overrun - Total Total MISC. COMBINATION PAD		Overrun	12 13 13 14 14 15 15	2021 Feb 1, 2021 Feb 16, 2021 Feb 16, 2021 Mar 1, 2021 Mar 15, 2021 Mar 15, 2021 Mar 15, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$3,063.35) \$3,063.35 (\$3,063.35) \$3,063.35 (\$3,063.35) \$3,063.35 \$3,063.35 \$3,063.35	Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 14.070; Overrun Quantity Balance 1.97. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 14.070;

Revision 4/1/2020 Page 24 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0640	Material - Total		.,,,,,				\$0.00			
0640 -	· Total						\$0.00			
0670	CONCRETE FOOTINGS, EMBEDDED	Material		8	Dec 2, 2020	SYSTEM	(\$20,930.00)			
				8	Dec 2, 2020	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.		
				9	Dec 16, 2020	SYSTEM	(\$20,930.00)			
				9	Dec 16, 2020	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user washid1 overridding Payment Estimate Exception 37 on the current Payment Estimate.		
				10	Jan 4, 2021	SYSTEM	(\$20,930.00)			
				10	Jan 4, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 35 on the current Payment Estimate.		
				11	Jan 19, 2021	SYSTEM	(\$20,930.00)			
				11	Jan 19, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 35 on the current Payment Estimate.		
				12	Feb 1, 2021	SYSTEM	(\$20,930.00)			
						12	Feb 1, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					13	Feb 16, 2021	SYSTEM	(\$20,930.00)		
				13	Feb 16, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.		
				14	Mar 1, 2021	SYSTEM	(\$20,930.00)			
					14	Mar 1, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	
				15	Mar 15, 2021	SYSTEM	(\$20,930.00)			
				15	Mar 15, 2021	SYSTEM	\$20,930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
0670 -	·Total						\$0.00			
0690	2 IN. PSST POST - 12 GA.	Material		8	Dec 2, 2020	SYSTEM	(\$10,932.00)			
				8	Dec 2, 2020	SYSTEM	\$10,932.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 30 on the current Payment Estimate.		
				9	Dec 16, 2020	SYSTEM	(\$10,932.00)			
				9	Dec 16, 2020	SYSTEM	\$10,932.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user washid1 overridding Payment Estimate Exception 38 on the current Payment Estimate.		
				10	Jan 4, 2021	SYSTEM	(\$10,932.00)			
				10	Jan 4, 2021	SYSTEM	\$10,932.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
0690 -	·Total						\$0.00			
0700	2.25 IN. PSST POST - 12 GA.	Material		8	Dec 2, 2020	SYSTEM	(\$1,092.00)			
				8	Dec 2,	SYSTEM	\$1,092.00	This adjustment offsets the original system-generated Overrun Payment		
	on 4/1/2020							Page 25 of 3		

Revision 4/1/2020 Page 25 of 28



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	·	Туре	Adjustment Type	Number	Date	Ву		
0700	2.25 IN. PSST POST - 12 GA.	Material			2020			Estimate Item Adjustment (0019) due to user washid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$1,092.00)	
				9	Dec 16, 2020	SYSTEM	\$1,092.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user washid1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$1,092.00)	
				10	Jan 4, 2021	SYSTEM	\$1,092.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user washid1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
			- Total				\$0.00	Zamae Zaspish of on the earth of a great Zamae.
	Material - Total						\$0.00	
0700 -	· Total						\$0.00	
0710	POST ANCHOR FOR 2 IN. PSST - 7 GA.	Material		8	Dec 2, 2020	SYSTEM	(\$7,740.00)	
				8	Dec 2, 2020	SYSTEM	\$7,740.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user washid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$7,740.00)	
				9	Dec 16, 2020	SYSTEM	\$7,740.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user washid1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$7,740.00)	
				10	Jan 4, 2021	SYSTEM	\$7,740.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user washid1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0710 -	· Total						\$0.00	
0720	2.5 IN. PSST POST - 12 GA.	Material		8	Dec 2, 2020	SYSTEM	(\$1,176.00)	
				8	Dec 2, 2020	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user washid1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$1,176.00)	
				9	Dec 16, 2020	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user washid1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$1,176.00)	
				10	Jan 4, 2021	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user washid1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0720 -	Total						\$0.00	
0730	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material		8	Dec 2, 2020	SYSTEM	(\$720.00)	
				8	Dec 2, 2020	SYSTEM	\$720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user washid1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				9	Dec 16, 2020	SYSTEM	(\$720.00)	
				9	Dec 16, 2020	SYSTEM	\$720.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user washid1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
				10	Jan 4, 2021	SYSTEM	(\$720.00)	
				10	Jan 4, 2021	SYSTEM	\$720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user washid1 overridding Payment Estimate Exception 40 on the current Payment Estimate.

Revision 4/1/2020 Page 26 of 28



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
2	25551,pas	Туре	Adjustment Type		Date	Ву	7 1110 0111	, condition	
0730		Material	- Total				\$0.00		
	Material - Total						\$0.00		
0730 -	Total						\$0.00		
0770	MISC. CCTV CAMERA	Material		14	Mar 1,	SYSTEM	(\$2,599.00)		
	ASSEMBLY			14	2021 Mar 1, 2021	SYSTEM	\$2,599.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user washid1 overridding Payment	
								Estimate Exception 37 on the current Payment Estimate.	
		- Total				\$0.00			
	Material - Total						\$0.00		
0770 -	Total						\$0.00		
0780	MISC. FIBER OPTIC FUSION SPLICE	Material		6	Nov 3, 2020	SYSTEM	(\$444.00)		
				6	Nov 3, 2020	SYSTEM	\$444.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user washid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
				7	Nov 16, 2020	SYSTEM	(\$444.00)		
				7	Nov 16, 2020	SYSTEM	\$444.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0780 -	Total						\$0.00		
0790	MISC. FIBER OPTIC JUMPER	Material		6	Nov 3, 2020	SYSTEM	(\$36.00)		
					6	Nov 3, 2020	SYSTEM	\$36.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user washid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				7	Nov 16, 2020	SYSTEM	(\$36.00)		
				7	Nov 16, 2020	SYSTEM	\$36.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user washid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0790 -	Total						\$0.00		
0800	MISC. FIBER OPTIC PIGTAIL	Material		6	Nov 3, 2020	SYSTEM	(\$36.00)		
				6	Nov 3, 2020	SYSTEM	\$36.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user washid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
				7	Nov 16, 2020	SYSTEM	(\$36.00)		
				7	Nov 16, 2020	SYSTEM	\$36.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0800 -	Total						\$0.00		
0830	MISC. ITS PULL BOX, CLASS 5	Material		11	Jan 19, 2021	SYSTEM	(\$1,498.00)		
				11	Jan 19, 2021	SYSTEM	\$1,498.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user washid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0830 -	Total						\$0.00		
0840	MISC. NETWORK CONNECTED SIGNAL MONITOR	Material		14	Mar 1, 2021	SYSTEM	(\$1,021.00)		
				14	Mar 1, 2021	SYSTEM	\$1,021.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user washid1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	

Revision 4/1/2020 Page 27 of 28



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0840		Material	- Total	- Total			\$0.00	
	Material - Total						\$0.00	
0840 -	0840 - Total						\$0.00	
Overa	Overall - Total						\$317.73	

Revision 4/1/2020 Page 28 of 28