Pay Estimate Created Date: September 16, 2020

Progress Estim 6	ate Number	Contract ID Prime Contrac	200515-H03 t or Robertson Contrac		ber 2, 2020 Original Contract Amoun ber 15, 2020 Net Change Order Amoun Current Contract Amount	nt \$0.00
Approval Date						By User
September 16, 2020			Generated and A	pproved (and should be considered	d Draft) at the Project Office Level by	FERGUJ1
September 16, 2020			Reviewed and Appro	ved (and should be considered Dra	ft) at the Resident Engineer Level by	PULLIA
September 17, 2020			F	Reviewed and Approved at the Cen	tral Office Controllers Office Level by	greggd1
Original Comp	oletion Date	Current	Completion Date	Actual Completion Date	% of Current Contract Amoun	t Complete
November	1, 2021	Nove	ember 1, 2021		44.24%	
No Milestones Exist	for Contract					

Contract Total Pay For Estimate No. 6 This Estimate Previous To Date 200515-H03 Total Posted Items Pay <mark>\$200,313.20</mark> \$580,308.10 \$780,621.30 **\$0.00** \$0.00 (\$1,233.58) \$0.00 Gross Item Adjustments (\$1,233.58) Incentive \$0.00 Disincentive \$0.00 \$0.00 \$0.00 Liquidated Damage \$0.00 \$0.00 \$0.00 Other Contract Adjustments \$0.00 \$0.00 \$0.00 \$579,074.52 \$779,387.72

\$200,313.20

Contract Total Payable This Estimate: Items Paid This Estimate Period

Project Number	Line Number	ltem Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9P3212	0200	6113020	FURNISHING TYPE 2 ROCK BLANKET	CUYD	\$35.000	600	\$21,000.00
	0210	6113040	PLACING TYPE 2 ROCK BLANKET	CUYD	\$12.000	600	\$7,200.00
	0281	6181000	MOBILIZATION	LS	\$144,103.000	0.5	\$72,051.50
	0340	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	SQYD	\$2.300	800	\$1,840.00
	0540	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	LF	\$950.000	33.2	\$31,540.00
	0550	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	LF	\$750.000	48.5	\$36,375.0
	0560	7011300	VIDEO CAMERA INSPECTION	EA	\$700.000	4	\$2,800.0
	0580	7011600	SONIC LOGGING TESTING	EA	\$2,000.000	2	\$4,000.0
	0620	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	CUYD	\$850.000	19	\$16,150.0
	0660	7061060	REINFORCING STEEL (BRIDGES)	LB	\$1.300	5,659	\$7,356.7
Project J9P32	12 - Total						\$200,313.2
Overall - Tota							\$200,313.2

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3212	0090	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material			-3,581	\$8.00	(\$28,648.00)
	0090	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user ferguj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	3,581	\$8.00	\$28,648.00
	0200	FURNISHING TYPE 2 ROCK BLANKET	Material			-600	\$35.00	(\$21,000.00)



Pay Estimate Created Date: September 16, 2020

Progre	ss Esti (mate Number	Contract ID Prime Contra	200515-F ctor Robertso		Pay Period Start September 2, 2020 Orig s, Inc. Pay Period End September 15, 2020 Net Cur	Change Ord		0.00
Project Number	Line No.	Item De	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
I9P3212	0200	FURNISHING	TYPE 2 ROCK BLANKET	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user ferguj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	600	\$35.00	\$21,000.00
	0300	WATERBORN	TE STANDARD IE PAVEMENT PAINT, TYPE P BEADS	Material			-3,042	\$0.45	(\$1,368.90
	0300	WATERBORN	TE STANDARD IE PAVEMENT PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user ferguj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	3,042	\$0.45	\$1,368.90
	0310	WATERBORN	W STANDARD IE PAVEMENT PAINT, TYPE P BEADS	Material			-3,042	\$0.45	(\$1,368.90)
	0310	WATERBORN	W STANDARD IE PAVEMENT PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user ferguj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	3,042	\$0.45	\$1,368.90
	0440		ARY SEEDING	Material			-0.6	\$5,000.00	(\$3,000.00
	0440		ARY SEEDING ND MULCHING	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user ferguj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	0.6	\$5,000.00	\$3,000.00
	0540	DRILLED SH	HAFTS (3 FT. 6 IN. DIA.)	Overrun			-7.2	\$950.00	(\$6,840.00
	0540	DRILLED SH	HAFTS (3 FT. 6 IN. DIA.)	Material			-33.2	\$950.00	(\$31,540.00
	0540	DRILLED SH	IAFTS (3 FT. 6 IN. DIA.)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 21 on the current Payment Estimate.	7.2	\$950.00	\$6,840.00
	0540	DRILLED SH	IAFTS (3 FT. 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user ferguj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	33.2	\$950.00	\$31,540.00
	0550	ROCK SOCKE	TS (3 FT 0 IN. DIA.)	Overrun			-8.5	\$750.00	(\$6,375.00)
	0550	ROCK SOCKE	TS (3 FT 0 IN. DIA.)	Material			-48.5	\$750.00	(\$36,375.00
	0550	ROCK SOCKE	TS (3 FT 0 IN. DIA.)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 22 on the current Payment Estimate.	8.5	\$750.00	\$6,375.00
	0550	ROCK SOCKE	TS (3 FT 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user ferguj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	48.5	\$750.00	\$36,375.00
	0610		PILE POINT	Material			-8	\$160.00	(\$1,280.00



Pay Estimate Created Date: September 16, 2020

Progre	ss Estir 6	nate Number	Contract ID Prime Contra	200515-F ctor Robertso		Pay Period Start September 2, 2020 Orig , Inc. Pay Period End September 15, 2020 Net Curr	Change Ord		0.00
Project Number	Line No.	Item Des	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3212		REIN	IFORCEMENT						
	0610	REIN	PILE POINT IFORCEMENT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user ferguj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	8	\$160.00	\$1,280.00
	0620		B CONCRETE STRUCTURE)	Material			-33	\$850.00	(\$28,050.00)
	0620		B CONCRETE STRUCTURE)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user ferguj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	33	\$850.00	\$28,050.00
Total									\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Informatio	on
Project Number	Federal Proj. Number	Description	Route	County			Location of Work
J9P3212	FAF 17-1(18)	Bridge replacement	17	TEXAS	over Big Creek		
Totals by .	Job Numb	ers					
J9P3212	Post	ed Item Pay ss Item Adjustn		<mark>s Item Pa</mark>	This Estimate \$200,313.20 \$0.00 \$200,313.20	Previous \$580,308.10 (\$1,233.58) \$579,074.52	To Date \$780,621.30 (\$1,233.58) \$779,387.72
	Liqu	ntive ncentive idated Damage er Contract Adji		5	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 3040143, Project Item Line Number 0090, Material Set 304014396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 6113020, Project Item Line Number 0200, Material Set 611302096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 6206000C, Project Item Line Number 0300, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 6206000C, Project Item Line Number 0300, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 6206001C, Project Item Line Number 0310, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 6206001C, Project Item Line Number 0310, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 7011105, Project Item Line Number 0540, Material Set 701110596, Material 1005FACCNSCC - Natural Sand for Conc Class C, Acceptance Action Generic 1005FACCNSCC is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 7011105, Project Item Line Number 0540, Material Set 701110596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 7011105, Project Item Line Number 0540, Material Set 701110596, Material 0701PLCA - Casing for Drilled Shafts, Acceptance Action Generic 0701PLCA is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 7011105, Project Item Line Number 0540, Material Set 701110596, Material 0701PLCSLT - Drilled Shaft CSL steel pipe, Acceptance Action Generic 0701PLCSLT is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 7011105, Project Item Line Number 0540, Material Set 701110596, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 7011204, Project Item Line Number 0550, Material Set 701120496, Material 1005FACCNSCC - Natural Sand for Conc Class C, Acceptance Action Generic 1005FACCNSCC is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 7011204, Project Item Line Number 0550, Material Set 701120496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 7011204, Project Item Line Number 0550, Material Set 701120496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 7027000, Project Item Line Number 0610, Material Set 702700096, Material 0702PLPT - Pile Point Reinforcement, Acceptance Action Generic 0702PLPT is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 7032003, Project Item Line Number 0620, Material Set 703200396, Material 1005FACCNSCC - Natural Sand for Conc Class C, Acceptance Action Generic 1005FACCNSCC is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 7032003, Project Item Line Number 0620, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 7032003, Project Item Line Number 0620, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3212, Item 8061017, Project Item Line Number 0440, Material Set 806101796, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-H03, Contract Project J9P3212, Project Item Line Number 0510, Contract Line Item Number 0510, Item 2061000, Minor Item.	No Remark was entered by Engineer	FERGUJ1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200515-H03, Contract Project J9P3212, Project Item Line Number 0540, Contract Line Item Number 0540, Item 7011105, Minor Item.	No Remark was entered by Engineer	FERGUJ1	Overridden
Estimate Exception Type: Item Overrun: Contract 200515-H03, Contract Project J9P3212, Project Item Line Number 0550, Contract Line Item Number 0550, Item 7011204, Minor Item.	No Remark was entered by Engineer	FERGUJ1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-H03	J9P3212	0001	0010	1041000	TEMPORARY SURFACING	24.00	0.00	24.00	CUYD	0.00	\$45.00	\$0.00
		0001	0020	2013000	CLEARING AND GRUBBING	2.00	0.00	2.00	ACRE	2.00	\$2,000.00	\$4,000.00
		0001	0030	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$12,500.00	\$0.00
		0001	0040	2031000	CLASS A EXCAVATION	6,105.00	0.00	6,105.00	CUYD	250.00	\$8.00	\$2,000.00
		0001	0050	2035500	EMBANKMENT IN PLACE	8,680.00	0.00	8,680.00	CUYD	3,896.00	\$11.20	\$43,635.20
		0001	0060	2036000	COMPACTING EMBANKMENT	863.00	0.00	863.00	CUYD	200.00	\$2.00	\$400.00
		0001	0070	2064000	POROUS BACKFILL	62.00	0.00	62.00	CUYD	0.00	\$68.00	\$0.00
		0001	0080	2149907	MISC.Furnishing and Placing Clean Rock Fill	814.00	0.00	814.00	CUYD	814.00	\$32.00	\$26,048.00
		0001	0090	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	3,581.00	0.00	3,581.00	SQYD	3,581.00	\$8.00	\$28,648.00
		0001	0100	3040163	TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)	2,042.00	0.00	2,042.00	SQYD	0.00	\$10.00	\$0.00
		0001	0110	3105003	GRAVEL (A) OR CRUSHED STONE (B)	612.00	0.00	612.00	SQYD	0.00	\$10.00	\$0.00
		0001	0120	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	170.50	0.00	170.50	TONS	0.00	\$100.00	\$0.00
		0001	0130	4019905	MISC.Optional Pavement-bypass	3,580.80	0.00	3,580.80	SQYD	3,580.80	\$38.50	\$137,860.80
		0001	0140	4019905	MISC.Optional Pavement	2,041.50	0.00	2,041.50	SQYD	0.00	\$58.50	\$0.00
		0001	0150	4071005	TACK COAT	139.00	0.00	139.00	GAL	0.00	\$5.50	\$0.00
		0001	0160	6079902	MISC.6" Steel Post	4.00	0.00	4.00	EA	0.00	\$325.00	\$0.00
		0001	0170	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	15.00	0.00	15.00	CUYD	0.00	\$50.00	\$0.00
		0001	0180	6096041	PLACING TYPE 1 ROCK DITCH LINER	15.00	0.00	15.00	CUYD	0.00	\$30.00	\$0.00
		0001	0190	6097000	ROCK LINING	2.00	0.00	2.00	CUYD	0.00	\$105.00	\$0.00
		0001	0200	6113020	FURNISHING TYPE 2 ROCK BLANKET	944.00	0.00	944.00	CUYD	600.00	\$35.00	\$21,000.00
		0001	0210	6113040	PLACING TYPE 2 ROCK BLANKET	944.00	0.00	944.00	CUYD	600.00	\$12.00	\$7,200.00
		0001	0220	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.00
		0001	0230	6161005	CONSTRUCTION SIGNS	569.00	0.00	569.00	SQFT	569.00	\$7.00	\$3,983.00
		0001	0240	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$35.00	\$70.00
		0001	0250	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	2.00	\$20.00	\$40.00
		0001	0260	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	50.00	\$22.00	\$1,100.00
		0001	0270	6161030	TYPE III MOVEABLE BARRICADE	6.00	0.00	6.00	EA	6.00	\$135.00	\$810.00
		0001	0280	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$158,000.00	\$0.00
		0001	0281	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$144,103.00	\$144,103.00
		0001	0290	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	3.00	0.00	3.00	EA	0.00	\$600.00	\$0.00
		0001	0300	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,075.00	0.00	6,075.00	LF	3,042.00	\$0.45	\$1,368.90
		0001	0310	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,075.00	0.00	6,075.00	LF	3,042.00	\$0.45	\$1,368.90
		0001	0320	6207001	PAVEMENT MARKING REMOVAL	570.00	0.00	570.00	LF	570.00	\$1.25	\$712.50
		0001	0330	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN, THICK OR LESS)	1,695.00	0.00	1,695.00	SQYD	0.00	\$5.75	\$0.00
		0001	0340	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	6,321.00	0.00	6,321.00	SQYD	5,841.00	\$2.30	\$13,434.30
		0001	0350	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	18.70	0.00	18.70	STA	0.00	\$725.00	\$0.00
		0001	0360	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.25	\$15,000.00	\$3,750.00
		0001	0370	7250418	18 IN. PIPE GROUP C	33.00	0.00	33.00	LF	0.00	\$45.00	\$0.00
		0001	0380	7250472	72 IN. PIPE GROUP C	723.00	0.00	723.00	LF	723.00	\$140.00	\$101,220.00
		0001	0390	8051000A	SEEDING - COOL SEASON MIXTURES	1.90	0.00	1.90	ACRE	0.00	\$2,850.00	\$0.00
		0001	0400	8061003	SEDIMENT TRAP EXCAVATION	4.00	0.00	4.00	CUYD	0.00	\$55.00	\$0.00
		0001	0410	8061004	SEDIMENT TRAP ROCK	4.00	0.00	4.00	CUYD	4.00	\$85.00	\$340.00
		0001	0420	8061005	ROCK DITCH CHECK	322.00	0.00	322.00	LF	310.00	\$11.50	\$3,565.00
		0001	0430	8061016	SEDIMENT REMOVAL	51.00	0.00	51.00	CUYD	0.00	\$5.00	\$0.00
		0001	0440	8061017	TEMPORARY SEEDING AND MULCHING	0.60	0.00	0.60	ACRE	0.60	\$5,000.00	\$3,000.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

d date and can differ from the posted amount at the time the Estimate was Generated.

					eport Generated date and can differ from the posted ar							1
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200515-H03	J9P3212	0001	0450	8061019	SILT FENCE	731.00	0.00	731.00	LF	289.00	\$3.00	\$867.00
		0001	0460	8061050	TYPE C BERM	1,626.00	0.00	1,626.00	LF	841.00	\$18.00	\$15,138.00
		0010	0470	6061060	MGS GUARDRAIL	163.00	0.00	163.00	LF	0.00	\$22.45	\$0.00
		0010	0480	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	0.00	\$2,875.00	\$0.00
		0010	0490	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,825.00	\$0.00
		0040	0500	9031260	WOOD POST, 4 IN. BY 4 IN.	12.00	0.00	12.00	LF	0.00	\$20.00	\$0.00
		0070	0510	2061000	CLASS 1 EXCAVATION	80.00	0.00	80.00	CUYD	112.00	\$25.00	\$2,800.00
		0070	0520	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$60,000.00	\$60,000.00
		0070	0530	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	128.00	0.00	128.00	SQYD	0.00	\$120.00	\$0.00
		0070	0540	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	26.00	0.00	26.00	LF	33.20	\$950.00	\$31,540.00
		0070	0550	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	40.00	0.00	40.00	LF	48.50	\$750.00	\$36,375.00
		0070	0560	7011300	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	4.00	\$700.00	\$2,800.00
		0070	0570	7011400	FOUNDATION INSPECTION HOLES	80.00	0.00	80.00	LF	80.00	\$150.00	\$12,000.00
		0070	0580	7011600	SONIC LOGGING TESTING	4.00	0.00	4.00	EA	2.00	\$2,000.00	\$4,000.00
		0070	0590	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	160.00	0.00	160.00	LF	148.00	\$95.00	\$14,060.00
		0070	0600	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$400.00	\$800.00
		0070	0610	7027000	PILE POINT REINFORCEMENT	8.00	0.00	8.00	EA	8.00	\$160.00	\$1,280.00
		0070	0620	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	84.10	0.00	84.10	CUYD	33.00	\$850.00	\$28,050.00
		0070	0630	7034213	SLAB ON CONCRETE I-GIRDER	758.00	0.00	758.00	SQYD	0.00	\$340.00	\$0.00
		0070	0640	7034219A	TYPE D BARRIER	491.00	0.00	491.00	LF	0.00	\$90.00	\$0.00
		0070	0650	7056003	TYPE 6 (54 IN.), PRESTRESSED CONCRETE I-GIRDER	879.00	0.00	879.00	LF	0.00	\$225.00	\$0.00
		0070	0660	7061060	REINFORCING STEEL (BRIDGES)	13,740.00	0.00	13,740.00	LB	5,659.00	\$1.30	\$7,356.70
		0070	0670	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	12.00	0.00	12.00	EA	0.00	\$750.00	\$0.00
		0070	0680	7123610	SLAB DRAIN	44.00	0.00	44.00	EA	0.00	\$280.00	\$0.00
		0070	0690	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$1,600.00	\$0.00
		0070	0700	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	0.00	\$200.00	\$0.00
		0070	0710	7161002	LAMINATED NEOPRENE BEARING PAD	16.00	0.00	16.00	EA	0.00	\$220.00	\$0.00
		0001	5001	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$13,897.00	\$13,897.00
	Project J	9P3212 - To	otal Value	Posted to D	Date as of Report Generated Date							\$780,621.30
200515-H03 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$780,621.30



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0200	6113020	FURNISHING TYPE 2 ROCK BLANKET	9/15/20	9/16/20	250.00	CUYD	South Bride End					
				9/16/20	350.00	CUYD	North Bridge End					
0210	6113040	PLACING TYPE 2 ROCK BLANKET	9/15/20	9/16/20	250.00	CUYD	South Bridge End					
				9/16/20	350.00	CUYD	North Bridge End					
0281	6181000	MOBILIZATION	9/3/20	9/15/20	0.50	LS	Mobilization					
0340	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	9/15/20	9/16/20	350.00	SQYD	South Bridge End					
				9/16/20	450.00	SQYD	North Bride End					
0540	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	9/4/20	9/15/20	15.00	LF	Bent 3 - Shafts 3 and 4					
			9/14/20	9/15/20	18.20	LF	Bent 2 - Shafts 1 and 2					
0550	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	9/4/20	9/15/20	20.00	LF	Bent 3 - Shafts 3 and 4					
			9/14/20	9/15/20	10.00	LF	Bent 2 Shaft 2					
				9/15/20	18.50	LF	Bent 2 - Shaft 1					
0560	7011300	VIDEO CAMERA INSPECTION	9/4/20	9/15/20	2.00	EA	Bent 3 - Shafts 3 and 4					
			9/14/20	9/15/20	2.00	EA	Bent 2 - Shaft 1 and 2					
0580	7011600	SONIC LOGGING TESTING	9/10/20	9/15/20	2.00	EA	Bent 3 - Shafts 3 and 4					
0620	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	9/3/20	9/15/20	14.00	CUYD	Bent 4					
			9/14/20	9/15/20	5.00	CUYD	Bent 3 Columns					
0660	7061060	REINFORCING STEEL (BRIDGES)	9/4/20	9/15/20	1,853.00	LB	Bent 3 - Shafts 3 and 4					
			9/14/20	9/15/20	1,571.00	LB	Bent 3 - Columns					
				9/15/20	2,235.00	LB	Bent 2 - Shaft 1 and 2					

The information below this line are details from Line Item agency views. No Agency View Details Exist



Type Adjustment Type Number Type Date By 0050 EMBANKMENT IN PLACE Material 2 Jul 16, 2020 SYSTEM \$43,635.20 2 Jul 16, 2 SYSTEM \$43,635.20 This adjustment offsets the original sy	Remarks al system-generated Overrun Payment due to user ferguj1 overridding Payment nt Payment Estimate.
Image: state of the s	due to user ferguj1 overridding Payment
Atterial - Total 2020 State Estimate Item Adjustment (0001) due Estimate Exception 1 on the current P 0050 - Total - Total \$0.00 <td>due to user ferguj1 overridding Payment</td>	due to user ferguj1 overridding Payment
Material - Total \$0.00 0050 - Total \$0.00 0060 COMPACTING EMBANKMENT Material 2 Jul 16, SYSTEM (\$400.00)	
0050 - Total \$0.00 0060 COMPACTING EMBANKMENT Material 2 Jul 16, SYSTEM (\$400.00)	
0060 COMPACTING EMBANKMENT Material 2 Jul 16, SYSTEM (\$400.00)	
	al system-generated Overrun Payment due to user ferguj1 overridding Payment nt Payment Estimate.
- Total \$0.00	
Material - Total \$0.00	
0060 - Total \$0.00	
0080 MISC. Furnishing and Placing Clean Rock Fill Material 3 Aug 3, 2020 SYSTEM (\$26,048.00)	
	al system-generated Overrun Payment due to user ferguj1 overridding Payment nt Payment Estimate.
4 Aug 17, SYSTEM (\$26,048.00) 2020	
2020 Estimate Item Adjustment (0001) due	al system-generated Overrun Payment due to user ferguj1 overridding Payment nt Payment Estimate.
Estimate Exception 1 on the current P	
- Total \$0.00	
- Total \$0.00	
- Total \$0.00 Material - Total \$0.00	
Image: Control with the control withe control withe control with the control withe control with the co	al system-generated Overrun Payment due to user ferguj1 overridding Payment nt Payment Estimate.
Image: Constraint of the second sec	due to user ferguj1 overridding Payment
Image: Constraint of the second of the se	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment
Image: Constraint of the sector of	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment
- Total \$0.00 Material - Total \$0.00 0080 - Total \$0.00 0090 TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) Material (5 IN) Material (2 IN) <td>due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment</td>	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment
Image: Control in the image: Contrecontrol in the image: Control in the image: Control	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment
Image: Control in the image: Control in theimage: Contrect in the image: Control in the image: Control in the	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate.
Instal S0.00 Material - Total S0.00 0080 - Total S0.00 OCCONSIDENTIAL OF TOTAL S0.00 0090 TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) Material (4 IN. THICK) This adjustment offsets the original sy (5 2020) SYSTEM (5 28,648.00) This adjustment offsets the original sy (5 2020) Estimate Exception 1 on the current P Estimate Exception 1 on the cur	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate.
Integration in the current provided integra	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate.
Image: second	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate.
Material - Total S0.00 0080 - Total \$0.00 0090 TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) Material (4 IN. THICK) Material (5 IN. 2020) SYSTEM \$28,648.00) This adjustment offsets the original sy Estimate Item Adjustment (0002) due Estimate Item Adjustment (00002) due Estimate Item Adjustment (00002) due Estimate I	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate.
Image: Control in the image: Control interval interv	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate.
Image: Control in the	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate.
I totalStoleMaterial - TotalSole0080 - TotalSystem\$20,000090TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)Material I	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate.
Image: Instrument of the second s	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate.
Initial - Total Source Material - Total Source Source OBBC - Total Source So	due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate. al system-generated Overrun Payment due to user ferguj1 overridding Payment int Payment Estimate.



	D		01	F .	A 1 1	0 1 1	. .	
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0200	Material - Total						\$0.00	
0200	Total		_				\$0.00	
0300	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		4	Aug 17, 2020	SYSTEM	(\$1,368.90)	
				4	Aug 17, 2020	SYSTEM	\$1,368.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user ferguj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Sep 2, 2020	SYSTEM	(\$1,368.90)	
				5	Sep 2, 2020	SYSTEM	\$1,368.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user ferguj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	Sep 16, 2020	SYSTEM	(\$1,368.90)	
				6	Sep 16, 2020	SYSTEM	\$1,368.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user ferguj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0300	- Total						\$0.00	
0310	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	Material		4	Aug 17, 2020	SYSTEM	(\$1,368.90)	
	MARKING PAINT, TYPE P BEADS			4	Aug 17, 2020	SYSTEM	\$1,368.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user ferguj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Sep 2, 2020	SYSTEM	(\$1,368.90)	
				5	Sep 2, 2020	SYSTEM	\$1,368.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user ferguj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	Sep 16, 2020	SYSTEM	(\$1,368.90)	
				6	Sep 16, 2020	SYSTEM	\$1,368.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user ferguj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0310	Total						\$0.00	
0410	SEDIMENT TRAP ROCK	Material		2	Jul 16, 2020	SYSTEM	(\$340.00)	
				2	Jul 16, 2020	SYSTEM	\$340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user ferguj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0410	- Total						\$0.00	
0440	TEMPORARY SEEDING AND MULCHING	Material		4	Aug 17, 2020	SYSTEM	(\$3,000.00)	
				4	Aug 17, 2020	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user ferguj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				5	Sep 2,	SYSTEM	(\$3,000.00)	
				5	2020			
				5	2020 Sep 2, 2020	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user ferguj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					Sep 2,	SYSTEM SYSTEM	\$3,000.00 (\$3,000.00)	Estimate Item Adjustment (0005) due to user ferguj1 overridding Payment
				5	Sep 2, 2020 Sep 16,			Estimate Item Adjustment (0005) due to user ferguj1 overridding Payment
			- Total	5	Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM	(\$3,000.00)	Estimate Item Adjustment (0005) due to user ferguj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user ferguj1 overridding Payment
	Material - Total		- Total	5	Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM	(\$3,000.00) \$3,000.00	Estimate Item Adjustment (0005) due to user ferguj1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user ferguj1 overridding Payment



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0460	TYPE C BERM	Material		2	Jul 16, 2020	SYSTEM	(\$11,628.00)	
				2	Jul 16, 2020	SYSTEM	\$11,628.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user ferguj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0460 -	Total						\$0.00	
0510	CLASS 1 EXCAVATION	Overrun	Overrun	5	Sep 2, 2020	SYSTEM	(\$800.00)	
		Overrun - Total				(\$800.00)		
	Overrun - Total						(\$800.00)	
0510 -	Total						(\$800.00)	
0540	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		6	Sep 16, 2020	SYSTEM	(\$31,540.00)	
				6	Sep 16, 2020	SYSTEM	\$31,540.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user ferguj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Overrun	Overrun	6	Sep 16, 2020	SYSTEM	(\$6,840.00)	
				6	Sep 16, 2020	SYSTEM	\$6,840.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 21 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0540 -	Total						\$0.00	
0550	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		6	Sep 16, 2020	SYSTEM	(\$36,375.00)	
				6	Sep 16, 2020	SYSTEM	\$36,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user ferguj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
	ROCK SOCKETS (3 FT 0 IN. DIA.)	Overrun	Overrun	6	Sep 16, 2020	SYSTEM	(\$6,375.00)	
				6	Sep 16, 2020	SYSTEM	\$6,375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 22 on the current Payment Estimate.
		Overrun - Total				\$0.00		
	Overrun - Total						\$0.00	
0550 -) - Total						\$0.00	
0590	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material		5	Sep 2, 2020	SYSTEM	(\$14,060.00)	
				5	Sep 2, 2020	SYSTEM	\$14,060.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user ferguj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0590 -	Total						\$0.00	
0610	PILE POINT REINFORCEMENT	Material		5	Sep 2, 2020	SYSTEM	(\$1,280.00)	
				5	Sep 2, 2020	SYSTEM	\$1,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user ferguj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				6	Sep 16, 2020	SYSTEM	(\$1,280.00)	
				6	Sep 16, 2020	SYSTEM	\$1,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user ferguj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0610	Material - Total						\$0.00	
0610 ·	Total						\$0.00	
0620	CLASS B CONCRETE (SUBSTRUCTURE)	Material		5	Sep 2, 2020	SYSTEM	(\$11,900.00)	
				5	Sep 2, 2020	SYSTEM	\$11,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user ferguj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				6	Sep 16, 2020	SYSTEM	(\$28,050.00)	
				6	Sep 16, 2020	SYSTEM	\$28,050.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user ferguj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0620 -	- Total						\$0.00	
Overa	all - Total						(\$1,233.58)	