

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2021

Progress Estimate Number	Contract ID	200918-D10	Pay Period Start	November 2, 2021	Original Contract Amount	\$565,123.19
7	Prime Contractor	Blevins Asphalt Construction Company	Pay Period End	November 15, 2021	Net Change Order Amount Current Contract Amoun	\$0.00 at\$565,123.19

Approval Date		By User
November 17, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	ahlboc1
November 17, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	browns1
November 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
October 1, 2021	October 1, 2021		84.51%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	October 7, 2020	October 7, 2020	
Letting Date	September 18, 2020	September 18, 2020	
Notice to Proceed Date	November 9, 2020	November 9, 2020	
Open to Traffic Date			
Work Began Date			

Contract Total Pay For Estimate No. 7			
	This Estimate	Previous	To Date
200918-D10			
Total Posted Items Pay	\$0.00	\$477,575.89	\$477,575.89
Gross Item Adjustments	\$0.00	(\$140,242.30)	(\$140,242.30)
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$337,333.59	\$337,333.59
Contract Total Payable This Estimate:	\$0.00		

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		stments Exist on Contract						
Line Item	<u>Adjust</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type Other Item Adjustment Type		Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
01	0120	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-142,252	\$0.11	(\$15,647.72)
	0120	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user ahlboc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	142,252	\$0.11	\$15,647.72
	0130	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-139,132	\$0.11	(\$15,304.52)
	0130	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user ahlboc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	139,132	\$0.11	\$15,304.52

Revision 4/1/2020 Page 1 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2021

Progress Estimate Number 7		Contract ID Prime Contractor	rime Blevins Asphalt Construct		Pay Period Start ion Pay Period End	November 2, 2021 November 15, 2021	Original Con Amount Net Change (Amount Current Cont	\$565,123.19 \$0.00 t \$565,123.19		
Project Number	Line No.			Adjustment Type	Other Item Adjustment Type	Commen	ts	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
Total										\$0.00

Revision 4/1/2020 Page 2 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informatio	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5S3355	FAS- S402(056)	Seal coat	D,V	PULASKI	from Rte. 28 to I-44 and	Maries County Rte. V from	Rte. 42 to Rte. N
Totals by .	Job Numbe	rs					
J5S3355		d Item Pay Item Adjustme		Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$477,575.89 (\$140,242.30) \$337,333.59	To Date \$477,575.89 (\$140,242.30) \$337,333.59
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3355, Item 4135000, Project Item Line Number 0050, Material Set 413500096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	QA error with sampling & testing checklist. All tests have been satisfied.	ahlboc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3355, Item 6206000C, Project Item Line Number 0120, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	QA performance inspection report not complete at this time.	ahlboc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3355, Item 6206000C, Project Item Line Number 0120, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	QA performance inspection report not complete at this time.	ahlboc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3355, Item 6206001C, Project Item Line Number 0130, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	QA performance inspection report not complete at this time.	ahlboc1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3355, Item 6206001C, Project Item Line Number 0130, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	QA performance inspection report not complete at this time.	ahlboc1	Overridden
Estimate Exception Type: Item Overrun: Contract 200918-D10, Contract Project J5S3355, Project Item Line Number 0040, Contract Line Item Number 0040, Item 4094012, Minor Item.	Change Order not complete at this time.	ahlboc1	Acknowledged

Revision 4/1/2020 Page 4 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200918-D10	J5S3355	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.77	\$10,565.00	\$8,135.05
		0001	0020	2153000	SHAPING SLOPES, CLASS III	34.00	0.00	34.00	100F	13.40	\$970.00	\$12,998.00
		0001	0030	4091048	EMULSIFIED ASPHALT, SEAL COAT	62,696.00	0.00	62,696.00	GAL	59,420.00	\$2.12	\$125,970.40
		0001	0040	4094012	SEAL COAT AGGREGATE, GRADE B2	223,913.00	0.00	223,913.00	SQYD	224,511.00	\$0.70	\$157,157.70
		0001	0050	4135000	BITUMINOUS PAVEMENT CRACK SEALING	1,744.00	0.00	1,744.00	LF	1,744.00	\$16.10	\$28,078.40
		0001	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,635.00	\$0.00
		0001	0070	6161005	CONSTRUCTION SIGNS	2,508.00	0.00	2,508.00	SQFT	1,985.00	\$7.15	\$14,192.75
		0001	0080	6161009	FLAG ASSEMBLY	33.00	0.00	33.00	EA	12.00	\$25.55	\$306.60
		0001	0090	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	45.00	\$15.35	\$690.75
		0001	0100	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$2,555.00	\$10,220.00
		0001	0110	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$47,500.00	\$47,500.00
		0001	0120	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	174,822.00	0.00	174,822.00	LF	142,252.00	\$0.11	\$15,647.72
		0001	0130	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	170,840.00	0.00	170,840.00	LF	139,132.00	\$0.11	\$15,304.52
		0010	0140	6061060	MGS GUARDRAIL	1,638.00	0.00	1,638.00	LF	587.50	\$26.00	\$15,275.00
		0010	0150	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	2.00	\$2,860.00	\$5,720.00
		0010	0155	6061074	MGS HEIGHT AND BLOCK TRANSITION	4.00	0.00	4.00	EA	4.00	\$536.00	\$2,144.00
		0010	0160	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,075.00	\$1,075.00
		0010	0170	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	9.00	0.00	9.00	EA	6.00	\$2,860.00	\$17,160.00
	Project J	5S3355 - To	otal Value	Posted to D	Date as of Report Generated Date							\$477,575.89
200918-D10 Ove	erall - Total	Value Pos	ted to Dat	te as of Repo	ort Generated Date							\$477,575.89

Page 5 of 10 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

The info	<u>rmation</u>	below	this line are det	ills for Construction Signs (if applicable).									
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post	
J5S3355	0070	June 17, 2021	867	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		0.003 south	Outer Road	1.00	16			16	
		2021		GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		0.010 south	Rte. V	1.00	10			10	
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		0.013 east	Rte. D	1.00	10			10	
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		0.014 north	Rte. V	1.00	10			10	
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE		0.018 south	Rte. V	1.00	8			8	
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE		0.020 north	Rte. V	1.00	8			8	
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		0.020 west	Rte. D	1.00	10			10	
				WO8-7 36x36 9.00 LOOSE GRAVEL		0.024 east	Rte D Fresh Oil	1.00	9			9	
				WO8-7 36x36 9.00 LOOSE GRAVEL		0.029 south	Rte. V Fresh Oil	1.00	9			9	
				WO8-7 36x36 9.00 LOOSE GRAVEL		0.030 north	Rte. V Fresh Oil	1.00	9			9	
				WO8-12 48x48 16.00 NO CENTER LINE		0.052 west	Rte. D	1.00	16			16	
				WO8-12 48x48 16.00 NO CENTER LINE		0.057 south	Rte. V	1.00	16			16	
				WO8-12 48x48 16.00 NO CENTER LINE		0.058 north	Rte. V	1.00	16			16	
				WO8-12 48x48 16.00 NO CENTER LINE		0.060 east	Rte. D	1.00	16			16	
				WO8-12 48x48 16.00 NO CENTER LINE		0.060 east	Rte. D		16				
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE		0.091 west	Rte. D	1.00	8			8	
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE		0.095 east	Rte. D	1.00	8			8	
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		0.105 south	Rte. V	1.00	12			12	
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		0.130 west	Rte. D	1.00	12			12	
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		0.150 east	Rte. D	1.00	12			12	
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		0.187 north	Rte. V	1.00	12			12	
				WO8-7 36x36 9.00 LOOSE GRAVEL		1.050 east	Rte D Fresh Oil	1.00	9			9	
				WO8-7 36x36 9.00 LOOSE GRAVEL		1.056 north	Rte. V Fresh Oil	1.00	9			9	
				WO8-7 36x36 9.00 LOOSE GRAVEL		1.060 south	Rte. V Fresh Oil	1.00	9			9	
				WO8-7 36x36 9.00 LOOSE GRAVEL		1.060 west	Rte D Fresh Oil	1.00	9			9	
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		1.351 west	Rte. N	1.00	16			16	
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		16.245 west	MO 42	1.00	16			16	
				WO8-7 36x36 9.00 LOOSE GRAVEL		2.030 east	Rte D Fresh Oil	1.00	9			9	
				WO8-7 36x36 9.00 LOOSE GRAVEL		2.055 south	Rte. V Fresh Oil	1.00	9			9	
				WO8-7 36x36 9.00 LOOSE GRAVEL		2.060 west	Rte D Fresh Oil	1.00	9			9	
				WO8-12 48x48 16.00 NO CENTER LINE		2.070 east	Rte. D	1.00	16			16	
				WO8-12 48x48 16.00 NO CENTER		2.083 south	Rte. V	1.00	16			16	

Revision 4/1/2020 Page 6 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable). Project Line DWR **Total Quantity** Sign Information Log Mile Location Number Special SF Each Total Posted For DWR Date Special Sign Number Date of Items Each Sign SF to Sign Post June J5S3355 0070 867 LINE WO8-12 2021 48x48 16.00 NO CENTER 2.092 west Rte. D 1.00 16 16 LINE WO8-7 36x36 9.00 LOOSE 2.096 north Rte. V Fresh Oil 1.00 9 9 **GRAVEL** WO8-12 48x48 16.00 NO CENTER 2.122 north 1.00 16 16 Rte. V LINE WO20-1 48x48 16.00 2.995 east 1.00 16 16 Rte. N ROAD/BRIDGE/RAMP WORK AHEAD WO20-1 48x48 16.00 west bound off Ramp I-44 16 200' south 1.00 16 ROAD/BRIDGE/RAMP WORK AHEAD intersection WO8-7 36x36 9.00 LOOSE Rte. V Fresh Oil 9 9 3.015 north 1.00 GRAVEL WO8-7 36x36 9.00 LOOSE Rte D Fresh Oil 1.00 9 9 3.040 east GRAVEL WO8-7 36x36 9.00 LOOSE 3.040 south Rte. V Fresh Oil 1.00 9 9 **GRAVEL** WO8-7 36x36 9.00 LOOSE 3.084 west Rte D Fresh Oil 1.00 9 9 **GRAVEL** 48x48 16.00 16 3.675 north Outer Road 1.00 16 ROAD/BRIDGE/RAMP WORK AHEAD WO8-7 36x36 9.00 LOOSE 4.005 north Rte. V Fresh Oil 1.00 9 9 GRAVEL WO8-12 48x48 16.00 NO CENTER 4 033 north Rte V 1.00 16 16 WO8-7 36x36 9.00 LOOSE 4.037 south Rte. V Fresh Oil 1.00 9 9 GRAVEL WO8-12 48x48 16.00 NO CENTER 4.069 south 1.00 16 16 LINE WO8-7 36x36 9.00 LOOSE 4.070 west Rte D Fresh Oil 1.00 9 **GRAVEL** WO8-7 9 36x36 9.00 LOOSE 4.097 east Rte D Fresh Oil 1.00 9 GRAVEL WO8-12 48x48 16.00 NO CENTER 4.118 west Rte. D 1.00 16 16 LINE WO8-12 48x48 16.00 NO CENTER 4.145 east Rte. D 1.00 16 16 LINE WO20-1 48x48 16.00 43.925 east MO 42 1.00 16 16 ROAD/BRIDGE/RAMP WORK AHEAD WO8-7 36x36 9.00 LOOSE 5.055 south Rte. V Fresh Oil 1.00 9 9 GRAVEL WO8-7 36x36 9.00 LOOSE Rte. V Fresh Oil 9 5.060 north 1.00 9 GRAVEL WO8-7 36x36 9.00 LOOSE 5.120 west Rte D Fresh Oil 1.00 9 9 GRAVEL WO8-7 36x36 9.00 LOOSE 5.213 east Rte D Fresh Oil 9 9 1.00 **GRAVEL** WO8-7 36x36 9.00 LOOSE 6.044 west Rte D Fresh Oil 1.00 9 9 GRAVEL WO8-7 36x36 9.00 LOOSE 6.047 south Rte. V Fresh Oil 1.00 9 9 GRAVEL WO8-7 36x36 9.00 LOOSE 6.050 north Rte. V Fresh Oil 1.00 9 9 **GRAVEL** WO8-12 48x48 16.00 NO CENTER 6.075 south Rte. V 1.00 16 16 LINE WO8-7 Rte D Fresh Oil 36x36 9.00 LOOSE 6.094 east 1.00 9 GRAVEL

Revision 4/1/2020 Page 7 of 10

6.102 west

6.115 north

6.130 east

Rte. D

Rte. V

Rte. D

16

16

16

1.00

1.00

1.00

16

16

16

WO8-12

LINE

LINE

48x48 16.00 NO CENTER

WO8-12 48x48 16.00 NO CENTER

WO8-12 48x48 16.00 NO CENTER



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

oject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign	Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post																								
3355	0070	June	867	LINE																																	
		17, 2021		WO8-7 36x36 GRAVEL	9.00 LOOSE		6.972 north	Rte. V Fresh Oil	1.00	9			(
				WO8-7 36x36 GRAVEL	9.00 LOOSE		7.079 south	Rte. V Fresh Oil	1.00	9			!																								
				WO8-7 36x36 GRAVEL	9.00 LOOSE		7.120 west	Rte D Fresh Oil	1.00	9			9																								
			WO8-7 36x36 GRAVEL	9.00 LOOSE		7.140 east	Rte D Fresh Oil	1.00	9																												
				GO20-2 48x24 WORK	8.00 END ROAD		7.420 south	Rte. V	1	8																											
				GO20-2 48x24 WORK	8.00 END ROAD		7.445 north	Rte. V	1.00	8																											
				WO8-7 36x36 GRAVEL	9.00 LOOSE		8.117 east	Rte D Fresh Oil	1.00	9																											
				WO8-7 36x36 GRAVEL	9.00 LOOSE		8.146 west	Rte D Fresh Oil	1.00	9																											
				WO8-12 48x48 LINE	16.00 NO CENTER		8.176 east	Rte. D	1.00	16			1																								
																									1	L	W L	WO8-12 48x48 LINE	16.00 NO CENTER		8.186 west	Rte. D	1.00	16			1
				WO8-7 36x36 GRAVEL	9.00 LOOSE		9.050 east	Rte. D Fresh Oil (angle sign face on north side)	1.00	9																											
				GO20-2 48x24 WORK	8.00 END ROAD		9.108 west	Rte. D	1.00	8																											
				GO20-2 48x24 WORK	8.00 END ROAD		9.166 east	Rte. D	1.00	8																											

Revision 4/1/2020 Page 8 of 10



Line Item Adjustments by Estimate

Contract ID:190621-F01

	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
5S3355	0030	EMULSIFIED ASPHALT, SEAL COAT	Material	Type	3	Sep 16, 2021	SYSTEM	\$125,970.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ahlboc1 overridding Payment
					3	Sep 16, 2021	SYSTEM	(\$125,970.40)	Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Other Item Adjustment	SEAL	3	Sep 17, 2021	ahlboc1	\$17,334.00	59420 gallons were used.
				SEAL - Tota	ıl			\$17,334.00	
			Other Item Adjustment - Total					\$17,334.00	
	0030 -	- Total						\$17,334.00	
	0040	SEAL COAT AGGREGATE, GRADE B2	Material		3	Sep 16, 2021	SYSTEM	(\$157,157.70)	
					4	Oct 1, 2021	SYSTEM	(\$157,157.70)	
				- Total				(\$314,315.40)	
			Material - Tota	ıl				(\$314,315.40)	
			MaterialCredit		4	Oct 1, 2021	SYSTEM	\$157,157.70	
					5	Oct 19, 2021	SYSTEM	\$157,157.70	
				- Total				\$314,315.40	
			MaterialCredit	- Total				\$314,315.40	
			Other Item Adjustment OADJ - Total	5	Oct 19, 2021	browns1	(\$157,157.70)	browns1 - this adjustment is to correct the system generated line item overpayment. Line 40 has already been paid up to plan quantity and AWP is trying to pay that item again.	
				OADJ - Tota	al			(\$157,157.70)	
			Other Item Ad	ljustment - Total				(\$157,157.70)	
			Overrun	Overrun					
			Overrun	Overrun	3	Sep 16, 2021	SYSTEM	\$418.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00.
			Overrun	Overrun	3		SYSTEM	\$418.60 (\$418.60)	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000;
			Overrun	Overrun		2021 Sep 16,			Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000;
			Overrun	Overrun	3	2021 Sep 16, 2021 Oct 1,	SYSTEM	(\$418.60)	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates
			Overrun	Overrun	3	2021 Sep 16, 2021 Oct 1, 2021 Oct 1,	SYSTEM SYSTEM	(\$418.60) (\$418.60)	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00.
			Overrun	Overrun - T	3 4 4 5	Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 19,	SYSTEM SYSTEM SYSTEM	(\$418.60) (\$418.60) \$418.60	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates
			Overrun - Tota	Overrun - T	3 4 4 5	Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 19,	SYSTEM SYSTEM SYSTEM	(\$418.60) (\$418.60) \$418.60	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates
	0040 -	· Total		Overrun - T	3 4 4 5	Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 19,	SYSTEM SYSTEM SYSTEM	(\$418.60) (\$418.60) \$418.60 (\$418.60)	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates
	0040 -	-Total 4 IN. WHITE WATERBORNE PAVEMENT		Overrun - T	3 4 4 5	Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 19,	SYSTEM SYSTEM SYSTEM	(\$418.60) (\$418.60) \$418.60 (\$418.60) (\$418.60)	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates
		4 IN. WHITE WATERBORNE	Overrun - Tota	Overrun - T	3 4 4 5 5 otal	2021 Sep 16, 2021 Oct 1, 2021 Oct 19, 2021 Oct 19, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$418.60) (\$418.60) \$418.60 (\$418.60) (\$418.60) (\$157,576.30)	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
		4 IN. WHITE WATERBORNE PAVEMENT	Overrun - Tota	Overrun - T	3 4 4 5 5 otal	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 19, 2021 Oct 19, 2021 Oct 19, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$418.60) (\$418.60) \$418.60 (\$418.60) (\$418.60) (\$418.60) (\$157,576.30) \$15,647.72	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
		4 IN. WHITE WATERBORNE PAVEMENT	Overrun - Tota	Overrun - T	3 4 4 5 5 ootal 5 5 5	2021 Sep 16, 2021 Oct 1, 2021 Oct 19, 2021 Oct 19, 2021 Oct 19, 2021 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$418.60) (\$418.60) \$418.60 (\$418.60) (\$418.60) (\$418.60) (\$157,576.30) \$15,647.72	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ahlboc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		4 IN. WHITE WATERBORNE PAVEMENT	Overrun - Tota	Overrun - T	3 4 4 5 5 5 6	2021 Sep 16, 2021 Oct 1, 2021 Oct 19, 2021 Oct 19, 2021 Nov 2, 2021 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$418.60) (\$418.60) \$418.60 (\$418.60) (\$418.60) (\$418.60) (\$157,576.30) \$15,647.72 (\$15,647.72)	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ahlboc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		4 IN. WHITE WATERBORNE PAVEMENT	Overrun - Tota	Overrun - T	3 4 4 5 5 5 6 6	2021 Sep 16, 2021 Oct 1, 2021 Oct 19, 2021 Oct 19, 2021 Vot 19, 2021 Nov 2, 2021 Nov 16, Nov 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$418.60) (\$418.60) \$418.60 (\$418.60) (\$418.60) (\$418.60) (\$157,576.30) \$15,647.72 (\$15,647.72)	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 224511.000; Overrun Quantity Balance 598.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ahlboc1 overridding Payment Estimate Item Adjustment (0001) due to user ahlboc1 overridding Payment Estimate Item Adjustment (0001) due to user ahlboc1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.





Line Item Adjustments by Estimate

Contract ID:190621-F01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3355	0120	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material - Tota	I				\$0.00	
	0120 -	20 - Total							
	0130	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		5	Oct 19, 2021	SYSTEM	\$15,304.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ahlboc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Oct 19, 2021	SYSTEM	(\$15,304.52)	
					6	Nov 2, 2021	SYSTEM	\$15,304.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ahlboc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Nov 2, 2021	SYSTEM	(\$15,304.52)	
					7	Nov 16, 2021	SYSTEM	\$15,304.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ahlboc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$15,304.52)	
				- Total				\$0.00	
			Material - Total						
	0130 -	0130 - Total							
J5S3355	3355 - Total								
Overall - Total								(\$140,242.30)	