

Pay Estimate Created Date: August 16, 2021

Progress Estimate Number	Contract ID 200918-F02	Pay Period Start August 2, 2021 Original Contract Amount \$10,232,211.33
19	Prime Contractor N.B. West Con	tracting Company Pay Period End August 15, 2021 Net Change Order Amount \$0.00
		Current Contract Amount \$10,232,211.33

Approval Date		By User
August 16, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	dunnj1
August 17, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	janssm
August 18, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
September 30, 2023	September 30, 2023		26.15%

	Contract Informational Dates							
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract					
Acceptance Date								
Awarded Date	October 7, 2020	October 7, 2020						
Letting Date	September 18, 2020	September 18, 2020						
Notice to Proceed Date	March 15, 2021	March 15, 2021						
Open to Traffic Date								
Work Began Date	February 2, 2021	February 2, 2021						

Contract Total Pa	ay For Estimate No. 19			
		This Estimate	Previous	To Date
200918-F02				
	Total Posted Items Pay	\$127,372.16	\$2,547,898.41	\$2,675,270.57
	Gross Item Adjustments	\$53.89	\$80,006.67	\$80,060.56
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$2,627,905.08	\$2,755,331.13
Contract Total Pa	avable This Estimate:	\$127.426.05		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3049	0070	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$5.100	1,112.8	\$5,675.28
	0800	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$2.500	342	\$855.00
	0090	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	TONS	\$125.000	16.07	\$2,008.75
	0130	5024008	CONCRETE BASE (8 IN. NON-REINF)	SQYD	\$61.200	216.5	\$13,249.80
	0210	6081012	TRUNCATED DOMES	SQFT	\$25.000	56	\$1,400.00
	0220	6083006	6 IN. CONCRETE MEDIAN STRIP	SQYD	\$50.000	37.7	\$1,885.00
	0230	6085007	PAVED APPROACH, 7 IN.	SQYD	\$80.000	87.8	\$7,024.00
	0250	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$36.000	1,112.8	\$40,060.80
	0260	6089902	MISC.ADA CURB RAMP	EA	\$300.000	4	\$1,200.00
	0310	6099903	MISC.INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B	LF	\$22.000	947	\$20,834.00
	0350	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$125.000	153	\$19,125.00
	0360	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	SQYD	\$0.010	153	\$1.53
	0370	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	SQYD	\$3.000	153	\$459.00
	0380	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$0.500	198	\$99.00
	0390	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$1.500	72	\$108.00
	1210	9014003	CONDUIT, 3 IN. RIGID, PUSHED	LF	\$31.000	337	\$10,447.00
	1220	9016110	PULL BOX, PREFORMED CLASS 1	EA	\$735.000	4	\$2,940.00

Revision 4/1/2020 Page 1 of 51



Pay Estimate Created Date: August 16, 2021

Progress Estimate Number
19
Contract ID 200918-F02 Pay Period Start August 2, 2021 Original Contract Amount \$10,232,211.33
Prime Contractor N.B. West Contracting Company Pay Period End August 15, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$10,232,211.33

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
Project J65	3049 - To	tal					\$127,372.16
Overall - To	otal						\$127,372.16

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
l6S3049	0070	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material			-7,153.16	\$5.10	(\$36,481.12)
	0070	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	7,153.16	\$5.10	\$36,481.12
	0800	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-4,825.91	\$2.50	(\$12,064.78)
	0080	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	4,825.91	\$2.50	\$12,064.78
	0090	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	16.07	\$3.35	\$53.89
	0130	CONCRETE BASE (8 IN. NON-REINF)	Material			-1,808.8	\$61.20	(\$110,698.56
	0130	CONCRETE BASE (8 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1,808.8	\$61.20	\$110,698.56
	0170	ADJUSTING MANHOLE	Material			-3	\$1,600.00	(\$4,800.00)
	0170	ADJUSTING MANHOLE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	3	\$1,600.00	\$4,800.00
	0190	PIPE COLLAR, TYPE A	Material			-2	\$300.00	(\$600.00
	0190	PIPE COLLAR, TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	2	\$300.00	\$600.00
	0220	6 IN. CONCRETE MEDIAN STRIP	Material			-272.03	\$50.00	(\$13,601.50)
	0220	6 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	272.03	\$50.00	\$13,601.50
	0230	PAVED APPROACH, 7 IN.	Material			-2,861.75	\$80.00	(\$228,940.00)
	0230	PAVED APPROACH, 7 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user dunnj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	2,861.75	\$80.00	\$228,940.00
	0240	PAVED APPROACH, 8 IN.	Overrun		Averaged Price Adjustment from this item on	-19.8	\$84.00	(\$1,663.20)

Revision 4/1/2020 Page 2 of 51



Pay Estimate Created Date: August 16, 2021

Progress Estimate Number
19
Contract ID 200918-F02 Pay Period Start August 2, 2021 Original Contract Amount \$10,232,211.33
Prime Contractor N.B. West Contracting Company Pay Period End August 15, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$10,232,211.33

Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.
			all previous payment estimates of '0.00000' is applied (if non-zero).	-71-			
(\$9,080.40	\$84.00	-108.1			Material	PAVED APPROACH, 8 IN.	0240
\$1,663.20	\$84.00	19.8	This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 104 on the current Payment Estimate. Material Insufficiency Quantity 108.100; Overrun Quantity Balance 19.80.		Overrun	PAVED APPROACH, 8 IN.	0240
\$9,080.40	\$84.00	108.1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.		Material	PAVED APPROACH, 8 IN.	0240
(\$197,609.76	\$36.00	-5,489.16			Material	CONCRETE SIDEWALK, 4 IN.	0250
\$197,609.76	\$36.00	5,489.16	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.		Material	CONCRETE SIDEWALK, 4 IN.	0250
(\$43,500.00	\$300.00	-145			Material	MISC.	0260
\$43,500.00	\$300.00	145	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.		Material	MISC.	0260
(\$76,691.20	\$46.00	-1,667.2			Material	MISC.	0270
\$76,691.20	\$46.00	1,667.2	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user dunnj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.		Material	MISC.	0270
(\$924.00	\$28.00	-33			Material	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	0280
\$924.00	\$28.00	33	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user dunnj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.		Material	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	0280
(\$4,776.20	\$26.00	-183.7			Material	CURB AND GUTTER TYPE B	0290
\$4,776.20	\$26.00	183.7	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user dunnj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.		Material	CURB AND GUTTER TYPE B	0290
(\$700.00	\$100.00	-7			Material	ROCK LINING	0300
\$700.00	\$100.00	7	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user dunnj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.		Material	ROCK LINING	0300
(\$204,888.20	\$22.00	-9,313.1			Material	MISC.	0310
\$204,888.20	\$22.00	9,313.1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user dunnj1 overridding Payment Estimate Exception 52		Material	MISC.	0310

Revision 4/1/2020 Page 3 of 51



Pay Estimate Created Date: August 16, 2021

Progress Estimate Number
19
Contract ID 200918-F02 Pay Period Start August 2, 2021 Original Contract Amount \$10,232,211.33
Prime Contractor N.B. West Contracting Company Pay Period End August 15, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$10,232,211.33

ct	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
49				7.	on the current Payment Estimate.			
	0350	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-449.1	\$125.00	(\$56,137.50
	0350	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user dunnj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.	449.1	\$125.00	\$56,137.50
	0360	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-450.9	\$0.01	(\$4.51
	0360	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user dunnj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.	450.9	\$0.01	\$4.51
	0370	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material			-450.9	\$3.00	(\$1,352.70
	0370	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user dunnj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	450.9	\$3.00	\$1,352.70
	0690	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-28	\$6.00	(\$168.00
	0690	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user dunnj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.	28	\$6.00	\$168.00
	0850	MISC.	Material			-5	\$3,200.00	(\$16,000.00
	0850	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user dunnj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.	5	\$3,200.00	\$16,000.00
	0860	PRECAST CONCRETE MANHOLE - 48 IN.	Material			-6	\$850.00	(\$5,100.00
	0860	PRECAST CONCRETE MANHOLE - 48 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user dunnj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.	6	\$850.00	\$5,100.00
	0950	15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	Material			-1	\$500.00	(\$500.00
	0950	15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.	1	\$500.00	\$500.00
	1250	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material			-450	\$0.50	(\$225.00
	1250	CABLE, 10 AWG 1	Material		This adjustment offsets the original system-	450	\$0.50	\$225.00

Revision 4/1/2020 Page 4 of 51



Pay Estimate Created Date: August 16, 2021

Progress Estimate Number
19
Contract ID 200918-F02 Pay Period Start August 2, 2021 Original Contract Amount \$10,232,211.33
Prime Contractor N.B. West Contracting Company Pay Period End August 15, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$10,232,211.33

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
6S3049		CONDUCTOR, POLE AND BRACKET			generated Material Payment Estimate Item Adjustment (0049) due to user dunnj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.			
	1273	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 2 AWG	Material			-710	\$6.00	(\$4,260.00
	1273	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 2 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0053) due to user dunnj1 overridding Payment Estimate Exception 70 on the current Payment Estimate.	710	\$6.00	\$4,260.00
	1277	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material			-2,820	\$2.70	(\$7,614.00
	1277	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0052) due to user dunnj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.	2,820	\$2.70	\$7,614.00
	1290	MISC.	Material			-4	\$3,104.00	(\$12,416.00
	1290	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0050) due to user dunnj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.	4	\$3,104.00	\$12,416.00
	1293	MISC.	Material			-5	\$1,539.00	(\$7,695.00
	1293	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0051) due to user dunnj1 overridding Payment Estimate Exception 73 on the current Payment Estimate.	5	\$1,539.00	\$7,695.00
	1300	SIGNAL HEAD, TYPE 3B	Material			-11	\$1,015.00	(\$11,165.00
	1300	SIGNAL HEAD, TYPE 3B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.	11	\$1,015.00	\$11,165.00
	1310	SIGNAL HEAD, TYPE 4B	Material			-11	\$1,038.00	(\$11,418.00
	1310	SIGNAL HEAD, TYPE 4B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user dunnj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.	11	\$1,038.00	\$11,418.00
	1320	SH-FLAT SHEET - SIGNAL SIGN	Material			-121.4	\$29.00	(\$3,520.60
	1320	SH-FLAT SHEET - SIGNAL SIGN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user dunnj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.	121.4	\$29.00	\$3,520.60
	1330	SIGNAL SIGN, MOUNTING HARDWARE	Material			-20	\$41.00	(\$820.00
	1330	SIGNAL SIGN, MOUNTING HARDWARE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user dunnj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.	20	\$41.00	\$820.00
	1340	POST, SIGNAL 8 FT. OR 2.4	Material			-15	\$640.00	(\$9,600.00)

Revision 4/1/2020 Page 5 of 51



Pay Estimate Created Date: August 16, 2021

Progress Estimate Number
19
Contract ID 200918-F02 Pay Period Start August 2, 2021 Original Contract Amount \$10,232,211.33
Prime Contractor N.B. West Contracting Company Pay Period End August 15, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$10,232,211.33

	L'AIIIOUIIL D							
Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.	roject umber
\$9,600.00	\$640.00	15	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user dunnj1 overridding Payment Estimate Exception 78 on the current Payment Estimate.		Material	M POST, SIGNAL 8 FT. OR 2.4 M	1340	33049
(\$2,826.00	\$942.00	-3			Material	POST, SIGNAL 15 FT. OR 4.6 M	1350	
\$2,826.00	\$942.00	3	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Exception 80 on the current Payment Estimate.		Material	POST, SIGNAL 15 FT. OR 4.6 M	1350	
(\$6,806.00	\$6,806.00	-1			Material	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1355	
\$6,806.00	\$6,806.00	1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0048) due to user dunnj1 overridding Payment Estimate Exception 82 on the current Payment Estimate.		Material	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1355	
(\$8,046.00	\$8,046.00	-1			Material	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	1357	
\$8,046.00	\$8,046.00	1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user dunnj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.		Material	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	1357	
(\$14,998.00	\$7,499.00	-2			Material	POST, TYPE C, 40 FT. ARM OR 12.2 M ARM	1370	
\$14,998.00	\$7,499.00	2	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment Estimate Exception 86 on the current Payment Estimate.		Material	POST, TYPE C, 40 FT. ARM OR 12.2 M ARM	1370	
(\$7,770.00	\$7,770.00	-1			Material	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	1380	
\$7,770.00	\$7,770.00	1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user dunnj1 overridding Payment Estimate Exception 88 on the current Payment Estimate.		Material	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	1380	
(\$16,155.00	\$16,155.00	-1			Material	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1390	
\$16,155.00	\$16,155.00	1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user dunnj1 overridding Payment Estimate Exception 90 on the current Payment Estimate.		Material	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1390	
(\$1,744.65	\$0.45	-3,877			Material	CABLE, 16 AWG 2 CONDUCTOR	1430	
\$1,744.65	\$0.45	3,877	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user dunnj1 overridding Payment Estimate Exception 91 on the current Payment Estimate.		Material	CABLE, 16 AWG 2 CONDUCTOR	1430	
(\$1,202.96	\$0.88	-1,367			Material	CABLE, 16 AWG 3 CONDUCTOR	1440	
\$1,202.96	\$0.88	1,367	This adjustment offsets the original system-		Material	CABLE, 16 AWG 3	1440	

Revision 4/1/2020 Page 6 of 51



Pay Estimate Created Date: August 16, 2021

Progress Estimate Number
19
Contract ID 200918-F02 Pay Period Start August 2, 2021 Original Contract Amount \$10,232,211.33
Prime Contractor N.B. West Contracting Company Pay Period End August 15, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$10,232,211.33

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
6S3049		CONDUCTOR			generated Material Payment Estimate Item Adjustment (0036) due to user dunnj1 overridding Payment Estimate Exception 92 on the current Payment Estimate.			
	1450	CABLE, 16 AWG 5 CONDUCTOR	Material			-3,902	\$1.05	(\$4,097.10
	1450	CABLE, 16 AWG 5 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0037) due to user dunnj1 overridding Payment Estimate Exception 93 on the current Payment Estimate.	3,902	\$1.05	\$4,097.10
	1460	CABLE, 16 AWG 7 CONDUCTOR	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-598	\$1.50	(\$897.00
	1460	CABLE, 16 AWG 7 CONDUCTOR	Material			-4,278	\$1.50	(\$6,417.00
	1460	CABLE, 16 AWG 7 CONDUCTOR	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0038) overridding Payment Estimate Exception 105 on the current Payment Estimate. Material Insufficiency Quantity 4278.000; Overrun Quantity Balance 598.00.	598	\$1.50	\$897.00
	1460	CABLE, 16 AWG 7 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0039) due to user dunnj1 overridding Payment Estimate Exception 94 on the current Payment Estimate.	4,278	\$1.50	\$6,417.00
	1470	RG-8/U COAXIAL CABLE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-311	\$1.00	(\$311.00
	1470	RG-8/U COAXIAL CABLE	Material			-1,678	\$1.00	(\$1,678.00
	1470	RG-8/U COAXIAL CABLE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0040) overridding Payment Estimate Exception 106 on the current Payment Estimate. Material Insufficiency Quantity 1678.000; Overrun Quantity Balance 311.00.	311	\$1.00	\$311.00
	1470	RG-8/U COAXIAL CABLE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0041) due to user dunnj1 overridding Payment Estimate Exception 95 on the current Payment Estimate.	1,678	\$1.00	\$1,678.00
	1510	BASE, CONCRETE	Material			-25.06	\$1,400.00	(\$35,084.00
	1510	BASE, CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0042) due to user dunnj1 overridding Payment Estimate Exception 96 on the current Payment Estimate.	25.06	\$1,400.00	\$35,084.00
	1520	MISC.	Material			-0.2	\$12,600.00	(\$2,520.00
	1520	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment Estimate Exception 99 on the current Payment Estimate.	0.2	\$12,600.00	\$2,520.00
	1530	MISC.	Material			-26	\$732.00	(\$19,032.00
	1530	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0045) due to user dunnj1	26	\$732.00	\$19,032.00

Revision 4/1/2020 Page 7 of 51



Pay Estimate Created Date: August 16, 2021

Progress Estimate Number
19
Contract ID 200918-F02 Pay Period Start August 2, 2021 Original Contract Amount \$10,232,211.33
Prime Contractor N.B. West Contracting Company Pay Period End August 15, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$10,232,211.33

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
l6S3049					overridding Payment Estimate Exception 101 on the current Payment Estimate.			
	1550	MISC.	Material			-26	\$440.00	(\$11,440.00)
	1550	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0044) due to user dunnj1 overridding Payment Estimate Exception 100 on the current Payment Estimate.	26	\$440.00	\$11,440.00
	1590	MISC.	Material			-2	\$8,460.00	(\$16,920.00)
	1590	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0046) due to user dunnj1 overridding Payment Estimate Exception 102 on the current Payment Estimate.	2	\$8,460.00	\$16,920.00
	1610	MISC.	Material			-1	\$2,166.00	(\$2,166.00)
	1610	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0047) due to user dunnj1 overridding Payment Estimate Exception 103 on the current Payment Estimate.	1	\$2,166.00	\$2,166.00
otal								\$53.89

Revision 4/1/2020 Page 8 of 51



						Contract Project Information	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6S3049	FAF- S500(33)	Coldmill and resurface	180	ST LOUIS	from Interstate 170 to St. Lo	ouis City limits	
Totals by J	Job Numbe	ers					
J6S3049		d Item Pay Item Adjustm		item Pay	This Estimate \$127,372.16 \$53.89 \$127,426.05	Previous \$2,547,898.41 \$80,006.67 \$2,627,905.08	To Date \$2,675,270.57 \$80,060.56 \$2,755,331.13
	Liquid	tive centive dated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 9 of 51



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 3040143, Project Item Line Number 0070, Material Set 304014396, Material 1007RCBT1T5 - Agg Base T1/T5 Reclaimed Concrete, Acceptance Action Generic 1007RCBT1T5 is insufficient.	Awaiting QA/QC aggregate tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 3040504, Project Item Line Number 0080, Material Set 304050496, Material 1007RCBT1T5 - Agg Base T1/T5 Reclaimed Concrete, Acceptance Action Generic 1007RCBT1T5 is insufficient.	Awaiting QA/QC aggregate tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 5024008, Project Item Line Number 0130, Material Set 502400896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 5024008, Project Item Line Number 0130, Material Set 502400896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 5024008, Project Item Line Number 0130, Material Set 502400896, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 5024008, Project Item Line Number 0130, Material Set 502400896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 5024008, Project Item Line Number 0130, Material Set 502400896, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 5024008, Project Item Line Number 0130, Material Set 502400896, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 5024008, Project Item Line Number 0130, Material Set 502400896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 5024008, Project Item Line Number 0130, Material Set 502400896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6042010, Project Item Line Number 0170, Material Set 6042010, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6042010, Project Item Line Number 0170, Material Set 6042010, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6042010, Project Item Line Number 0170, Material Set 6042010, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6042010, Project Item Line Number 0170, Material Set 6042010, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6044011, Project Item Line Number 0190, Material Set 604401196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6044011, Project Item Line Number 0190, Material Set 604401196, Material 0604CPCR - Collar for Pipe Connection, Acceptance Action Generic 0604CPCR is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6044011, Project Item Line Number 0190, Material Set 604401196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6049902, Project Item Line Number 0200, Material Set 604990296, Material 0604CPCR - Collar for Pipe Connection, Acceptance Action Generic 0604CPCR is insufficient.	Sample record will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6083006, Project Item Line Number 0220, Material Set 608300696, Material 1057JMDBEC6.02 - Dowel Bar Epoxy Ctd Gr60 0 5/8" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6083006, Project Item Line Number 0220, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6083006, Project Item Line Number 0220, Material Set 608300696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6083006, Project Item Line Number 0220, Material Set 608300696, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6085007, Project Item Line Number 0230, Material Set 608500796, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6085007, Project Item Line Number 0230, Material Set 608500796, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr	Awaiting QA/QC tests	dunnj1	Overridden

Revision 4/1/2020 Page 10 of 51



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period	Cyplanation	Futured	Ctatus
Exceptions / Discrepencies	Explanation	Entered By	Status
40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6085007, Project Item Line Number 0230, Material Set 608500796, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6085007, Project Item Line Number 0230, Material Set 608500796, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6085007, Project Item Line Number 0230, Material Set 608500796, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6085007, Project Item Line Number 0230, Material Set 608500796, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6085008, Project Item Line Number 0240, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6085008, Project Item Line Number 0240, Material Set 608500896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6085008, Project Item Line Number 0240, Material Set 608500896, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6085008, Project Item Line Number 0240, Material Set 608500896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6085008, Project Item Line Number 0240, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6085008, Project Item Line Number 0240, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6086004, Project Item Line Number 0250, Material Set 608600496, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6086004, Project Item Line Number 0250, Material Set 608600496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6086004, Project Item Line Number 0250, Material Set 608600496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6089902, Project Item Line Number 0260, Material Set 608990296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6089902, Project Item Line Number 0260, Material Set 608990296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6089902, Project Item Line Number 0260, Material Set 608990296, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6089905, Project Item Line Number 0270, Material Set 6089905, Material 1056TM - Tinting Material for Concrete, Acceptance Action Generic 1056TM is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6089905, Project Item Line Number 0270, Material Set 6089905, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6089905, Project Item Line Number 0270, Material Set 6089905, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6091010, Project Item Line Number 0280, Material Set 609101096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6091010, Project Item Line Number 0280, Material Set 609101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6091010, Project Item Line Number 0280, Material Set 609101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6091010, Project Item Line Number 0280, Material Set 609101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6091052, Project Item Line	Awaiting QA/QC tests	dunnj1	Overridden

Revision 4/1/2020 Page 11 of 51



Exceptions (Discrepancies) This Estimate Period

Number 0250. Maleral Set 00910538. Alberial 100010. P.CPALD - PCOFP or Majoriny Y Max LSDQ. Accipration Actino Control. VISION D'CHALD is structured. Accipration Actino Control. VISION D'CHALD IS SECURITY OF Accipration. Actino Control. VISION Actino Island in Control. VISION Actino Island Island Into Control. VISION D'CHALD ISland I	Exceptions (Discrepancies) This Estimate Period			- · ·
Acceptance Action General (1907) DC COMM by insulfacion III. Acceptance Action of Common (1907) De Common (Exceptions / Discrepencies	Explanation	Entered By	Status
Number 2005, Material Set 609105050, Named 10510CDA A Concrete, Class B Willin, Acceptance Acceptance Acceptance Patients (Concrete, Class B Willing Acceptance Acceptance Acceptance Patients (Concrete, Class B William) (Concrete, William) (Concrete, Class B William) (Concrete, William) (Concrete, Class B Will	Number 0290, Material Set 609105296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.			
Number 2012, Malerial Set 6010105005, Material 1005ACCHS. CA. Natural Sand for Core Class A, Acceptance Addron Graver 1009ACCHS CA. to membrane. Editantal Exception Plant Control Materials Project Sas SSSUR, Nam (2017) (Project Nam University Control Materials Project Sas SSSUR), Nam (2017) (Project Nam University Control Materials Project Sas SSSUR), Nam (2017) (Project Nam University Control Materials Project SSSUR), Nam (2018) (Project Nam University Control Materials Project SSSUR), Nam (2018) (Project Nam University Control Materials Project SSSUR), Nam (2018) (Project Nam University Control Materials Project SSSUR), Nam (2018) (Project Nam University Control Materials Project SSSUR), Nam (2018) (Project Nam University Control Materials Project SSSUR), Nam (2018) (Project Nam University Control Nam University Control Materials Project SSSUR), Nam (2018) (Project Nam University Control Nam University	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6091052, Project Item Line Number 0290, Material Set 609105296, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 2000, Material Set 6007000000, Material Set 6007000000, Material Set 600700000, Material Set 600700000, Material Set 60070000, Material Set 600700000, Material Set 600700000, Material Set 60070000000000000000000000000000000000	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6091052, Project Item Line Number 0290, Material Set 609105296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 2013, Material Set G0090303, Material G0510CD. A. Concrete, Class B WAIY, Acceptance Action Gorner (G010CD. As inclinificant. Set Foreign Type: Insufficial Materials: Project J853049, Item 6151010, Project Item Line Concrete, As insufficiant Materials: Project J853049, Item 6151010, Project Item Line Concrete, Acceptance Action Generic 10054A-CSCS Insufficiant Statistics (10054A-CSCS). Acceptance Action Generic 10054A-CSCS As in sufficiant Insufficial Statistics (10054A-CSCS). Acceptance Action Generic 10054A-CSCSS Local Statistics (10054A-CSCSS). Acceptance Action Generic 10054A-CSCSS Local Statistics (10054A-CSCSS). Acceptance Action Generic 10054A-CSCSS Local Statistics (10054A-CSCSSS). Acceptance Action Generic 10054A-CSCSSS Local Statistics (10054A-CSCSSSS). Acceptance Action Generic 10054A-CSCSSSSS Local Statistics (10054A-CSCSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSS	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6097000, Project Item Line Number 0300, Material Set 609700096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0203, Material See (8 101009), Material Project Seb	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6099903, Project Item Line Number 0310, Material Set 6099903, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0350, Material 35 et 61 3101098, Material 10058-ACONS. CA in stuturid Sand for Conc Class A, Acceptance Action Generic 10054-ACOS, CA in insufficient Exception Type: Insufficient Materials Project JSS3049, Item 6131010, Project Item Line Number 0350, Material 45 et 31010-05, Material 45 et 31010-05, Material 10010 LocyCALD - PCQP or Masonry IT Max LSDO, Acceptance Action Generic 10059-05, Acceptance Action Generic 10050-05, CPC-MLD is manifester. Exception Type: Insufficient Materials Project JSS3049, Item 6131012, Project Item Line Order Management of Common Project JSS3049, Item 6131012, Project Item Line Number 0250, Material 10010-07, ROBITTS is manifester. Exception Type: Insufficient Materials Project JSS3049, Item 6101012, Project Item Line Number 0250, Material 10010-07, ROBITTS is manifester. Exception Type: Insufficient Materials Project JSS3049, Item 6200124A, Project Item Line Number 0250, Material 1001-07, ROBITTS is manifester. Exception Type: Insufficient Materials: Project JSS3049, Item 6200124A, Project Item Line Number 0250, Material 10048-PMRETP is insufficient. Exception Type: Insufficient Materials: Project JSS3049, Item 6200124A, Project Item Line Number 0250, Material 10048-PMRETP is insufficient. Exception Type: Insufficient Materials: Project JSS3049, Item 6200124A, Project Item Line Number 0250, Material 10048-PMRETP is insufficient. Extension and the Control 10048-PMRETP is	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6131010, Project Item Line Number 0350, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0380, Material Set 613 110969, Material 101056 10, CPCMID - PCCP or Masoniny 1 Max LSIDO, Acceptance Action Generic 100510 - CPCMID is insufficient. Estimate Exception Type: Insufficient Materials: Project J853049, Item 81 31012, Project Item Line Number 0380, Material Set 61 311025 Askanian 2000XCS - Compacted Soll for Subgrade of Enhantment, Acceptance Action Generic 1000XCXCS is insufficient. Estimate Exception Type: Insufficient Materials: Project J853049, Item 81 31013, Project Item Line Number 0370, Material Set 61 3101396, Material 100XCR 201131 - Applicat J853049, Item 81 2001314, Project Item Line Number 0370, Material Set 610 110386, Material 100XCR 201131 - Insufficient. Estimate Exception Type: Insufficient Materials: Project J853049, Item 82001324A, Project Item Line Number 0380, Material Set 62001324A, Material 100XCR 201131 - Insufficient. Estimate Exception Type: Insufficient Materials: Project J853049, Item 82001324A, Project Item Line Number 0380, Material Set 62001324A, Material 1048FMTRP is insufficient. Estimate Exception Type: Insufficient Materials: Project J853049, Item 82001324A, Project Item Line Number 0380, Material Set 6200134A, Material 1048FMTRP Insufficient Materials: Project J853049, Item 82001324A, Project Item Line Number 0380, Material Set 6200134A, Material 1048FMTRP Insufficient Materials: Project J853049, Item 82001324A, Project Item Line Number 0380, Material Set 6200134A, Material 1048FMTRP Insufficient Materials: Project J853049, Item 720902, Project Item Line Number 0380, Material Set 6200134A, Materials Set 720902, Material Set 720902, Materials Set 720902, Material Set	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6131010, Project Item Line Number 0350, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number (1930, Material Set 61 310126), Material (2020XXCS - Compacted Soil for Subgrade ortherhankment, Acceptance Action Generic (2020XXCS is subtilicient.) Estimate Exception Type: Instifficient Materials: Project J853304), Item (717) Reclaimed Concrusts, Acceptance Action Generic 1007-RCSF1175 is instifficient. Concrusts, Acceptance Action Generic 1045PMRRTP resident (1987-1987). Available (1987-1987-1987) and the Acceptance Action Generic 1045PMRTRHSWWH-instifficient Materials. Project J853304), Item (20124A, Project Item Line Number 0500, Material Set 2605124A9, Material 1045PMRTRHSWWH-instifficient. Concrusts (1987-1987) and the Acceptance Action Generic 1045PMRTRHSWWH-instifficient. Concrusts (1987-1987) and the Action Generic 1045PMRTRHSWWH-instifficient. Concrusts (1987-1987) and the Acceptance Action Generic 1045PMRTRHSWWH-instifficient. Concrusts (1987-1987) and the Action Generic 1045PMRTRWWH-instifficient. Concrusts (1987-1987) and the Action Generic 10510-1078-1088-1088-1088-1088-1088-1088-10	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6131010, Project Item Line Number 0350, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0370, Material Set of 13101396, Material 1007. RCBT115 - Agg Base T1/T5 Reclaimed Connecte, Acceptance Action Genetic 1007. RCBT135 is instificient. Estimate Exception Type: Instificient Materials: Project JSS3049, Item 2008124A, Project Item Line Number 0890, Material Set 2008124AB, Material 1045PMRETP T- Reflective Glass Beads Type P Perf Spec. Acceptance Action Genetic 1048PMRETP Is Instificient. Estimate Exception Type: Instificient Materials: Project JSS3049, Item 2008124A, Project Item Line Number 0990, Material Set 2008124AB, Material 1045PMTRHBWHH Handrials Plant Acrylic Water Halld White. Acceptance Action Genetic 1048PMTRHBWHHH Handrials Plant Acrylic Water Halld White. Acceptance Action Genetic 1048PMTRHBWHH Handrials Plant Acrylic Waterborne White, Acceptance Action Genetic 1048PMTRHBWHH Handrials Plant Acrylic Waterborne White, Acceptance Action Genetic 1048PMTRHBWHH Handrials Plant Acrylic Waterborne White, Acceptance Action Genetic 1048PMTRHBWHH Handrials Plant Acrylic Waterborne White, Acceptance Action Genetic 1048PMTRHBWHH Handrials Plant Acrylic Waterborne White, Acceptance Action Genetic 1048PMTRHBWHH Handrials Plant Acrylic Waterborne White, Acceptance Action Genetic 1048PMTRHBWHH Handrials Plant Acrylic Waterborne White, Acceptance Action Genetic 10510 CDCPCMLD is instificient. Estimate Exception Type: Insufficient Materials: Project JSS3040, Item 7269902, Project Item Line Number 0850, Material State Vision Waterials Project JSS3040, Item 7269902, Project Item Line Number 0850, Material State Vision Waterials Project JSS3040, Item 7269902, Project Item Line Number 0850, Material State Vision Waterials Project JSS3040, Item 7269902, Project Item Line Number 0850, Material State Vision Waterials Project JSS3040, Item 7269902, Project Item Line Number 0850, Material State Vision Waterials Project JSS3040, Item 7269902, Project Item Line Number 0850, Material State Vision Waterials Project JSS3040, Item 7269902, Project Item Line Number 0850, Material State Vision Materials Project	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6131012, Project Item Line Number 0360, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 6890, Material Set 6206124A96, Material UNEPMRRTP is insufficient. Estimate Exception Type: Insufficient Materials: Project, 1853049, Item 6206124A, Project Item Line Number 6800, Material Set 6206124A6, Material Set 7206902, Project Item Line Number 6800, Material Set 7206902, Material Set 7206902, Project Item Line Number 6800, Material Set 7206902, Material Set 7206902, Project Item Line Number 6800, Material Set 7206902, Material Set 7206902, Project Item Line Number 6800, Material Set 7206902, Material Set 7206902, Project Item Line Number 6800, Material Set 7206902, Material Set 7206902, Material Set 7206902, Material Set 7206902, Project Item Line Number 6800, Material Set 7206902, Material Set 7206902, Project Item Line Number 6800, Material Set 7206902, Materia	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6131013, Project Item Line Number 0370, Material Set 613101396, Material 1007RCBT1T5 - Agg Base T1/T5 Reclaimed Concrete, Acceptance Action Generic 1007RCBT1T5 is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0690, Material Set 6206124496, Material 1045PMTRHBWBWH is instifficent. Estimate Exception Type: Insufficient Materials: Project J653049, Item 7269902, Project Item Line Number 0600, Material Set 7269902, Material 1051-010-010-010-010-010-010-010-010-010	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6206124A, Project Item Line Number 0690, Material Set 6206124A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0690, Material Set 6206124A96, Material 1048PMTRW9WH is insufficient Miles (Acceptance Action Generic 1049PMTRW9WH is insufficient Mumber 0690, Material Set 7269902, Material South Set 1048DMTRW9WH is insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0690, Material Set 7269902, Material South Set Materials (Project J6S3049), Item 7269902, Project Item Line Number 0690, Material Set 7269902, Material South Acceptance Action Generic 1005FACCNS. CA Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. CA Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. CA Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS. CA Natural Sand For Conc Class A, Acceptance Action Generic 1005FACCNS. CA Natural Sand For Concrete, Class B wAlf. Acceptance Action Generic 1005FACCNS. CA Natural Sand For Concrete, Class B wAlf. Acceptance Action Generic Rosport Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material OSGAMA. Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material Set 7269902, Material Set 7269902, Material Set 7269902, Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, M	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6206124A, Project Item Line Number 0690, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0850, Material set 7269902, Material 100510CPCMLD is nusfficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1005FACONS. CA - Natural Sand for Conc Class A. Acceptance Action Generic 1009FACONS. CA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Project Item Line Number 0850, Material Set 7269902, Material Set 7269902, Project Item Line Number 0850, Material Set 7269902, Material Set 7269902, Project Item Line Number 0850, Material Set 7269902, Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material Set 7269902, Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST2 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST2 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST2 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7310048, Project Item Line Number 0850, Material Set 731004896, Material 1055CMMLDST10 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7310048, Project Item Line Number 0850, Material Set 731004896, Material 1035CMMLDST10 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 73100489, Project Item Line Number 0850, Material Set 7320015A9, Material 1035CMAC is Insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 731004896, Material Set 730015A96, Material 1030015APC Project Item Line Number 0850, Material Set 730015A96, Material 1030015	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 6206124A, Project Item Line Number 0690, Material Set 6206124A96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0850, Material Set 7269902, Material 1005FACCNS. CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005Ch Sci insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 0501CCB. A i smufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M20 @ Acceptance Action Generic 0501CMB. A sustificient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST2 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST2 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST2 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST1 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7310048, Project Item Line Number 0860, Material Set 731004896, Material 1033MHRCPK - Precast Conc Manhole, Acceptance Action Generic 1053MHRCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7310048, Project Item Line Number 0860, Material Set 731004896, Material 10305AC - Flared End Section Aluminum coated steel, Acceptance Action Generic 10305MHRCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017110, Project Item Line Number 0850, Material Set 7310711096, Material 9011LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0850, Material Set 7269902, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 600/M420 @, Acceptance Action Generic ReSteelBars is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST10 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7310048, Project Item Line Number 0860, Material Set 731004896, Material 1033MHRCPK - Precast Conc Manhole, Acceptance Action Generic 1033MHRCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7320015A, Project Item Line Number 0950, Material Set 7320015A96, Material 1020ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 1020ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 10901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017401, Project Item Line Number 1273, Material Set 90171096, Material 9001LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017407, Project Item Line Numb	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0850, Material Set 7269902, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST2 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST1b is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST1D is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7310048, Project Item Line Number 0850, Material Set 73100489, Material 1033MHRCPK - Precast Conc Manhole, Acceptance Action Generic 1025MMLDST1D is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7320015A, Project Item Line Number 0950, Material Set 7320015A96, Material 1030ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 1020ESAC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017110, Project Item Line Number 1250, Material Set 90171096, Material 901LHXX - Highway Lighting Material, Acceptance Action Generic 1020ESAC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017401, Project Item Line Number 1273, Material Set 901740196, Material 9001LHXX - Highway Lighting Material, Acceptance Action Generic 02001LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017401, Project Item Line Number 1277, Material Set 901740796, Material Set 901740796, Material Set 901740796, Material Set 90174079, Material Set 90174079, Material Set 90174079, Material Set 901740796, Material Set 901740796, Material Set 90174079, Material Set 901740796, Material Set 90174079, Material Set 901740796, Material Set 901740	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0850, Materiál Set 7269902, Material 1055CMMLDST2 is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7310048, Project Item Line Number 0860, Material Set 7020015A96, Material 1033MHRCPK - Precast Conc Manhole, Acceptance Action Generic 1035MHRCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7310048, Project Item Line Number 0860, Material Set 731004896, Material 1033MHRCPK - Precast Conc Manhole, Acceptance Action Generic 1033MHRCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7320015A, Project Item Line Number 0950, Material Set 7320015A96, Material 1020ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 1020ESAC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017110, Project Item Line Number 1250, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017401, Project Item Line Number 1273, Material Set 9017140196, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017401, Project Item Line Number 1273, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017407, Project Item Line Number 1277, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient Materials: Project J6S3049, Item 9017407, Project Item Line Number 1277, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0850, Material Set 7269902, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7310048, Project Item Line Number 0860, Material Set 731004896, Material 1033MHRCPK - Precast Conc Manhole, Acceptance Action Generic 1033MHRCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7320015A, Project Item Line Number 0950, Material Set 7320015A96, Material 1020ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 1020ESAC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017110, Project Item Line Number 1250, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017401, Project Item Line Number 1273, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017407, Project Item Line Number 1277, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Number 1277, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0860, Material Set 731004896, Material 1033MHRCPK - Precast Conc Manhole, Acceptance Action Generic 1033MHRCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7320015A, Project Item Line Number 0950, Material Operation of Generic 1020ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 1020ESAC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017110, Project Item Line Number 1250, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017401, Project Item Line Number 1273, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017407, Project Item Line Number 1277, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Number 1277, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Number 1277, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7269902, Project Item Line Number 0850, Material Set 7269902, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Number 0950, Material Set 7320015A96, Material 1020ESAC - Flared End Section Alúminum coated steel, Acceptance Action Generic 1020ESAC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017110, Project Item Line Number 1250, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient Materials: Project J6S3049, Item 9017401, Project Item Line Number 1273, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient Materials: Project J6S3049, Item 9017401, Project Item Line Number 1273, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHX is insufficient Materials: Project J6S3049, Item 9017407, Project Item Line Number 1277, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7310048, Project Item Line Number 0860, Material Set 731004896, Material 1033MHRCPK - Precast Conc Manhole, Acceptance Action Generic 1033MHRCPK is insufficient.	Awaiting materials inspection	dunnj1	Overridden
Number 1250, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017401, Project Item Line Number 1273, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017407, Project Item Line Number 1277, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 7320015A, Project Item Line Number 0950, Material Set 7320015A96, Material 1020ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 1020ESAC is insufficient.	Sample record will be entered soon	dunnj1	Overridden
Number 1273, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017407, Project Item Line Number 1277, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Lighting sample records will be entered soon dunnj1 Overridden	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017110, Project Item Line Number 1250, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Lighting sample records will be entered soon	dunnj1	Overridden
Number 1277, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017401, Project Item Line Number 1273, Material Set 901740196, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Lighting sample records will be entered soon	dunnj1	Overridden
	Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9017407, Project Item Line Number 1277, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Lighting sample records will be entered soon	dunnj1	Overridden

Revision 4/1/2020 Page 12 of 51



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9019902, Project Item Line Number 1290, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Lighting sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9019902, Project Item Line Number 1293, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Lighting sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9020513, Project Item Line Number 1300, Material Set 902051396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9020514, Project Item Line Number 1310, Material Set 902051496, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9020833, Project Item Line Number 1320, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9020834, Project Item Line Number 1330, Material Set 9020834, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9022708, Project Item Line Number 1340, Material Set 902270896, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9022708, Project Item Line Number 1340, Material Set 902270896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9022715, Project Item Line Number 1350, Material Set 902271596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9022715, Project Item Line Number 1350, Material Set 902271596, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9023130, Project Item Line Number 1355, Material Set 902313096, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9023130, Project Item Line Number 1355, Material Set 902313096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9023140, Project Item Line Number 1357, Material Set 902314096, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9023140, Project Item Line Number 1357, Material Set 902314096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9023240, Project Item Line Number 1370, Material Set 902324096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9023240, Project Item Line Number 1370, Material Set 902324096, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9023250, Project Item Line Number 1380, Material Set 902325096, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9023250, Project Item Line Number 1380, Material Set 902325096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9024283, Project Item Line Number 1390, Material Set 902428396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9028308, Project Item Line Number 1430, Material Set 902830896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9028309, Project Item Line Number 1440, Material Set 902830996, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9028310, Project Item Line Number 1450, Material Set 902831096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9028311, Project Item Line Number 1460, Material Set 902831196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9028340, Project Item Line Number 1470, Material Set 902834096, Material 0902TSXX - Traffic Signals Material, Acceptance Action	Signal sample records will be entered soon	dunnj1	Overridden

Revision 4/1/2020 Page 13 of 51



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Generic 0902TSXX is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9029100, Project Item Line Number 1510, Material Set 902910096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9029100, Project Item Line Number 1510, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9029100, Project Item Line Number 1510, Material Set 902910096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC tests	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9029901, Project Item Line Number 1520, Material Set 9029901, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9029902, Project Item Line Number 1550, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9029902, Project Item Line Number 1530, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9029902, Project Item Line Number 1590, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3049, Item 9029902, Project Item Line Number 1610, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Signal sample records will be entered soon	dunnj1	Overridden
Estimate Exception Type: Item Overrun: Contract 200918-F02, Contract Project J6S3049, Project Item Line Number 0240, Contract Line Item Number 0240, Item 6085008, Minor Item.	No Remark was entered by Engineer	dunnj1	Overridden
Estimate Exception Type: Item Overrun: Contract 200918-F02, Contract Project J6S3049, Project Item Line Number 1460, Contract Line Item Number 1460, Item 9028311, Minor Item.	No Remark was entered by Engineer	dunnj1	Overridden
Estimate Exception Type: Item Overrun: Contract 200918-F02, Contract Project J6S3049, Project Item Line Number 1470, Contract Line Item Number 1470, Item 9028340, Minor Item.	No Remark was entered by Engineer	dunnj1	Overridden
Estimate Exception Type: Item Overrun: Contract 200918-F02, Contract Project J6S3049, Project Item Line Number 1500, Contract Line Item Number 1500, Item 9028812, Minor Item.	No Remark was entered by Engineer	dunnj1	Acknowledged

Revision 4/1/2020 Page 14 of 51



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTEI To Date (See repor generated date)
8-F02	J6S3049	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	Qty 0.25	\$1,191,442.00	\$297,860.5
		0001	0020	2029902	MISC.REMOVAL OF TREES	5.00	0.00	5.00	EA	4.00	\$650.00	\$2,600.0
		0001	0030	2063000	CLASS 3 EXCAVATION	4,575.00	0.00	4,575.00	CUYD	1,613.53	\$10.00	\$16,135.3
		0001	0040	2063500	CULVERT CLEANOUT	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.0
		0001	0050	2071000	LINEAR GRADING CLASS 1	22.80	0.00	22.80	STA	7.02	\$150.00	\$1,053.0
		0001	0060	2072000	LINEAR GRADING CLASS 2	326.70	0.00	326.70	STA	97.38	\$250.00	\$24,345.0
		0001	0070	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	16,415.00	0.00	16,415.00	SQYD	7,153.16	\$5.10	\$36,481.1
		0001	0800	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	12,447.00	0.00	12,447.00	SQYD	4,825.91	\$2.50	\$12,064.
		0001	0090	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	270.00	0.00	270.00	TONS	53.07	\$125.00	\$6,633.
		0001	0100	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	16,095.00	0.00	16,095.00	TONS	0.00	\$105.00	\$0.0
		0001	0110	4039910	MISC.ASPHALT FOR WEDGING	1,000.00	0.00	1,000.00	TONS	0.00	\$72.00	\$0.0
		0001	0120	4071005	TACK COAT	11,997.00	0.00	11,997.00	GAL	0.00	\$3.00	\$0.0
		0001	0130	5024008	CONCRETE BASE (8 IN. NON-REINF)	4,360.20	0.00	4,360.20	SQYD	1,808.80	\$61.20	\$110,698.5
		0001	0170	6042010	ADJUSTING MANHOLE	26.00	0.00	26.00	EA	9.00	\$1,600.00	\$14,400.0
		0001	0180	6042020	ADJUSTING BASIN OR INLET	15.00	0.00	15.00	EA	1.00	\$700.00	\$700.0
		0001	0190	6044011	PIPE COLLAR, TYPE A	21.00	0.00	21.00	EA	2.00	\$300.00	\$600.0
		0001	0200	6049902	MISC.PIPE CONNECTION TO REINFORCED CONCRETE BOX	3.00	0.00	3.00	EA	2.00	\$3,000.00	\$6,000.
					(INCLUDES ANY EXCAVATION)							
		0001	0210	6081012	TRUNCATED DOMES	2,293.00	0.00	2,293.00	SQFT	903.70	\$25.00	\$22,592.
		0001	0220	6083006	6 IN. CONCRETE MEDIAN STRIP	1,834.40	0.00	1,834.40	SQYD	272.03	\$50.00	\$13,601.
		0001	0230	6085007	PAVED APPROACH, 7 IN.	5,438.00	0.00	5,438.00	SQYD	2,861.75	\$80.00	\$228,940.
		0001	0240	6085008	PAVED APPROACH, 8 IN.	88.30	0.00	88.30	SQYD	108.10	\$84.00	\$9,080.
		0001	0250	6086004	CONCRETE SIDEWALK, 4 IN.	11,963.00	0.00	11,963.00	SQYD	5,489.16	\$36.00	\$197,609.
		0001	0260	6089902	MISC.ADA CURB RAMP	418.00	0.00	418.00	EA	145.00	\$300.00	\$43,500.
		0001	0270	6089905	MISC.CONCRETE SIDEWALK, 4 IN., TINTED	2,086.00	0.00	2,086.00	SQYD	1,667.20	\$46.00	\$76,691.
		0001	0280	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	1,119.00	0.00	1,119.00	LF	33.00	\$28.00	\$924.
		0001	0290	6091052	CURB AND GUTTER TYPE B	1,163.00	0.00	1,163.00	LF	183.70	\$26.00	\$4,776.
		0001	0300	6097000	ROCK LINING	12.00	0.00	12.00	CUYD	7.00	\$100.00	\$700.
		0001	0310	6099903	MISC.INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B	22,497.00	0.00	22,497.00	LF	9,313.10	\$22.00	\$204,888.
		0001	0320	6122008	IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY)	12.00	0.00	12.00	EA	0.00	\$300.00	\$0.
		0001	0330	6122020	REPLACEMENT SAND BARREL	8.00	0.00	8.00	EA	0.00	\$100.00	\$0.
		0001	0340	6122030	IMPACT ATTENUATOR (RELOCATION)	24.00	0.00	24.00	EA	0.00	\$50.00	\$0.
		0001	0350	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	3,481.10	0.00	3,481.10	SQYD	449.10	\$125.00	\$56,137.
		0001	0360	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	3,481.10	0.00	3,481.10	SQYD	450.90	\$0.01	\$4.
		0001	0370	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)	3,481.10	0.00	3,481.10	SQYD	450.90	\$3.00	\$1,352.
		0001	0380	6131014	(PAVEMENT REPAIR) FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER	16,350.43	0.00	16,350.43	LF	1,097.00	\$0.50	\$548.
		0001	0390	6131015	AND INTERNAL SAW CUTS) DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	8,184.00	0.00	8,184.00	EA	112.00	\$1.50	\$168.
		0001	0400	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	45.00	0.00	45.00	EA	24.00	\$1,000.00	\$24,000.
		0001	0410	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	25.00	0.00	25.00	EA	5.00	\$1,350.00	\$6,750.
		0001	0420	6143011	MANHOLE FRAME AND COVER, TYPE 1-B	26.00	0.00	26.00	EA	0.00	\$500.00	\$0.
		0001	0430	6149902	MISC.CURB INLET TYPE 'T'	7.00	0.00	7.00	EA	0.00	\$1,000.00	\$0.
		0001	0460	6169901	MISC.TEMPORARY TRAFFIC CONTROL ALLOWANCE	1.00	0.00	1.00	LS	0.40	\$250,000.00	\$100,000
		0001	0470	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNHISED/RETAINED)	4.00	0.00	4.00	EA	2.00	\$3,200.00	\$6,400.
		0001	0480	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,500.00	0.00	1,500.00	LF	0.00	\$3.00	\$0.
		0001	0490	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	4,500.00	0.00	4,500.00	LF	0.00	\$1.00	\$0.
		0001	0500	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.33	\$1,528,982.19	\$510,680.

Revision 4/1/2020 Page 15 of 51



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
918-F02	J6S3049	0001	0510	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.0
		0001	0520	6189902	MISC.ADDITIONAL MOBILIZATION FOR STRIPING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.0
		0001	0530	6191000	PAVEMENT EDGE TREATMENT	27,497.00	0.00	27,497.00	LF	0.00	\$0.01	\$0.0
		0001	0570	6200012	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE	367.00	0.00	367.00	LF	0.00	\$12.00	\$0.0
		0001	0600	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	159.00	0.00	159.00	EA	0.00	\$325.00	\$0.0
		0001	0620	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	4.00	0.00	4.00	EA	0.00	\$300.00	\$0.0
		0001	0630	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	8.00	0.00	8.00	EA	0.00	\$450.00	\$0.0
		0001	0640	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	139.00	0.00	139.00	EA	0.00	\$35.00	\$0.0
		0001	0650	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	43,610.00	0.00	43,610.00	LF	0.00	\$0.20	\$0.
		0001	0660	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	52,290.00	0.00	52,290.00	LF	0.00	\$0.20	\$0.
		0001	0670	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,109.00	0.00	2,109.00	LF	0.00	\$0.20	\$0.
		0001	0680	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT. TYPE P BEADS	183.00	0.00	183.00	LF	0.00	\$0.20	\$0.
		0001	0690	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	6,845.00	0.00	6,845.00	LF	28.00	\$6.00	\$168.
		0001	0700	6207001	PAINT, TYPE P BEADS PAVEMENT MARKING REMOVAL	96,256.00	0.00	96,256.00	LF	270.00	\$0.10	\$27
		0001	0710	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	107.00	0.00	107.00	EA	0.00	\$10.00	\$0
		0001	0720	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	74,860.00	0.00	74,860.00	LF	0.00	\$0.05	\$0
		0001	0730	6209902	MISC.18 IN. WHITE ISLAND TUBULAR MARKER	33.00	0.00	33.00	EA	0.00	\$60.00	\$0
		0001	0740	6209902	MISC.18 IN. YELLOW ISLAND TUBULAR MARKER	36.00	0.00	36.00	EA	0.00	\$60.00	\$0
		0001	0760	6209903	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN. YELLOW	379.00	0.00	379.00	LF	0.00	\$12.50	\$0
		0001	0770	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	118,772.00	0.00	118,772.00	SQYD	0.00	\$1.50	\$0
		0001	0780	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	12,200.00	0.00	12,200.00	SQYD	0.00	\$3.00	\$0
		0001	0790	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$87,325.00	\$0
		0001	0800	7261012	12 IN. PIPE GROUP A	51.00	0.00	51.00	LF	8.00	\$310.00	\$2,480
		0001	0810	7261015	15 IN. PIPE GROUP A	2,848.00	0.00	2,848.00	LF	1,849.00	\$70.00	\$129,430
		0001	0820	7261018	18 IN. PIPE GROUP A	571.00	0.00	571.00	LF	183.00	\$100.00	\$18,300
		0001	0830	7261024	24 IN. PIPE GROUP A	581.00	0.00	581.00	LF	0.00	\$125.00	\$0
		0001	0840	7269902	MISC.4' SPECIAL FLUME	1.00	0.00	1.00	EA	0.00	\$4,000.00	\$0
		0001	0850	7269902	MISC.REINFORCED SIDEWALK COVERED INLET EXTENSION	10.00	0.00	10.00	EA	5.00	\$3,200.00	\$16,000
		0001	0860	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	64.00	0.00	64.00	FT	6.00	\$850.00	\$5,100
		0001	0870	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	188.00	0.00	188.00	FT	109.00	\$605.00	\$65,945
		0001	0880	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	59.00	0.00	59.00	FT	23.00	\$575.00	\$13,225
		0001	0890	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	4.00	0.00	4.00	FT	0.00	\$730.00	\$0
		0001	0900	7319903	MISC.PRECAST CONC. AREA INLET 4' X 2'	20.00	0.00	20.00	LF	10.00	\$670.00	\$6,700
		0001	0910	7319903	MISC.PRECAST CONC. AREA INLET 5' X 3'	7.00	0.00	7.00	LF	0.00	\$800.00	\$0
		0001	0920	7319903	MISC.PRECAST CONC. CURB INLET 4' X 3.5'	7.00	0.00	7.00	LF	0.00	\$800.00	\$0
		0001	0930	7319903	MISC.PRECAST CONC. CURB INLET 5' X 4'	22.00	0.00	22.00	LF	0.00	\$575.00	\$0
		0001	0940	7319903	MISC.PRECAST CONC. DROP INLET 5' X 4'	7.00	0.00	7.00	LF	0.00	\$1,100.00	\$0
		0001	0945	7319903	MISC.MSD GRATE INLET 5' X 3'	78.00	0.00	78.00	LF	0.00	\$750.00	\$0
		0001	0950	7320015A	15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$500.00	\$500
		0001	0960	8031000A	TURF TYPE TALL FESCUE SODDING	3,545.00	0.00	3,545.00	SQYD	0.00	\$9.00	\$0
		0001	0970	8059919	MISC.WARM OR COOL SEASON MIXTURES	2.40	0.00	2.40	ACRE	0.00	\$5,000.00	\$0
		0001	0980	8061003	SEDIMENT TRAP EXCAVATION	224.00	0.00	224.00	CUYD	0.00	\$0.01	\$0
		0001	0990	8061005	ROCK DITCH CHECK	770.00	0.00	770.00	LF	0.00	\$1.00	\$0
		0001	1000	90610074	CURB INLET CHECK	192.00	0.00	192.00	EA	0.00	\$25.00	\$0

Page 16 of 51 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00918-F02	J6S3049	0001	1010	8061016	SEDIMENT REMOVAL	2,751.00	0.00	2,751.00	CUYD	0.00	\$0.01	\$0.00
		0001	1020	8061017	TEMPORARY SEEDING AND MULCHING	2.40	0.00	2.40	ACRE	0.00	\$1,000.00	\$0.00
		0001	1030	8061019	SILT FENCE	24,180.00	0.00	24,180.00	LF	0.00	\$0.01	\$0.00
		0001	1040	8064133	TYPE 1C EROSION CONTROL BLANKET	250.00	0.00	250.00	SQYD	0.00	\$5.00	\$0.00
		0001	1050	8064141	TYPE 4 EROSION CONTROL BLANKET	68.00	0.00	68.00	SQYD	0.00	\$10.00	\$0.00
		0001	1060	8069902	MISC.CONCRETE WASHOUTS	10.00	0.00	10.00	EA	0.00	\$0.01	\$0.00
		0001	1070	8069903	MISC.SILT FENCE- SEDIMENT LOG	9,515.00	0.00	9,515.00	LF	0.00	\$0.01	\$0.00
		0010	1080	6061060	MGS GUARDRAIL	852.00	0.00	852.00	LF	0.00	\$24.00	\$0.0
		0010	1090	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	252.00	0.00	252.00	LF	0.00	\$40.00	\$0.00
		0010	1100	6061065	MGS GUARDRAIL, 6 FT. POSTS, 1 FT 6.75 IN. SPACING	275.00	0.00	275.00	LF	0.00	\$58.00	\$0.0
		0010	1110	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	5.00	0.00	5.00	EA	0.00	\$3,200.00	\$0.0
		0010	1120	6061080	MGS END ANCHOR	7.00	0.00	7.00	EA	0.00	\$1,200.00	\$0.0
		0010	1130	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	0.00	\$2,900.00	\$0.00
		0010	1140	6069903	MISC."TIGHT RADIUS-MGS GUARDRAIL, 6 FT. POSTS, 1 FT	115.00	0.00	115.00	LF	0.00	\$88.00	\$0.0
		0020	1160	9011108	6.75 IN. SPACING" BRACKET ARM, 8 FT. OR 2.4 M	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.0
		0020	1170	9011110	BRACKET ARM, 10 FT. OR 3.0 M	9.00	0.00	9.00	EA	0.00	\$1.00	\$0.0
		0020	1190	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	4.00	0.00	4.00	EA	0.00	\$3,104.00	\$0.0
		0020	1200	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	318.00	0.00	318.00	LF	309.00	\$12.00	\$3,708.0
		0020	1210	9014003	CONDUIT, 3 IN. RIGID, PUSHED	1,155.00	0.00	1,155.00	LF	727.00	\$31.00	\$22,537.0
		0020	1220	9016110	PULL BOX, PREFORMED CLASS 1	14.00	0.00	14.00	EA	12.00	\$735.00	\$8,820.0
		0020	1250	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	1,210.00	0.00	1,210.00	LF	450.00	\$0.50	\$225.0
		0020	1270	9017208	WIRE, 8 AWG, BARE NEUTRAL	500.00	0.00	500.00	LF	0.00	\$0.90	\$0.0
		0020	1273	9017401	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	710.00	0.00	710.00	LF	710.00	\$6.00	\$4,260.0
		0020	1277	9017407	NEUTRAL, 2 AWG CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	2,820.00	0.00	2,820.00	LF	2,820.00	\$2.70	\$7,614.0
					NEUTRAL, 8 AWG							
		0020	1280	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	9.00	0.00	9.00	EA	5.00	\$1,033.00	\$5,165.0
		0020	1290	9019902	MISC.PAD MOUNTED 120/240 POWER SUPPLY WITH LIGHTING CONTROLLER	4.00	0.00	4.00	EA	4.00	\$3,104.00	\$12,416.0
		0020	1293	9019902	MISC.45 FT. TOP MOUNT LIGHT POLE	9.00	0.00	9.00	EA	5.00	\$1,539.00	\$7,695.0
		0020	1297	9019902	MISC.170W TOP MOUNTED LED-B LUMINAIRE	12.00	0.00	12.00	EA	6.00	\$596.00	\$3,576.0
		0030	1300	9020513	SIGNAL HEAD, TYPE 3B	11.00	0.00	11.00	EA	11.00	\$1,015.00	\$11,165.0
		0030	1310	9020514	SIGNAL HEAD, TYPE 4B	17.00	0.00	17.00	EA	11.00	\$1,038.00	\$11,418.0
		0030	1320	9020833	SH-FLAT SHEET - SIGNAL SIGN	223.00	0.00	223.00	SQFT	121.40	\$29.00	\$3,520.6
		0030	1330	9020834	SIGNAL SIGN, MOUNTING HARDWARE	61.00	0.00	61.00	EA	20.00	\$41.00	\$820.0
		0030	1340	9022708	POST, SIGNAL 8 FT. OR 2.4 M	23.00	0.00	23.00	EA	15.00	\$640.00	\$9,600.0
		0030	1350	9022715	POST, SIGNAL 15 FT. OR 4.6 M	3.00	0.00	3.00	EA	3.00	\$942.00	\$2,826.0
		0030	1355	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	1.00	\$6,806.00	\$6,806.0
		0030	1357	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	1.00	0.00	1.00	EA	1.00	\$8,046.00	\$8,046.0
		0030	1370	9023240	POST, TYPE C, 40 FT. ARM OR 12.2 M ARM	2.00	0.00	2.00	EA	2.00	\$7,499.00	\$14,998.0
		0030	1380	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	1.00	\$7,770.00	\$7,770.0
		0030	1390	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	2.00	0.00	2.00	EA	1.00	\$16,155.00	\$16,155.0
		0030	1400	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	920.00	0.00	920.00	LF	341.00	\$12.00	\$4,092.0
		0030	1410	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	1,844.00	0.00	1,844.00	LF	1,410.00	\$31.00	\$43,710.0
		0030	1420	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	60.00	0.00	60.00	LF	0.00	\$0.90	\$0.0
		0030	1425	9028302	CABLE, 12 AWG 2 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$0.85	\$0.0
		0030	1430	9028308	CABLE, 16 AWG 2 CONDUCTOR	6,200.00	0.00	6,200.00	LF	3,877.00	\$0.45	\$1,744.65
		0030	1440	9028309	CABLE, 16 AWG 3 CONDUCTOR	1,370.00	0.00	1,370.00	LF	1,367.00	\$0.88	\$1,202.96

Revision 4/1/2020 Page 17 of 51



Total Paid / All Items / All Estimates (Including this Estimate)

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00918-F02	J6S3049	0030	1450	9028310	CABLE, 16 AWG 5 CONDUCTOR	6,240.00	0.00	6,240.00	LF	3,902.00	\$1.05	\$4,097.10
		0030	1460	9028311	CABLE, 16 AWG 7 CONDUCTOR	3,680.00	0.00	3,680.00	LF	4,278.00	\$1.50	\$6,417.00
		0030	1470	9028340	RG-8/U COAXIAL CABLE	1,367.00	0.00	1,367.00	EA	1,678.00	\$1.00	\$1,678.00
		0030	1480	9028810	PULL BOX, PREFORMED CLASS 1	25.00	0.00	25.00	EA	16.00	\$756.00	\$12,096.00
		0030	1490	9028811	PULL BOX, PREFORMED CLASS 2	9.00	0.00	9.00	EA	6.00	\$1,206.00	\$7,236.00
		0030	1500	9028812	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	3.00	\$1,620.00	\$4,860.00
		0030	1510	9029100	BASE, CONCRETE	27.50	0.00	27.50	CUYD	25.06	\$1,400.00	\$35,084.00
		0030	1520	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE, PROGRAMMING, AND ADJUSTMENT	1.00	0.00	1.00	LS	0.20	\$12,600.00	\$2,520.00
		0030	1530	9029902	MISC AUDIBLE PUSH BUTTON & SIGNING W/ VERBAL WALK MESSAGE	48.00	0.00	48.00	EA	26.00	\$732.00	\$19,032.00
		0030	1540	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS	2.00	0.00	2.00	EA	0.00	\$13,835.00	\$0.00
		0030	1550	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S	48.00	0.00	48.00	EA	26.00	\$440.00	\$11,440.00
		0030	1560	9029902	MISC.NETWORK CONNECTED SIGNAL MONITOR	2.00	0.00	2.00	EA	0.00	\$1,130.00	\$0.00
		0030	1570	9029902	MISC.OPTIONAL DETECTION SYSTEM	2.00	0.00	2.00	EA	0.00	\$16,180.00	\$0.00
		0030	1580	9029902	MISC.PEDESTRIAN PUSH BUTTON STANCHION	1.00	0.00	1.00	EA	0.00	\$682.00	\$0.00
		0030	1590	9029902	MISC.RECTANGULAR RAPID FLASHING BEACON ASSEMBLY	16.00	0.00	16.00	EA	2.00	\$8,460.00	\$16,920.00
		0030	1600	9029902	MISC.RELOCATE TRAFFIC SIGNAL HEAD	16.00	0.00	16.00	EA	0.00	\$428.00	\$0.00
		0030	1610	9029902	MISC.SIGNAL CONTROLLER BASE WIDENING	2.00	0.00	2.00	EA	1.00	\$2,166.00	\$2,166.00
		0040	1620	9031010	CONCRETE FOOTINGS, EMBEDDED	5.20	0.00	5.20	CUYD	0.00	\$1,800.00	\$0.00
		0040	1630	9031210	STRUCTURAL STEEL POSTS	130.00	0.00	130.00	LB	0.00	\$8.00	\$0.00
		0040	1640	9031270A	2 IN. PSST POST - 12 GA.	2,684.00	0.00	2,684.00	LF	0.00	\$16.00	\$0.00
		0040	1650	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	654.00	0.00	654.00	LF	0.00	\$30.00	\$0.00
		0040	1660	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	117.00	0.00	117.00	LF	0.00	\$40.00	\$0.00
		0040	1670	9031280	2.5 IN. PSST POST - 12 GA.	130.00	0.00	130.00	LF	0.00	\$17.00	\$0.00
		0040	1680	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	33.00	0.00	33.00	LF	0.00	\$40.00	\$0.00
		0040	1690	9035004A	SH-FLAT SHEET	1,308.00	0.00	1,308.00	SQFT	0.00	\$24.00	\$0.00
		0040	1700	9035069A	SHF-FLAT SHEET FLUORESCENT	614.00	0.00	614.00	SQFT	0.00	\$26.00	\$0.00
		0050	1710	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	2.00	0.00	2.00	EA	0.00	\$3,495.00	\$0.00
		0050	1720	9105201	CONDUIT, 3 IN., RIGID, IN TRENCH	2,250.00	0.00	2,250.00	LF	1,950.00	\$12.00	\$23,400.00
		0050	1730	9108348	COAXIAL CABLE, RG-8/U	410.00	0.00	410.00	LF	0.00	\$1.00	\$0.00
		0050	1740	9108352	FIBER OPTIC CABLE, 24-STRAND, 18 SINGLE MODE, 6 MULTIMODE	2,400.00	0.00	2,400.00	LF	0.00	\$1.90	\$0.00
		0050	1750	9108811	PULL BOX, PREFORMED CLASS 2	1.00	0.00	1.00	EA	1.00	\$1,665.00	\$1,665.00
		0050	1760	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$500.00	\$0.00
		0050	1770	9109902	MISC.ADJUST TO GRADE ITS PULLBOXES (REMOVE AND REPLACE)	10.00	0.00	10.00	EA	1.00	\$1,860.00	\$1,860.00
		0050	1780	9109902	MISC.FIBER OPTIC JUMPER. SM FURNISH & INSTALL	8.00	0.00	8.00	EA	0.00	\$17.50	\$0.00
		0050	1790	9109902	MISC.FIBER OPTIC PIGTAIL. SM FURNISH & INSTALL	8.00	0.00	8.00	EA	0.00	\$9.00	\$0.00
		0050	1800	9109902	MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT	2.00	0.00	2.00	EA	0.00	\$430.00	\$0.00
		0050	1810	9109902	MISC.SM FIBER OPTIC SPLICE	52.00	0.00	52.00	EA	0.00	\$75.00	\$0.00
		0050	1820	9109902	MISC.WALL-MOUNTED INTERCONNECT CENTER F&I	2.00	0.00	2.00	EA	0.00	\$441.00	\$0.00
		0050	1830	9109903	MISC.MODOT ITS ASSET RELOCATION	1,200.00	0.00	1,200.00	LF	0.00	\$16.00	\$0.00
		0051	1840	6089905	MISC.GRG 8 IN. SPECIAL PAVED APPROACH WITH 2 IN. CURB	802.00	0.00	802.00	SQYD	0.00	\$82.00	\$0.00
		0051	1850	6089905	MISC.GRG CONCRETE SIDEWALK 4-IN.	1,160.00	0.00	1,160.00	SQYD	0.00	\$35.00	\$0.00
		0051	1860	6139904	MISC.GRG TRUNCATED DOMES	844.00	0.00	844.00	SQFT	0.00	\$25.00	\$0.00
		0051	1865	6169904	MISC.GRG MMA PAVEMENT MARKINGS GREEN DRIVEWAY	4,850.00	0.00	4,850.00	SQFT	0.00	\$12.00	\$0.00
		0051	1870	6209902	MISC.GRG 24 IN. WHITE ISLAND TUBULAR MARKER	34.00	0.00	34.00	EA	0.00	\$60.00	\$0.00
		0051	1880	6209902	MISC.GRG MMA WHITE ARROW SYMBOL	18.00	0.00	18.00	EA	0.00	\$200.00	\$0.00

Revision 4/1/2020 Page 18 of 51



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200918-F02	J6S3049	0051	1890	6209902	MISC.GRG MMA WHITE BIKE SYMBOL	18.00	0.00	18.00	EA	0.00	\$200.00	\$0.00
		0051	1900	6209902	MISC.GRG MMA WHITE WORD PAVEMENT MARKINGS "AHEAD"	18.00	0.00	18.00	EA	0.00	\$600.00	\$0.00
		0051	1910	6209902	MISC.GRG MMA WHITE WORD PAVEMENT MARKINGS "STOP"	30.00	0.00	30.00	EA	0.00	\$525.00	\$0.00
		0051	1920	6209903	MISC.GRG MMA 4 IN. SOLID YELLOW DASH	1,001.00	0.00	1,001.00	LF	0.00	\$6.00	\$0.00
		0051	1930	6209903	MISC.GRG MMA PAVEMENT MARKINGS 30 IN. GREEN CROSSWALK	342.00	0.00	342.00	LF	0.00	\$30.00	\$0.00
		0051	1940	6209903	MISC.GRG MMA PAVEMENT MARKINGS 30 IN. WHITE CROSSWALK	342.00	0.00	342.00	LF	0.00	\$30.00	\$0.00
		0051	1960	7209904	MISC.GRG MODULAR SMALL BLOCK WALL	85.00	0.00	85.00	SQFT	0.00	\$50.00	\$0.00
		0051	1970	9039903	MISC.GRG PERFORATED SQUARE STEEL TUBE POST - 2IN.	37.00	0.00	37.00	LF	0.00	\$16.00	\$0.00
		0051	1980	9039903	MISC.GRG POST ANCHOR FOR 2 IN. PSST - 12 GA.	12.00	0.00	12.00	LF	0.00	\$30.00	\$0.00
		0051	1990	9039904	MISC.GRG SH-FLAT SHEET	9.00	0.00	9.00	SQFT	0.00	\$24.00	\$0.00
	Project J	6S3049 - To	tal Value	Posted to D	Date as of Report Generated Date							\$2,667,153.33
200918-F02 Ove	rall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$2,667,153.33

Page 19 of 51 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3049

Line umber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0070	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	8/2/21	8/16/21	28.20		WB MO-180 between Colfax Ave and Pennsylvania Ave	589+55		593+00		28.2 sqyd of aggregate for sidewalk
			8/3/21	8/16/21	39.00			594+40		595+95		39 sqyd of aggregate for sidewalk
			0/4/24	8/16/21	48.10 66.00	SQYD	WB MO-180 between Colfax Ave and Pennsylvania Ave WB MO-180 between Colfax Ave and Pennsylvania Ave	589+55 589+55		604+72 604+72		48.1 sqyd of aggregate for sidewalk
			8/5/21	8/16/21	204.70		WB MO-180 between Colfax Ave and Pennsylvania Ave	589+55		604+72		66 sqyd of aggregate for sidewalk 204.7 sqyd of aggregate for sidewalk
			8/6/21	8/16/21	125.30		WB MO-180 between Lulu Ave and Pennsylvania Ave	648+07		660+42		125.3 sqyd of aggregate for sidewalk
			8/9/21	8/16/21			WB MO-180 between Colfax Ave and Pennsylvania Ave	648+07		660+42		84.1 sqyd of aggregate for sidewalk poured
				8/16/21	144.80	SQYD	WB MO-180 between Colfax Ave and Pennsylvania Ave	589+55		604+72		144.8 sqyd of aggregate for sidewalk
			8/10/21	8/16/21	138.00	SQYD	WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		138 sqyd of aggregate for sidewalk poured in front Normandy HS
				8/16/21	159.30		WB MO-180 between Colfax Ave and Pennsylvania Ave	589+55		604+72		159.3 sqyd of aggregate for sidewalk
			8/13/21	8/16/21	75.30		WB MO-180 between Colfax Ave and Pennsylvania Ave	589+55		604+72		75.3 sqyd of aggregate for sidewalk
080	3040504	TYPE 5 AGGREGATE FOR BASE	8/2/21	8/16/21	33.50		WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		33.5 sqyd of aggregate for concrete base
				8/16/21	37.70	SQYD	WB MO-180 between Atwater Ave and Colfax Ave	586+78.40		589+19.16		37.7 sqyd of aggregate for 6" median poured along MO-180 between mainline MO-180 and old St. Cha Rock Rd
			8/3/21	8/16/21	35.10	SQYD	WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		35.1 sqyd of aggregate for concrete base
				8/16/21	87.80	SQYD	WB MO-180 between Normandy Dr and Atwater Ave	584+70.56		585+29.97		87.8 sqyd of aggregate for paved approach at 756. Charles Rock Rd
			8/4/21	8/16/21	43.30	SQYD	WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		43.3 sqyd of aggregate for concrete base
			8/5/21	8/16/21	62.60			648+07		660+42		62.6 sqyd of aggregate for concrete base
			8/11/21	8/16/21	8.70	SQYD	EB MO-180 between Lulu Ave and Lucas-Hunt Rd	656+01		656+46		8.7 sqyd of aggregate for concrete base in front of
												approach to cemetery
			8/12/21	8/16/21		SQYD	WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		24.7 sqyd of aggregate for concrete base
90	4044000	RIT DAVEMENT MIVTURE DOGA 00 (DD 4)	8/13/21	8/16/21	8.60		EB MO-180 between Lulu Ave Lucas-Hunt Rd	648+07		660+42		8.6 sqyd of aggregate for concrete base
JU	4011209	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	8/13/21	8/16/21	16.07	TONS	EB MO-180 between Wageley Ave and Austin Dr	590+95		594+40		16.07 tons of asphalt placed at various locations we this section
130	5024008	CONCRETE BASE (8 IN. NON-REINF)	8/2/21	8/16/21	33.50	SQYD	WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		33.5 sqyd of base poured
			8/3/21	8/16/21	35.10	SQYD	WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		35.1 sqyd of concrete base poured
			8/4/21	8/16/21	43.30	SQYD	WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		43.3 sqyd of concrete base poured
			8/5/21	8/16/21	62.60	SQYD	WB MO-180 between Lulu Ave and Pennsylvania Ave	648+07		660+42		62.6 sqyd of concrete base poured
			8/11/21	8/16/21	8.70	SQYD	EB MO-180 between Lulu Ave and Lucas-Hunt Rd	656+01		656+46		8.7 sqyd of concrete base poured in front of paved approach to cemetery
			8/12/21	8/16/21	24.70	SQYD	WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		24.7 sqyd of concrete base poured
			8/13/21	8/16/21	8.60	SQYD	EB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		8.6 sqyd of concrete base poured
210	6081012	TRUNCATED DOMES	8/3/21	8/16/21	14.00	SQFT	EB MO-180 @ Austin Dr	594+60				14 sqft of domes placed at curb ramp on east side intersection
			8/9/21	8/16/21	26.00	SQFT	EB MO-180 @ Archway Manor Dr	595+42				26 sqft of domes placed at curb ramp on west side intersection
			8/11/21	8/16/21	16.00	SQFT	WB MO-180 between Colfax Ave and Pennsylvania Ave	596+80				16 sqft of domes placed at curb ramps at midblock crossing along WB MO-180
220	6083006	6 IN. CONCRETE MEDIAN STRIP	8/2/21	8/16/21	37.70	SQYD	WB MO-180 between Atwater Ave and Colfax Ave	586+78.40		589+19.16		6" median poured along WB MO-180 between mai MO-180 and old St. Charles Rock Rd
230	6085007	PAVED APPROACH, 7 IN.	8/3/21	8/16/21	87.80		WB MO-180 between Normandy Dr and Atwater Ave	584+70.58		585+29.97		87.8 sqyd of concrete poured for paved approach a St. Charles Rock Rd
250	6086004	CONCRETE SIDEWALK, 4 IN.	8/2/21				WB MO-180 between Colfax Ave and Pennsylvania Ave	589+55		593+00		28.2 sqyd of sidewalk poured
			8/3/21	8/16/21	39.00		EB MO-180 between Austin Dr and Archway Manor Dr	594+40		595+95		39 sqyd of sidewalk poured
			014104	8/16/21	48.10			589+55		604+72		48.1 sqyd of sidewalk poured
			8/4/21	8/16/21	66.00	SQYD	WB MO-180 between Colfax Ave and Pennsylvania Ave WB MO-180 between Colfax Ave and Pennsylvania Ave	589+55 589+55		604+72 604+72		99' of sidewalk poured 204.7 sqyd of sidewalk poured
			8/6/21	8/16/21	125.30		WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		125.3 sqyd of sidewalk poured
			8/9/21	8/16/21	84.10		WB MO-180 between Lulu Ave and Lucas-Hunt Ave	648+07		660+42		128.2' of sidewalk poured
				8/16/21	144.80		WB MO-180 between Colfax Ave and Pennsylvania Ave	589+55		604+72		218.9' of sidewalk poured
			8/10/21	8/16/21	138.00		WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		211' of sidewalk poured in front of Normandy HS
				8/16/21	159.30	SQYD	WB MO-180 between Colfax Ave and Pennsylvania Ave	589+55		604+72		239' of sidewalk poured
			8/13/21	8/16/21	75.30	SQYD	WB MO-180 between Colfax Ave and Pennsylvania Ave	589+55		604+72		75.3 sqyd of sidewalk poured
260	6089902	MISC. CONCRETE	8/3/21	8/16/21	1.00	EA	EB MO-180 @ Austin Drive	594+60				1 curb ramp poured on east side of intersection
			8/9/21	8/16/21	1.00	EA	EB MO-180 @ Archway Manor Dr	595+42				1 curb ramp poured on west side of intersection
			8/11/21	8/16/21	2.00	EA	WB MO-180 between Colfax Ave and Pennsylvania Ave	596+80				2 curb ramps poured at midblock crossing along W MO-180
310	6099903	MISC. PAVED DRAINAGE	8/2/21	8/16/21	215.00	LF	WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		215' of curb poured
			8/3/21	8/16/21	183.00		WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		183' of curb poured
			8/4/21	8/16/21	156.00		WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		156' of curb poured
			8/5/21	8/16/21	161.00		WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42		161' of curb poured
			8/12/21	8/16/21	80.00		WB MO-180 between Lulu Ave and Lucas-Hunt Rd	648+07		660+42 660+42		80' of curb poured
350	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	8/6/21	8/16/21	152.00 20.00		EB MO-180 @ Pennsylvania Ave	648+07 605+15.25		605+32.40		152' of curb poured 20 sqyd of concrete poured at old right-turn median to EB MO-180
			8/11/21	8/16/21	65.00	SQYD	WB MO-180 @ Lucas-Hunt Rd	657+50		659+97		65 sqyd of concrete for pavement repair in right tur
			8/12/21	8/16/21	68.00		WB MO-180 @ Lucas-Hunt Rd	657+50		659+97		68 sqyd of concrete for pavement repair in right tur
360	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM	8/6/21	8/16/21	20.00		EB MO-180 @ Pennsylvania Ave	605+15.25		605+32.40		20 sqyd of subgrade compaction for pavement rep old right-turn median island to EB MO-180
			8/11/21	8/16/21	65.00	SQYD	WB MO-180 @ Lucas-Hunt Rd	657+50		659+97		old right-turn median island to EB MO-180 65 sqyd of subgrade compaction for pavement rep right turn lane
			8/12/21	8/16/21	68.00	SQYD	WB MO-180 @ Lucas-Hunt Rd	657+50		659+97		right turn lane 68 sqyd of subgrade compaction for pavement repright turn lane
370	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	8/6/21	8/16/21	20.00	SQYD	EB MO-180 @ Pennsylvania Ave	605+15.25		605+32.40		20 sqyd of aggregate for pavement repair at old rig median island to EB MO-180
			8/11/21	8/16/21	65.00	SQYD	WB MO-180 @ Lucas-Hunt Ave	657+50		659+97		65 sqyd of aggregate for pavement repair in right to
			8/12/21	8/16/21	68.00		WB MO-180 @ Lucas-Hunt Rd	657+50		659+97		68 sqyd of aggregate for pavement repair in right to
380	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	8/6/21	8/16/21	55.00	LF	EB MO-180 @ Pennsylvania Ave	605+15.25		605+32.40		55' sawcut around existing right-turn median island removed) to EB MO-180 for pavement repair
			8/11/21	8/16/21	81.00	LF	WB MO-180 @ Lucas-Hunt Rd	657+50		659+97		81' of sawcut around pavement repair area (right to lane)
			8/12/21	8/16/21	62.00	LF	WB MO-180 @ Lucas-Hunt Rd	657+50		659+97		62' sawcut around pavement repair area (right turn

Revision 4/1/2020 Page 20 of 51



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0390	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	8/11/21	8/16/21	34.00	EA	WB MO-180 @ Lucas-Hunt Rd	657+50		659+97		34 dowel bars used for pavement repair in right turn lane
			8/12/21	8/16/21	38.00	EA	WB MO-180 @ Lucas-Hunt Rd	657+50		659+97		38 dowel bars placed for pavement repair in right turn lane
1210	9014003	CONDUIT, 3 IN. RIGID, PUSHED	8/11/21	8/12/21	237.00	LF	MO-180 at Normandy	583+00		585+00		New conduit for lighting changes at Normandy
			8/13/21	8/16/21	100.00	LF	MO-180 at Normandy	583+00		585+00		Design change lighting PB1 to PB2
1220	9016110	PULL BOX, PREFORMED CLASS 1	8/12/21	8/12/21	4.00	EA	MO-180 and Normandy	583+00		585+00		Lighting design changes. PB1, 2, 3 and 4

<u>The information below this line are details for Construction Signs (if applicable).</u>

No Data Available

Revision 4/1/2020 Page 21 of 51



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3049	0070	TYPE 1 AGGREGATE FOR BASE (4 IN.	Material		11	Apr 16, 2021	SYSTEM	\$10,024.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		THICK)			11	Apr 16, 2021	SYSTEM	(\$10,024.87)	
					12	May 3, 2021	SYSTEM	\$12,478.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	May 3, 2021	SYSTEM	(\$12,478.27)	
					13	May 17, 2021	SYSTEM	\$17,764.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$17,764.42)	
					14	Jun 2, 2021	SYSTEM	\$20,244.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Jun 2, 2021	SYSTEM	(\$20,244.04)	
					15	Jun 16, 2021	SYSTEM	\$20,987.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$20,987.32)	
					16	Jul 1, 2021	SYSTEM	\$25,113.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$25,113.22)	
					17	Jul 16, 2021	SYSTEM	\$29,710.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$29,710.36)	
					18	Aug 2, 2021	SYSTEM	\$30,949.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$30,949.66)	
					19	Aug 16, 2021	SYSTEM	\$36,481.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$36,481.12)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0070 -	TYPE 5 AGGREGATE FOR BASE	Material		8	Mar 2, 2021	SYSTEM	\$0.00 \$45.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		TONDAGE			8	Mar 2, 2021	SYSTEM	(\$45.15)	Example Exception For the current Faymon Estimate.
					9	Mar 16, 2021	SYSTEM	\$733.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Mar 16, 2021	SYSTEM	(\$733.20)	
					10	Apr 2, 2021	SYSTEM	\$2,324.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user dunnj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Apr 2, 2021	SYSTEM	(\$2,324.75)	
					11	Apr 16, 2021	SYSTEM	\$3,884.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
)49	0800	TYPE 5 AGGREGATE	Material		11	Apr 16, 2021	SYSTEM	(\$3,884.22)	
		FOR BASE			12	May 3, 2021	SYSTEM	\$4,927.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	May 3, 2021	SYSTEM	(\$4,927.02)	
					13	May 17, 2021	SYSTEM	\$5,032.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$5,032.28)	
					14	Jun 2, 2021	SYSTEM	\$6,225.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Jun 2, 2021	SYSTEM	(\$6,225.78)	
					15	Jun 16, 2021	SYSTEM	\$7,880.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$7,880.52)	
					16	Jul 1, 2021	SYSTEM	\$10,098.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$10,098.02)	
					17	Jul 16, 2021	SYSTEM	\$10,410.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$10,410.28)	
					18	Aug 2, 2021	SYSTEM	\$11,387.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$11,387.78)	
					19	Aug 16, 2021	SYSTEM	\$12,064.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$12,064.78)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
J	0080 -	Total						\$0.00	
	0090	BIT. PAVEMENT MIXTURE	Price FUEL		13	May 17, 2021	SYSTEM	\$23.90	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		PG64-22 (BP-1)			15	Jun 16, 2021	SYSTEM	\$66.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					18	Aug 2, 2021	SYSTEM	\$21.61	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					19	Aug 16, 2021	SYSTEM	\$53.89	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$165.87	
			Price FUEL -	Total				\$165.87	
	0090 -	Total						\$165.87	
	0130	CONCRETE BASE (8 IN. NON-REINF)	Material		8	Mar 2, 2021	SYSTEM	\$1,105.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Mar 2, 2021	SYSTEM	(\$1,105.27)	
					9	Mar 16, 2021	SYSTEM	\$14,508.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3049	0130	CONCRETE BASE (8 IN.	Material		9	Mar 16, 2021	SYSTEM	(\$14,508.07)	
		NON-REINF)			10	Apr 2, 2021	SYSTEM	\$25,757.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Apr 2, 2021	SYSTEM	(\$25,757.86)	
					11	Apr 16, 2021	SYSTEM	\$38,547.43	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Apr 16, 2021	SYSTEM	(\$38,547.43)	
					12	May 3, 2021	SYSTEM	\$39,633.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dunnj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	May 3, 2021	SYSTEM	(\$39,633.73)	
					13	May 17, 2021	SYSTEM	\$42,210.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$42,210.25)	
					14	Jun 2, 2021	SYSTEM	\$43,526.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					14	Jun 2, 2021	SYSTEM	(\$43,526.05)	
					15	Jun 16, 2021	SYSTEM	\$45,141.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$45,141.73)	
					16	Jul 1, 2021	SYSTEM	\$84,340.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$84,340.33)	
					17	Jul 16, 2021	SYSTEM	\$96,732.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user dunnj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$96,732.72)	
					18	Aug 2, 2021	SYSTEM	\$99,498.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$99,498.96)	
					19	Aug 16, 2021	SYSTEM	\$110,698.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$110,698.56)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0130 -						0)/0==-	\$0.00	
	0170	ADJUSTING MANHOLE	Material		14	Jun 2, 2021	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					14	Jun 2, 2021	SYSTEM	(\$3,200.00)	
					15	Jun 16, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$4,800.00)	
					16	Jul 1,	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
6S3049	0170	ADJUSTING MANHOLE	Material			2021			Estimate Item Adjustment (0010) due to user dunnj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$4,800.00)	
					17	Jul 16, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$4,800.00)	
					18	Aug 2, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$4,800.00)	
					19	Aug 16, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$4,800.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0170 -	Total						\$0.00	
	0190	PIPE COLLAR, TYPE A	Material		14	Jun 2, 2021	SYSTEM	\$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user dunnj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					14	Jun 2, 2021	SYSTEM	(\$300.00)	
					15	Jun 16, 2021	SYSTEM	\$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$300.00)	
					16	Jul 1, 2021	SYSTEM	\$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$300.00)	
					17	Jul 16, 2021	SYSTEM	\$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user dunnj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$300.00)	
					18	Aug 2, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$600.00)	
					19	Aug 16, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$600.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0190 -	Total						\$0.00	
	0200	MISC. DRAINAGE ITEM	Material		8	Mar 2, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Mar 2, 2021	SYSTEM	(\$3,000.00)	
					9	Mar 16, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dunnj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Mar 16, 2021	SYSTEM	(\$6,000.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3049	0200	MISC. DRAINAGE ITEM	Material		10	Apr 2, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dunnj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Apr 2, 2021	SYSTEM	(\$6,000.00)	
					11	Apr 16, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					11	Apr 16, 2021	SYSTEM	(\$6,000.00)	
					12	May 3, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					12	May 3, 2021	SYSTEM	(\$6,000.00)	
					13	May 17, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$6,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0200 -							\$0.00	
	0210	TRUNCATED DOMES	Material		10	Apr 2, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Apr 2, 2021	SYSTEM	(\$750.00)	
					11	Apr 16, 2021	SYSTEM	\$3,287.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user dunnj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					11	Apr 16, 2021	SYSTEM	(\$3,287.50)	
					12	May 3, 2021	SYSTEM	\$5,652.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user dunnj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	May 3, 2021	SYSTEM	(\$5,652.50)	
					13	May 17, 2021	SYSTEM	\$8,602.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$8,602.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0210 -				40		0)/0==-	\$0.00	71
	0220	6 IN. CONCRETE MEDIAN STRIP	Material		12	May 3, 2021	SYSTEM	\$2,161.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					12	May 3, 2021	SYSTEM	(\$2,161.50)	
					13	May 17, 2021	SYSTEM	\$3,831.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user dunnj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$3,831.50)	
					14	Jun 2, 2021	SYSTEM	\$3,921.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user dunnj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					14	Jun 2, 2021	SYSTEM	(\$3,921.50)	
					15	Jun 16, 2021	SYSTEM	\$3,921.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					15	Jun 16,	SYSTEM	(\$3,921.50)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3049	0220	6 IN. CONCRETE	Material			2021			
		MEDIAN STRIP			16	Jul 1, 2021	SYSTEM	\$7,421.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user dunnj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$7,421.50)	
					17	Jul 16, 2021	SYSTEM	\$8,936.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user dunnj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$8,936.50)	
					18	Aug 2, 2021	SYSTEM	\$11,716.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$11,716.50)	
					19	Aug 16, 2021	SYSTEM	\$13,601.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$13,601.50)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0220 -	Total						\$0.00	
	0230	PAVED APPROACH, 7 IN.	Material		9	Mar 16, 2021	SYSTEM	\$4,751.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Mar 16, 2021	SYSTEM	(\$4,751.20)	
					10	Apr 2, 2021	SYSTEM	\$40,975.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user dunnj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					10	Apr 2, 2021	SYSTEM	(\$40,975.20)	
					11	Apr 16, 2021	SYSTEM	\$76,288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					11	Apr 16, 2021	SYSTEM	(\$76,288.00)	
					12	May 3, 2021	SYSTEM	\$104,779.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					12	May 3, 2021	SYSTEM	(\$104,779.20)	
					13	May 17, 2021	SYSTEM	\$104,779.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$104,779.20)	
					14	Jun 2, 2021	SYSTEM	\$141,107.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user dunnj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					14	Jun 2, 2021	SYSTEM	(\$141,107.20)	
					15	Jun 16, 2021	SYSTEM	\$193,835.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user dunnj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$193,835.20)	
					16	Jul 1, 2021	SYSTEM	\$204,907.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$204,907.20)	
					17	Jul 16, 2021	SYSTEM	\$198,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user dunnj1 overridding Payment
						2021			25



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3049	0230	PAVED	Material						Estimate Exception 24 on the current Payment Estimate.
		APPROACH, 7 IN.			17	Jul 16, 2021	SYSTEM	(\$198,700.00)	
					18	Aug 2, 2021	SYSTEM	\$221,916.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user dunnj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$221,916.00)	
					19	Aug 16, 2021	SYSTEM	\$228,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user dunnj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$228,940.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0230 -	Total						\$0.00	
	0240	PAVED APPROACH, 8 IN.	Material		16	Jul 1, 2021	SYSTEM	\$9,080.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$9,080.40)	
					17	Jul 16, 2021	SYSTEM	\$9,080.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$9,080.40)	
					18	Aug 2, 2021	SYSTEM	\$9,080.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user dunnj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$9,080.40)	
					19	Aug 16, 2021	SYSTEM	\$9,080.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$9,080.40)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	16	Jul 1, 2021	SYSTEM	\$1,663.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 95 on the current Payment Estimate. Material Insufficiency Quantity 108.100; Overrun Quantity Balance 19.80.
					16	Jul 1, 2021	SYSTEM	(\$1,663.20)	
					17	Jul 16, 2021	SYSTEM	(\$1,663.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					17	Jul 16, 2021	SYSTEM	\$1,663.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 10 on the current Payment Estimate. Material Insufficiency Quantity 108.100; Overrun Quantity Balance 19.80.
					18	Aug 2, 2021	SYSTEM	(\$1,663.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					18	Aug 2, 2021	SYSTEM	\$1,663.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 10 on the current Payment Estimate. Material Insufficiency Quantity 108.100; Overrun Quantity Balance 19.80.
					19	Aug 16, 2021	SYSTEM	(\$1,663.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					19	Aug 16, 2021	SYSTEM	\$1,663.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 10 on the current Payment Estimate. Material Insufficiency Quantity 108.100; Overrun Quantity Balance 19.80.
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
		Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3049	0250	CONCRETE SIDEWALK, 4 IN.	Material		11	Apr 16, 2021	SYSTEM	\$70,763.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user dunnj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					11	Apr 16, 2021	SYSTEM	(\$70,763.76)	
					12	May 3, 2021	SYSTEM	\$88,081.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user dunnj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					12	May 3, 2021	SYSTEM	(\$88,081.92)	
					13	May 17, 2021	SYSTEM	\$113,803.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user dunnj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$113,803.92)	
					14	Jun 2, 2021	SYSTEM	\$127,563.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user dunnj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					14	Jun 2, 2021	SYSTEM	(\$127,563.12)	
					15	Jun 16, 2021	SYSTEM	\$132,924.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$132,924.96)	
					16	Jul 1, 2021	SYSTEM	\$134,490.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$134,490.96)	
					17	Jul 16, 2021	SYSTEM	\$149,816.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$149,816.16)	
					18	Aug 2, 2021	SYSTEM	\$158,564.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$158,564.16)	
					19	Aug 16, 2021	SYSTEM	\$197,609.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$197,609.76)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0250	MISC. CONCRETE	Material		10	Apr 2, 2021	SYSTEM	\$0.00 \$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Apr 2, 2021	SYSTEM	(\$300.00)	
					11	Apr 16, 2021	SYSTEM	\$5,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					11	Apr 16, 2021	SYSTEM	(\$5,700.00)	
					12	May 3, 2021	SYSTEM	\$11,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					12	May 3, 2021	SYSTEM	(\$11,400.00)	
					13	May 17, 2021	SYSTEM	\$17,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3049	0260	MISC. CONCRETE	Material		13	May 17, 2021	SYSTEM	(\$17,400.00)	
					14	Jun 2, 2021	SYSTEM	\$22,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					14	Jun 2, 2021	SYSTEM	(\$22,200.00)	
					15	Jun 16, 2021	SYSTEM	\$26,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user dunnj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$26,400.00)	
					16	Jul 1, 2021	SYSTEM	\$33,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$33,300.00)	
					17	Jul 16, 2021	SYSTEM	\$39,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$39,300.00)	
					18	Aug 2, 2021	SYSTEM	\$42,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$42,300.00)	
					19	Aug 16, 2021	SYSTEM	\$43,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$43,500.00)	
				- Total				\$0.00	
	0260 -	- Total	Material - To	tal				\$0.00 \$0.00	
	0260 -	- Total MISC. CONCRETE	Material - To	tal	13	May 17, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
		MISC.		tal	13		SYSTEM SYSTEM	\$0.00	Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment
		MISC.		tal		2021 May 17,		\$0.00 \$14,812.00	Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment
		MISC.		tal	13	2021 May 17, 2021 Jun 2,	SYSTEM	\$0.00 \$14,812.00 (\$14,812.00)	Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment
		MISC.		tal	13	2021 May 17, 2021 Jun 2, 2021 Jun 2,	SYSTEM SYSTEM	\$0.00 \$14,812.00 (\$14,812.00) \$19,596.00	Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment
		MISC.		tal	13 14 14	2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$14,812.00 (\$14,812.00) \$19,596.00 (\$19,596.00)	Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment
		MISC.		tal	13 14 14 15	2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$14,812.00 (\$14,812.00) \$19,596.00 (\$19,596.00) \$19,596.00	Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment
		MISC.		tal	13 14 14 15	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$14,812.00 (\$14,812.00) \$19,596.00 (\$19,596.00) \$19,596.00	Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment
		MISC.		tal	13 14 14 15 15 16	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$14,812.00 (\$14,812.00) \$19,596.00 (\$19,596.00) \$19,596.00 (\$19,596.00) \$54,809.00	Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment
		MISC.		tal	13 14 14 15 15 16	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$14,812.00 (\$14,812.00) \$19,596.00 (\$19,596.00) \$19,596.00 (\$19,596.00) \$54,809.00	Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 43 on the current Payment Estimate.
		MISC.		tal	13 14 14 15 15 16 16 17	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$14,812.00 (\$14,812.00) \$19,596.00 (\$19,596.00) \$19,596.00 (\$19,596.00) \$54,809.00 (\$54,809.00)	Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 43 on the current Payment Estimate.
		MISC.		tal	13 14 14 15 15 16 16 17	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$14,812.00 (\$14,812.00) \$19,596.00 (\$19,596.00) \$19,596.00 (\$19,596.00) \$54,809.00 (\$54,809.00) \$76,691.20	Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user dunnj1 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 42 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J6S3049	0270	MISC. CONCRETE				2021			Estimate Item Adjustment (0013) due to user dunnj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.											
					19	Aug 16, 2021	SYSTEM	(\$76,691.20)												
				- Total				\$0.00												
			Material - To	aterial - Total																
	0270 -	- Total						\$0.00												
	0280	CONCRETE CURB (6 IN. HEIGHT AND	Material		14	Jun 2, 2021	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user dunnj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.											
		UNDER)			14	Jun 2, 2021	SYSTEM	(\$420.00)												
					15	Jun 16, 2021	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.											
					15	Jun 16, 2021	SYSTEM	(\$420.00)												
					16	Jul 1, 2021	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user dunnj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.											
					16	Jul 1, 2021	SYSTEM	(\$420.00)												
					17	Jul 16, 2021	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.											
					17	Jul 16, 2021	SYSTEM	(\$420.00)												
					18	Aug 2, 2021	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user dunnj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.											
					18	Aug 2, 2021	SYSTEM	(\$924.00)												
					19	Aug 16, 2021	SYSTEM	\$924.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user dunnj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.											
					19	Aug 16, 2021	SYSTEM	(\$924.00)												
				- Total				\$0.00												
			Material - To	rial - Total				\$0.00												
	0280 -	Total						\$0.00												
	0290	CURB AND GUTTER TYPE B	Material		14	Jun 2, 2021	SYSTEM	\$1,612.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user dunnj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.											
						1	14	Jun 2, 2021	SYSTEM	(\$1,612.00)										
																15	Jun 16, 2021	SYSTEM	\$4,776.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user dunnj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
											15	Jun 16, 2021	SYSTEM	(\$4,776.20)						
													16	Jul 1, 2021	SYSTEM	\$4,776.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user dunnj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.			
					16	Jul 1, 2021	SYSTEM	(\$4,776.20)												
						17	Jul 16, 2021	SYSTEM	\$4,776.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user dunnj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.										
					17	Jul 16, 2021	SYSTEM	(\$4,776.20)												
					18	Aug 2, 2021	SYSTEM	\$4,776.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user dunnj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.											
					18	Aug 2, 2021	SYSTEM	(\$4,776.20)												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6S3049	0290	CURB AND GUTTER TYPE B	Material		19	Aug 16, 2021	SYSTEM	\$4,776.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user dunnj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.	
					19	Aug 16, 2021	SYSTEM	(\$4,776.20)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0290 -	- Total						\$0.00		
	0300	ROCK LINING	Material		13	May 17, 2021	SYSTEM	\$711.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user dunnj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	
					13	May 17, 2021	SYSTEM	(\$711.00)		
					17	Jul 16, 2021	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user dunnj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	
					17	Jul 16, 2021	SYSTEM	(\$700.00)		
					18	Aug 2, 2021	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user dunnj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	
					18	Aug 2, 2021	SYSTEM	(\$700.00)		
					19	Aug 16, 2021	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user dunnj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	
					19	Aug 16, 2021	SYSTEM	(\$700.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0300 -	- Total						\$0.00		
	0310	MISC. PAVED DRAINAGE		Material		9	Mar 16,	SYSTEM	\$14,245.00	This adjustment offsets the original system-generated Material Payment
		DRAINAGE				2021			Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
		DRAINAGE			9	2021 Mar 16, 2021	SYSTEM	(\$14,245.00)		
		DRAINAGE			9	Mar 16,	SYSTEM	(\$14,245.00) \$76,307.00		
		DRAINAGE				Mar 16, 2021 Apr 2,			Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunn/1 overridding Payment	
		DRAINAGE			10	Mar 16, 2021 Apr 2, 2021 Apr 2,	SYSTEM	\$76,307.00	Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunn/1 overridding Payment	
		DRAINAGE			10	Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16,	SYSTEM	\$76,307.00 (\$76,307.00)	Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment	
		DRAINAGE			10 10 11	Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16, 2021	SYSTEM SYSTEM	\$76,307.00 (\$76,307.00) \$87,177.20	Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment	
		DRAINAGE			10 10 11	Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3,	SYSTEM SYSTEM SYSTEM	\$76,307.00 (\$76,307.00) \$87,177.20 (\$87,177.20)	Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment	
		DRAINAGE			10 10 11 11 11 12	Mar 16, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$76,307.00 (\$76,307.00) \$87,177.20 (\$87,177.20) \$89,557.60	Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment	
		DRAINAGE			10 10 11 11 12	Mar 16, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021 May 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$76,307.00 (\$76,307.00) \$87,177.20 (\$87,177.20) \$89,557.60	Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user dunnj1 overridding Payment Estimate Item Adjustment (0014) due to user dunnj1 overridding Payment	
		DRAINAGE			10 10 11 11 12 12 13	Mar 16, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 17, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$76,307.00 (\$76,307.00) \$87,177.20 (\$87,177.20) \$89,557.60 (\$89,557.60) \$109,045.20	Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user dunnj1 overridding Payment Estimate Item Adjustment (0014) due to user dunnj1 overridding Payment	
		DRAINAGE			10 10 11 11 12 12 13 13	Mar 16, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3, 2021 May 17, 2021 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$76,307.00 (\$76,307.00) \$87,177.20 (\$87,177.20) \$89,557.60 (\$89,557.60) \$109,045.20 (\$109,045.20) \$114,360.40	Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user dunnj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 33 on the current Payment Estimate.	
		DRAINAGE			10 10 11 11 12 12 13 13 14	Mar 16, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 2, 2021	SYSTEM	\$76,307.00 (\$76,307.00) \$87,177.20 (\$87,177.20) \$89,557.60 (\$89,557.60) \$109,045.20 (\$109,045.20) \$114,360.40	Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user dunnj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 33 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3049	0310	MISC. PAVED	Material			2021			
		DRAINAGE			16	Jul 1, 2021	SYSTEM	\$150,235.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user dunnj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$150,235.80)	
					17	Jul 16, 2021	SYSTEM	\$170,216.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user dunnj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$170,216.20)	
					18	Aug 2, 2021	SYSTEM	\$188,784.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user dunnj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$188,784.20)	
					19	Aug 16, 2021	SYSTEM	\$204,888.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user dunnj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$204,888.20)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0310 -	Total						\$0.00	
	0350	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		13	May 17, 2021	SYSTEM	\$12,175.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user dunnj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					13	May 17, 2021	SYSTEM	(\$12,175.00)	
					14	Jun 2, 2021	SYSTEM	\$12,175.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user dunnj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					14	Jun 2, 2021	SYSTEM	(\$12,175.00)	
					15	Jun 16, 2021	SYSTEM	\$12,175.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user dunnj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$12,175.00)	
					16	Jul 1, 2021	SYSTEM	\$23,162.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user dunnj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$23,162.50)	
					17	Jul 16, 2021	SYSTEM	\$37,012.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user dunnj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$37,012.50)	
					18	Aug 2, 2021	SYSTEM	\$37,012.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user dunnj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$37,012.50)	
					19	Aug 16, 2021	SYSTEM	\$56,137.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user dunnj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$56,137.50)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0350 -	Total						\$0.00	
	0360	SUBGRADE COMPACTION (6 IN. DEPTH)	Material		13	May 17, 2021	SYSTEM	\$0.97	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user dunnj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J6S3049	0360	(PAVEM	Material		13	May 17, 2021	SYSTEM	(\$0.97)			
					14	Jun 2, 2021	SYSTEM	\$0.97	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user dunnj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.		
					14	Jun 2, 2021	SYSTEM	(\$0.97)			
							15	Jun 16, 2021	SYSTEM	\$0.97	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user dunnj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$0.97)			
					16	Jul 1, 2021	SYSTEM	\$1.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.		
					16	Jul 1, 2021	SYSTEM	(\$1.87)			
					17	Jul 16, 2021	SYSTEM	\$2.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user dunnj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.		
					17	Jul 16, 2021	SYSTEM	(\$2.98)			
					18	Aug 2, 2021	SYSTEM	\$2.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user dunnj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.		
					18	Aug 2, 2021	SYSTEM	(\$2.98)			
					19	Aug 16, 2021	SYSTEM	\$4.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user dunnj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.		
					19	Aug 16, 2021	SYSTEM	(\$4.51)			
				- Total				\$0.00			
	0360	- Total	Material - To	tal				\$0.00 \$0.00			
	0370	TYPE 1 OR 5 AGGREGATE	Material		13	May 17, 2021	SYSTEM	\$292.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user dunnj1 overridding Payment		
		FOR BASE (4 IN.	1 IN.		13	May 17,	SYSTEM	(\$292.20)	Estimate Exception 38 on the current Payment Estimate.		
					14	2021 Jun 2,	SYSTEM	\$292.20	This adjustment offsets the original system-generated Material Payment		
						2021			Estimate Item Adjustment (0021) due to user dunnj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.		
					14	Jun 2, 2021	SYSTEM	(\$292.20)			
							15	Jun 16, 2021	SYSTEM	\$292.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user dunnj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
										,	
					15	Jun 16, 2021	SYSTEM	(\$292.20)			
					15		SYSTEM	(\$292.20) \$561.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.		
						2021 Jul 1,			Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment		
					16	Jul 1, 2021 Jul 1, Jul 1,	SYSTEM	\$561.30	Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment		
					16	Jul 1, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16,	SYSTEM SYSTEM	\$561.30 (\$561.30)	Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user dunnj1 overridding Payment		
					16 16 17	Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM	\$561.30 (\$561.30) \$893.70	Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user dunnj1 overridding Payment		
					16 16 17	2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$561.30 (\$561.30) \$893.70 (\$893.70)	Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user dunnj1 overridding Payment Estimate Exception 58 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user dunnj1 overridding Payment		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3049	0370	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	Material			2021			Estimate Item Adjustment (0020) due to user dunnj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$1,352.70)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0370 -	- Total						\$0.00	
	0390	DOWEL BAR (DRILLING, FURNISHING			13	May 17, 2021	SYSTEM	\$45.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user dunnj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
		AND INST			13	May 17, 2021	SYSTEM	(\$45.00)	
					14	Jun 2, 2021	SYSTEM	\$45.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user dunnj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					14	Jun 2, 2021	SYSTEM	(\$45.00)	
					15	Jun 16, 2021	SYSTEM	\$45.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user dunnj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$45.00)	
					16	Jul 1, 2021	SYSTEM	\$45.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user dunnj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$45.00)	
					17	Jul 16, 2021	SYSTEM	\$60.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$60.00)	
						2021			
				- Total		2021		\$0.00	
			Material - To			2021		\$0.00 \$0.00	
	0390 -	- Total	Material - To			2021			
	0390 · 0400	CURVED VANE GRTE AND FRAME(2 FT. X 2			8	Mar 2, 2021	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		CURVED VANE GRTE AND			8	Mar 2,	SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment
		CURVED VANE GRTE AND FRAME(2 FT. X 2				Mar 2, 2021		\$0.00 \$0.00 \$5,000.00	Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment
		CURVED VANE GRTE AND FRAME(2 FT. X 2			8	Mar 2, 2021 Mar 2, 2021 Mar 16,	SYSTEM	\$0.00 \$0.00 \$5,000.00 (\$5,000.00)	Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment
		CURVED VANE GRTE AND FRAME(2 FT. X 2			8	Mar 2, 2021 Mar 2, 2021 Mar 16, 2021	SYSTEM SYSTEM	\$0.00 \$0.00 \$5,000.00 (\$5,000.00) \$6,000.00	Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment
		CURVED VANE GRTE AND FRAME(2 FT. X 2			9	Mar 2, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$5,000.00 (\$5,000.00) \$6,000.00	Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment
		CURVED VANE GRTE AND FRAME(2 FT. X 2			9 9 10	Mar 2, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021 Apr 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$5,000.00 (\$5,000.00) \$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment
		CURVED VANE GRTE AND FRAME(2 FT. X 2			8 9 9 10 10 10	Mar 2, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$5,000.00 (\$5,000.00) \$6,000.00 (\$6,000.00)	Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment
		CURVED VANE GRTE AND FRAME(2 FT. X 2			8 9 9 10 10 11 11	Mar 2, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$5,000.00 (\$5,000.00) \$6,000.00 (\$6,000.00) (\$6,000.00) \$6,000.00	Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment
		CURVED VANE GRTE AND FRAME(2 FT. X 2			9 9 10 10 11 11 11	Mar 2, 2021 Mar 2, 2021 Mar 16, 2021 Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16, 2021 May 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$5,000.00 (\$5,000.00) \$6,000.00 (\$6,000.00) (\$6,000.00) (\$6,000.00)	Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 25 on the current Payment Estimate.
		CURVED VANE GRTE AND FRAME(2 FT. X 2			8 9 9 10 10 11 11 11 12	Mar 2, 2021 Mar 16, 2021 Mar 16, 2021 Apr 2, 2021 Apr 2, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$5,000.00 (\$5,000.00) \$6,000.00 (\$6,000.00) \$6,000.00 (\$6,000.00) \$6,000.00	Estimate Item Adjustment (0005) due to user dunnj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 25 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J6S3049	0400	CURVED VANE GRTE AND	Material	- Total				\$0.00																
		FRAME(2 FT. X 2 FT)	Material - Total					\$0.00																
	0400 -	· Total						\$0.00																
	0460	MISC.	Material		12	May 3, 2021	SYSTEM	\$50,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user dunnj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.															
					12	May 3, 2021	SYSTEM	(\$50,000.00)																
					13	May 17, 2021	SYSTEM	\$50,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.															
					13	May 17, 2021	SYSTEM	(\$50,000.00)																
				- Total				\$0.00																
			Material - To	aterial - Total																				
	0460 -	· Total						\$0.00																
	0690	24 IN. WHITE WATERBORNE PAVEMENT	Material		18	Aug 2, 2021	SYSTEM	\$168.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user dunnj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.															
		MARKING			18	Aug 2, 2021	SYSTEM	(\$168.00)																
						19	Aug 16, 2021	SYSTEM	\$168.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user dunnj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.														
					19	Aug 16, 2021	SYSTEM	(\$168.00)																
				- Total				\$0.00																
			Material - To	rial - Total				\$0.00																
	0690 -	· Total						\$0.00																
	0850	MISC. RIGID PIPE CULVERT	Material		10	Apr 2, 2021	SYSTEM	\$6,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.															
					10	Apr 2, 2021	SYSTEM	(\$6,400.00)																
						11	Apr 16, 2021	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.														
					11	Apr 16, 2021	SYSTEM	(\$9,600.00)																
									12	May 3, 2021	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.											
									12	May 3, 2021	SYSTEM	(\$9,600.00)												
																					13	May 17, 2021	SYSTEM	\$9,600.00
									13	May 17, 2021	SYSTEM	(\$9,600.00)												
								14	Jun 2, 2021	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user dunnj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.												
					14	Jun 2, 2021	SYSTEM	(\$9,600.00)																
					15	Jun 16, 2021	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user dunnj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.															
					15	Jun 16, 2021	SYSTEM	(\$9,600.00)																
					16	Jul 1, 2021	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user dunnj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.															
					16	Jul 1,	SYSTEM	(\$9,600.00)																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6S3049	0850	MISC. RIGID	Material			2021															
		PIPE CULVERT			17	Jul 16, 2021	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user dunnj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.												
					17	Jul 16, 2021	SYSTEM	(\$16,000.00)													
					18	Aug 2, 2021	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user dunnj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.												
					18	Aug 2, 2021	SYSTEM	(\$16,000.00)													
					19	Aug 16, 2021	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user dunnj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.												
					19	Aug 16, 2021	SYSTEM	(\$16,000.00)													
				- Total				\$0.00													
			Material - Tot	tal				\$0.00													
	0850 -	Total						\$0.00													
	0860	PRECAST CONCRETE MANHOLE - 48 IN.	Material		9	Mar 16, 2021	SYSTEM	\$3,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.												
		IIV.			9	Mar 16, 2021	SYSTEM	(\$3,400.00)													
					10	Apr 2, 2021	SYSTEM	\$3,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user dunnj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.												
							10	Apr 2, 2021	SYSTEM	(\$3,400.00)											
					11	Apr 16, 2021	SYSTEM	\$3,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user dunnj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.												
					11	Apr 16, 2021	SYSTEM	(\$3,400.00)													
					12	May 3, 2021	SYSTEM	\$3,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user dunnj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.												
					12	May 3, 2021	SYSTEM	(\$3,400.00)													
					13	May 17, 2021	SYSTEM	\$5,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user dunnj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.												
					13	May 17, 2021	SYSTEM	(\$5,100.00)													
					14	Jun 2, 2021	SYSTEM	\$5,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user dunnj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.												
																	14	Jun 2, 2021	SYSTEM	(\$5,100.00)	
															15	Jun 16, 2021	SYSTEM	\$5,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user dunnj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.		
									15	Jun 16, 2021	SYSTEM	(\$5,100.00)									
																		16	Jul 1, 2021	SYSTEM	\$5,100.00
					16	Jul 1, 2021	SYSTEM	(\$5,100.00)													
					17	Jul 16, 2021	SYSTEM	\$5,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user dunnj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.												
					17	Jul 16, 2021	SYSTEM	(\$5,100.00)													
					18	Aug 2, 2021	SYSTEM	\$5,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user dunnj1 overridding Payment												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J6S3049	0860	PRECAST	Material						Estimate Exception 68 on the current Payment Estimate.											
		CONCRETE MANHOLE - 48 IN.			18	Aug 2, 2021	SYSTEM	(\$5,100.00)												
					19	Aug 16, 2021	SYSTEM	\$5,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user dunnj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.											
					19	Aug 16, 2021	SYSTEM	(\$5,100.00)												
				- Total				\$0.00												
			Material - Tot	al				\$0.00												
	0860 -	Total						\$0.00												
	0950	15 IN. GROUP B FLARED END SEC	Material		13	May 17, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user dunnj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.											
					13	May 17, 2021	SYSTEM	(\$500.00)												
					14	Jun 2, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.											
					14	Jun 2, 2021	SYSTEM	(\$500.00)												
					15	Jun 16, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user dunnj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.											
					15	Jun 16, 2021	SYSTEM	(\$500.00)												
							16	Jul 1, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user dunnj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.									
															16	16	Jul 1, 2021	SYSTEM	(\$500.00)	
							17	Jul 16, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user dunnj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.									
								17	Jul 16, 2021	SYSTEM	(\$500.00)									
					18	Aug 2, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.											
					18	Aug 2, 2021	SYSTEM	(\$500.00)												
				19	19	19	Aug 16, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.										
						19	Aug 16, 2021	SYSTEM	(\$500.00)											
				- Total				\$0.00												
			Material - Tot	al				\$0.00												
	0950 -							\$0.00												
	1080	MGS GUARDRAIL	Construction Stockpile STMI		1	Nov 16, 2020	SYSTEM	\$8,707.44	Payment Estimate Item Adjustment generated Stockpile Transaction											
				- Total				\$8,707.44												
			Construction	Stockpile S	ΓΜΙ - Total			\$8,707.44												
		Total						\$8,707.44												
	1090 GUARDRA	MGS GUARDRAIL, 6 FT. POSTS, 3	Construction Stockpile STMI		1	Nov 16, 2020	SYSTEM	\$4,183.20	Payment Estimate Item Adjustment generated Stockpile Transaction											
		FT 1.5		- Total				\$4,183.20												
			Construction	Stockpile S	ΓΜΙ - Total			\$4,183.20												
	GUARDRAIL, 6 S						\$4,183.20													
		Construction Stockpile STMI		1	Nov 16, 2020	SYSTEM	\$8,082.25	Payment Estimate Item Adjustment generated Stockpile Transaction												
			- Total				\$8,082.25													



1500 1500	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
110 MGS BRIDGE Construction 1 Nov.16, SYSTEM 57,440.00 Payment Estimate Itom Adjustment generated Stockpile Transaction 110 Total 110	J6S3049	1100	GUARDRAIL, 6 FT. POSTS, 1	Construction	Stockpile S1	ГМI - Total			\$8,082.25				
APP: TRANS Stockjele 2000 37,440 00 1110		1100 -	Total						\$8,082.25				
Contraction Stockapte STM - Total		1110	APP. TRANS	Stockpile		1		SYSTEM	\$7,540.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
110 - Total				STMI	- Total				\$7,540.00				
120			· ·	Construction	Stockpile S1	MI - Total			\$7,540.00				
1100 Total Total Sinckpile STMI - Sinckpile STMI - Total Sinckpile STMI - Total Sinckpile STMI - Total Sinckpile Sinc		1110 -	Total						\$7,540.00				
Total		1120		Stockpile		1		SYSTEM	\$3,724.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
1130 TYPE A Construction 1 Nov 16, SYSTEM \$11,928.00 Payment Estimate item Adjustment generated Stockpile Transaction 130 - Total String 28.00				OTIVII					\$3,724.00				
1130				Construction	Stockpile S1	MI - Total			\$3,724.00				
Total		1120 -	Total						\$3,724.00				
Total S11,328.00 S13,379.85 S11,328.00 S11,328.00 S13,379.85 S11,328.00 S11,328.00 S13,379.85 S13,379.85 S11,328.00 S11,328.00 S13,379.85 S11,328.00 S13,379.85 S11,328.00 S11,328.		1130	CRASHWORTHY	Stockpile		1		SYSTEM	\$11,928.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
1100 - Total									\$11,928.00				
1140				Construction	Construction Stockpile STMI - Total				\$11,928.00				
Construction Stockpile Total Similar Total Similar Sim		1130 -	Total						\$11,928.00				
140 - Total		1140	GUARDRAIL	Stockpile		1		SYSTEM	\$3,379.85	Payment Estimate Item Adjustment generated Stockpile Transaction			
1250 CABLE, 10 AWG 17			IIEM			- Total							
1250 CABLE, 10 AWG 1 CONDUCTOR 1				Construction	Stockpile S1	MI - Total			\$3,379.85				
1 CONDUCTOR POLE & BRACKE		1140 -	Total						\$3,379.85				
17		1250	1 CONDUCTOR, POLE &	BLE, 10 AWG CONDUCTOR, POLE &		17		SYSTEM	\$225.00	Estimate Item Adjustment (0049) due to user dunnj1 overridding Payment			
2021 Estimate Item Adjustment (004g) due to user durnif overridding Payment Estimate Exception 70 on the current Payment Estimate.			BRACKE					17		SYSTEM	(\$225.00)		
19									18		SYSTEM	\$225.00	Estimate Item Adjustment (0049) due to user dunnj1 overridding Payment
2021 Estimate Item Adjustment (0049) due to user durnj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.												18	Aug 2, 2021
1250 - Total S0.00						19		SYSTEM	\$225.00	Estimate Item Adjustment (0049) due to user dunnj1 overridding Payment			
1250 - Total						19		SYSTEM	(\$225.00)				
1250 - Total 18					- Total				\$0.00				
1273 CABLE-CONDUIT, 1 IN. 2 2021 18				Material - Tot	al				\$0.00				
CONDUIT, 1 IN., 2 CONDUCTORS 18		1250 -	Total						\$0.00				
18		1273	CONDUIT, 1 IN., 2	Material		18		SYSTEM	\$4,260.00	Estimate Item Adjustment (0053) due to user dunnj1 overridding Payment			
2021 Estimate Item Adjustment (0053) due to user dunnj1 overridding Payment Estimate Exception 70 on the current Payment Estimate. 19			CONDUCTORS			18		SYSTEM	(\$4,260.00)				
CABLE-CONDUCTORS 18 Aug 2, SYSTEM S7,614.00 Stimate Exception 72 on the current Payment Estimate. System System System System System Stimate Exception 72 on the current Payment Estimate. System						19		SYSTEM	\$4,260.00	Estimate Item Adjustment (0053) due to user dunnj1 overridding Payment			
Material - Total \$0.00						19		SYSTEM	(\$4,260.00)				
1273 - Total \$0.00									\$0.00				
1277 CABLE-CONDUIT, 1 IN., 2 CONDUCTORS Material 18 Aug 2, 2021 SYSTEM \$7,614.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user dunnj1 overridding Payment Estimate Exception 72 on the current Payment Estimate. 18 Aug 2, SYSTEM (\$7,614.00)				Material - Total					\$0.00				
CONDUIT, 1 IN., 2 CONDUCTORS 2 CONDUCTORS 2 CONDUCTORS 2 CONDUCTORS 3 18 Aug 2, SYSTEM (\$7,614.00) Estimate Item Adjustment (0052) dué to user dunnj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.		1273 -	Total						\$0.00				
18 Aug 2, SYSTEM (\$7,614.00)		1277	CONDUIT, 1 IN., 2	Material		18	Aug 2, 2021	SYSTEM	\$7,614.00	Estimate Item Adjustment (0052) due to user dunnj1 overridding Payment			
			CONDUCTORS			18		SYSTEM	(\$7,614.00)				



	Drainat	Lina	Description	A dissature a mt	Other	Fot	Created	Created	Amazunt	Demonto													
CONDUCTORS	Project	Line	Description	Adjustment Type	Adjustment	Est. Number	Created Date		Amount	Remarks													
1	J6S3049	1277	CONDUIT, 1 IN., 2	Material		19		SYSTEM	\$7,614.00	Estimate Item Adjustment (0052) due to user dunnj1 overridding Payment													
17			CONDUCTORS			19		SYSTEM	(\$7,614.00)														
1277 - Total 1270 MSC. HICHWAY Material 17					- Total				\$0.00														
1280 MISC HIGHWAY Makerial				Material - To	tal				\$0.00														
LIGHTING		1277 -	· Total						\$0.00														
LIGHTING				Material		17	Jul 16	SYSTEM		This adjustment offsets the original system-generated Material Payment													
18		.200		material			2021			Estimate Item Adjustment (0025) due to user dunnj1 overridding Payment													
2021 Estimate Item Adjustment (0000) due to user during) coveredding Payment Estimate Item Adjustment of Estimate Item Adjustment (0000) due to user during) coveredding Payment Estimate Item Adjustment of Item Organical system-generated Material Payment Item Item Item Item Item Item Item Ite						17		SYSTEM	(\$12,416.00)														
19						18		SYSTEM	\$12,416.00	Estimate Item Adjustment (0050) due to user dunnj1 overridding Payment													
2021 SYSTEM (\$12,416.00) System Estimate Exception 72 on the current Payment Estimate.						18		SYSTEM	(\$12,416.00)														
1280 - Total 17						19		SYSTEM	\$12,416.00	Estimate Item Adjustment (0050) due to user dunnj1 overridding Payment													
1293 Total						19		SYSTEM	(\$12,416.00)														
1293 MISC, HIGHWAY LIGHTING					- Total				\$0.00														
1203 MISC, HIGHWAY LIGHTING				Material - Total					\$0.00														
1293 MISC. HIGHWAY LIGHTING Material 17 Jul 16, SYSTEM 2021 SYSTEM 17, SOSTEM 17, SYSTEM 17, SYSTEM 17, SYSTEM 17, SYSTEM 18, Aug 2, SYSTEM 2021		1290 -	Total																				
2021			MISC. HIGHWAY	Material		17		SYSTEM		Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment													
2021 Estimate Item Aglustment (0051) due to user dunnj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.							17		SYSTEM	(\$7,695.00)													
2021 19							18		SYSTEM	\$7,695.00	Estimate Item Adjustment (0051) due to user dunnj1 overridding Payment												
2021 Estimate Item Adjustment (0051) due to user dunn)1 overridding Payment Estimate Exception 73 on the current Payment Estimate.										18		SYSTEM	(\$7,695.00)										
Total \$0.00						19		SYSTEM	\$7,695.00	Estimate Item Adjustment (0051) due to user dunnj1 overridding Payment													
Total \$0.00						19		SYSTEM	(\$7,695.00)														
1300 SIGNAL HEAD, TYPE 3B 16					- Total				\$0.00														
SIGNAL HEAD, TYPE 3B SIGNAL HEAD, TYPE 3B				Material - To																			
1300 SIGNAL HEAD, TYPE 3B Material TYPE		1202	Total	material - 10																			
16 Jul 1, 2021 SYSTEM (\$11,165.00) 17 Jul 16, 2021 SYSTEM \$11,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user dunnj1 overridding Payment Estimate Exception 71 on the current Payment Estimate. 17 Jul 16, 2021 SYSTEM (\$11,165.00) 18 Aug 2, 2021 SYSTEM \$11,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 75 on the current Payment Estimate. 18 Aug 2, 2021 SYSTEM (\$11,165.00) 19 Aug 16, SYSTEM \$11,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.			SIGNAL HEAD,	Material		16		SYSTEM		Estimate Item Adjustment (0016) due to user dunnj1 overridding Payment													
17 Jul 16, 2021 \$YSTEM \$11,165.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 71 on the current Payment Estimate. 17 Jul 16, 2021 \$YSTEM (\$11,165.00) 18 Aug 2, 2021 \$YSTEM \$11,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 75 on the current Payment Estimate. 18 Aug 2, 2021 \$YSTEM (\$11,165.00) 19 Aug 16, SYSTEM \$11,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.						16		SYSTEM	(\$11,165.00)	Example Exception of the control of													
17 Jul 16, 2021 (\$11,165.00) 18 Aug 2, 2021 \$YSTEM \$11,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 75 on the current Payment Estimate. 18 Aug 2, 2021 \$YSTEM (\$11,165.00) 19 Aug 16, 2021 \$YSTEM \$11,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.								17											17	Jul 16,	SYSTEM	\$11,165.00	Estimate Item Adjustment (0017) due to user dunnj1 overridding Payment
18 Aug 2, 2021 \$YSTEM \$11,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 75 on the current Payment Estimate. 18 Aug 2, 2021 \$YSTEM (\$11,165.00) 19 Aug 16, 2021 \$YSTEM \$11,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.									17		SYSTEM	(\$11,165.00)											
18 Aug 2, 2021 (\$11,165.00) 19 Aug 16, 2021 \$YSTEM \$11,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.					18	Aug 2,	SYSTEM	\$11,165.00	Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment														
19 Aug 16, 2021 \$11,165.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.						18		SYSTEM	(\$11,165.00)	,													
19 Aug 16, SYSTEM (\$11,165.00)						19	Aug 16,	SYSTEM	\$11,165.00	Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment													
						19	Aug 16, 2021	SYSTEM	(\$11,165.00)														



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
049	1300	SIGNAL HEAD, TYPE 3B	Material	- Total				\$0.00			
			Material - To	tal				\$0.00			
	1300 -							\$0.00			
	1310	SIGNAL HEAD, TYPE 4B	Material		16	Jul 1, 2021	SYSTEM	\$5,190.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user dunnj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.		
					16	Jul 1, 2021	SYSTEM	(\$5,190.00)			
					17	Jul 16, 2021	SYSTEM	\$11,418.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user dunnj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.		
					17	Jul 16, 2021	SYSTEM	(\$11,418.00)			
					18	Aug 2, 2021	SYSTEM	\$11,418.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user dunnj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.		
					18	Aug 2, 2021	SYSTEM	(\$11,418.00)			
					19	Aug 16, 2021	SYSTEM	\$11,418.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user dunnj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.		
						19	Aug 16, 2021	SYSTEM	(\$11,418.00)		
				- Total				\$0.00			
			Material - To	tal				\$0.00			
1310 -	Total						\$0.00				
	1320				16	Jul 1, 2021	SYSTEM	\$1,290.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user dunnj1 overridding Payment Estimate Exception 70 on the current Payment Estimate.		
							16	Jul 1, 2021	SYSTEM	(\$1,290.50)	
									17	Jul 16, 2021	SYSTEM
					17	Jul 16, 2021	SYSTEM	(\$2,856.50)			
					18	Aug 2, 2021	SYSTEM	\$3,520.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user dunnj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.		
					18	Aug 2, 2021	SYSTEM	(\$3,520.60)			
					19	Aug 16, 2021	SYSTEM	\$3,520.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user dunnj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.		
					19	Aug 16, 2021	SYSTEM	(\$3,520.60)			
				- Total				\$0.00			
			Material - To	tal				\$0.00			
	1320 -	Total						\$0.00			
	1330	SIGNAL SIGN, MOUNTING HARDWARE	Material		17	Jul 16, 2021	SYSTEM	\$656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user dunnj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.		
					17	Jul 16, 2021	SYSTEM	(\$656.00)			
					18	Aug 2, 2021	SYSTEM	\$820.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user dunnj1 overridding Payment Estimate Exception 78 on the current Payment Estimate.		
					18	Aug 2, 2021	SYSTEM	(\$820.00)			
					19	Aug 16, 2021	SYSTEM	\$820.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user dunnj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.		
					19	Aug 16, 2021	SYSTEM	(\$820.00)			



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
3049	1330	SIGNAL SIGN, MOUNTING	Material	- Total				\$0.00		
		HARDWARE	Material - To	tal				\$0.00		
	1330 -				45	1 40	0)/07514	\$0.00		
	1340	POST, SIGNAL 8 FT. OR 2.4 M	Material		15	Jun 16, 2021	SYSTEM	\$8,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user dunnj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.	
					15	Jun 16, 2021	SYSTEM	(\$8,960.00)		
					16	Jul 1, 2021	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user dunnj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.	
					16	Jul 1, 2021	SYSTEM	(\$9,600.00)		
					17	Jul 16, 2021	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user dunnj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.	
					17	Jul 16, 2021	SYSTEM	(\$9,600.00)		
					18	Aug 2, 2021	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user dunnj1 overridding Payment Estimate Exception 79 on the current Payment Estimate.	
					18	Aug 2, 2021	SYSTEM	(\$9,600.00)		
					19	Aug 16, 2021	SYSTEM	\$9,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user dunnj1 overridding Payment Estimate Exception 78 on the current Payment Estimate.	
					19	Aug 16, 2021	SYSTEM	(\$9,600.00)		
				- Total				\$0.00		
			Material - To	- Total				\$0.00		
	1340 -	Total						\$0.00		
	1350	POST, SIGNAL 15 FT. OR 4.6 M	Material		15	Jun 16, 2021	SYSTEM	\$942.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user dunnj1 overridding Payment Estimate Exception 65 on the current Payment Estimate.	
						15	Jun 16, 2021	SYSTEM	(\$942.00)	
						16	1.14			
						Jul 1, 2021	SYSTEM	\$2,826.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment Estimate Exception 73 on the current Payment Estimate.	
					16		SYSTEM	\$2,826.00 (\$2,826.00)	Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment	
					16	2021 Jul 1,			Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment	
						Jul 1, 2021 Jul 16,	SYSTEM	(\$2,826.00)	Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment Estimate Exception 73 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment	
					17	Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM	(\$2,826.00) \$2,826.00	Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment Estimate Exception 73 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment	
					17	Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM	(\$2,826.00) \$2,826.00 (\$2,826.00)	Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment Estimate Exception 73 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment	
					17 17 18	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,826.00) \$2,826.00 (\$2,826.00) \$2,826.00	Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment Estimate Exception 73 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment	
					17 17 18	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,826.00) \$2,826.00 (\$2,826.00) \$2,826.00 (\$2,826.00)	Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment Estimate Exception 73 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Exception 81 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment	
				- Total	17 17 18 18 19	2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,826.00) \$2,826.00 (\$2,826.00) \$2,826.00 (\$2,826.00) \$2,826.00	Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment Estimate Exception 73 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Exception 81 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment	
			Material - To		17 17 18 18 19	2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,826.00) \$2,826.00 (\$2,826.00) \$2,826.00 (\$2,826.00) \$2,826.00	Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment Estimate Exception 73 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Exception 81 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment	
	1350 -	Total	Material - To		17 17 18 18 19	2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,826.00) \$2,826.00 (\$2,826.00) \$2,826.00 (\$2,826.00) \$2,826.00 (\$2,826.00)	Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment Estimate Exception 73 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Exception 81 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment	
	1350 - 1355	Total POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	Material - To		17 17 18 18 19	2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,826.00) \$2,826.00 (\$2,826.00) \$2,826.00 (\$2,826.00) \$2,826.00 (\$2,826.00)	Estimate Item Adjustment (0038) due to user dunnj1 overridding Payment Estimate Exception 73 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Exception 81 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment	



353-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks																
201 201	1623040	1355	POST TYPE CI						\$6 808 00	This adjustment offsets the original system generated Material Daymont																
10 Aug. 2 975TEM 58,806.00 This adjustment offsets the original system-perceivated Material Payment Ediman. 10 Aug. 1	3033049	1333	30 FT. ARM OR	Material		17		STSTEW	φ0,000.00	Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment																
2021						17		SYSTEM	(\$6,806.00)																	
2021 19						18		SYSTEM	\$6,806.00	Estimate Item Adjustment (0048) due to user dunnj1 overridding Payment																
2021 19						18		SYSTEM	(\$6,806.00)																	
1355 Total 1357 Total 1358 POST, TYPE CL. Material 16						19		SYSTEM	\$6,806.00	Estimate Item Adjustment (0048) due to user dunnj1 overridding Payment																
1955 Total 1975						19	Aug 16, 2021	SYSTEM	(\$6,806.00)																	
1355 - Total 1367 POST, TYPE CL. 1377 POST, TYPE CL. 14 ARM 16 Jul 1, SYSTEM 2021 17 Jul 16, SYSTEM 2021 18 2021 18 2021 18 2021 18 2021 18 2021 18 2021 18 2021 18 2021 18 2021 18 2021 18 2021 2					- Total				\$0.00																	
187 POST_TYPE_CL 40 FT ARM OF T A				Material - Tot	tal				\$0.00																	
2021 SYSTEM (\$8.046.00)		1355 -	Total						\$0.00																	
17		1357	40 FT. ARM OR	Material		16		SYSTEM	\$8,046.00	Estimate Item Adjustment (0015) due to user dunnj1 overridding Payment																
2021 SySTEM (38,046.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 81 on the current Payment Estimate Exception 82 on the current Payment Estimate Exception 85 on the current Payment Estimate Exception 84 on the current Payment Estimate Exception 85 on the current Payment Estimate Exception 87 on the current Payment Estimate Exception 85 on the current Payment Estimate Extendic 10032) due to user dumpt overridding Payment Estimate Exception 85 on the current Payment Estimate Extendic 10032) due to user dumpt overridding Payment Estimate 10032 due to user dumpt overridding Payment Estimate						16		SYSTEM	(\$8,046.00)																	
18						17		SYSTEM	\$8,046.00	Estimate Item Adjustment (0016) due to user dunnj1 overridding Payment																
System Selfmate Item Adjustment (0025) due to user dunn) to veridding Payment Estimate Estimate Exception 85 on the current Payment Estimate.						17		SYSTEM	(\$8,046.00)																	
19							18		SYSTEM	\$8,046.00	Estimate Item Adjustment (0025) due to user dunnj1 overridding Payment															
2021 Sestimate Item Adjustment (0025) due to user dunn[1 overridding Payment Estimate Exception 84 on the current Payment Estimate.										18		SYSTEM	(\$8,046.00)													
1370 POST, TYPE C. 40 FT. ARM OR 12.2 M ARM 16								19		SYSTEM	\$8,046.00	Estimate Item Adjustment (0025) due to user dunnj1 overridding Payment														
1377 Total 1370 POST, TYPE C, 40 FT, ARM OR 12.2 M ARM 16						19		SYSTEM	(\$8,046.00)																	
1377 - Total 1377 - Total 1370 POST, TYPE C. 40 FT. ARM OR 12.2 M ARM 13.2 M ARM 14.2 M ARM 15.2 M ARM 15.2 M ARM 15.2 M ARM 16.2 M ARM 16.2 M ARM 17.2 M ARM 16.2 M ARM 17.2 M ARM 17.2 M ARM 16.2 M ARM 17.2 M ARM 17.2 M ARM 18.2 M ARM 18.					- Total				\$0.00																	
1370 POST, TYPE C, 40 FT. ARM OR 12.2 M ARM 12.2 M ARM 16 2021 SYSTEM \$14,998.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 79 on the current Payment Estimate Exception 79 on the current Payment Estimate Estimate Exception 79 on the current Payment Estimate Estimate Estimate Exception 79 on the current Payment Estimate Estimate Estimate Estimate Estimate Exception 83 on the current Payment Estimate. 17				Material - To	tal				\$0.00																	
2021 Estimate Item Adjustment (0039) due to user dunnj1 overridding Payment Estimate Exception 79 on the current Payment Estimate Exception 79 on the current Payment Estimate.		1357 -	Total						\$0.00																	
17		1370	40 FT. ARM OR	Material		16		SYSTEM	\$14,998.00	Estimate Item Adjustment (0039) due to user dunnj1 overridding Payment																
Estimate Item Adjustment (0044) due to user dunnj1 overridding Payment Estimate Exception 83 on the current Payment Estimate. 17 Jul 16, 2021 18 Aug 2, 2021 SYSTEM \$14,998.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment Estimate Exception 87 on the current Payment Estimate. 18 Aug 2, 2021 SYSTEM \$14,998.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 87 on the current Payment Estimate. 19 Aug 16, 2021 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment Estimate Exception 86 on the current Payment Estimate. 19 Aug 16, 2021 SYSTEM \$14,998.00 Material - Total \$0.00						16		SYSTEM	(\$14,998.00)																	
2021 18 Aug 2, 2021 \$\frac{1}{2021}\$ \$\																						17		SYSTEM	\$14,998.00	Estimate Item Adjustment (0044) due to user dunnj1 overridding Payment
Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment Estimate Exception 87 on the current Payment Estimate. 18 Aug 2, 2021 19 Aug 16, 2021 19 Aug 16, 2021 19 Aug 16, SYSTEM (\$14,998.00) 19 Aug 16, 2021 19 Aug 16, SYSTEM (\$14,998.00) 19 Aug 16, 2021 19 SySTEM (\$14,998.00) 19 Aug 16, 2021 19 SySTEM (\$14,998.00) 10 Aug 16, 2021 11 \$0.00 Material - Total						17		SYSTEM	(\$14,998.00)																	
2021 19 Aug 16, 2021 SYSTEM \$14,998.00 \$14,998.00 \$14,998.00 SYSTEM \$0.00 Material - Total \$0.00												18	Aug 2, 2021	SYSTEM	\$14,998.00	Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment										
Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment Estimate Exception 86 on the current Payment Estimate. 19 Aug 16, 2021 \$0.00 - Total \$0.00 Material - Total \$0.00						18		SYSTEM	(\$14,998.00)																	
2021						19		SYSTEM	\$14,998.00	Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment																
Material - Total \$0.00						19		SYSTEM	(\$14,998.00)																	
					- Total				\$0.00																	
1370 - Total \$0.00				Material - Tot	tal				\$0.00																	
		1370 -	Total						\$0.00																	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3049	1380	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	Material		16	Jul 1, 2021	SYSTEM	\$7,770.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user dunnj1 overridding Payment Estimate Exception 81 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$7,770.00)	
					17	Jul 16, 2021	SYSTEM	\$7,770.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user dunnj1 overridding Payment Estimate Exception 85 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$7,770.00)	
					18	Aug 2, 2021	SYSTEM	\$7,770.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user dunnj1 overridding Payment Estimate Exception 89 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$7,770.00)	
					19	Aug 16, 2021	SYSTEM	\$7,770.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user dunnj1 overridding Payment Estimate Exception 88 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$7,770.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1380 -	- Total						\$0.00	
	1390	CONTROLLER ASSEMBLY HOUSING,	Material		18	Aug 2, 2021	SYSTEM	\$16,155.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user dunnj1 overridding Payment Estimate Exception 91 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$16,155.00)	
					19	Aug 16, 2021	SYSTEM	\$16,155.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user dunnj1 overridding Payment Estimate Exception 90 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$16,155.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
		- Total						\$0.00 \$0.00	
	1390 - 1430	-Total CABLE, 16 AWG 2 CONDUCTOR			15	Jun 16, 2021	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
		CABLE, 16 AWG			15	Jun 16,	SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment
		CABLE, 16 AWG				Jun 16, 2021		\$0.00 \$0.00 \$1,429.20	Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment
		CABLE, 16 AWG			15	Jun 16, 2021 Jun 16, 2021 Jul 1,	SYSTEM	\$0.00 \$0.00 \$1,429.20 (\$1,429.20)	Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 68 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user dunnj1 overridding Payment
		CABLE, 16 AWG			15	Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM	\$0.00 \$0.00 \$1,429.20 (\$1,429.20) \$1,744.65	Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 68 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user dunnj1 overridding Payment
		CABLE, 16 AWG			15 16	Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$1,429.20 (\$1,429.20) \$1,744.65	Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 68 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user dunnj1 overridding Payment Estimate Exception 83 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user dunnj1 overridding Payment
		CABLE, 16 AWG			15 16 16 17	Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,429.20 (\$1,429.20) \$1,744.65 (\$1,744.65)	Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 68 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user dunnj1 overridding Payment Estimate Exception 83 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user dunnj1 overridding Payment
		CABLE, 16 AWG			15 16 16 17	Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,429.20 (\$1,429.20) \$1,744.65 (\$1,744.65) (\$1,744.65)	Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 68 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user dunnj1 overridding Payment Estimate Exception 83 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user dunnj1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user dunnj1 overridding Payment Estimate Item Adjustment (0035) due to user dunnj1 overridding Payment
		CABLE, 16 AWG			15 16 16 17 17	Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,429.20 (\$1,429.20) \$1,744.65 (\$1,744.65) (\$1,744.65) \$1,744.65	Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 68 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user dunnj1 overridding Payment Estimate Exception 83 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user dunnj1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user dunnj1 overridding Payment Estimate Item Adjustment (0035) due to user dunnj1 overridding Payment
		CABLE, 16 AWG			15 16 16 17 17 18	Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,429.20 (\$1,429.20) \$1,744.65 (\$1,744.65) \$1,744.65 (\$1,744.65)	Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 68 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user dunnj1 overridding Payment Estimate Exception 83 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user dunnj1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user dunnj1 overridding Payment Estimate Exception 92 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 92 on the current Payment Estimate.
		CABLE, 16 AWG			15 16 16 17 17 18 18	Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,429.20 (\$1,429.20) \$1,744.65 (\$1,744.65) \$1,744.65 (\$1,744.65) \$1,744.65	Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 68 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user dunnj1 overridding Payment Estimate Exception 83 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user dunnj1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user dunnj1 overridding Payment Estimate Exception 92 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 92 on the current Payment Estimate.
		CABLE, 16 AWG		- Total	15 16 16 17 17 18 18	Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,429.20 (\$1,429.20) \$1,744.65 (\$1,744.65) \$1,744.65 (\$1,744.65) \$1,744.65 (\$1,744.65)	Estimate Item Adjustment (0024) due to user dunnj1 overridding Payment Estimate Exception 68 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user dunnj1 overridding Payment Estimate Exception 83 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user dunnj1 overridding Payment Estimate Exception 87 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user dunnj1 overridding Payment Estimate Exception 92 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 92 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J6S3049	1440	CABLE, 16 AWG 3 CONDUCTOR	Material		16	Jul 1, 2021	SYSTEM	\$1,202.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user dunnj1 overridding Payment Estimate Exception 84 on the current Payment Estimate.									
					16	Jul 1, 2021	SYSTEM	(\$1,202.96)										
					17	Jul 16, 2021	SYSTEM	\$1,202.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user dunnj1 overridding Payment Estimate Exception 88 on the current Payment Estimate.									
					17	Jul 16, 2021	SYSTEM	(\$1,202.96)										
					18	Aug 2, 2021	SYSTEM	\$1,202.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user dunnj1 overridding Payment Estimate Exception 93 on the current Payment Estimate.									
					18	Aug 2, 2021	SYSTEM	(\$1,202.96)										
					19	Aug 16, 2021	SYSTEM	\$1,202.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user dunnj1 overridding Payment Estimate Exception 92 on the current Payment Estimate.									
					19	Aug 16, 2021	SYSTEM	(\$1,202.96)										
			Material - Tota	- Total				\$0.00										
				al				\$0.00										
		Total			45		0)/0==:	\$0.00	The state of the s									
	1450	CABLE, 16 AWG 5 CONDUCTOR	Material		15	Jun 16, 2021	SYSTEM	\$3,356.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user dunnj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.									
						15	Jun 16, 2021	SYSTEM	(\$3,356.85)									
						16	Jul 1, 2021	SYSTEM	\$4,097.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment Estimate Exception 85 on the current Payment Estimate.								
														16	Jul 1, 2021	SYSTEM	(\$4,097.10)	
							17	Jul 16, 2021	SYSTEM	\$4,097.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user dunnj1 overridding Payment Estimate Exception 89 on the current Payment Estimate.							
					17	Jul 16, 2021	SYSTEM	(\$4,097.10)										
					18	Aug 2, 2021	SYSTEM	\$4,097.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user dunnj1 overridding Payment Estimate Exception 94 on the current Payment Estimate.									
					18	Aug 2, 2021	SYSTEM	(\$4,097.10)										
				1	19	Aug 16, 2021	SYSTEM	\$4,097.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user dunnj1 overridding Payment Estimate Exception 93 on the current Payment Estimate.									
					19	Aug 16, 2021	SYSTEM	(\$4,097.10)										
				- Total				\$0.00										
			Material - Tot	al				\$0.00										
		Total						\$0.00										
	1460	CABLE, 16 AWG 7 CONDUCTOR	Material		15	Jun 16, 2021	SYSTEM	\$3,130.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user dunnj1 overridding Payment Estimate Exception 70 on the current Payment Estimate.									
					15	Jun 16, 2021	SYSTEM	(\$3,130.50)										
					16	Jul 1, 2021	SYSTEM	\$6,417.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 86 on the current Payment Estimate.									
					16	Jul 1, 2021	SYSTEM	(\$6,417.00)										
				17	Jul 16, 2021	SYSTEM	\$6,417.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user dunnj1 overridding Payment Estimate Exception 90 on the current Payment Estimate.										
					17	Jul 16,	SYSTEM	(\$6,417.00)										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6S3049	1460	CABLE, 16 AWG	Material			2021															
		7 CONDUCTOR			18	Aug 2, 2021	SYSTEM	\$6,417.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user dunnj1 overridding Payment Estimate Exception 95 on the current Payment Estimate.												
					18	Aug 2, 2021	SYSTEM	(\$6,417.00)													
					19	Aug 16, 2021	SYSTEM	\$6,417.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user dunnj1 overridding Payment Estimate Exception 94 on the current Payment Estimate.												
					19	Aug 16, 2021	SYSTEM	(\$6,417.00)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
			Overrun	Overrun	16	Jul 1, 2021	SYSTEM	\$897.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 96 on the current Payment Estimate. Material Insufficiency Quantity 4278.000; Overrun Quantity Balance 598.00.												
					16	Jul 1, 2021	dunnj1	(\$897.00)	This adjustment offsets the system override of the overrun adjustment. This amount will be paid after a change order has been approved												
					16	Jul 1, 2021	SYSTEM	(\$897.00)													
					17	Jul 16, 2021	SYSTEM	(\$897.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
						17	Jul 16, 2021	SYSTEM	\$897.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 101 on the current Payment Estimate. Material Insufficiency Quantity 4278.000; Overrun Quantity Balance 598.00.											
					18	Aug 2, 2021	SYSTEM	(\$897.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					18	Aug 2, 2021	SYSTEM	\$897.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) overridding Payment Estimate Exception 106 on the current Payment Estimate. Material Insufficiency Quantity 4278.000; Overrun Quantity Balance 598.00.												
						19	Aug 16, 2021	SYSTEM	(\$897.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).											
					19	Aug 16, 2021	SYSTEM	\$897.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) overridding Payment Estimate Exception 105 on the current Payment Estimate. Material Insufficiency Quantity 4278.000; Overrun Quantity Balance 598.00.												
				Overrun - T	otal			(\$897.00)													
			Overrun - To	tal				(\$897.00)													
	1460 -	Total						(\$897.00)													
	1470	RG-8/U COAXIAL CABLE	Material		15	Jun 16, 2021	SYSTEM	\$988.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user dunnj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.												
					15	Jun 16, 2021	SYSTEM	(\$988.00)													
														16	Jul 1, 2021	SYSTEM	\$1,678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 87 on the current Payment Estimate.			
					16	Jul 1, 2021	SYSTEM	(\$1,678.00)													
																	17	Jul 16, 2021	SYSTEM	\$1,678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dunnj1 overridding Payment Estimate Exception 91 on the current Payment Estimate.
												17	Jul 16, 2021	SYSTEM	(\$1,678.00)						
								18	Aug 2, 2021	SYSTEM	\$1,678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user dunnj1 overridding Payment Estimate Exception 96 on the current Payment Estimate.									
				18	Aug 2, 2021	SYSTEM	(\$1,678.00)														
					19	Aug 16, 2021	SYSTEM	\$1,678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user dunnj1 overridding Payment Estimate Exception 95 on the current Payment Estimate.												
				19	Aug 16,	SYSTEM	(\$1,678.00)														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6S3049	1470	RG-8/U COAXIAL CABLE	Material			2021															
		OOT WITTE OF IDEE		- Total				\$0.00													
			Material - To					\$0.00													
			Overrun	Overrun	16	Jul 1, 2021	SYSTEM	\$311.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 97 on the current Payment Estimate. Material Insufficiency Quantity 1678.000; Overrun Quantity Balance 311.00.												
					16	Jul 1, 2021	dunnj1	(\$311.00)	This adjustment offsets the system override of the overrun adjustment. This amount will be paid after a change order has been approved												
					16	Jul 1, 2021	SYSTEM	(\$311.00)													
					17	Jul 16, 2021	SYSTEM	(\$311.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					17	Jul 16, 2021	SYSTEM	\$311.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 102 on the current Payment Estimate. Material Insufficiency Quantity 1678.000; Overrun Quantity Balance 311.00.												
					18	Aug 2, 2021	SYSTEM	(\$311.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					18	Aug 2, 2021	SYSTEM	\$311.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) overridding Payment Estimate Exception 107 on the current Payment Estimate. Material Insufficiency Quantity 1678.000; Overrun Quantity Balance 311.00.												
					19	Aug 16, 2021	SYSTEM	(\$311.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
							19	Aug 16, 2021	SYSTEM	\$311.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) overridding Payment Estimate Exception 106 on the current Payment Estimate. Material Insufficiency Quantity 1678.000; Overrun Quantity Balance 311.00.										
			Overrun - Total					(\$311.00)													
			Overrun - To	tal				(\$311.00)													
	1470 -	Total						(\$311.00)													
	1500	PULL BOX, PREFORMED CLASS 3	Overrun	Overrun	14	Jun 2, 2021	SYSTEM	(\$1,620.00)													
		02.100 0		Overrun - To	otal			(\$1,620.00)													
			Overrun - To	tal				(\$1,620.00)													
	1500 -				40		OVOTEN	(\$1,620.00)	Ti. F. 4 . 6 . 4												
	1510	BASE, CONCRETE	Material				12	12	May 3, 2021	SYSTEM	\$3,696.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user dunnj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.									
								12 13	12	May 3, 2021	SYSTEM	(\$3,696.00)									
											13	May 17, 2021	SYSTEM	\$6,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user dunnj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.						
																13		May 17, 2021	SYSTEM	(\$6,160.00)	
																					14
										14	Jun 2, 2021	SYSTEM	(\$17,164.00)								
				1	18								15	Jun 16, 2021	SYSTEM	\$35,084.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user dunnj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.				
											15		15	Jun 16, 2021	SYSTEM	(\$35,084.00)					
												16	Jul 1, 2021	SYSTEM	\$35,084.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user dunnj1 overridding Payment Estimate Exception 88 on the current Payment Estimate.					
					16	Jul 1, 2021	SYSTEM	(\$35,084.00)													
				17	Jul 16, 2021	SYSTEM	\$35,084.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user dunnj1 overridding Payment Estimate Exception 92 on the current Payment Estimate.													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J6S3049	1510	BASE, CONCRETE	Material		17	Jul 16, 2021	SYSTEM	(\$35,084.00)						
					18	Aug 2, 2021	SYSTEM	\$35,084.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user dunnj1 overridding Payment Estimate Exception 97 on the current Payment Estimate.					
					18	Aug 2, 2021	SYSTEM	(\$35,084.00)						
					19	Aug 16, 2021	SYSTEM	\$35,084.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user dunnj1 overridding Payment Estimate Exception 96 on the current Payment Estimate.					
					19	Aug 16, 2021	SYSTEM	(\$35,084.00)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
	1510 -	Total						\$0.00						
	1520	MISC.	Material		14	Jun 2, 2021	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user dunnj1 overridding Payment Estimate Exception 65 on the current Payment Estimate.					
					14	Jun 2, 2021	SYSTEM	(\$2,520.00)						
					15	Jun 16, 2021	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user dunnj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.					
					15	Jun 16, 2021	SYSTEM	(\$2,520.00)						
							16	Jul 1, 2021	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user dunnj1 overridding Payment Estimate Exception 91 on the current Payment Estimate.			
								16	Jul 1, 2021	SYSTEM	(\$2,520.00)			
					17	Jul 16, 2021	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user dunnj1 overridding Payment Estimate Exception 95 on the current Payment Estimate.					
						17	Jul 16, 2021	SYSTEM	(\$2,520.00)					
					18	Aug 2, 2021	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment Estimate Exception 100 on the current Payment Estimate.					
					18	Aug 2, 2021	SYSTEM	(\$2,520.00)						
					19	Aug 16, 2021	SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user dunnj1 overridding Payment Estimate Exception 99 on the current Payment Estimate.					
					19	Aug 16, 2021	SYSTEM	(\$2,520.00)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
	1520 -	· Total						\$0.00						
	1530	MISC.	Material		15	Jun 16, 2021	SYSTEM	\$8,784.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user dunnj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.					
					15	Jun 16, 2021	SYSTEM	(\$8,784.00)						
												16	Jul 1, 2021	SYSTEM
								16	Jul 1, 2021	SYSTEM	(\$13,176.00)			
				17	Jul 16, 2021	SYSTEM	\$19,032.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user dunnj1 overridding Payment Estimate Exception 97 on the current Payment Estimate.						
				17	Jul 16, 2021	SYSTEM	(\$19,032.00)							
									18	Aug 2, 2021	SYSTEM	\$19,032.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user dunnj1 overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3049	1530	MISC.	Material						Estimate Exception 102 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$19,032.00)	
					19	Aug 16, 2021	SYSTEM	\$19,032.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user dunnj1 overridding Payment Estimate Exception 101 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$19,032.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1530 -	· Total						\$0.00	
	1550	MISC.	Material		15	Jun 16, 2021	SYSTEM	\$6,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user dunnj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$6,160.00)	
					16	Jul 1, 2021	SYSTEM	\$7,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user dunnj1 overridding Payment Estimate Exception 92 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$7,920.00)	
					17	Jul 16, 2021	SYSTEM	\$11,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user dunnj1 overridding Payment Estimate Exception 96 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$11,440.00)	
					18	Aug 2, 2021	SYSTEM	\$11,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user dunnj1 overridding Payment Estimate Exception 101 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$11,440.00)	
					19	Aug 16, 2021	SYSTEM	\$11,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user dunnj1 overridding Payment Estimate Exception 100 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$11,440.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1550 -	Total						\$0.00	
	1590	MISC.	Material		17	Jul 16, 2021	SYSTEM	\$16,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 98 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$16,920.00)	
					18	Aug 2, 2021	SYSTEM	\$16,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user dunnj1 overridding Payment Estimate Exception 103 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$16,920.00)	
					19	Aug 16, 2021	SYSTEM	\$16,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user dunnj1 overridding Payment Estimate Exception 102 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$16,920.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1590 -	90 - Total							
	1610	MISC.	Material		14	Jun 2, 2021	SYSTEM	\$2,166.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dunnj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					14	Jun 2, 2021	SYSTEM	(\$2,166.00)	
					15	Jun 16, 2021	SYSTEM	\$2,166.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user dunnj1 overridding Payment



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3049	1610	MISC.	Material						Estimate Exception 78 on the current Payment Estimate.
					15	Jun 16, 2021	SYSTEM	(\$2,166.00)	
					16	Jul 1, 2021	SYSTEM	\$2,166.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dunnj1 overridding Payment Estimate Exception 94 on the current Payment Estimate.
					16	Jul 1, 2021	SYSTEM	(\$2,166.00)	
					17	Jul 16, 2021	SYSTEM	\$2,166.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user dunnj1 overridding Payment Estimate Exception 99 on the current Payment Estimate.
					17	Jul 16, 2021	SYSTEM	(\$2,166.00)	
					18	Aug 2, 2021	SYSTEM	\$2,166.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user dunnj1 overridding Payment Estimate Exception 104 on the current Payment Estimate.
					18	Aug 2, 2021	SYSTEM	(\$2,166.00)	
					19	Aug 16, 2021	SYSTEM	\$2,166.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user dunnj1 overridding Payment Estimate Exception 103 on the current Payment Estimate.
					19	Aug 16, 2021	SYSTEM	(\$2,166.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1610 -	Total						\$0.00	
	1640	2 IN. PSST POST - 12 GA.	Construction Stockpile STMI		8	Mar 2, 2021	SYSTEM	\$11,594.88	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$11,594.88	
			Construction Stockpile STMI - Total					\$11,594.88	
	1640 -	· Total						\$11,594.88	
	1650	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Construction Stockpile STMI		8	Mar 2, 2021	SYSTEM	\$3,119.58	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$3,119.58	
	1000	Construction Stockpile STMI - Total						\$3,119.58	
	1650 - 1660	POST ANCHOR FOR 2 IN. PSST - 7 GA.	Construction Stockpile STMI				OVOTEM	\$3,119.58	
				Takal	8	Mar 2, 2021	SYSTEM	\$1,766.70	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total				\$1,766.70	
	1660	Total	Construction Stockpile STMI - Total					\$1,766.70	
	1660 -	2.5 IN. PSST	Construction		8	Mor 2	SYSTEM	\$1,766.70 \$657.80	
	1670	POST - 12 GA.	Stockpile STMI	Takal	0	Mar 2, 2021	STSTEM	,	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total				\$657.80 \$657.80	
	1670	· Total	Construction Stockpile STMI - Total						
		POST ANCHOR	Construction		0	Mer o	CVCTEM	\$657.80	Doumant Estimate Itam Adjustment repeated Ct In it. Towards
	1680	FOR 2.5 IN. PSST - 7 GA.	Stockpile STMI	Total	8	Mar 2, 2021	SYSTEM	\$725.01	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total Construction Stockpile STMI - Total					\$725.01 \$725.01	
		Total	construction	Stockpile S	rwii - Total			\$725.01	
	1000	10161	Construction Stocknile					\$725.01	
	1680 - 1690	SH-FLAT SHEET			8	Mar 2, 2021	SYSTEM	\$10,333.20	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction Stockpile STMI	- Total	8	Mar 2, 2021	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
			Stockpile STMI	- Total		2021	SYSTEM	\$10,333.20	Payment Estimate Item Adjustment generated Stockpile Transaction
	1690	SH-FLAT SHEET	Stockpile STMI	- Total 1 Stockpile S		2021	SYSTEM	\$10,333.20 \$10,333.20	Payment Estimate Item Adjustment generated Stockpile Transaction
		SH-FLAT SHEET	Stockpile STMI Construction			2021	SYSTEM	\$10,333.20	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction

Aug 19, 2021



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3049	1700	SHF-FLAT SHEET FLUORESCENT	Construction Stockpile STMI	- Total				\$6,692.60	
			Construction	Stockpile S	MI - Total			\$6,692.60	
	1700 -	Total	Total						
	1970	MISC. HIGHWAY SIGNING	Construction Stockpile STMI		8	Mar 2, 2021	SYSTEM	\$159.84	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$159.84	
			Construction Stockpile STMI - Total					\$159.84	
	1970 -	- Total						\$159.84	
	1980	MISC. HIGHWAY SIGNING	Construction Stockpile		8	Mar 2, 2021	SYSTEM	\$57.24	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$57.24	
			Construction	Stockpile S	MI - Total			\$57.24	
	1980 -	Total						\$57.24	
	1990	MISC. HIGHWAY SIGNING	Construction Stockpile		8	Mar 2, 2021	SYSTEM	\$71.10	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$71.10	
			Construction Stockpile STMI - Total					\$71.10	
	1990 -	Total						\$71.10	
J6S3049 -	Total							\$80,060.56	
Overall - Total								\$80,060.56	