

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 18, 2022

Progress Estimate 18	Number	Contract ID Prime Contracto	201016-H01 or Apex Paving Co		eriod Start eriod End	December 2 January 15,	2022 I	Original Contract Amount Net Change Order Amount Current Contract Amount	\$6,773,481.30 \$383,190.18 \$7,156,671.48
Approval Date									By User
January 18, 2022			Generated and A	pproved (a	ind should b	oe considered	d Draft) a	the Project Office Level by	brooks3
January 18, 2022		Re	viewed and Approv	ved (and sh	nould be co	nsidered Dra	ft) at the	Resident Engineer Level by	bollis1
January 19, 2022			R	deviewed a	nd Approve	ed at the Cent	tral Office	Controllers Office Level by	ramses1
Original Completion	n Date	Current Con	pletion Date	l Completi	on Date	%	of Current Contract Amount Complete		
November 1, 20	21	Decembe	er 7, 2021				98.70%		
	Contract	Informational Dat	es			Milestones			
Date Description	Original	Completion Date	Current Complet	tion Date	No Milest	ones Exist fo	t		
Acceptance Date									
Awarded Date	Novembe	er 5, 2020	November 5, 2020	0					
Letting Date									
Notice to Proceed Date	otice to Proceed Date March 15, 2021			March 15, 2021					
Work Began Date	ork Began Date March 22, 2021								

Contract Total Pa	ay For Estimate No. 18				
		This Estimate	Previous	To Date	
201016-H01					
	Total Posted Items Pay	\$0.00	\$7,063,941.68	\$7,063,941.68	
	Gross Item Adjustments	\$0.00	\$385,356.47	\$385,356.47	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$125,739.82	\$82,917.86	\$208,657.68	
	•		\$7,532,216.01	\$7,657,955.83	
Contract Total Pa	ayable This Estimate:	\$125,739.82			

Items Paid This Estimate Period

No Data Available

No Dat	a Available												
Contract.	<u>Adjustments</u>	This E	<u>stimate</u>										
	Adj Type		Entered By		C	Comment	S	Time	Units	Rat	te	Amo	ount
SPA	ADOther Co Adjus		br	rooks3			o value is - Mix SP125 21-72.						(\$3,232.24)
AE	BIROther Co Adjus		br	rooks3		ess Boni	iving Lane us value is 29,391.73.						\$29,391.73
SPA	ADOther Co Adjus		br	rooks3			D value is Mix SP125 21-72.						\$13,516.64
AE	BIROther Co Adjus		br	rooks3		ess Boni	iving Lane us value is 30,895.32.						\$30,895.32
AE	BIROther Co Adjus		br	rooks3		ess Boni	ssing Lane us value is 29,339.18.						\$29,339.18
AE	BIROther Co Adjus		br	rooks3		ess Boni	ssing Lane us value is 25,829.19.						\$25,829.19
Overall -		se amo	unts are listed in t	he Incer	ntive, Disi	ncentive	e, Liquidate	ed Damages	s or Other (Contract Adj	ustments		\$125,739.82
Line Item	Adjustments	s This	<u>Estimate</u>										
Project Number	Line No.					er Item istment ype		Com	ments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3545	0030		MISC.	Over	run		Averaged	l Price Adjus	stment from	this item on	-41.16	\$26.90	(\$1,107.20)

Revision 4/1/2020 Page 1 of 30



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 18, 2022

Progress Estimate Number	Contract ID					\$6,773,481.30
18	Prime Contractor	Apex Paving Co.	Pay Period End	January 15, 2022	Net Change Order Amount	\$383,190.18
					Current Contract Amount	\$7,156,671.48

roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
913545					all previous payment estimates of '0.00000' is applied (if non-zero).			
	0030	MISC.	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user brooks3 overridding Payment Estimate Exception 6 on the current Payment Estimate.	41.16	\$26.90	\$1,107.20
	0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Material			-4,864.5	\$50.02	(\$243,322.29
	0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	4,864.5	\$50.02	\$243,322.29
	0050	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-593.5	\$73.46	(\$43,598.51
	0050	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Material			-7,479.9	\$73.46	(\$549,473.45
	0050	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 7479.900; Overrun Quantity Balance 593.50.	593.5	\$73.46	\$43,598.51
	0050	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.	7,479.9	\$73.46	\$549,473.45
	0500	SEAL COAT AGGREGATE, GRADE B1	Material			-851	\$5.00	(\$4,255.00
	0500	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.	851	\$5.00	\$4,255.00
	0610	SEAL COAT AGGREGATE, GRADE B1	Material			-851	\$5.00	(\$4,255.00
	0610	SEAL COAT AGGREGATE, GRADE B1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment Estimate Exception 4 on the current Payment Estimate.	851	\$5.00	\$4,255.00
otal								\$0.00

Revision 4/1/2020 Page 2 of 30



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	1
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9I3545	I 55-1(173)	Resurface	I-55	SCOTT	from I-57 to Rte. 77		
Totals by .	Job Numbe	rs					
J9I3545		d Item Pay Item Adjustm		s Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$7,063,941.68 \$385,356.47 \$7,449,298.15	To Date \$7,063,941.68 \$385,356.47 \$7,449,298.15
				·	\$0.00 \$0.00 \$0.00 \$125,739.82	\$0.00 \$0.00 \$0.00 \$82,917.86	\$0.00 \$0.00 \$0.00 \$208.657.68

Revision 4/1/2020 Page 3 of 30



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9I3545, Item 4011211, Project Item Line Number 0040, Material Set 401121196, Material 0401BPPMBP2 - Plant Mix for Bit Pavement BP-2, Acceptance Action Generic AspLow is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3545, Item 4030132, Project Item Line Number 0050, Material Set 403013296, Material 0403SP125BSM - Superpave 12.5 mm, Des B SM, Acceptance Action Generic AspHigh is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3545, Item 4094011, Project Item Line Number 0500, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3545, Item 4094011, Project Item Line Number 0610, Material Set 409401196, Material 1003GB - Aggregate for Seal Coat Grade B1, Acceptance Action Generic 1003GB is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9l3545, Item 7040101, Project Item Line Number 5010, Material Set 704010196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Item Overrun: Contract 201016-H01, Contract Project J9I3545, Project Item Line Number 0030, Contract Line Item Number 0030, Item 3049910, Minor Item.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Item Overrun: Contract 201016-H01, Contract Project J9I3545, Project Item Line Number 0050, Contract Line Item Number 0050, Item 4030132, Minor Item.	No Remark was entered by Engineer	brooks3	Overridden

Revision 4/1/2020 Page 4 of 30



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT		Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201016-H01	J9I3545	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$58,420.05	\$58,420.05
		0001	0020	2159903	MISC.MODIFIED SHAPING SLOPES CLASS III	3,750.00	0.00	3,750.00	LF	3,300.00	\$7.50	\$24,750.00
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	3,710.80	0.00	3,710.80	TONS	3,751.96	\$26.90	\$100,927.72
		0001	0040	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	14,032.60	0.00	14,032.60	TONS	13,864.50	\$50.02	\$693,502.29
		0001	0050	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	54,886.40	0.00	54,886.40	TONS	55,479.90	\$73.46	\$4,075,553.45
		0001	0060	4071005	TACK COAT	54,787.00	0.00	54,787.00	GAL	53,192.00	\$1.90	\$101,064.80
		0001	0070	4134000	BITUMINOUS FOG SEAL	13,348.00	0.00	13,348.00	GAL	0.00	\$2.56	\$0.00
		0001	0080	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	2.00	2.00	4.00	EA	4.00	\$4,250.00	\$17,000.00
		0001	0090	6122020	REPLACEMENT SAND BARREL	8.00	0.00	8.00	EA	0.00	\$300.00	\$0.00
		0001	0100	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	9.00	11.00	EA	11.00	\$687.00	\$7,557.00
		0001	0110	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$250.00	\$0.00
		0001	0120	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	48.00	28.00	76.00	SQYD	76.00	\$462.62	\$35,159.12
		0001	0130	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	5.00	-5.00	0.00	SQYD	0.00	\$30.00	\$0.00
		0001	0140	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	5.00	-5.00	0.00	SQYD	0.00	\$98.00	\$0.00
		0001	0150	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER	204.00	132.00	336.00	LF	336.00	\$6.00	\$2,016.00
		0001	0160	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	120.00	50.00	170.00	EA	170.00	\$18.50	\$3,145.00
		0001	0170	6161005	CONSTRUCTION SIGNS	5,187.00	0.00	5,187.00	SQFT	4,678.00	\$7.00	\$32,746.00
		0001	0180	6161008	ADVANCED WARNING RAIL SYSTEM	42.00	-12.00	30.00	EA	14.00	\$45.00	\$630.00
		0001	0190	6161009	FLAG ASSEMBLY	16.00	0.00	16.00	EA	0.00	\$20.00	\$0.00
		0001	0200	6161025	CHANNELIZER (TRIM LINE)	794.00	0.00	794.00	EA	515.00	\$16.00	\$8,240.00
		0001	0210	6161033	DIRECTIONAL INDICATOR BARRICADE	204.00	0.00	204.00	EA	149.00	\$50.00	\$7,450.00
		0001	0220	6161040	FLASHING ARROW PANEL	11.00	0.00	11.00	EA	10.00	\$725.00	\$7,250.00
		0001	0230	6161055	SEQUENTIAL FLASHING WARNING LIGHT	46.00	0.00	46.00	EA	36.00	\$80.00	\$2,880.00
		0001	0240	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	1.00	3.00	EA	3.00	\$3,500.00	\$10,500.00
		0001	0250	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	8.00	\$2,000.00	\$16,000.00
		0001	0260	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	270.00	30.00	300.00	LF	300.00	\$258.03	\$77,409.00
		0001	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,222.00	675.00	1,897.00	LF	1,897.00	\$31.89	\$60,495.33
		0001	0280	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,222.00	1,222.00	2,444.00	LF	2,444.00	\$11.32	\$27,666.08
		0001	0290	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$48,386.40	\$48,386.40
		0001	0300	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	24.00	0.00	24.00	LF	24.00	\$18.00	\$432.00
		0001	0310	6200039	PREFORMED THERMOPLASTIC PAVEMENT MARKING, OFF RAMP WRONG WAY ARROW	3.00	0.00	3.00	EA	2.00	\$1,800.00	\$3,600.00
		0001	0320	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	8,876.00	0.00	8,876.00	LF	5,078.00	\$1.25	\$6,347.50
		0001	0330	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	201,642.00	0.00	201,642.00	LF	96,516.00	\$0.20	\$19,303.20
		0001	0340	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	161,010.00	0.00	161,010.00	LF	80,743.00	\$0.20	\$16,148.60
		0001	0350	6205906A		3,228.00	0.00	3,228.00	LF	1,750.00	\$0.75	\$1,312.50
		0001	0360	6207001	PAVEMENT MARKING REMOVAL	8,876.00	5,537.00	14,413.00	LF	14,413.00	\$0.70	\$10,089.10
		0001	0370	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0001	0380	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	529,219.00	0.00	529,219.00	SQYD	516,238.00	\$0.60	\$309,742.80
		0001	0390	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	19,092.00	0.00	19,092.00	SQYD	17,669.00	\$2.59	\$45,762.71
		0001	0400	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	3,078.00	0.00	3,078.00	STA	3,078.00	\$21.22	\$65,315.16
		0001	0410	7123000	STEEL BAR DAM	2.00	-2.00	0.00	EA	0.00	\$6,700.00	\$0.00
		0010	0420	6061060	MGS GUARDRAIL	13,550.00	213.00	13,763.00	LF	13,763.00	\$18.00	\$247,734.00
		0010	0430	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	31.00	1.00	32.00	EA	32.00	\$2,450.00	\$78,400.00

Page 5 of 30 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	Line	Item	Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.	Category	No.	Code	Description	Quantity	Change Order	Current Quantity	Offic	Posted Approved Qty	Offit Price	To Date (See report generated date)
201016-H01	J9I3545	0010	0440	6061080	MGS END ANCHOR	24.00	0.00	24.00	EA	24.00	\$950.00	\$22,800.00
		0010	0450	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	29.00	0.00	29.00	EA	29.00	\$2,350.00	\$68,150.00
		0070	0460	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7,612.00	0.00	7,612.00	SQFT	7,612.00	\$1.36	\$10,352.32
		0070	0470	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	71.00	0.00	71.00	LF	71.00	\$310.00	\$22,010.00
		0070	0480	2169903	MISC.Remove and Replace Curb	8.00	0.00	8.00	LF	8.00	\$650.00	\$5,200.00
		0070	0490	4091048	EMULSIFIED ASPHALT, SEAL COAT	341.00	0.00	341.00	GAL	341.00	\$5.00	\$1,705.00
		0070	0500	4094011	SEAL COAT AGGREGATE, GRADE B1	851.00	0.00	851.00	SQYD	851.00	\$5.00	\$4,255.00
		0070	0510	7034214	CLASS B-2 CONCRETE	8.30	0.00	8.30	CUYD	8.30	\$3,940.00	\$32,702.00
		0070	0520	7034600	CURB BLOCKOUT	510.00	0.00	510.00	LF	510.00	\$120.00	\$61,200.00
		0070	0530	7040104	HALF-SOLE REPAIR	700.00	2,280.00	2,980.00	SQFT	2,980.00	\$50.50	\$150,490.00
		0070	0540	7040106	FULL DEPTH REPAIR	200.00	-194.00	6.00	SQFT	6.00	\$70.00	\$420.00
		0070	0550	7101000	REINFORCING STEEL (EPOXY COATED)	540.00	0.00	540.00	LB	540.00	\$6.25	\$3,375.00
		0070	0560	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	71.00	0.00	71.00	LF	71.00	\$475.00	\$33,725.00
		0071	0570	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7,612.00	0.00	7,612.00	SQFT	7,612.00	\$1.36	\$10,352.32
		0071	0580	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	71.00	0.00	71.00	LF	71.00	\$310.00	\$22,010.00
		0071	0590	2169903	MISC.Rermove and Replace Curb	8.00	0.00	8.00	LF	8.00	\$650.00	\$5,200.00
		0071	0600	4091048	EMULSIFIED ASPHALT, SEAL COAT	341.00	0.00	341.00	GAL	341.00	\$5.00	\$1,705.00
		0071	0610	4094011	SEAL COAT AGGREGATE, GRADE B1	851.00	0.00	851.00	SQYD	851.00	\$5.00	\$4,255.00
		0071	0620	7034214	CLASS B-2 CONCRETE	8.30	0.00	8.30	CUYD	8.30	\$3,940.00	\$32,702.00
		0071	0630	7034600	CURB BLOCKOUT	510.00	0.00	510.00	LF	510.00	\$120.00	\$61,200.00
		0071	0640	7040104	HALF-SOLE REPAIR	500.00	2,883.00	3,383.00	SQFT	3,383.00	\$52.00	\$175,916.00
		0071	0650	7040106	FULL DEPTH REPAIR	200.00	-196.70	3.30	SQFT	3.30	\$70.00	\$231.00
		0071	0660	7101000	REINFORCING STEEL (EPOXY COATED)	540.00	0.00	540.00	LB	540.00	\$6.25	\$3,375.00
		0071	0670	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	71.00	0.00	71.00	LF	71.00	\$475.00	\$33,725.00
		0001	5001	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	0.00	4.00	4.00	EA	4.00	\$2,100.00	\$8,400.00
		0001	5002	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	0.00	10,018.00	10,018.00	LF	10,018.00	\$1.25	\$12,522.50
		0071	5003	6214600A	FLOWABLE BACKFILL	0.00	0.00	0.00	CUYD	0.00	\$1,118.40	\$0.00
		0070	5004	7040101	SUBSTRUCTURE REPAIR (FORMED)	0.00	0.00	0.00	SQFT	0.00	\$12,903.93	\$0.00
		0070	5005	7049901	MISC.Girder Modifications Structures A09131 and A09132, Stage 1	0.00	0.00	0.00	LS	0.00	\$2,071.52	\$0.00
		0070	5006	7040101	SUBSTRUCTURE REPAIR (FORMED)	0.00	0.00	0.00	SQFT	0.00	\$8,280.63	\$0.00
		0070	5007	7049901	MISC.Girder Modifications Structures A09131 and A09132 Stage 2	0.00	0.00	0.00	LS	0.00	\$3,444.44	\$0.00
		0010	5008	3109910	MISC.Furnish and Place 6" rock fill in wash outs behind guardrail.	0.00	0.00	0.00	TONS	0.00	\$33.67	\$0.00
		0071	5009	6214600A	FLOWABLE BACKFILL	0.00	1.00	1.00	CUYD	1.00	\$1,174.32	\$1,174.32
		0070	5010	7040101	SUBSTRUCTURE REPAIR (FORMED)	0.00	1.00	1.00	SQFT	1.00	\$13,549.13	\$13,549.13
		0070	5011	7049901	MISC.Girder Modifications Structures A09131 and A09132, Stage 1	0.00	1.00	1.00	LS	1.00	\$2,175.10	\$2,175.10
		0070	5012	7040101	SUBSTRUCTURE REPAIR (FORMED)	0.00	1.00	1.00	SQFT	1.00	\$8,694.66	\$8,694.66
		0070	5013	7049901	MISC.Girder Modifications Structures A09131 and A09132 Stage 2	0.00	1.00	1.00	LS	1.00	\$3,616.66	\$3,616.66
		0010	5014	3109910	MISC.Furnish and Place 6" rock fill in wash outs behind guardrail.	0.00	47.10	47.10	TONS	47.10	\$35.35	\$1,664.98
		0001	5015	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0.00	100,821.00	100,821.00	LF	100,821.00	\$0.12	\$12,098.52
		0001	5016	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0.00	80,505.00	80,505.00	LF	80,505.00	\$0.12	\$9,660.60
		0001	5017	6161030	TYPE III MOVEABLE BARRICADE	0.00	5.00	5.00	EA	5.00	\$78.75	\$393.75
					Date as of Report Generated Date							\$7,063,941.68
201016-H01 Over	rall - Tota	I Value Pos	sted to Da	ite as of Rep	port Generated Date							\$7,063,941.68

Page 6 of 30 Revision 4/1/2020



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post									
913545	0170	March 31, 2021	529	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		76.403	NB I-55, LT. and RT.	2.00	16			3									
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	981+97		NB I-55, LT. and RT	2.00	16			3									
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		76.592	NB I-55, LT. and RT.	2.00	4.67			9.3									
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		76.781	NB I-55, LT. and RT.	2.00	6			1									
				R4-1 36x48 12.00 DO NOT PASS		76.781	NB I-55, LT. and RT.	2.00	12			2									
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		76.971	NB I-55, LT. and RT.	2.00	16			3									
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		77.255	NB I-55, LT.	1.00	16												
				WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)		77.255	NB I-55, RT.	1.00	16												
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		77.255	NB I-55, LT. and RT.	2.00	6												
				R2-1 36x48 12.00 SPEED LIMIT XX		77.255	NB I-55, LT. and RT.	2.00	12			2									
				WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)	916+61		SB I-55, RT.	1	16			1									
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	916+61		SB I-55, LT.	1.00	16			·									
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	966+97		NB I-55, LT.	1.00	16												
								WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)	966+97		NB I-55, RT	1.00	16								
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)	916+61		SB I-55, LT. and RT.	2.00	6												
									G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)	966+97		NB I-55, LT. and RT.	2.00	6							
										R2-1 36x48 12.00 SPEED LIMIT XX	916+61		SB I-55, LT. and RT.	2.00	12			2			
				R2-1 36x48 12.00 SPEED LIMIT XX	928+78		NB I-55, LT. and RT.	2.00	12			2									
				R2-1 36x48 12.00 SPEED LIMIT XX	954+80		SB I-55, LT. and RT.	2.00	12			2									
				R2-1 36x48 12.00 SPEED LIMIT XX	966+97		NB I-55, LT. and RT.	2.00	12			2									
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	1008+37		NB I-55, LT. and RT	2.00	16			3									
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	875+21		SB I-55, LT. and RT.	2.00	16			3									
													WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	901+61		SB I-55, LT. and RT.	2.00	16			3
				CONST-3A 60x48 20.00 FINE SIGN		76.592	NB I-55, LT. and RT.	2.00	20												
		April 19, 2021	217	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		71.16	NB I-55	2	16			;									
		2021		CONST-3A 60x48 20.00 FINE SIGN		71.34	NB I-55	2.00	20			4									
							CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		71.347	NB I-55	2.00	4.67			9.3						
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		71.54	NB I-55	2.00	6												
				R2-1 36x48 12.00 SPEED LIMIT XX		72.2	NB I-55	2.00	12			2									
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		71.72	NB I-55	2.00	16			3									
				WO20-6a 48x48 16.00		72.0	NB I-55	1.00	16			1									

Page 7 of 30 Revision 4/1/2020



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line Number	DWR Date	Total Quantity Posted For	Sign Information	Station	Log Mile	Location	Number of Items	SF Each	Special Sign	SF Each Special	Total SF to															
			DWR Date					0. 1101110	Sign		Sign	Post															
13545	0170	April 19, 2021	217	RIGHT/CENTER/LEFT LANE CLOSED WO4-1aL 48x48 16.00 MERGE		72.0	NB I-55	1.00	16			1															
				(SYMBOL FROM LEFT)		72.0	IND I-00	1.00	10			'															
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		72.2	NB I-55	2.00	6			1:															
				R4-1 36x48 12.00 DO NOT PASS		71.54	NB I-55	2.00	12			2															
		June 15, 2021	216	R4-1 36x48 12.00 DO NOT PASS		131.054	SB I-55 RT/LT	2.00	12			2															
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		131.054	SB I-55 RT/LT	2.00	6			1:															
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		130.865	SB I-55 RT/LT	2.00	16			33															
				R2-1 36x48 12.00 SPEED LIMIT XX		132.490	SB I-55 RT/LT	2.00	12			24															
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		131.244	SB I-55 RT/LT	2.00	16			3:															
				R2-1 36x48 12.00 SPEED LIMIT XX		131.717	SB I-55 RT/LT	2.00	12			24															
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		131.717	SB I-55 RT/LT	2.00	6			12															
				WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)		131.528	SB I-55 RT	1.00	16			16															
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		131.528	SB I-55 LT	1.00	16			16															
				R4-2 36x48 12.00 PASS WITH CARE		132.301	SB I-55 RT/LT	2.00	12			24															
		June 16, 2021	156	WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)		142.750	RT & LT	1.00	16			1															
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		142.894	RT & LT	2.00	6			1:															
					R2-1 36x48 12.00 SPEED LIMIT XX		142.894	RT & LT	2.00	12			24														
																	WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		142.750	RT & LT	1.00	16			10		
						WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		142.465	RT & LT	2.00	16			3:													
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		141.965	RT & LT	2.00	16			3:															
					F > > C ((V ((V F F) >) V ((V F F) >) V ((V F F) >) V (((V F F) >) V (((V F F) >)) V ((((V F F) >))) (((((V F F) >))) ((((((V F F) >)))) ((((((((((((((F X X X X X X X X X X X X X X X X X X X	F X X C G (I) V (G X V F F X X V V	R2-1 36x48 12.00 SPEED LIMIT XX		139.107	RT & LT	2.00	12			24											
								R2-1 36x48 12.00 SPEED LIMIT XX		138.479	RT & LT	2.00	12			2											
								(((((((((((((((((((G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		138.479	RT & LT	2.00	6			1:										
									,	1	V	V	1	1	1	v	v	WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)		138.335	RT & LT	1.00	16			16	
									WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		138.335	RT & LT	1.00	16			16										
											1	F >	F	F >	F >		1	F	R2-1 36x48 12.00 SPEED LIMIT XX		143.522	RT & LT	2.00	12			2
																			v	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		137.550	RT & LT	2.00	16		
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		138.050	RT & LT	2.00	16			3:															
		July 27, 2021	100	WO8-1(36) 36x36 9.00 BUMP		142.329	North of Bridge A0938 SB DL/PL	2.00	9			1															
				WO8-15 48x48 16.00 GROOVED PAVEMENT		67.474	South of Bridge A0938 NB DL/PL	2.00	16			3															
				WO8-1(36) 36x36 9.00 BUMP		67.474	South of Bridge A0938	2.00	9			1															

Revision 4/1/2020 Page 8 of 30



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line Number	DWR	Total Quantity Posted For	Sign Information	Station	Log	Location	Number of Items	SF Each	Special Sign	SF Each	Total SF to															
10105 : 5			DWR Date			Mile	ND DI :=:	OI ILEITIS	Each Sign		Special Sign	Post															
J9I3545	0170	July 27, 2021	100				NB DL/PL																				
				WO8-15 48x48 16.00 GROOVED PAVEMENT		142.329	North of Bridge A0938 SB DL/PL	2.00	16			32															
			396	CONST-3A 60x48 20.00 FINE SIGN		65.044	DL/PL	2.00	20			40															
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		65.044	DL/PL	2.00	4.67			9.34															
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		65.200	DL/PL	2.00	6			12															
				R4-1 36x48 12.00 DO NOT PASS		65.200	DL/PL	2.00	12			24															
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		65.400	DL/PL	2.00	16			32															
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		64.841	DL/PL	2.00	16			3:															
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		64.646	DL/PL	2.00	12			24															
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		64.548	DL/PL	2.00	10			20															
				CONST-7-72 72x36 18.00 RATE OUR WORK ZONE		64.449	DL	1.00	18			18															
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		65.635	DL	1.00	16			16															
				R1-2 48 TRI 6.93 YIELD		Rte HH to I-55 NB	Ramp	1.00	6.93			6.9															
				WO4-1aR 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		65.635	PL	1.00	16			1															
						G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		65.885	DL/PL	2.00	6			1:													
					R2-1 36x48 12.00 SPEED LIMIT XX		65.885	DL/PL	2.00	12			2														
									WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		Rte 60 W to I-55 NB	Ramp	1.00	16			1										
					WO4-1R 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		Rte 60 W to I-55 NB	Ramp	1.00	16			10														
																			R1-2 48 TRI 6.93 YIELD		Rte 60 W to I-55 NB	Ramp	1.00	6.93			6.93
																					WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		Rte 62 to I-55 NB	Ramp	1.00	16	
				WO3-2 48x48 16.00 YIELD AHEAD (SYMBOL)		Rte 62 to I-55 NB	Ramp	1.00	16			16															
																		R1-2 48 TRI 6.93 YIELD		Rte 62 to I-55 NB	Ramp	1.00	6.93			6.93	
																	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		Rte HH to I-55 NB	Ramp	1.00	16			16		
		July 28, 2021				WO3-2 48x48 16.00 YIELD AHEAD (SYMBOL)		Rte HH to I-55 NB	Ramp	1.00	16			10													
			64	WO8-11 48x48 16.00 UNEVEN LANES		67.024	DL/PL	2.00	16			3:															
				WO8-11 48x48 16.00 UNEVEN LANES		67.964		2.00	16			3:															
		August 3, 2021	90	WO8-15 48x48 16.00 GROOVED PAVEMENT		66.086	S of Bridge crossing I-57	1.00	16			10															
				WO8-1(36) 36x36 9.00 BUMP		66.086	S of Bridge Crossing I-57	1.00	9			!															
				WO8-15p 30x24 5.00		66.106	S of Bridge	1.00	5																		

Revision 4/1/2020 Page 9 of 30



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line	DWR	Total Quantity	Sign Information	Station	Log	Location	Number	SF	Special Sign	SF Each	Total
	Number	Date	Posted For DWR Date			Mile		of Items	Each Sign		Special Sign	SF to Post
J9I3545	0170	August 3, 2021	90	MOTORCYCLE (PLAQUE)			crossing I-57					
		2021		WO8-15 48x48 16.00 GROOVED PAVEMENT		67.391	NB DL	1.00	16			16
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		69.460	NB PL	1.00	5			5
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		67.417	NB DL	1.00	5			5
				WO8-1(36) 36x36 9.00 BUMP		69.405	NB PL	1.00	9			9
				WO8-15 48x48 16.00 GROOVED PAVEMENT		69.460	NB PL	1.00	16			16
				WO8-1(36) 36x36 9.00 BUMP		67.391	NB DL	1.00	9			9
		August 5, 2021	178	WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		66.755	DL/PL	2.00	5			10
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		66.755	DL/PL	2.00	16			32
				WO8-11 48x48 16.00 UNEVEN LANES		70.961	DL/PL	2.00	16			32
				WO8-11 48x48 16.00 UNEVEN LANES		69.956	DL/PL	2.00	16			32
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		68.770	DL	1.00	5			5
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		67.766	DL/PL	2.00	5			10
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		67.766	DL/PL	2.00	16			32
				WO8-1(36) 36x36 9.00 BUMP		68.715	DL	1.00	9			9
				WO8-15 48x48 16.00 GROOVED PAVEMENT		68.770	DL	1.00	16			16
		August 6, 2021	64	WO8-11 48x48 16.00 UNEVEN LANES		72.979	DL/PL	2.00	16			32
			42	WO8-11 48x48 16.00 UNEVEN LANES		72.015	DL/PL	2.00	16			32
		August 9, 2021	42	WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		69.75	DL/PL	2.00	5			10
				WO8-17 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		69.75	DL/PL	2.00	16			32
		October 4, 2021	538	WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		70.771	Passing Lane	1.00	16			16
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		70.771	Driving Lane	1.00	16			16
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		70.771	PL/DL	2.00	5			10
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		71.766	Passing Lane	1.00	16			16
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		71.766	Driving Lane	1.00	16			16
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		71.766	PL/DL	2.00	5			10
				WO8-5 48x48 16.00 SLIPPERY WHEN WET (SYMBOL)		72.009	Driving Lane	1.00	16			16
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		72.777	Passing Lane	1.00	16			16
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		72.777	Driving Lane	1.00	16			16
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		72.777	PL/DL	2.00	5			10
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		73.780	Passing Lane	1.00	16			16
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		73.780	Driving Lane	1.00	16			16
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		73.780	PL/DL	2.00	5			10

Revision 4/1/2020 Page 10 of 30



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
913545	0170	October 4, 2021	538	WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		74.784	Passing Lane	1.00	16			16
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		74.784	Driving Lane	1.00	16			10
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		74.784	PL/DL	2.00	5			10
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		75.780	Passing Lane	1.00	16			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		75.780	Driving Lane	1.00	16			1
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		75.780	PL/DL	2.00	5			1
				WO8-11 48x48 16.00 UNEVEN LANES		75.992	PL/DL	2.00	16			3
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		76.805	Passing Lane	1.00	16			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		76.805	Driving Lane	1.00	16			1
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		76.805	PL/DL	2.00	5			1
				WO8-11 48x48 16.00 UNEVEN LANES		76.991	PL/DL	2.00	16			3
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		77.803	Passing Lane	1.00	16			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		77.803	Driving Lane	1.00	16			1
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		77.803	PL/DL	2.00	5			1
				WO8-11 48x48 16.00 UNEVEN LANES		78.009	PL	1.00	16			1
				WO8-11 48x48 16.00 UNEVEN LANES		79.024	PL/DL	2.00	16			3
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		79.816	Passing Lane	1.00	16			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		79.816	Driving Lane	1.00	16			1
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		79.816	PL/DL	2.00	5			1
				WO8-11 48x48 16.00 UNEVEN LANES		80.022	PL/DL	2.00	16			3
		October	240	See Special Sign Details See Special Sign Details		0.129	Rte H	0.00		M1-1 I-55, M3-1	19.50	19.
		12, 2021	2.0	See Special Sign Details		1.06	Rte H	1.00		Detour, M6-3 Ahead M1-1 I-55, M3-1	19.50	19.
				See Special Sign Details		1.00	Rte H at HH	1.00		Detour, M6-3 Ahead M1-1 I-55, M3-1	19.50	19.
				See Special Sign Details			East of I-55	1.00		Detour, M6-1 Right M1-1 I-55, M3-1	19.50	19.
							Bridge on Rte HH			Detour, M6-1 Left		
				WO8-5 48x48 16.00 SLIPPERY WHEN WET (SYMBOL)		65.65	NB I-55	1.00	16		16.00	1
				See Special Sign Details		61.915	Rte 62 East	1.00		M1-1 I-55, M3-1 Detour, M6-1 Left	19.50	19.
				See Special Sign Details		61.817	Rte 62 East	1.00		M1-1 I-55, M3-1 Detour, M5-1L Up and to the Left	19.50	19.
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		61.715	Rte 62 East	1.00	16		16.00	1
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		4.426	East of Rte HH	1.00	16		16.00	1
				See Special Sign Details		24.706	Rte 62 West	1.00		M1-1 I-55, M3-1 Detour, M6-1 Right	19.50	19.

Revision 4/1/2020 Page 11 of 30



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
913545	0170	October 12, 2021	240	See Special Sign Details		24.425	Rte 62 West	1.00		M1-1 I-55, M3-1 Detour, M6-3 Ahead	19.50	19.
				WO20-2 48x48 16.00 DETOUR AHEAD		24.261	Rte 62 West	1.00	16		16.00	1
				See Special Sign Details		1.746	Rte H	1.00		M1-1 I-55, M3-1 Detour, M5-1R Up and to the Right	19.50	19.
		October 19, 2021	222	WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		132.041	DL/PL	2.00	5			10
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		132.041	DL	1.00	16			1
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		132.041	PL	1.00	16			1
				WO8-11 48x48 16.00 UNEVEN LANES		131.832	DL/PL	2.00	16			3
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		131.034	DL/PL	2.00	5			1
				WO8-11 48x48 16.00 UNEVEN LANES		132.852	DL/PL	2.00	16			3.
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		131.034	PL	1.00	16			10
				WO8-11 48x48 16.00 UNEVEN LANES		130.820	DL/PL	2.00	16			3:
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		130.019	DL/PL	2.00	5			10
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		130.019	DL	1.00	16			1
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		130.019	PL	1.00	16			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		131.034	DL	1.00	16			1
		November 3, 2021	708	WO8-11 48x48 16.00 UNEVEN LANES		129.824	DL/PL	2.00	16			3
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		133.037	Passing Lane	1.00	16			1
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		143.074	DL/PL	2.00	5			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		143.074	Driving Lane	1.00	16			1
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		143.074	Passing Lane	1.00	16			1
				WO8-11 48x48 16.00 UNEVEN LANES		142.089	DL/PL	2.00	16			3
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		142.058	DL/PL	2.00	5			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		142.058	Driving Lane	1.00	16			10
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		142.058	Passing Lane	1.00	16			1
				WO8-11 48x48 16.00 UNEVEN LANES		141.865	DL/PL	2.00	16			3
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		140.076	DL/PL	2.00	5			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		133.037	Driving Lane	1.00	16			1
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		133.037	DL/PL	2.00	5			10
				WO8-11 48x48 16.00 UNEVEN LANES		133.856	DL/PL	2.00	16			3:
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		134.046	Passing Lane	1.00	16			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		134.046	Driving Lane	1.00	16			10

Revision 4/1/2020 Page 12 of 30



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line	DWR	Total Quantity	Sign Information	Station	Log	Location	Number	SF	Special Sign	SF Each	Total
,	Number	Date	Posted For DWR Date	9		Mile		of Items	Each Sign	,	Special Sign	SF to Post
913545	0170	November 3, 2021	708	WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		134.046	DL/PL	2.00	5			10
				WO8-11 48x48 16.00 UNEVEN LANES		134.819	DL/PL	2.00	16			3:
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		135.062	Passing Lane	1.00	16			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		135.062	Driving Lane	1.00	16			1
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		135.062	DL/PL	2.00	5			1
				WO8-11 48x48 16.00 UNEVEN LANES		135.869	DL/PL	2.00	16			3
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		136.058	Passing Lane	1.00	16			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		136.058	Driving Lane	1.00	16			1
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		136.058	DL/PL	2.00	5			1
				WO8-11 48x48 16.00 UNEVEN LANES		136.860	DL/PL	2.00	16			3
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		137.058	Passing Lane	1.00	16			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		137.058	Driving Lane	1.00	16			1
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		137.058	DL/PL	2.00	5			1
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		138.066	Passing Lane	1.00	16			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		138.066	Driving Lane	1.00	16			1
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		138.066	DL/PL	2.00	5			1
				WO8-11 48x48 16.00 UNEVEN LANES		138.900	DL/PL	2.00	16			3
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		139.073	Passing Lane	1.00	16			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		139.073	Driving Lane	1.00	16			1
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		139.073	DL/PL	2.00	5			1
				WO8-11 48x48 16.00 UNEVEN LANES		139.883	DL/PL	2.00	16			3
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		140.076	Passing Lane	1.00	16			1
				WO8-17R 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		140.076	Driving Lane	1.00	16			1
		November 16, 2021	217	WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		69.731	Passing Lane	1.00	16			1
				WO4-1aR 48x48 16.00 MERGE (ARROW SYMBOL)		69.731	Driving Lane	1.00	16			1
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		69.546	DL/PL	2.00	16			3
				R4-1 36x48 12.00 DO NOT PASS		69.35	DL/PL	2.00	12			2
				R2-1 36x48 12.00 SPEED LIMIT XX		69.95	DL/PL	2.00	12			2
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		69.185	DL/PL	2.00	4.67			9.3
				CONST-3A 60x48 20.00 FINE SIGN		69.185	DL/PL	2.00	20			4
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		69.01	DL/PL	2.00	16			3
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		69.95	DL/PL	2.00	6			1

Revision 4/1/2020 Page 13 of 30



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J9I3545	0170	November 16, 2021	217	GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		69.35	DL/PL	2.00	6			12
		November 19, 2021	513	See Special Sign Details		28.349	Rte 60 West Driving Lane	1.00		M3-3, M1-1 and M6-1 Left Arrow	19.50	19.5
				See Special Sign Details		314.109	Rte 60 EB Driving Lane	1.00		M3-3, M1-1 and M6-3 Straight	19.50	19.5
				See Special Sign Details		315.228	Rte 60 EB Driving Lane	1.00		M3-3, M1-1 and M6-3 Straight	19.50	19.5
				See Special Sign Details		316.236	Rte 60 EB Driving Lane	1.00		M3-3, M1-1 and M6-3 Straight	19.50	19.5
				See Special Sign Details		316.552	Rte 60 EB Driving Lane	1.00		M3-3, M1-1 and M6-2R Angled to the Right	19.50	19.5
				See Special Sign Details		324.398	Rte 61 SB Driving Lane	1.00		M3-3, M1-1 and M6-1 Left Arrow	19.50	19.5
				WO20-2 48x48 16.00 DETOUR AHEAD		65.525	NB Driving Lane	1.00	16			16
				See Special Sign Details		65.736	NB Driving Lane	1.00		M3-4, M1-4 and M6-3 Straight	19.50	19.5
				See Special Sign Details		66.288	NB Driving Lane	1.00		M3-4, M1-4 and M6-3 Straight	19.50	19.5
				See Special Sign Details		66.805	NB Driving Lane	1.00		M3-4, M1-4 and M6-3 Straight	19.50	19.5
				See Special Sign Details		67.129	NB Driving Lane	1.00		M3-4, M1-4 and M6-2R Angled to the Right	19.50	19.5
				GO20-2 48x24 8.00 END ROAD WORK		81.321	DL/PL	2.00	8			16
				See Special Sign Details		0.143	Rte 62 East to I-55 SB Ramp	1.00		M3-4, M1-4 and M6-3 Straight	19.50	19.5
				See Special Sign Details		0.199	I-55 NB to Rte 62 Off-Ramp	1.00		M3-4, M1-4 and M5-1L Turn Left	19.50	19.5
				See Special Sign Details		0.279	I-55 NB to Rte 62 Off-Ramp	1.00		M3-4, M1-4 and M6-1 Left Arrow	19.50	19.5
				See Special Sign Details		142.974	SB Driving Lane	1.00		M3-4, M1-4 and M6-3 Straight	19.50	19.5
				See Special Sign Details		143.265	SB Driving Lane	1.00		M3-4, M1-4 and M6-2R Angled to the Right	19.50	19.5
				GO20-2 48x24 8.00 END ROAD WORK		144.096	DL/PL	2.00	8			16
				WO20-2 48x48 16.00 DETOUR AHEAD		21.653	I-57 SB Driving Lane	1.00	16			16
				See Special Sign Details		21.810	I-57 SB Driving Lane	1.00		M3-3, M1-1 and M6-3 Straight	19.50	19.5
				See Special Sign Details		24.424	Rte 62 West	1.00		M3-4, M1-4 and M6-3 Straight	19.50	19.5
				See Special Sign Details		24.449	Rte 60 West Driving Lane	1.00		M3-3, M1-1 and M6-3 Straight	19.50	19.5
				See Special Sign Details		24.550	Rte 62 West	1.00		M3-4, M1-4 and M6-1 Left Arrow	19.50	19.5
				See Special Sign Details		24.980	Rte 60 West Driving Lane	1.00		M3-3, M1-1 and M6-3 Straight	19.50	19.5
				See Special Sign Details		25.800	Rte 60 West Driving Lane	1.00		M3-3, M1-1 and M6-3 Straight	19.50	19.5
				See Special Sign Details		26.897	Rte 60 West Driving Lane	1.00		M3-3, M1-1 and M6-2R Angled to the Right	19.50	19.5
				See Special Sign Details		27.204	Rte 60 West Driving Lane	1.00		M3-3, M1-1 and M5-1L Turn Left	19.50	19.5
	0170 - To	otal										4646.15

Revision 4/1/2020 Page 14 of 30



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
3545	0030	MISC. AGGREGATE FOR BASE	Material		17	Dec 2, 2021	SYSTEM	\$100,927.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					17	Dec 2, 2021	SYSTEM	(\$100,927.72)		
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
			Overrun	Overrun	17	Dec 2, 2021	SYSTEM	\$1,107.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 10 on the current Payment Estimate. Material Insufficiency Quantity 3751.960; Overrun Quantity Balance 41.16.	
					17	Dec 2, 2021	SYSTEM	(\$1,107.20)		
					18	Jan 18, 2022	SYSTEM	(\$1,107.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
					18	Jan 18, 2022	SYSTEM	\$1,107.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user brooks3 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
				Overrun - T	otal			\$0.00	Estimate Exception 6 on the current rayment Estimate.	
			Overrun - Tota					\$0.00		
	0030 -	Total						\$0.00		
	0040	BIT. PAVEMENT MIXTURE PG64-22 (BP-2)	Material		16	Nov 16, 2021	SYSTEM	\$412,414.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					16	Nov 16, 2021	SYSTEM	(\$412,414.90)		
						17	Dec 2, 2021	SYSTEM	\$243,322.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Dec 2, 2021	SYSTEM	(\$243,322.29)		
					18	Jan 18, 2022	SYSTEM	\$243,322.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					18	Jan 18, 2022	SYSTEM	(\$243,322.29)		
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
			Other Item Adjustment	ACAD	10	Aug 16, 2021	brooks3	\$4,489.97	For 1353.4 tons placed the value is \$4489.97	
					14	Oct 19, 2021	brooks3	\$16,140.80	For the 5044 tons placed the value is \$16,140.80.	
					16	Nov 16, 2021	brooks3	\$17,269.12	For the 5396.60 Tons placed the value is \$17,269.12.	
					17	Dec 2, 2021	brooks3	\$5,182.40	For the 1619.50 tons placed the value is \$5,182.40.	
				ACAD - Tot	al			\$43,082.29		
			Other Item Ad	justment - To	otal			\$43,082.29		
	0040 -	Total						\$43,082.29		
	0050	ASPHALTIC CONCRETE	Material		10	Aug 23, 2021	SYSTEM	(\$497,662.12)	Addded to address the 'ghost' adjustment on Estimate 0010	
		MIXTURE PG 76-22 (SP1			10	Aug 17, 2021	SYSTEM	\$497,662.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user bollis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					10	Aug 17, 2021	SYSTEM	(\$497,662.12)		
			11	1:	11	Sep 2, 2021	SYSTEM	\$1,401,411.11	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					11	Sep 2, 2021	SYSTEM	(\$1,401,411.11)		
					12	Sep 15, 2021	SYSTEM	\$1,401,411.11	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					12	Sep 15,	SYSTEM	(\$1,401,411.11)		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3545	0050	ASPHALTIC	Material			2021			
		CONCRETE MIXTURE PG 76-22 (SP1			13	Oct 1, 2021	SYSTEM	\$1,637,144.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Oct 1, 2021	SYSTEM	(\$1,637,144.25)	
					14	Oct 19, 2021	SYSTEM	\$497,662.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Oct 19, 2021	SYSTEM	(\$497,662.12)	
					15	Nov 2, 2021	SYSTEM	\$497,662.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Nov 2, 2021	SYSTEM	(\$497,662.12)	
					16	Nov 16, 2021	SYSTEM	\$1,010,221.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Nov 16, 2021	SYSTEM	(\$1,010,221.92)	
					17	Dec 2, 2021	SYSTEM	\$549,473.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					17	Dec 2, 2021	SYSTEM	(\$549,473.45)	
					18	Jan 18, 2022	SYSTEM	\$549,473.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					18	Jan 18, 2022	SYSTEM	(\$549,473.45)	
				- Total		ZUZZ		(\$497,662.12)	
			Material - Tota					(\$497,662.12)	
			MaterialCredit		11	Sep 2, 2021	SYSTEM	\$497,662.12	
				- Total				\$497,662.12	
			MaterialCredit	- Total				\$497,662.12	
			Other Item Adjustment	ACAD	9	Aug 2, 2021	woodsk1	\$16,823.89	AC Adjustment.
			,		10	Aug 16, 2021	brooks3	\$43,348.62	For the 6739.00 tons placed the value is \$43,348.62.
					11	Sep 2, 2021	brooks3	\$59,698.10	For 9280.7 tons placed the value is \$59,698.10.
					13	Oct 1, 2021	woodsk1	\$20,890.59	AC Adjustment For Hot Mix Asphalt This Pay Period.
					14	Oct 19, 2021	brooks3	\$54,582.32	For the 8803.60 tons placed the value is \$54,582.32
					15	Nov 2, 2021	brooks3	\$78,159.68	For the 12,606.40 tons placed the value is \$78,159.68.
					16	Nov 16, 2021	brooks3	\$65,148.36	For the 10,507.80 Tons placed the value is \$65,148.36.
					17	Dec 2, 2021	brooks3	\$10,712.98	For the 1727.90 tons placed the value was \$10,712.98
				ACAD - Tot	al			\$349,364.54	
				OTHR		Oct 1,	woodsk1	\$29,384.00	TSR Adjustment (For SP-125)
						2021			Lot #2 \$14,692
									Lot #3 \$14,692
					14	Oct 19, 2021	brooks3	(\$29,384.00)	The sum of \$29,384.00 was paid in estimate 0013 as TSR Adjustment. This should've been paid as a Contract Adjustment for SPAD. Will correct in estimate 0014.
				OTHR - Tota	al			\$0.00	
			Other Item Ad	justment - To	otal			\$349,364.54	
			Overrun	Overrun	17	Dec 2,	SYSTEM	\$33,997.29	This adjustment offsets the original system-generated Overrun Payment



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5	0050	ASPHALTIC CONCRETE MIXTURE PG	Overrun	Overrun		2021			Estimate Item Adjustment (0003) overridding Payment Estimate Exception 1 on the current Payment Estimate. Material Insufficiency Quantity 7479.900; Overrun Quantity Balance 593.50.
		76-22 (SP1			17	Dec 2, 2021	SYSTEM	\$9,601.22	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 1 on the current Payment Estimate. Material Insufficiency Quantity 7479.900; Overrun Quantity Balance 593.50.
					17	Dec 2, 2021	SYSTEM	(\$43,598.51)	
					18	Jan 18, 2022	SYSTEM	(\$43,598.51)	Averaged Price Adjustment from this item on all previous payment estimate of '0.00000' is applied (if non-zero).
					18	Jan 18, 2022	SYSTEM	\$43,598.51	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception on the current Payment Estimate. Material Insufficiency Quantity 7479.900; Overrun Quantity Balance 593.50.
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0050 -	Total						\$349,364.54	
Ī	0060	TACK COAT	Material		9	Aug 2, 2021	SYSTEM	\$5,061.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Paymer Estimate Exception 1 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$5,061.60)	
					10	Aug 23, 2021	SYSTEM	(\$18,944.90)	Addded to address the 'ghost' adjustment on Estimate 0010
					10	Aug 17, 2021	SYSTEM	\$18,944.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user bollis1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Aug 17, 2021	SYSTEM	(\$18,944.90)	
					13	Oct 1, 2021	SYSTEM	\$38,881.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Oct 1, 2021	SYSTEM	(\$38,881.60)	
					14	Oct 19, 2021	SYSTEM	\$58,026.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Oct 19, 2021	SYSTEM	(\$58,026.00)	
					15	Nov 2, 2021	SYSTEM	\$77,708.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Nov 2, 2021	SYSTEM	(\$77,708.10)	
				- Total				(\$18,944.90)	
			Material - Tota	al .				(\$18,944.90)	
			MaterialCredit		11	Sep 2, 2021	SYSTEM	\$18,944.90	
				- Total				\$18,944.90	
			MaterialCredit	- Total				\$18,944.90	
	0060 -				_		0)40==::	\$0.00	
	0100	IMPACT ATTENUATOR (RELOCATION)	Overrun	Overrun		Jul 1, 2021	SYSTEM	(\$2,061.00)	
					8	Jul 15, 2021	SYSTEM	\$2,061.00	Unit price based on averaged overrun adjustments for installed quantity on previous payment estimates. Price Adjustments of ',687.00000 - 687.00000 applied (if non-zero).
				Overrun - T	otal			\$0.00	
	0100		Overrun - Tota	al				\$0.00	
	0100 -		Material		0	Mari 2	OVOTE:	\$0.00	This adjustment offset the original and
	0120	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		3	May 3, 2021	SYSTEM	\$22,205.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user connen1 overridding Paymen Estimate Exception 1 on the current Payment Estimate.
							SYSTEM	(\$22,205.76)	



	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
CONTROL CAMPATER	,		'		Adjustment					
Total	J9I3545	0120	CONC MATL FOR	Material		4		SYSTEM	\$22,205.76	Estimate Item Adjustment (0002) due to user connen1 overridding Payment
Section Color Co						4		SYSTEM	(\$22,205.76)	
CASK NC					- Total				\$0.00	
CAS CAS Covers Covers				Material - Tota	al				\$0.00	
COMMUNICATION NITERY ACC. 14		0120 -	Total						\$0.00	
14		0240	COMMUNICATION INTERFACE,	Overrun	Overrun	14		SYSTEM	\$3,500.00	Estimate Item Adjustment (0001) due to user brooks3 overridding Payment
15			CONT F/			14		SYSTEM	(\$3,500.00)	
2021 Settinate Item Adjustment (000°) due to user brooks3 overniding Payment Estimate Exception 1 on the Payment Estimate Exception 1 on the Current Payment Estimate (1974) Settinate Item Adjustment Item Adjustme						15		SYSTEM	(\$3,500.00)	
2021 16						15		SYSTEM	\$3,500.00	Estimate Item Adjustment (0001) due to user brooks3 overridding Payment
Community Comm						16		SYSTEM	(\$3,500.00)	
						16		SYSTEM	\$3,500.00	Estimate Item Adjustment (0001) due to user brooks3 overridding Payment
1					Overrun - T	otal			\$0.00	
A				Overrun - Tota	al				\$0.00	
### TRAFFIC BARRIER, TYPE B 2021		0240 -	Total						\$0.00	
2021		0260	TRAFFIC	Material		4		SYSTEM	\$10,321.20	Estimate Item Adjustment (0003) due to user connen1 overridding Payment
2021 SYSTEM S94,834,05 SYSTEM S47,735,55 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate Payment Estimate Exception 1 on the current Payment Estimate Payment Estimate Item Adjustment (002) due to user lezer J overridding Payment Estimate Item Adjustment (002) due to user lezer J overridding Payment Estimate Item Adjustment (002) due to user lezer J overridding Payment Estimate Item Adjustment (013) due to user lezer J overridding Payment Estimate Item Adjustment (013) due to user lezer J overridding Payment Estimate Item Adjustment (013) due to user lezer J overridding Payment Estimate Item Adjustment (013) due to user lezer J overridding Payment Estimate Exception 1 on the current Payment Estimate Payment Estimate Exception 1 on the current Payment Estimate Payment Estimate Exception 1 on the current Payment Estimate Payment Estimate Exception 1 on the current Payment Estimate Payment Estimate Exception 1 on the current Payment Estimate Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Payment Estimate Payment Estimate Payment Estimate Payment Estimate Payment Estimate Exception 7 on the current Payment Estimate Payment Payment Estimate Payment Payment Estimate Payment Pay						4		SYSTEM	(\$10,321.20)	
2021 6						5		SYSTEM	\$34,834.05	Estimate Item Adjustment (0002) due to user brooks3 overridding Payment
2021 Estimate tem Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						5		SYSTEM	(\$34,834.05)	
2021						6		SYSTEM	\$47,735.55	Estimate Item Adjustment (0002) due to user leez1 overridding Payment
Estimate Item Adjustment (0013) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						6		SYSTEM	(\$47,735.55)	
2021 8						7		SYSTEM	\$64,507.50	Estimate Item Adjustment (0013) due to user leez1 overridding Payment
System						7		SYSTEM	(\$64,507.50)	
2021 9						8		SYSTEM	\$69,668.10	Estimate Item Adjustment (0011) due to user leez1 overridding Payment
2021 Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						8		SYSTEM	(\$69,668.10)	
10						9		SYSTEM	\$69,668.10	Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment
2021 10 Aug 17, 2021 \$69,668.10 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user bollis1 overridding Payment Estimate Exception 8 on the current Payment Estimate. 10 Aug 17, 2021 \$(\$69,668.10)						9		SYSTEM	(\$69,668.10)	
2021 Estimate Item Adjustment (0036) due to user bollis1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						10		SYSTEM	(\$69,668.10)	Addded to address the 'ghost' adjustment on Estimate 0010
2021 (\$69,668.10)						10		SYSTEM	\$69,668.10	Estimate Item Adjustment (0036) due to user bollis1 overridding Payment
Material - Total (\$69,668.10)						10		SYSTEM	(\$69,668.10)	
					- Total				(\$69,668.10)	
MaterialCredit 11 Sep 2, SYSTEM \$69,668.10				Material - Tota	al				(\$69,668.10)	
				MaterialCredit		11	Sep 2,	SYSTEM	\$69,668.10	



oject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks							
			Туре	Adjustment Type	Number	Date	Ву									
3545	0260	CONCRETE TRAFFIC	MaterialCredit			2021										
		BARRIER, TYPE B		- Total				\$69,668.10								
			MaterialCredit	- Total				\$69,668.10								
	0260 -							\$0.00								
	0270	TEMPORARY TRAFFIC BARRIER, CONT.	Overrun	Overrun	7	Jul 1, 2021	SYSTEM	(\$14,350.50)								
		FURN/RE			8	Jul 15, 2021	SYSTEM	\$14,350.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',31.89000 - 31.89000, 'is applied (if non-zero).							
				Overrun - T	otal			\$0.00								
			Overrun - Tota	il				\$0.00								
	0270 -	Total						\$0.00								
	0280	RELOCATING TEMPORARY	Overrun	Overrun	7	Jul 1, 2021	SYSTEM	(\$10,437.04)								
		TRAFFIC BARRIER			8	Jul 15, 2021	SYSTEM	\$10,437.04	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',11.32000 - 11.32000, 'is applied (if non-zero).							
				Overrun - T	otal			\$0.00								
			Overrun - Tota	ıl				\$0.00								
	0280 -	Total						\$0.00								
	0300	PREF THERMO PVMT MARK, 24 IN WHIT	Material		17	Dec 2, 2021	SYSTEM	\$432.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brooks3 overridding Payment Estimate Exception 7 on the current Payment Estimate.							
					17	Dec 2, 2021	SYSTEM	(\$432.00)								
				- Total				\$0.00								
		2000 T-4-1	Material - Tota					\$0.00								
	0300 -	Total						\$0.00								
	0320	TEMPORARY REMOVABLE MARKING TAPE 4	Material		1	Apr 2, 2021	SYSTEM	\$5,878.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
				IN.,	IN.,	IN.,	IN.,	IN.,	IN.,			1	Apr 2, 2021	SYSTEM	(\$5,878.75)	
					2	Apr 16, 2021	SYSTEM	\$5,878.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					2	Apr 16, 2021	SYSTEM	(\$5,878.75)								
				- Total				\$0.00								
			Material - Tota					\$0.00								
	0320 -	Total						\$0.00								
	0330	6 IN. WHITE HIGH BUILD WATERBORNE	Material		15	Nov 2, 2021	SYSTEM	\$19,303.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate.							
		PAINT			15	Nov 2, 2021	SYSTEM	(\$19,303.20)								
				- Total				\$0.00								
			Material - Tota	ı				\$0.00								
			Other Item Adjustment	REFL	15	Nov 2, 2021	brooks3	(\$3,860.64)	Withheld 20% until Retroreflectivity Test are validated \$19,303.20 x 20% = \$3,860.64							
				REFL - Tota	ı			(\$3,860.64)								
			Other Item Ad	justment - To	tal			(\$3,860.64)								
	0330 -	Total						(\$3,860.64)								
	0340	6 IN. YELLOW HIGH BUILD WATERBORNE	Material		15	Nov 2, 2021	SYSTEM	\$16,148.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brooks3 overridding Payment Estimate Exception 7 on the current Payment Estimate.							
		PAINT			15	Nov 2, 2021	SYSTEM	(\$16,148.60)								
				- Total				\$0.00								
			Material - Tota	ı				\$0.00								



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
45	0340	6 IN. YELLOW HIGH BUILD WATERBORNE	Other Item Adjustment	REFL		Nov 2, 2021	brooks3	(\$3,229.72)	Withheld 20% until Retroreflectivity Test are validated \$16,148.60 x 20% = \$3,229.72	
		PAINT		REFL - Tota				(\$3,229.72)		
			Other Item Ad	justment - To	tal			(\$3,229.72)		
	0340 -							(\$3,229.72)		
	0350	12 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material		15	Nov 2, 2021	SYSTEM	\$1,312.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brooks3 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
		. /			15	Nov 2, 2021	SYSTEM	(\$1,312.50)		
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
	0350 -	Total						\$0.00		
	0360	PAVEMENT MARKING REMOVAL	Overrun	Overrun		Jul 1, 2021	SYSTEM	(\$106.40)		
					8	Jul 15, 2021	SYSTEM	\$106.40	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.70000 - 0.70000, 'is applied (if non-zero).	
				Overrun - T	otal			\$0.00		
			Overrun - Tota	al				\$0.00		
	0360 -							\$0.00		
	0420	MGS GUARDRAIL	Construction Stockpile		2	Apr 16, 2021	SYSTEM	(\$15,550.17)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					4	May 17, 2021	SYSTEM	(\$74,443.58)	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Construction Construction	- Total				(\$89,993.75)		
					Stockpile - To				(\$89,993.75)	
				Construction Stockpile STMI		2	Apr 16, 2021	SYSTEM	\$89,993.75	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total					\$89,993.75		
			Construction	ıction Stockpile STMI - Total				\$89,993.75		
	0420 -							\$0.00		
	0430	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		2	Apr 16, 2021	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction	
					4	May 17, 2021	SYSTEM	(\$14,071.53)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					5	Jun 2, 2021	SYSTEM	(\$11,257.22)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					6	Jun 16, 2021	SYSTEM	(\$10,806.94)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$38,950.00)		
			Construction	Stockpile - 10		4 40	OVOTEM	(\$38,950.00)		
			Construction Stockpile STMI	Total	2	Apr 16, 2021	SYSTEM	\$38,950.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$38,950.00		
	0.100		Construction	Stockpile STI	vii - Total			\$38,950.00		
	0430 -		0 1 "		,		0)/0==:	\$0.00		
	0440	MGS END ANCHOR	Construction Stockpile		4	May 17, 2021	SYSTEM	(\$9,418.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$9,418.00)		
			Construction	Stockpile - To			0)/0==:	(\$9,418.00)		
			Construction Stockpile STMI		2	Apr 16, 2021	SYSTEM	\$9,418.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$9,418.00		
			Construction					\$9,418.00		
			Overrun	Overrun		Jul 1, 2021	SYSTEM	(\$950.00)		
					8	Jul 15, 2021	SYSTEM	\$950.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',950.00000 - 950.00000, 'is applied (if non-zero).	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J9I3545	0440	MGS END ANCHOR	Overrun	Overrun - T	otal			\$0.00			
		ANCHOR	Overrun - Tota	al				\$0.00			
	0440 -	Total						\$0.00			
	0450	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		2	Apr 16, 2021	SYSTEM	(\$9,415.29)	Payment Estimate Item Adjustment generated Stockpile Transaction		
		(MASH)			4	May 17, 2021	SYSTEM	(\$20,148.71)	Payment Estimate Item Adjustment generated Stockpile Transaction		
				- Total				(\$29,564.00)			
			Construction	Stockpile - To	otal			(\$29,564.00)			
			Construction Stockpile STMI		2	Apr 16, 2021	SYSTEM	\$29,564.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
			STIVII	- Total				\$29,564.00			
			Construction	Stockpile STI	MI - Total			\$29,564.00			
	0450 -	Total						\$0.00			
	0490	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 2, 2021	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					9	Aug 2, 2021	SYSTEM	(\$1,705.00)			
					10	Aug 23, 2021	SYSTEM	(\$1,705.00)	Addded to address the 'ghost' adjustment on Estimate 0010		
							10	Aug 17, 2021	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user bollis1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Aug 17, 2021	SYSTEM	(\$1,705.00)			
				- Total	- Total			(\$1,705.00)			
			Material - Tota	al				(\$1,705.00)			
			MaterialCredit		11	Sep 2, 2021	SYSTEM	\$1,705.00			
				- Total				\$1,705.00			
			MaterialCredit	t - Total				\$1,705.00			
	0490 -	Total						\$0.00			
	0500	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 2, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					9	Aug 2, 2021	SYSTEM	(\$4,255.00)			
					10	Aug 23, 2021	SYSTEM	(\$4,255.00)	Addded to address the 'ghost' adjustment on Estimate 0010		
					10	Aug 17, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user bollis1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					10	Aug 17, 2021	SYSTEM	(\$4,255.00)			
					11	Sep 2, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					11	Sep 2, 2021	SYSTEM	(\$4,255.00)			
					12	Sep 15, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					12	Sep 15, 2021					
				13	13	Oct 1, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					13	Oct 1, 2021	SYSTEM	(\$4,255.00)			
					14	Oct 19, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3545	0500	SEAL COAT AGGREGATE,	Material		14	Oct 19, 2021	SYSTEM	(\$4,255.00)	
		GRADE B1			15	Nov 2, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Nov 2, 2021	SYSTEM	(\$4,255.00)	
					16	Nov 16, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					16	Nov 16, 2021	SYSTEM	(\$4,255.00)	
					17	Dec 2, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brooks3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					17	Dec 2, 2021	SYSTEM	(\$4,255.00)	
					18	Jan 18, 2022	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					18	Jan 18, 2022	SYSTEM	(\$4,255.00)	
				- Total				(\$4,255.00)	
			Material - Tota	ıl				(\$4,255.00)	
			MaterialCredit		11	Sep 2, 2021	SYSTEM	\$4,255.00	
				- Total				\$4,255.00	
			MaterialCredit	- Total				\$4,255.00	
	0500 -	Total						\$0.00	
	0510	CLASS B-2 CONCRETE			4	May 17, 2021	SYSTEM	\$16,548.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$16,548.00)	
				- Total				\$0.00	
			Material - Tota	al .				\$0.00	
	0510 -	Total						\$0.00	
	0520	CURB BLOCKOUT	Material		4	May 17, 2021	SYSTEM	\$30,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user connen1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$30,600.00)	
					5	Jun 2, 2021	SYSTEM	\$30,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jun 2, 2021	SYSTEM	(\$30,600.00)	
					6	Jun 16, 2021	SYSTEM	\$61,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jun 16, 2021	SYSTEM	(\$61,200.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0520 -							\$0.00	
	0530	HALF-SOLE REPAIR	Material		2	Apr 16, 2021	SYSTEM	\$35,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Apr 16, 2021	SYSTEM	(\$35,350.00)	
					0	May 3,	SYSTEM	\$35,350.00	This adjustment offsets the original system-generated Material Payment
					3	2021		***,******	Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3545	0530	HALF-SOLE REPAIR	Material		5	Jun 2, 2021	SYSTEM	\$70,195.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jun 2, 2021	SYSTEM	(\$70,195.00)	
					6	Jun 16, 2021	SYSTEM	\$70,195.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Jun 16, 2021	SYSTEM	(\$70,195.00)	
					7	Jul 1, 2021	SYSTEM	\$70,195.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$70,195.00)	
					8	Jul 15, 2021	SYSTEM	\$70,195.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jul 15, 2021	SYSTEM	(\$70,195.00)	
					9	Aug 2, 2021	SYSTEM	\$70,195.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$70,195.00)	
				- Total				\$0.00	
			Material - Tota Overrun	Overrun	7	Jul 1,	leez1	\$0.00 (\$10,100.00)	Offset system generated adjustment since Change Order has not been
					7	Jul 1, 2021	SYSTEM	\$10,100.00	approved. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 1390.000;
					7	Jul 1,	SYSTEM	(\$10,100.00)	Overrun Quantity Balance 200.00.
					8	2021 Jul 15,	leez1	\$10,100.00	Change Order number 0002 has been approved. Payment for overrun
				Overrun - T	otal	2021		\$0.00	adjustment on estimate 0007.
			Overrun - Tota	al				\$0.00	
	0530 -	Total						\$0.00	
	0540	FULL DEPTH REPAIR	Material		5	Jun 2, 2021	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brooks3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Jun 2, 2021	SYSTEM	(\$280.00)	
					6	Jun 16, 2021	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Jun 16, 2021	SYSTEM	(\$280.00)	
					7	Jul 1, 2021	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$420.00)	
					8	Jul 15, 2021	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Jul 15, 2021	SYSTEM	(\$420.00)	
					9	Aug 2, 2021	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$420.00)	
					10	Aug 23, 2021	SYSTEM	(\$420.00)	Addded to address the 'ghost' adjustment on Estimate 0010



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
15	0540	FULL DEPTH REPAIR	Material		10	Aug 17, 2021	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user bollis1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					10	Aug 17, 2021	SYSTEM	(\$420.00)										
				- Total				(\$420.00)										
			Material - Tota	ı				(\$420.00)										
			MaterialCredit		11	Sep 2, 2021	SYSTEM	\$420.00										
				- Total				\$420.00										
			MaterialCredit					\$420.00										
	0540 -	Total						\$0.00										
	0550	REINFORCING STEEL (EPOXY COATED)	Material		2	Apr 16, 2021	SYSTEM	\$843.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate.									
					2	Apr 16, 2021	SYSTEM	(\$843.75)										
					3	May 3, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate.									
					3	May 3, 2021	SYSTEM	(\$1,687.50)										
					4	May 17, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 37 on the current Payment Estimate.									
					4	May 17, 2021	SYSTEM	(\$1,687.50)										
				- Total				\$0.00										
			Material - Tota					\$0.00										
	0550 -	Total						\$0.00										
	0600	EMULSIFIED ASPHALT, SEAL COAT	Material		9	Aug 2, 2021	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.									
								9	Aug 2, 2021	SYSTEM	(\$1,705.00)							
																	10	Aug 23, 2021
					10	Aug 17, 2021	SYSTEM	\$1,705.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user bollis1 overridding Payment Estimate Exception 5 on the current Payment Estimate.									
					10	Aug 17, 2021	SYSTEM	(\$1,705.00)										
				- Total				(\$1,705.00)										
			Material - Tota					(\$1,705.00)										
			MaterialCredit		11	Sep 2, 2021	SYSTEM	\$1,705.00										
				- Total		· - ·		\$1,705.00										
			MaterialCredit					\$1,705.00										
	0600 -	Total						\$0.00										
	0610	SEAL COAT AGGREGATE, GRADE B1	Material		9	Aug 2, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Paymen Estimate Exception 6 on the current Payment Estimate.									
					9	Aug 2, 2021	SYSTEM	(\$4,255.00)										
					10	Aug 23, 2021	SYSTEM	(\$4,255.00)	Addded to address the 'ghost' adjustment on Estimate 0010									
					10	Aug 17, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user bollis1 overridding Payment Estimate Exception 7 on the current Payment Estimate.									
					10	Aug 17, 2021	SYSTEM	(\$4,255.00)										
					11	Sep 2, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.									



	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
15 (0610	SEAL COAT	Material	Туре	11	Sep 2,	SYSTEM	(\$4,255.00)	
3 (0010	AGGREGATE,	iviateriai		11	2021	STSTEW	(\$4,255.00)	
		GRADE B1			12	Sep 15, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Paymen Estimate Exception 3 on the current Payment Estimate.
					12	Sep 15, 2021	SYSTEM	(\$4,255.00)	
					13	Oct 1, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Paymen Estimate Exception 4 on the current Payment Estimate.
					13	Oct 1, 2021	SYSTEM	(\$4,255.00)	
					14	Oct 19, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brooks3 overridding Paymen Estimate Exception 4 on the current Payment Estimate.
					14	Oct 19, 2021	SYSTEM	(\$4,255.00)	
					15	Nov 2, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brooks3 overridding Paymer Estimate Exception 4 on the current Payment Estimate.
					15	Nov 2, 2021	SYSTEM	(\$4,255.00)	
					16	Nov 16, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brooks3 overridding Paymer Estimate Exception 4 on the current Payment Estimate.
					16	Nov 16, 2021	SYSTEM	(\$4,255.00)	
				17	17	Dec 2, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					17	Dec 2, 2021	SYSTEM	(\$4,255.00)	
					18	Jan 18, 2022	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Paymer Estimate Exception 4 on the current Payment Estimate.
					18	Jan 18, 2022	SYSTEM	(\$4,255.00)	
			Material - Tota	- Total				(\$4,255.00) (\$4,255.00)	
			MaterialCredit		11	Sep 2, 2021	SYSTEM	\$4,255.00	
				- Total					
				- Total				\$4,255.00	
			MaterialCredit					\$4,255.00 \$4,255.00	
0	0610 -	Total	MaterialCredit						
	0 610 - 0 62 0	Total CLASS B-2 CONCRETE			4	May 17, 2021	SYSTEM	\$4,255.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user connen1 overridding Payme Estimate Exception 15 on the current Payment Estimate.
		CLASS B-2			4	2021	SYSTEM SYSTEM	\$4,255.00 \$0.00	Estimate Item Adjustment (0010) due to user connen1 overridding Payme
		CLASS B-2			4 5	2021 May 17,		\$4,255.00 \$0.00 \$16,548.00	Estimate Item Adjustment (0010) due to user connen1 overridding Payme Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
		CLASS B-2				2021 May 17, 2021 Jun 2,	SYSTEM	\$4,255.00 \$0.00 \$16,548.00 (\$16,548.00)	Estimate Item Adjustment (0010) due to user connen1 overridding Payme Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment
		CLASS B-2			5	2021 May 17, 2021 Jun 2, 2021	SYSTEM SYSTEM	\$4,255.00 \$0.00 \$16,548.00 (\$16,548.00) \$16,548.00	Estimate Item Adjustment (0010) due to user connen1 overridding Payme Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment
		CLASS B-2		- Total	5	2021 May 17, 2021 Jun 2, 2021	SYSTEM SYSTEM	\$4,255.00 \$0.00 \$16,548.00 (\$16,548.00) \$16,548.00	Estimate Item Adjustment (0010) due to user connen1 overridding Payme Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment
(CLASS B-2 CONCRETE	Material	- Total	5	2021 May 17, 2021 Jun 2, 2021	SYSTEM SYSTEM	\$4,255.00 \$0.00 \$16,548.00 (\$16,548.00) \$16,548.00 (\$16,548.00) \$0.00	Estimate Item Adjustment (0010) due to user connen1 overridding Payme Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment
(0620	CLASS B-2 CONCRETE	Material	- Total	5	2021 May 17, 2021 Jun 2, 2021	SYSTEM SYSTEM SYSTEM	\$4,255.00 \$0.00 \$16,548.00 (\$16,548.00) \$16,548.00 (\$16,548.00) \$0.00	Estimate Item Adjustment (0010) due to user connen1 overridding Payme Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
(0620 -	CLASS B-2 CONCRETE	Material Material - Tota	- Total	5	2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021	SYSTEM SYSTEM SYSTEM	\$4,255.00 \$0.00 \$16,548.00 (\$16,548.00) \$16,548.00 (\$16,548.00) \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user connen1 overridding Payme Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user connen1 overridding Payment Estimate Item Adjustment (0011) due to user connen1 overridding Payment
(0620 -	CLASS B-2 CONCRETE	Material Material - Tota	- Total	5	2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 May 17, 2021 May 17, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$4,255.00 \$0.00 \$16,548.00 (\$16,548.00) \$16,548.00 (\$16,548.00) \$0.00 \$0.00 \$0.00 \$30,600.00	Estimate Item Adjustment (0010) due to user connen1 overridding Payme Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user connen1 overridding Payment Estimate Item Adjustment (0011) due to user connen1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
913545	0630	CURB BLOCKOUT	Material			2021			
					6	Jun 16, 2021	SYSTEM	\$61,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Jun 16, 2021	SYSTEM	(\$61,200.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0630 -	Total						\$0.00	
	0640	HALF-SOLE REPAIR	Material		2	Apr 16, 2021	SYSTEM	\$26,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user connen1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Apr 16, 2021	SYSTEM	(\$26,000.00)	
					3	May 3, 2021	SYSTEM	\$26,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	May 3, 2021	SYSTEM	(\$26,000.00)	
					6	Jun 16, 2021	SYSTEM	\$86,632.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jun 16, 2021	SYSTEM	(\$86,632.00)	
					7	Jul 1, 2021	SYSTEM	\$86,632.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$86,632.00)	
					8	Jul 15, 2021	SYSTEM	\$86,632.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Jul 15, 2021	SYSTEM	(\$86,632.00)	
					9	Aug 2, 2021	SYSTEM	\$86,632.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$86,632.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
			Overrun	Overrun	7	Jul 1, 2021	leez1	(\$2,496.00)	Offset system generated adjustment since Change Order has not been approved.
					7	Jul 1, 2021	SYSTEM	\$2,496.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 13 on the current Payment Estimate. Material Insufficiency Quantity 1666.000; Overrun Quantity Balance 48.00.
					7	Jul 1, 2021	SYSTEM	(\$2,496.00)	
					8	Jul 15, 2021	leez1	\$2,496.00	Change Order number 0002 has been approved. Payment for overrun adjustment on estimate 0007.
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0640 -	Total						\$0.00	
	0650	FULL DEPTH REPAIR	Material		4	May 17, 2021	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user connen1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$231.00)	
					5	Jun 2, 2021	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brooks3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	Jun 2, 2021	SYSTEM	(\$231.00)	
					6	Jun 16, 2021	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
45	0650	FULL DEPTH REPAIR	Material						Estimate Exception 8 on the current Payment Estimate.
		KEFAIK			6	Jun 16, 2021	SYSTEM	(\$231.00)	
					7	Jul 1, 2021	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$231.00)	
					8	Jul 15, 2021	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Jul 15, 2021	SYSTEM	(\$231.00)	
					9	Aug 2, 2021	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$231.00)	
					10	Aug 23, 2021	SYSTEM	(\$231.00)	Addded to address the 'ghost' adjustment on Estimate 0010
					10	Aug 17, 2021	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user bollis1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Aug 17, 2021	SYSTEM	(\$231.00)	
				- Total				(\$231.00)	
			Material - Tota	ıl				(\$231.00)	
			MaterialCredit		11	Sep 2, 2021	SYSTEM	\$231.00	
				- Total				\$231.00	
			MaterialCredit	- Total				\$231.00	
		650 - Total						\$0.00	
	0660	REINFORCING STEEL (EPOXY COATED)	Material		3	May 3, 2021	SYSTEM	\$843.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	May 3, 2021	SYSTEM	(\$843.75)	
					4	May 17, 2021	SYSTEM	\$843.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user connen1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$843.75)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0660 -	Total						\$0.00	
	5001	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		4	May 17, 2021	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$8,400.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	5001 -						0)/0==::	\$0.00	
	5002	TEMPORARY REMOVABLE MARKING TAPE	Material		4	May 17, 2021		\$5,878.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user connen1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$5,878.75)	
				- Total				\$0.00	
			Material - Tota		-		0)/0==::	\$0.00	
			Overrun	Overrun	7	Jul 1, 2021	SYSTEM	(\$6,643.75)	
					8	Jul 15,	SYSTEM	\$6,643.75	Unit price based on averaged overrun adjustments for installed quantity on al



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3545	5002	TEMPORARY REMOVABLE	Overrun	Overrun		2021			previous payment estimates. Price Adjustments of ',1.25000 - 1.25000, 'is applied (if non-zero).
		MARKING TAPE		Overrun - T	otal			\$0.00	
			Overrun - Tot	al				\$0.00	
	5002 -	Total						\$0.00	
	5003	FLOWABLE BACKFILL	Material		11	Sep 2, 2021	SYSTEM	\$1,118.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brooks3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$1,118.40)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	5003 -	Total						\$0.00	
	5004	SUBSTRUCTURE REPAIR (FORMED)	Material		11	Sep 2, 2021	SYSTEM	\$12,903.93	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brooks3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$12,903.93)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	5004 -	Total						\$0.00	
	5006	SUBSTRUCTURE REPAIR (FORMED)	Material		11	Sep 2, 2021	SYSTEM	\$8,280.63	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$8,280.63)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	5006 -	Total						\$0.00	
	5009	FLOWABLE BACKFILL	Material		12	Sep 15, 2021	SYSTEM	\$1,174.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brooks3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Sep 15, 2021	SYSTEM	(\$1,174.32)	
					13	Oct 1, 2021	SYSTEM	\$1,174.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	Oct 1, 2021	SYSTEM	(\$1,174.32)	
					14	Oct 19, 2021	SYSTEM	\$1,174.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					14	Oct 19, 2021	SYSTEM	(\$1,174.32)	
					15	Nov 2, 2021	SYSTEM	\$1,174.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brooks3 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					15	Nov 2, 2021	SYSTEM	(\$1,174.32)	
					16	Nov 16, 2021	SYSTEM	\$1,174.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					16	Nov 16, 2021	SYSTEM	(\$1,174.32)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	5009 -	Total						\$0.00	
	5010	SUBSTRUCTURE REPAIR (FORMED)	Material		12	Sep 15, 2021	SYSTEM	\$13,549.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		, ,			12	Sep 15, 2021	SYSTEM	(\$13,549.13)	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
545 5	5010	SUBSTRUCTURE REPAIR	Material			2021			Estimate Item Adjustment (0005) due to user woodsk1 overridding Paymer Estimate Exception 6 on the current Payment Estimate.
		(FORMED)			13	Oct 1, 2021	SYSTEM	(\$13,549.13)	
					14	Oct 19, 2021	SYSTEM	\$13,549.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Paymen Estimate Exception 6 on the current Payment Estimate.
					14	Oct 19, 2021	SYSTEM	(\$13,549.13)	
					15	Nov 2, 2021	SYSTEM	\$13,549.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brooks3 overridding Paymer Estimate Exception 12 on the current Payment Estimate.
					15	Nov 2, 2021	SYSTEM	(\$13,549.13)	
					16	Nov 16, 2021	SYSTEM	\$13,549.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Paymer Estimate Exception 6 on the current Payment Estimate.
					16	Nov 16, 2021	SYSTEM	(\$13,549.13)	
					17	Dec 2, 2021	SYSTEM	\$13,549.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brooks3 overridding Paymer Estimate Exception 8 on the current Payment Estimate.
					17	Dec 2, 2021	SYSTEM	(\$13,549.13)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	5010 -	Total						\$0.00	
	5012	SUBSTRUCTURE REPAIR (FORMED)	Material		12	Sep 15, 2021	SYSTEM	\$8,694.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Paymer Estimate Exception 6 on the current Payment Estimate.
					12	Sep 15, 2021	SYSTEM	(\$8,694.66)	
					13	Oct 1, 2021	SYSTEM	\$8,694.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payme Estimate Exception 7 on the current Payment Estimate.
					13	Oct 1, 2021	SYSTEM	(\$8,694.66)	
					14	Oct 19, 2021	SYSTEM	\$8,694.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brooks3 overridding Paymer Estimate Exception 7 on the current Payment Estimate.
					14	Oct 19, 2021	SYSTEM	(\$8,694.66)	
					15	Nov 2, 2021	SYSTEM	\$8,694.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brooks3 overridding Paymer Estimate Exception 13 on the current Payment Estimate.
					15	Nov 2, 2021	SYSTEM	(\$8,694.66)	
					16	Nov 16, 2021	SYSTEM	\$8,694.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brooks3 overridding Paymer Estimate Exception 7 on the current Payment Estimate.
					16	Nov 16, 2021	SYSTEM	(\$8,694.66)	
				17	17	Dec 2, 2021	SYSTEM	\$8,694.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brooks3 overridding Paymer Estimate Exception 9 on the current Payment Estimate.
					17	Dec 2, 2021	SYSTEM	(\$8,694.66)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	5012 -	Total						\$0.00	
	5017	TYPE III MOVEABLE BARRICADE	Material		17	Dec 2, 2021	SYSTEM	\$393.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brooks3 overridding Paymer Estimate Exception 6 on the current Payment Estimate.
					17	Dec 2, 2021	SYSTEM	(\$393.75)	
				- Total				\$0.00	

Jan 20, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3545	45 5017 TYPE III Material - Total MOVEABLE BARRICADE								
	5017 -	Total						\$0.00	
J9I3545 -	- Total						\$385,356.47		
Overall -	Total						\$385,356.47		