

Pay Estimate Created Date: July 15, 2021

Progress Estimate 8	Number	Contract ID Prime Contract	201016-H01 tor Apex Paving		Period Start Period End	July 1, 2021 July 15, 202	1 Net	inal Contract Amount Change Order Amount rent Contract Amount	\$6,773,481.30 \$312,702.06 \$7,086,183.36	
Approval Date									By User	
July 15, 2021			Generated and Ap	pproved (ar	nd should be a	considered Dra	aft) at th	e Project Office Level by	leez1	
July 15, 2021		sident Engineer Level by	holtb1							
July 19, 2021	Reviewed and Approved at the Central Office Controllers Office Lev									
Original Completion	n Date	Current Com	pletion Date	Actua	I Completion	Date	% o	f Current Contract Amou	nt Complete	
November 1, 202	21	Novembe	r 1, 2021					20.86%		
	Contract	Informational Dat	tes		N	lilestones				
Date Description	Original	Completion Date	Current Comple	tion Date	No Mileston	es Exist for Co	ontract			
Acceptance Date										
Awarded Date	Novembe	er 5, 2020	November 5, 202	20						
Letting Date	October ?									
Notice to Proceed Date	March 15	i, 2021	March 15, 2021							
Work Began Date	March 22	., 2021	March 22, 2021							

Contract Total Pay For Estimate No. 8

0	yable This Estimate:	\$82.273.44	φ1,000,001.02	ψ1,410,211.00	
			\$1,395,937.92	\$1,478,211.36	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Gross Item Adjustments	\$47,144.69	(\$47,144.69)	\$0.00	
	Total Posted Items Pay	\$35,128.75	\$1,443,082.61	\$1,478,211.36	
201016-H01					
		This Estimate	Previous	To Date	

Contract Total Payable This Estimate:

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3545	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$58,420.050	0.07	\$4,089.40
	0100	6122030	IMPACT ATTENUATOR (RELOCATION)	EA	\$687.000	1	\$687.00
	0260	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	LF	\$258.030	20	\$5,160.60
	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	LF	\$31.890	75	\$2,391.75
	0430	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$2,450.000	7	\$17,150.00
	0440	6061080	MGS END ANCHOR	EA	\$950.000	1	\$950.00
	0450	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$2,350.000	2	\$4,700.00
Project J9I3	545 - Total						\$35,128.75
Overall - To	tal						\$35,128.75

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

	Aujusi							
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3545	0100	IMPACT ATTENUATOR (RELOCATION)	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',687.00000 - 687.00000, 'is applied (if non-zero).	3	\$687.00	\$2,061.00
	0260	CONCRETE TRAFFIC	Material			-270	\$258.03	(\$69,668.10)



Pay Estimate Created Date: July 15, 2021

Prog	jress E		ntract I me Cor)1016-H01 bex Paving Co	. Pay Period End July 15, 2021 Net	jinal Contract Am Change Order Ar rent Contract Am	nount \$31	773,481.30 2,702.06 086,183.36
ject nber	Line No.	Item Description		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustmen amount
3545		BARRIER, TY	PE B						
	0260	CONCRETE TRA BARRIER, TY		Material		This adjustment offsets the original sys generated Material Payment Estimate Adjustment (0011) due to user lo overridding Payment Estimate Exception the current Payment Estim	ltem eez1 1 on	\$258.03	\$69,668.10
	0270	TEMPORARY TRA BARRIER, CONTRAC FURNISHED / RETA	TOR	Overrun		Unit price based on averaged over adjustments for installed quantity of previous payment estimates. F Adjustments of ',31.89000 - 31.8900 applied (if non-z	n all Price 0, 'is	\$31.89	\$14,350.50
	0280	RELOCATING TEMPOF TRAFFIC BAR		Overrun		Unit price based on averaged over adjustments for installed quantity of previous payment estimates. F Adjustments of ',11.32000 - 11.3200 applied (if non-z	n all Price 0, 'is	\$11.32	\$10,437.04
	0360	PAVEMENT MAR REMO		Overrun		Unit price based on averaged over adjustments for installed quantity of previous payment estimates. F Adjustments of ',0.70000 - 0.70000, 'is ap (if non-z	n all Price blied	\$0.70	\$106.40
	0440	MGS END ANC	HOR	Overrun		Unit price based on averaged over adjustments for installed quantity of previous payment estimates. F Adjustments of ',950.00000 - 950.0000 applied (if non-z	n all Price 0, 'is	\$950.00	\$950.00
	0530	HALF-SOLE RE	PAIR	Material			-1,390	\$50.50	(\$70,195.00
	0530	HALF-SOLE RE	PAIR	Material		This adjustment offsets the original sys generated Material Payment Estimate Adjustment (0007) due to user le overridding Payment Estimate Exception the current Payment Estin	Item eez1 2 on	\$50.50	\$70,195.00
	0530	HALF-SOLE RE	PAIR	Overrun	Overrun	Change Order number 0002 has approved. Payment for overrun adjustmer estimate 0	nt on		\$10,100.00
	0540	FULL DEPTH RE	PAIR	Material			-6	\$70.00	(\$420.00
	0540	FULL DEPTH RE	PAIR	Material		This adjustment offsets the original sys generated Material Payment Estimate Adjustment (0008) due to user le overridding Payment Estimate Exception the current Payment Estin	ltem eez1 4 on	\$70.00	\$420.00
	0640	HALF-SOLE RE	PAIR	Material			-1,666	\$52.00	(\$86,632.00
	0640	HALF-SOLE RE	PAIR	Material		This adjustment offsets the original sys generated Material Payment Estimate Adjustment (0009) due to user le overridding Payment Estimate Exception the current Payment Estin	Item eez1 3 on	\$52.00	\$86,632.00
	0640	HALF-SOLE RE	PAIR	Overrun	Overrun	Change Order number 0002 has b approved. Payment for overrun adjustmer estimate 0	nt on		\$2,496.00
	0650	FULL DEPTH RE	PAIR	Material			-3.3	\$70.00	(\$231.00
	0650	FULL DEPTH RE	PAIR	Material		This adjustment offsets the original sys generated Material Payment Estimate Adjustment (0010) due to user le overridding Payment Estimate Exception the current Payment Estim	ltem eez1 6 on	\$70.00	\$231.00
	5002	TEMPORARY REMOVA		Overrun		Unit price based on averaged over adjustments for installed quantity or		\$1.25	\$6,643.75



Pay Estimate Created Date: July 15, 2021

Prog	jress E	stimate Number 8	Contract ID 201016-H01 Prime Contractor Apex Paving Co			Pay Period Start D. Pay Period End	July 1, 2021 July 15, 2021	Net Char	Contract Am nge Order An Contract Am	nount \$31	773,481.30 12,702.06 086,183.36
Project Number	Line No.	Item Descript	ion	Adjustment Type	Other Item Adjustment Type	Cor	nments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3545		YELLOW				previous Adjustments of ',1.25	,				
Total											\$47,144.69



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9I3545	l 55-1(173)	Resurface	I-55	SCOTT	from I-57 to Rte. 77		
Totals by	Job Numbe	rs					
J9I3545					This Estimate	Previous	To Date
	Poste	d Item Pay			\$35,128.75	\$1,443,082.61	\$1,478,211.36
	Gross	Item Adjustm	ents		\$47,144.69	(\$47,144.69)	\$0.00
			Gross	Item Pay	\$82,273.44	\$1,395,937.92	\$1,478,211.36
	Incent	ive			\$0.00	\$0.00	\$0.00
	Dising	entive			\$0.00	\$0.00	\$0.00
			•		\$0.00	\$0.00	\$0.00
	Liquic	lated Damages	5		ψ0.00		



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9I3545, Item 6172000, Project Item Line Number 0260, Material Set 617200096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3545, Item 7040104, Project Item Line Number 0530, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3545, Item 7040104, Project Item Line Number 0640, Material Set 704010496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3545, Item 7040106, Project Item Line Number 0540, Material Set 704010696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3545, Item 7040106, Project Item Line Number 0540, Material Set 704010696, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	No Remark was entered by Engineer	leez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3545, Item 7040106, Project Item Line Number 0650, Material Set 704010696, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	No Remark was entered by Engineer	leez1	Overridden

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	les are l	based on F	Report Generated date and can differ from the posted am	ount at the	time the E	stimate was	Genera	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201016-H01	J9I3545	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$58,420.05	\$58,420.05
		0001	0020	2159903	MISC.MODIFIED SHAPING SLOPES CLASS III	3,750.00	0.00	3,750.00	LF	3,300.00	\$7.50	\$24,750.00
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	3,710.80	0.00	3,710.80	TONS	0.00	\$26.90	\$0.00
		0001	0040	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	14,032.60	0.00	14,032.60	TONS	0.00	\$50.02	\$0.00
		0001	0050	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	54,886.40	0.00	54,886.40	TONS	0.00	\$73.46	\$0.00
		0001	0060	4071005	TACK COAT	54,787.00	0.00	54,787.00	GAL	0.00	\$1.90	\$0.00
		0001	0070	4134000	BITUMINOUS FOG SEAL	13,348.00	0.00	13,348.00	GAL	0.00	\$2.56	\$0.00
		0001	0080	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	2.00	2.00	4.00	EA	4.00	\$4,250.00	\$17,000.00
		0001	0090	6122020	REPLACEMENT SAND BARREL	8.00	0.00	8.00	EA	0.00	\$300.00	\$0.00
		0001	0100	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	9.00	11.00	EA	11.00	\$687.00	\$7,557.00
		0001	0110	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$250.00	\$0.00
		0001	0120	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	48.00	28.00	76.00	SQYD	76.00	\$462.62	\$35,159.12
		0001	0130	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	5.00	-5.00	0.00	SQYD	0.00	\$30.00	\$0.00
		0001	0140	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	5.00	-5.00	0.00	SQYD	0.00	\$98.00	\$0.00
		0001	0150	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	204.00	132.00	336.00	LF	336.00	\$6.00	\$2,016.00
		0001	0160	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	120.00	50.00	170.00	EA	170.00	\$18.50	\$3,145.00
		0001	0170	6161005	CONSTRUCTION SIGNS	5,187.00	0.00	5,187.00	SQFT	1,274.00	\$7.00	\$8,918.00
		0001	0180	6161008	ADVANCED WARNING RAIL SYSTEM	42.00	-12.00	30.00	EA	14.00	\$45.00	\$630.00
		0001	0190	6161009	FLAG ASSEMBLY	16.00	0.00	16.00	EA	0.00	\$20.00	\$0.00
		0001	0200	6161025	CHANNELIZER (TRIM LINE)	794.00	0.00	794.00	EA	303.00	\$16.00	\$4,848.00
		0001	0210	6161033	DIRECTIONAL INDICATOR BARRICADE	204.00	0.00	204.00	EA	130.00	\$50.00	\$6,500.00
		0001	0220	6161040	FLASHING ARROW PANEL	11.00	0.00	11.00	EA	8.00	\$725.00	\$5,800.00
		0001	0230	6161055	SEQUENTIAL FLASHING WARNING LIGHT	46.00	0.00	46.00	EA	36.00	\$80.00	\$2,880.00
		0001	0240	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0250	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	0.00	\$2,000.00	\$0.00
		0001	0260	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	270.00	0.00	270.00	LF	270.00	\$258.03	\$69,668.10
		0001	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,222.00	675.00	1,897.00	LF	1,897.00	\$31.89	\$60,495.33
		0001	0280	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,222.00	1,222.00	2,444.00	LF	2,444.00	\$11.32	\$27,666.08
		0001	0290	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$48,386.40	\$24,193.20
		0001	0300	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	24.00	0.00	24.00	LF	0.00	\$18.00	\$0.00
		0001	0310	6200039	PREFORMED THERMOPLASTIC PAVEMENT MARKING, OFF RAMP WRONG WAY ARROW	3.00	0.00	3.00	EA	0.00	\$1,800.00	\$0.00
		0001	0320	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	8,876.00	0.00	8,876.00	LF	5,078.00	\$1.25	\$6,347.50
		0001	0330	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	201,642.00	0.00	201,642.00	LF	0.00	\$0.20	\$0.00
		0001	0340	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	161,010.00	0.00	161,010.00	LF	0.00	\$0.20	\$0.00
		0001	0350	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,228.00	0.00	3,228.00	LF	0.00	\$0.75	\$0.00
		0001	0360	6207001	PAVEMENT MARKING REMOVAL	8,876.00	152.00	9,028.00	LF	9,028.00	\$0.70	\$6,319.60
		0001	0370	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0001	0380	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	529,219.00	0.00	529,219.00	SQYD	0.00	\$0.60	\$0.00
		0001	0390	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	19,092.00	0.00	19,092.00	SQYD	0.00	\$2.59	\$0.00
		0001	0400	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	3,078.00	0.00	3,078.00	STA	0.00	\$21.22	\$0.00
		0001	0410	7123000	STEEL BAR DAM	2.00	-2.00	0.00	EA	0.00	\$6,700.00	\$0.00
		0010	0420	6061060	MGS GUARDRAIL	13,550.00	213.00	13,763.00	LF	13,763.00	\$18.00	\$247,734.00
		0010	0430	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	31.00	0.00	31.00	EA	31.00	\$2,450.00	\$75,950.00
					(REGULAR/NO CURB)							

Total Paid / All Items / All Estimates (Including this Estimate)

m the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted an Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201016-H01	J9I3545	0010	0440	6061080	MGS END ANCHOR	24.00	0.00	24.00	EA	24.00	\$950.00	\$22,800.00
		0010	0450	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	29.00	0.00	29.00	EA	29.00	\$2,350.00	\$68,150.00
		0070	0460	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7,612.00	0.00	7,612.00	SQFT	7,612.00	\$1.36	\$10,352.32
		0070	0470	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	71.00	0.00	71.00	LF	71.00	\$310.00	\$22,010.00
		0070	0480	2169903	MISC.Remove and Replace Curb	8.00	0.00	8.00	LF	8.00	\$650.00	\$5,200.00
		0070	0490	4091048	EMULSIFIED ASPHALT, SEAL COAT	341.00	0.00	341.00	GAL	0.00	\$5.00	\$0.00
		0070	0500	4094011	SEAL COAT AGGREGATE, GRADE B1	851.00	0.00	851.00	SQYD	0.00	\$5.00	\$0.00
		0070	0510	7034214	CLASS B-2 CONCRETE	8.30	0.00	8.30	CUYD	8.30	\$3,940.00	\$32,702.00
		0070	0520	7034600	CURB BLOCKOUT	510.00	0.00	510.00	LF	510.00	\$120.00	\$61,200.00
		0070	0530	7040104	HALF-SOLE REPAIR	700.00	2,280.00	2,980.00	SQFT	2,980.00	\$50.50	\$150,490.00
		0070	0540	7040106	FULL DEPTH REPAIR	200.00	-194.00	6.00	SQFT	6.00	\$70.00	\$420.00
		0070	0550	7101000	REINFORCING STEEL (EPOXY COATED)	540.00	0.00	540.00	LB	540.00	\$6.25	\$3,375.00
		0070	0560	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	71.00	0.00	71.00	LF	71.00	\$475.00	\$33,725.00
		0071	0570	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7,612.00	0.00	7,612.00	SQFT	7,612.00	\$1.36	\$10,352.32
		0071	0580	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	71.00	0.00	71.00	LF	71.00	\$310.00	\$22,010.00
		0071	0590	2169903	MISC.Rermove and Replace Curb	8.00	0.00	8.00	LF	8.00	\$650.00	\$5,200.00
		0071	0600	4091048	EMULSIFIED ASPHALT, SEAL COAT	341.00	0.00	341.00	GAL	0.00	\$5.00	\$0.00
		0071	0610	4094011	SEAL COAT AGGREGATE, GRADE B1	851.00	0.00	851.00	SQYD	0.00	\$5.00	\$0.00
		0071	0620	7034214	CLASS B-2 CONCRETE	8.30	0.00	8.30	CUYD	8.30	\$3,940.00	\$32,702.00
		0071	0630	7034600	CURB BLOCKOUT	510.00	0.00	510.00	LF	510.00	\$120.00	\$61,200.00
		0071	0640	7040104	HALF-SOLE REPAIR	500.00	2,883.00	3,383.00	SQFT	3,383.00	\$52.00	\$175,916.00
		0071	0650	7040106	FULL DEPTH REPAIR	200.00	-196.70	3.30	SQFT	3.30	\$70.00	\$231.00
		0071	0660	7101000	REINFORCING STEEL (EPOXY COATED)	540.00	0.00	540.00	LB	405.00	\$6.25	\$2,531.25
		0071	0670	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	71.00	0.00	71.00	LF	71.00	\$475.00	\$33,725.00
		0001	5001	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	0.00	4.00	4.00	EA	4.00	\$2,100.00	\$8,400.00
		0001	5002	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	0.00	10,018.00	10,018.00	LF	10,018.00	\$1.25	\$12,522.50
					Date as of Report Generated Date							\$1,478,211.37
201016-H01 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Rep	oort Generated Date							\$1,478,211.37



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log	Offset/ Distance	To Station/ Log	Offset/ Distance	Comments
				Duto				Mile		Mile		
0010	2022010	REMOVAL OF IMPROVEMENTS	7/6/21	7/12/21	0.07	LS	30/30 Locations removed Box Culvert SB 135.266 Box Culvert NB 74.566	74.566		135.266		
0100	6122030	IMPACT ATTENUATOR (RELOCATION)	7/12/21	7/15/21	1.00	EA	Box Culvert Type B Barrier Install	74.566	RT			
0260	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	7/8/21	7/12/21	20.00	LF	I-55 NB LM 74.566 Plan Qty = 50 FT Pay 20 FT Other 30 FT to be added to Change Order	74.566		74.566		
0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	7/12/21	7/15/21	75.00	LF	Type B Barrier Install	74.566	RT			
0430	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	7/12/21	7/15/21	1.00	EA	Bridge A0938	142.329	LT			
				7/15/21	2.00	EA	Bridge A09131 Driving Lane	75.416	RT			
				7/15/21	2.00	EA	Bridge A0938	142.329	RT			
				7/15/21	2.00	EA	Type B Barrier at Box Culvert	74.566	RT			
0440	6061080	MGS END ANCHOR	7/12/21	7/15/21	1.00	EA	Type B Barrier at Box Culvert	74.566	RT			
0450	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	7/12/21	7/15/21	1.00	EA	Box Culvert	138.880	RT			
				7/15/21	1.00	EA	Type B Barrier at Box Culvert	74.566	RT			

The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Pos
13545	0170	March 31, 2021	529	G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		76.781	NB I-55, LT. and RT.	2.00	6			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	981+97		NB I-55, LT. and RT	2.00	16			
				CONST-3A 60x48 20.00 FINE SIGN		76.592	NB I-55, LT. and RT.	2.00	20			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		76.403	NB I-55, LT. and RT.	2.00	16			
				R4-1 36x48 12.00 DO NOT PASS		76.781	NB I-55, LT. and RT.	2.00	12			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		76.971	NB I-55, LT. and RT.	2.00	16			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		77.255	NB I-55, LT.	1.00	16			
				WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)		77.255	NB I-55, RT.	1.00	16			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		77.255	NB I-55, LT. and RT.	2.00	6			
				R2-1 36x48 12.00 SPEED LIMIT XX		77.255	NB I-55, LT. and RT.	2.00	12			
				WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)	916+61		SB I-55, RT.	1	16			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	916+61		SB I-55, LT.	1.00	16			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED	966+97		NB I-55, LT.	1.00	16			
				WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)	966+97		NB I-55, RT	1.00	16			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)	916+61		SB I-55, LT. and RT.	2.00	6			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)	966+97		NB I-55, LT. and RT.	2.00	6			
				R2-1 36x48 12.00 SPEED LIMIT XX	916+61		SB I-55, LT. and RT.	2.00	12			
				R2-1 36x48 12.00 SPEED LIMIT XX	928+78		NB I-55, LT. and RT.	2.00	12			
				R2-1 36x48 12.00 SPEED LIMIT XX	954+80		SB I-55, LT. and RT.	2.00	12			
				R2-1 36x48 12.00 SPEED LIMIT XX	966+97		NB I-55, LT. and RT.	2.00	12			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	1008+37		NB I-55, LT. and RT	2.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD	875+21		SB I-55, LT. and RT.	2.00	16			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD	901+61		SB I-55, LT. and RT.	2.00	16			
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		76.592	NB I-55, LT. and RT.	2.00	4.67			
		April 19, 2021	217	G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		71.54	NB I-55	2.00	6			
				CONST-3X 56x12 4.67 SPEEDING/PASSING (PLATE)		71.347	NB I-55	2.00	4.67			
				CONST-3A 60x48 20.00 FINE SIGN		71.34	NB I-55	2.00	20			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		71.16	NB I-55	2	16			
				R4-1 36x48 12.00 DO NOT PASS		71.54	NB I-55	2.00	12			
				R2-1 36x48 12.00 SPEED LIMIT XX		72.2	NB I-55	2.00	12			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		72.2	NB I-55	2.00	6			
				WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)		72.0	NB I-55	1.00	16			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		72.0	NB I-55	1.00	16			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		71.72	NB I-55	2.00	16			
		June 15, 2021	216	R4-1 36x48 12.00 DO NOT PASS		131.054	SB I-55 RT/LT	2.00	12			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		131.054	SB I-55 RT/LT	2.00	6			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		130.865	SB I-55 RT/LT	2.00	16			
				R2-1 36x48 12.00 SPEED LIMIT XX		132.490	SB I-55 RT/LT	2.00	12			



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail. location and quantity of work. The information below this line are details for Construction Signs (if applicable).

ct Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Po
45 0170	June 15, 2021	216	WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		131.244	SB I-55 RT/LT	2.00	16			
			R2-1 36x48 12.00 SPEED LIMIT XX		131.717	SB I-55 RT/LT	2.00	12			
			G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		131.717	SB I-55 RT/LT	2.00	6			
			WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)		131.528	SB I-55 RT	1.00	16			
			WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		131.528	SB I-55 LT	1.00	16			
			R4-2 36x48 12.00 PASS WITH CARE		132.301	SB I-55 RT/LT	2.00	12			
June 16,	June 16, 2021	156	WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)		142.750	RT & LT	1.00	16			
			WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		142.750	RT & LT	1.00	16			
			WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		142.465	RT & LT	2.00	16			
			G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		142.894	RT & LT	2.00	6			
			R2-1 36x48 12.00 SPEED LIMIT XX		142.894	RT & LT	2.00	12			
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		141.965	RT & LT	2.00	16			
			R2-1 36x48 12.00 SPEED LIMIT XX		139.107	RT & LT	2.00	12			
			R2-1 36x48 12.00 SPEED LIMIT XX		138.479	RT & LT	2.00	12			
			G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		138.479	RT & LT	2.00	6			
			WO4-1aL 48x48 16.00 MERGE (SYMBOL FROM LEFT)		138.335	RT & LT	1.00	16			
			WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		138.335	RT & LT	1.00	16			
			R2-1 36x48 12.00 SPEED LIMIT XX		143.522	RT & LT	2.00	12			
			WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		137.550	RT & LT	2.00	16			
			WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		138.050	RT & LT	2.00	16			



Jul 19, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3545	0100		Overrun	Overrun	7	Jul 1, 2021	SYSTEM	(\$2,061.00)	
		(RELOCATION)			8	Jul 15, 2021	SYSTEM	\$2,061.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',687.00000 - 687.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0100 -	Total						\$0.00	
	0120	FURN & PLACE CONC MATL FOR FULL	Material		3	May 3, 2021	SYSTEM	\$22,205.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		DEPTH			3	May 3, 2021	SYSTEM	(\$22,205.76)	
					4	May 17, 2021	SYSTEM	\$22,205.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user connen1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$22,205.76)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0120 -	Total						\$0.00	
	0260	CONCRETE TRAFFIC BARRIER, TYPE B	Material		4	May 17, 2021	SYSTEM	\$10,321.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$10,321.20)	
					5	Jun 2, 2021	SYSTEM	\$34,834.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 2, 2021	SYSTEM	(\$34,834.05)	
					6	Jun 16, 2021	SYSTEM	\$47,735.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2021	SYSTEM	(\$47,735.55)	
					7	Jul 1, 2021	SYSTEM	\$64,507.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$64,507.50)	
					8	Jul 15, 2021	SYSTEM	\$69,668.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user leez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jul 15, 2021	SYSTEM	(\$69,668.10)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0260 -	Total						\$0.00	
	0270	TEMPORARY TRAFFIC	Overrun	Overrun	7	Jul 1, 2021	SYSTEM	(\$14,350.50)	
		BARRIER, CONT. FURN/RE			8	Jul 15, 2021	SYSTEM	\$14,350.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',31.89000 - 31.89000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0270 -	Total						\$0.00	
	0280	RELOCATING TEMPORARY	Overrun	Overrun	7	Jul 1, 2021	SYSTEM	(\$10,437.04)	
		TRAFFIC BARRIER			8	Jul 15, 2021	SYSTEM	\$10,437.04	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',11.32000 - 11.32000, 'is applied (if non-zero).



Jul 19, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3545	0280	RELOCATING TEMPORARY	Overrun	Overrun - T	otal			\$0.00	
		TRAFFIC BARRIER	Overrun - To	tal				\$0.00	
	0280 -	Total						\$0.00	
	0320	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	Material		1	Apr 2, 2021	SYSTEM	\$5,878.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		4 IN.,			1	Apr 2, 2021	SYSTEM	(\$5,878.75)	
					2	Apr 16, 2021	SYSTEM	\$5,878.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Apr 16, 2021	SYSTEM	(\$5,878.75)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0320 -	Total						\$0.00	
	0360	PAVEMENT MARKING REMOVAL	Overrun	Overrun	7	Jul 1, 2021	SYSTEM	(\$106.40)	
					8	Jul 15, 2021	SYSTEM	\$106.40	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.70000 - 0.70000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0360 -	Total						\$0.00	
	0420	MGS GUARDRAIL	Construction Stockpile		2	Apr 16, 2021	SYSTEM	(\$15,550.17)	Payment Estimate Item Adjustment generated Stockpile Transaction
					4	May 17, 2021	SYSTEM	(\$74,443.58)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total	1			(\$89,993.75)	
			Construction Stockpile - Total					(\$89,993.75)	
			Construction Stockpile		2	Apr 16, 2021	SYSTEM	\$89,993.75	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$89,993.75	
			Construction Stockpile STMI - Total					\$89,993.75	
	0420 -	Total						\$0.00	
	0430	MGS BRIDGE APP. TRANS	Construction Stockpile		2	Apr 16, 2021	SYSTEM	(\$2,814.31)	Payment Estimate Item Adjustment generated Stockpile Transaction
		SEC (REG/NO CURB)			4	May 17, 2021	SYSTEM	(\$14,071.53)	Payment Estimate Item Adjustment generated Stockpile Transaction
					5	Jun 2, 2021	SYSTEM	(\$11,257.22)	Payment Estimate Item Adjustment generated Stockpile Transaction
					6	Jun 16, 2021	SYSTEM	(\$10,806.94)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total	1			(\$38,950.00)	
			Construction	Stockpile - 1	Fotal			(\$38,950.00)	
			Construction Stockpile		2	Apr 16, 2021	SYSTEM	\$38,950.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$38,950.00	
			Construction	Stockpile S	TMI - T <u>ota</u> l			\$38,950.00	
	0430 -	Total						\$0.00	
	0440		Construction Stockpile		4	May 17, 2021	SYSTEM	(\$9,418.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$9,418.00)	
			Construction	Stockpile - 1	Total			(\$9,418.00)	
			Construction Stockpile		2	Apr 16, 2021	SYSTEM	\$9,418.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total	1			\$9,418.00	



Jul 19, 2021

Instant Image: Second	Ducient	Line	Description	A	Others	E-t	One start	Oue etc.d	A	Demonto						
940 MSE EX Construction Stochall STML Total 9591EM 0400 0400 NSE EX Overan 7 221 973TEM 0400 000 Image: Construction Stochall Part Part Stand on paragraph overan existence information and parameter of the construction of the of the constructin of the constructin of the construction of the con	Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks						
AMCHOR Derrun 0 0 Marcel SYSTEM (000000000000000000000000000000000000																
Overnin Overnin Overnin P July 1 (2) SYSTEM (8950.00) Overnin	J9I3545	0440		Construction	n Stockpile ST	「MI - Total			\$9,418.00							
Image: second parameter elimination in the Adjustment of r-950 00000-950 000000, second 0000, secon			ANOHOIX	Overrun	Overrun	7		SYSTEM	(\$950.00)							
Overa <table-cell> Overa Solution <thsolution< th=""> Solution <ths< td=""><td></td><td></td><td></td><td></td><td></td><td>8</td><td></td><td>SYSTEM</td><td>\$950.00</td><td>previous payment estimates. Price Adjustments of ',950.00000 - 950.00000, 'is</td></ths<></thsolution<></table-cell>						8		SYSTEM	\$950.00	previous payment estimates. Price Adjustments of ',950.00000 - 950.00000, 'is						
Seta Total Construction Construction <t< td=""><td></td><td></td><td></td><td></td><td>Overrun - T</td><td>otal</td><td></td><td></td><td>\$0.00</td><td></td></t<>					Overrun - T	otal			\$0.00							
0450 ENAMPORTIN END TERMINAL OUX Construction END TERMINAL (MASH) Construction END TERMINAL (MASH) Construction For Call 2 Apr 15, 2021 SYSTEM (89,415:20) Payment Estimate Item Adjustment generated Stockple Transaction - Total - Total (23,044.00) Payment Estimate Item Adjustment generated Stockple Transaction - Total - Total (23,044.00) Payment Estimate Item Adjustment generated Stockple Transaction - Total - Total - S29,044.00 Payment Estimate Item Adjustment generated Stockple Transaction - Total - Construction Stockple STMI - Total 529,044.00 Payment Estimate Item Adjustment generated Stockple Transaction 0510 - Construction Stockple STMI - Total 529,044.00 Payment Estimate Item Adjustment generated Stockple Transaction 0510 - Construction Stockple STMI - Total 529,044.00 Private Statimate Item Adjustment of thest the original system generated Material Payment Estimate Endpoint of the state original system generated Material Payment Estimate Endpoint of the state original system generated Material Payment Estimate Endpoint of the state original system generated Material Payment Estimate Endpoint of the state original system generated Material Payment Estimate Endpoint of the state original system generated Material Payment Estimate Endpoint of the state original system generated Material Payment Estimate Endpoint of the state original syst				Overrun - To	tal				\$0.00							
CRASHWORTH, MASH Sockpile 2011 Construction Sockpile 2021 Construction (23,344.00) Payment Estimate Item Adjustment generated Stockpile Transaction Construction Stockpile -Total 2 Apr 16, STAI SYSTEM (20,148.77) Payment Estimate Item Adjustment generated Stockpile Transaction Construction Stockpile -Total 2 Apr 16, STAI SYSTEM \$20,564.00 Payment Estimate Item Adjustment generated Stockpile Transaction Construction Stockpile -Total -Total 520,564.00 Payment Estimate Item Adjustment generated Stockpile Transaction Construction Stockpile -Total -Total 520,564.00 Payment Estimate Item Adjustment officits the original system-generated Material Payment Estimate Exception 1: on ite narrow Payment Estimate 0510 -Total -Total 500.00 -Total 500.00 0510 -Total -To		0440 -	Total						\$0.00							
END TERMINAL (MASH) Ford 4 May '7. SYSTEM (62), 148-71 Payment Estimate Item Adjustment generated Stockpile Transaction - Total - Stab.00 Payment Estimate Item Adjustment generated Stockpile Transaction 0450 - Total - Total - Stab.00 Payment Estimate Item Adjustment generated Stockpile Transaction 0450 - Total - Stab.00 - Total - Stab.00 - Total - Stab.00 - Total - Total - Stab.00 - Total - Stab.00 - Total - Stab.00 - Total - Total - Stab.00 - Total - Stab.00 - Total - Stab.00 - Total - Total - Total - Stab.00 - Total - Stab.00 - Stab.00 - Stab.00 - Stab.		0450				2		SYSTEM	(\$9,415.29)	Payment Estimate Item Adjustment generated Stockpile Transaction						
Construction Construction Sockpile Test Gas Payment Estimate Item Adjustment generated Slockpile Transaction STM - rotal 520 Apr 16. SYSTEM 520 S44.00 Payment Estimate Item Adjustment generated Slockpile Transaction 6460 - Total 500 Construction Slockpile STM - Total 520 S46.00 Formula (1990) 500 Construction Slockpile STM - Total 520 S46.00 6460 - Total 500 Construction Slockpile STM - Total 500 Construction Slockpile Sloc						4		SYSTEM	(\$20,148.71)	Payment Estimate Item Adjustment generated Stockpile Transaction						
Construction Construction Sockpile Test Gas Payment Estimate Item Adjustment generated Slockpile Transaction STM - rotal 520 Apr 16. SYSTEM 520 S44.00 Payment Estimate Item Adjustment generated Slockpile Transaction 6460 - Total 500 Construction Slockpile STM - Total 520 S46.00 Formula (1990) 500 Construction Slockpile STM - Total 520 S46.00 6460 - Total 500 Construction Slockpile STM - Total 500 Construction Slockpile Sloc					- Total				(\$29.564.00)							
Construction STM Construction STM Construction Construction Stockplis Page 16. For Status System Status 0400 - Total Construction Stockplis Tests Status S				Construction		Total										
Shockpile Output 9221 Visite 923, 564.00 0450 - Total Construction Stockpile STM - Total 523, 564.00 Construction Stockpile STM - Total 523, 564.00 0510 CONRETE Material Visite 510, 510, 500, 500 File adjustment offsets the original system-apmented Material Payment Estimate Exception 11 on the current Payment Estimate. 0510 CONRETE Material Visite Stockpile Stockpile 0510 CONRETE Material Visite Stockpile Stockpile 0510 CONRETE Material Visite Stockpile Stockpile 0510 Total Visite Stockpile Stockpile Stockpile 0510 Total Visite Stockpile Stockpile Stockpile 0520 BLOCKOUT Material Visite Stockpile Stockpile Stockpile 0520 CURB Material Stockpile Stockpile Stockpile Stockpile Stockpile 0520 CURB Material Stockpile Stockp							A == 40	OVOTEM		Devenue of Estimate Ham Adjustment as a set of Ote shalls. Taken as then						
Original Stockpile STML + Total S23, 54.00 Second Stockpile STML + Total S23, 54.00 0450 - Total CONCREE II Matrial Nervital SYSTEM S16,548,00 This adjustment Offsets the original system-generated Matrial Payment Estimate 0510 - Total SYSTEM S16,548,00 This adjustment Offsets the original system-generated Matrial Payment Estimate 0510 - Total - Total SYSTEM S16,548,00 Internal - Total Status 0510 - Total - Total SYSTEM S16,548,00 Internal - Total Status 0520 CONCOUT Material - Total SYSTEM S10,000 This adjustment offsets the original system-generated Material Payment 0520 CONCOUT May 17. SYSTEM S30,600.00 This adjustment offsets the original system-generated Material Payment 0520 CONCOUT Subscription SUB 20,000 This adjustment offsets the original system-generated Material Payment 0520 Total SYSTEM S03,000.00 This adjustment offsets the original system-generated Material Payment 0520 Total SYSTEM S03,000.00 This adjustm				Stockpile		2		SYSTEM		Payment Estimate item Adjustment generated Stockpile Transaction						
Odds - Total Status Status Status 0510 CLASS B.2 CONCRETE Material - Total 4 May 17, 2021 SYSTEM S16,548.00 This adjustment officits the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate 0510 - Total - Total 50.00 - 0520 CUBB BLOCKOUT Material - Total 50.00 - 0520 CUBB BLOCKOUT Material - Total 50.00 - 0520 CUBB BLOCKOUT Material - Total 50.00 - This adjustment officits the original system-generated Material Payment Estimate Item Adjustment (0003) due to user corrent orwerinding Payment Estimate Item Adjustment (0003) due to user corrent orwerinding Payment Estimate Item Adjustment (0003) due to user incols orwerinding Payment Estimate Item Adjustment (0003) due to user incols orwerinding Payment Estimate Item Adjustment (0003) due to user incols orwerinding Payment Estimate Item Adjustment (0003) due to user incols orwerinding Payment Estimate Item Adjustment (0003) due to user incols orwerinding Payment Estimate Item Adjustment (0003) due to user incols orwerinding Payment Estimate Item Adjustment (0003) due to user incols orwerinding Payment Estimate Item Adjustment (0003) due to user incols orwerinding Payment Estimate Item Adjustment (0003) due to user incols orwerinding Payment Estimate Item Adjustment (0003) due to user incols orwerinding Payment Estimate Item Adjustment (0003) due to user incols orwerinding																
0510 CLASS B-2 CONCRETE Material 4 May 17, 2021 SYSTEM \$16,548.00 This adjustment offsets the original system-generated Material Payment Estimate teaching				Construction	n Stockpile ST	MI - Total			\$29,564.00							
CONCRETE CONCRETE Pair Pair Pair Pair Pair Pair Pair Pair		0450 - Total	Total						\$0.00							
OS20 Hole Jord Solution 0510 - Total - Total 50.00 - Total 50.00 0510 - Total - Total 50.00 - Total 50.00 0520 CURB Material - Total 50.00 This adjustment offsets the original system-generated Material Payment Estimate Ism Adjustment (0004) due to user connent overridding Payment Estimate Exception 21 on the current Payment Estimate. 0520 BLOCKOUT Material - Solution 50.00 This adjustment offsets the original system-generated Material Payment Estimate. 0520 BLOCKOUT Material - Solution 50.00 This adjustment offsets the original system-generated Material Payment Estimate. 0520 Jun 2, 2021 SYSTEM \$30,600.00 This adjustment (0003) due to user check3 overridding Payment Estimate. 0520 - Total 50.01 61.00.00 This adjustment (0003) due to user check3 overridding Payment Estimate. 0520 - Total - Total 50.00 SYSTEM \$61.200.00 This adjustment offsets the original system-generated Material Payment Estimate. 0530 HALE-SOLE Material Total 50.00 This adjustment offsets the original system-generated Material Payment E		0510				4		SYSTEM	\$16,548.00	Estimate Item Adjustment (0007) due to user connen1 overridding Payment						
Material - Total 90.00 0570 - Total 50.00 0520 CURB Material Material May 17, 2021 SYSTEM \$30,600.00 Estimate item Adjustment (0008) due to user connent overridding Payment Estimate item Adjustment (0003) due to user connent overridding Payment Estimate item Adjustment (0003) due to user brooks3 overridding Payment Estimate item Adjustment (0003) due to user brooks3 overridding Payment Estimate item Adjustment (0003) due to user brooks3 overridding Payment Estimate item Adjustment (0003) due to user brooks3 overridding Payment Estimate item Adjustment (0003) due to user brooks3 overridding Payment Estimate item Adjustment (0003) due to user brooks3 overridding Payment Estimate item Adjustment (0003) due to user brooks3 overridding Payment Estimate item Adjustment (0003) due to user brooks3 overridding Payment Estimate item Adjustment (0003) due to user brooks3 overridding Payment Estimate item Adjustment (0003) due to user brooks3 overridding Payment Estimate item Adjustment (0003) due to user brooks3 overridding Payment Estimate item Adjustment (0003) due to user brooks3 overridding Payment Estimate item Adjustment (0003) due to user connent overridding Payment Estimate item Adjustment (0003) due to user connent overridding Payment Estimate item Adjustment (0003) due to user connent overridding Payment Estimate item Adjustment (0003) due to user connent overridding Payment Estimate item Adjustment (0003) due to user connent overridding Payment Estimate Exception 2 on the current Payment Estimate. 0530 HALF-SOLE Apr 16, SYSTEM S30.500.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.						4		SYSTEM	(\$16,548.00)							
0510 Total Secure Sum 0520 CURB BLOCKOUT Meterial A Moy 17, 2021 SYSTEM \$30,600,00, 2021 This adjustment (foreits the original system-generated Material Payment Estimate litem Adjustment (0009) due to user connent overridding Payment Estimate litem Adjustment (0000) due to user connent overridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxic 30 verridding Payment Estimate litem Adjustment (0000) due to user toxic 10 verridding Payment Estimate litem Adjustment (0000) due to user toxic 10 verridding Payment Estimate litem Adjustment (0000) due to user recent 10 verridding Payment Estimate litem Adjustment (0000) due to user connent 0 verridding Payment Estimate litem Adjustment (0000) due to user connent 0 verridding Payment Estimate litem Adjustment (0000) due to user connent 0 verridding Payment Estimate litem Adjustment (0001) due to user connent 0 verridding Payment Estimate litem Adjustment (0001) due to user connent 0 verridding Payment Estimate litem Adjustment (0001) due to user connent 0 verridding Payment Estimate litem Adjustment (0001) due to user connent 0 verridding Payment Estimate litem Adjustment (0001) due to user connent 0 verridding Payment Estimate litem Adjustment (0001)					- Total				\$0.00							
0510 Total Secure Sum 0520 CURB BLOCKOUT Meterial A Moy 17, 2021 SYSTEM \$30,600,00, 2021 This adjustment (foreits the original system-generated Material Payment Estimate litem Adjustment (0009) due to user connent overridding Payment Estimate litem Adjustment (0000) due to user connent overridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxics 30 verridding Payment Estimate litem Adjustment (0000) due to user toxic 30 verridding Payment Estimate litem Adjustment (0000) due to user toxic 10 verridding Payment Estimate litem Adjustment (0000) due to user toxic 10 verridding Payment Estimate litem Adjustment (0000) due to user recent 10 verridding Payment Estimate litem Adjustment (0000) due to user connent 0 verridding Payment Estimate litem Adjustment (0000) due to user connent 0 verridding Payment Estimate litem Adjustment (0000) due to user connent 0 verridding Payment Estimate litem Adjustment (0001) due to user connent 0 verridding Payment Estimate litem Adjustment (0001) due to user connent 0 verridding Payment Estimate litem Adjustment (0001) due to user connent 0 verridding Payment Estimate litem Adjustment (0001) due to user connent 0 verridding Payment Estimate litem Adjustment (0001) due to user connent 0 verridding Payment Estimate litem Adjustment (0001)				Material - To	tal				\$0.00							
0520 CURB BLOCKOUT Material 4 May 17, 2021 SYSTEM \$30,600.00 This adjustment (0008) due to user connent overridding Payment Estimate Exception 21 on the current Payment Estimate. 4 May 17, 2021 SYSTEM \$30,600.00 This adjustment (0008) due to user connent overridding Payment Estimate Exception 21 on the current Payment Estimate. 5 Jun 2, 2021 SYSTEM \$30,600.00 This adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate. 6 Jun 2, 2021 SYSTEM \$30,600.00 This adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate. 6 Jun 16, 2021 SYSTEM \$61,200.00 This adjustment (0003) due to user leezt overridding Payment Estimate Exception 2 on the current Payment Estimate. 6 Jun 16, 2021 SYSTEM \$61,200.00 This adjustment (0003) due to user leezt overridding Payment Estimate Exception 2 on the current Payment Estimate. 6 Jun 16, 2021 SYSTEM \$61,200.00 This adjustment (0003) due to user connent overridding Payment Estimate Exception 2 on the current Payment Estimate. 6 Jun 16, 2021 SYSTEM \$50.00 This adjustment (0003) due to user connent overridding Payment Estimate E		0510 -	Total						\$0.00							
6 May 17. SYSTEM (\$30,600.0) Performance 5 Jun 2. SYSTEM \$30,600.00 This adjustment offsets the original system-generated Material Payment Estimate learn Adjustment (0003) due to user brooks3 overridding Payment Estimate learn Adjustment (0003) due to user brooks3 overridding Payment Estimate learn Adjustment (0003) due to user brooks3 overridding Payment Estimate learn Adjustment (0003) due to user lear 1 overridding Payment Estimate learn Adjustment (0003) due to user lear 1 overridding Payment Estimate learn Adjustment (0003) due to user lear 1 overridding Payment Estimate learn Adjustment (0003) due to user lear 1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 000 1000 1000 10000 10000 10000 10000 10000 10000 10000 10000 10000 10000 10000 10000 10000 10000 10000 10000 10000 2001			CURB	Material		4		SYSTEM		Estimate Item Adjustment (0008) due to user connen1 overridding Payment						
Value 5 Jun 2, 2021 SYSTEM \$30,600.00 This adjustment offsets the original system-generated Material Payment Estimate tices Adjustment (0003) due to user brooks3 overridding Payment Estimate tices Adjustment (0003) due to user brooks3 overridding Payment Estimate tices Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate. 6 Jun 16, 2021 SYSTEM \$61,200.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 6 Jun 16, 2021 SYSTEM \$61,200.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 0520 - Total - Total SYSTEM \$61,200.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 0530 HALF-SOLE REPAR Material - Total SYSTEM \$3,50.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 0530 HALF-SOLE REPAR Material Apr 16, 2021 SYSTEM \$3,550.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 10 May 3, 2021 SYSTEM \$3,550.00 This adjustment offsets the original system-generated Material Payment Es						4		SYSTEM	(\$30,600.00)	Estimate Exception 21 on the current Payment Estimate.						
0520 - Total 							5	Jun 2,	SYSTEM	\$30,600.00	Estimate Item Adjustment (0003) due to user brooks3 overridding Payment					
6 Jun 16, 2021 \$VSTEM \$61,200.00 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0003) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 0 Jun 16, 2021 \$VSTEM \$61,200.00 • Total • Total \$0.00 0 Material - Total \$0.00 0 • Total \$0.01 0 • Total \$0.01 0 • Total \$0.01 </td <td></td> <td></td> <td></td> <td rowspan="2"></td> <td rowspan="2"></td> <td rowspan="2"></td> <td rowspan="2"></td> <td rowspan="2"></td> <td></td> <td></td> <td>5</td> <td></td> <td>SYSTEM</td> <td>(\$30,600.00)</td> <td>Estimate Exception 3 on the current Payment Estimate.</td>													5		SYSTEM	(\$30,600.00)
Image: base base base base base base base base												6	Jun 16,	SYSTEM	\$61,200.00	
Image: Contrained by the second se							6		SYSTEM	(\$61,200.00)						
Material - Total \$0.00 0520 - Total 0530 HALF-SOLE REPAIR Material Apr 16, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Cology) due to user connen1 overridding Payment Estimate 2 Apr 16, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate 3 May 3, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate 3 May 3, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate 3 May 3, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate 5 Jun 2, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate 5 Jun 2, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate																
O520 - Total S0.00 0530 HALF-SOLE REPAIR Material REPAIR Apr 16, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 2 Apr 16, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 3 May 3, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 3 May 3, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 3 May 3, 2021 SYSTEM \$70,195.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate. 5 Jun 2, SYSTEM \$70,195.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.					- Total				\$0.00							
0530 HALF-SOLE REPAIR Material 2 Apr 16, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user connen1 overridding Payment 2 Apr 16, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 3 May 3, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 3 May 3, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 5 Jun 2, 2021 SYSTEM \$70,195.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate.				Material - To	tal				\$0.00							
REPAIR 2021 2021 Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 2 Apr 16, 2021 SYSTEM (\$35,350.00) 3 May 3, 2021 SYSTEM \$35,350.00 5 Jun 2, 2021 SYSTEM \$70,195.00 5 Jun 2, SYSTEM \$70,195.00 This adjustment (0004) due to user brooks3 overridding Payment Estimate. 5 Jun 2, SYSTEM \$70,195.00 This adjustment (0004) due to user brooks3 overridding Payment Estimate.		0520 -	Total						\$0.00							
3 May 3, 2021 SYSTEM \$35,350.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user connent overridding Payment Estimate Exception 4 on the current Payment Estimate. 3 May 3, 2021 SYSTEM \$35,350.00 5 Jun 2, 2021 SYSTEM \$70,195.00 5 Jun 2, SYSTEM \$70,195.00 This adjustment (0004) due to user brooks3 overridding Payment Estimate Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate.		0530		Material		2		SYSTEM	\$35,350.00	Estimate Item Adjustment (0009) due to user connen1 overridding Payment						
2021 2021 Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 3 May 3, 2021 SYSTEM (\$35,350.00) 5 Jun 2, 2021 SYSTEM \$70,195.00 This adjustment offsets the original system-generated Material Payment Estimate. 5 Jun 2, 2021 SYSTEM \$70,195.00 This adjustment (0004) due to user brooks3 overridding Payment Estimate. 5 Jun 2, SYSTEM \$70,195.00 System Exception 5 on the current Payment Estimate.						2		SYSTEM	(\$35,350.00)							
2021 2021 5 Jun 2, 2021 5 SYSTEM 6 SYSTEM 5 Jun 2, 5 SYSTEM 5 SYSTEM 5 SYSTEM 5 SYSTEM 5 SYSTEM 5 SYSTEM 6 SYSTEM 6 SYSTEM						3		SYSTEM	\$35,350.00	Estimate Item Adjustment (0001) due to user connen1 overridding Payment						
2021 Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate. 5 Jun 2, SYSTEM (\$70,195.00)						3		SYSTEM	(\$35,350.00)							
						5		SYSTEM	\$70,195.00	Estimate Item Adjustment (0004) due to user brooks3 overridding Payment						
						5		SYSTEM	(\$70,195.00)							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J913545	0530	HALF-SOLE REPAIR	Material		6	Jun 16, 2021	SYSTEM	\$70,195.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					6	Jun 16, 2021	SYSTEM	(\$70,195.00)		
					7	Jul 1, 2021	SYSTEM	\$70,195.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					7	Jul 1, 2021	SYSTEM	(\$70,195.00)		
					8	Jul 15, 2021	SYSTEM	\$70,195.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					8	Jul 15, 2021	SYSTEM	(\$70,195.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
			Overrun	Overrun	7	Jul 1, 2021	leez1	(\$10,100.00)	Offset system generated adjustment since Change Order has not been approved.	
					7	Jul 1, 2021	SYSTEM	\$10,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 1390.000; Overrun Quantity Balance 200.00.	
					7	Jul 1, 2021	SYSTEM	(\$10,100.00)		
					8	Jul 15, 2021	leez1	\$10,100.00	Change Order number 0002 has been approved. Payment for overrun adjustment on estimate 0007.	
				Overrun - T	otal			\$0.00		
			Overrun - To	tal				\$0.00		
	0530 -	Total						\$0.00		
	0540	FULL DEPTH REPAIR	Material		5	Jun 2, 2021	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brooks3 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					5	Jun 2, 2021	SYSTEM	(\$280.00)		
					6	Jun 16, 2021	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					6	Jun 16, 2021	SYSTEM	(\$280.00)		
					7	Jul 1, 2021	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					7	Jul 1, 2021	SYSTEM	(\$420.00)		
					8	Jul 15, 2021	SYSTEM	\$420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					8	Jul 15, 2021	SYSTEM	(\$420.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0540 -	Total						\$0.00		
	0550	0 REINFORCING I STEEL (EPOXY COATED)	Material	aterial	2	Apr 16, 2021	SYSTEM	\$843.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					2	Apr 16, 2021	SYSTEM	(\$843.75)		
					3	May 3, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
							3	May 3, 2021	SYSTEM	(\$1,687.50)



Jul 19, 2021

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks			
J913545	0550	REINFORCING STEEL (EPOXY	Material	Туре	4	May 17, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user connen1 overridding Payment			
		COATED)			4	May 17,	SYSTEM	(\$1,687.50)	Estimate Exception 37 on the current Payment Estimate.			
				Tedal		2021		¢0.00				
			Material - To	- Total				\$0.00 \$0.00				
	0550 -	Total	inatorial 10					\$0.00				
	0620	CLASS B-2 CONCRETE	Material		4	May 17, 2021	SYSTEM	\$16,548.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user connen1 overridding Payment			
				4	4	May 17,	SYSTEM	(\$16,548.00)	Estimate Exception 15 on the current Payment Estimate.			
					5	2021 Jun 2, 2021	SYSTEM	\$16,548.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment			
					5	Jun 2,	SYSTEM	(\$16,548.00)	Estimate terr Adjustment (6000) due to user brokss overholing Payment Estimate Exception 2 on the current Payment Estimate.			
					5	2021	STOTEM	(\$10,540.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0620 -		Meterial		4	May 17	SYSTEM	\$0.00	This adjustment effects the aviatinal system approvated Material Downant			
	0630	CURB BLOCKOUT	Material		4	May 17, 2021	STOTEM	\$30,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user connen1 overridding Payment Estimate Exception 27 on the current Payment Estimate.			
								4	May 17, 2021	SYSTEM	(\$30,600.00)	
					5	Jun 2, 2021	SYSTEM	\$30,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brooks3 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					5	Jun 2, 2021	SYSTEM	(\$30,600.00)				
							6	Jun 16, 2021	SYSTEM	\$61,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					6	Jun 16, 2021	SYSTEM	(\$61,200.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	0630 -	Total						\$0.00				
	0640	HALF-SOLE REPAIR	Material		2	Apr 16, 2021	SYSTEM	\$26,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user connen1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					2	Apr 16, 2021	SYSTEM	(\$26,000.00)				
					3	May 3, 2021	SYSTEM	\$26,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
					3	May 3, 2021	SYSTEM	(\$26,000.00)				
					6	Jun 16, 2021	SYSTEM	\$86,632.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user leez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
					6	Jun 16, 2021	SYSTEM	(\$86,632.00)				
					7	Jul 1, 2021	SYSTEM	\$86,632.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					7	Jul 1, 2021	SYSTEM	(\$86,632.00)				
					8	Jul 15, 2021	SYSTEM	\$86,632.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user leez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					8	Jul 15,	SYSTEM	(\$86,632.00)				



Jul	19,	2021
Jul	19,	2021

oject	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks						
3545	0640	HALF-SOLE	Material	Туре		2021									
		REPAIR		- Total				\$0.00							
			Material - To					\$0.00							
			Overrun	Overrun	7	Jul 1, 2021	leez1	(\$2,496.00)	Offset system generated adjustment since Change Order has not been approved.						
					7	Jul 1, 2021	SYSTEM	\$2,496.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception on the current Payment Estimate. Material Insufficiency Quantity 1666.000 Overrun Quantity Balance 48.00.						
					7	Jul 1, 2021	SYSTEM	(\$2,496.00)							
					8	Jul 15, 2021	leez1	\$2,496.00	Change Order number 0002 has been approved. Payment for overrun adjustment on estimate 0007.						
				Overrun - T	otal			\$0.00							
			Overrun - To	tal				\$0.00							
	0640 -	Total						\$0.00							
	0650	FULL DEPTH REPAIR	Material		4	May 17, 2021	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user connen1 overridding Payme Estimate Exception 35 on the current Payment Estimate.						
							4	May 17, 2021	SYSTEM	(\$231.00)					
											5	Jun 2, 2021	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brooks3 overridding Paymen Estimate Exception 9 on the current Payment Estimate.
							5 Jun 2, SYSTEM (\$231.00) 2021								
					6	Jun 16, 2021	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user leez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					6	Jun 16, 2021	SYSTEM	(\$231.00)							
					7	Jul 1, 2021	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
					7	Jul 1, 2021	SYSTEM	(\$231.00)							
								8	Jul 15, 2021	SYSTEM	\$231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user leez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					8	Jul 15, 2021	SYSTEM	(\$231.00)							
				- Total				\$0.00							
			Material - To	tal				\$0.00							
	0650 -	Total						\$0.00							
	0660	REINFORCING STEEL (EPOXY COATED)	Material		3	May 3, 2021	SYSTEM	\$843.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user connen1 overridding Payme Estimate Exception 7 on the current Payment Estimate.						
					3	May 3, 2021	SYSTEM	(\$843.75)							
						May 17, 2021	SYSTEM	\$843.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user connen1 overridding Payme Estimate Exception 38 on the current Payment Estimate.						
					4	May 17, 2021	SYSTEM	(\$843.75)							
				- Total				\$0.00							
		Material - Total													
	0660 -	Total						\$0.00							
	5001	TEMPORARY LONG-TERM RUMBLE	Material		4	May 17, 2021	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user connen1 overridding Payme Estimate Exception 4 on the current Payment Estimate.						
		STRIPS			4	May 17, 2021	SYSTEM	(\$8,400.00)							



Jul 19, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3545	5001	TEMPORARY LONG-TERM	Material	- Total				\$0.00	
		RUMBLE STRIPS	Material - Tot	tal				\$0.00	
	5001 - Total							\$0.00	
	5002	TEMPORARY REMOVABLE MARKING TAPE	Material		4	May 17, 2021	SYSTEM	\$5,878.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user connen1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$5,878.75)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
			Overrun	Overrun Overrun	7	Jul 1, 2021	SYSTEM	(\$6,643.75)	
					8	Jul 15, 2021	SYSTEM	\$6,643.75	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.25000 - 1.25000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	5002 -	Total						\$0.00	
J9I3545 -	Total							\$0.00	
Overall -	Total							\$0.00	