

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 16, 2021

| Progress Estimate Number | Contract ID         | 201120-C08                             | Pay Period<br>Start | August 2, 2021     | Original Contract Amount                              | \$1,268,980.49                   |
|--------------------------|---------------------|--|---------------------|--------------------|---|----------------------------------|
| 8                        | Prime<br>Contractor | Superior Bowen Asphalt Company,<br>LLC | Pay Period End      | August 15,<br>2021 | Net Change Order<br>Amount<br>Current Contract Amount | (\$124,957.39)<br>\$1,144,023.10 |

| Original Comp   | etion Date Current Completion Date Actual Completion Date % of Current Contract Amoun |  |  |  |  |  |  |  |  |
|-----------------|---|--|--|--|--|--|--|--|--|
| August 18, 2021 |   | ramses1  |  |  |  |  |  |  |  |
| August 17, 2021 |   | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by |  |  |  |  |  |  |  |
| August 17, 2021 |   | Generated and Approved (and should be considered Draft) at the Project Office Level by   |  |  |  |  |  |  |  |
| Approval Date   |   |  |  |  |  |  |  |  |  |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete |
|--------------------------|-------------------------|------------------------|---------------------------------------|
| October 29, 2021         | October 29, 2021        |                        | 95.24%                                |
| Contract I               | nformational Dates      | Milestones             |                                       |

|                        | Milestones               |                                 |  |  |  |
|------------------------|--------------------------|---------------------------------|--|--|--|
| Date Description       | Original Completion Date | No Milestones Exist for Contrac |  |  |  |
| Acceptance Date        | June 28, 2021            | June 28, 2021                   |  |  |  |
| Awarded Date           | December 2, 2020         | December 2, 2020                |  |  |  |
| Letting Date           | November 20, 2020        | November 20, 2020               |  |  |  |
| Notice to Proceed Date | January 4, 2021          | January 4, 2021                 |  |  |  |
| Work Began Date        |                          |                                 |  |  |  |

| Contract Total Pay For Estimat | te No. 8            |               |                       |                |  |
|--------------------------------|---------------------|---------------|-----------------------|----------------|--|
|                                |                     | This Estimate | Previous              | To Date        |  |
| 201120-C08                     |                     |               |                       |                |  |
| Total Po                       | sted Items Pay      | \$0.00        | \$1,089,566.73        | \$1,089,566.73 |  |
| Gross Ite                      | em Adjustments      | \$685.07      | \$0.00                | \$685.07       |  |
| Incentive                      | 9                   | \$0.00        | \$0.00                | \$0.00         |  |
| Disincen                       | tive                | \$0.00        | \$0.00                | \$0.00         |  |
| Liquidate                      | ed Damage           | \$0.00        | \$0.00                | \$0.00         |  |
| Other Co                       | ontract Adjustments | \$25,830.30   | \$0.00                | \$25,830.30    |  |
|                                |                     |               | <b>\$1,089,566.73</b> | \$1,116,082.10 |  |
| Contract Total Payable This Es | timate:             | \$26,515.37   |                       |                |  |

#### Items Paid This Estimate Period

No Data Available

| Contract Adjustments This E      | <u>stimate</u> |   |            |      |             |
|----------------------------------|----------------|---|------------|------|-------------|
| Adj Type                         | Entered By     | Comments  | Time Units | Rate | Amount      |
| SPADOther Contract<br>Adjustment | weathc1        | Job Number: J4S3328 Line Number: 0050, 1.75", ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C) 21-37 SuperPave Pay Factor SP125C (PG 70-22) Lot 1 = 105% SuperPave Pay Factor SP125C (PG 70-22) Lot 2 = 104% TSR Pay Factor there was none. Lot #1 was \$14,320.00 Lot #2 was \$11,510.30 Total \$25,830.30 |            |      | \$25,830.30 |

Overall - Total \$25,830.30

These amounts are listed in the Incentive, Disincentive, Liquidated Damages or Other Contract Adjustments

| Line Item         | Adjusti     | ments This Estimate  |                    |                                  |  |                        |                                       |                      |
|-------------------|-------------|--|--------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| Project<br>Number | Line<br>No. | Item Description   | Adjustment<br>Type | Other Item<br>Adjustment<br>Type | Comments   | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount |
| J4S3328           | 0070        | FURNISHING AND PLACING<br>CONCRETE MATERIAL FOR<br>FULL DEPTH PAVEMENT<br>REPAIR | Material           |                                  |  | -334.63                | \$191.75                              | (\$64,165.30)        |
|                   | 0070        | FURNISHING AND PLACING CONCRETE MATERIAL FOR                                     | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item | 334.63                 | \$191.75                              | \$64,165.30          |

Revision 4/1/2020 Page 1 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 16, 2021

| Progress Estimate<br>Number | Contract ID         | 201120-C08                             | Pay Period<br>Start | August 2, 2021     | Original Contract Amount                              | \$1,268,980.49                   |
|-----------------------------|---------------------|--|---------------------|--------------------|---|----------------------------------|
| 8                           | Prime<br>Contractor | Superior Bowen Asphalt Company,<br>LLC | Pay Period End      | August 15,<br>2021 | Net Change Order<br>Amount<br>Current Contract Amount | (\$124,957.39)<br>\$1,144,023.10 |

| oject<br>mber | Line<br>No. | Item Description  | Adjustment<br>Type       | Other Item<br>Adjustment<br>Type | Comments  | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount |
|---------------|-------------|---|--------------------------|----------------------------------|---|------------------------|---------------------------------------|----------------------|
| 3328          |             | FULL DEPTH PAVEMENT<br>REPAIR   |                          |                                  | Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.   |                        |                                       |                      |
|               | 0110        | DOWEL BAR (DRILLING,<br>FURNISHING AND<br>INSTALLATION) FOR FULL<br>DEPTH PAVEMENT REPAIR | Material                 |                                  |   | -311                   | \$4.50                                | (\$1,399.50          |
|               | 0110        | DOWEL BAR (DRILLING,<br>FURNISHING AND<br>INSTALLATION) FOR FULL<br>DEPTH PAVEMENT REPAIR | Material                 |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0003) due to user weathc1<br>overridding Payment Estimate Exception 4 on<br>the current Payment Estimate. | 311                    | \$4.50                                | \$1,399.50           |
|               | 0290        | 4 IN. WHITE STANDARD<br>WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE P<br>BEADS             | Overrun                  |                                  | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).   | -50                    | \$0.18                                | (\$9.00              |
|               | 0290        | 4 IN. WHITE STANDARD<br>WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE P<br>BEADS             | Overrun                  |                                  | This adjustment offsets the original system-<br>generated Overrun Payment Estimate Item<br>Adjustment (0001) due to user weathc1<br>overridding Payment Estimate Exception 5 on<br>the current Payment Estimate.  | 50                     | \$0.18                                | \$9.00               |
|               | 0290        | 4 IN. WHITE STANDARD<br>WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE P<br>BEADS             | Other Item<br>Adjustment | Retroreflectivity<br>Adjustment  | Adjustment based on the retro-reflectivity adjustment spreadsheet that was calculated for this line item.   |                        |                                       | \$409.61             |
|               | 0300        | 4 IN. YELLOW STANDARD<br>WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE P<br>BEADS            | Other Item<br>Adjustment | Retroreflectivity<br>Adjustment  | Adjustment based on the retro-reflectivity adjustment spreadsheet that was calculated for this line item.   |                        |                                       | \$275.46             |
|               | 0330        | MGS GUARDRAIL, 8 FT.<br>POSTS, 6 FT 3 IN.<br>SPACING                                      | Material                 |                                  |   | -1,075                 | \$21.00                               | (\$22,575.00         |
|               | 0330        | MGS GUARDRAIL, 8 FT.<br>POSTS, 6 FT 3 IN.<br>SPACING                                      | Material                 |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0004) due to user weathc1<br>overridding Payment Estimate Exception 1 on<br>the current Payment Estimate. | 1,075                  | \$21.00                               | \$22,575.00          |
| al            |             |   |                          |                                  |   |                        |                                       | \$685.07             |

Revision 4/1/2020 Page 2 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

|                   |                                    |                            |       |            | Cor   | ntract Project Information                                  |   |
|-------------------|------------------------------------|----------------------------|-------|------------|---|---|---|
| Project<br>Number | Federal<br>Proj.<br>Number         | Project<br>Description     | Route | County     |   |   | Location of Work  |
| J4S3328           | FAS<br>S302(83)                    | Resurface                  | 12    | JACKSON    | from I-435 to Spring Street                     |   |   |
|                   |                                    |                            |       |            |   |   |   |
| Totals by .       | Job Numbe                          | rs                         |       |            |   |   |   |
| Totals by J4S3328 | Job Numbe                          | rs                         |       |            | This Estimate                                   | Previous  | To Date   |
| •                 |                                    | rs<br>d Item Pay           |       |            | This Estimate<br>\$0.00                         | Previous<br>\$1,089,566.73                                  | <b>To Date</b><br>\$1,089,566.73                              |
| •                 | Poste                              |                            | ents  |            |   |   |   |
| •                 | Poste                              | d Item Pay                 |       | s Item Pay | \$0.00  | \$1,089,566.73  | \$1,089,566.73  |
| •                 | Poste                              | d Item Pay<br>Item Adjustm |       | s Item Pay | \$0.00<br>\$685.07                              | \$1,089,566.73<br>\$0.00                                    | \$1,089,566.73<br>\$685.07                                    |
| •                 | Poste<br>Gross                     | d Item Pay<br>Item Adjustm |       | s Item Pay | \$0.00<br>\$685.07<br><b>\$685.07</b>           | \$1,089,566.73<br>\$0.00<br><b>\$1,089,566.73</b>           | \$1,089,566.73<br>\$685.07<br><b>\$1,090,251.80</b>           |
| •                 | Poste<br>Gross<br>Incent<br>Disino | d Item Pay<br>Item Adjustm | Gross | s Item Pay | \$0.00<br>\$685.07<br><b>\$685.07</b><br>\$0.00 | \$1,089,566.73<br>\$0.00<br><b>\$1,089,566.73</b><br>\$0.00 | \$1,089,566.73<br>\$685.07<br><b>\$1,090,251.80</b><br>\$0.00 |

Revision 4/1/2020 Page 3 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

| Exceptions / Discrepencies   | Explanation            | Entered<br>By | Status     |
|--|------------------------|---------------|------------|
| Estimate Exception Type: Insufficient Materials: Project J4S3328, Item 6061061, Project Item Line Number 0330, Material Set 606106196, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.                                    | Working with Materials | weathc1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3328, Item 6131010, Project Item Line Number 0070, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.       | Working with Materials | weathc1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3328, Item 6131010, Project Item Line Number 0070, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.      | Working with Materials | weathc1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3328, Item 6131015, Project Item Line Number 0110, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient. | Working with Materials | weathc1       | Overridden |
| Estimate Exception Type: Item Overrun: Contract 201120-C08, Contract Project J4S3328, Project Item Line Number 0290, Contract Line Item Number 0290, Item 6206000C, Minor Item.  | On Change Order        | weathc1       | Overridden |

Revision 4/1/2020 Page 4 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| 201120-C08 J4S3:                | 000° 000° 000° 000° 000° 000° 000° 000 | 0020<br>0030<br>0040<br>0050 | 2022010<br>2063500<br>2153000<br>4011209 | REMOVAL OF IMPROVEMENTS  CULVERT CLEANOUT  SHAPING SLOPES, CLASS III                               | 1.00<br>4.00 | 0.00      | 1.00       | LS<br>EA | 1.00       | \$3,150.00  | \$3,150.00   |
|---------------------------------|--|------------------------------|--|--|--------------|-----------|------------|----------|------------|-------------|--------------|
|                                 | 000.<br>000.<br>000.<br>000.<br>000.   | 0030<br>0040<br>0050         | 2153000<br>4011209                       |  | 4.00         | 0.00      | 4.00       | ΕΛ       | 4.00       | CO 404 20   | *******      |
|                                 | 000.<br>000.<br>000.<br>000.           | 0040                         | 4011209                                  | SHAPING SLOPES, CLASS III  |              |           |            | LA       | 4.00       | \$2,421.30  | \$9,685.20   |
|                                 | 000-<br>000-<br>000-                   | 0050                         |  |  | 4.50         | 0.00      | 4.50       | 100F     | 4.50       | \$610.00    | \$2,745.00   |
|                                 | 000                                    |                              |  | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  | 1,709.90     | -468.50   | 1,241.40   | TONS     | 1,241.40   | \$70.65     | \$87,704.91  |
|                                 | 000                                    | 0060                         | 4030103                                  | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)   | 9,867.80     | 155.90    | 10,023.70  | TONS     | 10,023.70  | \$57.28     | \$574,157.54 |
|                                 | 000                                    |                              | 4071005                                  | TACK COAT  | 11,904.00    | -5,495.00 | 6,409.00   | GAL      | 6,409.00   | \$2.15      | \$13,779.35  |
|                                 |  | 0070                         | 6131010                                  | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR                            | 690.70       | -356.07   | 334.63     | SQYD     | 334.63     | \$191.75    | \$64,165.30  |
|                                 | 000                                    | 0080                         | 6131012                                  | SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)  | 69.10        | -69.10    | 0.00       | SQYD     | 0.00       | \$1.15      | \$0.00       |
|                                 |  | 0090                         | 6131013                                  | TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)                                     | 69.10        | -69.10    | 0.00       | SQYD     | 0.00       | \$1.15      | \$0.00       |
|                                 | 000                                    | 0100                         | 6131014                                  | FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)                           | 2,368.00     | -1,012.00 | 1,356.00   | LF       | 1,356.00   | \$1.90      | \$2,576.40   |
|                                 | 000                                    | 0110                         | 6131015                                  | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR                   | 1,700.00     | -1,389.00 | 311.00     | EA       | 311.00     | \$4.50      | \$1,399.50   |
|                                 | 000                                    | 0120                         | 6133018                                  | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR               | 140.80       | -120.25   | 20.55      | TONS     | 20.55      | \$99.60     | \$2,046.78   |
|                                 | 000                                    | 0130                         | 6133019                                  | REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR  | 847.20       | 0.00      | 847.20     | SQYD     | 79.00      | \$70.90     | \$5,601.10   |
|                                 | 000                                    | 0140                         | 6161005                                  | CONSTRUCTION SIGNS   | 739.00       | 184.00    | 923.00     | SQFT     | 923.00     | \$4.00      | \$3,692.00   |
|                                 | 000                                    | 0150                         | 6161008                                  | ADVANCED WARNING RAIL SYSTEM   | 2.00         | 0.00      | 2.00       | EA       | 2.00       | \$20.00     | \$40.00      |
|                                 | 000                                    | 0160                         | 6161009                                  | FLAG ASSEMBLY  | 20.00        | -20.00    | 0.00       | EA       | 0.00       | \$20.00     | \$0.00       |
|                                 | 000                                    | 0170                         | 6161025                                  | CHANNELIZER (TRIM LINE)  | 165.00       | 175.00    | 340.00     | EA       | 340.00     | \$15.00     | \$5,100.00   |
|                                 | 000                                    | 0180                         | 6161031                                  | TYPE III MOVEABLE BARRICADE WITH LIGHTS  | 2.00         | 0.00      | 2.00       | EA       | 2.00       | \$50.00     | \$100.00     |
|                                 | 000                                    | 0190                         | 6161034                                  | DIRECTIONAL INDICATOR BARRICADE WITH LIGHT   | 14.00        | -14.00    | 0.00       | EA       | 0.00       | \$25.00     | \$0.00       |
|                                 | 000                                    | 0200                         | 6161040                                  | FLASHING ARROW PANEL   | 2.00         | 1.00      | 3.00       | EA       | 3.00       | \$700.00    | \$2,100.00   |
|                                 | 000                                    | 0210                         | 6161098A                                 | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 4.00         | 0.00      | 4.00       | EA       | 4.00       | \$1,750.00  | \$7,000.00   |
|                                 | 000                                    | 0220                         | 6181000                                  | MOBILIZATION   | 1.00         | 0.00      | 1.00       | LS       | 1.00       | \$98,500.00 | \$98,500.00  |
|                                 | 000                                    | 0230                         | 6200003                                  | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE   | 3,194.00     | 0.00      | 3,194.00   | LF       | 3,194.00   | \$2.00      | \$6,388.00   |
|                                 | 000                                    | 0240                         | 6200015                                  | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE   | 918.00       | -107.00   | 811.00     | LF       | 811.00     | \$10.00     | \$8,110.00   |
|                                 | 000                                    | 0250                         | 6200018                                  | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  | 155.00       | -11.00    | 144.00     | LF       | 144.00     | \$10.00     | \$1,440.00   |
|                                 | 000                                    | 0260                         | 6200021                                  | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW   | 18.00        | -4.00     | 14.00      | EA       | 14.00      | \$200.00    | \$2,800.00   |
|                                 | 000                                    | 0270                         | 6200036                                  | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK                                     | 259.00       | -38.00    | 221.00     | EA       | 221.00     | \$90.00     | \$19,890.00  |
|                                 | 000                                    | 0280                         | 6205906A                                 | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE L BEADS                         | 497.00       | 0.00      | 497.00     | LF       | 497.00     | \$1.00      | \$497.00     |
|                                 | 000                                    | 0290                         | 6206000C                                 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS                               | 49,747.00    | 0.00      | 49,747.00  | LF       | 49,797.00  | \$0.18      | \$8,963.46   |
|                                 | 000                                    | 0300                         | 6206001C                                 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS                              | 45,182.00    | 0.00      | 45,182.00  | LF       | 45,182.00  | \$0.18      | \$8,132.76   |
|                                 | 000                                    | 0310                         | 6207001                                  | PAVEMENT MARKING REMOVAL   | 922.00       | 0.00      | 922.00     | LF       | 922.00     | \$1.00      | \$922.00     |
|                                 | 000                                    | 0320                         | 6221001                                  | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)                     | 119,039.00   | 0.00      | 119,039.00 | SQYD     | 119,039.00 | \$0.78      | \$92,850.42  |
|                                 | 0010                                   | 0330                         | 6061061                                  | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING   | 1,075.00     | 0.00      | 1,075.00   | LF       | 1,075.00   | \$21.00     | \$22,575.00  |
|                                 | 0010                                   | 0340                         | 6062202A                                 | BRIDGE ANCHOR SECTION, 7.5 FT. POSTS (SAFETY BARRIER CURB) (ROADWAY AND REHABILITATION WORK ONLY)  | 4.00         | 0.00      | 4.00       | EA       | 4.00       | \$1,870.00  | \$7,480.00   |
|                                 | 0010                                   | 0350                         | 6063014                                  | TYPE A CRASHWORTHY END TERMINAL (MASH)   | 6.00         | 0.00      | 6.00       | EA       | 6.00       | \$2,360.00  | \$14,160.00  |
|                                 |  | 0360                         | 6123000A                                 | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  | 2.00         | 0.00      | 2.00       | EA       | 2.00       | \$500.00    | \$1,000.00   |
|                                 | 000                                    |                              | 0020500                                  | CARLE LOOP RETECTOR IN DUCT  | 1,240.00     | 0.00      | 1,240.00   | LF       | 1,240.00   | \$7.35      | \$0.114.00   |
|                                 | 000                                    | 0370                         | 9028500                                  | CABLE, LOOP DETECTOR, IN DUCT  | ,_ 10.00     |           |            |          | 1,240.00   | Ψ1.55       | \$9,114.00   |
| Proje<br>201120-C08 Overall - T |  |                              | 2069901                                  | MISC.Culvert Cleanout  | 0.00         | 1.00      | 1.00       | LS       | 1.00       |             | \$1,701.00   |

Page 5 of 12 Revision 4/1/2020



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

| Line<br>Number | Item<br>Code | Description                              | DWR<br>Date | DWR<br>Approval<br>Date | Quantity<br>Posted | Units | Location | From<br>Station/<br>Log<br>Mile | Offset/<br>Distance | To<br>Station/<br>Log<br>Mile | Offset/<br>Distance | Comments                      |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|----------|---------------------------------|---------------------|-------------------------------|---------------------|-------------------------------|
| 0800           | 6131012      | SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM | 8/9/21      | 8/9/21                  | 0.00               | SQYD  |          | 1                               |                     | 1                             |                     | None were used on the project |
| 0090           | 6131013      | TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH | 8/9/21      | 8/9/21                  | 0.00               | SQYD  |          | 1                               |                     | 1                             |                     | None were used on the project |
| 0160           | 6161009      | FLAG ASSEMBLY                            | 8/9/21      | 8/9/21                  | 0.00               | EA    |          | 1                               |                     | 1                             |                     | None were used on the project |
| 0180           | 6161031      | TYPE III MOVEABLE BARRICADE WITH LIGHTS  | 8/9/21      | 8/9/21                  | 0.00               | EA    |          | 1                               |                     | 1                             |                     | None were used on the project |

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 12



| Project | Line   | Description  | Adjustment    | Other              | Est. | Created         | Created         | Amount          | Remarks   |               |  |
|---------|--------|--|---------------|--------------------|------|-----------------|-----------------|-----------------|---|---------------|--|
| rioject | Line   | Безеприон  | Туре          | Adjustment<br>Type |      | Date            | Ву              | Amount          | Remarks   |               |  |
| J4S3328 | 0050   | ASPHALTIC<br>CONCRETE<br>MIXTURE PG<br>70-22 (SP125C<br>MIX) | Material      |                    | 2    | May 17,<br>2021 | SYSTEM          | \$574,157.54    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  |               |  |
|         |        |  |               |                    | 2    | May 17,<br>2021 | SYSTEM          | (\$574,157.54)  |   |               |  |
|         |        |  |               | - Total            |      |                 |                 | \$0.00          |   |               |  |
|         |        |  | Material - To | otal               |      |                 |                 | \$0.00          |   |               |  |
|         |        |  | Overrun       | Overrun            | 2    | May 17,<br>2021 | SYSTEM          | \$8,929.95      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 10023.700; Overrun Quantity Balance 155.90. |               |  |
|         |        |  |               |                    | 2    | May 17,<br>2021 | SYSTEM          | (\$8,929.95)    |   |               |  |
|         |        |  |               |                    | 3    | Jun 2,<br>2021  | SYSTEM          | (\$8,929.95)    | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).   |               |  |
|         |        |  |               |                    | 3    | Jun 2,<br>2021  | SYSTEM          | \$8,929.95      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  |               |  |
|         |        |  |               | Overrun - T        | otal |                 |                 | \$0.00          |   |               |  |
|         |        |  | Overrun - T   | otal               |      |                 |                 | \$0.00          |   |               |  |
|         | 0050 - | Total  |               |                    |      |                 |                 | \$0.00          |   |               |  |
|         | 0060   | TACK COAT  | Material      |                    | 2    | May 17,<br>2021 | SYSTEM          | \$13,529.95     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  |               |  |
|         |        |  |               |                    | 2    | May 17,<br>2021 | SYSTEM          | (\$13,529.95)   |   |               |  |
|         |        |  |               | - Total            |      |                 |                 | \$0.00          |   |               |  |
|         |        |  | Material - To | otal               |      |                 |                 | \$0.00          |   |               |  |
|         | 0060 - | Total  |               |                    |      |                 |                 | \$0.00          |   |               |  |
|         | 0070   | FURN & PLACE<br>CONC MATL<br>FOR FULL<br>DEPTH               | Material      |                    | 1    | May 3,<br>2021  | SYSTEM          | \$24,415.53     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  |               |  |
|         |        |  |               |                    | 1    | May 3,<br>2021  | SYSTEM          | (\$24,415.53)   |   |               |  |
|         |        |  |               |                    | 2    | May 17,<br>2021 | SYSTEM          | \$42,434.28     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  |               |  |
|         |        |  |               |                    |      |                 | 2               | May 17,<br>2021 | SYSTEM  | (\$42,434.28) |  |
|         |        |  |               |                    |      |                 | 3               | Jun 2,<br>2021  | SYSTEM  | \$64,165.30   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
|         |        |  |               |                    | 3    | Jun 2,<br>2021  | SYSTEM          | (\$64,165.30)   |   |               |  |
|         |        |  |               |                    | 4    | Jun 16,<br>2021 | SYSTEM          | \$64,165.30     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  |               |  |
|         |        |  |               |                    | 4    | Jun 16,<br>2021 | SYSTEM          | (\$64,165.30)   |   |               |  |
|         |        |  |               |                    | 5    | Jun 30,<br>2021 | SYSTEM          | \$64,165.30     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  |               |  |
|         |        |  |               |                    |      | 5               | Jun 30,<br>2021 | SYSTEM          | (\$64,165.30)   |               |  |
|         |        |  |               |                    |      |                 |                 | 6               | Jul 16,<br>2021   | SYSTEM        | \$64,165.30  |
|         |        |  |               |                    |      | 6               | Jul 16,<br>2021 | SYSTEM          | (\$64,165.30)   |               |  |
|         |        |  |               |                    | 7    | Aug 2,<br>2021  | SYSTEM          | \$64,165.30     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  |               |  |
|         |        |  |               |                    |      |                 |                 |                 |   |               |  |



| Project | Line   | Description                                    | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By   | Amount        | Remarks  |  |              |  |  |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|-----------------|---------------|--|--|--------------|--|--|
| J4S3328 | 0070   | FURN & PLACE<br>CONC MATL<br>FOR FULL<br>DEPTH | Material           |                             | 8              | Aug 16,<br>2021 | SYSTEM          | \$64,165.30   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |  |              |  |  |
|         |        | DEFIN  |                    |                             | 8              | Aug 16,<br>2021 | SYSTEM          | (\$64,165.30) |  |  |              |  |  |
|         |        |  |                    | - Total                     |                |                 |                 | \$0.00        |  |  |              |  |  |
|         |        |  | Material - To      | otal                        |                |                 |                 | \$0.00        |  |  |              |  |  |
|         | 0070 - | Total  |                    |                             |                |                 |                 | \$0.00        |  |  |              |  |  |
|         | 0110   | DOWEL BAR<br>(DRILLING,<br>FURNISHING          | Material           |                             | 1              | May 3,<br>2021  | SYSTEM          | \$918.00      | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |  |              |  |  |
|         |        | AND INST                                       |                    |                             | 1              | May 3,<br>2021  | SYSTEM          | (\$918.00)    |  |  |              |  |  |
|         |        |  |                    |                             | 2              | May 17,<br>2021 | SYSTEM          | \$1,399.50    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |  |              |  |  |
|         |        |  |                    |                             | 2              | May 17,<br>2021 | SYSTEM          | (\$1,399.50)  |  |  |              |  |  |
|         |        |  |                    |                             | 3              | Jun 2,<br>2021  | SYSTEM          | \$1,399.50    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |  |              |  |  |
|         |        |  |                    |                             | 3              | Jun 2,<br>2021  | SYSTEM          | (\$1,399.50)  |  |  |              |  |  |
|         |        |  |                    |                             |                | 4               | Jun 16,<br>2021 | SYSTEM        | \$1,399.50   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |              |  |  |
|         |        |  |                    |                             |                | 4               | Jun 16,<br>2021 | SYSTEM        | (\$1,399.50)   |  |              |  |  |
|         |        |  |                    |                             | 5              | Jun 30,<br>2021 | SYSTEM          | \$1,399.50    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |  |              |  |  |
|         |        |  |                    |                             | 5              | Jun 30,<br>2021 | SYSTEM          | (\$1,399.50)  |  |  |              |  |  |
|         |        |  |                    |                             |                | 6               | Jul 16,<br>2021 | SYSTEM        | \$1,399.50   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |              |  |  |
|         |        |  |                    |                             |                |                 |                 | 6             | Jul 16,<br>2021  | SYSTEM   | (\$1,399.50) |  |  |
|         |        |  |                    |                             |                | 7               | Aug 2,<br>2021  | SYSTEM        | \$1,399.50   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |              |  |  |
|         |        |  |                    |                             |                |                 |                 |               | 7  | Aug 2,<br>2021   | SYSTEM       | (\$1,399.50)   |  |
|         |        |  |                    |                             |                |                 |                 | 8             | Aug 16,<br>2021  | SYSTEM   | \$1,399.50   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |  |
|         |        |  |                    |                             | 8              | Aug 16,<br>2021 | SYSTEM          | (\$1,399.50)  |  |  |              |  |  |
|         |        |  |                    | - Total                     |                |                 |                 | \$0.00        |  |  |              |  |  |
|         |        |  | Material - To      | otal                        |                |                 |                 | \$0.00        |  |  |              |  |  |
|         | 0110 - | Total  |                    |                             |                |                 |                 | \$0.00        |  |  |              |  |  |
|         | 0120   | FURN & PLACE<br>BIT. MATL FOR<br>CL B PARTIAL  | Material           |                             | 1              | May 3,<br>2021  | SYSTEM          | \$2,046.78    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |  |              |  |  |
|         |        |  |                    |                             |                | 1               | May 3,<br>2021  | SYSTEM        | (\$2,046.78)   |  |              |  |  |
|         |        |  |                    |                             |                |                 |                 | 2             | May 17,<br>2021  | SYSTEM   | \$2,046.78   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |  |
|         |        |  |                    |                             | 2              | May 17,<br>2021 | SYSTEM          | (\$2,046.78)  |  |  |              |  |  |
|         |        |  |                    |                             | 3              | Jun 2,<br>2021  | SYSTEM          | \$2,046.78    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |  |              |  |  |



|         | Line   | Description                             | Adjustment<br>Type | Other<br>Adjustment | Est.<br>Number             | Created<br>Date   | Created<br>By   | Amount   | Remarks   |
|---------|--------|---|--------------------|---------------------|----------------------------|---|---|--|---|
| J4S3328 | 0120   | FURN & PLACE                            | Material           | Туре                | 3                          | Jun 2,  | SYSTEM  | (\$2,046.78)   |   |
| 0400020 | 0120   | BIT. MATL FOR<br>CL B PARTIAL           | iviateriai         |                     | 3                          | 2021  | STOTEM  |  |   |
|         |        |   |                    | - Total             |                            |   |   | \$0.00   |   |
|         |        |   | Material - T       | otal                |                            |   |   | \$0.00   |   |
|         | 0120 - |   |                    |                     |                            |   | 0.40==1.4   | \$0.00   |   |
|         | 0140   | CONSTRUCTION SIGNS                      | Overrun            | Overrun             | 4                          | Jun 16,<br>2021   | SYSTEM  | \$736.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weatho1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  |
|         |        |   |                    |                     | 4                          | Jun 16,<br>2021   | SYSTEM  | (\$736.00)   |   |
|         |        |   |                    | Overrun - T         | otal                       |   |   | \$0.00   |   |
|         |        |   | Overrun - T        | otal                |                            |   |   | \$0.00   |   |
|         | 0140 - | - Total                                 |                    |                     |                            |   |   | \$0.00   |   |
|         | 0170   | CHANNELIZER<br>(TRIM LINE)              | Overrun            | Overrun             | 4                          | Jun 16,<br>2021   | SYSTEM  | \$2,625.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 16 on the current Payment Estimate.  |
|         |        |   |                    |                     | 4                          | Jun 16,<br>2021   | SYSTEM  | (\$2,625.00)   |   |
|         |        |   |                    | Overrun - T         | otal                       |   |   | \$0.00   |   |
|         |        |   | Overrun - T        | otal                |                            |   |   | \$0.00   |   |
|         | 0170 - | - Total                                 |                    |                     |                            |   |   | \$0.00   |   |
|         | 0200   | FLASHING<br>ARROW PANEL                 | Overrun            | Overrun             | 4                          | Jun 16,<br>2021   | SYSTEM  | \$700.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  |
|         |        |   |                    |                     | 4                          | Jun 16,<br>2021   | SYSTEM  | (\$700.00)   |   |
|         |        |   |                    | Overrun - T         | otal                       |   |   | \$0.00   |   |
|         |        |   | Overrun - T        | otal                |                            |   |   | \$0.00   |   |
|         | 0200 - | - Total                                 |                    |                     |                            |   |   | \$0.00   |   |
|         | 0240   |   |                    |                     |                            |   |   | •  |   |
|         | 0240   | PREF THERMO<br>PVMT MARK, 24<br>IN WHIT | Material           |                     | 3                          | Jun 2,<br>2021  | SYSTEM  | \$3,340.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  |
|         | 0240   | PVMT MARK, 24                           | Material           |                     | 3                          |   | SYSTEM<br>SYSTEM  |  | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment   |
|         | 0240   | PVMT MARK, 24                           | Material           |                     |                            | 2021<br>Jun 2,  |   | \$3,340.00   | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment   |
|         | 0240   | PVMT MARK, 24                           | Material           |                     | 3                          | Jun 2,<br>2021<br>Jun 16,   | SYSTEM  | \$3,340.00<br>(\$3,340.00)   | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment   |
|         | 0240   | PVMT MARK, 24                           | Material           |                     | 3                          | Jun 2,<br>2021<br>Jun 16,<br>2021<br>Jun 16,  | SYSTEM SYSTEM   | \$3,340.00<br>(\$3,340.00)<br>\$8,110.00   | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment   |
|         | 0240   | PVMT MARK, 24                           | Material           |                     | 3 4                        | Jun 2,<br>2021<br>Jun 16,<br>2021<br>Jun 16,<br>2021<br>Jun 30,   | SYSTEM SYSTEM   | \$3,340.00<br>(\$3,340.00)<br>\$8,110.00<br>(\$8,110.00)   | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment   |
|         | 0240   | PVMT MARK, 24                           | Material           |                     | 3 4 4 5                    | 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30,   | SYSTEM SYSTEM SYSTEM SYSTEM                             | \$3,340.00<br>(\$3,340.00)<br>\$8,110.00<br>(\$8,110.00)<br>\$8,110.00   | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment   |
|         | 0240   | PVMT MARK, 24                           | Material           |                     | 3 4 4 5 5 5                | 2021<br>Jun 2,<br>2021<br>Jun 16,<br>2021<br>Jun 30,<br>2021<br>Jun 30,<br>2021<br>Jun 30,<br>2021<br>Jun 30, | SYSTEM SYSTEM SYSTEM SYSTEM                             | \$3,340.00<br>(\$3,340.00)<br>\$8,110.00<br>(\$8,110.00)<br>\$8,110.00   | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment   |
|         | 0240   | PVMT MARK, 24                           | Material           |                     | 3<br>4<br>4<br>5<br>5<br>6 | 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jul 16, 2021 Jul 16,                     | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM               | \$3,340.00<br>(\$3,340.00)<br>\$8,110.00<br>(\$8,110.00)<br>\$8,110.00<br>(\$8,110.00)   | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment   |
|         | 0240   | PVMT MARK, 24                           | Material           |                     | 3 4 4 5 5 6 6 6            | 2021 Jun 2, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,                      | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM               | \$3,340.00<br>(\$3,340.00)<br>\$8,110.00<br>(\$8,110.00)<br>\$8,110.00<br>(\$8,110.00)<br>(\$8,110.00)                         | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. |
|         | 0240   | PVMT MARK, 24                           | Material           | - Total             | 3 4 4 5 5 6 6 7 7          | 2021 Jun 2, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,          | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$3,340.00<br>(\$3,340.00)<br>\$8,110.00<br>(\$8,110.00)<br>\$8,110.00<br>(\$8,110.00)<br>(\$8,110.00)<br>\$8,110.00           | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. |
|         | 0240   | PVMT MARK, 24                           | Material - To      |                     | 3 4 4 5 5 6 6 7 7          | 2021 Jun 2, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,          | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$3,340.00<br>(\$3,340.00)<br>\$8,110.00<br>(\$8,110.00)<br>\$8,110.00<br>(\$8,110.00)<br>\$8,110.00<br>(\$8,110.00)           | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. |
|         | 0240   | PVMT MARK, 24<br>IN WHIT                |                    |                     | 3 4 4 5 5 6 6 7 7          | 2021 Jun 2, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,          | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$3,340.00  (\$3,340.00)  \$8,110.00  (\$8,110.00)  \$8,110.00  (\$8,110.00)  \$8,110.00  (\$8,110.00)  \$8,110.00  \$8,110.00 | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. |
|         |        | PVMT MARK, 24<br>IN WHIT                |                    |                     | 3 4 4 5 5 6 6 7 7          | 2021 Jun 2, 2021 Jun 16, 2021 Jun 30, 2021 Jun 30, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,          | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$3,340.00  (\$3,340.00)  \$8,110.00  (\$8,110.00)  \$8,110.00  (\$8,110.00)  \$8,110.00  (\$8,110.00)  \$8,110.00  \$0.00     | Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. |



| Project | Line   | Description                                       | Adjustment<br>Type       | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By  | Amount        | Remarks  |  |         |         |  |                 |        |        |   |
|---------|--------|---|--------------------------|-----------------------------|----------------|-----------------|----------------|---------------|--|--|---------|---------|--|-----------------|--------|--------|---|
| J4S3328 | 0250   | PREF THERMO<br>PVMT MARK, 24<br>IN YELLOW         | Material                 |                             | 5              | Jun 30,<br>2021 | SYSTEM         | \$1,440.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.   |  |         |         |  |                 |        |        |   |
|         |        |   |                          |                             | 5              | Jun 30,<br>2021 | SYSTEM         | (\$1,440.00)  |  |  |         |         |  |                 |        |        |   |
|         |        |   |                          |                             | 6              | Jul 16,<br>2021 | SYSTEM         | \$1,440.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.   |  |         |         |  |                 |        |        |   |
|         |        |   |                          |                             | 6              | Jul 16,<br>2021 | SYSTEM         | (\$1,440.00)  |  |  |         |         |  |                 |        |        |   |
|         |        |   |                          |                             | 7              | Aug 2,<br>2021  | SYSTEM         | \$1,440.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.   |  |         |         |  |                 |        |        |   |
|         |        |   |                          |                             | 7              | Aug 2,<br>2021  | SYSTEM         | (\$1,440.00)  |  |  |         |         |  |                 |        |        |   |
|         |        |   |                          | - Total                     |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         |        |   | Material - To            |                             |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         | 0250 - | Total   | material 1               | , tui                       |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         |        |   |                          |                             |                | 1 40            | 0)/07514       |               | Title of the state |  |         |         |  |                 |        |        |   |
|         | 0260   | PREF THERMO<br>PVMT MARK,<br>LT/RT ARROW          | Material                 |                             | 4              | Jun 16,<br>2021 | SYSTEM         | \$2,800.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.   |  |         |         |  |                 |        |        |   |
|         |        |   |                          |                             | 4              | Jun 16,<br>2021 | SYSTEM         | (\$2,800.00)  |  |  |         |         |  |                 |        |        |   |
|         |        |   |                          | - Total                     |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         |        |   | Material - To            | otal                        |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         | 0260 - | Total   |                          |                             |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         | 0270   | PREF THERMO<br>PVMT MARK,<br>30" WHT MIDBL        |                          | Material                    |                | 3               | Jun 2,<br>2021 | SYSTEM        | \$12,420.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |         |         |  |                 |        |        |   |
|         |        |   |                          |                             | 3              | Jun 2,<br>2021  | SYSTEM         | (\$12,420.00) |  |  |         |         |  |                 |        |        |   |
|         |        |   |                          |                             | 4              | Jun 16,<br>2021 | SYSTEM         | \$19,890.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.   |  |         |         |  |                 |        |        |   |
|         |        |   |                          |                             | 4              | Jun 16,<br>2021 | SYSTEM         | (\$19,890.00) |  |  |         |         |  |                 |        |        |   |
|         |        |   |                          | - Total                     |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         |        |   | Material - To            | otal                        |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         | 0270 - | Total   |                          |                             |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         | 0280   | 12 IN. WHITE<br>HIGH BUILD<br>WATERBORNE<br>PAINT | Material                 |                             | 4              | Jun 16,<br>2021 | SYSTEM         | \$497.00      | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user weathc1 overridding Payment Estimate Exception 9 on the current Payment Estimate.   |  |         |         |  |                 |        |        |   |
|         |        |   |                          |                             | 4              | Jun 16,<br>2021 | SYSTEM         | (\$497.00)    |  |  |         |         |  |                 |        |        |   |
|         |        |   |                          | - Total                     |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         |        |   | Material - To            | otal                        |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         | 0280 - | Total   |                          |                             |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         | 0290   | 4 IN. WHITE<br>WATERBORNE<br>PAVEMENT             | Material                 |                             | 4              | Jun 16,<br>2021 | SYSTEM         | \$8,963.46    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  |  |         |         |  |                 |        |        |   |
|         |        | MARKING   |                          |                             | 4              | Jun 16,<br>2021 | SYSTEM         | (\$8,963.46)  |  |  |         |         |  |                 |        |        |   |
|         |        |   |                          | - Total                     |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         |        |   | Material - To            |                             |                |                 |                | \$0.00        |  |  |         |         |  |                 |        |        |   |
|         |        |   | Other Item<br>Adjustment | REFL                        | 8              | Aug 16,<br>2021 | weathc1        | \$409.61      | Adjustment based on the retro-reflectivity adjustment spreadsheet that was calculated for this line item.  |  |         |         |  |                 |        |        |   |
|         |        |   |                          | REFL - Tota                 | ı              |                 |                | \$409.61      |  |  |         |         |  |                 |        |        |   |
|         |        |   | Other Item               | Adjustment -                | Total          |                 |                | \$409.61      |  |  |         |         |  |                 |        |        |   |
|         |        |   |                          |                             |                |                 |                |               |  |  | Overrun | Overrun |  | Jun 16,<br>2021 | SYSTEM | \$9.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 18 on the current Payment Estimate. Material Insufficiency Quantity 49797.000; Overrun Quantity Balance 50.00. |
|         |        |   |                          |                             |                |                 |                |               | * **   |  |         |         |  |                 |        |        |   |



| Project | Line   | Description  | Adjustment<br>Type       | Other<br>Adjustment<br>Type | Est.<br>Number  | Created<br>Date | Created<br>By  | Amount         | Remarks   |  |  |  |
|---------|--------|--|--------------------------|-----------------------------|-----------------|-----------------|----------------|----------------|---|--|--|--|
| J4S3328 | 0290   | 0 4 IN. WHITE<br>WATERBORNE<br>PAVEMENT<br>MARKING | Overrun                  | Overrun                     | 4               | Jun 16,<br>2021 | SYSTEM         | (\$9.00)       |   |  |  |  |
|         |        |  |                          |                             | 5               | Jun 30,<br>2021 | SYSTEM         | (\$9.00)       | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).   |  |  |  |
|         |        |  |                          |                             | 5               | Jun 30,<br>2021 | SYSTEM         | \$9.00         | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate.   |  |  |  |
|         |        |  |                          |                             | 6               | Jul 16,<br>2021 | SYSTEM         | (\$9.00)       | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).   |  |  |  |
|         |        |  |                          |                             | 6               | Jul 16,<br>2021 | SYSTEM         | \$9.00         | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.   |  |  |  |
|         |        |  |                          |                             | 7               | Aug 2,<br>2021  | SYSTEM         | (\$9.00)       | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).   |  |  |  |
|         |        |  |                          |                             | 7               | Aug 2,<br>2021  | SYSTEM         | \$9.00         | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.   |  |  |  |
|         |        |  |                          |                             | 8               | Aug 16,<br>2021 | SYSTEM         | (\$9.00)       | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).   |  |  |  |
|         |        |  |                          |                             | 8               | Aug 16,<br>2021 | SYSTEM         | \$9.00         | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.   |  |  |  |
|         |        |  |                          | Overrun - T                 | Overrun - Total |                 |                | \$0.00         |   |  |  |  |
|         |        |  | Overrun - T              | otal                        |                 |                 |                | \$0.00         |   |  |  |  |
|         | 0290 - | Total  |                          |                             |                 |                 |                | \$409.61       |   |  |  |  |
|         | 0300   | 4 IN. YELLOW<br>WATERBORNE<br>PAVEMENT<br>MARKING  | Material                 |                             | 4               | Jun 16,<br>2021 | SYSTEM         | \$8,132.76     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |  |  |  |
|         |        | WARRING  |                          |                             | 4               | Jun 16,<br>2021 | SYSTEM         | (\$8,132.76)   |   |  |  |  |
|         |        |  |                          | - Total                     |                 |                 |                | \$0.00         |   |  |  |  |
|         |        |  | Material - To            | otal                        |                 |                 |                | \$0.00         |   |  |  |  |
|         |        |  | Other Item<br>Adjustment | REFL                        | 8               | Aug 16,<br>2021 | weathc1        | \$275.46       | Adjustment based on the retro-reflectivity adjustment spreadsheet that was calculated for this line item.   |  |  |  |
|         |        |  |                          | REFL - Tota                 |                 |                 |                |                |   |  |  |  |
|         |        |  | Other Item /             | Adjustment -                | Total           |                 |                | \$275.46       |   |  |  |  |
|         | 0300 - | Total  |                          |                             |                 |                 |                | \$275.46       |   |  |  |  |
|         | 0330   | MGS<br>GUARDRAIL, 8<br>FT. POSTS, 6 FT.<br>- 3 IN  | Material                 | Material                    |                 | 3               | Jun 2,<br>2021 | SYSTEM         | \$22,575.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |  |  |
|         |        | 0  |                          |                             | 3               | Jun 2,<br>2021  | SYSTEM         | (\$22,575.00)  |   |  |  |  |
|         |        |  |                          |                             | 4               | Jun 16,<br>2021 | SYSTEM         | \$22,575.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  |  |  |  |
|         |        |  |                          |                             | 4               | Jun 16,<br>2021 | SYSTEM         | (\$22,575.00)  |   |  |  |  |
|         |        |  |                          |                             | 5               | Jun 30,<br>2021 | SYSTEM         | \$22,575.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  |  |  |  |
|         |        |  |                          |                             |                 |                 |                | 5              | Jun 30,<br>2021   | SYSTEM   | (\$22,575.00)  |  |
|         |        |  |                          |                             |                 |                 |                | 6              | Jul 16,<br>2021   | SYSTEM   | \$22,575.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
|         |        |  |                          |                             |                 |                 |                | 6              | 6   | Jul 16,<br>2021  | SYSTEM   | (\$22,575.00)  |
|         |        |  |                          |                             |                 |                 | 7              | Aug 2,<br>2021 | SYSTEM  | \$22,575.00  | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |  |
|         |        |  |                          |                             | 7               | Aug 2,<br>2021  | SYSTEM         | (\$22,575.00)  |   |  |  |  |
|         |        |  |                          |                             | 8               | Aug 16,<br>2021 | SYSTEM         | \$22,575.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user weathc1 overridding Payment  |  |  |  |





| Project   | Line   | Description                                   | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks  |
|-----------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J4S3328   | 0330   | MGS<br>GUARDRAIL. 8                           | Material           |                             |                |                 |               |               | Estimate Exception 1 on the current Payment Estimate.  |
|           |        | FT. POSTS, 6 FT.                              |                    |                             | 8              | Aug 16,<br>2021 | SYSTEM        | (\$22,575.00) |  |
|           |        |   |                    | - Total                     |                |                 |               | \$0.00        |  |
|           |        |   | Material - To      | otal                        |                |                 |               | \$0.00        |  |
|           | 0330 - | Total   |                    |                             |                |                 |               | \$0.00        |  |
|           | 0340   | BRIDGE<br>ANCHOR<br>SECTION, 7.5              | Material           |                             | 3              | Jun 2,<br>2021  | SYSTEM        | \$7,480.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user weathc1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
|           |        | FT. POSTS                                     |                    |                             | 3              | Jun 2,<br>2021  | SYSTEM        | (\$7,480.00)  |  |
|           |        |   |                    | - Total                     |                |                 |               | \$0.00        |  |
|           |        |   | Material - To      | otal                        |                |                 |               | \$0.00        |  |
|           | 0340 - | Total   |                    |                             |                |                 |               | \$0.00        |  |
|           | 0360   | TRUCK OR<br>TRAILER<br>MOUNTED<br>ATTEN (TMA) | Material           |                             | 3              | Jun 2,<br>2021  | SYSTEM        | \$1,000.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user weathc1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
|           |        |   |                    |                             | 3              | Jun 2,<br>2021  | SYSTEM        | (\$1,000.00)  |  |
|           |        |   |                    | - Total                     |                |                 |               | \$0.00        |  |
|           |        |   | Material - To      | otal                        |                |                 |               | \$0.00        |  |
|           | 0360 - | Total   |                    |                             |                |                 |               | \$0.00        |  |
|           | 0370   | CABLE, LOOP<br>DETECTOR, IN<br>DUCT           | Material           |                             | 6              | Jul 16,<br>2021 | SYSTEM        | \$9,114.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
|           |        |   |                    |                             | 6              | Jul 16,<br>2021 | SYSTEM        | (\$9,114.00)  |  |
|           |        |   |                    |                             | 7              | Aug 2,<br>2021  | SYSTEM        | \$9,114.00    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
|           |        |   |                    |                             | 7              | Aug 2,<br>2021  | SYSTEM        | (\$9,114.00)  |  |
|           |        |   |                    | - Total                     |                |                 |               | \$0.00        |  |
|           |        |   | Material - To      | otal                        |                |                 |               | \$0.00        |  |
|           | 0370 - | Total   |                    |                             |                |                 |               | \$0.00        |  |
| I4S3328 - | Total  |   |                    |                             |                |                 |               | \$685.07      |  |
| Overall - | Total  |   |                    |                             |                |                 |               | \$685.07      |  |