

Pay Estimate Created Date: August 2, 2021

Progress Estimate N 3	umber	Contract ID Prime Contractor	201120-H03 Joe's Bridge & G	rading, Inc.	Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$349,628.84 \$864.00 \$350,492.84
Approval Date								By User
August 2, 2021			Generated and A	pproved (a	nd should be consid	lered Draft) at th	ne Project Office Level by	smithl5
August 2, 2021		Re	viewed and Approv	ved (and sh	ould be considered	Draft) at the Re	sident Engineer Level by	wilkem1
August 3, 2021			F	Reviewed ar	nd Approved at the	Central Office C	controllers Office Level by	ramses1
Original Completion	n Date	Current Com	pletion Date	Actua	I Completion Date	% o	f Current Contract Amount	Complete
December 1, 202	21	Decembe	er 1, 2021				81.29%	
	Contrac	t Informational Dat	tes		Milesto	nes		
Date Description	Origina	I Completion Date	Current Comple	tion Date	No Milestones Exi	st for Contract		
Acceptance Date								
Awarded Date	Decemb	er 2, 2020	December 2, 202	:0				
Letting Date	Novemb	er 20, 2020	November 20, 20	20				
Notice to Proceed Date	January	4, 2021	January 4, 2021					
Work Began Date								

Contract Total Pay For Es	timate No. 3				
		This Estimate	Previous	To Date	
201120-H03					
Tot	al Posted Items Pay	\$51,625.00	\$233,303.40	\$284,928.40	
Gro	oss Item Adjustments	\$0.00	\$0.00	\$0.00	
Ince	entive	\$0.00	\$0.00	\$0.00	
Dis	incentive	\$0.00	\$0.00	\$0.00	
Liqu	uidated Damage	\$0.00	\$0.00	\$0.00	
Oth	ner Contract Adjustments	\$0.00	\$0.00	\$0.00	
			<mark>\$233,303.40</mark>	\$284,928.40	
Contract Total Payable Th	is Estimate:	\$51,625.00			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3368	0170	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$3,000.000	0.5	\$1,500.00
	0290	7034212	SLAB ON STEEL	SQYD	\$400.000	85	\$34,000.00
	0300	7034216	TYPE H BARRIER	LF	\$125.000	129	\$16,125.00
Project J9S33	68 - Total						\$51,625.00
Overall - Total							\$51,625.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3368	0290	SLAB ON STEEL	Material			-189	\$400.00	(\$75,600.00)
	0290	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user smithl5 overridding Payment Estimate Exception 1 on the current Payment Estimate.	189	\$400.00	\$75,600.00
	0300	TYPE H BARRIER	Material			-129	\$125.00	(\$16,125.00)
	0300	TYPE H BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user smithl5 overridding Payment Estimate Exception 8 on the current Payment Estimate.	129	\$125.00	\$16,125.00



Pay Estimate Created Date: August 2, 2021

Progre	ess Est	imate Number 3	Contract ID Prime Contra	20112(actor Joe's E		ing, Inc. Pay Period End August 1, 2021 Net	ginal Contrac Change Ord rent Contrac	er Amount	\$349,628.84 \$864.00 \$350,492.84
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3368	0310	SUBSTRUCT	URE REPAIR (FORMED)	Material			-20	\$50.00	(\$1,000.00)
	0310	SUBSTRUCT	URE REPAIR (FORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user smithl5 overridding Payment Estimate Exception 11 on the current Payment Estimate.	20	\$50.00	\$1,000.00
Total									\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informat	ion
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9S3368	FAS S702(68)	Bridge rehabilitation	ZZ	DUNKLIN	over north Deering Draina	age Ditch	
Totals by J	Job Numbe	ərs					
J9S3368		ed Item Pay s Item Adjustm		Item Pay	This Estimate \$51,625.00 \$0.00 \$51,625.00	Previous \$233,303.40 \$0.00 \$233,303.40	To Date \$284,928.40 \$0.00 \$284,928.40
	Liquid	tive centive dated Damages · Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3368, Item 7034212, Project Item Line Number 0290, Material Set 703421296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Material tests are still pending for the bridge deck placed on 7/16/21. smithl5	smithl5	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3368, Item 7034212, Project Item Line Number 0290, Material Set 703421296, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Material tests are still pending for the bridge deck placed on 7/16/21. smithl5	smithl5	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3368, Item 7034212, Project Item Line Number 0290, Material Set 703421296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Material tests are still pending for the bridge deck placed on 7/16/21. smithl5	smithl5	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3368, Item 7034212, Project Item Line Number 0290, Material Set 703421296, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Material tests are still pending for the bridge deck placed on 7/16/21. smithl5	smithl5	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3368, Item 7034212, Project Item Line Number 0290, Material Set 703421296, Material 3703SIPF - Stay in Place Forms, Acceptance Action Generic 3703SIPF is insufficient.	Material tests are still pending for the bridge deck placed on 7/16/21. smithl5	smithl5	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3368, Item 7034212, Project Item Line Number 0290, Material Set 703421296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Material tests are still pending for the bridge deck placed on 7/16/21. smithl5	smithl5	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3368, Item 7034212, Project Item Line Number 0290, Material Set 703421296, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Material tests are still pending for the bridge deck placed on 7/16/21. smithl5	smithl5	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3368, Item 7034216, Project Item Line Number 0300, Material Set 7034216, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Material tests are still pending for the barrier curb placed on 7/26/21. smithl5	smithl5	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3368, Item 7034216, Project Item Line Number 0300, Material Set 7034216, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Material tests are still pending for the barrier curb placed on 7/26/21. smithl5	smithl5	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3368, Item 7034216, Project Item Line Number 0300, Material Set 7034216, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Material tests are still pending for the barrier curb placed on 7/26/21. smithl5	smithl5	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3368, Item 7040101, Project Item Line Number 0310, Material Set 704010196, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Material tests are still pending for the cap substructure(cap) repair. smithl5	smithl5	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3368, Item 7040101, Project Item Line Number 0310, Material Set 704010196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Material test are still pending for the substructure (cap) repair. smithl5	smithl5	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201120-H03	J9S3368	0001	0010	2064000	POROUS BACKFILL	36.00	0.00	36.00	CUYD	0.00	\$80.00	\$0.00
		0001	0020	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	1.70	0.00	1.70	STA	0.00	\$2,700.00	\$0.00
		0001	0030	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	245.00	0.00	245.00	SQYD	0.00	\$16.00	\$0.00
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	9.00	0.00	9.00	TONS	0.00	\$35.00	\$0.00
		0001	0050	4019905	MISC.OPTIONAL PAVEMENT	244.50	0.00	244.50	SQYD	0.00	\$79.12	\$0.00
		0001	0060	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	125.00	0.00	125.00	CUYD	97.10	\$26.00	\$2,524.60
		0001	0070	6096042	PLACING TYPE 2 ROCK DITCH LINER	125.00	0.00	125.00	CUYD	97.10	\$26.00	\$2,524.60
		0001	0080	6113020	FURNISHING TYPE 2 ROCK BLANKET	226.00	0.00	226.00	CUYD	226.00	\$20.00	\$4,520.00
		0001	0090	6113040	PLACING TYPE 2 ROCK BLANKET	226.00	0.00	226.00	CUYD	226.00	\$38.00	\$8,588.00
		0001	0100	6161005	CONSTRUCTION SIGNS	141.00	0.00	141.00	SQFT	141.00	\$9.00	\$1,269.00
		0001	0110	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	2.00	\$65.00	\$130.00
		0001	0120	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$20.00	\$0.00
		0001	0130	6161030	TYPE III MOVEABLE BARRICADE	4.00	0.00	4.00	EA	4.00	\$125.00	\$500.00
		0001	0140	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	6.00	0.00	6.00	EA	6.00	\$150.00	\$900.00
		0001	0150	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$60,000.00	\$60,000.00
		0001	0160	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	725.00	0.00	725.00	SQYD	627.40	\$3.00	\$1,882.20
		0001	0170	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$3,000.00	\$1,500.00
		0001	0180	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.00	\$4,200.00	\$0.00
		0001	0190	8061005	ROCK DITCH CHECK	54.00	0.00	54.00	LF	0.00	\$25.00	\$0.00
		0001	0200	8061016	SEDIMENT REMOVAL	7.00	0.00	7.00	CUYD	0.00	\$10.00	\$0.00
		0001	0210	8061017	TEMPORARY SEEDING AND MULCHING	1.00	0.00	1.00	ACRE	0.00	\$200.00	\$0.0
		0001	0220	8061019	SILT FENCE	210.00	0.00	210.00	LF	0.00	\$6.00	\$0.0
		0001	0230	8061050	TYPE C BERM	160.00	0.00	160.00	LF	0.00	\$5.00	\$0.0
		0040	0240	9031270A	2 IN. PSST POST - 12 GA.	48.00	0.00	48.00	LF	0.00	\$7.00	\$0.0
		0040	0250	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	36.00	0.00	36.00	LF	0.00	\$12.00	\$0.0
		0040	0260	9035069A	SHF-FLAT SHEET FLUORESCENT	36.00	0.00	36.00	SQFT	0.00	\$18.00	\$0.0
		0070	0270	2169901	MISC.Removal of Existing Superstructure	1.00	0.00	1.00	LS	1.00	\$25,000.00	\$25,000.0
		0070	0280	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	109.00	0.00	109.00	SQYD	0.00	\$145.00	\$0.0
		0070	0290	7034212	SLAB ON STEEL	189.00	0.00	189.00	SQYD	189.00	\$400.00	\$75,600.0
		0070	0300	7034216	TYPE H BARRIER	129.00	0.00	129.00	LF	129.00	\$125.00	\$16,125.0
		0070	0310	7040101	SUBSTRUCTURE REPAIR (FORMED)	20.00	0.00	20.00	SQFT	20.00	\$50.00	\$1,000.0
		0070	0320	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$6,000.00	\$0.0
		0070	0330	7121111	FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709, GRADE 50	21,130.00	0.00	21,130.00	LB	21,130.00	\$2.70	\$57,051.0
		0070	0340	7123610	SLAB DRAIN	12.00	0.00	12.00	EA	12.00	\$300.00	\$3,600.0
		0070	0350	7129901	MISC.Galvanizing Structural Steel	1.00	0.00	1.00	LS	1.00	\$11,750.00	\$11,750.0
		0070	0360	7161000	PLAIN NEOPRENE BEARING PAD	4.00	0.00	4.00	EA	4.00	\$300.00	\$1,200.0
		0070	0370	7161002	LAMINATED NEOPRENE BEARING PAD	4.00	0.00	4.00	EA	4.00	\$300.00	\$1,200.0
		0070	0380	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$900.00	\$7,200.0
		0070	5001	7169901	MISC.Galvanizing (8) Bearing Pad & Bolt Assemblies	0.00	1.00	1.00	LS	1.00	\$864.00	\$864.0
	Project J	9S336 <u>8 - To</u>	otal Value	e Posted to D	Date as of Report Generated Date							\$284,928.4
01120-H03 Ove	rall - Total	Value Post	ted to Da	te as of Rep	ort Generated Date							\$284,928.40



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	J9S3368	8									
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location From Station Log Mile	n/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0170	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	7/30/21	8/2/21	0.50	LS	Sta 158+74		Sta 160+78		50% of Plan Qty
0290	7034212	SLAB ON STEEL	7/16/21	7/22/21	75.60	SQYD	Sta 159+44			Rt & Lt of C/L / 13.3	40 % of plan for Deck Placement .
			7/30/21	8/2/21	9.40	SQYD	Sta 159+44		Sta 160+08		Remaining 5% for stripping and sealing deck.
0300	7034216	TYPE H BARRIER	7/26/21	8/2/21	129.00	LF	Sta 159+44			Rt & Lt of C/L / 12'	Barrier Curb

The information below this line are details for Construction Signs (if applicable), No Data Available



Line Item Adjustments by Estimate

Aug 4, 2021

Contract ID:190621-F01

ect									
	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
				Туре					
368	0060	FURN. TYPE 2 ROCK DITCH LINER	Material		1	Jul 2, 2021	SYSTEM	\$2,524.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user smithl5 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jul 2, 2021	SYSTEM	(\$2,524.60)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0060 -	Total						\$0.00	
	0080	FURNISHING TYPE 2 ROCK BLANKET	Material		1	Jul 2, 2021	SYSTEM	\$4,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user smithl5 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Jul 2, 2021	SYSTEM	(\$4,520.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	- 0800	Total						\$0.00	
	0100	CONSTRUCTION SIGNS	Material		1	Jul 2, 2021	SYSTEM	\$1,269.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user smithl5 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jul 2, 2021	SYSTEM	(\$1,269.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0100 -	Total						\$0.00	
	0110	ADVANCED WARNING RAIL SYSTEM	Material		1	Jul 2, 2021	SYSTEM	\$130.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user smithl5 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Jul 2, 2021	SYSTEM	(\$130.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0110 -	Total						\$0.00	
	0130		Material		1	Jul 2,	SYSTEM	\$500.00	
		30 TYPE III MOVEABLE BARRICADE				2021		<i>\\</i>	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user smithl5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					1	2021 Jul 2, 2021	SYSTEM	(\$500.00)	Estimate Item Adjustment (0009) due to user smithI5 overridding Payment
				- Total	1	Jul 2,	SYSTEM		Estimate Item Adjustment (0009) due to user smithI5 overridding Payment
			Material - T		1	Jul 2,	SYSTEM	(\$500.00)	Estimate Item Adjustment (0009) due to user smithl5 overridding Payment
	0130 -	BARRICADE	Material - T		1	Jul 2,	SYSTEM	(\$500.00) \$0.00	Estimate Item Adjustment (0009) due to user smithl5 overridding Payment
	0130 - 0290	BARRICADE			2	Jul 2,	SYSTEM	(\$500.00) \$0.00 \$0.00	Estimate Item Adjustment (0009) due to user smithl5 overridding Payment
- 1		BARRICADE				Jul 2, 2021 Jul 16,		(\$500.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0009) due to user smithl5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		BARRICADE			2	Jul 2, 2021 Jul 16, 2021 Jul 16,	SYSTEM	(\$500.00) \$0.00 \$0.00 \$41,600.00	Estimate Item Adjustment (0009) due to user smithl5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		BARRICADE		otal	2	Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM	(\$500.00) \$0.00 \$0.00 \$41,600.00 (\$41,600.00) \$75,600.00 (\$75,600.00)	Estimate Item Adjustment (0009) due to user smithl5 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user smithl5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user smithl5 overridding Payment Estimate Item Adjustment (0001) due to user smithl5 overridding Payment
- 5		BARRICADE	Material	otal - Total	2 2 3	Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM	(\$500.00) \$0.00 \$0.00 \$41,600.00 (\$41,600.00) \$75,600.00 (\$75,600.00	Estimate Item Adjustment (0009) due to user smithl5 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user smithl5 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user smithl5 overridding Payment Estimate Item Adjustment (0001) due to user smithl5 overridding Payment
	0290	BARRICADE Total SLAB ON STEEL		otal - Total	2 2 3	Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM	(\$500.00) \$0.00 \$0.00 \$41,600.00 (\$41,600.00) \$75,600.00 (\$75,600.00) \$0.00	Estimate Item Adjustment (0009) due to user smithl5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		BARRICADE Total SLAB ON STEEL	Material	otal - Total	2 2 3	Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM	(\$500.00) \$0.00 \$0.00 \$41,600.00 (\$41,600.00) \$75,600.00 (\$75,600.00	Estimate Item Adjustment (0009) due to user smithl5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	0290	BARRICADE Total Total	Material	otal - Total	2 2 3	Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM	(\$500.00) \$0.00 \$0.00 \$41,600.00 (\$41,600.00) \$75,600.00 (\$75,600.00) \$0.00	Estimate Item Adjustment (0009) due to user smithl5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	0290	BARRICADE Total Total Total	Material Material - T	otal - Total	2 2 3 3	Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$500.00) \$0.00 \$41,600.00 (\$41,600.00) \$75,600.00 (\$75,600.00) (\$75,600.00 \$0.00	Estimate Item Adjustment (0009) due to user smithl5 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	0290	BARRICADE Total Total Total	Material Material - T	otal - Total	2 2 3 3 3 3	2021 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$500.00) \$0.00 \$0.00 \$41,600.00 (\$41,600.00) \$75,600.00 (\$75,600.00 \$0.00 \$0.00 \$0.00 \$16,125.00	Estimate Item Adjustment (0009) due to user smithI5 overridding Payment Estimate Exception 5 on the current Payment Estimate.



Line Item Adjustments by Estimate

Aug 4, 2021

Contract ID:190621-F01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J9S3368	0300 -	Total						\$0.00						
	0310	SUBSTRUCTURE REPAIR (FORMED)	Material		1	Jul 2, 2021	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user smithI5 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					1	Jul 2, 2021	SYSTEM	(\$1,000.00)						
							2	Jul 16, 2021	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user smithI5 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					2	Jul 16, 2021	SYSTEM	(\$1,000.00)						
					3	Aug 2, 2021	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user smithI5 overridding Payment Estimate Exception 11 on the current Payment Estimate.					
					3	Aug 2, 2021	SYSTEM	(\$1,000.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0310 -	Total						\$0.00						
	0360	360 PLAIN NEOPRENE BEARING PAD	Material		1	Jul 2, 2021	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user smithl5 overridding Payment Estimate Exception 9 on the current Payment Estimate.					
											1	Jul 2, 2021	SYSTEM	(\$1,200.00)
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0360 -	Total						\$0.00						
	0370	LAMINATED NEOPRENE BEARING PAD	Material		1	Jul 2, 2021	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user smithI5 overridding Payment Estimate Exception 10 on the current Payment Estimate.					
					1	Jul 2, 2021	SYSTEM	(\$1,200.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0370 -	Total						\$0.00						
	0380	LAMINATED NEOPRENE BEARING PAD	Material		1	Jul 2, 2021	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user smithI5 overridding Payment Estimate Exception 11 on the current Payment Estimate.					
	ASSEMBLY	ASSEMBLY			1 Jul 2, 2021		SYSTEM	(\$7,200.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0380 -	Total						\$0.00						
J9S3368 -	- Total							\$0.00						