

# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2021

Progress Estimate Number	Contract ID	201218-B02	Pay Period Start	September 16, 2021	Original Contract Amount	\$2,014,127.80
6	Prime Contractor	Mid-River Asphalt, Inc.	Pay Period End		Net Change Order Amount	
•					Current Contract Amount	\$2,013,927.79

By User		Approval Date
haggaj1	Generated and Approved (and should be considered Draft) at the Project Office Level by	October 1, 2021
baxtem1	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	October 3, 2021
ramses1	Reviewed and Approved at the Central Office Controllers Office Level by	October 4, 2021

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete				
November 1, 2021	November 1, 2021		95.62%				

### Contract Informational Dates

Date Description	Original Completion Date	Current Completion Date				
Acceptance Date						
Awarded Date	January 6, 2021	January 6, 2021				
Letting Date	December 18, 2020	December 18, 2020				
Notice to Proceed Date	March 8, 2021	March 8, 2021				
Work Began Date						

Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
Milestone - Calendar Time - JSP B - Calendar Days, J2P3201	August 19, 2021	August 19, 2021	Milestone Complete	
Milestone - Calendar Time - JSP B - Calendar Days, J2S3189	August 24, 2021	August 24, 2021	Milestone Complete	
Milestone - Calendar Time - JSP B - Calendar Days, J2S3308	August 25, 2021	August 25, 2021	Milestone Complete	

Milestones

### Contract Total Pay For Estimate No. 6 This Estimate Previous To Date 201218-B02 \$66,275.98 \$22,093.53 \$0.00 \$0.00 Total Posted Items Pay \$1,859,487.09 \$1,925,763.07 Gross Item Adjustments \$90,615.85 \$112,709.38 Incentive \$0.00 \$0.00 \$0.00 Disincentive \$0.00 \$0.00 \$0.00 Liquidated Damage \$0.00 Other Contract Adjustments \$0.00 \$0.00 \$0.00 \$1,950,102.94 \$2,038,472.45 **Contract Total Payable This Estimate:** \$88,369.51

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
J2P3201	0110	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$10.000	48	\$480.00			
	0120	6209903	MISC.6" WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$5.000	48	\$240.00			
Project J2F	23201 - Tot	al					\$720.00			
J2S3303	0330	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	TONS	\$11.520	4,344.66	\$50,050.48			
	0410	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$25.000	30	\$750.00			
	0420	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$350.000	1	\$350.00			
	0430	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.100	100,912	\$10,091.20			
	0440	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.100	43,143	\$4,314.30			
Project J2S	Project J2S3303 - Total									
Overall - To	Overall - Total									

### **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract

Revision 4/1/2020 Page 1 of 16



### **Missouri Department of Transportation Contractor's Pay Estimate Summary**

Pay Estimate Created Date: October 1, 2021

**Progress Estimate Number** 

Contract ID201218-B02Pay Period StartSeptember 16, 2021Original Contract Amount\$2,014,127.80Prime ContractorMid-River Asphalt, Inc.Pay Period EndSeptember 30, 2021Net Change Order Amount\$2,013,927.79Current Contract Amount\$2,013,927.79

ine item	Aujusti	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2P3201	0090	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Other	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount			\$8,700.00
	0100	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Other	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount			\$4,700.00
	0110	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-48	\$10.00	(\$480.00)
	0110			48	\$10.00	\$480.00		
J2S3189	0200	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Other	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount			\$2,700.00
	0210	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Other	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount			\$2,100.00
J2S3238	0220	GRAVEL (A) OR CRUSHED STONE (B)	Material			-190.34	\$34.00	(\$6,471.56)
	0220	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user haggaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	190.34	\$34.00	\$6,471.56
	0240	TACK COAT	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-179	\$1.93	(\$345.47)
J2S3303	0330	MISC.	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 6102.190; Overrun Quantity Balance 528.39.	528.39	\$11.52	\$6,087.05
	0330	MISC.	Overrun			-528.39	\$11.52	(\$6,087.05)
	0330	MISC.	Material			-6,102.19	\$11.52	(\$70,297.23)
	0330	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	6,102.19	\$11.52	\$70,297.23
	0410	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-30	\$25.00	(\$750.00)
	0410	PREFORMED THERMOPLASTIC	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	30	\$25.00	\$750.00

Revision 4/1/2020 Page 2 of 16



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2021

Progress Estimate Number

6

Contract ID 201218-B02 Pay Period Start September 16, 2021 Original Contract Amount \$2,014,127.80
Prime Contractor Mid-River Asphalt, Inc. Pay Period End September 30, 2021 Net Change Order Amount (\$200.01)
Current Contract Amount \$2,013,927.79

Number   No.   PAVEMENT MARKING, 24   IN. WHITE   Material Type   Adjustment (0005) due to user haggail overridding Payment Estimate Exception 3 on the current Payment Estimate.   -1   \$350.00									, ,
IN. WHITE			Item Description	,	Adjustment	Comments		Adjustment	Adjustment amount
THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW  0420 PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW  0430 A IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0440 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0560 6 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0570 6 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0580 6 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0580 6 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0580 6 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0580 6 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0590 7 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0590 8 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0510 9 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0510 9 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0510 9 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0510 9 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0510 9 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT MARKING PAINT MARKING PAINT MARKING PAINT MARKING	J2S3303		,			overridding Payment Estimate Exception 3 on			
THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW  Other Item Adjustment is to withhold 40% of posted quantity, pending retroreflectivity testing, and will be released upon acceptance for retroreflectivity.  Other Item Adjustment is to withhold 40% of posted quantity, pending retroreflectivity testing, and will be released upon acceptance for retroreflectivity.  Other Marking Paint, Type p BEADS  Other Item Adjustment is to withhold 40% of posted quantity, pending retroreflectivity testing, and will be released upon acceptance for retroreflectivity.  Other Marking Paint, Type p BEADS  Other Item Adjustment will be released upon acceptance for retroreflectivity.  Other Alin. White Standard will be released upon acceptance for retroreflectivity.  Other Adjustment is to withhold 40% of posted quantity, pending retroreflectivity testing, and will be released upon acceptance for retroreflectivity.  Other Adjustment will be released upon acceptance for retroreflectivity.  Other Adjustment is to acceptance for retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount.  Other Adjustment withheld amount.  Other Adjustment withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount.		0420	THERMOPLASTIC PAVEMENT MARKING,	Material			-1	\$350.00	(\$350.00
WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0440  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0540  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550  5 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550  6 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  0550  6 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  15 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  16 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  17 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  18 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  18 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  18 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  18 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  18 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS		0420	THERMOPLASTIC PAVEMENT MARKING,	Material		generated Material Payment Estimate Item Adjustment (0006) due to user haggaj1 overridding Payment Estimate Exception 4 on	1	\$350.00	\$350.00
WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment  Other  40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount.  Other  Other  40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount		0430	WATERBORNE PAVEMENT MARKING PAINT, TYPE P		Other	quantity, pending retroreflectivity testing, and will be released upon acceptance for			(\$4,036.00
WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment  Other MARKING PAINT, TYPE P BEADS  Other Item Adjustment  Other MARKING PAINT, TYPE P BEADS  Other Item Adjustment  Other Marking Paint, Type P BEADS  Other Item Adjustment  Other Marking Paint, Type P BEADS		0440	WATERBORNE PAVEMENT MARKING PAINT, TYPE P		Other	quantity, pending retroreflectivity testing, and will be released upon acceptance for			(\$1,725.00
WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  WATERBORNE PAVEMENT Adjustment retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount	J2S3308	0540	WATERBORNE PAVEMENT MARKING PAINT, TYPE P		Other	retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the			\$5,500.00
Total \$22,093		0550	WATERBORNE PAVEMENT MARKING PAINT, TYPE P		Other	retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the			\$4,500.00
	Total								\$22,093.53

Revision 4/1/2020 Page 3 of 16



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J2P3201	FAF-79-1(80)	Seal coat	79	LINCOLN	from Pike County line	to Route N near Winfield					
J2S3189	FAS- S202(017)	Seal coat	EE	LINCOLN	from Route Y to Route	e 47 near Winfield					
J2S3238	FAS S201(65)	Resurface	W	LINCOLN	from Route B to Route	from Route B to Route KK near Brussells					
J2S3303	FAS S201(74)	Resurface	В	LINCOLN	from Route 61 to Rout	from Route 61 to Route 79 at Elsberry					
J2S3308	FAS- S202(018)	Seal coat	Е	LINCOLN	from Route O north ju	nction to Route UU in Silex					
otals by	Job Numbers										
J2P3201	Posted Ite	n Adjustments	s iross Iter	m Pav	This Estimate \$720.00 \$13,400.00 <b>\$14,120.00</b>	Previous \$360,848.02 (\$1,325.78) \$359,522.24	To Date \$361,568.02 \$12,074.22 \$373,642.24				
	Incentive Disincent Liquidate Other Cor			<b>.,</b>	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J2S3189	Posted Ite Gross Iter	n Adjustments	s Gross Iter	m Pay	This Estimate \$0.00 \$4,800.00 <b>\$4,800.00</b>	Previous \$101,690.70 (\$2,054.97) \$99,635.73	<b>To Date</b> \$101,690.70 \$2,745.03 <b>\$104,435.73</b>				
	Liquidate	Incentive Disincentive Liquidated Damages Other Contract Adjustments			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J2S3238		Posted Item Pay Gross Item Adjustments Gross Item Pay			This Estimate \$0.00 (\$345.47) (\$345.47)	Previous \$446,049.20 \$35,836.95 \$481,886.15	To Date \$446,049.20 \$35,491.48 \$481,540.68				
		ive d Damages ntract Adjustm	ents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J2S3303	Posted Ite	n Adjustments	s iross Ite	m Pay	This Estimate \$65,555.98 (\$5,761.00) \$59,794.98	Previous \$748,477.27 \$62,880.92 \$811,358.19	To Date \$814,033.25 \$57,119.92 \$871,153.17				
	Liquidate	Incentive Disincentive Liquidated Damages Other Contract Adjustments			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J2S3308		Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive Disincentive Liquidated Damages Other Contract Adjustments			This Estimate \$0.00 \$10,000.00 <b>\$10,000.00</b>	Previous \$202,421.90 (\$4,721.27) \$197,700.63	<b>To Date</b> \$202,421.90 \$5,278.73 <b>\$207,700.63</b>				
	Disincent Liquidate				\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 4/1/2020 Page 4 of 16



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J2S3303, Item 3049910, Project Item Line Number 0330, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material was inspected and accepted for use on project. AWP Materials reporting could not be completed prior to estimate generation.	haggaj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3303, Item 3049910, Project Item Line Number 0330, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material was QA Sampled and tested and visually inspected. QA Sample did meet specifications for Crushed Stone as placed in the field. JSP's stated that material was to be accepted on certification. Contractor did submit a Certification with a gradation, but certification was rejected due to not having all required information. Material was accepted for use on the project, but AWP Materials reporting could not be completed prior to estimate generation.	haggaj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3238, Item 3105002, Project Item Line Number 0220, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material was inspected and accepted for use on project.  AWP Materials reporting could not be completed prior to estimate generation.	haggaj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3238, Item 3105002, Project Item Line Number 0220, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material was inspected and accepted for use on the project. AWP Materials Reporting could not be completed prior to estimate generation.	haggaj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3303, Item 6200015, Project Item Line Number 0410, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Material was inspected and accepted for use on project. AWP Materials reporting could not be completed prior to estimate generation.	haggaj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3303, Item 6200021, Project Item Line Number 0420, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indicat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Material was inspected and accepted for use on project. AWP Materials reporting could not be completed prior to estimate generation.	haggaj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3201, Item 6206124A, Project Item Line Number 0110, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Material was inspected and accepted for use on the project. AWP Materials Reporting could not be completed prior to estimate generation.	haggaj1	Overridden
Estimate Exception Type: Item Overrun: Contract 201218-B02, Contract Project J2S3303, Project Item Line Number 0330, Contract Line Item Number 0330, Item 3049910, Minor Item.	No Remark was entered by Engineer	haggaj1	Overridden
Estimate Exception Type: Item Overrun: Contract 201218-B02, Contract Project J2S3238, Project Item Line Number 0240, Contract Line Item Number 0240, Item 4071005, Minor Item.	No Remark was entered by Engineer	haggaj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201218-B02, Contract Project J2S3303, Project Item Line Number 0340, Contract Line Item Number 0340, Item 4020520, Minor Item.	No Remark was entered by Engineer	haggaj1	Acknowledged

Revision 4/1/2020 Page 5 of 16



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

tract Project NTRACT No.					arre ar are			s Gener	atou.		
	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
B02 J2P3201	0001	0010	4091048	EMULSIFIED ASPHALT, SEAL COAT	72,828.00	0.00	72,828.00	GAL	72,444.00	\$1.98	\$143,439.12
	0001	0020	4094002	SEAL COAT AGGREGATE, GRADE A2	260,100.00	0.00	260,100.00	SQYD	260,100.00	\$0.68	\$176,868.00
	0001	0030	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.00
	0001	0040	6161005	CONSTRUCTION SIGNS	2,220.00	0.00	2,220.00	SQFT	773.00	\$4.50	\$3,478.50
	0001	0050	6161009	FLAG ASSEMBLY	4.00	-4.00	0.00	EA	0.00	\$10.00	\$0.00
	0001	0060	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$20.00	\$0.00
	0001	0070	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
	0001	0080	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$7,200.00	\$7,200.00
	0001	0090	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	174,008.00	0.00	174,008.00	LF	174,008.00	\$0.10	\$17,400.80
	0001	0100	6206001C	PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	94,616.00	0.00	94,616.00	LF	94,616.00	\$0.10	\$9,461.60
	0001	0110	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	48.00	0.00	48.00	LF	48.00	\$10.00	\$480.00
	0001	0120	6209903	MISC.6" WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	48.00	0.00	48.00	LF	48.00	\$5.00	\$240.00
Project 3	2P3201 - To	tal Value	Posted to D	ate as of Report Generated Date							\$361,568.02
J2S3189	0001	0130	4091048	EMULSIFIED ASPHALT, SEAL COAT	18,962.00	0.00	18,962.00	GAL	18,438.00	\$1.98	\$36,507.24
	0001	0140	4094002	SEAL COAT AGGREGATE, GRADE A2	67,722.00	0.00	67,722.00	SQYD	67,722.00	\$0.68	\$46,050.96
	0001	0150	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.00
	0001	0160	6161005	CONSTRUCTION SIGNS	990.00	0.00	990.00	SQFT	477.00	\$4.50	\$2,146.50
	0001	0170	6161009	FLAG ASSEMBLY	4.00	-4.00	0.00	EA	0.00	\$10.00	\$0.00
	0001	0180	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$1.00	\$0.00
	0001	0190	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$7,200.00	\$7,200.00
	0001	0200	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	55,408.00	0.00	55,408.00	LF	55,408.00	\$0.10	\$5,540.80
	0001	0210	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	42,452.00	0.00	42,452.00	LF	42,452.00	\$0.10	\$4,245.20
				MARKING PAINT, TYPE P BEADS ate as of Report Generated Date							
Project.	2S3189 - To	tal Value	Posted to D								\$101.690.70
Project C	2S3189 - To	otal Value 0220	Posted to D 3105002	GRAVEL (A) OR CRUSHED STONE (B)	518.00	0.00	518.00	TONS	190.34	\$34.00	\$101,690.70 \$6,471.56
				GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	518.00 8,274.80	0.00	518.00 8,274.80	TONS	190.34 7,428.56	\$34.00 \$50.80	
	0001	0220	3105002	GRAVEL (A) OR CRUSHED STONE (B)							\$6,471.56
	0001	0220	3105002 4020520	GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	8,274.80	0.00	8,274.80	TONS	7,428.56	\$50.80	\$6,471.56 \$377,370.85
	0001 0001 0001	0220 0230 0240	3105002 4020520 4071005	GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT	8,274.80 7,574.00	0.00	8,274.80 7,574.00	TONS	7,428.56 7,753.00	\$50.80 \$1.93	\$6,471.56 \$377,370.85 \$14,963.29
	0001 0001 0001 0001	0220 0230 0240 0250	3105002 4020520 4071005 6123000A	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	8,274.80 7,574.00 2.00	0.00	8,274.80 7,574.00 2.00	TONS GAL EA	7,428.56 7,753.00 2.00	\$50.80 \$1.93 \$1.00	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00
	0001 0001 0001 0001 0001	0220 0230 0240 0250 0260	3105002 4020520 4071005 6123000A 6161005	GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS	8,274.80 7,574.00 2.00 1,691.00	0.00 0.00 0.00 0.00	8,274.80 7,574.00 2.00 1,691.00	TONS  GAL  EA  SQFT	7,428.56 7,753.00 2.00 730.00	\$50.80 \$1.93 \$1.00 \$4.50	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00
	0001 0001 0001 0001 0001	0220 0230 0240 0250 0260 0270	3105002 4020520 4071005 6123000A 6161005 6161009	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY	8,274.80 7,574.00 2.00 1,691.00 4.00	0.00 0.00 0.00 0.00 -4.00	8,274.80 7,574.00 2.00 1,691.00	TONS  GAL  EA  SQFT  EA	7,428.56 7,753.00 2.00 730.00 0.00	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00
	0001 0001 0001 0001 0001 0001	0220 0230 0240 0250 0260 0270	3105002 4020520 4071005 6123000A 6161005 6161009 6161025	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE)	8,274.80 7,574.00 2.00 1,691.00 4.00	0.00 0.00 0.00 0.00 -4.00	8,274.80 7,574.00 2.00 1,691.00 0.00	TONS GAL EA SQFT EA EA	7,428.56 7,753.00 2.00 730.00 0.00	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00 \$0.00
	0001 0001 0001 0001 0001 0001 0001	0220 0230 0240 0250 0260 0270 0280	3105002 4020520 4071005 6123000A 6161005 6161009 6161025 6181000 6206000C	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE)  MOBILIZATION  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	8,274.80 7,574.00 2.00 1,691.00 4.00 100.00	0.00 0.00 0.00 0.00 -4.00 0.00	8,274.80 7,574.00 2.00 1,691.00 0.00 100.00 1.00	TONS GAL EA SQFT EA EA LS	7,428.56 7,753.00 2.00 730.00 0.00 0.00	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00
	0001 0001 0001 0001 0001 0001 0001 000	0220 0230 0240 0250 0260 0270 0280 0290	3105002 4020520 4071005 6123000A 6161005 6161009 6161025 6181000 6206000C	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE)  MOBILIZATION  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	8,274.80 7,574.00 2.00 1,691.00 4.00 100.00 1.00 82,262.00	0.00 0.00 0.00 0.00 -4.00 0.00 0.00	8,274.80 7,574.00 2.00 1,691.00 0.00 100.00 1.00 82,262.00	TONS GAL EA SQFT EA LS LF	7,428.56 7,753.00 2.00 730.00 0.00 0.00 1.00 82,262.00	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20
J2S3238	0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	0220 0230 0240 0250 0260 0270 0280 0290 0300 0310	3105002 4020520 4071005 6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE)  MOBILIZATION  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	8,274.80 7,574.00 2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00	0.00 0.00 0.00 0.00 -4.00 0.00 0.00	8,274.80 7,574.00 2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00	TONS GAL EA SQFT EA LS LF	7,428.56 7,753.00 2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30
J2S3238	0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	0220 0230 0240 0250 0260 0270 0280 0290 0300 0310	3105002 4020520 4071005 6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE)  MOBILIZATION  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  MODIFIED COLDMILLING (DEPTH TRANSITIONS)	8,274.80 7,574.00 2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00	0.00 0.00 0.00 0.00 -4.00 0.00 0.00	8,274.80 7,574.00 2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00	TONS GAL EA SQFT EA LS LF	7,428.56 7,753.00 2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$2,712.00
J2S3238	0001 0001 0001 0001 0001 0001 0001 000	0220 0230 0240 0250 0260 0270 0280 0290 0300 0310 0320	3105002 4020520 4071005 6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE)  MOBILIZATION  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  MODIFIED COLDMILLING (DEPTH TRANSITIONS)  ate as of Report Generated Date	8,274.80 7,574.00 2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00 800.00	0.00 0.00 0.00 0.00 -4.00 0.00 0.00 0.00	8,274.80 7,574.00 2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00	TONS GAL EA SQFT EA LS LF LF SQYD	7,428.56 7,753.00 2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 339.00	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$2,712.00
J2S3238	0001 0001 0001 0001 0001 0001 0001 000	0220 0230 0240 0250 0260 0270 0280 0290 0300 0310 0320 0310 0320	3105002 4020520 4071005 6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE)  MOBILIZATION  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  MODIFIED COLDMILLING (DEPTH TRANSITIONS)  ate as of Report Generated Date  MISC.PERMANENT AGGREGATE EDGE TREATMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	8,274.80 7,574.00 2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00 800.00	0.00 0.00 0.00 0.00 -4.00 0.00 0.00 0.00	8,274.80 7,574.00 2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00	TONS GAL EA SQFT EA LS LF LF SQYD	7,428.56 7,753.00 2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 339.00	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$2,712.00 \$446,049.20 \$70,297.23
J2S3238	0001 0001 0001 0001 0001 0001 0001 000	0220 0230 0240 0250 0260 0270 0280 0290 0300 0310 0320  stal Value 0330 0340	3105002 4020520 4071005 6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D 3049910 4020520	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE)  MOBILIZATION  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  MODIFIED COLDMILLING (DEPTH TRANSITIONS)  ate as of Report Generated Date  MISC. PERMANENT AGGREGATE EDGE TREATMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	8,274.80 7,574.00 2.00 1,691.00 4.00 100.00 1.00 82,262.00 800.00 5,573.80 12,722.60	0.00 0.00 0.00 0.00 -4.00 0.00 0.00 0.00 0.00	8,274.80 7,574.00 2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00	TONS GAL EA SQFT EA LS LF LF SQYD TONS	7,428.56 7,753.00 2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 339.00 6,102.19	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00 \$11.52 \$51.76	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$2,712.00 \$446,049.20 \$70,297.23 \$667,652.24
J2S3238	0001 0001 0001 0001 0001 0001 0001 000	0220 0230 0240 0250 0260 0270 0280 0290 0300 0310 0320 0340 0350	3105002 4020520 4071005 6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D 3049910 4020520 4071005	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE)  MOBILIZATION  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  MODIFIED COLDMILLING (DEPTH TRANSITIONS)  ate as of Report Generated Date  MISC.PERMANENT AGGREGATE EDGE TREATMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT	8,274.80 7,574.00 2.00 1,691.00 4.00 100.00 1.00 82,262.00 800.00 5,573.80 12,722.60 13,878.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	8,274.80 7,574.00 2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00 12,722.60 13,878.00	TONS GAL EA SQFT EA LS LF LF SQYD TONS TONS GAL	7,428.56 7,753.00 2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 339.00 6,102.19 12,899.00 13,770.00	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00 \$11.52 \$51.76 \$1.93	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$2,712.00 \$446,049.20 \$70,297.23 \$667,652.24
J2S3238	0001 0001 0001 0001 0001 0001 0001 000	0220 0230 0240 0250 0260 0270 0280 0290 0300 0310 0320  stal Value 0330 0340 0350	3105002 4020520 4071005 6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D 3049910 4020520 4071005 6123000A	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE)  MOBILIZATION  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  MODIFIED COLDMILLING (DEPTH TRANSITIONS)  ate as of Report Generated Date  MISC. PERMANENT AGGREGATE EDGE TREATMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	8,274.80 7,574.00 2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00 800.00 5,573.80 12,722.60 13,878.00 2.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	8,274.80 7,574.00 2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00 12,722.60 13,878.00 2.00	TONS GAL EA SQFT EA LS LF LF SQYD TONS GAL EA	7,428.56 7,753.00 2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 339.00 6,102.19 12,899.00 13,770.00 0.00	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00 \$11.52 \$51.76 \$1.93 \$1.00	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$2,712.00 \$446,049.20 \$70,297.23 \$667,652.24 \$26,576.10 \$0.00
J2S3238	0001 0001 0001 0001 0001 0001 0001 000	0220 0230 0240 0250 0260 0270 0280 0390 0310 0320 etal Value 0330 0340 0350 0360 0370	3105002 4020520 4071005 6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D 3049910 4020520 4071005 6123000A 6161005	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE)  MOBILIZATION  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  MODIFIED COLDMILLING (DEPTH TRANSITIONS)  ate as of Report Generated Date  MISC.PERMANENT AGGREGATE EDGE TREATMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS	8,274.80 7,574.00 2.00 1,691.00 4.00 100.00 1.00 82,262.00 75,883.00 800.00 12,722.60 13,878.00 2.00 2,218.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	8,274.80 7,574.00 2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00 5,573.80 12,722.60 13,878.00 2.00 2,218.00	TONS  GAL  EA  SQFT  EA  LS  LF  SQYD  TONS  TONS  GAL  EA  SQFT	7,428.56 7,753.00 2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 339.00 6,102.19 12,899.00 13,770.00 0.00 903.50	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00 \$10.00 \$25,430.00 \$0.10 \$8.00 \$11.52 \$51.76 \$1.93 \$1.00 \$4.50	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00 \$0.00 \$0.00 \$25,430.00 \$4,26.20 \$7,588.30 \$2,712.00 \$446,049.20 \$70,297.23 \$667,652.24 \$26,576.10 \$0.00 \$4,065.75
J2S3238	0001 0001 0001 0001 0001 0001 0001 000	0220 0230 0240 0250 0260 0270 0280 0290 0300 0310 0320 0340 0350 0360 0370 0380	3105002 4020520 4071005 6123000A 6161005 6161009 6161025 6181000 6206000C 6206001C 6224010 Posted to D 3049910 4020520 4071005 6123000A 6161005 6161009	GRAVEL (A) OR CRUSHED STONE (B)  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE)  MOBILIZATION  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  MODIFIED COLDMILLING (DEPTH TRANSITIONS)  ate as of Report Generated Date  MISC.PERMANENT AGGREGATE EDGE TREATMENT  BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)  TACK COAT  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)  CONSTRUCTION SIGNS  FLAG ASSEMBLY	8,274.80 7,574.00 2.00 1,691.00 4.00 100.00 1.00 82,262.00 800.00 5,573.80 12,722.60 13,878.00 2.00 2,218.00 4.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	8,274.80 7,574.00 2.00 1,691.00 0.00 100.00 1.00 82,262.00 75,883.00 800.00 12,722.60 13,878.00 2.00 2,218.00 0.00	TONS GAL EA SQFT EA LS LF LF SQYD TONS TONS GAL EA SQFT EA	7,428.56 7,753.00 2.00 730.00 0.00 0.00 1.00 82,262.00 75,883.00 339.00 6,102.19 12,899.00 13,770.00 0.00 903.50 0.00	\$50.80 \$1.93 \$1.00 \$4.50 \$10.00 \$1.00 \$25,430.00 \$0.10 \$8.00 \$11.52 \$51.76 \$1.93 \$1.00 \$4.50	\$6,471.56 \$377,370.85 \$14,963.29 \$2.00 \$3,285.00 \$0.00 \$25,430.00 \$8,226.20 \$7,588.30 \$2,712.00 \$446,049.20 \$70,297.23 \$667,652.24 \$26,576.10 \$0.00 \$4,065.75

Page 6 of 16 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-B02	J2S3303	0001	0420	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	1.00	\$350.00	\$350.00
		0001	0430	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	100,912.00	0.00	100,912.00	LF	100,912.00	\$0.10	\$10,091.20
	Project J2 J2S3308	0001	0440	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	43,143.00	0.00	43,143.00	LF	43,143.00	\$0.10	\$4,314.30
		0001	0450	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	15,988.00	0.00	15,988.00	SQYD	5,486.50	\$0.82	\$4,498.93
		0001	0460	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,438.00	0.00	1,438.00	SQYD	375.00	\$0.82	\$307.50
		2S3303 - To	otal Value	Posted to D	vate as of Report Generated Date							\$814,033.25
		0001	0470	4091048	EMULSIFIED ASPHALT, SEAL COAT	40,952.00	0.00	40,952.00	GAL	39,035.00	\$1.98	\$77,289.30
		0001	0480	4094002	SEAL COAT AGGREGATE, GRADE A2	146,255.00	0.00	146,255.00	SQYD	137,440.00	\$0.68	\$93,459.20
		0001	0490	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.00
		0001	0500	6161005	CONSTRUCTION SIGNS	1,632.00	0.00	1,632.00	SQFT	929.00	\$4.50	\$4,180.50
		0001	0510	6161009	FLAG ASSEMBLY	4.00	-4.00	0.00	EA	0.00	\$10.00	\$0.00
		0001	0520	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	0.00	\$1.00	\$0.00
		0001	0530	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$7,200.00	\$7,200.00
		0001	0540	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	111,633.00	0.00	111,633.00	LF	111,633.00	\$0.10	\$11,163.30
		0001	0550	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	91,296.00	0.00	91,296.00	LF	91,296.00	\$0.10	\$9,129.60
	Project J	2S3308 - To	otal Value	Posted to D	vate as of Report Generated Date							\$202,421.90
201218-B02 Ove	Overall - Total Value Posted to Date as of Report Generated Date										\$1,925,763.07	

Page 7 of 16 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J2P3201

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0110	6206124A	24 IN. WHITE WATERBORNE PAVEMENT MARKING	9/23/21	10/1/21	48.00	LF	Route 79 Plan Locations	59.58		68.63		
0120	6209903	MISC. PAVEMENT MARKINGS	9/23/21	10/1/21	48.00	LF	Route 79 Plan Locations					

### Project: J2S3303

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0330	3049910	MISC. AGGREGATE FOR BASE	9/16/21	10/1/21	593.28	TONS	Route B Left Shoulder					
				10/1/21	1,174.00	TONS	Route B Right Shoulder.					
			9/17/21	10/1/21	1,956.64	TONS	Route B Left Shoulder					
			9/20/21	10/1/21	620.74	TONS	Route B Left Shoulder					
0410	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	9/23/21	10/1/21	30.00	LF	Route B Plan Locations					
0420	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	9/23/21	10/1/21	1.00	EA	Route B, 79 Intersection Right Turn Lane					
0430	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	9/23/21	10/1/21	100,912.00	LF	Route B Edgeline					
0440	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	9/23/21	10/1/21	43,143.00	LF	Route B Centerline					

<u>The information below this line are details for Construction Signs (if applicable).</u>

No Data Available

Revision 4/1/2020 Page 8 of 16



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J2P3201	0010	EMULSIFIED ASPHALT,	Other Item Adjustment	ACAD	2	Aug 2, 2021	haggaj1	\$19,284.19	Adjustment calculated using department approved methods with the following factors: 72444 Gallons at 60 Degrees F.				
		SEAL COAT		ACAD - Tota	al			\$19,284.19					
				OTHR	2	Aug 2, 2021	haggaj1	(\$28,687.80)	Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work.				
					3	Aug 15, 2021	haggaj1	\$28,687.80	20% was withheld on previous estimate, pending acceptance of Seal Coat work. This Adjustment releases the withheld amount.				
				OTHR - Tota	al			\$0.00					
			Other Item	Adjustment -	Total			\$19,284.19					
	0010 -	· Total						\$19,284.19					
	0020	SEAL COAT AGGREGATE, GRADE A2	Material		2	Aug 2, 2021	SYSTEM	\$176,868.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
					2	Aug 2, 2021	SYSTEM	(\$176,868.00)					
					3	Aug 16, 2021	SYSTEM	\$176,868.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user phillf2 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
									3	Aug 16, 2021	SYSTEM	(\$176,868.00)	
							4	Sep 2, 2021	SYSTEM	\$176,868.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user haggaj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					4	Sep 2, 2021	SYSTEM	(\$176,868.00)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
			Other Item Adjustment		OTHR	2	Aug 2, 2021	haggaj1	(\$35,373.60)	Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work.			
					3	Aug 15, 2021	haggaj1	\$28,163.63	20% was withheld on previous estimate, pending acceptance of Seal Coat work. Seal Coat has been accepted and this Adjustment releases the withheld amount except 5% being withheld due to CRE2O report has not been submitted as of this estimate. A total payment of \$28,163.63 will be released on estimate 0003.				
								(\$7,209.97)					
			Other Item /	Adjustment -	Total			(\$7,209.97)					
	0020 -	Total						(\$7,209.97)					
	0090	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		4	Sep 2, 2021	SYSTEM	\$17,400.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haggaj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.				
					4	Sep 2, 2021	SYSTEM	(\$17,400.80)					
					5	Sep 16, 2021	SYSTEM	\$17,400.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user haggaj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					5	Sep 16, 2021	SYSTEM	(\$17,400.80)					
				- Total				\$0.00					
			Material - To					\$0.00					
			Other Item Adjustment	OTHR		Sep 2, 2021	haggaj1	(\$8,700.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.				
					6	Oct 1, 2021	haggaj1	\$8,700.00	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount				
				OTHR - Tota	al			\$0.00					
			Other Item /	Adjustment -	Total			\$0.00					
	0090 -	Total						\$0.00					
	0100	4 IN. YELLOW WATERBORNE PAVEMENT	Material		4	Sep 2, 2021	SYSTEM	\$9,461.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user haggaj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.				



ъ		D	A 11 ( )	011		0 1 1	0 ( )		D 1																
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J2P3201	0100	MARKING	Material		4	Sep 2, 2021	SYSTEM	(\$9,461.60)																	
					5	Sep 16, 2021	SYSTEM	\$9,461.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user haggaj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																
					5	Sep 16, 2021	SYSTEM	(\$9,461.60)																	
				- Total				\$0.00																	
			Material - To	otal				\$0.00																	
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$4,700.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.																
					6	Oct 1, 2021	haggaj1	\$4,700.00	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount																
				OTHR - Tota	al			\$0.00																	
			Other Item	Adjustment -				\$0.00																	
	0100 -	Total						\$0.00																	
						0.11	0) (0.751.4																		
	0110	24 IN. WHITE WATERBORNE PAVEMENT	Material		6	Oct 1, 2021	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user haggaj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																
		MARKING			6	Oct 1, 2021	SYSTEM	(\$480.00)																	
				- Total				\$0.00																	
			Material - Tota					\$0.00																	
	0110 -	Total						\$0.00																	
J2P3201 -	- Total							\$12,074.22																	
J2S3189	0130 EMULSIFIED ASPHALT,	Other Item Adjustment	ACAD	2	Aug 2, 2021	haggaj1	\$5,047.58	Adjustment calculated using department approved methods with the following factors: 18962 Gallons at 60 Degrees F.																	
		SEAL COAT	SEAL COAT	SEAL COAT	OLAL OOAT															ACAD - Tota	al			\$5,047.58	
										OTHR	2	Aug 2, 2021	haggaj1	(\$7,508.95)	Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work.										
					3	Aug 15, 2021	haggaj1	\$7,508.95	20% was withheld on previous estimate, pending acceptance of Seal Coat work. This Adjustment releases the withheld amount.																
				OTHR - Total				\$0.00																	
			Other Item /	Adjustment -	Total			\$5,047.58																	
	0130 -	Total						\$5,047.58																	
	0140	SEAL COAT AGGREGATE, GRADE A2	Material		2	Aug 2, 2021	SYSTEM	\$46,050.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user haggaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
					2	Aug 2, 2021	SYSTEM	(\$46,050.96)																	
																	3	3	Aug 16, 2021	SYSTEM	\$46,050.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user philif2 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					3	Aug 16, 2021	SYSTEM	(\$46,050.96)																	
					4	Sep 2, 2021	SYSTEM	\$46,050.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																
					4	Sep 2, 2021	SYSTEM	(\$46,050.96)																	
				- Total				\$0.00																	
			Material - To	otal				\$0.00																	
			Material - To Other Item Adjustment	OTHR	2	Aug 2, 2021	haggaj1	(\$9,210.19)	Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work.																
			, age			3	Aug 15, 2021	haggaj1	\$6,907.64	20% was withheld on previous estimate, pending acceptance of Seal Coat work. Seal Coat has been accepted and this Adjustment releases the withheld amount except 5% being withheld due to CRE2O report has not been submitted as of this estimate. A total payment of \$6,907.64 will be released on															



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks															
Froject	LINE	Description	Туре	Adjustment		Date	By	Amount	Itellians															
1000100			0.1. 11	Туре																				
J2S3189	0140	SEAL COAT AGGREGATE,	Other Item Adjustment	OTHR				(00.000.00)	estimate 0003.															
		GRADE A2	- · · · · ·	OTHR - Tota				(\$2,302.55)																
	0440		Other Item	Adjustment -	lotai			(\$2,302.55)																
		- Total						(\$2,302.55)																
	0200	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		4	Sep 2, 2021	SYSTEM	\$5,540.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user haggaj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.															
		W/ W W W W			4	Sep 2, 2021	SYSTEM	(\$5,540.80)																
					5	Sep 16, 2021	SYSTEM	\$5,540.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user haggaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.															
					5	Sep 16, 2021	SYSTEM	(\$5,540.80)																
				- Total				\$0.00																
			Material - T	otal				\$0.00																
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$2,700.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.															
					Adjustment		6	Oct 1, 2021	haggaj1	\$2,700.00	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount													
				OTHR - Tota	al			\$0.00																
			Other Item	Adjustment -	Total			\$0.00																
	0200 -	· Total																						
	0210		Material		4	Sep 2, 2021	SYSTEM	\$4,245.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user haggaj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.															
			MARKING	MARKING	MARKING	MARKING			4	Sep 2, 2021	SYSTEM	(\$4,245.20)												
									5	Sep 16, 2021	SYSTEM	\$4,245.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user haggaj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.											
					5	Sep 16, 2021	SYSTEM	(\$4,245.20)																
				- Total				\$0.00																
			Material - T	otal				\$0.00																
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$2,100.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.															
					6	Oct 1, 2021	haggaj1	\$2,100.00	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount															
				OTHR - Tota	al			\$0.00																
			Other Item	Adjustment -	Total			\$0.00																
	0210	- Total						\$0.00																
J2S3189	- Total							\$2,745.03																
J2S3238		GRAVEL (A) OR CRUSHED STONE (B)	Material		4	Sep 2, 2021	SYSTEM	\$3,389.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.															
																	4	Sep 2, 2021	SYSTEM	(\$3,389.80)	•			
												5	5	Sep 16, 2021	SYSTEM	\$6,471.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user haggaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
					5	Sep 16, 2021	SYSTEM	(\$6,471.56)																
																				6	Oct 1, 2021	SYSTEM	\$6,471.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user haggaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Oct 1, 2021	SYSTEM	(\$6,471.56)																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2S3238	0220	GRAVEL (A) OR CRUSHED STONE (B)	Material - To	otal				\$0.00	
	0220 -	Total						\$0.00	
	0230	BITUMINOUS PAVEMENT MIXTURE	Material		4	Sep 2, 2021	SYSTEM	\$373,162.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user haggaj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		PG64-22 (SUR			4	Sep 2, 2021	SYSTEM	(\$373,162.07)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	4	Sep 2, 2021	haggaj1	\$23,417.64	Adjustment was calculated using department approved spreadsheets with following factors: 7346.71 Tons with a Virgin AC of 3.00%
					5	Sep 16, 2021	haggaj1	\$267.19	Adjustment calculated electronically using department approved Excel Spreadsheets with the following data: 82.85 Tons of Mix ID SL 19-21, with a virgin AC of 3.00%.
				ACAD - Tota	al			\$23,684.83	
			Other Item	Adjustment -	Total			\$23,684.83	
			Price FUEL		4	Sep 2, 2021	SYSTEM	\$19,754.08	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Sep 16, 2021	SYSTEM	\$198.04	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$19,952.12	
			Price FUEL	- Total				\$19,952.12	
	0230 -	Total						\$43,636.95	
	0240	TACK COAT	AT Material		4	Sep 2, 2021	SYSTEM	\$14,963.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
						4	Sep 2, 2021	SYSTEM	(\$14,963.29)
					5	Sep 16, 2021	SYSTEM	\$14,963.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user haggaj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$14,963.29)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	4	Sep 2, 2021	SYSTEM	\$345.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 23 on the current Payment Estimate. Material Insufficiency Quantity 7753.000; Overrun Quantity Balance 179.00.
					4	Sep 2, 2021	SYSTEM	(\$345.47)	
					5	Sep 16, 2021	SYSTEM	(\$345.47)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Sep 16, 2021	SYSTEM	\$345.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 7753.000; Overrun Quantity Balance 179.00.
					6	Oct 1, 2021	SYSTEM	(\$345.47)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				Overrun - T	otal			(\$345.47)	
			Overrun - T	otal				(\$345.47)	
	0240 -	Total						(\$345.47)	
	0300	4 IN. WHITE WATERBORNE PAVEMENT	Material		4	Sep 2, 2021	SYSTEM	\$8,226.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user haggaj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		MARKING	MARKING		4	Sep 2, 2021	SYSTEM	(\$8,226.20)	
					5	Sep 16, 2021	SYSTEM	\$8,226.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user haggaj1 overridding Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2S3238	0300	4 IN. WHITE	Material						Estimate Exception 6 on the current Payment Estimate.
		WATERBORNE PAVEMENT MARKING			5	Sep 16, 2021	SYSTEM	(\$8,226.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$4,100.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.
				OTHR - Tota	al			(\$4,100.00)	
			Other Item	Adjustment -	Total			(\$4,100.00)	
	0300 -	· Total						(\$4,100.00)	
	0310	4 IN. YELLOW WATERBORNE PAVEMENT	Material		4	Sep 2, 2021	SYSTEM	\$7,588.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user haggaj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
		MARKING			4	Sep 2, 2021	SYSTEM	(\$7,588.30)	
					5	Sep 16, 2021	SYSTEM	\$7,588.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user haggaj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$7,588.30)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$3,700.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.
				OTHR - Tota	al			(\$3,700.00)	
			Other Item	Adjustment -	Total			(\$3,700.00)	
	0310 -	· Total						(\$3,700.00)	
J2S3238 -	- Total							\$35,491.48	
J2S3303	0330	MISC. AGGREGATE FOR BASE			-		OVOTEN		
		AGGREGATE	Material		5	Sep 16, 2021	SYSTEM	\$20,246.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		AGGREGATE	Material		5		SYSTEM	\$20,246.75 (\$20,246.75)	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment
		AGGREGATE	Material			2021 Sep 16,			Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment
		AGGREGATE	Material		5	2021 Sep 16, 2021 Oct 1,	SYSTEM	(\$20,246.75)	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment
		AGGREGATE	Material	- Total	5	2021 Sep 16, 2021 Oct 1, 2021	SYSTEM	(\$20,246.75) \$70,297.23	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment
		AGGREGATE	Material  Material - To		5	2021 Sep 16, 2021 Oct 1, 2021	SYSTEM	(\$20,246.75) \$70,297.23 (\$70,297.23)	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment
		AGGREGATE			5 6	2021 Sep 16, 2021 Oct 1, 2021	SYSTEM	(\$20,246.75) \$70,297.23 (\$70,297.23)	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment
		AGGREGATE	Material - To	otal	5 6	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM	(\$20,246.75) \$70,297.23 (\$70,297.23) \$0.00	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 6102.190;
		AGGREGATE	Material - To	otal	5 6 6	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM	(\$20,246.75) \$70,297.23 (\$70,297.23) \$0.00 \$6,087.05	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 6102.190;
		AGGREGATE	Material - To	otal Overrun Overrun - To	5 6 6	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM	(\$20,246.75) \$70,297.23 (\$70,297.23) \$0.00 \$0.00 \$6,087.05	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 6102.190;
		AGGREGATE	Material - To	otal Overrun Overrun - To	5 6 6	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM	(\$20,246.75) \$70,297.23 (\$70,297.23) \$0.00 \$6,087.05 (\$6,087.05)	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 6102.190;
		AGGREGATE FOR BASE  Total  BITUMINOUS PAVEMENT MIXTURE	Material - To	otal Overrun Overrun - To	5 6 6 6 otal	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM	(\$20,246.75) \$70,297.23 (\$70,297.23) \$0.00 \$0.00 \$6,087.05 (\$6,087.05) \$0.00 \$0.00	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 6102.190;
	0330 -	AGGREGATE FOR BASE  Total  BITUMINOUS PAVEMENT	Material - To Overrun  Overrun - T	Overrun  Overrun - Tootal	5 6 6 6 otal 5	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$20,246.75) \$70,297.23 (\$70,297.23) \$0.00 \$0.00 \$6,087.05 (\$6,087.05) \$0.00 \$0.00	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 6102.190; Overrun Quantity Balance 528.39.  Adjustment calculated electronically using department approved Excel Spreadsheets with the following data:
	0330 -	AGGREGATE FOR BASE  Total  BITUMINOUS PAVEMENT MIXTURE	Material - To Overrun - T Other Item Adjustment	Overrun  Overrun - Total	5 6 6 6 otal	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$20,246.75) \$70,297.23 (\$70,297.23) \$0.00 \$0.00 \$6,087.05 (\$6,087.05) \$0.00 \$0.00 \$0.00 \$41,599.28	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 6102.190; Overrun Quantity Balance 528.39.  Adjustment calculated electronically using department approved Excel Spreadsheets with the following data:
	0330 -	AGGREGATE FOR BASE  Total  BITUMINOUS PAVEMENT MIXTURE	Material - To Overrun - T Other Item Adjustment	Overrun - Total  ACAD - Total	5 6 6 6 otal 5 Total	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$20,246.75) \$70,297.23 (\$70,297.23) \$0.00 \$0.00 \$6,087.05 (\$6,087.05) \$0.00 \$0.00 \$41,599.28	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 6102.190; Overrun Quantity Balance 528.39.  Adjustment calculated electronically using department approved Excel Spreadsheets with the following data: 12899 Tons of Mix ID SL 19-21, with a virgin AC of 3.00%.
	0330 -	AGGREGATE FOR BASE  Total  BITUMINOUS PAVEMENT MIXTURE	Material - To Overrun - T Other Item Adjustment	Overrun - Total  ACAD - Tota  Adjustment -	5 6 6 6 otal 5 Total 5	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021  Oct 1, 2021  Sep 16, 2021  Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM haggaj1	(\$20,246.75) \$70,297.23 (\$70,297.23) \$0.00 \$0.00 \$6,087.05 (\$6,087.05) \$0.00 \$0.00 \$0.00 \$41,599.28 \$41,599.28	Estimate Item Adjustment (0014) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 6102.190; Overrun Quantity Balance 528.39.  Adjustment calculated electronically using department approved Excel Spreadsheets with the following data: 12899 Tons of Mix ID SL 19-21, with a virgin AC of 3.00%.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J2S3303	0340	BITUMINOUS PAVEMENT MIXTURE	Price FUEL		5	Sep 16, 2021	SYSTEM	\$30,833.77	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		PG64-22 (SUR		- Total				\$30,833.77	
			Price FUEL	- Total				\$30,833.77	
	0340 -	Total						\$62,880.92	
	0350	TACK COAT	Material		5	Sep 16, 2021	SYSTEM	\$26,576.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$26,576.10)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0350 -	Total						\$0.00	
	0410		Material		6	Oat 1	SYSTEM		This adjustment affects the evisinal quotern generated Material Deument
	0410	PREF THERMO PVMT MARK, 24 IN WHIT	Material		0	Oct 1, 2021	STSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Oct 1, 2021	SYSTEM	(\$750.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0410 -	Total						\$0.00	
	0410	PREF THERMO PVMT MARK, LT/RT ARROW	Material		6	Oct 1, 2021	SYSTEM	\$350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user haggaj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Oct 1, 2021	SYSTEM	(\$350.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0420 -	Total						\$0.00	
			Other Item	OTHR	6	Oct 1,	hoggoi1		This adjustment is to withhold 40% of posted quantity, pending retroreflectivity
	0430 4 IN. WHITE WATERBORNE PAVEMENT		Adjustment			2021	haggaj1	(\$4,036.00)	testing, and will be released upon acceptance for retroreflectivity.
				OTHR - Tota				(\$4,036.00)	
			Other Item /	Adjustment -	Total			(\$4,036.00)	
	0430 -	Total						(\$4,036.00)	
	0440	4 IN. YELLOW WATERBORNE PAVEMENT	Other Item Adjustment	OTHR		Oct 1, 2021	haggaj1	(\$1,725.00)	This adjustment is to withhold 40% of posted quantity, pending retroreflectivity testing, and will be released upon acceptance for retroreflectivity.
		MARKING		OTHR - Tota	al			(\$1,725.00)	
			Other Item /	Adjustment -	Total			(\$1,725.00)	
	0440 -	Total						(\$1,725.00)	
J2S3303 -	- Total							\$57,119.92	
J2S3308	0470	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	2	Aug 2, 2021	haggaj1	\$10,251.42	Adjustment calculated using department approved methods with the following factors: 38511 Gallons at 60 Degrees F.
		52/12 50/AT		ACAD - Tota	al			\$10,251.42	
				OTHR	2	Aug 2, 2021	haggaj1	(\$15,250.36)	Per Section 409, Seal Coat Work may not be accepted until 14 Days after completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work.
					3	Aug 15, 2021	haggaj1	\$15,250.36	20% was withheld on previous estimate, pending acceptance of Seal Coat work. This Adjustment releases the withheld amount.
				OTHR - Tota	al			\$0.00	
			Other Item /	Adjustment -	Total			\$10,251.42	
	0470 -	Total						\$10,251.42	
	0480	SEAL COAT AGGREGATE, GRADE A2	Material		2	Aug 2, 2021	SYSTEM	\$99,453.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user haggaj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			SIVIDE/YE		2	Aug 2, 2021	SYSTEM	(\$99,453.40)	



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks				
				Туре									
J2S3308	0480	SEAL COAT AGGREGATE,	Material						Estimate Exception 1 on the current Payment Estimate.				
		GRADE A2			3	Aug 16, 2021	SYSTEM	(\$93,459.20)					
					4	Sep 2, 2021	SYSTEM	\$93,459.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user haggaj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					4	Sep 2, 2021	SYSTEM	(\$93,459.20)					
				- Total				\$0.00					
			Material - To					\$0.00					
			Other Item	OTHR	2	Aug 2,	haggaj1	(\$19,890.70)	Per Section 409, Seal Coat Work may not be accepted until 14 Days after				
			Adjustment			2021	completion of the work	completion of the work. Per direction from MoDOT Management, 20% Withheld and will be paid back to contractor upon acceptance of the work.					
					3	Aug 15, 2021	haggaj1	\$14,918.01	20% was withheld on previous estimate, pending acceptance of Seal Coat work. Seal Coat has been accepted and this Adjustment releases the withheld amount except 5% being withheld due to CRE2O report has not been submitted as of this estimate. A total payment of \$14,918.01 will be released on estimate 0003.				
				OTHR - Tota	al			(\$4,972.69)					
			Other Item /	Adjustment -	Total			(\$4,972.69)					
		Total						(\$4,972.69)					
	0540	4 IN. WHITE WATERBORNE PAVEMENT	Material		4	Sep 2, 2021	SYSTEM	\$11,163.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user haggaj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
		MARKING			4	Sep 2, 2021	SYSTEM	(\$11,163.30)					
							5	Sep 16, 2021	SYSTEM	\$11,163.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user haggaj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					5	Sep 16, 2021	SYSTEM	(\$11,163.30)					
				- Total				\$0.00					
			Material - T			Material - To		otal				\$0.00	
			Other Item Adjustment		OTHR	4	Sep 2, 2021	haggaj1	(\$5,500.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.			
					6	Oct 1, 2021	haggaj1	\$5,500.00	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount.				
				OTHR - Tota	al			\$0.00					
			Other Item /	Adjustment -	Total			\$0.00					
	0540 -	Total						\$0.00					
	0550	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		4	Sep 2, 2021	SYSTEM	\$9,129.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user haggaj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
		DINIAMIN			4	Sep 2, 2021	SYSTEM	(\$9,129.60)					
					5	Sep 16, 2021	SYSTEM	\$9,129.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user haggaj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
					5	Sep 16, 2021	SYSTEM	(\$9,129.60)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
			Other Item Adjustment	OTHR	4	Sep 2, 2021	haggaj1	(\$4,500.00)	This adjustment is to withhold a portion pavement marking pay. This portion will be paid after acceptance for retroreflectivity.				
					6	Oct 1, 2021	haggaj1	\$4,500.00	40% was withheld on Estimate 0004 pending retroreflectivity testing. Testing was completed and material met retroreflectivity specifications. This adjustment is to pay the contractor the withheld amount				
				OTHR - Tota	al			\$0.00					
			Other Item /	Adjustment -	Total			\$0.00					
	0550 -	Total						\$0.00					



Oct 5, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2S3308 - Total									
Overall -	Total						\$112,709.38		