

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 15, 2021

Progress Estimate Number	Contract ID	201218-B04	Pay Period Start	October 30, 2021	Original Contract Amour	nt\$3,579,261.50
7	Prime Contractor	Capital Paving & Construction, LLC	Pay Period End	November 15, 2021	Net Change Order Amount Current Contract Amoun	\$91,454.93 t \$3,670,716.43

Approval Date		By User				
November 15, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	vierss				
November 15, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	vierss				
November 17, 2021	7, Reviewed and Approved at the Central Office Controllers Office Level by					

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2021	November 1, 2021		91.12%

	Milestones						
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract				
Acceptance Date							
Awarded Date	January 6, 2021	January 6, 2021					
Letting Date	December 18, 2020	December 18, 2020					
Notice to Proceed Date	February 8, 2021	February 8, 2021					
Work Began Date	August 2, 2021	August 2, 2021					

Contract Total Pay For Estimate No. 7									
		This Estimate	Previous	To Date					
201218-B04									
	Total Posted Items Pay	\$26,805.48	\$3,318,086.86	\$3,344,892.34					
	Gross Item Adjustments	\$39,272.62	\$71,085.23	\$110,357.85					
	Incentive	\$0.00	\$0.00	\$0.00					
	Disincentive	\$0.00	\$0.00	\$0.00					
	Liquidated Damage	\$0.00	\$0.00	\$0.00					
	Other Contract Adjustments	\$18,750.00	\$79,045.21	\$97,795.21					
			\$3,468,217.30	\$3,553,045.40					
Contract Total Pa	ayable This Estimate:	\$84,828.10							

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J2P3254	0050	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	TONS	\$48.180	19.14	\$922.17	
	0070	4079912	MISC.TACK COAT LOW-TRACKING OR NON-TRACKING	GAL	\$2.350	-35	(\$82.25)	
	0800	6057000	AGGREGATE DRAIN	LF	\$18.750	657	\$12,318.75	
	0160	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR					
	0170	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	EA	\$7.750	26	\$201.50	
	0370	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	LS	\$0.000	1	\$0.00	
	5001	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.040	46,528	\$1,861.12	
	5002	6209903	MISC.6" White Standard Waterborne, Type P Bead	LF	\$0.070	73,737	\$5,161.59	
	5003	6209903	MISC.12" White Standard Waterborne, Type P Bead	LF	\$0.210	1,530	\$321.30	
Project J2	P3254 - T	otal					\$21,289.18	
J2S3255	0710	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$45.000	-0.1	(\$4.50)	
Project J2	S3255 - T	otal					(\$4.50)	
J2S3350	0820	4094012	SEAL COAT AGGREGATE, GRADE B2	SQYD	\$0.670	8,240	\$5,520.80	
Project J2	S3350 - T	otal					\$5,520.80	
Overall - 1	otal						\$26,805.48	

Revision 4/1/2020 Page 1 of 20

\$18,750.00



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 15, 2021

Progress Estimate Number 7
Prime Contract or LLC
Prime Contractor LLC
Pay Period Start
Pay Period Start
Pay Period Start
Pay Period End November 15, 2021
Current Contract Amount \$3,679,261.50
Current Contract Amount \$3,679,261.50

Contract Adjustments This E	stimate				
Adj Type	Entered By	Comments	Time Units	Rate	Amount
SPADOther Contract Adjustment	vierss				\$30,669.81
SPADOther Contract Adjustment	vierss	correcting adjustment made on Estimate 0005			(\$30,669.81)
TSROther Contract Adjustment	vierss	correct adjustment to estimate 0006			(\$28,307.96)
ABIROther Contract Adjustment	vierss	correct adjustment to estimate 0006			(\$28,694.71)
TSROther Contract Adjustment	vierss	correct adjustment to estimate 0006			\$28,307.96
	vierss	correct previous adjustment on estimate 0004			\$18,750.00
ABIROther Contract Adjustment	vierss	correct adjustment to estimate 0006			\$28,694.71

Overall - Total These amounts are listed in the Incentive, Disincentive, Liquidated Damages or Other Contract Adjustments

 Line Item Adjustments This Estimate

 Project Number
 Line No.
 Item Description
 Adjustment Type
 Other Item Adjustment Adjustment Type
 Comments
 Adjustment Quantity
 Line Item Adjustment Adjustment Adjustment amount Unit Price
 Adjustment Adjustment amount

Number	No.		Туре	Adjustment Type		Quantity	Adjustment Unit Price	amount
J2P3254	0030	GRAVEL (A) OR CRUSHED STONE (B)	Material			-109	\$23.44	(\$2,554.96)
	0030	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.	109	\$23.44	\$2,554.96
	0040	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP048F MIX)	Material			-6,274.1	\$53.78	(\$337,421.10)
	0040	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP048F MIX)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.	6,274.1	\$53.78	\$337,421.10
	0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	19.14	\$3.42	\$65.45
	0050	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',50.57041 - 48.18000, 'is applied (if non-zero).	761.16	\$50.57	\$38,492.17
	0070	MISC.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.35000 - 2.35000, 'is applied (if non-zero).	1,284	\$2.35	\$3,017.40
	0110	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-1,154	\$197.50	(\$227,915.00)
	0110	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user liebhd overridding Payment Estimate Exception 5 on	1,154	\$197.50	\$227,915.00

Revision 4/1/2020 Page 2 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 15, 2021

Progress Estimate Number 7
Contract ID 201218-B04 Prime Capital Paving & Construction, LLC Pay Period Start October 30, 2021 Original Contract Amount \$3,579,261.50
Pay Period End November 15, November 15, 2021 Original Contract Amount \$3,679,261.50
Pay Period End November 15, 2021 Original Contract Amount \$3,679,261.50
Current Contract Amount \$3,670,716.43

ct er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
54					the current Payment Estimate.			
	0140	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-18	\$6.25	(\$112.50
	0150	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.20000 - 5.20000, 'is applied (if non-zero).	792	\$5.20	\$4,118.4
	0170	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material			-26	\$7.75	(\$201.50
	0170	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user liebhd overridding Payment Estimate Exception 6 on the current Payment Estimate.	26	\$7.75	\$201.50
	0200	CONSTRUCTION SIGNS	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-144	\$5.50	(\$792.00
	0300	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-478	\$25.00	(\$11,950.0
	0300	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user liebhd overridding Payment Estimate Exception 7 on the current Payment Estimate.	478	\$25.00	\$11,950.0
	0310	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material			-703	\$25.00	(\$17,575.0
	0310	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user liebhd overridding Payment Estimate Exception 8 on the current Payment Estimate.	703	\$25.00	\$17,575.0
	0320	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-67	\$190.00	(\$12,730.00
	0320	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user liebhd overridding Payment Estimate Exception 9 on the current Payment Estimate.	67	\$190.00	\$12,730.0
(0330	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Material			-2	\$950.00	(\$1,900.00
	0330	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user liebhd overridding Payment Estimate Exception 10 on the current Payment Estimate.	2	\$950.00	\$1,900.0

Revision 4/1/2020 Page 3 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 15, 2021

Progress Estimate Number 7
Prime Contractor LLC
Prime Contractor LLC
Pay Period Start
Pay Period Start
Pay Period Start
Pay Period End November 15, 2021
Pay Period E

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2P3254	5001	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-46,528	\$0.04	(\$1,861.12)
	5001	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user liebhd overridding Payment Estimate Exception 13 on the current Payment Estimate.	46,528	\$0.04	\$1,861.12
J2S3206	0540	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-224	\$1.00	(\$224.00)
	0540	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user liebhd overridding Payment Estimate Exception 17 on the current Payment Estimate.	224	\$1.00	\$224.00
J2S3207	0670	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-96	\$2.00	(\$192.00)
	0670	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user liebhd overridding Payment Estimate Exception 20 on the current Payment Estimate.	96	\$2.00	\$192.00
J2S3255	0700	GRAVEL (A) OR CRUSHED STONE (B)	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-52	\$68.91	(\$3,583.32)
	0700	GRAVEL (A) OR CRUSHED STONE (B)	Material			-189	\$68.91	(\$13,023.99)
	0700	GRAVEL (A) OR CRUSHED STONE (B)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 25 on the current Payment Estimate. Material Insufficiency Quantity 189.000; Overrun Quantity Balance 52.00.	52	\$68.91	\$3,583.32
	0700	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user liebhd overridding Payment Estimate Exception 1 on the current Payment Estimate.	189	\$68.91	\$13,023.99
	0710	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	-0.1	\$3.42	(\$0.34)
	0710	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',48.35331 - 45.00000, 'is applied (if non-zero).	0.1	\$48.35	\$4.84
	0720	TACK COAT	Material			-4,170	\$2.05	(\$8,548.50)
	0720	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user liebhd overridding Payment Estimate Exception 4 on the current Payment Estimate.	4,170	\$2.05	\$8,548.50
	0780	4 IN. WHITE STANDARD	Material			-39,854	\$0.09	(\$3,586.86)

Revision 4/1/2020 Page 4 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 15, 2021

Progress Estimate Number	Contract ID	201218-B04	Pay Period Start	October 30, 2021	Original Contract Amoun	t\$3,579,261.50
7	Prime Contractor	Capital Paving & Construction, LLC	Pay Period End	November 15, 2021	Net Change Order Amount Current Contract Amount	\$91,454.93 \$3,670,716.43

					Current Contract Amount \$6,676,710.40				
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J2S3255		WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS							
	0780	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 11 on the current Payment Estimate.	39,854	\$0.09	\$3,586.86	
	0790	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-30,440	\$0.09	(\$2,739.60)	
	0790	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 15 on the current Payment Estimate.	30,440	\$0.09	\$2,739.60	
J2S3350	0820	SEAL COAT AGGREGATE, GRADE B2	Overrun			-8,240	\$0.67	(\$5,520.80)	
Total								\$39,272.62	

Revision 4/1/2020 Page 5 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information							
						act							
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work						
J2P3254	FAF 24-2(48)	Resurface	24	RANDOLPH	from 1.5 miles west of	Rte. C to 0.9 mile east of F	Rte. 63 near Moberly						
J2S3206	FAS- S202(009)	Seal coat	С	MACON	from 0.4 mile south of	Rte. 36 to Rte. JJ in Hunts	ville						
J2S3207	FAS- S202(010)	Seal coat	Α	RANDOLPH	from Bus. 63 in Mober	ly to Rte. B south junction r	near Higbee						
J2S3255	FAS- S202(011)	Resurface	EE	RANDOLPH	from just east of Rte. 6	63 to end of state maintena	nce near Moberly						
J2S3350	FAS- S202(012)	Chip seal	В	RANDOLPH	from Rte. 63 near Clar	k to Rte. 3 near Roanoke ii	n Howard County						
Totals by	Job Number	s											
J2P3254		Item Pay Item Adjustme		Item Pay	This Estimate \$21,289.18 \$44,788.92 \$66,078.10	Previous \$2,130,570.07 \$42,150.87 \$2,172,720.94	To Date \$2,151,859.25 \$86,939.79 \$2,238,799.04						
			stments		\$0.00 \$0.00 \$0.00 \$21,350.93	\$0.00 \$0.00 \$0.00 \$51,245.01	\$0.00 \$0.00 \$0.00 \$72,595.94						
J2S3206	Incenti Disince Liquida		Gross	Item Pay	This Estimate \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 (\$913.73)	Previous \$404,151.92 (\$2,980.00) \$401,171.92 \$0.00 \$0.00 \$0.00 \$9,769.99	To Date \$404,151.92 (\$2,980.00) \$401,171.92 \$0.00 \$0.00 \$0.00 \$8,856.26						
J2S3207				Item Pay	This Estimate \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Previous \$167,746.07 \$0.00 \$167,746.07 \$0.00 \$0.00	To Date \$167,746.07 \$0.00 \$167,746.07 \$0.00 \$0.00						
	Liquida	ated Damages Contract Adjus	tments		\$0.00 (\$397.34)	\$0.00 \$4,244.73	\$0.00 \$3,847.39						
J2S3255		Item Pay Item Adjustme		Item Pay	This Estimate (\$4.50) \$4.50 \$0.00	Previous \$307,451.63 \$32,540.14 \$339,991.77	To Date \$307,447.13 \$32,544.64 \$339,991.77						
			tments		\$0.00 \$0.00 \$0.00 (\$639.99)	\$0.00 \$0.00 \$0.00 \$6,837.41	\$0.00 \$0.00 \$0.00 \$6,197.42						
J2S3350		Item Pay Item Adjustme		Item Pay	This Estimate \$5,520.80 (\$5,520.80) \$0.00	Previous \$308,167.17 (\$625.78) \$307,541.39	To Date \$313,687.97 (\$6,146.58) \$307,541.39						
	Incentive Disincentive Liquidated Damages Other Contract Adjustments		\$0.00 \$0.00 \$0.00 (\$649.87)	\$0.00 \$0.00 \$0.00 \$6,948.07	\$0.00 \$0.00 \$0.00 \$6,298.20								

Revision 4/1/2020 Page 6 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exception December	Exceptions (Discrepancies) This Estimate Period			
Namere 2010, Marcini Set 3190000000, Marcini (1017 FABL D. Th. Age blace Type 1 & 5. 1 Carlina Excellent Condon Type Insufficiant Materials Proved, 20250, fleen 3190002, Project Bern Live Understandshooms, Association of Condon Type Insufficiant Materials Proved, 20250, fleen 3190002, Project Bern Live Namere 2010, Marcini Set 500001000, Marcini (10050002, Project Bern Live Namere 2010), Marcini Set 500001000, Marcini (10050002, Project Bern Live Namere 2010), Marcini Set 500001000, Marcini Set 5000000, Marcini Set 50000000, Marcini Set 50000000, Marcini Set 5000000000000000000000000000000000000	Exceptions / Discrepencies	Explanation		Status
Number 2013, Material Set STREEDINGE, Material 1907 FLAB D. Th. Ang black Type 1 & 5 Entermation Continues, Accordance Materials (Poper 1872 SEC), the resultions of the Continues of the Continu	Number 0700, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0.049, Marterial Sex 4,000.01956, Material Polisias/Sex/Sex/Sex 5 mm, Das F, Acceptance Action Genetic Anglands Sex 2,000.0196, in institutions of the Control of th	Number 0030, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5	No Remark was entered by Engineer	LIEBHD	Overridden
Nameber (172). Masterial Sex 49/17/10066, Material 10/56/EA_SS1 Fernullified Applaid SS1 Acceptance Action General Applaidation in insulficients. Estimate Exception Type: Insulficient Materials Proport 29/25/25 Insulficient Materials Proport 10/25/25 Insulficient Materials Proport 10/25/25 Insulficient Materials Proport 29/25/25 Insulficient Materials Proport 10/25/25 Insulficient Materials Proport 29/25/25 Insulficient Materials Proport 29/25/25/25 Insulficient Materials Proport 29/25/25/25/25/25/25/25/25/25/25/25/25/25/	Number 0040, Material Set 403001696, Material 0403SP048F - Superpave 4.8 mm, Des F, Acceptance	No Remark was entered by Engineer	LIEBHD	Overridden
Number 017, Material Set 6130108, Material 1015EA. SSTAYH - Emudialed Appliats - Trackees Taxx, Acceptance Action Generic Appliancians in similaridient. Eliminate Exception Type: Insufficiant Materials: Project LEPSEA, Here 1020015, Project Item Line Market 107, AMTERIA 2019 - To fibr Ep Chi 447 No. (MMT Or ON) ACCEPTION SET 1015 CHILD AND ACCEPTION SET 1015 CHILD ACCEPTION SET 10	Number 0720, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance	No Remark was entered by Engineer	LIEBHD	Overridden
Number 070, Material Set 613 101880, Material 1070, Material 2070, Material 1070,	Number 0110, Material Set 613101096, Material 1015EASS1VH - Emulsified Asphalt - Trackless Tack,	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0300, Material Sel 620001596, Material OASPMPFWH. Performed Thermoplastic Marking Tape VI., Acceptance Action Generic 1048PMFWP and Sel 200018, Project Item Line Number 0310, Material Sel 20001696, Material 1048PMFWP. Performed Thermoplastic Marking Tape VI., Acceptance Action Generic 1048PMFWP Line Institution. Editinate Exception Type: Institlicient Materials: Project 207254, Item 0200027, Project Item Line Number 0310, Materials Project 207254, Item 0200027, Project Item Line Number 0300, Material 048PMFWP Line Institution. No Remark was entered by Engineer LIEBHO Overridden Number 0300, Material 1048PMFWP Line Institution. No Remark was entered by Engineer	Number 0170, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr	No Remark was entered by Engineer	LIEBHD	Overridden
Number 030, Material Sel 620001696, Material OSPAMPFYL - Performed Thermoplastic Marking Tape Y Acceptance Action Generic 1048PMPFYLs insufficient Martinal Sel 62000169, Material OSPAMPFYNCX - Perf Mix Tape Direct Indeat or Shape WIA Acceptance Action Generic 1048PMPFYNCX - Perf Mix Tape Direct Indeat or Shape WIA Acceptance Action Generic 1048PMPFYNCX - Perf Mix Tape Direct Indeat or Shape WIA Acceptance Action Generic 1048PMPFYNCX - Perf Mix Tape Direct Indeat or Shape WIA Acceptance Action Generic 1048PMPFYNCX - Perf Mix Tape Direct Indeat or Shape WIA Acceptance Action Generic 1048PMPFYNCX - Perf Mix Tape Direct Indeat or Shape WIA Acceptance Action Generic 1048PMPFYNCX - Perf Mix Tape Direct Indeat or Shape WIA Acceptance Action Generic 1048PMPFYNCX - Perf Mix Tape Direct Indeat or Shape WIA Acceptance Action Generic 1048PMPFYNCX - Perf Mix Tape Direct Indeat or Shape WIA Acceptance Action Generic 1048PMPFYNCX - Perf Mix Tape Direct Indeat Or Shape WIA Acceptance Action Generic 1048PMPFYNCX - Perf Mix Tape Direct Indeat Or White Acceptance Action Generic 1048PMPFYNCX - Perf Mix Tape Direct Indeat Or White Acceptance Action Generic 1048PMPFYNCX - Perf Mix Tape Direct Indeat Or White Acceptance Action Generic 1048PMPFYNCX - Indeated Company or Indeated Company	Number 0300, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0320, Material Set 620002156, Material 1048PMFPWHXX - Pet Mix Tape Direct Indicat or Shape WH. Acceptance Action Generic 1048PMFPWHXX is insufficient. Elithinate Exception Type: Insufficient Materials Project J25254, Item 6200027, Project Item Line Number 0330, Material Set 620002756, Material 1048PMFPWHXX report Wirth Tape Direct Indicat or Shape WH. Acceptance Action Generic 1048PMFPWHXX is insufficient. Elithinate Exception Type: Insufficient Materials Project J25255, Item 6200000C, Project Item Line Number 0730, Material Set 6200000CS, Material 1048PMFPWHX Park Intelligent Line Number 0730, Material Set 6200000CS, Material 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Acceptance Action Generic 1048PMFRWHWH - Marking Paint Acylic Waterborne Wirth Accept	Number 0310, Material Set 620001896, Material 1048PMPFYL - Performed Thermoplastic Marking Tape	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0330, Material Set 620002796, Material 1048PMPFTWHXX : Insufficient Capability Ca	Number 0320, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0780, Material Set 200900CO26, Material 1048PMRTWBWH in instfficient. Estimate Exception Type: Instfficient Materials: Project J253255, Item 8206000C, Project Item Line Number 0780, Material Set 620000CO89, Material 1048PMRSTP: Reflective Glass Beads Type P Perf Spec. Acceptance Action Generic 1048PMRSTP is insufficient. State of the Special Set of Special	Number 0330, Material Set 620002796, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0780, Material Set 82060000269, Material 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project 1292924, Hem 8206000C, Project Item Line Number 5001, Material Set 82080000069, Material 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project 1292924, Hem 8208000C, Project Item Line Number 5001, Material Set 82080000069, Material 1048PMRBMH is insufficient. Estimate Exception Type: Insufficient Materials: Project 12929254, Hem 8208000C, Project Item Line Number 0010, Material Set 8208000069, Material 1048PMRBTP is Insufficient. Estimate Exception Type: Insufficient Materials: Project 12929254, Hem 8208001C, Project Item Line Number 0790, Material Set 8208001C98, Material 1048PMRBTP is Insufficient. Estimate Exception Type: Insufficient Materials: Project 1283255, Item 8208001C, Project Item Line Number 0790, Material Set 8208001C98, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec. Acceptance Action Generic 1048PMRBTP is Insufficient. Estimate Exception Type: Insufficient Materials: Project 1283206, Item 820801C, Project Item Line Number 0790, Material Set 8208001C98, Material 1048PMRBMPWH - Marking Paint Acrylic Waterborne Yollow, Acceptance Action Generic 1048PMRBMPWH - Marking Paint Acrylic Waterborne Yollow, Acceptance Action Generic 1048PMRBWH - Marking Paint Acrylic Waterborne Yollow, Acceptance Action Generic 1048PMRBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMRBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMRBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMRBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMRBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMRBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMRBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMRBWH - Marking Paint Acrylic Waterborne White, Acceptance Action G	Number 0780, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne	No Remark was entered by Engineer	LIEBHD	Overridden
Number 5001, Material 5et 6206000CS6, Material 1048PMTRWBWH is insufficient Mumber 5001, Material Set 6206000CS6, Material 1048PMRRBTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRBTP is insufficient Materials Set 6206000CS6, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRBTP is insufficient Materials Set 620600CS6, Material 1048PMRBTP is insufficient Materials Exception Type: Insufficient Materials Set 62060CS6, Material 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials Project 1283255, Item 6206001C, Project Item Line Number 0706, Material Set 62060COCS6, Material 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project 1283255, Item 6206001C, Project Item Line Number 0705, Material Set 62060COCS6, Material 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project 1283255, Item 6206001C, Project Item Line Number 0705, Material Set 62060COCS6, Material 1048PMRTWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMRWPVL is insufficient Materials Project 1283206, Item 6206124A, Project Item Line Number 0540, Material Set 6206124A96, Material 1048PMRTWBWH - Marking Paint Acrylic Waterborne Withle, Acceptance Action Generic 1048PMRWPWH is insufficient Number 0540, Material Set 6206124A96, Material 1048PMRTWBWH - Marking Paint Acrylic Waterborne Withle, Acceptance Action Generic 1048PMRTWBWH - Marking Paint Acrylic Waterborne Withle, Acceptance Action Generic 1048PMRTWBWH - Marking Paint Acrylic Waterborne Withle, Acceptance Action Generic 1048PMRTWBWH - Marking Paint Acrylic Waterborne Withle, Acceptance Action Generic 1048PMRTWBWH is insufficient Number 0540, Material Set 6206124A96, Material 1048PMRTWBWH - Marking Paint Acrylic Waterborne Withle, Acceptance Action Generic 1048PMRTWBWH - Marking Paint Acrylic Waterborne Withle, Acceptance Action Generic 1048PMRTWBWH - Marking Paint Acrylic Waterborne Withle, Acceptance Action	Number 0780, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf	No Remark was entered by Engineer	LIEBHD	Overridden
Number 5001, Material Set 620600C68, Material 1048PMRTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRSTP is insufficient Materials: Project J2S3255, Item 6206001C, Project Item Line Number 0790, Material Set 6206001C98, Material 1048PMRSTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRSTP is insufficient Materials: Project J2S3255, Item 6206001C, Project Item Line Number 0790, Material Set 6206001C98, Material 1048PMRSTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRSTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3256, Item 620601C, Project Item Line Number 0790, Material Set 620601C38, Material 1048PMRSTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRSTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRSTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRSTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRSTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRSTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRSTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A68, Material 1048PMRSTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRSTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A68, Material 1048PMRSTP - Reflective Glass Beads Type P Perf Spee, Acceptance Action Generic 1048PMRSTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A68, Material 1048PMRSTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set	Number 5001, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0790, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3255, Item 6206001C, Project Item Line Number 0790, Material Set 6206001C96, Material 1048PMTRWBYL is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S32506, Item 6206124A, Project Item Line Number 0540, Material Set 6206124A9, Material 1048PMTRHBWSWH - Marking Paint Acrylic Water Hilbid White, Acceptance Action Generic 1048PMTRHBWSWH - Marking Paint Acrylic Water Developed Control of Control	Number 5001, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0790, Material Set 8206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient. Estimate Exception Type: Insufficient Materials: Project JZS3206, Item 6206124A, Project Item Line Number 0540, Material Set 6206124A96, Material 1048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project JZS3206, Item 6206124A, Project Item Line Number 0540, Material Set 6206124A96, Material 1048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project JZS3206, Item 6206124A, Project Item Line Number 0540, Material Set 6206124A96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project JZS3206, Item 6206124A, Project Item Line Number 0540, Material Set 6206124A98, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048	Number 0790, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0540, Material Set 6206124A96, Material 1048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3206, Item 6206124A, Project Item Line Number 0540, Material Set 6206124A96, Material 1048PMTRWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3206, Item 6206124A, Project Item Line Number 0540, Material Set 6206124A96, Material 1048PMTRWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3206, Item 6206124A, Project Item Line Number 0540, Material Set 6206124A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A96, Material 1048PMTRHBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A96, Material 1048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0700, Material Set 6206124A96, Material 1048PMTRWBWH - Marking Paint Acrylic Water Milbld White, Acceptance Action Generic 1048PMRTBWBWH is insufficient. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2S3255, Project Item Line Number 0710, Contract Line Item Number 0710, Item 4020520, Minor Item. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2P3254, Project Item Line Number 0050, Contract Line Item Number 0050, Item 4030103, Minor Item.	Number 0790, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0540, Material Set 6206124A96, Material 1048PMTRWBWH - Marking Paint Ácrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3206, Item 6206124A, Project Item Line Number 0540, Material Set 6206124A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A96, Material 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A96, Material 1048PMTRWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0710, Contract D48PMTRWBWH is insufficient. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2S3255, Project Item No Remark was entered by Engineer LIEBHD Acknowledged Line Number 0710, Contract Line Item Number 0710, Item 4020520, Minor Item. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2P3254, Project Item Number 0050, Contract Line Item Number 0050, Item 4030103, Minor Item.	Number 0540, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0540, Material Set 6206124A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRHBWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2S3255, Project Item Wumber 0710, Contract Line Item Number 0710, Item 4020520, Minor Item. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2P3254, Project Item Number 0710, Contract Line Item Number 0050, Item 4030103, Minor Item. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2P3254, Project Item Number 0050, Contract Line Item Number 0050, Item 4030103, Minor Item.	Number 0540, Material Set 6206124A96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0670, Material Set 6206124A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2S3255, Project Item Number 0710, Contract Line Item Number 0710, Item 4020520, Minor Item. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2P3254, Project Item Number 0050, Contract Line Item Number 0050, Item 4030103, Minor Item. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2P3254, Project Item Number 0050, Contract Line Item Number 0050, Item 4030103, Minor Item.	Number 0540, Material Set 6206124A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0670, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. Estimate Exception Type: Insufficient Materials: Project J2S3207, Item 6206124A, Project Item Line Number 0670, Material Set 6206124A96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2S3255, Project Item Line Number 0710, Contract Line Item Number 0710, Item 4020520, Minor Item. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2P3254, Project Item Line Number 0750, Contract Line Item Number 0750, Item 4030103, Minor Item. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2P3254, Project Item Line Number 0050, Contract Line Item Number 0050, Item 4030103, Minor Item.	Number 0670, Material Set 6206124A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf	No Remark was entered by Engineer	LIEBHD	Overridden
Number 0670, Material Set 6206124A96, Material 1048PMTRWBWH - Marking Paint Ácrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2S3255, Project Item Line Number 0710, Contract Line Item Number 0710, Item 4020520, Minor Item. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2P3254, Project Item Line Number 0710, Contract Line Item Number 0710, Item 4020520, Minor Item. No Remark was entered by Engineer Line Number 0710, Contract Line Item Number 0050, Contract Line Item Number 0050, Item 4030103, Minor Item.	Number 0670, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr	No Remark was entered by Engineer	LIEBHD	Overridden
Line Number 0710, Contract Line Item Number 0710, Item 4020520, Minor Item. Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2P3254, Project Item Line Number 0050, Contract Line Item Number 0050, Item 4030103, Minor Item. No Remark was entered by Engineer LIEBHD Acknowledged	Number 0670, Material Set 6206124A96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne	No Remark was entered by Engineer	LIEBHD	Overridden
Line Number 0050, Contract Line Item Number 0050, Item 4030103, Minor Item.		No Remark was entered by Engineer	LIEBHD	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2S3255, Project Item No Remark was entered by Engineer LIEBHD Overridden	Line Number 0050, Contract Line Item Number 0050, Item 4030103, Minor Item.	, ,		, and the second
, . , . , . , ,	Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2S3255, Project Item	No Remark was entered by Engineer	LIEBHD	Overridden

Revision 4/1/2020 Page 7 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Line Number 0700, Contract Line Item Number 0700, Item 3105002, Minor Item.			
Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2P3254, Project Item Line Number 0140, Contract Line Item Number 0140, Item 6131014, Minor Item.	No Remark was entered by Engineer	LIEBHD	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2P3254, Project Item Line Number 0200, Contract Line Item Number 0200, Item 6161005, Minor Item.	No Remark was entered by Engineer	LIEBHD	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2S3350, Project Item Line Number 0820, Contract Line Item Number 0820, Item 4094012, Minor Item.	No Remark was entered by Engineer	LIEBHD	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2S3206, Project Item Line Number 0550, Contract Line Item Number 0550, Item 6209902, Minor Item.	No Remark was entered by Engineer	LIEBHD	Acknowledged
Estimate Exception Type: Item Overrun: Contract 201218-B04, Contract Project J2S3206, Project Item Line Number 0570, Contract Line Item Number 0570, Item 6209903, Minor Item.	No Remark was entered by Engineer	LIEBHD	Acknowledged

Revision 4/1/2020 Page 8 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
1218-B04	J2P3254	0001	0005	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$7,745.00	\$7,745.00
		0001	0010	2153000	SHAPING SLOPES, CLASS III	13.00	0.00	13.00	100F	13.00	\$922.00	\$11,986.00
		0001	0020	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	2,622.10	0.00	2,622.10	TONS	2,168.00	\$25.98	\$56,324.6
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	109.00	0.00	109.00	TONS	109.00	\$23.44	\$2,554.9
		0001	0040	4030016	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP048F MIX)	5,097.90	1,176.20	6,274.10	TONS	6,274.10	\$53.78	\$337,421.1
		0001	0050	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	18,723.70	780.30	19,504.00	TONS	19,604.00	\$48.18	\$944,520.7
		0001	0060	4079912	MISC.POLYMER MODIFIED EMULSION MEMBRANE	24,891.00	-6,431.00	18,460.00	GAL	18,460.00	\$4.84	\$89,346.4
		0001	0070	4079912	MISC.TACK COAT LOW-TRACKING OR NON-TRACKING	13,481.00	1,249.00	14,730.00	GAL	14,730.00	\$2.35	\$34,615.5
		0001	0080	6057000	AGGREGATE DRAIN	512.00	802.00	1,314.00	LF	657.00	\$18.75	\$12,318.7
		0001	0090	6083003	3 IN. CONCRETE MEDIAN STRIP	361.70	-361.70	0.00	SQYD	0.00	\$65.25	\$0.0
		0001	0100	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.0
		0001	0110	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	2,098.80	208.20	2,307.00	SQYD	1,154.00	\$197.50	\$227,915.0
		0001	0120	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	212.00	-212.00	0.00	SQYD	0.00	\$1.00	\$0.0
		0001	0130	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	212.00	-212.00	0.00	SQYD	0.00	\$1.00	\$0.0
		0001	0140	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	8,666.00	-1,036.00	7,630.00	LF	7,648.00	\$6.25	\$47,800.0
		0001	0150	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	3,880.00	2,592.00	6,472.00	EA	4,672.00	\$5.20	\$24,294.4
		0001	0160	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	120.00	-60.00	60.00	EA	60.00	\$9.75	\$585.0
		0001	0170	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	92.00	-66.00	26.00	EA	26.00	\$7.75	\$201.5
		0001	0180	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	22.00	-17.80	4.20	TONS	4.20	\$77.59	\$325.8
		0001	0190	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	100.00	-62.40	37.60	SQYD	37.60	\$82.90	\$3,117.0
		0001	0200	6161005	CONSTRUCTION SIGNS	2,137.00	-419.00	1,718.00	SQFT	1,862.00	\$5.50	\$10,241.0
		0001	0210	6161008	ADVANCED WARNING RAIL SYSTEM	14.00	0.00	14.00	EA	14.00	\$50.00	\$700.0
		0001	0220	6161009	FLAG ASSEMBLY	12.00	0.00	12.00	EA	12.00	\$10.00	\$120.0
		0001	0230	6161025	CHANNELIZER (TRIM LINE)	460.00	0.00	460.00	EA	460.00	\$18.00	\$8,280.0
		0001	0240	6161030	TYPE III MOVEABLE BARRICADE	6.00	0.00	6.00	EA	6.00	\$125.00	\$750.0
		0001	0250	6161033	DIRECTIONAL INDICATOR BARRICADE	28.00	0.00	28.00	EA	28.00	\$25.00	\$700.
		0001	0260	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.
		0001	0270	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.
		0001	0280	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	2.00	0.00	2.00	EA	2.00	\$250.00	\$500.
		0001	0290	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$89,386.89	\$89,386.
		0001	0300	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	478.00	0.00	478.00	LF	478.00	\$25.00	\$11,950.
		0001	0310	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	703.00	0.00	703.00	LF	703.00	\$25.00	\$17,575.
		0001	0320	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	67.00	0.00	67.00	EA	67.00	\$190.00	\$12,730.
		0001	0330	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	2.00	0.00	2.00	EA	2.00	\$950.00	\$1,900.
		0001	0340	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	58,159.90	-58,159.90	0.00	LF	0.00	\$0.10	\$0.0
		0001	0350	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	92,171.00	-92,171.00	0.00	LF	0.00	\$0.14	\$0.
		0001	0360	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,530.00	-1,530.00	0.00	LF	0.00	\$0.35	\$0.0
		0001	0370	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	1.00	\$0.00	\$0.
		0001	0380	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	71,859.00	0.00	71,859.00	SQYD	71,859.00	\$1.68	\$120,723.
		0001	0390	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	3,892.00	-247.00	3,645.00	SQYD	3,645.00	\$0.93	\$3,389.
		0001	0400	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	510.00	0.00	510.00	STA	425.00	\$19.97	\$8,487.
		0001	0410	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	275.90	0.00	275.90	STA	233.40	\$22.23	\$5,188.4
		0010	0420	6061060	MGS GUARDRAIL	838.00	0.00	838.00	LF	838.00	\$22.52	\$18,871.7

Page 9 of 20 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract ONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
8-B04	J2P3254	0010	0430	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	10.00	0.00	10.00	EA	10.00	\$2,695.00	\$26,950.00
		0001	5001	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0.00	58,159.90	58,159.90	LF	46,528.00	\$0.04	\$1,861.1
		0001	5002	6209903	MISC.6" White Standard Waterborne, Type P Bead	0.00	92,171.00	92,171.00	LF	73,737.00	\$0.07	\$5,161.5
		0001	5003	6209903	MISC.12" White Standard Waterborne, Type P Bead	0.00	1,530.00	1,530.00	LF	1,530.00	\$0.21	\$321.3
	Project J	2P3254 - To	otal Value	Posted to E	Date as of Report Generated Date							\$2,151,859.2
	J2S3206	0001	0440	4091048	EMULSIFIED ASPHALT, SEAL COAT	88,488.00	0.00	88,488.00	GAL	69,300.00	\$1.85	\$128,205.0
		0001	0450	4094012	SEAL COAT AGGREGATE, GRADE B2	316,026.00	0.00	316,026.00	SQYD	316,026.00	\$0.67	\$211,737.4
		0001	0460	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.0
		0001	0470	6161005	CONSTRUCTION SIGNS	2,193.00	0.00	2,193.00	SQFT	1,382.00	\$5.50	\$7,601.0
		0001	0480	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$10.00	\$40.0
		0001	0490	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	25.00	\$18.00	\$450.0
		0001	0500	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.0
		0001	0510	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$7,340.00	\$7,340.0
		0001	0520	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	224,718.00	0.00	224,718.00	LF	224,718.00	\$0.10	\$22,471.8
		0001	0530	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	163,027.00	0.00	163,027.00	LF	163,027.00	\$0.10	\$16,302.7
		0001	0540	6206124A	$24\mbox{In.}$ WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	224.00	0.00	224.00	LF	224.00	\$1.00	\$224.0
		0001	0550	6209902	MISC.30" WHITE MID BLOCK STANDARD WATERBORNE PAVMENT MARKING PAINT, TYPE P BEADS	7.00	0.00	7.00	EA	17.00	\$50.00	\$850.0
		0001	0560	6209902	MISC.RAILROAD CROSSING PAVEMENT MARKING	5.00	0.00	5.00	EA	5.00	\$250.00	\$1,250.
		0001	0570	6209903	MISC.6 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	120.00	0.00	120.00	LF	368.00	\$10.00	\$3,680.0
	Project J	2S3206 - To	otal Value	Posted to E	Date as of Report Generated Date							\$404,151.9
	J2S3207	0001	0580	4091048	EMULSIFIED ASPHALT, SEAL COAT	37,816.00	0.00	37,816.00	GAL	30,380.00	\$1.85	\$56,203.0
		0001	0590	4094002	SEAL COAT AGGREGATE, GRADE A2	135,056.00	0.00	135,056.00	SQYD	123,801.00	\$0.67	\$82,946.6
		0001	0600	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.
		0001	0610	6161005	CONSTRUCTION SIGNS	1,264.00	0.00	1,264.00	SQFT	906.00	\$5.50	\$4,983.
		0001	0620	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$10.00	\$40.0
		0001	0630	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	25.00	\$18.00	\$450.
		0001	0640	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$6,850.00	\$6,850.
		0001	0650	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	100,664.00	0.00	100,664.00	LF	100,664.00	\$0.09	\$9,059.
		0001	0660	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	47,924.00	0.00	47,924.00	LF	47,924.00	\$0.11	\$5,271.
		0001	0670	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	96.00	0.00	96.00	LF	96.00	\$2.00	\$192.
		0001	0680	6209902	MISC.RAILROAD CROSSING PAVEMENT MARKING	3.00	0.00	3.00	EA	3.00	\$250.00	\$750.
	Project J	2S3207 - To	otal Value	Posted to E	Date as of Report Generated Date							\$167,746.
	J2S3255	0001	0690	3049910	MISC.MISC. {PERM. AGGR. EDGE TREATMENT}	134.00	0.00	134.00	TONS	98.00	\$53.58	\$5,250.
		0001	0700	3105002	GRAVEL (A) OR CRUSHED STONE (B)	137.00	0.00	137.00	TONS	189.00	\$68.91	\$13,023.
		0001	0710	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	5,607.50	0.00	5,607.50	TONS	5,633.10	\$45.00	\$253,489.
		0001	0720	4071005	TACK COAT	4,995.00	0.00	4,995.00	GAL	4,170.00	\$2.05	\$8,548.
		0001	0730	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.
		0001	0740	6161005	05 CONSTRUCTION SIGNS 876.00 0.00 876.00 SQFT 810.00							\$4,455.
			0750	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$10.00	\$40.
		0001				100.00	0.00	100.00	EA	25.00	\$18.00	\$450.
		0001	0760	6161025	CHANNELIZER (TRIM LINE)							
			0760 0770	6161025 6181000	CHANNELIZER (TRIM LINE) MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$6,891.18	\$6,891.
		0001			MOBILIZATION	1.00	0.00	1.00 49,818.00	LS	1.00 39,854.00	\$6,891.18 \$0.09	
		0001	0770	6181000	MOBILIZATION 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS							\$6,891.1 \$3,586.8 \$2,739.6

Revision 4/1/2020 Page 10 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-B04	Project J	2 S3255 - To	tal Value	Posted to D	ate as of Report Generated Date							\$307,447.13
	J2S3350	0001	0810	4091048	EMULSIFIED ASPHALT, SEAL COAT	62,868.00	0.00	62,868.00	GAL	61,060.00	\$1.85	\$112,961.00
		0001	0820	4094012	SEAL COAT AGGREGATE, GRADE B2	224,526.00	0.00	224,526.00	SQYD	233,700.00	\$0.67	\$156,579.00
		0001	0830	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0840	6161005	CONSTRUCTION SIGNS	1,687.00	0.00	1,687.00	SQFT	1,272.00	\$5.50	\$6,996.00
		0001	0850	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$10.00	\$40.00
		0001	0860	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	25.00	\$18.00	\$450.00
		0001	0870	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$7,300.00	\$7,300.00
		0001	0880	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	151,219.00	0.00	151,219.00	LF	151,219.00	\$0.09	\$13,609.71
		0001	0890	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	163,914.00	0.00	163,914.00	LF	163,914.00	\$0.09	\$14,752.26
	Project J2	2S3350 - To	tal Value	Posted to D	ate as of Report Generated Date							\$313,687.97
201218-B04 Ove	erall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$3,344,892.34

Page 11 of 20 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J2P3254

Line Number	Item Code	Description	DWR Date	DWR Approval	Quantity Posted	Units	Location	From Station/	Offset/ Distance	To Station/	Offset/ Distance	Comments
				Date				Log Mile		Log Mile		
0050	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	11/9/21	11/15/21	19.14	TONS	Rte. 24	133.379		142.344		Quantity Correction
0070	4079912	MISC. NON STANDARD TACK COAT	11/9/21	11/15/21	-35.00	GAL	Rte. 24	133.379		142.344		Quantity Correction
0800	6057000	AGGREGATE DRAIN	11/9/21	11/15/21	657.00	LF	Rte. 24	133.379		142.344		
0160	6131017	DOWEL BAR (FURNISH AND INSTALL WITH BASK	11/9/21	11/15/21	60.00	EA	Rte. 24	134.686		138.282		
0170	6131018	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	11/9/21	11/15/21	26.00	EA	Rte. 24	134.686		138.282		
0370	6209901	MISC. PAVEMENT MARKINGS	11/4/21	11/4/21	1.00	LS	Rte. 24	133.379		142.344		
5001	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	11/4/21	11/4/21	46,528.00	LF	Rte. 24	133.379		142.344		
5002	6209903	MISC. PAVEMENT MARKINGS	11/4/21	11/4/21	73,737.00	LF	Rte. 24	133.379		142.344		
5003	6209903	MISC. PAVEMENT MARKINGS	11/4/21	11/4/21	1,530.00	LF	Rte. 24	133.379		142.344		

Project: J2S3255

Line Number	Item Code	Description		DWR Approval Date		Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0710	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	11/9/21	11/15/21	-0.10	TONS	Rte. EE	1.323		6.057		

Project: J2S3350

Line Number	Item Code	Description	DWR Date		Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0820	4094012	SEAL COAT AGGREGATE, GRADE B2	11/9/21	11/15/21	8,240.00	SQYD	Rte. B	0.00		20.516		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 12 of 20



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3254	0030	GRAVEL (A) OR CRUSHED STONE (B)	Material		5	Oct 15, 2021	SYSTEM	\$2,554.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Oct 15, 2021	SYSTEM	(\$2,554.96)	
					6	Oct 29, 2021	SYSTEM	\$2,554.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Oct 29, 2021	SYSTEM	(\$2,554.96)	
					7	Nov 15, 2021	SYSTEM	\$2,554.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Nov 15, 2021	SYSTEM	(\$2,554.96)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0030 -	Total						\$0.00	
	0040	ASPH. CONC. MIXTURE PG 70-22 (SP048F)	Material		4	Oct 4, 2021	SYSTEM	\$337,421.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vierss overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Oct 2, 2021	SYSTEM	(\$337,421.10)	
					5	Oct 15, 2021	SYSTEM	\$337,421.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Oct 15, 2021	SYSTEM	(\$337,421.10)	
					6	Oct 29, 2021	SYSTEM	\$337,421.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Oct 29, 2021	SYSTEM	(\$337,421.10)	
					7	Nov 15, 2021	SYSTEM	\$337,421.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user liebhd overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Nov 15, 2021	SYSTEM	(\$337,421.10)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	3	Sep 20, 2021	vierss	\$13,296.97	saved to eProjects
					4	Oct 4, 2021	vierss	\$13,007.19	calculated and saved to eProjects
				ACAD - Tota	al			\$26,304.16	
				OADJ	6	Nov 1, 2021	vierss	(\$63,256.04)	
				OADJ - Tota	al			(\$63,256.04)	
			Other Item	Adjustment -				(\$36,951.88)	
			Overrun	Overrun		Oct 2, 2021	SYSTEM	(\$66,067.63)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Oct 2, 2021	SYSTEM	\$23,060.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 6274.100; Overrun Quantity Balance 1176.20.
					4	Oct 2, 2021	SYSTEM	\$43,006.87	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 6274.100; Overrun Quantity Balance 1176.20.
					5	Oct 15, 2021	SYSTEM	(\$66,067.62)	Averaged Price Adjustment from this item on all previous payment estimates of '2.39040' is applied (if non-zero).
					5	Oct 15, 2021	SYSTEM	\$66,067.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 17 on the current Payment Estimate. Material Insufficiency Quantity 6274.100;



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3254	0040	ASPH. CONC.	Overrun	Overrun					Overrun Quantity Balance 1176.20.
		MIXTURE PG 70-22 (SP048F)			6	Oct 29, 2021	SYSTEM	(\$66,067.62)	Averaged Price Adjustment from this item on all previous payment estimates of '2.39040' is applied (if non-zero).
					6	Oct 29, 2021	SYSTEM	\$66,067.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 26 on the current Payment Estimate. Material Insufficiency Quantity 6274.100; Overrun Quantity Balance 1176.20.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
			Price FUEL		3	Sep 16, 2021	SYSTEM	\$7,581.41	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Oct 2, 2021	SYSTEM	\$7,416.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$14,997.60	
			Price FUEL	- Total				\$14,997.60	
	0040 -	Total						(\$21,954.28)	
	0050	ASPHALTIC CONCRETE MIXTURE PG	Material		3	Sep 16, 2021	SYSTEM	\$387,881.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 1 on the current Payment Estimate.
		70-22 (SP125C MIX)			3	Sep 16, 2021	SYSTEM	(\$387,881.28)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	2	Sep 2, 2021	vierss	\$7,916.36	Doc Record saved to eProjects
					3	Sep 20, 2021	vierss	\$19,684.82	saved to eProjects
					4	Oct 4, 2021	vierss	\$39,677.61	calculated and saved to eProjects
				ACAD - Tota	al			\$67,278.79	
			Other Item	Adjustment -	Total			\$67,278.79	
			Overrun	Overrun	4	Oct 2, 2021	SYSTEM	(\$43,549.21)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Nov 15, 2021	SYSTEM	\$38,492.17	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',50.57041 - 48.18000, 'is applied (if non-zero).
				Overrun - T	otal			(\$5,057.04)	
			Overrun - T	otal				(\$5,057.04)	
			Price FUEL		2	Sep 2, 2021	SYSTEM	\$6,261.37	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	Sep 16, 2021	SYSTEM	\$2,345.75	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	Sep 16, 2021	SYSTEM	\$11,332.92	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Oct 2, 2021	SYSTEM	\$27,571.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Nov 15, 2021	SYSTEM	\$65.45	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Price FUEL	- Total				\$47,576.82	
	0050	Total	Price FUEL	- Total				\$47,576.82	
	0050 - 0070	MISC. NON STANDARD	Overrun	Overrun	4	Oct 2, 2021	SYSTEM	\$109,798.57 (\$3,017.40)	
		TACK COAT			7	Nov 15, 2021	SYSTEM	\$3,017.40	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.35000 - 2.35000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	<u>αργίου (ii Ποίτ-2οτο).</u>
			Overrun - T		otai			\$0.00	
	0070 -	Total	Overruii - I	otai				\$0.00	
	-0070 -	Total						\$0.00	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
254	0110	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		5	Oct 15, 2021	SYSTEM	\$227,915.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user liebhd overridding Payment Estimate Exception 5 on the current Payment Estimate.
		DEFIII			5	Oct 15, 2021	SYSTEM	(\$227,915.00)	
					6	Oct 29, 2021	SYSTEM	\$227,915.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user liebhd overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Oct 29, 2021	SYSTEM	(\$227,915.00)	
					7	Nov 15, 2021	SYSTEM	\$227,915.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user liebhd overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Nov 15, 2021	SYSTEM	(\$227,915.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0110 -	Total						\$0.00	
	0140	FULL DEPTH PAVEMENT	Overrun	Overrun	7	Nov 15, 2021	SYSTEM	(\$112.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
		REPAIR SAW CUT (FOR		Overrun - T	otal			(\$112.50)	
			Overrun - T	otal				(\$112.50)	
	0140 -	Total						(\$112.50)	
	0150	DOWEL BAR (DRILLING, FURNISHING	Material		4	Oct 4, 2021	SYSTEM	\$26,416.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.
		AND INST			4	Oct 2, 2021	SYSTEM	(\$26,416.00)	
					5	Oct 15, 2021	SYSTEM	\$24,294.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user liebhd overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Oct 15, 2021	SYSTEM	(\$24,294.40)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	4	Oct 2, 2021	SYSTEM	\$6,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 5080.000; Overrun Quantity Balance 1200.00.
					4	Oct 2, 2021	SYSTEM	(\$6,240.00)	
					5	Oct 15, 2021	SYSTEM	(\$4,118.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Oct 15, 2021	SYSTEM	\$4,118.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4672.000; Overrun Quantity Balance 792.00.
					6	Oct 29, 2021	SYSTEM	(\$4,118.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Nov 15, 2021	SYSTEM	\$4,118.40	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.20000 - 5.20000, 'is applied (if non-zero).
					otal			\$0.00	
				Overrun - T	Otal				
			Overrun - T		otai			\$0.00	
	0150 -	Total	Overrun - T		otai			\$0.00 \$0.00	
	0150 - 0170	Total TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Overrun - T		7	Nov 15, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user liebhd overridding Payment Estimate Exception 6 on the current Payment Estimate.
		TIE BAR (DRILL, FURN & INSTAL)					SYSTEM SYSTEM	\$0.00	Estimate Item Adjustment (0015) due to user liebhd overridding Payment
		TIE BAR (DRILL, FURN & INSTAL)			7	2021 Nov 15,		\$0.00 \$201.50	Estimate Item Adjustment (0015) due to user liebhd overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J2P3254	0170 -	Total						\$0.00		
	0200	CONSTRUCTION SIGNS	Overrun	Overrun		Nov 15, 2021	SYSTEM	(\$792.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
				Overrun - To	otal			(\$792.00)		
			Overrun - T	otal				(\$792.00)		
	0200 -	Total						(\$792.00)		
	0300	PREF THERMO PVMT MARK, 24 IN WHIT	Material		6	Oct 29, 2021	SYSTEM	\$11,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user liebhd overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					6	Oct 29, 2021	SYSTEM	(\$11,950.00)		
					7	Nov 15, 2021	SYSTEM	\$11,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user liebhd overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					7	Nov 15, 2021	SYSTEM	(\$11,950.00)		
				- Total				\$0.00		
			Material - Total					\$0.00		
	0300 -	Total						\$0.00		
	0310	PREF THERMO PVMT MARK, 24 IN YELLOW	Material		6	Oct 29, 2021	SYSTEM	\$17,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user liebhd overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					6	Oct 29, 2021	SYSTEM	(\$17,575.00)		
					7	Nov 15, 2021	SYSTEM	\$17,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user liebhd overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					7	Nov 15, 2021	SYSTEM	(\$17,575.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0310 -	Total						\$0.00		
	0320	PREF THERMO PVMT MARK, LT/RT ARROW	K,		6	Oct 29, 2021	SYSTEM	\$12,730.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user liebhd overridding Payment Estimate Exception 8 on the current Payment Estimate.	
						6	Oct 29, 2021	SYSTEM	(\$12,730.00)	
					7	Nov 15, 2021	SYSTEM	\$12,730.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user liebhd overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					7	Nov 15, 2021	SYSTEM	(\$12,730.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0320 -	Total						\$0.00		
	0330	PREF THERMO PVMT MARKING, COMBO			6	Oct 29, 2021	SYSTEM	\$1,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user liebhd overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					6	Oct 29, 2021	SYSTEM	(\$1,900.00)		
					7	Nov 15, 2021	SYSTEM	\$1,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user liebhd overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					7	Nov 15, 2021	SYSTEM	(\$1,900.00)		
				- Total						
			Material - To	otal				\$0.00		
	0330 -	Total						\$0.00		
	5001	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		7	Nov 15, 2021	SYSTEM	\$1,861.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user liebhd overridding Payment Estimate Exception 13 on the current Payment Estimate.	
		(1 (11 10								



		5							
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3254	5001	4 IN. WHITE WATERBORNE	Material		7	Nov 15, 2021	SYSTEM	(\$1,861.12)	
		PAVEMENT MARKING		- Total				\$0.00	
			Material - T	otal				\$0.00	
	5001 -	Total						\$0.00	
J2P3254 -	- Total							\$86,939.79	
J2S3206	0520	4 IN. WHITE WATERBORNE PAVEMENT	Material		3	Sep 16, 2021	SYSTEM	\$17,977.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user liebhd overridding Payment Estimate Exception 2 on the current Payment Estimate.
		MARKING			3	Sep 16, 2021	SYSTEM	(\$17,977.40)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0520 -	Total						\$0.00	
	0530	4 IN. YELLOW WATERBORNE PAVEMENT	Material		3	Sep 16, 2021	SYSTEM	\$13,042.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user liebhd overridding Payment Estimate Exception 8 on the current Payment Estimate.
		MARKING			3	Sep 16, 2021	SYSTEM	(\$13,042.20)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0530 -	Total						\$0.00	
	0540	24 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		5	Oct 15, 2021	SYSTEM	\$224.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user liebhd overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Oct 15, 2021	SYSTEM	(\$224.00)	
					6	Oct 29, 2021	SYSTEM	\$224.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user liebhd overridding Payment Estimate Exception 14 on the current Payment Estimate.
					6	Oct 29, 2021	SYSTEM	(\$224.00)	
					7	Nov 15, 2021	SYSTEM	\$224.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user liebhd overridding Payment Estimate Exception 17 on the current Payment Estimate.
					7	Nov 15, 2021	SYSTEM	(\$224.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0540 -	Total						\$0.00	
	0550	MISC. PAVEMENT MARKINGS	NT	Overrun	5	Oct 15, 2021	SYSTEM	(\$500.00)	
				Overrun - Total				(\$500.00)	
			Overrun - T	otal				(\$500.00)	
	0550 -	Total						(\$500.00)	
	0570	MISC. PAVEMENT MARKINGS	Overrun	Overrun	5	Oct 15, 2021	SYSTEM	(\$2,480.00)	
		WARTINGO		Overrun - T	otal			(\$2,480.00)	
		Overrun - Total						(\$2,480.00)	
	0570 -	Total						(\$2,480.00)	
J2S3206 -	- Total							(\$2,980.00)	
J2S3207	0650	4 IN. WHITE WATERBORNE PAVEMENT MARKING	-		3	Sep 16, 2021	SYSTEM	\$7,247.79	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user liebhd overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	Sep 16, 2021	SYSTEM	(\$7,247.79)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0650 -	Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2S3207	0660	4 IN. YELLOW WATERBORNE PAVEMENT	Material		3	Sep 16, 2021	SYSTEM	\$4,217.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user liebhd overridding Payment Estimate Exception 12 on the current Payment Estimate.
		MARKING			3	Sep 16, 2021	SYSTEM	(\$4,217.29)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0660 -	Total						\$0.00	
	0670	24 IN. WHITE WATERBORNE PAVEMENT	Material		5	Oct 15, 2021	SYSTEM	\$192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user liebhd overridding Payment Estimate Exception 12 on the current Payment Estimate.
		MARKING			5	Oct 15, 2021	SYSTEM	(\$192.00)	
					6	Oct 29, 2021	SYSTEM	\$192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user liebhd overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Oct 29, 2021	SYSTEM	(\$192.00)	
					7	Nov 15, 2021	SYSTEM	\$192.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user liebhd overridding Payment Estimate Exception 20 on the current Payment Estimate.
					7	Nov 15, 2021	SYSTEM	(\$192.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0670 -	Total						\$0.00	
J2S3207 -	- Total							\$0.00	
J2S3255	0700	GRAVEL (A) OR CRUSHED STONE (B)	Material		5	Oct 15, 2021	SYSTEM	\$13,023.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Oct 15, 2021	SYSTEM	(\$13,023.99)	
					6	Oct 29, 2021	SYSTEM	\$13,023.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user liebhd overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Oct 29, 2021	SYSTEM	(\$13,023.99)	
					7	Nov 15, 2021	SYSTEM	\$13,023.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user liebhd overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Nov 15, 2021	SYSTEM	(\$13,023.99)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment Other Item A Overrun	OADJ	6	Nov 1, 2021	vierss	(\$3,583.32)	
				OADJ - Total				(\$3,583.32)	
				Adjustment -	Total			(\$3,583.32)	
					5	Oct 15, 2021	SYSTEM	\$3,583.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 189.000; Overrun Quantity Balance 52.00.
					5	Oct 15, 2021	SYSTEM	(\$3,583.32)	
					6	Oct 29, 2021	SYSTEM	(\$3,583.32)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Oct 29, 2021	SYSTEM	\$3,583.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 25 on the current Payment Estimate. Material Insufficiency Quantity 189.000; Overrun Quantity Balance 52.00.
					7	Nov 15, 2021	SYSTEM	(\$3,583.32)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Nov 15,	SYSTEM	\$3,583.32	This adjustment offsets the original system-generated Overrun Payment



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks			
			Туре	Adjustment Type	Number	Date	Ву					
J2S3255	0700	GRAVEL (A) OR CRUSHED STONE (B)	Overrun	Overrun		2021			Estimate Item Adjustment (0003) overridding Payment Estimate Exception 25 on the current Payment Estimate. Material Insufficiency Quantity 189.000; Overrun Quantity Balance 52.00.			
				Overrun - T	otal			\$0.00				
			Overrun - T	otal				\$0.00				
	0700 -	· Total						(\$3,583.32)				
	0710	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Other Item Adjustment	ACAD	5	Oct 18, 2021	vierss	\$18,476.90	spreadsheet and doc record saved to eProjects			
				ACAD - Tota	al			\$18,476.90				
			Other Item /	Adjustment -				\$18,476.90				
			Overrun	Overrun	5	Oct 15, 2021	SYSTEM	(\$1,242.68)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					7	Nov 15, 2021	SYSTEM	\$4.84	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',48.35331 - 45.00000, 'is applied (if non-zero).			
				Overrun - T	otal			(\$1,237.84)				
			Overrun - T	otal				(\$1,237.84)				
			Price FUEL		5	Oct 15, 2021	SYSTEM	\$18,889.24	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					7	Nov 15, 2021	SYSTEM	(\$0.34)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				- Total				\$18,888.90				
			Price FUEL	- Total				\$18,888.90				
	0710 -	· Total						\$36,127.96				
	0720	TACK COAT	Material		5	Oct 15, 2021	SYSTEM	\$8,548.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					5	Oct 15, 2021	SYSTEM	(\$8,548.50)				
					6	Oct 29, 2021	SYSTEM	\$8,548.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 4 on the current Payment Estimate.			
								6	Oct 29, 2021	SYSTEM	(\$8,548.50)	
					7	Nov 15, 2021	SYSTEM	\$8,548.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user liebhd overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					7	Nov 15, 2021	SYSTEM	(\$8,548.50)				
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	0720 -	· Total						\$0.00				
	0780	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		6	Oct 29, 2021	SYSTEM	\$3,586.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 10 on the current Payment Estimate.			
					6	Oct 29, 2021	SYSTEM	(\$3,586.86)				
					7	Nov 15, 2021	SYSTEM	\$3,586.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user liebhd overridding Payment Estimate Exception 11 on the current Payment Estimate.			
					7	Nov 15, 2021	SYSTEM	(\$3,586.86)				
				- Total				\$0.00				
			Material - To	Total Total				\$0.00				
	0780 -	· Total						\$0.00				
	0790	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	NE NT		6	Oct 29, 2021	SYSTEM	\$2,739.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user liebhd overridding Payment Estimate Exception 12 on the current Payment Estimate.			
					6	Oct 29, 2021	SYSTEM	(\$2,739.60)				
					7	Nov 15,	SYSTEM	\$2,739.60	This adjustment offsets the original system-generated Material Payment			

Nov 18, 2021



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			1 900	Туре	rambor	Buto			
J2S3255	0790	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material			2021			Estimate Item Adjustment (0007) due to user liebhd overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Nov 15, 2021	SYSTEM	(\$2,739.60)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0790 -	Total						\$0.00	
J2S3255 -	- Total							\$32,544.64	
J2S3350	0820	SEAL COAT AGGREGATE,	Overrun	Overrun	1	Aug 16, 2021	SYSTEM	(\$625.78)	
		GRADE B2			7	Nov 15, 2021	SYSTEM	(\$5,520.80)	
				Overrun - Total				(\$6,146.58)	
			Overrun - T	otal				(\$6,146.58)	
	0820 -	Total						(\$6,146.58)	
	0880	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		3	Sep 16, 2021	SYSTEM	\$10,887.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user liebhd overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Sep 16, 2021	SYSTEM	(\$10,887.75)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0880 -	Total						\$0.00	
	0890	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		3	Sep 16, 2021	SYSTEM	\$11,801.79	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user liebhd overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Sep 16, 2021	SYSTEM	(\$11,801.79)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0890 -	Total						\$0.00	
J2S3350 -	- Total							(\$6,146.58)	
Overall - Total								\$110,357.85	