

# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 2, 2021

| Progress Estimate<br>Number | Contract ID         | 201218-C06                          | Pay Period<br>Start | June 16,<br>2021   | Original Contract Amou                              | nt\$2,392,908.04                 |
|-----------------------------|---------------------|-------------------------------------|---------------------|--------------------|---|----------------------------------|
| 5                           | Prime<br>Contractor | Superior Bowen Asphalt Company, LLC | Pay Period En       | d June 30,<br>2021 | Net Change Order<br>Amount<br>Current Contract Amou | \$96,514.82<br>nt \$2,489,422.86 |

| Approval Date |  | By User |
|---------------|--|---------|
| July 2, 2021  | Generated and Approved (and should be considered Draft) at the Project Office Level by   | mcclon1 |
| July 2, 2021  | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | sandis1 |
| July 6, 2021  | Reviewed and Approved at the Central Office Controllers Office Level by                  | ramses1 |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete |
|--------------------------|-------------------------|------------------------|---------------------------------------|
| October 30, 2021         | October 30, 2021        |                        | 19.58%                                |

|                        | Contract Informational Dates |                                |                                  |  |  |  |  |  |  |  |  |
|------------------------|------------------------------|--------------------------------|----------------------------------|--|--|--|--|--|--|--|--|
| Date Description       | Original Completion Date     | <b>Current Completion Date</b> | No Milestones Exist for Contract |  |  |  |  |  |  |  |  |
| Acceptance Date        |                              |                                |                                  |  |  |  |  |  |  |  |  |
| Awarded Date           | January 6, 2021              | January 6, 2021                |                                  |  |  |  |  |  |  |  |  |
| Letting Date           | December 18, 2020            | December 18, 2020              |                                  |  |  |  |  |  |  |  |  |
| Notice to Proceed Date | March 8, 2021                | March 8, 2021                  |                                  |  |  |  |  |  |  |  |  |
| Work Began Date        | April 24, 2021               | April 24, 2021                 |                                  |  |  |  |  |  |  |  |  |

| Contract Total Pay For Estimate No. 5 |               |                            |              |  |  |  |  |  |  |  |  |
|---------------------------------------|---------------|----------------------------|--------------|--|--|--|--|--|--|--|--|
|                                       | This Estimate | Previous                   | To Date      |  |  |  |  |  |  |  |  |
| 201218-C06                            |               |                            |              |  |  |  |  |  |  |  |  |
| Total Posted Items Pay                | \$0.00        | \$487,537.37               | \$487,537.37 |  |  |  |  |  |  |  |  |
| Gross Item Adjustments                | \$0.00        | \$0.00                     | \$0.00       |  |  |  |  |  |  |  |  |
| Incentive                             | \$0.00        | \$0.00                     | \$0.00       |  |  |  |  |  |  |  |  |
| Disincentive                          | \$0.00        | \$0.00                     | \$0.00       |  |  |  |  |  |  |  |  |
| Liquidated Damage                     | \$0.00        | \$0.00                     | \$0.00       |  |  |  |  |  |  |  |  |
| Other Contract Adjustments            | \$0.00        | \$0.00                     | \$0.00       |  |  |  |  |  |  |  |  |
|                                       |               | \$ <mark>487,537.37</mark> | \$487,537.37 |  |  |  |  |  |  |  |  |
| Contract Total Payable This Estimate: | \$0.00        |                            |              |  |  |  |  |  |  |  |  |

### Items Paid This Estimate Period

# No Data Available Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

|                   |             | tments Exist on Contract   |                    |                                  |   |                        |                                       |                      |
|-------------------|-------------|--|--------------------|----------------------------------|---|------------------------|---------------------------------------|----------------------|
| Line Item         | Adjust      | ments This Estimate  |                    |                                  |   |                        |                                       |                      |
| Project<br>Number | Line<br>No. | Item Description   | Adjustment<br>Type | Other Item<br>Adjustment<br>Type | Comments  | Adjustment<br>Quantity | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>amount |
| J4S3251           | 0090        | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  | Material           |                                  |   | -533                   | \$13.65                               | (\$7,275.45)         |
|                   | 0090        | 090 TYPE 5 AGGREGATE FOR<br>BASE (6 IN. THICK)                                   |                    |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0001) due to user mcclon1<br>overridding Payment Estimate Exception 1 on<br>the current Payment Estimate. | 533                    | \$13.65                               | \$7,275.45           |
|                   | 0160        | PAVED APPROACH, 8 IN.  | Material           |                                  |   | -93                    | \$78.60                               | (\$7,309.80)         |
|                   | 0160        | PAVED APPROACH, 8 IN.  | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0002) due to user mcclon1<br>overridding Payment Estimate Exception 2 on<br>the current Payment Estimate. | 93                     | \$78.60                               | \$7,309.80           |
|                   | 0210        | FURNISHING AND PLACING<br>CONCRETE MATERIAL FOR<br>FULL DEPTH PAVEMENT<br>REPAIR | Material           |                                  |   | -206.4                 | \$451.80                              | (\$93,251.52)        |
|                   | 0210        | FURNISHING AND PLACING<br>CONCRETE MATERIAL FOR<br>FULL DEPTH PAVEMENT<br>REPAIR | Material           |                                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0003) due to user mcclon1<br>overridding Payment Estimate Exception 11                                    | 206.4                  | \$451.80                              | \$93,251.52          |

Revision 4/1/2020 Page 1 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 2, 2021

| Progress Estimate<br>Number | Contract ID         | 201218-C06                             | Pay Period<br>Start | June 16,<br>2021   | Original Contract Amount       | t\$2,392,908.04 |
|-----------------------------|---------------------|--|---------------------|--------------------|--------------------------------|-----------------|
| 5                           | Prime<br>Contractor | Superior Bowen Asphalt Company,<br>LLC | Pay Period End      | d June 30,<br>2021 | Net Change Order<br>Amount     | \$96,514.82     |
|                             |                     |  |                     |                    | <b>Current Contract Amount</b> | \$2,489,422.86  |

| Adjustment amount | Line Item<br>Adjustment<br>Unit Price | Adjustment<br>Quantity | Comments   | Other Item<br>Adjustment<br>Type   | Adjustment<br>Type | Item Description  | Line<br>No. | Project<br>Number |
|-------------------|---------------------------------------|------------------------|--|--|--------------------|---|-------------|-------------------|
|                   |                                       |                        | on the current Payment Estimate.   |  |                    |   |             | J4S3251           |
| (\$1,051.60)      | \$4.40                                | -239                   |  |  | Material           | DOWEL BAR (DRILLING,<br>FURNISHING AND<br>INSTALLATION) FOR FULL<br>DEPTH PAVEMENT REPAIR     | 0250        |                   |
| \$1,051.60        | \$4.40                                | 239                    | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0004) due to user mcclon1<br>overridding Payment Estimate Exception 14<br>on the current Payment Estimate. |  | Material           | DOWEL BAR (DRILLING,<br>FURNISHING AND<br>INSTALLATION) FOR FULL<br>DEPTH PAVEMENT REPAIR     | 0250        |                   |
| (\$60,287.00)     | \$95.00                               | -634.6                 |  |  | Material           | FURNISHING AND PLACING<br>BITUMINOUS MATERIAL<br>FOR CLASS C PARTIAL<br>DEPTH PAVEMENT REPAIR | 0260        |                   |
| \$60,287.00       | \$95.00                               | 634.6                  | This adjustment offsets the original system-<br>generated Material Payment Estimate Item<br>Adjustment (0005) due to user mcclon1<br>overridding Payment Estimate Exception 16<br>on the current Payment Estimate. | BITUMINOUS MATERIAL generated FOR CLASS C PARTIAL Adjust DEPTH PAVEMENT REPAIR overridding |                    | 0260  |             |                   |
| \$0.00            |                                       |                        |  |  |                    |   |             | Total             |

Revision 4/1/2020 Page 2 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

|                   |                            |                            |       |            | (   | Contract Project Information                       | n   |
|-------------------|----------------------------|----------------------------|-------|------------|---|--|---|
| Project<br>Number | Federal<br>Proj.<br>Number | Project<br>Description     | Route | County     |   |  | Location of Work                                  |
| J4S3251           | FAS<br>S302(75)            | Resurface                  | 78    | JACKSON    | from Speck Road to Rte.                     | . 7  |   |
| J4S3258           | FAS<br>S302(78)            | Resurface                  | 78    | JACKSON    | from Rte. 291 to Belmon                     | t Boulevard  |   |
| Γotals by .       | Job Numbe                  | rs                         |       |            |   |  |   |
| J4S3251           |                            | d Item Pay<br>Item Adjustm |       | s Item Pay | This Estimate<br>\$0.00<br>\$0.00<br>\$0.00 | Previous<br>\$487,537.37<br>\$0.00<br>\$487,537.37 | To Date<br>\$487,537.37<br>\$0.00<br>\$487,537.37 |
|                   |                            |                            |       | i          | \$0.00<br>\$0.00<br>\$0.00<br>\$0.00        | \$0.00<br>\$0.00<br>\$0.00<br>\$0.00               | \$0.00<br>\$0.00<br>\$0.00<br>\$0.00              |
| J4S3258           |                            | d Item Pay<br>Item Adjustm |       | s Item Pay | This Estimate<br>\$0.00<br>\$0.00<br>\$0.00 | Previous<br>\$0.00<br>\$0.00<br>\$0.00             | To Date<br>\$0.00<br>\$0.00<br><b>\$0.00</b>      |
|                   |                            |                            |       |            | \$0.00<br>\$0.00<br>\$0.00<br>\$0.00        | \$0.00<br>\$0.00<br>\$0.00<br>\$0.00               | \$0.00<br>\$0.00<br>\$0.00<br>\$0.00              |

Revision 4/1/2020 Page 3 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

| Exceptions (Discrepancies) This Estimate Ferroa   |                                   |               |            |
|---|-----------------------------------|---------------|------------|
| Exceptions / Discrepencies  | Explanation                       | Entered<br>By | Status     |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 3040506, Project Item Line Number 0090, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.        | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6085008, Project Item Line Number 0160, Material Set 608500896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.      | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6085008, Project Item Line Number 0160, Material Set 608500896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.      | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6085008, Project Item Line Number 0160, Material Set 608500896, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.                             | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6085008, Project Item Line Number 0160, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.                  | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6085008, Project Item Line Number 0160, Material Set 608500896, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.                             | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6085008, Project Item Line Number 0160, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.                 | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6085008, Project Item Line Number 0160, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.            | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6085008, Project Item Line Number 0160, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6085008, Project Item Line Number 0160, Material Set 608500896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient. | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6131010, Project Item Line Number 0210, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.                           | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6131010, Project Item Line Number 0210, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.                 | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6131010, Project Item Line Number 0210, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.                  | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6131015, Project Item Line Number 0250, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.            | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6131015, Project Item Line Number 0250, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.                    | No Remark was entered by Engineer | mcclon1       | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3251, Item 6133020, Project Item Line Number 0260, Material Set 613302096, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.                      | No Remark was entered by Engineer | mcclon1       | Overridden |

Revision 4/1/2020 Page 4 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | eport Generated date and can differ from the posted amo  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit | Total<br>Posted<br>Approved<br>Qty | Unit Price   | Total Value POSTED<br>To Date (See report<br>generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| 201218-C06              | J4S3251        | 0001     | 0010        | 2022010      | REMOVAL OF IMPROVEMENTS  | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$40,157.60  | \$0.00   |
|                         |                | 0001     | 0020        | 2063000      | CLASS 3 EXCAVATION   | 43.00           | 0.00                   | 43.00                        | CUYD | 0.00                               | \$12.00      | \$0.00   |
|                         |                | 0001     | 0030        | 2071000      | LINEAR GRADING CLASS 1   | 1.20            | 0.00                   | 1.20                         | STA  | 0.00                               | \$9,830.00   | \$0.00   |
|                         |                | 0001     | 0040        | 2099905      | MISC.MODIFIED 6 INCH SUBGRADE COMPACTION   | 350.00          | 0.00                   | 350.00                       | SQYD | 0.00                               | \$4.30       | \$0.00   |
|                         |                | 0001     | 0050        | 2122000A     | SUBGRADING AND SHOULDERING CLASS 2   | 6.00            | 0.00                   | 6.00                         | 100F | 0.00                               | \$756.00     | \$0.00   |
|                         |                | 0001     | 0060        | 2152000A     | SHAPING SLOPES, CLASS II   | 1.00            | 0.00                   | 1.00                         | 100F | 0.00                               | \$2,167.00   | \$0.00   |
|                         |                | 0001     | 0070        | 2153000      | SHAPING SLOPES, CLASS III  | 5.00            | 0.00                   | 5.00                         | 100F | 0.00                               | \$675.00     | \$0.00   |
|                         |                | 0001     | 0080        | 3040504      | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)  | 706.00          | 0.00                   | 706.00                       | SQYD | 0.00                               | \$23.00      | \$0.00   |
|                         |                | 0001     | 0090        | 3040506      | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  | 533.00          | 0.00                   | 533.00                       | SQYD | 533.00                             | \$13.65      | \$7,275.45   |
|                         |                | 0001     | 0100        | 4011209      | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  | 1,986.00        | 0.00                   | 1,986.00                     | TONS | 0.00                               | \$85.00      | \$0.00   |
|                         |                | 0001     | 0110        | 4013000      | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)   | 110.00          | 0.00                   | 110.00                       | TONS | 0.00                               | \$105.00     | \$0.00   |
|                         |                | 0001     | 0120        | 4030103      | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)   | 10,636.00       | 0.00                   | 10,636.00                    | TONS | 0.00                               | \$65.00      | \$0.00   |
|                         |                | 0001     | 0130        | 4071005      | TACK COAT  | 12,756.00       | 0.00                   | 12,756.00                    | GAL  | 0.00                               | \$2.15       | \$0.00   |
|                         |                | 0001     | 0140        | 6081010      | CONCRETE CURB RAMP   | 36.00           | 0.00                   | 36.00                        | SQYD | 0.00                               | \$201.30     | \$0.00   |
|                         |                | 0001     | 0150        | 6081012      | TRUNCATED DOMES  | 48.00           | 0.00                   | 48.00                        | SQFT | 0.00                               | \$26.10      | \$0.00   |
|                         |                | 0001     | 0160        | 6085008      | PAVED APPROACH, 8 IN.  | 350.00          | 0.00                   | 350.00                       | SQYD | 93.00                              | \$78.60      | \$7,309.80   |
|                         |                | 0001     | 0170        | 6092011      | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A  | 100.00          | 0.00                   | 100.00                       | LF   | 0.00                               | \$12.00      | \$0.00   |
|                         |                | 0001     | 0180        | 6097000      | ROCK LINING  | 2.00            | 0.00                   | 2.00                         | CUYD | 0.00                               | \$501.00     | \$0.00   |
|                         |                | 0001     | 0190        | 6122012      | IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)   | 1.00            | 0.00                   | 1.00                         | EA   | 0.00                               | \$2,000.00   | \$0.00   |
|                         |                | 0001     | 0200        | 6122020      | REPLACEMENT SAND BARREL  | 2.00            | 0.00                   | 2.00                         | EA   | 0.00                               | \$290.00     | \$0.00   |
|                         |                | 0001     | 0210        | 6131010      | FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL  | 96.00           | 110.40                 | 206.40                       | SQYD | 206.40                             | \$451.80     | \$93,251.52  |
|                         |                | 0001     | 0220        | 6131012      | DEPTH PAVEMENT REPAIR SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)                          | 31.00           | -31.00                 | 0.00                         | SQYD | 0.00                               | \$1.00       | \$0.00   |
|                         |                | 0001     | 0230        | 6131013      | TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)                                     | 31.00           | -31.00                 | 0.00                         | SQYD | 0.00                               | \$1.00       | \$0.00   |
|                         |                | 0001     | 0240        | 6131014      | FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)                           | 396.00          | 380.00                 | 776.00                       | LF   | 776.00                             | \$1.75       | \$1,358.00   |
|                         |                | 0001     | 0250        | 6131015      | DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR                   | 240.00          | -1.00                  | 239.00                       | EA   | 239.00                             | \$4.40       | \$1,051.60   |
|                         |                | 0001     | 0260        | 6133020      | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR               | 537.10          | 97.50                  | 634.60                       | TONS | 634.60                             | \$95.00      | \$60,287.00  |
|                         |                | 0001     | 0270        | 6133021      | REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR  | 1,934.60        | 294.20                 | 2,228.80                     | SQYD | 2,228.80                           | \$125.00     | \$278,600.00   |
|                         |                | 0001     | 0280        | 6141021      | GRATE AND BEARING PLATE (3 FT. X 2 FT. OR 914 MM X 610 MM)   | 1.00            | 0.00                   | 1.00                         | EA   | 1.00                               | \$926.00     | \$926.00   |
|                         |                | 0001     | 0290        | 6161005      | CONSTRUCTION SIGNS   | 1,307.00        | 0.00                   | 1,307.00                     | SQFT | 914.00                             | \$3.00       | \$2,742.00   |
|                         |                | 0001     | 0300        | 6161008      | ADVANCED WARNING RAIL SYSTEM   | 18.00           | 0.00                   | 18.00                        | EA   | 0.00                               | \$25.00      | \$0.00   |
|                         |                | 0001     | 0310        | 6161009      | FLAG ASSEMBLY  | 34.00           | 0.00                   | 34.00                        | EA   | 0.00                               | \$25.00      | \$0.00   |
|                         |                | 0001     | 0320        | 6161025      | CHANNELIZER (TRIM LINE)  | 275.00          | 0.00                   | 275.00                       | EA   | 272.00                             | \$13.00      | \$3,536.00   |
|                         |                | 0001     | 0330        | 6161030      | TYPE III MOVEABLE BARRICADE  | 10.00           | 0.00                   | 10.00                        | EA   | 2.00                               | \$90.00      | \$180.00   |
|                         |                | 0001     | 0340        | 6161033      | DIRECTIONAL INDICATOR BARRICADE  | 56.00           | 0.00                   | 56.00                        | EA   | 0.00                               | \$40.00      | \$0.00   |
|                         |                | 0001     | 0350        | 6161040      | FLASHING ARROW PANEL   | 4.00            | 0.00                   | 4.00                         | EA   | 3.00                               | \$650.00     | \$1,950.00   |
|                         |                | 0001     | 0360        | 6161055      | SEQUENTIAL FLASHING WARNING LIGHT  | 60.00           | 0.00                   | 60.00                        | EA   | 0.00                               | \$55.00      | \$0.00   |
|                         |                | 0001     | 0365        | 6161070      | TUBULAR MARKER   | 130.00          | 0.00                   | 130.00                       | EA   | 0.00                               | \$70.00      | \$0.00   |
|                         |                | 0001     | 0370        | 6161098A     | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 4.00            | 0.00                   | 4.00                         | EA   | 4.00                               | \$2,100.00   | \$8,400.00   |
|                         |                | 0001     | 0380        | 6162004      | TEMPORARY SHORT-TERM RUMBLE STRIPS   | 6.00            | 0.00                   | 6.00                         | EA   | 0.00                               | \$2,190.00   | \$0.00   |
|                         |                | 0001     | 0390        | 6181000      | MOBILIZATION   | 1.00            | 0.00                   | 1.00                         | LS   | 0.00                               | \$267,000.00 | \$0.00   |
|                         |                | 0001     | 0400        | 6200009      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE  | 11,163.00       | 0.00                   | 11,163.00                    | LF   | 0.00                               | \$3.30       | \$0.00   |
|                         |                | 0001     | 0410        | 6200015      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE   | 1,366.00        | 0.00                   | 1,366.00                     | LF   | 0.00                               | \$12.00      | \$0.00   |
|                         |                | 0001     | 0420        | 6200018      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW  | 2,179.00        | 0.00                   | 2,179.00                     | LF   | 0.00                               | \$12.00      | \$0.00   |
|                         |                | 0001     | 0430        | 6200021      | PREFORMED THERMOPLASTIC PAVEMENT MARKING,  | 12.00           | 0.00                   | 12.00                        | EA   | 0.00                               | \$200.00     | \$0.00   |

Page 5 of 12 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| lote: Posted Q          | uantities      | and Valu | es are b    | ased on R    | eport Generated date and can differ from the posted am                               | ount at the     | time the               | Estimate wa                  | s Gene | rated.                             |                        |  |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|--------|------------------------------------|------------------------|--|
| Contract<br>Nm.CONTRACT | Project<br>No. | Category | Line<br>No. | Item<br>Code | Description  | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit   | Total<br>Posted<br>Approved<br>Qty | Unit Price             | Total Value POSTED<br>To Date (See report<br>generated date) |
| 201218-C06              | J4S3251        |          |             |              | LEFT/RIGHT ARROW   |                 |                        |                              |        | Qty                                |                        |  |
|                         |                | 0001     | 0440        | 6200024      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW                             | 4.00            | 0.00                   | 4.00                         | EA     | 0.00                               | \$200.00               | \$0.00   |
|                         |                | 0001     | 0450        | 6200036      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK                       | 87.00           | 0.00                   | 87.00                        | EA     | 0.00                               | \$100.00               | \$0.00   |
|                         |                | 0001     | 0460        | 6200045      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LT/RT FISH HOOK ARROW                      | 4.00            | 0.00                   | 4.00                         | EA     | 0.00                               | \$450.00               | \$0.00   |
|                         |                | 0001     | 0470        | 6205901A     | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS              | 38,649.00       | 0.00                   | 38,649.00                    | LF     | 0.00                               | \$0.15                 | \$0.00   |
|                         |                | 0001     | 0480        | 6205902A     | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS               | 57,738.00       | 0.00                   | 57,738.00                    | LF     | 0.00                               | \$0.18                 | \$0.00   |
|                         |                | 0001     | 0490        | 6205903A     | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT<br>MARKING PAINT, TYPE L BEADS           | 24,005.00       | 0.00                   | 24,005.00                    | LF     | 0.00                               | \$0.18                 | \$0.00   |
|                         |                | 0001     | 0500        | 6207001      | PAVEMENT MARKING REMOVAL   | 2,140.00        | 0.00                   | 2,140.00                     | LF     | 0.00                               | \$0.50                 | \$0.00   |
|                         |                | 0001     | 0510        | 6208064A     | TEMPORARY RAISED PAVEMENT MARKER   | 70.00           | 0.00                   | 70.00                        | EA     | 0.00                               | \$3.00                 | \$0.00   |
|                         |                | 0001     | 0520        | 6209903      | MISC.OPTIONAL TEMPORARY PAVEMENT MARKING   | 16,500.00       | 0.00                   | 16,500.00                    | LF     | 0.00                               | \$0.06                 | \$0.00   |
|                         |                | 0001     | 0530        | 6221001      | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)       | 131,241.00      | 0.00                   | 131,241.00                   | SQYD   | 0.00                               | \$1.47                 | \$0.00   |
|                         |                | 0001     | 0540        | 6261000A     | BITUMINOUS SHOULDER RUMBLE STRIP   | 256.30          | 0.00                   | 256.30                       | STA    | 0.00                               | \$28.50                | \$0.00   |
|                         |                | 0001     | 0550        | 6261001      | BITUMINOUS CENTERLINE RUMBLE STRIP   | 43.90           | 0.00                   | 43.90                        | STA    | 0.00                               | \$28.50                | \$0.00   |
|                         |                | 0001     | 0560        | 6269905      |  | 293.00          | 0.00                   | 293.00                       | SQYD   | 0.00                               | \$25.00                | \$0.00   |
|                         |                | 0001     | 0570        | 6274000      | CONTRACTOR FURNISHED SURVEYING AND STAKING   | 1.00            | 0.00                   | 1.00                         | LS     | 0.00                               | \$10,000.00            | \$0.00   |
|                         |                | 0001     | 0580        | 7261015      | 15 IN. PIPE GROUP A  | 56.00           | 0.00                   | 56.00                        | LF     | 56.00                              | \$269.00               | \$15,064.00  |
|                         |                | 0001     | 0590        | 7311032      | PRECAST CONCRETE DROP INLET 3 FT X 2 FT  | 3.00            | 0.00                   | 3.00                         | FT     | 3.00                               | \$1,472.00             | \$4,416.00   |
|                         |                | 0001     | 0600        | 7320615A     | 15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION                              | 1.00            | 0.00                   | 1.00                         | EA     | 1.00                               | \$1,190.00             | \$1,190.00   |
|                         |                | 0001     | 0610        | 7321018A     | 36 IN. OR ALLOWED SUBSTITUTE SAFETY SLOPE END SECTION                                | 2.00            | 0.00                   | 2.00                         | EA     | 0.00                               | \$4,912.00             | \$0.00   |
|                         |                | 0001     | 0620        | 8051000A     | SEEDING - COOL SEASON MIXTURES   | 0.10            | 0.00                   | 0.10                         | ACRE   | 0.00                               | \$24,600.00            | \$0.00   |
|                         |                | 0010     | 0630        | 6061060      | MGS GUARDRAIL  | 1,338.00        | 0.00                   | 1,338.00                     | LF     | 0.00                               | \$18.25                | \$0.00   |
|                         |                | 0010     | 0640        | 6061069      | MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)                             | 5.00            | 0.00                   | 5.00                         | EA     | 0.00                               | \$2,400.00             | \$0.00   |
|                         |                | 0010     | 0650        | 6061080      | MGS END ANCHOR   | 1.00            | 0.00                   | 1.00                         | EA     | 0.00                               | \$953.00               | \$0.00   |
|                         |                | 0010     | 0660        | 6063014      | TYPE A CRASHWORTHY END TERMINAL (MASH)   | 6.00            | 0.00                   | 6.00                         | EA     | 0.00                               | \$2,384.00             | \$0.00   |
|                         |                | 0030     | 0670        | 9020811      | SIGNAL HEAD, TYPE 1S, PEDESTRIAN SH-FLAT SHEET - SIGNAL SIGN                         | 4.00            | 0.00                   | 4.00                         | EA     | 0.00                               | \$1,447.00             | \$0.00   |
|                         |                | 0030     | 0680        | 9020833      | MISC.Accessible Pedestrian Signals (Pushbuttons)                                     | 4.00            | 0.00                   | 4.00                         | SQFT   | 0.00                               | \$206.00<br>\$1,874.00 | \$0.00   |
|                         | Dunia et L     |          |             |              |  | 4.00            | 0.00                   | 4.00                         | EA     | 0.00                               | \$1,674.00             | -  |
|                         | J4S3258        | 0001     | 0700        | 2022010      | late as of Report Generated Date  REMOVAL OF IMPROVEMENTS                            | 1.00            | 0.00                   | 1.00                         | LS     | 0.00                               | \$3,000.00             | \$487,537.37<br>\$0.00                                       |
|                         |                | 0001     | 0710        | 3040504      | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)  | 51.00           | 0.00                   | 51.00                        | SQYD   | 0.00                               | \$52.95                | \$0.00   |
|                         |                | 0001     | 0720        | 4030103      | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)                                     | 851.10          | 0.00                   | 851.10                       | TONS   | 0.00                               | \$62.89                | \$0.00   |
|                         |                | 0001     | 0730        | 4071005      | TACK COAT  | 706.00          | 0.00                   | 706.00                       | GAL    | 0.00                               | \$2.15                 | \$0.00   |
|                         |                | 0001     | 0740        | 5029905      | MISC.Place UTW High Early Strength Concrete  | 129.80          | 0.00                   | 129.80                       | SQYD   | 0.00                               | \$395.80               | \$0.00   |
|                         |                | 0001     | 0750        | 5029907      | MISC.Furnish UTW High Early Strength Concrete  | 25.00           | 0.00                   | 25.00                        | CUYD   | 0.00                               | \$475.25               | \$0.00   |
|                         |                | 0001     | 0760        | 6133020      | FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR | 2.20            | 0.00                   | 2.20                         | TONS   | 0.00                               | \$500.00               | \$0.00   |
|                         |                | 0001     | 0770        | 6133021      | REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR                                    | 8.00            | 0.00                   | 8.00                         | SQYD   | 0.00                               | \$325.00               | \$0.00   |
|                         |                | 0001     | 0780        | 6181000      | MOBILIZATION   | 1.00            | 0.00                   | 1.00                         | LS     | 0.00                               | \$75,000.00            | \$0.00   |
|                         |                | 0001     | 0790        | 6200009      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE                                | 4,201.00        | 0.00                   | 4,201.00                     | LF     | 0.00                               | \$1.70                 | \$0.00   |
|                         |                | 0001     | 0800        | 6200015      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE                               | 264.00          | 0.00                   | 264.00                       | LF     | 0.00                               | \$8.00                 | \$0.00   |
|                         |                | 0001     | 0810        | 6200018      | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW                              | 80.00           | 0.00                   | 80.00                        | LF     | 0.00                               | \$12.00                | \$0.00   |
|                         |                | 0001     | 0820        | 6200021      | PREFORMED THERMOPLASTIC PAVEMENT MARKING,<br>LEFT/RIGHT ARROW                        | 23.00           | 0.00                   | 23.00                        | EA     | 0.00                               | \$135.00               | \$0.00   |
|                         |                | 0001     | 0830        | 6205902A     | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING<br>PAINT, TYPE L BEADS            | 3,780.00        | 0.00                   | 3,780.00                     | LF     | 0.00                               | \$0.18                 | \$0.00   |
|                         |                | 0001     | 0840        | 6205903A     | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT  | 4,061.00        | 0.00                   | 4,061.00                     | LF     | 0.00                               | \$0.18                 | \$0.00   |
|                         |                |          |             |              | MARKING PAINT, TYPE L BEADS  | ,               |                        | ,                            |        |                                    |                        | ļ  |

Revision 4/1/2020 Page 6 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract<br>Nm.CONTRACT   | Project<br>No. | Category    | Line<br>No. | Item<br>Code | Description   | Bid<br>Quantity | Net<br>Change<br>Order | Total<br>Current<br>Quantity | Unit | Total<br>Posted<br>Approved<br>Qty | Unit Price | Total Value POSTED<br>To Date (See report<br>generated date) |
|---|----------------|-------------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|------------|--|
| 201218-C06  | J4S3258        | 0001        | 0850        | 6221001      | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)      | 8,829.00        | 0.00                   | 8,829.00                     | SQYD | 0.00                               | \$2.07     | \$0.00   |
|   |                | 0001        | 0860        | 6221003      | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK) | 130.00          | 0.00                   | 130.00                       | SQYD | 0.00                               | \$113.00   | \$0.00   |
|   |                | 0030        | 0870        | 9028500      | CABLE, LOOP DETECTOR, IN DUCT   | 2,060.00        | 0.00                   | 2,060.00                     | LF   | 0.00                               | \$13.20    | \$0.00   |
|   | Project J      | 4S3258 - To | tal Value   | Posted to D  | Date as of Report Generated Date  |                 |                        |                              |      |                                    |            | \$0.00   |
| 201218-C06 Overall - Total Value Posted to Date as of Report Generated Date |                |             |             |              |   |                 |                        |                              |      | \$487,537.37                       |            |  |

Revision 4/1/2020 Page 7 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 8 of 12



## Line Item Adjustments by Estimate

| Project | Line   | Description                        | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By  | Amount         | Remarks   |  |             |   |
|---------|--------|------------------------------------|--------------------|-----------------------------|----------------|-----------------|----------------|----------------|---|--|-------------|---|
| J4S3251 | 0090   | TYPE 5<br>AGGREGATE<br>FOR BASE (6 | Material           |                             | 4              | Jun 17,<br>2021 | SYSTEM         | \$7,275.45     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  |  |             |   |
|         |        | IN. THICK)                         |                    |                             | 4              | Jun 17,<br>2021 | SYSTEM         | (\$7,275.45)   |   |  |             |   |
|         |        |                                    |                    |                             | 5              | Jul 2,<br>2021  | SYSTEM         | \$7,275.45     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  |  |             |   |
|         |        |                                    |                    |                             | 5              | Jul 2,<br>2021  | SYSTEM         | (\$7,275.45)   |   |  |             |   |
|         |        |                                    |                    | - Total                     |                |                 |                | \$0.00         |   |  |             |   |
|         |        |                                    | Material - To      | otal                        |                |                 |                | \$0.00         |   |  |             |   |
|         | 0090 - | Total                              |                    |                             |                |                 |                | \$0.00         |   |  |             |   |
|         | 0160   | PAVED                              | Material           |                             | 4              | Jun 17,         | SYSTEM         |                | This adjustment affects the original system generated Material Poyment  |  |             |   |
|         |        | APPROACH, 8<br>IN.                 | Material           |                             |                | 2021            |                | \$7,309.80     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  |  |             |   |
|         |        |                                    |                    |                             | 4              | Jun 17,<br>2021 | SYSTEM         | (\$7,309.80)   |   |  |             |   |
|         |        |                                    |                    |                             | 5              | Jul 2,<br>2021  | SYSTEM         | \$7,309.80     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  |  |             |   |
|         |        |                                    |                    |                             | 5              | Jul 2,<br>2021  | SYSTEM         | (\$7,309.80)   |   |  |             |   |
|         |        |                                    |                    | - Total                     |                |                 |                | \$0.00         |   |  |             |   |
|         |        |                                    | Material - To      | otal                        |                |                 |                | \$0.00         |   |  |             |   |
|         | 0160 - | Total                              |                    |                             |                |                 |                | \$0.00         |   |  |             |   |
|         | 0210   |                                    | Material           | Material                    |                | 1               | May 4,<br>2021 | SYSTEM         | \$93,251.52   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |             |   |
|         |        |                                    |                    |                             |                |                 | 1              | May 4,<br>2021 | SYSTEM  | (\$93,251.52)  |             |   |
|         |        |                                    |                    |                             | 2              | May 17,<br>2021 | SYSTEM         | \$93,251.52    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  |  |             |   |
|         |        |                                    |                    |                             | 2              | May 17,<br>2021 | SYSTEM         | (\$93,251.52)  |   |  |             |   |
|         |        |                                    |                    |                             | 3              | Jun 1,<br>2021  | SYSTEM         | \$93,251.52    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  |  |             |   |
|         |        |                                    |                    |                             | 3              | Jun 1,<br>2021  | SYSTEM         | (\$93,251.52)  |   |  |             |   |
|         |        |                                    |                    |                             | 4              | Jun 17,<br>2021 | SYSTEM         | \$93,251.52    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcclon1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |  |             |   |
|         |        |                                    |                    |                             | 4              | Jun 17,<br>2021 | SYSTEM         | (\$93,251.52)  |   |  |             |   |
|         |        |                                    |                    |                             | 5              | Jul 2,<br>2021  | SYSTEM         | \$93,251.52    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcclon1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |  |             |   |
|         |        |                                    |                    |                             | 5              | Jul 2,<br>2021  | SYSTEM         | (\$93,251.52)  |   |  |             |   |
|         |        |                                    |                    | - Total                     |                |                 |                | \$0.00         |   |  |             |   |
|         |        |                                    | Material - To      | aterial - Total             |                |                 |                | \$0.00         |   |  |             |   |
|         |        |                                    | Overrun            | Overrun                     | Overrun        | Overrun         | Overrun        | 1              | May 4,<br>2021  | SYSTEM   | \$49,878.72 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 206.400; Overrun Quantity Balance 110.40. |
|         |        |                                    |                    |                             | 1              | May 4,<br>2021  | SYSTEM         | (\$49,878.72)  |   |  |             |   |
|         |        |                                    |                    |                             | 2              | May 17,<br>2021 | SYSTEM         | (\$49,878.72)  | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).   |  |             |   |
|         |        |                                    |                    |                             | 2              | May 17,<br>2021 | SYSTEM         | \$49,878.72    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8  |  |             |   |



## Line Item Adjustments by Estimate

| oject | Line   | Description                                       | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks   |        |                |  |            |   |  |   |                |        |              |  |
|-------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|--------|----------------|--|------------|---|--|---|----------------|--------|--------------|--|
| 3251  | 0210   | FURN &<br>PLACE CONC<br>MATL FOR                  | Overrun            | Overrun                     |                |                 |               |               | on the current Payment Estimate. Material Insufficiency Quantity 206.400; Overrun Quantity Balance 110.40.  |        |                |  |            |   |  |   |                |        |              |  |
|       |        | FULL DEPTH  |                    |                             | 3              | Jun 1,<br>2021  | SYSTEM        | (\$49,878.72) | Averaged Price Adjustment from this item on all previous payment estimate of '0.00000' is applied (if non-zero).  |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   |                    |                             | 3              | Jun 1,<br>2021  | SYSTEM        | \$49,878.72   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception on the current Payment Estimate. Material Insufficiency Quantity 206.400; Overrun Quantity Balance 110.40. |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   |                    | Overrun - To                | otal           |                 |               | \$0.00        |   |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   | Overrun - T        | otal                        |                |                 |               | \$0.00        |   |        |                |  |            |   |  |   |                |        |              |  |
|       | 0210 - | Total   |                    |                             |                |                 |               | \$0.00        |   |        |                |  |            |   |  |   |                |        |              |  |
|       | 0240   | FULL DEPTH<br>PAVEMENT<br>REPAIR SAW<br>CUT (FOR  | Overrun            | Overrun                     | 1              | May 4,<br>2021  | SYSTEM        | \$665.00      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mcclon1 overridding Paymen Estimate Exception 9 on the current Payment Estimate.  |        |                |  |            |   |  |   |                |        |              |  |
|       |        | 001 (1011   |                    |                             | 1              | May 4,<br>2021  | SYSTEM        | (\$665.00)    |   |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   |                    |                             | 2              | May 17,<br>2021 | SYSTEM        | (\$665.00)    | Averaged Price Adjustment from this item on all previous payment estimat of '0.00000' is applied (if non-zero).   |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   |                    |                             | 2              | May 17,<br>2021 | SYSTEM        | \$665.00      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mcclon1 overridding Paymer Estimate Exception 9 on the current Payment Estimate.  |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   |                    |                             | 3              | Jun 1,<br>2021  | SYSTEM        | (\$665.00)    | Averaged Price Adjustment from this item on all previous payment estimat of '0.00000' is applied (if non-zero).   |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   |                    |                             | 3              | Jun 1,<br>2021  | SYSTEM        | \$665.00      | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mcclon1 overridding Paymen Estimate Exception 8 on the current Payment Estimate.  |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   |                    | Overrun - To                | otal           |                 |               | \$0.00        |   |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   | Overrun - T        | otal                        |                |                 |               | \$0.00        |   |        |                |  |            |   |  |   |                |        |              |  |
|       | 0240 - | Total   |                    |                             |                |                 |               | \$0.00        |   |        |                |  |            |   |  |   |                |        |              |  |
|       | 0250   | DOWEL BAR<br>(DRILLING,<br>FURNISHING<br>AND INST |                    |                             | 1              | May 4,<br>2021  | SYSTEM        | \$1,051.60    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mcclon1 overridding Paymer Estimate Exception 4 on the current Payment Estimate.   |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   |                    |                             |                |                 |               |               |   |        |                |  |            |   |  | 1 | May 4,<br>2021 | SYSTEM | (\$1,051.60) |  |
|       |        |   |                    |                             |                |                 |               | 2             | May 17,<br>2021   | SYSTEM | \$1,051.60     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcclon1 overridding Paymer Estimate Exception 4 on the current Payment Estimate.  |            |   |  |   |                |        |              |  |
|       |        |   |                    |                             |                |                 |               |               |   |        | 2              | May 17,<br>2021  | SYSTEM     | (\$1,051.60)  |  |   |                |        |              |  |
|       |        |   |                    |                             |                |                 |               |               |   | 3      | Jun 1,<br>2021 | SYSTEM   | \$1,051.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcclon1 overridding Paymer Estimate Exception 4 on the current Payment Estimate. |  |   |                |        |              |  |
|       |        |   |                    |                             | 3              | Jun 1,<br>2021  | SYSTEM        | (\$1,051.60)  |   |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   |                    |                             |                |                 |               | 4             | Jun 17,<br>2021   | SYSTEM | \$1,051.60     | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcclon1 overridding Paymer Estimate Exception 14 on the current Payment Estimate. |            |   |  |   |                |        |              |  |
|       |        |   |                    |                             | 4              | Jun 17,<br>2021 | SYSTEM        | (\$1,051.60)  |   |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   |                    |                             | 5              | Jul 2,<br>2021  | SYSTEM        | \$1,051.60    | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 14 on the current Payment Estimate.   |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   |                    |                             | 5              | Jul 2,<br>2021  | SYSTEM        | (\$1,051.60)  |   |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   |                    | - Total                     |                |                 |               | \$0.00        |   |        |                |  |            |   |  |   |                |        |              |  |
|       |        |   | Material - To      | otal                        |                |                 |               | \$0.00        |   |        |                |  |            |   |  |   |                |        |              |  |
|       | 0250 - | Total   |                    |                             |                |                 |               | \$0.00        |   |        |                |  |            |   |  |   |                |        |              |  |
|       | 0000   | FURN &  | Material           |                             | 1              | May 4,          | SYSTEM        | \$57,627.00   | This adjustment offsets the original system-generated Material Payment  |        |                |  |            |   |  |   |                |        |              |  |
|       | 0260   | PLACE BIT.<br>MATL FOR CL<br>C PARTIAL            |                    |                             |                | 2021            |               |               | Estimate Item Adjustment (0006) due to user mcclon1 overridding Paymer Estimate Exception 6 on the current Payment Estimate.  |        |                |  |            |   |  |   |                |        |              |  |



## Line Item Adjustments by Estimate

| PALCE BIT   NAT FOR TO   2011   1  | Project | Line   | Description               | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount        | Remarks   |
|--|---------|--------|---------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 2  | J4S3251 | 0260   | PLACE BIT.<br>MATL FOR CL | Material           |                             | 2              |                 | SYSTEM        | \$57,627.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  |
| 2021   SYSTEM   357,527,000   STREAM   SYSTEM   STREAM  |         |        | CFARTIAL                  |                    |                             | 2              |                 | SYSTEM        | (\$57,627.00) |   |
| A  |         |        |                           |                    |                             | 3              |                 | SYSTEM        | \$57,627.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  |
| 2021   SYSTEM   September  |         |        |                           |                    |                             | 3              |                 | SYSTEM        | (\$57,627.00) |   |
| 2021   5   |         |        |                           |                    |                             | 4              |                 | SYSTEM        | \$60,287.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcclon1 overridding Payment Estimate Exception 16 on the current Payment Estimate.   |
| 2021   Estimate Exception 16 on the current Payment Estimate.  |         |        |                           |                    |                             | 4              |                 | SYSTEM        | (\$60,287.00) |   |
| Total  |         |        |                           |                    |                             | 5              |                 | SYSTEM        | \$60,287.00   | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcclon1 overridding Payment Estimate Exception 16 on the current Payment Estimate.   |
| Material - Total   |         |        |                           |                    |                             | 5              |                 | SYSTEM        | (\$60,287.00) |   |
| Overrun  |         |        |                           |                    | - Total                     |                |                 |               | \$0.00        |   |
|  |         |        |                           | Material - To      | otal                        |                |                 |               | \$0.00        |   |
| 2021   SYSTEM   S6,602.50    Averaged Price Adjustment (0005) overidding Payment Estimate I on the current Payment Estimate Issumate. Material Insufficiency Quantily Overrun Quantity Balance 69.50.    1   |         |        |                           | Overrun            | Overrun                     | 1              |                 | SYSTEM        | \$4,902.00    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 10 on the current Payment Estimate. Material Insufficiency Quantity 606.600; Overrun Quantity Balance 69.50. |
| 2021 2 May 17, 2021 2 May 17, 2021 3 Jun 1, 2021 3 Jun 1, 2021 5 SySTEM (\$6,602.50) 3 Jun 1, 2021 3 Jun 1, 2021 5 SySTEM (\$6,602.50) 4 SySTEM (\$6,602.50) 3 Jun 1, 2021 3 Jun 1, 2021 5 SySTEM (\$6,602.50) 4 SySTEM (\$6,602.50) 5 SySTEM (\$6,602.50) 5 SySTEM (\$6,602.50) 6 SySTEM (\$6,602.50) 7 SySTEM (\$6,602 |         |        |                           |                    |                             | 1              |                 | SYSTEM        | \$1,700.50    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 10 on the current Payment Estimate. Material Insufficiency Quantity 606.600; Overrun Quantity Balance 69.50. |
| 2021 2 May 17, 2021 3 May 14, 2021 2 May 17, 2021 2 May 17, 2021 2 May 17, 2021 3 May 17, 2021 3 May 18, 2021 2 May 17, 2021 2 May 17, 2021 3   |         |        |                           |                    |                             | 1              |                 | SYSTEM        | (\$6,602.50)  |   |
| 2021   SYSTEM   Section   System   Syste   |         |        |                           |                    |                             | 2              |                 | SYSTEM        | (\$6,602.50)  | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).   |
| 2021   SYSTEM   \$6,602.50   This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overrun Hestimate.  |         |        |                           |                    |                             | 2              |                 | SYSTEM        | \$6,602.50    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 10 on the current Payment Estimate. Material Insufficiency Quantity 606.600; Overrun Quantity Balance 69.50. |
| Description   Support   Stimate   Item Adjustment (0004) overridding Payment Estimate   Stimate   Item Adjustment   Stimate   Item Adjustment   Stimate   Stimate   Item Adjustment   Stimate   St   |         |        |                           |                    |                             | 3              |                 | SYSTEM        | (\$6,602.50)  | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).   |
| Solution  |         |        |                           |                    |                             | 3              |                 | SYSTEM        | \$6,602.50    | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 606.600; Overrun Quantity Balance 69.50.  |
| Solid   Seminary   S   |         |        |                           |                    | Overrun - To                | otal           |                 |               | \$0.00        |   |
| Overrun FOR CLASS C PARTIAL DEPTH PAVT REPAIR  Overrun Payment Estimate  Nay 4, 2021  May 17, 2021   |         |        |                           | Overrun - T        | otal                        |                |                 |               | \$0.00        |   |
| FOR CLASS C PARTIAL DEPTH PAVT REPAIR  1 May 4, 2021  2 May 17, 2021  2 May 17, 2021  2 May 17, 2021  2 May 17, 2021  3 Jun 1, 2021  3 Jun 1, 2021  3 SYSTEM (\$36,775.00)  Estimate Item Adjustment (0007) due to user mcclon1 overridding Estimate Exception 11 on the current Payment Estimate.  Estimate Exception 11 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous paymer of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Prestimate Exception 11 on the current Payment Estimate Exception 11 on the current Payment Estimate of '0.00000' is applied (if non-zero).  3 Jun 1, 2021  SYSTEM \$36,775.00  Averaged Price Adjustment from this item on all previous paymer of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Prestimate Item Adjustment (0006) due to user mcclon1 overridding Estimate Exception 10 on the current Payment Estimate.   | J       | 0260 - | Total                     |                    |                             |                |                 |               | \$0.00        |   |
| REPAIR  1 May 4, 2021 2 May 17, 2021 2 May 17, 2021 3 Jun 1, 2021 3 SYSTEM \$36,775.00 3 SYSTEM \$36,775.00 3 SYSTEM \$36,775.00 3 Jun 1, 2021 3 SYSTEM \$36,775.00 4 Averaged Price Adjustment from this item on all previous paymer of '0.00000' is applied (if non-zero).  Averaged Price Adjustment (0006) due to user mcclon1 overridding Estimate Exception 11 on the current Payment Estimate.  3 SYSTEM \$36,775.00 4 Averaged Price Adjustment from this item on all previous paymer of '0.00000' is applied (if non-zero).  3 Jun 1, 2021 5 SYSTEM \$36,775.00 5 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user mcclon1 overridding Estimate Exception 10 on the current Payment Estimate.  |         | 0270   | FOR CLASS C<br>PARTIAL    | Overrun            | Overrun                     | 1              |                 | SYSTEM        | \$36,775.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  |
| 2021 of '0.00000' is applied (if non-zero).  2 May 17, 2021 SYSTEM \$36,775.00 This adjustment offsets the original system-generated Overrun Prestimate Item Adjustment (0006) due to user mcclon1 overridding Estimate Exception 11 on the current Payment Estimate.  3 Jun 1, 2021 SYSTEM (\$36,775.00) Averaged Price Adjustment from this item on all previous paymer of '0.00000' is applied (if non-zero).  3 Jun 1, 2021 SYSTEM \$36,775.00 This adjustment offsets the original system-generated Overrun Prestimate Item Adjustment (0006) due to user mcclon1 overridding Estimate Exception 10 on the current Payment Estimate.  |         |        |                           |                    |                             | 1              |                 | SYSTEM        | (\$36,775.00) |   |
| Estimate Item Adjustment (0006) due to user mcclon1 overridding Estimate Exception 11 on the current Payment Estimate.  3 Jun 1, 2021  SYSTEM (\$36,775.00) Averaged Price Adjustment from this item on all previous paymer of '0.00000' is applied (if non-zero).  3 Jun 1, 2021  SYSTEM \$36,775.00 This adjustment offsets the original system-generated Overrun Patient (0006) due to user mcclon1 overridding Estimate Exception 10 on the current Payment Estimate.  |         |        |                           |                    |                             | 2              |                 | SYSTEM        | (\$36,775.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).   |
| 2021 of '0.00000' is applied (if non-zero).  3 Jun 1, SYSTEM \$36,775.00 This adjustment offsets the original system-generated Overrun Prestimate Item Adjustment (0006) due to user mcclon1 overridding Estimate Exception 10 on the current Payment Estimate.  |         |        |                           |                    |                             | 2              |                 | SYSTEM        | \$36,775.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user mcclon1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  |
| 2021 Estimate Item Adjustment (0006) due to user mcclon1 overridding Estimate Exception 10 on the current Payment Estimate.  |         |        |                           |                    |                             | 3              |                 | SYSTEM        | (\$36,775.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).   |
| Overrup - Total \$0.00   |         |        |                           |                    |                             | 3              |                 | SYSTEM        | \$36,775.00   | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user mcclon1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  |
| 30.00 July 10.00   |         |        |                           |                    | Overrun - To                | otal           |                 |               | \$0.00        |   |
| Overrun - Total \$0.00   |         |        |                           | Overrun - T        | otal                        |                |                 |               | \$0.00        |   |

Jul 6, 2021



## Line Item Adjustments by Estimate

| Project   | Line   | Description                                      | Adjustment<br>Type | Other<br>Adjustment<br>Type | Est.<br>Number | Created<br>Date | Created<br>By | Amount           | Remarks   |
|-----------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|------------------|---|
| J4S3251   | 0270 - | · Total  |                    |                             |                |                 |               | \$0.00           |   |
|           | 0280   | GRATES AND<br>BEARING<br>PLATES (3 FT            | Material           |                             | 4              | Jun 17,<br>2021 | SYSTEM        | \$926.00         | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcclon1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
|           |        | X 2 FT)  |                    |                             | 4              | Jun 17,<br>2021 | SYSTEM        | (\$926.00)       |   |
|           |        |  |                    | - Total                     |                |                 |               | \$0.00           |   |
|           |        |  | Material - T       | otal                        |                |                 |               | \$0.00           |   |
|           | 0280 - | · Total  |                    |                             |                |                 |               | \$0.00           |   |
|           | 0320   | CHANNELIZER<br>(TRIM LINE)                       | Material           |                             | 1              | May 4,<br>2021  | SYSTEM        | \$3,536.00       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user mcclon1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  |
|           |        |  |                    |                             | 1              | May 4,<br>2021  | SYSTEM        | (\$3,536.00)     |   |
|           |        |  |                    |                             | 2              | May 17,<br>2021 | SYSTEM        | \$3,536.00       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mcclon1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  |
|           |        |  |                    |                             | 2              | May 17,<br>2021 | SYSTEM        | (\$3,536.00)     |   |
|           |        |  |                    | - Total                     |                |                 |               | \$0.00           |   |
|           |        |  | Material - T       | otal                        |                |                 |               | \$0.00           |   |
|           | 0320 - | · Total  |                    |                             |                |                 |               | \$0.00           |   |
|           | 0590   | PRECAST<br>CONCRETE<br>DROP INLET 3<br>FT X 2 FT | Material           |                             | 4              | Jun 17,<br>2021 | SYSTEM        | \$4,416.00       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
|           |        |  |                    |                             | 4              | Jun 17,<br>2021 | SYSTEM        | (\$4,416.00)     |   |
|           |        |  |                    | - Total                     |                |                 |               | \$0.00           |   |
|           |        |  | Material - Total   |                             |                |                 |               | \$0.00           |   |
|           | 0590 - | 0590 - Total                                     |                    |                             |                |                 |               |                  |   |
|           | 0600   | 15 IN. GROUP<br>A FLARED<br>END SECT             | Material           |                             | 4              | Jun 17,<br>2021 | SYSTEM        | \$1,190.00       | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mcclon1 overridding Payment  |
|           |        |  |                    |                             |                |                 |               |                  | Estimate Exception 19 on the current Payment Estimate.  |
|           |        |  |                    |                             | 4              | Jun 17,<br>2021 | SYSTEM        | (\$1,190.00)     | Estimate Exception 19 on the current Payment Estimate.  |
|           |        |  |                    | - Total                     | 4              |                 | SYSTEM        | (\$1,190.00)     | Estimate Exception 19 on the current Payment Estimate.  |
|           |        |  | Material - T       |                             | 4              |                 | SYSTEM        | , , ,            | Estimate Exception 19 on the current Payment Estimate.  |
|           | 0600 - | END SECT   | Material - T       |                             | 4              |                 | SYSTEM        | \$0.00           | Estimate Exception 19 on the current Payment Estimate.  |
| J4S3251 - |        | END SECT   | Material - T       |                             | 4              |                 | SYSTEM        | \$0.00<br>\$0.00 | Estimate Exception 19 on the current Payment Estimate.  |