

Pay Estimate Created Date: November 2, 2022

Progress Estimate 13	Number	Contract ID Prime Contracto	201218-D03 or E & C Bridge, I		Period Start Period End	June 2, 20 November		Original Contract Amount Net Change Order Amount Current Contract Amount	\$565,088.00 \$141,472.53 \$706,560.53
Approval Date									By User
November 2, 2022			Generated and A	Approved (and should be	e considered	l Draft) at	the Project Office Level by	hensor
November 3, 2022		Re	viewed and Appro	ved (and s	hould be con	sidered Dra	ft) at the F	Resident Engineer Level by	browns1
November 4, 2022			F	Reviewed a	and Approved	l at the Cent	ral Office	Controllers Office Level by	ramses1
Original Completio	n Date	Current Con	pletion Date	Actu	al Completio	n Date	%	of Current Contract Amount	Complete
December 1, 20	21	Decembe	er 1, 2021					100.00%	
	Contract	Informational Dat	es		ſ	lilestones			
Date Description	Original	Completion Date	Current Comple	tion Date	No Milestor	nes Exist for	Contract		
Acceptance Date									
Awarded Date	January 6	6, 2021	January 6, 2021						
Letting Date	Decembe	er 18, 2020	December 18, 20	20					
Notice to Proceed Date	February	8, 2021	February 8, 2021						
Work Began Date									

Contract Total Pay For Estimate No. 13				
	This Estimate	Previous	To Date	
201218-D03				
Total Posted Items Pay	\$145.00	\$706,415.53	\$706,560.53	
Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		\$706,415.53	\$706,560.53	
Contract Total Payable This Estimate:	\$145.00			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5S3229	0240	8061005	ROCK DITCH CHECK	LF	\$14.500	10	\$145.00
Project J5S3229 - 1	Total						\$145.00
Overall - Total							\$145.00
Contract Adjustment	e This Fetimato						

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3229	0240	ROCK DITCH CHECK	Material			-10	\$14.50	(\$145.00)
	0240	ROCK DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.	10	\$14.50	\$145.00
	5004	BRIDGE APPROACH SLAB (MAJOR)	Material			-110	\$235.00	(\$25,850.00)
	5004	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.	110	\$235.00	\$25,850.00
Total								\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informati	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5S3229	FAS S401(98)	Bridge superstructure replacement	Н	COLE	over Bois Brule Creek 2.0	mile south of Rte. E	
Fotals by J	Job Numbe	rs					
J5S3229		d Item Pay Item Adjustme		tem Pay	This Estimate \$145.00 \$0.00 \$145.00	Previous \$706,415.53 \$0.00 \$706,415.53	To Date \$706,560.53 \$0.00 \$706,560.53
	Liquid	tive centive lated Damages Contract Adjust	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	hensor: waiting on MoDot QA entry.	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	hensor: waiting on MoDot QA entry.	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 5031010A, Project Item Line Number 5004, Material Set 5031010A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	hensor: waiting on MoDot QA entry.	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3229, Item 8061005, Project Item Line Number 0240, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	hensor: waiting on MoDot QA entry.	hensor	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-D03	J5S3229	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$15,000.00	\$15,000.00
		0001	0020	2035000	UNCLASSIFIED EXCAVATION	229.00	0.00	229.00	CUYD	229.00	\$75.00	\$17,175.0
		0001	0030	2035500	EMBANKMENT IN PLACE	111.00	0.00	111.00	CUYD	111.00	\$45.00	\$4,995.00
		0001	0040	2036000	COMPACTING EMBANKMENT	170.00	0.00	170.00	CUYD	170.00	\$12.00	\$2,040.0
		0001	0050	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	360.00	0.00	360.00	SQYD	360.00	\$9.00	\$3,240.0
		0001	0060	4019905	MISC.OPTIONAL PAVEMENT	360.00	-360.00	0.00	SQYD	0.00	\$87.00	\$0.0
		0001	0070	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	5.00	0.00	5.00	CUYD	5.00	\$125.00	\$625.0
		0001	0080	6096041	PLACING TYPE 1 ROCK DITCH LINER	5.00	0.00	5.00	CUYD	5.00	\$100.00	\$500.0
		0001	0090	6161005	CONSTRUCTION SIGNS	890.00	-112.00	778.00	SQFT	778.00	\$5.50	\$4,279.0
		0001	0100	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$35.00	\$140.0
		0001	0110	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	2.00	\$20.00	\$40.0
		0001	0120	6161025	CHANNELIZER (TRIM LINE)	25.00	-15.00	10.00	EA	10.00	\$18.00	\$180.0
		0001	0130	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	10.00	0.00	10.00	EA	10.00	\$185.00	\$1,850.0
		0001	0140	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.0
		0001	0150	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	-4.00	0.00	EA	0.00	\$1.00	\$0.0
		0001	0160	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$42,000.00	\$0.0
		0001	0161	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$37,533.00	\$37,533.0
		0001	0170	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	4.00	\$600.00	\$2,400.0
		0001	0180	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,182.00	0.00	1,182.00	LF	1,182.00	\$0.60	\$709.2
		0001	0190	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,218.00	0.00	2,218.00	LF	2,218.00	\$0.60	\$1,330.8
		0001	0200	6207001	PAVEMENT MARKING REMOVAL	495.00	199.00	694.00	LF	694.00	\$1.50	\$1,041.0
		0001	0210	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	16.00	0.00	16.00	SQYD	16.00	\$35.00	\$560.0
		0001	0220	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1,500.00	\$1,500.0
		0001	0230	8059901	MISC.Misc. (Seeding - Coole Season Mixture)	1.00	0.00	1.00	LS	1.00	\$7,500.00	\$7,500.0
		0001	0240	8061005	ROCK DITCH CHECK	95.00	-85.00	10.00	LF	10.00	\$14.50	\$145.0
		0001	0250	8061010A	TYPE B BERM	316.00	-316.00	0.00	LF	0.00	\$12.00	\$0.0
		0001	0260	8061016	SEDIMENT REMOVAL	19.00	-19.00	0.00	CUYD	0.00	\$1.00	\$0.0
		0001	0270	8061050	TYPE C BERM	526.00	-356.00	170.00	LF	170.00	\$15.00	\$2,550.0
		0010	0280	6061060	MGS GUARDRAIL	38.00	39.00	77.00	LF	77.00	\$22.50	\$1,732.5
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	4.00	0.00	4.00	EA	4.00	\$2,100.00	\$8,400.0
		0010	0300	6061078	(REGULAR/NO CURB) MGS EMBEDDED ANCHOR SECTION (WITH RUBRAIL)	250.00	-125.00	125.00	LF	125.00	\$30.14	\$3,767.5
		0010	0310	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	1.00	3.00	EA	3.00	\$2,900.00	\$8,700.0
		0070	0320	2169901	MISC.Removal of Existing Superstructure	1.00	0.00	1.00	LS	1.00		\$41,000.0
		0070	0330	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	110.00	-110.00	0.00	SQYD	0.00	\$100.00	\$0.0
			0340	7034216	TYPE H BARRIER	312.00	0.00	312.00	LF	312.00	\$60.00	\$18,720.0
		0070		7039905		463.00	0.00	463.00	SQYD	463.00		
		0070	0350		MISC.Slab on Steel (GFRP Rebar)						\$255.00	\$118,065.0
		0070	0360	7040101		20.00	0.00	20.00	SQFT	20.00	\$200.00	\$4,000.0
		0070	0370	7110500	TEMPORARY COATING - CONCRETE BENTS AND PIERS (WEATHERING STEEL) FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709,	1.00	0.00	1.00	LS	60,880.00	\$7,342.00	\$7,342.0
					GRADE 50W SLAB DRAIN				EA			¢6 500 0
		0070	0390	7123610		26.00	0.00	26.00	EA	26.00	\$250.00	\$6,500.0
		0070	0400	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.0
		0070	0410	7161000		8.00	0.00	8.00	EA	8.00	\$150.00	\$1,200.0
		0070	0420	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$1,200.00	\$9,600.0
		0001	5001	6189901	MISC.Adjust Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$4,467.00	\$4,467.0



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-D03	J5S3229	0070	5002	7049901	MISC.Fiber Reinforced Polymer Wrap	0.00	1.00	1.00	LS	1.00	\$75,746.76	\$75,746.76
		0001	5003	4019905		0.00	360.00	360.00	SQYD	360.00	\$95.00	\$34,200.00
		0070	5004	5031010A	BRIDGE APPROACH SLAB (MAJOR)	0.00	110.00	110.00	SQYD	110.00	\$235.00	\$25,850.00
		0010	5005	2153000	SHAPING SLOPES, CLASS III	0.00	1.00	1.00	100F	1.00	\$1,250.00	\$1,250.00
		0070	5006	7049901	MISC.Force Account No. 1 - Cold Weathering Cost of FRP Installation	0.00	1.00	1.00	LS	1.00	\$16,787.43	\$16,787.43
		0070	5007	1099901	MISC.COMPENSATION FOR PROJECT DELAY	0.00	1.00	1.00	LS	1.00	\$40,923.34	\$40,923.34
	Project J	5S3229 - To	otal Value	Posted to D	ate as of Report Generated Date							\$706,560.53
201218-D03 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$706,560.53



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line																
Number	ltem Code	De	escription	DWR Date	DWR Quantit Approval Posted Date			Location		From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance		Comments	
0240	8061005 ROC	K DITCH CHECK		10/31/22	11/2/22 10.0	D LF Bridge R0	250							Left and Right	of roadway Rt H at Bridge	R0250
ne infori Project	mation below	this line are de	tails for Construction S			formation	Station	Log Mile	Location	Numb	er of Items	SE E	ach Sign	Special Sign	SF Each Special Sign	Total SF to Po
583229	0090	October 18, 2021	778		SPECIAL 36x60 ASSEMBLY			0.011	Rt BB EB	1.00		15				
					SPECIAL 36x60	15.00 DETOUR		6.754	Rt H NB	1.00		15				
					ASSEMBLY R11-3a 60x30			0.071	Rt H SB	1.00		12.5				12
					CLOSED XX MILE TRAFFIC ONLY	S AHEAD LOCAL										
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		0.129	MO 17 SB	1.00		15				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		0.17	Rt E EB	1.00		15				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		0.196	Offramp 54-Mo 17 NB	1.00		15				
					CONST-5 96x48 PRESENCE	32.00 POINT OF		0.206	Rt H SB	1.00		32				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		0.285	Rt BB EB	1.00		15				
						3.00 END DETOUR		0.34	Rt H SB	1.00		3				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		0.348	Rt E EB	1.00		15				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		0.829	MO 17 SB	1.00		15				
					WO20-2 48x48 AHEAD	16.00 DETOUR		0.903	Rt H NB	1.00		16				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		0.928	MO 17 SB	1.00		15				
					SPECIAL 36x60	15.00 DETOUR		1.009	Rt H NB	1.00		15				
					ASSEMBLY SPECIAL 36x60	15.00 DETOUR		1.154	Rt H NB	1.00		15				
					ASSEMBLY SPECIAL 36x60	15.00 DETOUR		1.202	Rt E EB	1.00		15				
					ASSEMBLY R11-3a 60x30			1.213	Rt H NB	1.00		12.5				1
					CLOSED XX MILE TRAFFIC ONLY	S AHEAD LOCAL										
					WO20-3 48x48 CLOSED AHEAD	16.00 ROAD		1.726	Rt H SB	1.00		16				
						3.00 END DETOUR		1.784	Rt H NB	1.00		3				
					WO20-3 48x48 CLOSED AHEAD	16.00 ROAD		1.841	Rt H SB	1.00		16				
					R11-2 48x30 1 CLOSED	0.00 ROAD		1.958	Rt H SB	1.00		10				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		115.601	Hwy 54 WB	1.00		15				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		115.803	Hwy 54 WB	1.00		15				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		116.093	Hwy 54 WB	1.00		15				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		117.401	Hwy 54 WB	1.00		15				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		119.126	Hwy 54 WB	1.00		15				
					SPECIAL 36x60	15.00 DETOUR		122.353	Hwy 54 WB	1.00		15				
					ASSEMBLY SPECIAL 36x60	15.00 DETOUR		149.496	Hwy 54 EB	1.00		15				
					ASSEMBLY SPECIAL 36x60			151.618	Hwy 54 EB	1.00		15				
					ASSEMBLY SPECIAL 36x60			154.447	Hwy 54 EB	1.00		15				
					ASSEMBLY											
					SPECIAL 36x60 ASSEMBLY			155.705	Hwy 54 EB	1.00		15				
					SPECIAL 36x60 ASSEMBLY			155.851	Hwy 54 EB	1.00		15				
					SPECIAL 36x60 ASSEMBLY			156.01	Hwy 54 EB	1.00		15				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		156.213	Hwy 54 EB	1.00		15				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		186.377	MO 17 NB	1.00		15				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		186.61	MO 17 NB	1.00		15				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		186.72	MO 17 NB	1.00		15				
					SPECIAL 36x60 ASSEMBLY	15.00 DETOUR		4.277	Rt BB WB	1.00		15				
					SPECIAL 36x60	15.00 DETOUR		4.309	Rt BB WB	1.00		15				
					ASSEMBLY WO20-3 48x48	16.00 ROAD		4.393	Rt H NB	1.00		16				
					CLOSED AHEAD SPECIAL 36x60			4.441	Rt BB WB	1.00		15				
					ASSEMBLY SPECIAL 36x60			4.448	Rt BB WB	1.00		15				
					ASSEMBLY WO20-3 48x48				Rt H NB	1.00						
					CLOSED AHEAD			4.516				16				
					SPECIAL 36x60 ASSEMBLY			4.567	Rt E WB	1.00		15				
					R11-2 48x30 1 CLOSED	0.00 ROAD		4.646	Rt H NB	1.00		10				



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J5S3229	0090	October 18, 2021	778	ASSEMBLY								
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.032	Rt H SB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.351	Rt H SB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.599	Rt E WB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.603	Rt H SB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		6.476	Rt H NB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		6.64	Rt H NB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.02	Offramp 54-Mo 17 NB	1.00	15			15
	0090 - Total											778



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
29	0030	EMBANKMENT IN PLACE	Material		8	Mar 18, 2022	SYSTEM	\$4,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user lafava1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Mar 18, 2022	SYSTEM	(\$4,995.00)	
					9	Apr 5, 2022	SYSTEM	\$4,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Apr 5, 2022	SYSTEM	(\$4,995.00)	
					10	Apr 18, 2022	SYSTEM	\$4,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Apr 18, 2022	SYSTEM	(\$4,995.00)	
					11	May 19, 2022	SYSTEM	\$4,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user browns1 overridding Paymen Estimate Exception 1 on the current Payment Estimate.
					11	May 19, 2022	SYSTEM	(\$4,995.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0030 -	Total						\$0.00	
	0040	COMPACTING EMBANKMENT	Material		8	Mar 18, 2022	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user Iafava1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Mar 18, 2022	SYSTEM	(\$2,040.00)	
					9	Apr 5, 2022	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Apr 5, 2022	SYSTEM	(\$2,040.00)	
					10	Apr 18, 2022	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Apr 18, 2022	SYSTEM	(\$2,040.00)	
					11	May 19, 2022	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user browns1 overridding Paymen Estimate Exception 2 on the current Payment Estimate.
					11	May 19, 2022	SYSTEM	(\$2,040.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
- 5	0040 -							\$0.00	
	0070	FURNISHING TYPE 1 ROCK DITCH LINER	Material		9	Apr 5, 2022	SYSTEM	\$625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Apr 5, 2022	SYSTEM	(\$625.00)	
					10	Apr 18, 2022	SYSTEM	\$625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate.
					10	Apr 18, 2022	SYSTEM	(\$625.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0070 -	Total						\$0.00	
	0090	CONSTRUCTION SIGNS	Material		4	Nov 2, 2021	SYSTEM	\$4,279.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$4,279.00)	
					5	Nov 16, 2021	SYSTEM	\$4,279.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.



Nov 5, 2022

ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
229	0090	CONSTRUCTION SIGNS	Material		5	Nov 16, 2021	SYSTEM	(\$4,279.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0090 -	Total						\$0.00	
	0100	ADVANCED WARNING RAIL SYSTEM	Material		3	Oct 18, 2021	SYSTEM	\$140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Paymen Estimate Exception 1 on the current Payment Estimate.
					3	Oct 18, 2021	SYSTEM	(\$140.00)	
					4	Nov 2, 2021	SYSTEM	\$140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Paymen Estimate Exception 2 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$140.00)	
					5	Nov 16, 2021	SYSTEM	\$140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Paymen Estimate Exception 2 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$140.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0100 -	Total						\$0.00	
	0110	FLAG ASSEMBLY	Material		3	Oct 18, 2021	SYSTEM	\$40.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Paymen Estimate Exception 2 on the current Payment Estimate.
					3	Oct 18, 2021	SYSTEM	(\$40.00)	
					4	Nov 2, 2021	SYSTEM	\$40.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Paymen Estimate Exception 3 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$40.00)	
					5	Nov 16, 2021	SYSTEM	\$40.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Paymen Estimate Exception 3 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$40.00)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
	0110 - 0120	CHANNELIZER (TRIM LINE)	Material		3	Oct 18, 2021	SYSTEM	\$0.00 \$144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Paymer Estimate Exception 3 on the current Payment Estimate.
					3	Oct 18, 2021	SYSTEM	(\$144.00)	
					4	Nov 2, 2021	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Paymen Estimate Exception 4 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$180.00)	
					5	Nov 16, 2021	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Paymen Estimate Exception 4 on the current Payment Estimate.
					5		SYSTEM	(\$180.00)	Estimate Item Adjustment (0004) due to user hensor overridding Paymen
				- Total		2021 Nov 16,		(\$180.00) \$0.00	Estimate Item Adjustment (0004) due to user hensor overridding Paymen
			Material - To			2021 Nov 16,		(\$180.00) \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user hensor overridding Paymen
	0120 - 0130	TYPE III MOVEABLE BARRICADE WITH	Material - Tof Material			2021 Nov 16,		(\$180.00) \$0.00	Estimate Item Adjustment (0004) due to user hensor overridding Paymen Estimate Exception 4 on the current Payment Estimate.
		TYPE III MOVEABLE			5	2021 Nov 16, 2021 Oct 18,	SYSTEM	(\$180.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user hensor overridding Paymen Estimate Exception 4 on the current Payment Estimate.



Nov 5, 2022

roject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
S3229	0130	TYPE III MOVEABLE BARRICADE WITH	Material			2021			Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
		LIGHTS			4	Nov 2, 2021	SYSTEM	(\$1,850.00)	
					5	Nov 16, 2021	SYSTEM	\$1,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$1,850.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0130 -	Total						\$0.00	
	0140	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		3	Oct 18, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Oct 18, 2021	SYSTEM	(\$5,600.00)	
					4	Nov 2, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$5,600.00)	
					5	Nov 16, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$5,600.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0140 -	Total						\$0.00	
	0180	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		9	Apr 5, 2022	SYSTEM	\$709.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 15 on the current Payment Estimate.
					9	Apr 5, 2022	SYSTEM	(\$709.20)	
					10	Apr 18, 2022	SYSTEM	\$709.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 15 on the current Payment Estimate.
					10	Apr 18, 2022	SYSTEM	(\$709.20)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0180 -	Total						\$0.00	
	0190	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		9	Apr 5, 2022	SYSTEM	\$1,330.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 18 on the current Payment Estimate.
					9	Apr 5, 2022	SYSTEM	(\$1,330.80)	
					10	Apr 18, 2022	SYSTEM	\$1,330.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Apr 18, 2022	SYSTEM	(\$1,330.80)	
			- Total					\$0.00	
			Material - Total					\$0.00	
	0190 -	Total						\$0.00	
	0200	PAVEMENT MARKING REMOVAL	Overrun	Overrun	10	Apr 18, 2022	SYSTEM	(\$298.50)	
					11	May 19, 2022	SYSTEM	\$298.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.50000 - 1.50000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - Total					\$0.00	
	0200 -	Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
583229	0210	PERMANENT EROSION CONTROL GEOTEXTILE	Material		9	Apr 5, 2022	SYSTEM	\$560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	Apr 5, 2022	SYSTEM	(\$560.00)	
					10	Apr 18, 2022	SYSTEM	\$560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 21 on the current Payment Estimate.
					10	Apr 18, 2022	SYSTEM	(\$560.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0210 -	Total						\$0.00	
	0240	ROCK DITCH CHECK	Material		13	Nov 2, 2022	SYSTEM	\$145.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Nov 2, 2022	SYSTEM	(\$145.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0240 -	Total						\$0.00	
	0270	TYPE C BERM	Material		4	Nov 2, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$2,550.00)	
					5	Nov 16, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$2,550.00)	
					6	Dec 1, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Dec 1, 2021	SYSTEM	(\$2,550.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0270 -	Total						\$0.00	
	0280	MGS GUARDRAIL	Overrun	Overrun	9	Apr 5, 2022	SYSTEM	(\$877.50)	
					11	May 19, 2022	SYSTEM	\$877.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',22.50000 - 22.50000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0280 -	Total						\$0.00	
	0300	MGS EMBEDDED ANCHOR SECTION (W/ RUBRAIL)	Material		9	Apr 5, 2022	SYSTEM	\$3,767.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Apr 5, 2022	SYSTEM	(\$3,767.50)	
					10	Apr 18, 2022	SYSTEM	\$3,767.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Apr 18, 2022	SYSTEM	(\$3,767.50)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0300 -	Total						\$0.00	
	0310	TYPE A CRASHWORTHY END TERMINAL (MASH)	Overrun	Overrun	9	Apr 5, 2022	SYSTEM	(\$2,900.00)	
					11	May 19, 2022	SYSTEM	\$2,900.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2900.00000 - 2900.00000,



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
229	0310	TYPE A	Overrun	Overrun					'is applied (if non-zero).
		CRASHWORTHY END TERMINAL		Overrun - T	otal			\$0.00	
I		(MASH)	Overrun - Tot	al				\$0.00	
	0310 -	0 - Total							
	0340	TYPE H BARRIER	Material		8	Mar 18, 2022	SYSTEM	\$18,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Mar 18, 2022	SYSTEM	(\$18,720.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0340 -	Total						\$0.00	
	0350	MISC. CONCRETE CONSTRUCTION	Material		6	Dec 1, 2021	SYSTEM	\$70,839.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
I					6	Dec 1, 2021	SYSTEM	(\$70,839.00)	
					7	Mar 3, 2022	SYSTEM	\$118,065.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Mar 3, 2022	SYSTEM	(\$118,065.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0350 -							\$0.00	
	0370	TEMPORARY COATING CONCRETE BENTS AND P	Material		4	Nov 2, 2021	SYSTEM	\$7,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$7,342.00)	
					5	Nov 16, 2021	SYSTEM	\$7,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$7,342.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0370 - 0380	FAB. STRUCT.LOW ALLOY STEEL(IBM)A709,50W	Construction Stockpile		4	Nov 2, 2021	SYSTEM	\$0.00 (\$133,936.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total		2021		(\$133,936.00)	
			Construction		ckpile - Total			(\$133,936.00)	
			Construction Stockpile		2	Jun 1, 2021	SYSTEM	\$133,936.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$133,936.00	
			Construction	Stockpile ST	MI - Tota			\$133,936.00	
	0380 -	Total						\$0.00	
	0410	PLAIN NEOPRENE BEARING PAD	Construction Stockpile		4	Nov 2, 2021	SYSTEM	(\$560.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$560.00)	
			Construction Construction Stockpile STMI	Stockpile - 1				(\$560.00)	
				Total	2	Jun 1, 2021	SYSTEM	\$560.00 \$560.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total Construction Stockpile STMI - Total						
	0440	Total	construction	Stockpile S	wir - Tota			\$560.00	
	0410 - 0420	Total LAMINATED NEOPRENE BEARING PAD ASSEMBLY	Construction Stockpile		4	Nov 2, 2021	SYSTEM	\$0.00 (\$5,380.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			1	- Total				(\$5,380.00)	
		. COLLIDET	Construction	Stockpile - 1	otal			(\$5,380.00)	
								(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	



Nov 5, 2022

Project	Line	Description							
		Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3229 (0420	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	Construction Stockpile STMI		2	Jun 1, 2021	SYSTEM	\$5,380.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$5,380.00	
			Construction	Stockpile S	TMI - Tota			\$5,380.00	
C	0420 -	20 - Total							
Ę	5004	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		8	Mar 18, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lafava1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Mar 18, 2022	SYSTEM	(\$25,850.00)	
					9	Apr 5, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Apr 5, 2022	SYSTEM	(\$25,850.00)	
					10	Apr 18, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Apr 18, 2022	SYSTEM	(\$25,850.00)	
					11	May 19, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user browns1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	May 19, 2022	SYSTEM	(\$25,850.00)	
					12	Jun 2, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Jun 2, 2022	SYSTEM	(\$25,850.00)	
					13	Nov 2, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Nov 2, 2022	SYSTEM	(\$25,850.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
e	5004 -	Total						\$0.00	
J5S3229 - T	Total							\$0.00	
Overall - To	otal							\$0.00	